



2010 FACILITIES ASSESSMENT
 BOOKER T. WASHINGTON HIGH




Project Data	
Location Code:	148
Address:	715 Lauderdale
Year Built:	1949
Grade Configuration:	9-12
Student Capacity:	650
Ideal Capacity:	803
ADA Student Enrollment:	0
Size:	10.37 acres
Portables:	0
Building & additions	202,918 s. f.

2010 FACILITIES ASSESSMENT
BOOKER T. WASHINGTON HIGH


<p>Description:</p> <p>Upgrade to ADA guidelines</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$95,000</p>


<p>Description:</p> <p>Replace approximately (90) windows in gym and annex building</p>	
<p>Timeline:</p> <p>2010-11</p>	<p>Cost:</p> <p>\$229,500</p>

<p>Description:</p> <p>Upgrade to ADA guidelines</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$14,000</p>

2010 FACILITIES ASSESSMENT BOOKER T. WASHINGTON HIGH


<p>Description:</p> <p>See previous item</p>	


<p>Description:</p> <p>Lay-in ceiling tile in poor condition, mold forms and causes potential health concerns</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$6,000</p>

<p>Description:</p> <p>Store Front doors and windows in gym are in poor condition</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$22,000</p>

2010 FACILITIES ASSESSMENT


BOOKER T. WASHINGTON HIGH

<p>Description:</p> <p>See previous item</p>	


<p>Description:</p> <p>Gym lighting is inadequate.</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$60,000</p>

<p>Description:</p> <p>Upgrade to ADA guidelines</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$23,000</p>



2010 FACILITIES ASSESSMENT
BOOKER T. WASHINGTON HIGH

<p>Description:</p> <p>Stairwell treads have lost their integrity</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$24,000</p>

<p>Description:</p> <p>See previous item.</p>	

<p>Description:</p> <p>Awnings are damaged in annex.</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$18,000</p>

2010 FACILITIES ASSESSMENT BOOKER T. WASHINGTON HIGH

<p>Description:</p> <p>Washington Sr.</p> <p>Bogen MCP35A</p> <p>Installation Date: 1997</p>	
<p>Timeline:</p> <p>2014-15</p>	<p>Cost:</p> <p>\$90,000</p>
<p>Description:</p> <p>PVC Single ply roof: 12 years-poor</p> <p>Built up modified roof: 15 years-poor</p> <p>Metal roof 15 years-fair</p> <p>Plex-i- glass roof: 15 years-fair</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$659,000</p>