



2010 FACILITIES ASSESSMENT FOX MEADOWS ELEMENTARY





Project Data

Location Code:	071
Address:	2960 Emerald Street
Year Built:	Original Building 1965
Grade Configuration:	K-5
Student Capacity:	800
Ideal Capacity:	467
ADA Student Enrollment:	0
Size:	11.0 acres
Portables:	0
Building & Additions	55,553 s. f.


2010 FACILITIES ASSESSMENT FOX MEADOWS ELEMENTARY


<p>Description:</p> <p>Upgrade to ADA guidelines</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$28,000</p>


<p>Description:</p> <p>Same as previous item</p>	

<p>Description:</p> <p>Existing floor tile in gymnasium contain asbestos and is in poor to fair condition.</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$20,000</p>

2010 FACILITIES ASSESSMENT FOX MEADOWS ELEMENTARY




Description: Kitchen ceiling has water damage.	 A photograph showing a kitchen ceiling with significant water damage. The ceiling is stained with brown and yellowish marks, and a white pipe is visible running across it.
Timeline: TBD	Cost: \$3,000

Description: Existing door frame is old, in poor condition and rusting creating health department concerns and issues.	 A photograph showing a close-up of a door frame. The frame is heavily rusted and appears to be made of metal. The surrounding wall is painted yellow and orange.
Timeline: TBD	Cost: \$4,700

Description: Exterior of building has residual material in several areas.	 A photograph showing the exterior of a brick building. There are several dark, irregular stains on the brickwork, indicating residual material or mold.
Timeline: TBD.	Cost: \$3,000

2010 FACILITIES ASSESSMENT

FOX MEADOWS ELEMENTARY

<p>Playground/Surfaces Equipment Status:</p> <p>Fully equipped Has cast in place rubber surface.</p>	
<p>Playground Equipment / Surface Condition:</p> <p>New equipment, good Good, surface Fence enclosure inadequate needs replacing</p>	
<p>Description:</p> <p>Replace cooling tower</p>	
<p>Timeline:</p> <p>2016-17</p>	<p>Cost:</p> <p>\$228,000</p>
<p>Description:</p> <p>Intercom System Rauland MCZ3000 Installation Date: 2001</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$50,000</p>