

Project Data	
Location Code:	202
Address:	3866 Patte Ann
Year Built:	1958
Grade Configuration:	K-5
Student Capacity:	720/740
Ideal Capacity:	915
ADA Student Enrollment:	0
Size:	15.0 acres
Portables:	6
Building & Addition	91,552 s. f.

Description: Window system is old and needs replacing. In addition, panels underneath windows contain asbestos and will need to be replaced.	
Timeline:	Cost:
TBD	\$1,300,000
Description: Upgrade to ADA guidelines.	
Timeline:	Cost:
2010-11	\$484,500

Description: Transom windows do not provide code required 1 hour fire rating of compliance.	
Timeline:	Cost:
TBD	\$7,500


Description: Replacement of existing tile and lighting	
Timeline:	Cost:
TBD	\$1,600.000
	· · · /
Description:	
Existing 12"x12"ceiling tile in annex is in poor condition.	
Timeline:	Cost:
TBD	Included in previous pricing
Description	
Description: Asbestos pipe installation in poor to fair condition leading to potential health concerns.	
Timeline:	Cost:
TDD	¢18.000
TBD	\$18,000

Description: Interior of school need painting.	
Timeline:	Cost:
TBD	\$125,000
Description: Bathroom stall doors are missing. Install new stall partitions throughout.	

Timeline:	Cost:
TBD	\$63,300
Description:	A Longer (2)
Lockers are in poor condition and need replacing.	

Timeline:	Cost:
TBD	\$92,000
100	\$74,000

Description: Exterior brick is cracked mortar is loose or missing.	
Timeline:	Cost:
TBD	\$12,500
Description:	



Description: Sprayed acoustical ceiling is filthy and in poor condition.	
	CEVIENT NET DECENTION CAMPS SOUTH LE
Timeline:	Cost:
TBD	\$24,500

Description: Existing gym bleachers are old and in poor condition.	
Timeline: TBD	Cost: \$90,000
	\$90,000
Description: Existing gym floor is "rubber" material and is in poor condition.	
Timeline:	Cost:

TBD	

	/
Cost:	
\$90,000	

Description:	
Covered walkways paint is in poor condition	
Timeline:	Cost:
TBD	\$2,500

Description: Hallway radiators are old and damaged.	
Timeline:	Cost:
TBD	\$55,000
Description:	
No A/C in kitchen	Picture not available
Timeline:	Cost:
TBD	\$65,000
Description:	
Built up roof: 17 years-poor Metal roof: 30 years-fair	
Timeline:	Costs:
2012-13	\$412,000

Playground/Surfaces Equipment Status:	
No equipment	No picture available
Timeline:	Cost:
TBD	\$75,000

Description: Replace (2) condenser units, (2) boilers, (7) RUT, and domestic water with tank	Stuff Barrier
Timeline:	Cost:
2012-13	\$1,103,000

Description: Clean, seal and paint exterior	
Timeline:	Cost:
2012-13	\$201,400

Description:	
Replace old interior brick wall structure	
	No Picture Available
Timeline:	Cost:
TBD:	\$2,300.000

Description:	
Removal of old asbestos floor tile	
	No Picture Available
Timeline:	Cost:
TBD:	\$1,400.000

Description:	
Intercom System:	
Dukane 3200	
Installation Date: 2000	
Timeline:	Cost:
TBD	\$50,000