


Description: Upgrade to ADA guidelines	
Timeline:	Cost:
TBD	\$21,000



Description:	
Same as previous.	

LAREVIEW ELEWIENTARI		
Description: Window system is old and need replacing.		
Timeline: TBD	Cost: \$272,000	
100	ψ=1=,000	
Description: Existing parking area in poor condition.		
Timeline:	Cost:	
TBD		
	\$80,000	

Description:	
Paint on canopy ceiling in poor condition.	
Timeline:	Cost:
TBD	\$6,500

LAKEVIEW ELEMENTARY	
Description:	
No A/C in kitchen	
	Picture not available
Timeline:	Cost:
TBD	\$55,000
	\$55,000
Playground/Surfaces Equipment Status:	
Fully equipped	
Has cast in place rubber surface,	
Playground Equipment / Surface Condition:	
Good equipment	
Good surface No fence enclosure	
Description:	
Replace (2) boilers, (9) pumps, domestic water boiler with tank (41) unit ventilators and controls	

Cost:

0 0

2013-14 \$2,263,700

Description: PVC Single ply roof: 11 years-poor	
Timeline:	Cost:
TBD	\$200,000
Description: Intercom System: Bogen MCP 35A Installation Date: 1994	
Timeline:	Costs:
TBD	\$50,000