

Project Data	
<b>Location Code:</b>	481
Address:	1237 College
Year Built:	1965
Grade Configuration:	K-5
Student Capacity:	NA
Ideal Capacity:	NA
ADA Student Enrollment:	0
Size:	7.03 acres
Portables:	0
Building & Addition:	56,356 s. f.
Portables:	0

<b>Description:</b>	Every Da College Bou
Upgrade to ADA guidelines	
Timeline:	Cost:
TBD	\$45,000
<b>Description:</b>	PER TOTAL TO
Existing floor tiles contains Asbestos and is in poor condition.	W. T.
Condition	A PORT OF THE PROPERTY OF THE PARTY OF THE P
	AND THE PROPERTY.
Timeline:	Cost:
i interne:	Cost.
TBD	\$87,000
<b>Description:</b>	
Kitchen vent hood needs fire suppression system.	
Timeline:	Cost:
1	1

\$6,000

TBD

Description:	MANAGE
Stage curtains are in poor condition.	
Timeline:	Cost:
TBD	\$28,000
<b>Description:</b>	
Replace boilers, pumps and classroom EMS system	
Timeline:	Cost:
2013-14	\$718,200
<b>Description:</b>	
Incinerator not in use.	
Timeline:	Cost:
TBD	\$3,000

Description:  Dumpster has no enclosure.	
Timeline:	Cost:
TBD	\$5,000
IDD	\$5,000
<b>Description:</b>	
Description.	
Exterior of building need pressure washing.	
Timeline:	Cost:
TBD	\$2,800
100	ψ 2000
<b>Description:</b>	
See previous item.	

Description: Window system is old and needs replacing	
Timeline:	Cost:
TBD	\$375,000
100	\$373,000
Description:	
Exterior paint in poor condition.	
Timeline:	Cost:
TBD	\$36,000
Description:	
Foundation and structural issues.	
Timeline:	Cost:

\$N/A

**TBD** 

Description:  Replace domestic water boiler  Timeline: 2014-15	Cost: \$34,100
Description:	
Repair spaulded concrete on building and paint exterior	No Picture Available
Timeline:	Cost:
2011-12	\$83,200
Description:	
Intercom System: Bogen MCP35A	S THE STATE OF THE
Installation Date: 1994	
Timeline:	Cost:
TBD	\$70,000