

Project Data	
Location Code:	170
Address:	4480 Westmont Rd
Year Built:	1958
Grade Configuration:	9-12
Student Capacity:	1325
Ideal Capacity:	982
ADA Student Enrollment:	0
Size:	27.47 acres with Westwood Elementary
Portables:	0
Building & Addition	181,342 s. f.

Description: Store front doors and windows in poor condition.	
Timeline:	Cost:
TBD	\$25,000
Description: Metal building near stadium not being used, seems to be in good structural condition, however it needs overhead	

 doors (2).

 Timeline:

 TBD

 \$5,000

Description:	
Perimeter fencing in need of repair.	
Timeline:	Cost:
TBD	\$22,000


Description: Clean, seal and paint exterior	
Timeline:	Cost:
2012-13	\$275,600

Description:	
Replace approximately (314) windows.	
Timeline:	Cost:
2016-17	\$895,000

Description: Existing ceiling tile in poor condition, mold is forming and cause potential health hazards and concerns.	
Timeline:	Cost:
TBD	\$300,000

2010 FACILITIES ASSESSMENT westwood high school


Description: Rain penetrates from roof to inside walls in several locations of school.	
Timeline:	Cost:
TBD	\$1,200
Description:	The second second second



Description:	
Exterior lighting damaged and / or not working properly.	
Timeline:	Cost:
TBD	\$11,500

2010 FACILITIES ASSESSMENT westwood high school

Description: Same a previous item	



Description:	
Water has damaged walls at greenery in foyer of school.	
Timeline:	Cost:
TBD	\$4,300

Timeline:Cost:TBD\$110,000Description:Image: Cost:Acoustical panels in music room are damagedImage: Cost:Timeline:Cost:TBD\$5,200	Description: Return grill of heating units are damaged in majority of classrooms. Temperature control for these units not working properly.	
Description: Acoustical panels in music room are damaged Image: Timeline: Cost:	Timeline:	
Acoustical panels in music room are damaged Image: Cost: Timeline: Cost:	TBD	\$110,000
Acoustical panels in music room are damaged Image: Cost: Timeline: Cost:		
	Acoustical panels in music room are damaged	
TBD \$5.200	Timeline:	Cost:
	TRD	\$5 200
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		\$ 5 ,200

Description:	
Existing stage floor in poor condition.	
	A Carl and a second
	A CONTRACTOR
Timeline:	Cost:
TBD	\$8,000

WEST WOOD HIGH	IJUIUUL
Description: Existing stage curtains are damaged and in poor condition.	
Timeline:	Cost:
TBD	\$20,000
Description:	
Same as previous item	

Description: Slope too sleep in auditorium	
Timeline:	Cost:
TBD	\$150.000

Description: Same as previous item	

Description:	
Light (1) is missing in auditorium	
	5
Timeline:	Cost:
TBD	\$600

Description: Existing kitchen equipment is in poor condition and pilot light on stove goes out creating gas overnight.	
Timeline:	Cost:
TBD	\$10,000

	CHOOL
Description: Lay-in ceiling tile in poor condition, apparent mold growth and causes potential health concerns	
Timeline:	Cost:
TBD	\$6,250
Description: Dumpsters (3) need enclosures	
Timeline:	Cost:
TBD	\$15,000

Description:	
No A/C in kitchen	
	Picture not available
Timeline:	Cost:
TBD	\$66,000

Description:	
Replace major components and parts to bring elevator up to ADA compliance	Picture not available
Timeline:	Cost:
2010-11	\$71,400
Description: Intercom System: Rauland MCI2000 Installation Date: 1985	
Timeline:	Cost:
2011-12	\$90,000

Description:	
DVC Single ply roof:	
PVC Single ply roof:	
13 years-poor	
	and the second
Shingled roof:	the state of the s
12 years-poor	and give go at a story - side
	and the state of t
Built up:	the part of the second
20 year-poor	
20 year poor	
Built up modified:	
15 years-poor	
Metal roof:	
30 years-poor	
Timeline:	Cost:
TBD	\$582,500