


Project Data	
Location Code:	167
Address:	4417 Willow
Year Built:	1957
Grade Configuration:	K-5
Student Capacity:	680/740
Ideal Capacity:	662
ADA Student Enrollment:	0
Size:	11.58 acres
Portables:	5
Building & Addition:	74,349 s. f.

Description: Dumpsters need enclosures.	
Timeline:	Cost:
TBD	\$10,000
Descriptions	
Description:	





Description: See previous items.	

Description: Existing 12"x12" ceiling tile is in poor condition and in some locations, spline is exposed.	
Timeline:	Cost:
TBD	\$312,000

Description: Existing non - asbestos pipe lagging in poor condition.	
Timeline:	Cost:
TBD	\$3,000

Description:

Damaged, asbestos-containing pipe insulation in boiler room.



Timeline:

Cost:

TBD

\$4,000

Description: Transom windows do not provide code required 1 hour fire rating of compliance.	
Timeline:	Cost:
TBD	\$55,000

Description: Covered walkways are in poor condition and need painting.	
Timeline:	Cost:
TBD	\$6,000

Description:	
Upgrade to ADA guidelines.	
Timeline:	Cost:
TBD	\$42,000
Description	
Description: Existing floor tiles contain asbestos and are in poor condition.	

Timeline:	Cost:
TBD	\$135,000

Description: See previous item.	

Description:	Bar i M That I have a
Stage floor is in poor condition.	
Timeline:	Cost:
TBD	\$2,000
Description: Dishwasher not operable.	
Timeline:	Cost:
TBD	\$12,000
Description:	
No A/C in kitchen.	

No A/C in kitchen.	
	Picture not available
Timeline:	Cost:
TBD	\$55,000

Playground/Surfaces Equipment Status:		
No continuent		
No equipment.		
	No Picture Available	
Playground Equipment / Surface Condition:		

Description:	
Intercom System	
Rauland 350	
Installation Date: 1999	
Timeline:	Cost:
2011-12	\$50,000

Description:	
PVC Single ply roof: 7 years-good	
Built up modified roof: 5 years-good	
Timeline:	Cost:
TBD	\$437,500