

| Project Data | |
|-------------------------|--------------------|
| Location Code: | 287 |
| Address: | 4080 Kirby Parkway |
| Year Built: | 1980 |
| Grade Configuration: | 9-12 |
| Student Capacity: | 1500/1675 |
| Ideal Capacity: | 1,577 |
| ADA Student Enrollment: | 1 |
| Size: | |
| Portables: | 7 |
| Building & Additions: | 212,272 s. f. |

2010 FACILITIES ASSESSMENT

KIRBY HIGH SCHOOL **Description:**

Greenhouse in poor condition and doesn't appear to be in-use (could not confirm its use or "non-use")



Timeline: **Cost:**

\$20,000 **TBD**

Description:

Exterior of building needs pressure washing.



Timeline: Cost:

\$8,000 **TBD**

Description:

Replace auditorium seating



Timeline: Cost:

2010-11. \$14,200

| Description: | |
|---|----------|
| Foundation cracking near boiler room. | |
| Timeline: | Cost: |
| TBD | \$12,000 |
| | |
| Description: Door frames in the kitchen are rusting creating health department issues. | |
| Timeline: | Cost: |
| TBD | \$3,700 |
| Description: | |
| Whiteboards needed in some classrooms. | |
| Timeline: | Cost: |

\$3,000

TBD

| Description: Damaged sink counters in restrooms. | |
|---|-----------------|
| Timeline: | Cost: |
| TBD | \$7,500 |
| | |
| Description: Upgrade to ADA requirements. | |
| | |
| Timeline: | Cost: |
| TBD | \$35.000 |
| | |
| Description: | |
| Interior of school needs painting in certain areas. Hallways have recently been painted. Timeline: | Cost: |
| | |

\$197,000

TBD

| Description: | |
|---------------------------|-----------------------|
| Install A/C in kitchen | |
| | 71. |
| | Picture not available |
| | |
| | |
| Timeline: | Cost: |
| 2010-11. | \$204,000 |
| Description: | |
| No A/C in gym | |
| | |
| | Picture not available |
| | |
| | |
| Remedy: | Cost: \$350,000 |
| Install A/C in this area. | |
| | Priority: II |
| Description: | |
| Intercom System | |
| Telecor XL | |
| Installation Date: 1995 | |
| | |
| | A Barren |
| | |
| | O Manus |
| Timeline: | Cost: |
| | 000 000 |
| TBD | \$90,000 |

| Description: | |
|----------------------------|----------|
| Replace gymnasium lighting | |
| Timeline: | Cost: |
| 2010-11 | \$36,000 |

| Description: | |
|-----------------------------------|----------|
| Replace auditorium house lighting | 5 60 600 |
| | |
| Timeline: | Cost: |
| 2010-11 | \$30,600 |

| Description: | |
|----------------------------|----------------------|
| Replace clocks/bell system | time control carrier |
| Timeline: | Cost: |
| 2015-16 | \$37,000 |

| Description: | |
|--|----------------------|
| Replace all HVAC Roof Top Units | No Picture Available |
| Timeline: | Cost: |
| 2010-11 | \$714,067.00 |
| Descriptions | |
| Description: PVC Single ply roof: 9 years-fair Metal roof: 30 years-good Plexiglass roof: 30 years-poor | |
| Timeline: | Cost: |

\$977,250

TBD