2010 FACILITIES ASSESSMENT LINCOLN ELEMENTARY



Project Data		
Location Code:	081	
Address:	1566 S. Orleans	
Year Built:	1923	
Grade Configuration:	K-5	
Student Capacity:	740	
Ideal Capacity:	684	
ADA Student Enrollment:	0	
Size:	2.63 acres	
Portables:	0	
Building & Addition	80,00 s. f.	

2010 FACILITIES ASSESSMENT LINCOLN ELEMENTARY

Description: Problems with water ponding on roof.	
Timeline:	Cost:
TBD	\$1,000
Description: Dumpster has no enclosure. Timeline:	Cost:
TBD	\$5,000
Playground/Surfaces Equipment Status: No equipment at school.	No Picture available
Playground equipment / Surface Condition:	
No equipment at school.	

2010 FACILITIES ASSESSMENT LINCOLN ELEMENTARY

Description:	
Repair sewer	No Picture available
Timeline:	Cost:
2010-11	\$66,300
Description:	
	Control of the Contro
Intercom System	
Rauland MLZ300	
Installation Date: 1996	
Timeline:	Cost:
Timeme.	Cust.
2013-14	\$50,000
	4
Description:	
PVC Single ply roof:	
9 years-	1
Timeline:	Cost:
TBD	\$229,700