

Project Data	
Location Code:	052
Address:	993 Roland Street
Year Built:	1914
Grade Configuration:	K-5
Student Capacity:	480
Ideal Capacity:	390
ADA Student Enrollment:	0
Size:	4.98 acres
Portables:	0
Building & Addition	58,750 s. f.

	,
Description: Fencing damaged around perimeter of school.	
Timeline:	Cost:
TBD	\$8,000
Description: See previous item	
Description:	
Parking lines have faded.	
Timeline:	Cost:
TBD	\$1,000

Description: Upgrade to ADA guidelines	
Timeline:	Cost:
TBD.	\$40,000
Description:	
Paint interior of building.	
Timeline:	Cost:
2013-14.	\$105,300
Description:	
See previous item	

Descri	nti	Λn	•
DUSCII	и	VII	•

Water ponds in this area, drainage not adequate. Water penetrates walls into lower level (sub-floor) rooms.



Timeline: Cost:

TBD \$80,000

Description:

Damaged, asbestos containing floor tile.



Timeline: Cost:

TBD \$114,000

Description:

Transom windows do not provide code required 1 hour fire rating of compliance.



Timeline: Cost:

TBD \$8,000

Playground/Surfaces Equipment Status:	
No Equipment	
	No picture available
	G
Playground Equipment / Surface Condition:	Cost: \$75,000
	Priority: II
	Thomy. II
Description:	
Replace cooling tower	
	No Picture Available
Timeline:	Cost:
2010-11	\$204,000

Description: PVC Single ply roof: 6 years-good	
Timeline:	Cost:
TBD	\$120,500
TD 1.4	

IDD	\$120,500
Description:	
	R O THE REST OF TH
Intercom System: Rauland 350	
Installation Date: 1995	THE RESERVE THE PROPERTY OF TH

Timeline:	Costs:
TBD	\$50,000