



2010 FACILITIES ASSESSMENT  
WHITE STATION ELEMENTARY




<b>Project Data</b>	
<b>Location Code:</b>	065
<b>Address:</b>	4840 Chickasaw Rd
<b>Year Built:</b>	1998
<b>Grade Configuration:</b>	K-5
<b>Student Capacity:</b>	920
<b>Ideal Capacity:</b>	827
<b>ADA Student Enrollment:</b>	30
<b>Size:</b>	N/A
<b>Portables:</b>	0
<b>Building &amp; Addition:</b>	79,293 s. f.


# 2010 FACILITIES ASSESSMENT WHITE STATION ELEMENTARY

<p><b>Description:</b></p> <p>Replace damaged glass panes north/south ends of building</p>	
<p><b>Timeline:</b></p> <p>2018-19</p>	<p><b>Cost:</b></p> <p>\$23,600</p>

<p><b>Description:</b></p> <p>Storage area is minimal.</p>	
<p><b>Timeline:</b></p> <p>TBD</p>	<p><b>Cost:</b></p> <p>\$10,000</p>

<p><b>Description:</b></p> <p>Existing parking area has limited spaces, causing people to park in "violation".</p>	
<p><b>Timeline:</b></p> <p>TBD</p>	<p><b>Cost:</b></p> <p>\$90,000</p>


## 2010 FACILITIES ASSESSMENT WHITE STATION ELEMENTARY

<p><b>Description:</b></p> <p>Dumpsters (2) need enclosed.</p>	
<p><b>Timeline:</b></p> <p><b>TBD</b></p>	<p><b>Cost:</b></p> <p><b>\$10,000</b></p>

<p><b>Playground/Surfaces Equipment Status:</b></p> <p>No equipment, Park Commission playground equipment adjoins school.</p>	<p style="text-align: center;"><b>No picture available</b></p>
<p><b>Playground Equipment / Surface Condition:</b></p> <p>No equipment, Park Commission playground equipment adjoins school.</p>	

<p><b>Description:</b></p> <p>Built up modified roof: 11 years-fair</p> <p>Plexiglass roof: 11 years-poor</p> <p>Metal roof 11 years-fair</p>	
<p><b>Timeline:</b></p> <p><b>TBD</b></p>	<p><b>Cost:</b></p> <p><b>\$387,500</b></p>

# 2010 FACILITIES ASSESSMENT WHITE STATION ELEMENTARY

<p><b>Description:</b></p> <p>Intercom System</p> <p>Bogen Multicom2000</p> <p>Installation Date: 2002</p>	
<p><b>Timeline:</b></p> <p><b>TBD</b></p>	<p><b>Cost:</b></p> <p><b>\$50,000</b></p>