



2010 FACILITIES ASSESSMENT
HOLLYWOOD PROMISE ACADEMY




| Project Data | |
|--------------------------------|--------------|
| Location Code: | 091 |
| Address: | 1346 Bryan |
| Year Built: | 1928 |
| Grade Configuration: | N/A |
| Student Capacity: | 560 |
| Ideal Capacity: | 0 |
| ADA Student Enrollment: | 0 |
| Size: | 2.24 acres |
| Portables: | 0 |
| Building & Addition | 67,769 s. f. |


2010 FACILITIES ASSESSMENT
HOLLYWOOD PROMISE ACADEMY


| | |
|--|--|
| Description: Replace FA system and upgrade cabling support |  |
| Timeline: 2012-13 | Cost: \$154,000 |


| | |
|---|---|
| Description: Replace (2) 1990 boilers |  |
| Timeline: 2014-15 | Cost: \$440,000 |

| | |
|--|--|
| Description: Upgrade to ADA guidelines |  |
| Timeline: 2018-19 | Cost: \$212,400 |


2010 FACILITIES ASSESSMENT HOLLYWOOD PROMISE ACADEMY


| | |
|--|--|
| Description: Replace rotten wood on café soffet and fascia. Tuck point, clean and paint exterior |  |
| Timeline: 2009-10 | Cost: \$125,000 |

| | |
|--|---|
| Description: Plaster interior walls need repairing |  |
| Timeline: 2009-10 | Cost: \$116,300 |

| | |
|---|--|
| Description: Patch and overlay 3,675 sq. yd.. asphalt parking |  |
| Timeline: 2011-12 | Cost: \$41,000 |

2010 FACILITIES ASSESSMENT HOLLYWOOD PROMISE ACADEMY

| | |
|---|--|
| <p>Description:</p> <p>PVC Single Ply roof: 6 years-good</p> <p>Shingled roof: 6 years-fair</p> <p>Metal roof: 30 years-fair</p> |  |
| <p>Timeline:</p> <p>TBD</p> | <p>Cost:</p> <p>\$184,400</p> |

| | |
|---|---|
| <p>Description:</p> <p>Intercom System</p> <p>Rauland MCI2000</p> <p>Installation Date: 2002</p> |  |
| <p>Timeline:</p> <p>TBD</p> | <p>Cost:</p> <p>\$50,000</p> |