





2010 FACILITIES ASSESSMENT SHERWOOD ELEMENTARY





Project Data	
Address:	1156 Robinhood Lane
Year Built:	1950
Grade Configuration:	K-5
Student Capacity:	800/920
Ideal Capacity:	667
ADA Student Enrollment:	0
Size:	7.54 Acres
Portables:	6
Building & Additions	94,516 s. f.


2010 FACILITIES ASSESSMENT SHERWOOD ELEMENTARY

<p>Description:</p> <p>Upgrade to ADA guidelines</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$3,000</p>
<p>Description:</p> <p>Stairwell treads have lost their integrity.</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$17,000</p>
<p>Description:</p> <p>Boiler has exceeded its life expectancy.</p>	
<p>Timeline:</p> <p>2010-11</p>	<p>Cost:</p> <p>\$140,000</p>


2010 FACILITIES ASSESSMENT SHERWOOD ELEMENTARY

Description: Existing floor tile contains Asbestos and is in poor condition	
Timeline: TBD	Cost: \$213,000


Description: See previous item.	

Description: Whiteboards needed in some classrooms.	
Timeline: TBD	Cost: \$4,000




2010 FACILITIES ASSESSMENT SHERWOOD ELEMENTARY

<p>Description:</p> <p>Interior paint in poor condition.</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$128,000</p>


<p>Description:</p> <p>See previous item.</p>	


<p>Description:</p> <p>Install A/C and code-compliant vent-a-hood with fire suppression in kitchen</p>	
<p>Timeline:</p> <p>2010-11</p>	<p>Cost:</p> <p>\$210,364.00</p>

2010 FACILITIES ASSESSMENT SHERWOOD ELEMENTARY

<p>Playground/Surfaces Equipment Status:</p> <p>Fully equipped Has surface Woodchips w/heavy plastic border</p>	
<p>Playground Equipment / Surface Condition:</p> <p>New equipment Good Surface No fence</p>	
<p>Description:</p> <p>Replace HVAC/EMS system</p>	
<p>Timeline:</p> <p>2013-14</p>	<p>Cost:</p> <p>\$129,600</p>

2010 FACILITIES ASSESSMENT SHERWOOD ELEMENTARY

<p>Description:</p> <p>PVC single Ply roof: 13 years-poor</p> <p>PVC single Ply roof: 1 year-good</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$240,000</p>

<p>Description:</p> <p>Intercom System Dukane 3200</p> <p>Installation Date: 2003</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$50,000</p>