

Project Data		
Location Code:	066	
Address:	993 Roland Street	
Year Built:	1960	
Grade Configuration:	K-6	
Student Capacity:	600/680	
Ideal Capacity:	509	
ADA Student Enrollment:	0	
Size:	12.43 acres	
Portables:	5	
Building & Addition	38,000 s. f.	


	IAKI
Description: Dumpsters (2) need enclosures.	
Timeline:	Cost:
TBD	\$10,000
D 1.0	
Description: Replace approximately (264) windows	
Timeline:	Cost:
2014-15	\$726,000
2014-13	\$720,000
Description: Transom windows do not provide code required 1 hour rating of compliance. Timeline:	Roots:

TBD

\$16,000

Description: Upgrade to ADA guidelines	
Timeline:	Cost:
2015-16	\$TBD

Description:	
Paint interior of building.	
Timeline:	Cost:
2013-14	\$93,300



VV FILLINE I ELEIVIE.	NIAKI
Description: Door frames in kitchen are rusting creating health department issues.	
Timeline:	Cost:
TBD	\$4,700
D 1.0	
Description:	and the second second
Built up modified roof:	
14 years-poor	
J	
Built up roof:	247-16-16-16-16-16-16-16-16-16-16-16-16-16-
16 years-poor	
Timeline:	Cost:
TBD	\$305,600
100	ψ505,000
Description:	
See previous item.	

Playground/Surfaces Equipment Status:	
No equipment, Park Commission playground equipment adjoins school.	Picture not available
Playground Equipment / Surface Condition:	
Description:	
Replace (2) boilers, pumps, controls, EMS system and install A/C in kitchen	
Timeline:	Cost:
2010-11	\$719,000
Description:	
Replace outside water service main, service to annex	No picture available
Timeline:	Cost:
2009-10	\$40,000

Description:		9
Intercom System:	W	-5 · 5 · ==
Dukane 3200	Ť N 5	
Installation Date: 2000	and the same of th	
	- Carlo	

Timeline: Cost:

TBD \$50,000