



## Department of Procurement Services

---

160 South Hollywood Street · Room 126 · Memphis, TN 38112 · (901) 416-5376

### QUESTIONS AND ANSWERS

#### **IFB11132023AJKG Central HS Exterior Repairs**

1. **These existing windows cannot be reinstalled once removed because:**
  - a) **This type of window most likely contains Asbestos (Cannot reinstall any material with asbestos)**
  - b) **Old steel sash windows imbedded in concrete.**
  - c) **They will be damaged during removal.**

**The only solution is to remove existing windows and install new storefront windows. Existing window screens can be removed and reinstalled. Please advise.**

**Please install new windows to match as close as possible and reuse existing screens.**

2. **Is there a way to do another walk through with my subs if they need to go out there and take a look at the scope of work?**

**Yes. Check in with the Plant Manager (Mr. John Chandler 901-598-9355)**

Thank you,

Procurement Services