
2010 FACILITIES ASSESSMENT BRUCE ELEMENTARY



| Project Data | | |
|-------------------------|-------------------------|--|
| Location Code: | 005 | |
| Address: | 581 South Bellevue Blvd | |
| Year Built: | 1999 | |
| Grade Configuration: | K-5 | |
| Student Capacity: | 640 | |
| Ideal Capacity: | 672 | |
| ADA Student Enrollment: | 2 | |
| Size: | N/A | |
| Portables: | 0 | |
| Building & Additions: | 68,491 | |
| | | |
| | | |

2010 FACILITIES ASSESSMENT BRUCE ELEMENTARY

| Description: | |
|---|---------|
| Existing lay-in tile has several areas of damaged or molded tile throughout entire facility. | |
| Timeline: | Cost: |
| TBD | \$5,000 |

Description: Same as previous item

| Description: Damage to interior walls in kitchen due to lack of maneuvering space. | |
|--|---------|
| Timeline: | Cost: |
| TBD | \$8,800 |

2010 FACILITIES ASSESSMENT BRUCE ELEMENTARY

| Description: | |
|--|-----------|
| Built up modified roof: 10 years-fair | |
| Timeline: | Cost: |
| TBD | \$321,750 |
| Description: | |
| Bruce Elem. | |
| Telecor AL | |
| Installation Date: 1999 | |
| Suggested Upgrade: | Cost: |
| 2013-14 | \$50,000 |