



2010 FACILITIES ASSESSMENT  
HAMILTON HIGH




<b>Project Data</b>	
<b>Location Code:</b>	129
<b>Address:</b>	1363 Person
<b>Year Built:</b>	1972
<b>Grade Configuration:</b>	9-12
<b>Student Capacity:</b>	1725
<b>Ideal Capacity:</b>	2065
<b>ADA Student Enrollment:</b>	0
<b>Size:</b>	8.14 acres
<b>Portables:</b>	0
<b>Building &amp; Addition</b>	336,151 s. f.


# 2010 FACILITIES ASSESSMENT HAMILTON HIGH


<b>Description:</b>  Dumpsters (2) do not have enclosures.	
<b>Timeline:</b>	<b>Cost:</b>  \$5,000


<b>Description:</b>  Replace auditorium seating.	
<b>Timeline:</b>  2010-11	<b>Cost:</b>  \$224,400

<b>Description:</b>  Replace auditorium house lighting	
<b>Timeline:</b>  2010-11	<b>Cost:</b>  \$46,000

## 2010 FACILITIES ASSESSMENT HAMILTON HIGH

<p><b>Description:</b></p> <p>Replace lighting in gymnasium</p>	
<p><b>Timeline:</b></p> <p>2010-11</p>	<p><b>Cost:</b></p> <p>\$42,800</p>

<p><b>Description:</b></p> <p>Intercom System</p>	
<p><b>Timeline:</b></p> <p>2014-15</p>	<p><b>Cost:</b></p> <p>\$90,000</p>

<p><b>Description:</b></p> <p>PVC Single ply roof: 8 years-fair</p> <p>Built up modified roof: 20 years-poor</p>	
<p><b>Timeline:</b></p> <p>TBD</p>	<p><b>Cost:</b></p> <p>\$851,250</p>