

Project Data

Location Code: 43

Address: 2727 Kate Bond Rd

Year Built: 1993

Grade Configuration: K-5

Student Capacity: 1060/1360

Ideal Capacity: 827

ADA Student Enrollment: 22

Size:

Portables: 15

Building & Additions: 104,260 s. f.

KATE BOND ELEME	
Description: Upgrade to ADA guidelines	EX1001523
Timeline:	Cost:
TBD	\$20,000
Description: Bathroom stall doors are missing.	
Timeline:	Cost:
TBD	\$2,000
Description:	
Ceiling tile and grid in kitchen is old and damaged. Timeline:	Cost:
imeme:	Cusi.

\$1,000

TBD

Description: Interior of school needs painting.	
Timeline:	Cost:
TBD	\$141,000
Description: Replace bleachers in gymnasium	
Timeline:	Cost:
2011-12.	\$104,000
Description: Downspout is damaged.	
Timeline: TBD	\$350

Description:	
Install A/C in gymnasium	
	Picture not available
Timeline:	Cost:

Playground/Surfaces Equipment Status:

Fully equipped Has woodchips with crossties border surface

Playground Equipment / Surface Condition:

Good equipment Good surface No fence enclosure

2013-14



Description:

EPDM Single ply with gravel:

18 years-poor

Built up modified roof:

1 year-good



Timeline:

Cost:

TBD

\$450,000

\$216,000

Crack repair and seal (11,528)sq. yd of asphalt surface	
Timeline:	Cost:
2011-12	\$126,000
Description:	
Replace all HVAC equipment and controls	
	No Picture Available
Timeline:	Cost:
2010-11	\$854,312
Description:	
Kate Bond Elem.	K
Telecor XL	TE O
Installation Date: 1996	B D D D D D D D D D D D D D D D D D D D
Timeline:	Cost:
TRD	\$50,000