



# 2010 FACILITIES ASSESSMENT NORTHSIDE HIGH




<b>Project Data</b>	
<b>Location Code:</b>	144
<b>Address:</b>	1212 Vollintine
<b>Year Built:</b>	1967
<b>Grade Configuration:</b>	9-12
<b>Student Capacity:</b>	1175
<b>Ideal Capacity:</b>	1458
<b>ADA Student Enrollment:</b>	0
<b>Size:</b>	14.26 acres
<b>Portables:</b>	0
<b>Building &amp; Addition</b>	293,868 s. f.


# 2010 FACILITIES ASSESSMENT NORTHSIDE HIGH


<b>Description:</b>  Rusting frames in Kitchen area. Health Department citations result.	
<b>Timeline:</b>  TBD	<b>Cost:</b>  \$5,000

<b>Description:</b>  Dumpster has no enclosure.	
<b>Timeline:</b>  TBD	<b>Cost:</b>  \$5,000

<b>Description:</b>  Sprayed-on Acoustic ceiling in shop area is discolored, overall poor condition. Ceiling material does not contain asbestos.	
<b>Timeline:</b>  TBD	<b>Cost:</b>  \$20,000


# 2010 FACILITIES ASSESSMENT NORTHSIDE HIGH


<p><b>Description:</b></p> <p>Exterior of building needs pressure washing</p>	
<p><b>Timeline:</b></p> <p>TBD</p>	<p><b>Cost:</b></p> <p>\$5,000</p>


<p><b>Description:</b></p> <p>Re-construction of (9,176) sq. yd. of asphalt parking lot</p>	
<p><b>Timeline:</b></p> <p>2009-10</p>	<p><b>Cost:</b></p> <p>\$121,000</p>

<p><b>Description:</b></p> <p>Bring elevator up to ADA compliance</p>	<p style="text-align: center;"><b>No Picture Available</b></p>
<p><b>Timeline:</b></p> <p>2010-11</p>	<p><b>Cost:</b></p> <p>\$71,400</p>


# 2010 FACILITIES ASSESSMENT NORTHSIDE HIGH


<b>Description:</b> Replace auditorium seating	
<b>Timeline:</b> 2012-13	<b>Cost:</b> \$233,200


<b>Description:</b> Replace gymnasium lighting	
<b>Timeline:</b> 2011-12	<b>Cost:</b> \$37,400

<b>Description:</b> Replace auditorium house lighting	
<b>Timeline:</b> 2011-12	<b>Cost:</b> \$45,000

## 2010 FACILITIES ASSESSMENT NORTHSIDE HIGH

<p><b>Description:</b></p> <p>Replace clock/bell system</p>	
<p><b>Timeline:</b></p> <p>2010-11</p>	<p><b>Cost:</b></p> <p>\$34,000</p>

<p><b>Description:</b></p> <p>PVC Single Ply roof: 4 years-good</p>	
<p><b>Timeline:</b></p> <p>TBD</p>	<p><b>Cost:</b></p> <p>\$557,500</p>

<p><b>Description:</b></p> <p>Northside High Dukane 3200 Installation Date: 1994</p>	
<p><b>Timeline:</b></p> <p>TBD</p>	<p><b>Costs:</b></p> <p>\$90,000</p>