

Project Data	
<b>Location Code:</b>	206
Address:	430 Ivan Rd
Year Built:	1959
Grade Configuration:	K-5
Student Capacity:	640/680
Ideal Capacity:	582
ADA Student Enrollment:	0
Size:	15.2 acres
Portables:	0
Building & Addition	68,470 s. f.

Description:	
Window system is old and needs replacing.	
Timeline:	Cost:
TBD	\$650,000
Description:	THE THE PARTY OF T
Existing floor tile contain asbestos and is in poor condition.	
Timeline:	Cost:
TBD	\$78,000
Description: Wooden shelves in pantry	
Timeline:	Cost:

\$4,500

TBD

Description:	
Kitchen vent hood needs fire suppression system.	
Timeline:	Cost:
TBD	\$76,000

TBD	\$76,000
Description:	
Boiler is old, needs replacing	
Timeline:	Cost:
TBD	\$50,000

עעו	\$30,000
<b>Description:</b>	
Dumpsters (2) need enclosures	
Timeline:	Cost:
TBD	\$10,000

Description: Upgrade to ADA guidelines	
Timeline:	Cost:
TBD	\$39,000
Description	
Description:	
Existing 12"x12" ceiling tiles are in poor condition.	
Timeline:	Cost:
TBD	\$12,000
Description:	
Interior of school need painting.	
Timeline:	Cost:
TBD	\$99,000

<b>Description:</b>	
No A/C in kitchen.	
	Picture not available
70°1°	Cont
Timeline:	Cost:
TBD	\$55,000
<b>Description:</b>	
Built up modified roof: 14 years-fair	
14 years-ran	
	3.5
Timeline:	Cost:
TDD	¢202 500
TBD	\$293,500
Description:	
Replace ventilators and domestic water boiler with tank	
Timeline:	Costs:
2012-13	\$2 320 200

Description: Intercom System: Rauland 350 Installation Date: 1985	
Timeline:	Cost:
2010-11	\$50,000