2010 FACILITIES ASSESSMENT

RESIDENTIAL TRAINING CENTER



Project Data		
Location Code:	192	
Address:	3232 East Raines Road	
Year Built:	N/A	
Grade Configuration:	N/A	
Student Capacity:	N/A	
Ideal Capacity:	N/A	
ADA Student Enrollment:	N/A	
Size:	N/A	
Portables:		
Building & Addition		

2010 FACILITIES ASSESSMENT

RESIDENTIAL TRAINING CENTER

Description:	
Dumpster need enclosed.	
Timeline:	Cost:
TBD	\$5,000

Description:	
Window system is old and need replacing	



m: 14	α .
Timeline:	Cost:

TBD \$410,000

Descrip	tion:	The state of the s
See prev	vious item.	

2010 FACILITIES ASSESSMENT

RESIDENTIAL TRAINING CENTER

Description: Stairwell treads have lost their integrity.	
Timeline:	Cost: \$8,500
	1 1 2 9 2 2 2
Description: See previous item.	
Description: No ramp access to facility from east parking area.	
Timeline:	Cost:

\$9,500

TBD

2010 FACILITIES ASSESSMENT RESIDENTIAL TRAINING CENTER

Description: Upgrade to ADA guidelines	
Timeline:	Cost:
TBD.	\$35,000
Description:	
Interior paint in poor to fair condition.	
Timeline:	Cost:
TBD	\$80,000
Description:	
Exterior paint in poor to fair condition.	No picture available
Timeline:	Cost:
TBD	\$40,000

2010 FACILITIES ASSESSMENT RESIDENTIAL TRAINING CENTER

Description:	
PVC single ply roof: 4 years-good	No picture available
Timeline:	Cost:
TBD	\$40,000
Description:	
Intercom System:	R A R III e
Bogen MCP35A	RATIVE SUBSTITUTE OF THE PROPERTY OF THE PROPE
Installation Date: 2005	The - o - ear Uneth
Timeline:	Costs:
TBD	\$50,000