

Project Data		
Location Code:	051	
Address:	260 Joubert	
Year Built:	1952	
Grade Configuration:	K-5	
Student Capacity:	840	
Ideal Capacity:	690	
ADA Student Enrollment:	0	
Size:	12.62 acres share with Riverview Middle	
Portables:	0	
Building & Addition	69,422 s. f.	

	<u>эт / п т лп / п</u>
Description: Some lay-in ceiling tile has water damage.	Contraction of the second seco
Timeline:	Cost:
TBD	\$3,000
Description:	
See previous item	52

Description:	
Covered walkway ceiling paint is in poor condition	
Timeline:	Cost:
TBD	\$6,000

KIVEKVIEVV ELEIVIE	
Description: Restroom does not have a floor drain.	
Timeline:	Cost:
	\$2,000
TBD	\$2,000
Playground/Surfaces Equipment Status: Fully equipped Has cast in place rubber surface	
Playground Equipment / Surface Condition:	
Good equipment Good surface Courtyard not enclosed	

Description:	
Built up roof:	
16 years-poor	
Built up modified roof:	
15 years-poor	- Hart-share have
	4 4
Shingled roof:	
16 years-poor	
Metal roof:	Careford Frederic C
15 years-fair	
Timeline:	Cost:
TBD	\$200,100
עסו	\$299,100

Description:	
Intercom System:	R TU U F
Bogen MCP35A	
Installation Date: 1995	
Timeline:	Costs:
TBD	\$50,000