

## **Department of Procurement Services**

160 South Hollywood Street · Room 126 · Memphis, TN 38112 · (901) 416-5376

## **QUESTIONS AND ANSWERS**

## IFB03082024SD Treadwell Northeast Regional RTU Replacement

1. During the pre-bid meeting a MSCS official told us that the unit was 20-25 tons. The name plate of the unit indicates a unit much larger than 25 tons. Is the replacement unit to match the tonnage of the existing unit or is the need for the project indeed a 20-25 ton unit?

No, match tonnage of the existing unit.

- 2. It was mentioned that a new roof curb was needed. As a matter of clarification, in lieu of a brand-new roof curb down to the deck which would involve new roofing, can the old adapter curb be removed, and a new curb adapter be provided if needed? Yes, a new adapter curb can be used if acceptable by the unit manufacturer.
- 3. RTU is VAV. Does the gas heat need to be modulated?
  2 stage primary heat is required. Modulating will be accepted.
- 4. The existing unit does not have enough room and the economizer/power exhaust hood hits the parapet wall frame. Does the unit need to be shifted some for correction and proper access?

Yes, we do not want the unit hitting the parapet wall.

- 5. Do the separated parapet wall panels need to be repaired and put back together? Yes, please repair the parapet wall panels and assemble them back together.
- 6. Does the new 40-ton RTU need to be 2" double wall with foam insulation? Please follow the MSCS Design Guidelines. The link is attached within the IFB.
- 7. Does the new Seismic curb need to be 18" tall?

  If you are using a new curb, the answer is yes. If you are reusing the existing curb with an adapter, please follow the manufacturer recommendations.
- 8. The Academic Conference does not have supply or return duct and diffusers. Does the space require adding supply and return air duct and diffusers?

  Yes, please add supply and return air duct along with diffusers.
- 9. Does RTU-2 need to be added to the controls upgrade and the BAS? Yes, please add the RTU-2 to the controls upgrade and the BAS.

10. Does the RTU Manufacturer have to provide Factory Startup and 1st year labor warranty?

Yes, please follow the MSCS Design Guidelines. The link is attached within the IFB.

11. What is the quantity of VAVs?

Contractor shall visit site to get an accurate quantity of the VAV boxes. Please call Mr. Rayford (901)490-5135) or Mr. Rudolph (901) 634-3610 to access the building.

12. Does RTU-2 need to be included in the controls price?

Yes, please include the RTU-2 within the control price.

13. Do the 2 MAUs need to be included in the controls price?

Yes, please include the 2 MAUs within the controls price.