December 15, 2024 Facilities Update

Intercom Projects
21 Phase I installations complete.
16 Phase II projects in progress; 4 installations complete, training pending; all equipment
delivered; cabling in progress at 5; 10 switch installs complete

Project BUILD Phase I						
52 total projects; 34 Board approved and in progress						
Remainder estimated to be heard at January 2025 Board meeting						
4 Outdoor athletic lighting projects						
1 Track resurfacing project						
10 LED gym lighting upgrades						
3 Fire system replacements						
3 Foundation repairs						
11 HVAC upgrades						
5 Paving projects						
2 Plumbing projects						
8 Roof replacements						
5 Window replacements						

Ongoing Capital Projects
53 total projects
1 Auditorium renovation
1 Building addition
1 Drainage/Building envelope repair
1 US Dept of Energy Grant (HVAC, Windows, Lighting)
15 Fire alarm upgrades
2 Foundation repair
2 Gym floor projects
7 HVAC Upgrades
12 Intercom replacements
2 New schools
1 Restroom renovation
7 Roof replacements
1 Insurance claim storm repair

Vacancy Report50 total vacancies	

Cleaning Vendor Average Scores				
District average cleaning score	93.0%			
HES	94.9%			
ParCou	91.2%			
Service Master	92.8%			

Work Order Types Sumr	narv
Total Work Orders	5,300
Apparent Mold Growth (AMG)	2
Asbestos	20
Audio Visual	30
Bleachers and Seats	44
Carpentry	349
Carpet Repair	48
Electrical	1454
Elevators	66
Energy Management System	8
Fire Alarm System	210
Fire Extinguishers	42
Fire Sprinkler System	86
Fire Watch	5
Flooring	141
Generators	15
Heating/Ventilation/Air Conditioning	837
Key & Lock	375
Kitchen Hood	8
Masonry	183
Painting	616
Plumbing	433
Roll Up Doors	13
Roofing	133
Shades/Blinds	76
Sheet Metal	59
Vehicle Maintenance	20
Welding	27

December 15, 2024

	December 15, 2024						
PCN	EMPLOYEE_ID	LAST_NAME	FIRST_NAME	JOB_TITLE			
49676	Vacant	Vacant	Vacant	Senior-Construction Manager			
16107	Vacant	Vacant	Vacant	Zone 1A-4B Supervisor			
49805	Vacant	Vacant	Vacant	Carpenter			
49806	Vacant	Vacant	Vacant	Carpenter			
49817	Vacant	Vacant	Vacant	Electrician			
49818	Vacant	Vacant	Vacant	Electrician			
49819	Vacant	Vacant	Vacant	Electrician			
49820	Vacant	Vacant	Vacant	Electrician			
49821	Vacant	Vacant	Vacant	Electrician			
49812	Vacant	Vacant	Vacant	Electrician			
49850	Vacant	Vacant	Vacant	HVAC Technician			
49851	Vacant	Vacant	Vacant	HVAC Technician			
49852	Vacant	Vacant	Vacant	HVAC Technician			
49856	Vacant	Vacant	Vacant	HVAC Technician			
49865	Vacant	Vacant	Vacant	Plumber			
49873	Vacant	Vacant	Vacant	Plumber			
49874	Vacant	Vacant	Vacant	Plumber			
49879	Vacant	Vacant	Vacant	Plumber			
49800	Vacant	Vacant	Vacant	Carpenter Zone 1			
49804	Vacant	Vacant	Vacant	Carpenter Zone 3			
49815	Vacant	Vacant	Vacant	Electrician Zone 1			
49816	Vacant	Vacant	Vacant	Electrician Zone 1			
49813	Vacant	Vacant	Vacant	Electrician Zone 3			
49814	Vacant	Vacant	Vacant	Electrician Zone 3			
21442	Vacant	Vacant	Vacant	Steam - Pipe Fitter			
49854	Vacant	Vacant	Vacant	HVAC Technician Zone 1			
49855	Vacant	Vacant	Vacant	HVAC Technician Zone 1			
49853	Vacant	Vacant	Vacant	HVAC Technician Zone 3			
49878	Vacant	Vacant	Vacant	Plumber Zone 1			
49867	Vacant	Vacant	Vacant	Plumber Zone 3			
49887	Vacant	Vacant	Vacant	Roofer Zone 3			
49783	Vacant	Vacant	Vacant	Sheet Metal Worker Zone 1			
49786	Vacant	Vacant	Vacant	Asbestos Abatement Technicians			
49789	Vacant	Vacant	Vacant	Asbestos Abatement Technicians			
49829	Vacant	Vacant	Vacant	Flooring Technician			
48802	Vacant	Vacant	Vacant	Supervisor Energy Management			
27401	Vacant	Vacant	Vacant	Master HVAC			
49825	Vacant	Vacant	Vacant	Electronics Technicians			
17687	Vacant	Vacant	Vacant	Diesel Mechanic Certified			
21312	Vacant	Vacant	Vacant	Maintenance Technician - Plasterer			
17692	Vacant	Vacant	Vacant	Mechanic I - Certified			
49857	Vacant	Vacant	Vacant	Painter			
48834	Vacant	Vacant	Vacant	SUPERVISOR FLEET MAINTENANCE			
21477	Vacant	Vacant	Vacant	Truck Driver - Maintenance			
49797	Vacant	Vacant	Vacant	Locksmith			
49791	Vacant	Vacant	Vacant	Brick Mason			
48802	Vacant	Vacant	Vacant	Supervisor Energy Management			
38205	Vacant	Vacant	Vacant	Demographer			
18464	Vacant	Vacant	Vacant	Plant Manager			
18436	Vacant	Vacant	Vacant	Plant Manager			
10400	Vacant	Vacant	Vacant	i tunt i unugoi			

De

	024 Weekly Custodial Cleaning Scores HES			ParCou	
Board	Building Name	Average	Board	Building Name	Average
Member		Grade	Member		Grade
Coleman	Admin Getwell Bus Lot	92.0%	McKissack	A. B. Hill E.S.	91.39
Coleman	Admin Knight Road	96.0% 98.9%	Murphy	A. Maceo Walker M.S.	93.69
Porter	Balmoral/Ridgeway E.S	98.9%	Murphy	Admin Bond Bldg. Admin Messick	95.0° 95.3°
Porter Coleman	Belle Forest Community School Colonial M.S.	88.8%	Coleman Murphy	Alcy E.S.	91.29
Murphy	Cromwell E.S	89.6%	Williams	Alton	93.09
Murphy	Crump E.S	96.0%	Murphy	American Way M.S.	91.69
Coleman	Evans E.S	96.0%	McKissack	Bellevue M.S.	94.0
Coleman	Fox Meadows E.S	92.8%	Coleman	Bethel Grove E.S.	96.0
Porter	Germanshire E.S	96.3%	McKissack	Bruce E.S.	81.3
Porter	Germantown E.S	95.0%	McKissack	BT Washington H.S.	91.0
Porter	Germantown H.S.	96.0%	McKissack	Central H.S.	83.0
Porter	Germantown M.S.	94.6%	Coleman	Cherokee E.S.	96.0
Murphy	Getwell E.S	94.0%	Williams	Chickasaw M.S.	93.3
Murphy	Hickory Ridge E.S	96.0%	Love	Delano E.S.	93.69
Porter	Hickory Ridge M.S.	96.0%	Williams	Doubletree E.S.	89.0
Porter	Highland Oaks E.S	100.0%	McKissack	Downtown E.S.	91.7
Porter	Highland Oaks M.S.	99.2%	Coleman	Dunbar E.S.	100.0
Porter	Kirby H.S.	96.0%	Love	E.E. Jeter School	77.6
Porter	Lowrance School	95.2%	Williams	Fairley HS	96.0
Murphy	Newberry E.S	93.6%	Williams	Ford Road E.S.	87.3
Porter	Oak Forest E.S		Love	Frayser-Corning E.S.	94.0
Coleman	Overton H.S.	94.7%	Williams	G.W. Carver College & Career Academy	96.0
Coleman	Parkway Village E.S	92.0%	Murphy	Gardenview E.S.	89.5
Porter	Ridgeway Early Learning Center	100.0% 92.0%	Williams	Geeter School	94.49
Coleman	Ridgeway H.S. Ridgeway M.S.	92.0%	Love	Georgian Hills E.S. Georgian Hills M.S.	84.0
Porter	Ross E.S	98.0%	Love		95.0
Murphy		92.0%	McKissack	Gordon Achievement Academy E.S. Grandview Heights M.S.	99.29
Coleman Coleman	Sea Isle E.S Sheffield Career & Technology Center	96.0%	Love Murphy	Hamilton H.S.	98.79
Coleman	Sheffield E.S	94.0%	Murphy	Hamilton School	80.0
Coleman	Sheffield H.S.	96.0%	Coleman	Hanley School	91.0
Coleman	Shrine School	97.0%	Williams	Havenview M.S.	92.7
Coleman	South Park E.S	92.0%	Williams	Holmes Road E.S.	92.0
Porter	Southwind E.S	94.0%	Murphy	Ida B. Wells Academy	92.19
Porter	Southwind H.S.	94.0%	Murphy	Invictus Academy at Airways	94.7
Coleman	Willow Oaks E.S	93.3%	Williams	J. P. Freeman School	97.6
Coleman	Wooddale H.S.	96.0%		Larose E.S.	
			McKissack		82.0
	Total	94.9%	McKissack Williams	Levi E.S.	
	Total			Levi E.S. Manassas H.S.	90.5° 94.7°
	Total		Williams		90.5°
	Total		Williams McKissack	Manassas H.S.	90.5° 94.7° 88.0° 81.6°
	Total		Williams McKissack Coleman	Manassas H.S. Melrose H.S.	90.5° 94.7° 88.0° 81.6°
	Total		Williams McKissack Coleman Williams	Manassas H.S. Melrose H.S. Mitchell H.S. Norris Achievement Academy M.S. Northaven E.S.	90.5' 94.7' 88.0' 81.6' 97.7' 83.1'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy	Manassas H.S. Melrose H.S. Mitchell H.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S.	90.5' 94.7' 88.0' 81.6' 97.7' 83.1' 85.6'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy	Manassas H.S. Melrose H.S. Mitchell H.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S. Oakhaven H.S.	90.5' 94.7' 88.0' 81.6' 97.7' 83.1' 85.6' 94.0'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Murphy	Manassas H.S. Melrose H.S. Mitchell H.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaven M.S.	90.5' 94.7' 88.0' 81.6' 97.7' 83.1' 85.6' 94.0' 88.0'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Murphy Williams	Manassas H.S. Melrose H.S. Mitchell H.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaven M.S. Oakhaven M.S. Oakshire E.S.	90.5' 94.7' 88.0' 81.6' 97.7' 83.1' 85.6' 94.0' 88.0'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Murphy Williams Williams	Manassas H.S. Melrose H.S. Mitchell H.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaven M.S. Oakshire E.S. Riverview School	90.5' 94.7' 88.0' 81.6' 97.7' 83.1' 85.6' 94.0' 88.0' 94.7'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Murphy Williams Williams Williams	Manassas H.S. Melrose H.S. Mitchell H.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaven M.S. Oakhaire E.S. Riverview School Robert R. Church E.S.	90.5' 94.7' 88.0' 81.6' 97.7' 83.1' 85.6' 94.0' 88.0' 94.7' 92.0' 86.0'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Williams Williams Williams Williams Coleman	Manassas H.S. Melrose H.S. Mitchell H.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaven M.S. Riverview School Robert R. Church E.S. Sharpe E.S.	90.5' 94.7' 88.0' 81.6' 97.7' 83.1' 85.6' 94.0' 94.7' 92.0' 86.0' 91.2'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Williams Williams Williams Williams Coleman	Manassas H.S. Melrose H.S. Mitchell H.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaven M.S. Oakhaven M.S. Aikhire E.S. Riverview School Robert R. Church E.S. Sharpe E.S. Sherwood E.S.	90.5' 94.7' 88.0' 81.6: 97.7' 83.1' 85.6: 94.0' 94.0' 94.7' 92.0' 86.0' 91.2'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Milliams Williams Williams Coleman Coleman	Manassas H.S. Meirose H.S. Mitchell H.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaire E.S. Riverview School Robert R. Church E.S. Sharpe E.S. Sherwood E.S. Sherwood M.S.	90.5' 94.7' 88.0' 81.6: 97.7' 83.1' 85.6: 94.0' 88.0' 94.7' 92.0' 86.0' 91.2' 92.0' 85.6:
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Williams Williams Williams Coleman Coleman McKinney	Manassas H.S. Melrose H.S. Mitchell H.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaire E.S. Riverview School Robert R. Church E.S. Sharpe E.S. Sherwood E.S. Sherwood M.S. Snowden School	90.5' 94.7' 88.0' 81.6' 97.7' 88.0' 85.6' 94.0' 88.0' 94.7' 92.0' 86.0' 91.2' 92.0' 85.6' 88.0'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Williams Williams Williams Williams Coleman Coleman Coleman McKinney Williams	Manassas H.S. Melrose H.S. Mitchell H.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaven M.S. Oakhaven M.S. Oakshire E.S. Riverview School Robert R. Church E.S. Sharpe E.S. Sherwood M.S. Snowden School Southwest Career & Technology Center	90.5' 94.7' 88.0' 81.6' 97.7' 85.0' 94.0' 88.0' 94.0' 92.0' 86.0' 91.2' 92.0' 85.6' 88.0' 92.0'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Williams Williams Coleman Coleman McKinney Williams Williams	Manassas H.S. Meirose H.S. Meirose H.S. Norris Achievement Academy M.S. Norrhaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaven M.S. Oakshire E.S. Riverview School Robert R. Church E.S. Sharpe E.S. Sherwood E.S. Sherwood M.S. Snowden School Southwest Career & Technology Center Trezevant H.S.	90.5 94.7' 88.0' 81.6' 97.7' 83.1' 85.6' 94.0' 94.7' 92.0' 86.0' 91.2' 92.0' 85.6' 85.6' 97.2' 97.2' 97.2' 97.2' 97.2' 97.2' 97.2'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Williams Williams Williams Williams Coleman Coleman McKinney Williams Love Williams	Manassas H.S. Melrose H.S. Melrose H.S. Norris Achievement Academy M.S. Norrhaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaven M.S. Oakshire E.S. Riverview School Robert R. Church E.S. Sharpe E.S. Sherwood E.S. Sherwood E.S. Sherwood M.S. Snowden School Southwest Career & Technology Center Trezevant H.S. Westhaven E.S.	90.5' 94.7' 88.0' 81.6' 97.7' 83.1' 85.6' 94.0' 94.0' 86.0' 92.0' 85.6' 88.0.0 92.0' 92.0' 92.0' 92.0' 92.0' 92.0'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Williams Williams Williams Williams Williams Coleman Coleman Coleman Coleman Coleman Coleman McKinney Williams Love Williams Love	Manassas H.S. Melrose H.S. Melrose H.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S. Oakhaven H.S. Oakshire E.S. Riverview School Robert R. Church E.S. Sharpe E.S. Sherwood E.S. Sherwood M.S. Snowden School Southwest Career & Technology Center Trezevant H.S. Westhaven E.S. Westside E.S.	90.5 94.7 88.0 97.7 83.1 85.6 94.0 94.7 92.0 86.0 91.2 92.0 85.6 88.0 92.0 92.0 92.0 92.0 92.0
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Milliams Williams Williams Williams Coleman McKinney Williams	Manassas H.S. Meirose H.S. Meirose H.S. Norris Achievement Academy M.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaven M.S. Oakshire E.S. Riverview School Robert R. Church E.S. Sharpe E.S. Sherwood E.S. Sherwood M.S. Sowden School Southwest Career & Technology Center Trezevant H.S. Westhaven E.S. Westhaven E.S. Westwood H.S.	90.5' 94.7' 88.0' 81.6' 97.7' 83.1' 85.6' 94.7' 92.0' 94.0' 91.2' 92.0' 85.6' 88.0' 92.0' 92.0' 92.0' 100.0'
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Williams Williams Williams Coleman Coleman McKinney Williams Love Williams Williams Love Williams Williams	Manassas H.S. Melrose H.S. Melrose H.S. Norris Achievement Academy M.S. Norrhaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaven M.S. Oakshire E.S. Riverview School Robert R. Church E.S. Sharpe E.S. Sherwood E.S. Sherwood E.S. Sherwood H.S. Westhaven E.S. Westside E.S. Westside E.S. Westwood H.S. Whitehaven E.S.	90.5° 94.7° 88.0° 81.6° 97.7° 83.1° 88.0° 94.0° 88.0° 94.0° 88.0° 91.2° 92.0° 85.6° 88.0° 92.0° 92.0° 92.0° 100.0° 100.0°
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Williams Williams Williams Williams Coleman Coleman McKinney Williams Love Williams Love Williams Love Williams Williams Love Williams Williams Williams Williams Williams Williams Williams Williams Williams	Manassas H.S. Melrose H.S. Melrose H.S. Norris Achievement Academy M.S. Norrhaven E.S. Oakhaven E.S. Oakhaven H.S. Oakshire E.S. Cakshire E.S. Cakshire E.S. Sharve W.S. Sharpe E.S. Sherwood E.S. Sherwood M.S. Snowden School Southwest Career & Technology Center Trezevant H.S. Westhaven E.S. Westwood H.S. Westhaven E.S. Westwood H.S. Whitehaven E.S.	90.5° 94.7° 88.0° 81.6° 97.7° 83.1° 85.6° 94.0° 88.0° 94.7° 92.0° 86.0° 91.2° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0°
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Milliams Williams Williams Williams Coleman Coleman Coleman Coleman Coleman Coleman Williams Unitiams Williams Williams Williams Williams Love Williams Williams Williams Williams	Manassas H.S. Melrose H.S. Melrose H.S. Norris Achievement Academy M.S. Norris Achievement Academy M.S. Northaven E.S. Oakhaven E.S. Oakhaven H.S. Oakhaven M.S. Oakshire E.S. Riverview School Robert R. Church E.S. Sharpe E.S. Sherwood E.S. Sherwood M.S. Sherwood H.S. Showden School Southwest Career & Technology Center Trezevant H.S. Westhaven E.S. Westwood H.S. Whitehaven E.S. Whitehaven E.S.	90.5° 94.7° 94.7° 88.0° 81.6° 97.7° 88.0° 94.0° 88.0° 92.0° 86.0° 92.0° 85.6° 92.0° 100.0° 100.0° 92.0° 86.3°
	Total		Williams McKissack Coleman Williams Murphy Love Murphy Murphy Williams Williams Williams Williams Coleman Coleman McKinney Williams Love Williams Love Williams Love Williams Williams Love Williams Williams Williams Williams Williams Williams Williams Williams Williams	Manassas H.S. Melrose H.S. Melrose H.S. Norris Achievement Academy M.S. Norrhaven E.S. Oakhaven E.S. Oakhaven H.S. Oakshire E.S. Cakshire E.S. Cakshire E.S. Sharve W.S. Sharpe E.S. Sherwood E.S. Sherwood M.S. Snowden School Southwest Career & Technology Center Trezevant H.S. Westhaven E.S. Westwood H.S. Westhaven E.S. Westwood H.S. Whitehaven E.S.	90.5° 94.7° 88.0° 81.6° 97.7° 83.1° 85.6° 94.0° 88.0° 94.7° 92.0° 86.0° 91.2° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0° 92.0°

	Service Master	
Board	Building Name	Average
Member		Grade
McKissack	Admin BOE/COE	92.0% 96.0%
McKissack	Admin Flicker St Clinic Admin North Area Office/TTC/Gragg	99.0%
McKinney McKinney	Admin SCS HQ (Bayer)	83.8%
McKissack	Admin SCS Welcome Center	94.0%
McKissack	Admin Teachers Learning Academy	96.0%
Huett-Garcia	Avon School	95.2%
Huett-Garcia	Barret's Chapel School	96.0%
McKinney	Berclair E.S.	88.0%
Huett-Garcia	Bolton H.S.	88.0%
Love	Brownsville Road E.S.	92.8%
Otey	Chimneyrock E.S.	97.6%
Otey	Cordova E.S.	93.2%
Otey	Cordova H.S.	91.0%
Otey	Cordova M.S. Covington Pike Head Start	92.0% 97.0%
McKinney	Craigmont H.S.	84.0%
McKinney McKinney	Craigmont M.S.	98.7%
McKissack	Cummings School	96.0%
Huett-Garcia	Dexter E.S.	90.7%
Huett-Garcia	Dexter M.S.	94.0%
McKinney	Douglass H.S.	94.0%
McKinney	Douglass Head Start	94.7%
McKinney	Douglass School	89.0%
Huett-Garcia	East H.S./Maxine Smith STEAM Academy	93.0%
Love	Egypt E.S.	92.0%
Huett-Garcia	Grahamwood E.S.	89.9%
Love	Hawkins Mill	82.7%
McKissack	Idlewild E.S.	89.3%
McKinney	Jackson E.S.	95.0%
McKinney	Kate Bond E.S.	91.9%
McKinney	Kate Bond M.S. Keystone E.S.	96.0% 91.7%
Love McKinney	Kingsbury Career & Technology Center	97.0%
McKinney	Kingsbury E.S.	98.0%
McKinney	Kingsbury H.S.	94.7%
McKinney	Kingsbury M.S.	96.8%
Love	Lucie E. Capbell E.S.	89.6%
Otey	Lucy E.S.	94.7%
McKissack	Macon-Hall E.S.	79.2%
Otey	Middle College H.S.	96.0%
McKinney	Mt Pisgah M.S.	98.0%
McKissack	Northeast Prep Academy	100.0%
Love	Peabody E.S.	95.4%
Love	Raleigh Barlett Meadows E.S.	87.0%
Unatt Com	Raleigh-Egypt H.S. Raleigh-Egypt M.S.	93.0% 88.0%
Huett-Garcia Otey	Richland E.S.	99.2%
McKissack	Riverwood E.S.	82.7%
Love	Rozelle E.S.	91.3%
Huett-Garcia	Scenic Hills E.S.	90.1%
Huett-Garcia	Shady Grove	99.2%
McKinney	Shelby Oaks E.S.	90.7%
McKinney	Springdale E.S.	96.0%
McKinney	Treadwell E.S.	92.0%
Love	Treadwell M.S./Northeast RegOff	92.0%
McKinney	Trezevant Career & Technology Center	98.6%
McKinney	Vollentine E.S. Wells Station E.S.	91.3%
Huett-Garcia	Wells Station E.S. White Station E.S.	100.0% 88.8%
Huett-Garcia Huett-Garcia	White Station E.S. White Station H.S.	86.0%
McKinney	White Station M.S.	96.0%
Love	William Herbert Brewster E.S.	91.7%
	Woodstock M.S.	92.8%
	Total	92.8%

December 15, 2024 Work Orders								
Source Location	Created On	Assigned To Last Name	Problem	Work Order #	Work requested			
A. B. Hill Elementary	12/10/2024 12:19	ARNOLD	Carpentry	Z4-044292	Outside door in the boiler room not closing properly.			
A. B. Hill Elementary	12/10/2024 12:54	HALL	Electrical	Z4-044317	Smoke detector hanging off			
A. B. Hill Elementary	12/10/2024 12:51		Electrical	Z4-044314	Riser missing wrench and spare sprinkler heads.			
A. B. Hill Elementary	12/10/2024 12:41		Electrical	Z4-044305	Fire alarm breaker needs to be lock out.			
A. B. Hill Elementary	10/2/2024 9:11	CALDWELL	Elevators	Z4-035851	e have someone come out to fix elevator, due to we have wheelchair kids in the building. Thank you			
A. B. Hill Elementary	12/10/2024 13:25		Fire Sprinkler System	Z4-044327	Need 5year inspections and test			
A. B. Hill Elementary	12/10/2024 12:32		Fire Sprinkler System	Z4-044301	Sprinkler heads needs a cover over it.			
A. B. Hill Elementary	5/31/2024 12:17	CALDWELL	Fire Sprinkler System	Z4-016731	Need sprinkler ring. Thanks			
					HVAC UNIT IN RM N123 - NOT COMING ON PM/TAYLOR 416-7844			
A. B. Hill Elementary	11/15/2024 7:33	WILSON	Heating/Ventilation/Air Conditioning	Z4-040989				
A. B. Hill Elementary	3/28/2024 15:39	CORONADO	Masonry	WO1004139	Please replace broken and cracked tile near freezer. (Tripping Haz). Thanks			
A. B. Hill Elementary	9/16/2024 13:24	BURCHETT	Painting	Z4-032983	Plaster is falling down in the Library. Thanks			
A D Hill Flomenton	9/19/2024 8:12	FINNIE	Dlumbing	Z4-033569	Water pouring down			
A. B. Hill Elementary A. B. Hill Elementary	11/14/2024 12:40	GILL	Plumbing	Z4-033569 Z4-040869	Poof looking			
A. B. Hill Elementary	11/14/2024 12.40	GILL	Roofing	24-040809	Roof leaking. Roof leak in classroom.			
A. B. Hill Elementary	11/14/2024 12:38	GILL	Roofing	Z4-040868	noor teak iii classroom.			
A. B. Hill Elementary	12/10/2024 13:02	SMITH	Sheet Metal	Z4-044319	Please clean dryer vent hose line and vent.			
A. B. Hill Elementary	11/5/2024 9:40	TEDDER	Sheet Metal	Z4-039580	Principal is requesting a fence placed around both dumpsters for safety purposes. Thanks			
A. B. Till Elementary	11/0/2024 0.40	TEDDEN	onectricut	24 000000	Timespacia requesting a renee placed around boar damps cas for surely purposes. Thanks			
					Please re-attach the chain link handrail on the right-hand side of the bleachers (home side)			
A. Maceo Walker Middle	8/29/2024 10:59	CALDWELL	Bleachers and Seats	Z4-030253				
					Please replace the missing door window trim that secures the windowpane in place.			
A. Maceo Walker Middle	10/30/2024 10:02	FORD	Carpentry	Z4-038873				
A. Maceo Walker Middle	8/1/2024 10:46	STAFFORD	Carpentry	Z4-024393	Please install a 4x4 bulletin board			
A. Maceo Walker Middle	12/13/2024 7:23	HALL	Electrical	Z4-044804	Please replace the blown ballast handicap stall			
					Please replace the blown light bulbs in the gym			
A. Maceo Walker Middle	10/17/2024 10:10	HALL	Electrical	Z4-037351				
					replace the batteries in exit lights #54 & #56			
A. Maceo Walker Middle	10/7/2024 13:52	HALL	Electrical	Z4-036509				
A Magas Walker Middle	10/7/2024 12:51	HALL	Floatrical	74 020500	Replace battery in exit light# 16			
A. Maceo Walker Middle	10/7/2024 13:51	HALL	Electrical	Z4-036508	replace battery in exit light #49			
A. Maceo Walker Middle	10/7/2024 13:49	HALL	Electrical	Z4-036507	replace buttery in exit agric 140			
711 Tubbo Wallor Finance	10///2024 10:40	10122	Elootiloat	24 000007	replace batteries in exit lights #45,#46,#47			
A. Maceo Walker Middle	10/7/2024 13:48	HALL	Electrical	Z4-036506				
					replace battery in exit light 10			
A. Maceo Walker Middle	10/7/2024 13:47	HALL	Electrical	Z4-036505				
					replace emergency light batteries in units #10, #6 & #7			
A. Maceo Walker Middle	10/7/2024 13:43	HALL	Electrical	Z4-036504				
					Replace exit light battery in the band room #34			
A. Maceo Walker Middle	10/7/2024 13:41	TEDDER	Electrical	Z4-036503				
					Battery replacement at exit light #23			
A. Maceo Walker Middle	10/7/2024 13:34	HALL	Electrical	Z4-036502				
				7	Please replace back-up battery in exit light #21			
A. Maceo Walker Middle	10/7/2024 13:32	HALL	Electrical	Z4-036498	Dalarra Okara Erika			
A. Maceo Walker Middle	10/3/2024 9:21	CHALK	Electrical	Z4-036036	Relamp Stage lights			
A. Maceo Walker Middle	8/13/2024 10:44	HALL	Electrical		ll of our stage spot lights are out (none of them will come on, possible issue with the controller)			
A. Placeo Walker Pliquie	0/13/2024 10:44	TIALL	Liectricat	24-02/200	Replace receptacles with GFIC where needed			
A. Maceo Walker Middle	4/29/2024 11:48	CHALK	Electrical	Z4-011991	replace receptacies with or to where needed			
					Bleachers are not working in the Gym			
A. Maceo Walker Middle	3/25/2024 11:48	HALL	Electrical	Z4-006152	, , , , , , , , , , , , , , , , , , ,			
A. Maceo Walker Middle	2/3/2024 16:12	HALL	Electrical	WO1024783	le and wall mounted overhead exterior lights that have blown bulbs around the front side and rear parking lot			
					Our elevator is malfunctioning without depressing any buttons (continues to go up and			
					down non-stop without stopping)			
A. Maceo Walker Middle	12/3/2024 9:50	CALDWELL	Elevators	Z4-042811				
					Fire panel is in trouble mode (power supply negative earth ground card 2)			
A. Maceo Walker Middle	9/19/2024 10:08	CALDWELL	Fire Alarm System	Z4-033683				

please perform an indoor air quality test N-215 has a very heavy mold/mildew smell.

Light fixtures needs to be repaired dark at this entry

					placed perform an inacer an quality test in 220 has a very moury mountains.
A. Maceo Walker Middle	6/12/2024 10:00	FINNIE	Heating/Ventilation/Air Conditioning	Z4-018136	Inspected by EH&S Manager on 6/27/24. Please Check the HVAC drain pan for mildew.
					Please cut an interior GMA key for Assistant Principal Ford (It's broken, and I have the key)
A. Maceo Walker Middle	10/3/2024 6:55	MALONE	Key & Lock	Z4-035984	Please re-stripe the parking lot and paint designated areas.
A. Maceo Walker Middle	10/3/2024 6:59	BURCHETT	Painting	Z4-035985	Please paint classroom N-118
A. Maceo Walker Middle	5/21/2024 9:38	BURCHETT	Painting	Z4-015401	please paint the top portion of the tar stained wall in the band room.
A. Maceo Walker Middle	3/19/2024 8:58	BURCHETT	Painting	Z4-005343	
					Please paint the top portion of the tar stained wall in the cafeteria (from a major roof leak)
A. Maceo Walker Middle	3/19/2024 8:57	BURCHETT	Painting	Z4-005341	
A. Maceo Walker Middle	12/13/2024 7:24	HARRIS	Plumbing	Z4-044807	Please replace the damaged wax ring middle stall please replace the broken lavatory faucet
A. Maceo Walker Middle	10/30/2024 10:03	HARRIS	Plumbing	Z4-038874	
	0.0.000.17.40			7	Please replace the water filter on bottle filler (no cut off valve)
A. Maceo Walker Middle	8/9/2024 7:49	HARRIS	Plumbing	Z4-026558	places replace the 2rd toilet in the girls restroom (erselved persolain hour)
A. Maceo Walker Middle	5/3/2024 10:00	HARRIS	Plumbing	Z4-012966	please replace the 3rd toilet in the girls restroom (cracked porcelain bowl)
A. Flaces Walker Fladie	0/0/2024 10:00	Trattio	i turnomg	24 012500	help roofer
A. Maceo Walker Middle	10/23/2024 12:24	ANDERSON	Roofing	Z4-038020	
			_		please repair the roof leak in the hallway outside of he cafeteria
A. Maceo Walker Middle	9/16/2024 8:57	STEVENSON	Roofing	Z4-032835	
					please repair the roof leak in the main office
A. Maceo Walker Middle	9/16/2024 8:10	STEVENSON	Roofing	Z4-032804	
					please repair the roof leak in the media hall
A. Maceo Walker Middle	9/16/2024 8:08	STEVENSON	Roofing	Z4-032803	please repair the reaf leak in the media center office
A. Maceo Walker Middle	9/16/2024 8:07	STEVENSON	Roofing	Z4-032801	please repair the roof leak in the media center office
Administration Building (Avery)	12/12/2024 14:04	STEVENSON	Asbestos	Z2-044763	Wall peeling crack walls
Administration Building (Avery)	12/12/2024 14:04		Asbestos	Z2-044763 Z2-044762	Wall peeling dust
Administration Building (Avery)	12/12/2024 14:03		Asbestos	Z2-044762 Z2-044760	Wall cracking and peeling very bad personnel concern about dust
Administration Building (Avery)	12/4/2024 14:43	STAFFORD	Carpentry	Z2-044700 Z2-043401	Walt cracking and peeting very bad personner concern about dust Walt repair holes
Administration Building (Avery)	11/19/2024 7:41	ROY	Carpentry	Z2-043401 Z2-041391	Bottom hinge off
Administration Building (Avery)	12/4/2024 12:03	POWELL	Electrical	Z2-043353	Wall switch loose not making good contact
Administration Building (Avery)	12/4/2024 11:54	POWELL	Electrical	Z2-043347	Replace light ballast
Administration Building (Avery)	12/3/2024 11:45	POWELL	Electrical	Z2-042919	Light ballast replacement green dot front desk
Administration Building (Avery)	12/3/2024 11:03	POWELL	Electrical	Z2-042888	Hallway in lobby in front of room A
Administration Building (Avery)	12/2/2024 8:31	POWELL	Electrical	Z2-042000 Z2-042280	Replace exits signs lights near gym door
Administration Building (Avery)	11/25/2024 10:45	POWELL	Electrical	Z2-042173	Light ballast out and cover fell off replace cover
Administration Building (Avery)	11/22/2024 14:44	POWELL	Electrical	Z2-042116	Wall receptor replacement
Administration Building (Avery)	11/22/2024 14:43	POWELL	Electrical	Z2-042115	Wall receptor cracked
Administration Building (Avery)	11/22/2024 14:42	POWELL	Electrical	Z2-042113	Wall receptor cracked
Administration Building (Avery)	11/22/2024 14:18	POWELL	Electrical	Z2-042105	Replace light ballast
Administration Building (Avery)	11/22/2024 13:17	POWELL	Electrical	Z2-042088	Replace light LED two lights out
Administration Building (Avery)	11/22/2024 10:35	POWELL	Electrical	Z2-042062	Ballast out yellow dot
Administration Building (Avery)	11/21/2024 8:09	POWELL	Electrical	Z2-041839	Light ballast causing light to flicker place yellow dot on light
Administration Building (Avery)	11/18/2024 14:07	POWELL	Electrical	Z2-041345	Wall receptor out near plaque
Administration Building (Avery)	11/18/2024 14:04	POWELL	Electrical	Z2-041343	Breaker keep tripping Tiger woods sign at the door room 88
Administration Building (Avery)	11/18/2024 6:15	POWELL	Electrical	Z2-041156	Two outside lights near chiller out
Administration Building (Avery)	11/15/2024 9:23	POWELL	Electrical	Z2-041032	Wall receptacles not working
Administration Building (Avery)	11/13/2024 8:32	POWELL	Electrical	Z2-040572	Light ballast out through out office door entry
Administration Building (Avery)	11/6/2024 6:32	POWELL	Electrical	Z2-039661	Light ballast
Administration Building (Avery)	11/6/2024 6:21	POWELL	Electrical	Z2-039659	Light ballast out
Administration Building (Avery)	11/6/2024 6:18	POWELL	Electrical	Z2-039658	Ballast out near landing
Administration Building (Avery)	11/5/2024 8:05	POWELL	Electrical	Z2-039545	Ballast out in office first light near hallway
Administration Building (Avery)	9/30/2024 20:59	POWELL	Electrical	Z2-035556	Four ballast out in this area, changed bulbs
Administration Building (Avery)	0/30/2024 6:37	DOW/ELL	Electrical	72-035360	Light fixtures peads to be repaired dark at this entry

Electrical

Z2-035269

Administration Building (Avery)

9/30/2024 6:37

POWELL

Administration Building (Avery)	9/30/2024 6:34	POWELL	Electrical	Z2-035264	Light fixture needs to be replaced very dark at entry point.
Administration Building (Avery)	7/16/2024 12:56	POWELL	Electrical	Z2-021394	Five ballast out in this office suite
Administration Building (Avery)	5/10/2024 7:16	POWELL	Electrical	Z2-013982	Basement hallway seven lights ballast out
Administration Building (Avery)	12/16/2024 8:30	TOWELL	Elevators	Z2-044980	Elevator not working again
Administration building (Avery)	12/10/2024 0:00		Elevators	22 044500	Elevator not working again
					Freight elevator has stopped working. Elevator is nonresponsive to any commands.
Administration Building (Avery)	10/14/2024 12:49	Coleman	Elevators	Z2-036880	······································
Administration Building (Avery)	3/5/2024 6:30	Coleman	Elevators	Z2-003862	Freight elevator is not working
Administration building (Avery)	0/0/2024 0.00	Coteman	Elevators	22 000002	A/C blowing hot air in several rooms
Administration Building (Avery)	10/30/2024 12:01	BALLARD	Energy Management System	Z2-038931	70 O Blowning Hot all III Several Tooliis
Administration Building (Avery)	10/29/2024 10:08	LEWIS	Fire Extinguishers	Z2-038693	25 Sign for fire extinguishers
Administration Building (Avery)	12/12/2024 9:10	HANSON	Heating/Ventilation/Air Conditioning	Z2-030093 Z2-044586	Heater not working
			-		
Administration Building (Avery)	12/12/2024 13:51	MALONE	Key & Lock	Z2-044759	Dr Jones office need a key for door lock
Administration Building (Avery)	12/3/2024 10:09	SCHAEFFER	Key & Lock	Z2-042846	Inner office key duplicate plant manager does not have key
Administration Building (Avery)	5/10/2024 7:28	CORONADO	Masonry	Z2-013992	Broken steps needs to be repaired
Administration Building (Avery)	3/28/2024 15:49	CORONADO	Masonry	WO979973	There a big crack in the wall outside the restroom. please repair, plaster wall
Administration Building (Avery)	11/22/2024 14:36	BURCHETT	Painting	Z2-042111	Outside office door needs painting
Administration Building (Avery)	9/17/2024 11:41	BURCHETT	Painting	Z2-033208	Hole in Security Managers office, needs to be repaired and painted
					Wall need to be repaired and painted, plaster has fallen and damaged this area
Administration Building (Avery)	9/13/2024 9:36	DIXON	Painting	Z2-032568	
Administration Building (Avery)	7/2/2024 6:43	BURCHETT	Painting	Z2-020017	Window need's plastering and painted.
Administration Building (Avery)	5/3/2024 17:11	BURCHETT	Painting	Z2-013038	Hole in the wall needs to be repaired and wall needs to be painted.
Administration Building (Avery)	2/22/2024 13:30	BURCHETT	Painting	Z2-002509	This lady's restroom needs to be painted
Administration Building (Avery)	11/15/2024 9:20	STAFFORD	Plumbing	Z2-041029	Drain unclogged front entrance
					PIPE IN THE BOILER RM - BUSTED PM/STRICKLAND 416-5793
Administration Building (Avery)	4/18/2024 7:32	SEMLER	Plumbing	Z2-010075	
Administration Building (Avery)	12/9/2024 13:24	WHITE	Sheet Metal	Z2-044090	Panels coming off track to overhead door
					make urinal screen for plumber
Administration Building (Avery)	10/23/2024 7:18	WHITE	Sheet Metal	Z2-037911	
0, 0,					clean up around shop
Administration Building (Avery)	9/9/2024 14:33	WHITE	Sheet Metal	Z2-031604	·
3(),					repair duct from water boiler in basement
Administration Building (Avery)	8/14/2024 7:45	WHITE	Sheet Metal	Z2-027385	
rammonation banamig (rivery)	0/1-1/2024 /140	*******	SHOOT ISLAT	22 027000	change over welder and tools to new truck
Administration Building (Avery)	12/12/2024 7:28	CARLOS	Welding	Z2-044532	
Alcy Elementary	8/21/2024 11:29	CALDWELL	Bleachers and Seats	Z4-028902	I have bleachers need bolts seat are loosening
Alcy Elementary	12/10/2024 16:46	FORD	Carpentry	Z4-044364	Door not latching
Alcy Elementary	12/1/2024 15:24	FORD	Carpentry	Z4-042193	Partition need replacing
Alcy Elementary	8/27/2024 13:24	HALL	Electrical	Z4-042193 Z4-029853	
	7/1/2024 9:48	HALL	Electrical	Z4-029853 Z4-019913	Receptacle to promethan board not working Storage rm need light replaced
Alcy Elementary	7/1/2024 9.46	HALL	Electricat	24-019913	Overhead light fixture need replacing
Alex Flores and an	7/1/2024 9:41	HALL	Electrical	Z4-019907	Overnead light lixture need replacing
Alcy Elementary					a la mare a la l
Alcy Elementary	5/3/2024 8:26	HALL	Electrical	Z4-012921	Overhead light fixture need replacing
					Led light out
Alcy Elementary	3/19/2024 7:25	HALL	Electrical	Z4-005308	
					Light out
Alcy Elementary	3/12/2024 12:56	HALL	Electrical	Z4-004927	
Alcy Elementary	8/23/2024 15:16	CALDWELL	Elevators	Z4-029341	Elevator not woriking
Alcy Elementary	3/28/2024 15:46	CASEY	Flooring	WO1012842	damaged carpet water fountain burst
					Mr. hancock 63674 not coming on at all
Alcy Elementary	12/3/2024 11:58	DOWNER	Heating/Ventilation/Air Conditioning	Z4-042942	
Alcy Elementary	9/25/2024 9:10	BURCHETT	Masonry	Z4-034605	Classroom has crack in wall
Alcy Elementary	9/5/2024 8:06	BURCHETT	Masonry	Z4-031021	Crack in wall need repair
Alcy Elementary	2/23/2024 13:50	CORONADO	Masonry	Z4-002714	ceramic tile need repair from water fountain removal
Alcy Elementary	11/18/2024 4:39	BURCHETT	Painting	Z4-041154	handrails need painting
Alcy Elementary	11/12/2024 10:22	BURCHETT	Painting	Z4-040438	Wall needs painting
Alcy Elementary	5/30/2024 12:01	BURCHETT	Painting	Z4-016510	Needs to be mudded painted will need lift
Alcy Elementary	3/28/2024 15:49	BURCHETT	Painting	WO996683	handrails need painting
Alcy Elementary	12/5/2024 8:56	JOHNSON	Plumbing	Z4-043485	Bradley sink leaking
Alcy Elementary	8/13/2024 11:00	JOHNSON	Plumbing	Z4-027270	hand sink has no cold water
Alcy Elementary	12/3/2024 16:43	TEDDER	Roofing	Z4-043061	Metal roof leaking active
Alcy Elementary	12/3/2024 16:43	TEDDER	Roofing	Z4-043061 Z4-043060	Metal roof has leak active
Alcy Elementary	12/1/2024 15:27	LESSEN	Roofing	Z4-043000 Z4-042195	Roof leak by. Window
Aloy Elementary	12/1/2024 10/2/		Noning	L- 0-2100	HOOF CORE DY. WIIIIUUW

Alton (Security Training Academy)	8/1/2024 11:26	HALL	Electrical	Z4-024421	Need balancer license have been changed
Alton (Security Training Academy)	8/1/2024 9:35	HALL	Electrical	Z4-024320	Need balancer license have been changed
Alton (Security Training Academy)	8/1/2024 9:26	HALL	Electrical	Z4-024307	Need cover for light fixture
American Way Middle	6/18/2024 14:58	CALDWELL	Bleachers and Seats	Z4-018826	Maintenance and operation of folding and telescopic seating
					Outlet has sparked overnight, nothing was plugged into
American Way Middle	8/13/2024 12:11	HALL	Electrical	Z4-027296	Dealers are the least the OFIO where are ded
American Way Middle	4/29/2024 11:49	CHALK	Electrical	Z4-011992	Replace receptacles with GFIC where needed
American Way Middle	4/29/2024 11:49	CHALK	Electrical	24-011992	
					Fire alarm will not sound, double doors will close, lights flash but no sound from alarm
American Way Middle	11/1/2024 8:54	CALDWELL	Fire Alarm System	Z4-039204	The dam without sound, doubte doors with close, agrics leash but no sound from dami
7 mionean Tray i nade	11/1/2024 0104	0/12511222	i ne mann eyetem	27 000207	Fire panel have codes PIV SW Tamper
American Way Middle	6/18/2024 14:54	CALDWELL	Fire Sprinkler System	Z4-018825	
American Way Middle	6/18/2024 14:47	CALDWELL	Fire Sprinkler System	Z4-018822	Replace missing sprinkler heads
American Way Middle	3/4/2024 13:23	CASEY	Flooring	Z4-003779	Principal requests carpet be removed
American Way Middle	3/28/2024 15:46	CASEY	Flooring	WO999621	Carpet needs to be removed from office
American Way Middle	5/8/2024 10:27	CALDWELL	Generators	Z4-013673	Power outage April 17th, generator did not activate.
					HEATING UNIT IN RM D212 - BLOWING COLD AIR PM/CHOICE 416-1250
American Way Middle	12/13/2024 9:37	WRIGHT	Heating/Ventilation/Air Conditioning	Z4-044862	
					F201b and F201b storage rooms will not open, we have the key but the doors will not unlock
American Way Middle	11/1/2024 9:35	MALONE	Key & Lock	Z4-039227	
					Key hole came out
American Way Middle	10/29/2024 10:12	MALONE	Key & Lock	Z4-038696	
American Way Middle	5/8/2024 10:19	SMITH	Key & Lock	Z4-013666	Master B key for plant manager has broken
American Way Middle	4/5/2024 14:18	CORONADO	Masonry	Z4-007967	Plaza floor by library needs new floor tile
					Damage caused by leak
American Way Middle	9/25/2024 12:49	BURCHETT	Painting	Z4-034677	Demosts several hadrades
	0.05.00044045			74.004070	Damage caused by leaks
American Way Middle	9/25/2024 12:45	BURCHETT	Painting	Z4-034676	Crean string on hallway peeds pointing
American Way Middle	7/25/2024 10:33	BURCHETT	Painting	Z4-022566	Green stripe on hallway needs painting
American way Middle	//25/2024 10.33	BURGHEII	Painting	24-022566	
					First toilet left side is clogged, had been plunged and snaked but remains clogged
American Way Middle	12/11/2024 10:59	JOHNSON	Plumbing	Z4-044466	r not tollet talt olda la ologged, had been planged and elialisa bat remains clogged
,					
					First stall on the left is clogged, it's been plunged and snaked but remains clogged
American Way Middle	12/11/2024 10:55	JOHNSON	Plumbing	Z4-044465	
					Third stall leaks at bottom of pipe when flushed
American Way Middle	11/20/2024 11:55	JOHNSON	Plumbing	Z4-041739	
					Leak in ceiling by window
American Way Middle	11/6/2024 10:37	GILL	Roofing	Z4-039837	
					Ceiling leaking
American Way Middle	11/6/2024 10:35	GILL	Roofing	Z4-039835	
					Leak in ceiling
American Way Middle	11/6/2024 10:33	GILL	Roofing	Z4-039834	
					Leak in ceiling
American Way Middle	11/6/2024 10:28	GILL	Roofing	Z4-039826	
A	0/05/000440-00	GILL	Danifier #	74 00 4070	Leak in cafeteria
American Way Middle Avon School	9/25/2024 12:29 10/14/2024 15:09	Coleman	Roofing Fire Alarm System	Z4-034672 Z2-036923	I need all of the old batteries replaced in Avon's fire alarm systems.
AVOIT SCHOOL	10/14/2024 15.09	Coteman	File Ataliii Systelli	22-030923	Theed all of the old batteries replaced in Avon's fire alarm systems.
					I need a key made for Room 214 and two master keys for the PLC and Financial Secretary.
Avon School	11/6/2024 11:07	MALONE	Key & Lock	Z2-039854	Thouse a nay made for hoom 224 and the made nayers and the field and manual cooledary.
			, 2 200		Paint has begun peeling from the walls after a pipe burst in the kitchen manager's office. I
					need this to be handle as soon as possible.
Avon School	2/14/2024 8:55	BRYANT	Painting	Z2-001358	
			-		black board need to be removed
B. T. Washington High	8/20/2024 10:33		Carpentry	Z1-028628	
					blackboard need to be removed from wall disgarded them
B. T. Washington High	3/26/2024 9:26	RUSSELL	Carpentry	Z1-006310	
					unbold windows [poca]
B. T. Washington High	3/13/2024 15:14	RUSSELL	Carpentry	Z1-005028	

B. T. Washington High	3/5/2024 12:07	CASEY	Carpentry	Z1-004035	no noda opodat dat tonot in natinajo
D. 1. Washington riigh	3/3/2024 12:07	CASEI	Carpentry	21-004033	outlet are out in this room
B. T. Washington High	12/3/2024 15:10	ANDREWS	Electrical	Z1-043049	outlet all o out in this room
					OUTLET'S ARE NOT WORKING BREAKERS ARE TRIPPING
B. T. Washington High	12/2/2024 13:33	ANDREWS	Electrical	Z1-042566	
0 0					trouble smoke beam atrium 2nd foor main also ahu 1d supply
B. T. Washington High	11/20/2024 14:14	GREER	Fire Alarm System	Z1-041780	
					hole in floor in the back
B. T. Washington High	11/20/2024 9:26	RUSSELL	Flooring	Z1-041654	
					floor has hole in court
B. T. Washington High	9/10/2024 7:04	LEWIS	Flooring	Z1-031634	
					Mr. hubbard, 67240 unit leaking
B. T. Washington High	10/31/2024 10:51	WEBB	Heating/Ventilation/Air Conditioning	Z1-039079	
					REPLACE UNIT VENT DOOR
B. T. Washington High	10/23/2024 13:40	WEBB	Heating/Ventilation/Air Conditioning	Z1-038035	
					AHU #6 NOT COOLING (WAITING ON 5 OF THE 6 MOTORS TO COME IN)
B. T. Washington High	10/8/2024 6:21	WEBB	Heating/Ventilation/Air Conditioning	Z1-036547	
5.7.11.11.11.11.11	F 10.1 10.00 1.0 F.O.	BUBBUETT		74 045447	building brick are fallen off
B. T. Washington High	5/21/2024 9:53	BURCHETT	Masonry	Z1-015417	Allahad assas afficiall
D. T. Marchinester allies	4/4/00040-40	000011400	Manager	74 000000	tile had came off wall
B. T. Washington High	4/1/2024 8:16	CORONADO	Masonry	Z1-006908	the walls need painting badley
B. T. Washington High	8/20/2024 7:32	BURCHETT	Painting	Z1-028507	the watts need painting badtey
B. I. Washington riigh	0/20/2024 / .32	BUNCHETT	Faillung	21-020307	Please paint door for restroom gray in color. Door is in the paint shop.
B. T. Washington High	8/16/2024 8:15	BURCHETT	Painting	Z1-027982	r lease paint door for restroom gray in color. Door is in the paint shop.
b. 1. Washington riigh	0/10/2024 0.10	DONORETT	runing	21 02/302	walls are damage
B. T. Washington High	7/12/2024 7:40	BURCHETT	Painting	Z1-020967	Traile are damage
D	7712720247140	5011011211	. umang	21 020007	plumbing is stopped up
B. T. Washington High	12/16/2024 8:27		Plumbing	Z1-044977	haman Grandhar ah
					door will not roll up
B. T. Washington High	9/27/2024 14:20	GREER	Roll Up Doors	Z1-035207	·
B. T. Washington High	3/28/2024 15:46	BENTON	Shades/Blinds	WO993922	WE NEED SHADES IN THIS ROOM BADLEY
					seats are broken [4]
B. T. Washington High	9/25/2024 14:02	SHIPPS	Welding	Z1-034724	
					windows are broken and rain comes in
B.T. Washington Stadium	8/30/2024 7:24		Carpentry	Z1-030387	
					no power to lights
B.T. Washington Stadium	8/21/2024 14:15	ANDREWS	Electrical	Z1-028947	
					needs painting badley walls [chipping] falling off
B.T. Washington Stadium	8/30/2024 7:26	BURCHETT	Painting	Z1-030388	
					toilets are not useable rusted out
B.T. Washington Stadium	8/30/2024 7:22	14/500	Plumbing	Z1-030386	404400040
Balmoral/Ridgeway Elementary	12/13/2024 14:02	WEBB WEBB	Carpentry	Z3-044925	12/13/2024 Door want close on it's on
Balmoral/Ridgeway Elementary Balmoral/Ridgeway Elementary	12/13/2024 13:59 12/3/2024 9:56	WEBB	Carpentry Carpentry	Z3-044924 Z3-042818	12/13/2024 Portable door want close 11/3/2024 Need stag resurfacing
Balmoral/Ridgeway Elementary		CROUSE		Z3-042818 Z3-023945	ů ů
Balmoral/Ridgeway Elementary	7/31/2024 7:50 12/13/2024 14:19	SCOTT	Carpentry Electrical	Z3-044927	7/31/24 portable 270 ramp needs replacing 12/13/2024 Magnet does not work on door by custodial room
Balmoral/Ridgeway Elementary	11/1/2024 6:29	SCOTT	Electrical	Z3-039162	11/1/24 Balance out in boys bathroom on 2nd Grade across from Mrs Whitley
Balmoral/Ridgeway Elementary	10/14/2024 11:41	SCOTT	Electrical	Z3-036846	10/14/2024 Balance out in Ms white office
Balmoral/Ridgeway Elementary	10/14/2024 11:38	SCOTT	Electrical	Z3-036845	Balance out in Ms White office
Balmoral/Ridgeway Elementary	10/1/2024 12:37	SCOTT	Electrical	Z3-035737	10/01/2024 Balance out in library
Balmoral/Ridgeway Elementary	10/1/2024 12:36	SCOTT	Electrical	Z3-035736	11/01/2024 Balance out in library
Balmoral/Ridgeway Elementary	10/1/2024 11:15	SCOTT	Electrical	Z3-035710	10/1/2024 Balance out in Rolfe room out
Balmoral/Ridgeway Elementary	9/18/2024 8:39	SCOTT	Electrical	Z3-033368	9/18/2024. Cafeteria line Balance out
Balmoral/Ridgeway Elementary	9/16/2024 7:06	SCOTT	Electrical	Z3-032760	9/16/2024. Balance out in Bathroom
Balmoral/Ridgeway Elementary	8/26/2024 11:10	SCOTT	Electrical	Z3-029556	8/26/24 Balance out in Spanish class
Balmoral/Ridgeway Elementary	7/30/2024 7:59	SCOTT	Electrical	Z3-023578	7/3024 socket does not work
Balmoral/Ridgeway Elementary	7/29/2024 12:20	SCOTT	Electrical	Z3-023354	7/29/24 Socket doesn't work
Balmoral/Ridgeway Elementary	7/16/2024 7:35	SCOTT	Electrical	Z3-021298	7/16/24 socket on serving line broken
Balmoral/Ridgeway Elementary	7/15/2024 10:11	SCOTT	Electrical	Z3-021186	7/15/24 PA in office not working correctly
Balmoral/Ridgeway Elementary	12/13/2024 14:45		Fire Alarm System	Z3-044933	12/13 /2024 fire device has came off wall
					7/31/24 & 8/15/24 Fire Alarm didn't go off in Portables during the fire drill
Balmoral/Ridgeway Elementary	7/31/2024 11:53	SMALL	Fire Alarm System	Z3-024099	

we need special cut towel in hallways

Balmoral/Ridgeway Elementary	12/13/2024 14:14		Fire Sprinkler System	Z3-044926	12/13/2024 Fire alarm has fallen
Balmoral/Ridgeway Elementary	7/22/2024 10:27	CASEY	Flooring	Z3-021866	7/22/24 stage needs resurfing
Balmoral/Ridgeway Elementary	6/12/2024 9:56	CASEY	Flooring	Z3-018132	6/12/24. Portable by container.
			3		9/12/24. 1st Portable needs a key for it
Balmoral/Ridgeway Elementary	9/12/2024 8:36	SMITH	Key & Lock	Z3-032122	•
Balmoral/Ridgeway Elementary	7/8/2024 9:37	SMITH	Key & Lock	Z3-020408	7/8/24 need keys to front Door Per Principal Lowe
Balmoral/Ridgeway Elementary	7/4/2024 8:05	BURCHETT	Painting	Z3-020254	7/5/24 paint inside. In front of office
Balmoral/Ridgeway Elementary	6/12/2024 8:01	BURCHETT	Painting	Z3-018089	6/12/24 parking lot needs stripping the parking lot
Balmoral/Ridgeway Elementary	3/28/2024 15:45	BURCHETT	Painting		aint is chipping on the bottom of the window need touch up work I didn't have the paint to do the job
Balmoral/Ridgeway Elementary	3/28/2024 15:45	BURCHETT	Painting		s on both sides of the building that needs the doors an frame painted the same color as doors in main office
baumorav Riugeway Elementary	3/28/2024 15.45	DURCHEII	Pallung	WO1000597	s off both sides of the building that needs the doors an frame painted the same color as doors in main office
Balmoral/Ridgeway Elementary	3/28/2024 15:45	HARRIS	Painting	W0994032	There are five entry ways to the building that needs to be painted on the outside two on each side of the building and the one in the back of the building
					A receptacle is needed to be installed to connect kitchen equipment (Steamer, Hot Box,
					etc.)
Barrets Chapel School	12/13/2024 12:03	POWELL	Electrical	Z2-044895	
					Replace actual Duplex receptacle by a Quad receptacle (Safety).
Barrets Chapel School	12/13/2024 11:08	POWELL	Electrical	Z2-044889	
					Ballast needs to be replaced.
Barrets Chapel School	12/13/2024 11:01	POWELL	Electrical	Z2-044884	
					Doorbell is not buzzing, fix it or replace it.
Barrets Chapel School	12/12/2024 7:51	POWELL	Electrical	Z2-044538	bootbeats not buzzing, in it of replace to
Darrets Chapet School	12/12/2024 /.51	TOWLLL	Liectificat	22-044550	Short Circuit correction in the electrical cabinet.
Barrets Chapel School	12/9/2024 15:10	POWELL	Floatrical	Z2-044117	Short Gircuit Correction in the electrical Cabinet.
Barrets Chapet School	12/9/2024 15.10	POWELL	Electrical	22-044117	Heater not weaking it needs to be about and fiver replaced (Ondestainvall beside suit
					Heater not working, it needs to be check and fix or replaced (2nd. stainwell beside exit
					door).
Barrets Chapel School	10/18/2024 9:29	POWELL	Electrical	Z2-037476	
					Heater not working, it needs to be check and fix or replaced (1st. stairwell beside exit door).
Barrets Chapel School	10/18/2024 9:28	POWELL	Electrical	Z2-037474	
					Light not working (it makes noise continuously, left side).
Barrets Chapel School	9/20/2024 9:22	POWELL	Electrical	Z2-033940	
					Light not working (it makes noise continuously, right side).
Barrets Chapel School	9/20/2024 9:22	POWELL	Electrical	Z2-033939	
					Please fix or replace Exhaust fan not working.
Barrets Chapel School	5/1/2024 8:51	POWELL	Electrical	Z2-012468	
·					Please check and fix not working lights around the building (Band room).
Barrets Chapel School	5/1/2024 8:05	POWELL	Electrical	Z2-012442	0,000,000,000
					Please replace light bulb not working (Exterior lights are over 10 ft).
Barrets Chapel School	5/1/2024 7:50	POWELL	Electrical	Z2-012432	r tease replace agric bath not working (Exterior agrics are over 10 ft).
Darrets Chapet School	3/1/2024 /.30	TOWLLL	Liectificat	22-012432	Exhaust Fan is not working, it needs to be fix or replace.
Daviete Chanal Cahaal	4/20/2024 10:00	DOWELL	Floatrical	70.010010	Exhaust 1 am is not working, it needs to be involveptace.
Barrets Chapel School	4/30/2024 10:09	POWELL	Electrical	Z2-012213	Fiver replace for (making naise)
Downto Observat Cobservat	4/4/000445:50	DOMELL	Floration	70 007000	Fix or replace fan (making noise).
Barrets Chapel School	4/1/2024 15:52	POWELL	Electrical	Z2-007098	
					Exhaust Fan is not working, it needs to be fix or replace.
Barrets Chapel School	3/18/2024 8:14	POWELL	Electrical	Z2-005060	
					Replace light (parking light pole) burned out.
Barrets Chapel School	3/13/2024 11:53	POWELL	Electrical	Z2-005004	
					Replace light (parking light pole) burned out.
Barrets Chapel School	3/13/2024 11:51	POWELL	Electrical	Z2-005003	
					Replace light (parking light pole) burned out.
Barrets Chapel School	3/13/2024 11:48	POWELL	Electrical	Z2-005002	
					Replace light (parking light pole) burned out.
Barrets Chapel School	3/13/2024 11:47	POWELL	Electrical	Z2-005001	
					Replace light (parking light pole) burned out.
Barrets Chapel School	3/13/2024 11:44	POWELL	Electrical	Z2-004999	
•					Replace light (parking light pole) burned out.
Barrets Chapel School	3/13/2024 11:42	POWELL	Electrical	Z2-004998	,
	-				Replace light pole burned out.
Barrets Chapel School	3/13/2024 9:36	POWELL	Electrical	Z2-004976	
				30.07.0	Replace light bulb burned out.
Barrets Chapel School	3/13/2024 9:33	POWELL	Electrical	Z2-004975	riopiaso agrit saus surrios sati
Sarrets Onaper ochoot	3, 10, 2024 0.00	TOWLL	Licotricut	22 00-070	

					Replace light bulb burned out.
Barrets Chapel School	3/13/2024 9:30	POWELL	Electrical	Z2-004973	. •
Barrets Chapel School	12/6/2024 13:01	Coleman	Fire Sprinkler System	Z2-043840	The sprinkler wrench is missing from the fire sprinkler spare head box.
Barrets Chapel School	12/6/2024 12:56	Coleman	Fire Sprinkler System	Z2-043838	Annual Service Needed
Barrets Chapel School	12/3/2024 14:38	Coleman	Fire Sprinkler System	Z2-043041	5 Year Sprinkler Inspection
Barrets Chapel School	4/25/2024 14:25	LEWIS	Fire Sprinkler System	Z2-011607	replace sprinkler head
Barrets Chapel School	3/28/2024 15:45	CHASE	Flooring	WO992337	Requesting carpet be taken up and replaced with floor tile. RTU 4 blowing bellow 66 degrees (Energy Management cannot read it.). Fix it
Barrets Chapel School	12/5/2024 13:06	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043637	RTU 2 blowing bellow 66 degrees (Energy Management cannot read it.). Fix it
Barrets Chapel School	12/5/2024 13:05	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043636	RTU 1 blowing bellow 66 degrees (Energy Management watch 72 degrees on the screen). Fix
Barrets Chapel School	12/5/2024 13:03	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043635	Replace door lock with one that work with Plant Manager Master Key (A)
Barrets Chapel School	4/11/2024 15:28	SMITH	Key & Lock	Z2-008926	···
Barrets Chapel School	8/9/2024 11:47	BURCHETT	Painting	Z2-026712	Please paint Rear Exit Door.
Barrets Chapel School	7/1/2024 9:50	BURCHETT	Painting	Z2-019914	Please repaint (almost erased), straight lines on the parking lots (front and rear).
Barrets Chapel School	5/31/2024 11:41	BURCHETT	Painting	Z2-016724	Work over the hummed wall and paint it.
Barrets Chapel School	4/2/2024 14:32	BURCHETT	Painting	Z2-007422	Paint new double side Door (Gym) recently replaced.
			·		REQUESTING A PLUMBER TO UNHOOK OLD STEAMER AND REPIPE NEW STEAMER. CALL DARRYL HUNT 901-626-1546. TO ARRANGE DELIVERY OF NEW STEAMER.
Barrets Chapel School	10/17/2024 10:08	WILSON	Plumbing	Z2-037348	we have to have our Bleachers inspected and documented, per fire inspection
Belle Forest Community School	5/16/2024 14:27	SMALL	Bleachers and Seats	Z3-014921	one of the screws came out of the bleacher on a step. the coach was able to find one of the screws. (Hightower)
Belle Forest Community School	2/8/2024 11:13	SMALL	Bleachers and Seats	Z3-000699	Check/Repair Handicap Door
Belle Forest Community School	12/11/2024 7:18	CROUSE	Carpentry	Z3-044404	Should hapail Haharaap 5001
Belle Forest Community School	12/9/2024 13:51	WEBB	Carpentry	Z3-044099	The ceiling need grids to hold the ceiling tile in place stairwell #2 has 1 light fixture with a bad ballast
Belle Forest Community School	4/18/2024 12:03	WHITWORTH	Electrical	Z3-010375	stairwell #1, has all ceiling light fixtures out
Belle Forest Community School	4/18/2024 12:02	SCOTT	Electrical	Z3-010372	stairwell # 4 has 4 light fixtures out with bad ballast
Belle Forest Community School	4/18/2024 12:00	SCOTT	Electrical	Z3-010370	we are having problems with our elevators; elevator keeps stopping and is operating slow. I
Belle Forest Community School	12/2/2024 10:04		Elevators	Z3-042382	have reset it twice
beac rotest community ceriod	12/2/2024 10:04		Lations	25 042502	we had an alarm go off over the weekend, the cleaning crew spilled water in the elevator causing the alarm to go off. the panel is saying heat alarm act. heat in elevator pit, please send someone ASAP! THANKS
Belle Forest Community School	7/22/2024 6:54	SMALL	Elevators	Z3-021790	fire alarm is not free and clear of troubles
Belle Forest Community School	12/12/2024 15:34	SMALL	Fire Alarm System	Z3-044785	replace sprinkler heads and repair leak
Belle Forest Community School	12/13/2024 12:18	GREER	Fire Sprinkler System	Z3-044900	2 sprinkler heads escutcheons on the north side of the building near the kitchen are not aligned with the ceiling
Belle Forest Community School	12/12/2024 15:37	SMALL	Fire Sprinkler System	Z3-044786	Need 2 sprinkler head rings in the custodian closet.
Belle Forest Community School	5/20/2024 7:34	SMALL	Fire Sprinkler System	Z3-015115	Trock 2 aprillings in the descendiff offether.
Belle Forest Community School	5/17/2024 14:30	CHASE	Flooring		is requesting to have the carpet removed from the library and all office areas. It has smell and holding ants and other bugs
Belle Forest Community School	5/17/2024 14:30	CHASE	Flooring	WO1013780	The principal is requesting carpet removed in all office areas in the main office
Belle Forest Community School	5/17/2024 14:30	CHASE	Flooring	WO1013777	Principal is requesting carpet to be removed in his office

HEATING UNIT IN RM A103 -NOT COMING ON PM/DEAN 416-7200	
---------------------------------------------------------	--

					HEATING UNIT IN RM A103 -NOT COMING ON PM/DEAN 416-7200
Belle Forest Community School	12/4/2024 13:05	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043374	Mr. Door 67999 so heat in years
Belle Forest Community School	11/22/2024 9:33	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-042048	Mr. Dean 67200 no heat in room
,					
					we need copies to classrooms A109, B115, C103, C102. the keys that were dropped off
Belle Forest Community School	12/4/2024 12:23	MALONE	Key & Lock	Z3-043364	from wo z3-033825 do not work. also need 2 A keys the A keys are lost
			,		ROOM C105, the outside door handle is about to fall off, if it falls off teachers may not be
					able to get back in room
Belle Forest Community School	9/25/2024 6:21	MALONE	Key & Lock	Z3-034548	We need room C102 lock changed from a PLC lock to regular teachers lock, the room will
					used as a classroom this year
Belle Forest Community School	7/24/2024 11:50	SMITH	Key & Lock	Z3-022386	
					Principle would like the 3 doors leading to the Multipurpose Partnership room rekeyed. The
					inside bar are A keys and the outside going in are B KEYS. We need the changed to B key.
					Also need copies to room C103 and B115, one A and one B KEY teachers lost these keys
Belle Forest Community School	7/12/2024 13:23	SMITH	Key & Lock	Z3-021075	and the state of t
Belle Forest Community School	6/3/2024 11:46	BURCHETT	Painting	Z3-016958	request to have hallway walls in school painted
					annule testing of backflow devices
Belle Forest Community School	10/3/2024 12:48	WILSON	Plumbing	Z3-036127	
Belle Forest Community School	6/8/2024 9:09	WILSON	Plumbing	Z3-017774	prep bottle fillers for inspections
beate i diest community condet	0/0/2024 0:00	WILDON	i turnomg	20 01///4	Water fountain damaged in multiple places, hazard for the students.
Belle Forest Community School	4/22/2024 14:09	BARNES	Plumbing	Z3-010958	
					Rooms A103, A104, A105, A110, B107, C100, C102, E209, and our Multipurpose room has turn blinds that dont work.
Belle Forest Community School	8/26/2024 11:47	BENTON	Shades/Blinds	Z3-029592	direction and done work.
-					Alarm panel is showing 001 trouble, 150 Pull Station Lecture Hall North, have to push the
Bellevue Middle	12/2/2024 13:58	GREER	Fire Alarm System	Z1-042582	Ack/panel Silence button to turn off Trouble is showing a yellow light
Dellevue Pildule	12/2/2024 13.36	GREEN	riie Adiiii System	21-042302	UNIT NOT HEATING -CL-RM 303, 3RD FLOOR
					P/M ALLEN 416-1466
Bellevue Middle	12/6/2024 14:38	WEBB	Heating/Ventilation/Air Conditioning	Z1-043884	UNIT NOT HEATING - PRINCIPALS OFFICE
					PM ALLEN 416-1466
Bellevue Middle	12/6/2024 14:37	WEBB	Heating/Ventilation/Air Conditioning	Z1-043883	
					UNIT NOT HEATING - GYM P/M ALLEN 416-1446
Bellevue Middle	12/4/2024 7:47	WEBB	Heating/Ventilation/Air Conditioning	Z1-043113	77F1 RLLEN 4.10-1440
					anita allen 61466 units leaking
Bellevue Middle	12/2/2024 14:19	WEBB	Heating/Ventilation/Air Conditioning	Z1-042593	anile alles C4 (C5 units too had in years
Bellevue Middle	12/2/2024 14:18	WEBB	Heating/Ventilation/Air Conditioning	Z1-042592	anita allen 61466 units too hot in rrom
					anita allen 61466 units too hot in rrom
Bellevue Middle	12/2/2024 14:17	WEBB	Heating/Ventilation/Air Conditioning	Z1-042591	
Bellevue Middle	12/2/2024 14:16	WEBB	Heating/Ventilation/Air Conditioning	Z1-042589	anita allen 61466 units not coming on at all
					anita allen 61466 units not heating
Bellevue Middle	12/2/2024 14:15	WEBB	Heating/Ventilation/Air Conditioning	Z1-042588	
Bellevue Middle	11/15/2024 11:17	WEBB	Heating/Ventilation/Air Conditioning	Z1-041079	Ms. Allen 61466 heat too hot and energy management can't see it to turn it down
Delicade i liddie	11,10,202711.1/	***	rossing ventuations an conditioning	21 0410/0	Ms. Allen 61466 heat too hot and energy management can't see it to turn it down
Bellevue Middle	11/15/2024 11:17	WEBB	Heating/Ventilation/Air Conditioning	Z1-041078	
Bellevue Middle	11/15/2024 11:16	WEBB	Heating/Ventilation/Air Conditioning	Z1-041077	Ms. Allen 61466 heat too hot and energy management can't see it to turn it down
Deliciae Minaile	11/10/2024 11.10	VVLDD	nearing/ventiladon/An Conditioning	21-0410//	
					At the top of the stairs the wall is peeling really bad worry that some of the paint or the white
Bellevue Middle	8/23/2024 8:03	BURCHETT	Painting	Z1-029197	stuff falling with the paint will fall on the student going up and down the stairs going to class
Bellevue Middle	8/20/2024 9:07	BURCHETT	Painting		reaking up into white Stuff and the children walks their side of the stairs going to their classrooms. Can we please have someone to come and look at that wall, please
Bellevue Middle	7/19/2024 15:01	BURCHETT	Painting	Z1-021752	Please paint newly installed entry doors to the courtyard.

Bellevue Middle	6/21/2024 7:28	BURCHETT	Painting	Z1-018967	needs painting where a hole was fixed in wall
believue Muule	0/21/2024 /.26	BUNCHETT	ranning	21-010907	Has a big hole in the wall
Bellevue Middle	5/21/2024 7:44	BURCHETT	Painting	Z1-015325	
					Stall walls needs painting walls are Blue
Bellevue Middle	5/21/2024 7:38	BURCHETT	Painting	Z1-015321	Obelluselle accele acintica quell in Disc
Bellevue Middle	5/21/2024 7:35	BURCHETT	Painting	Z1-015319	Stall walls needs painting wall is Blue
Delicede i fidale	0/21/2024 / .00	DONOTIETT	T dillang	21 010010	Stall walls needs painting walls are Blue
Bellevue Middle	5/21/2024 7:33	BURCHETT	Painting	Z1-015318	
					Test RP device as noted on letter.
Bellevue Middle	12/10/2024 9:47	OWENS	Plumbing	Z1-044226	when flushing the toilet water comes to the top on to the floor i can not turn it off or down
					can we get some help
Bellevue Middle	12/5/2024 9:20	SINK	Plumbing	Z1-043510	
					Can not get toilet unplug
Bellevue Middle	12/5/2024 9:12	SINK	Plumbing	Z1-043505	Needs help water is leading from the since of the toilet 4th stell
Bellevue Middle	12/4/2024 7:39	SINK	Plumbing	Z1-043106	Needs help water is leaking from the pipes of the toilet 4th stall
Bellevue Middle	11/15/2024 11:40	DIAZ	Roofing	Z1-043106 Z1-041086	Please repair roof over generator room.
Dellevae Pilaale	11/13/2024 11:40	DIAL	Nooning	21-041000	Size Shades I need for work order Z1-020585 is 3feet and 42inches
Bellevue Middle	7/9/2024 12:23	BENTON	Shades/Blinds	Z1-020591	0.25 0.14400 1.0544 10. 1151.05142 12. 22.0500 10.0500 11.0
Donovao i maato	7707202-4 22120	BEITTOIT	Sildada Ballad	21 020001	Needs 10 Window Shades for 108 needs 4, 110 needs 1, and room 100 in the Gym Lobby
					area needs 5 thank you
Bellevue Middle	7/9/2024 12:09	BENTON	Shades/Blinds	Z1-020585	,
					Needs dryer vent hose line cleaned and documented POCA
Bellevue Middle	10/15/2024 10:27	Williams	Sheet Metal	Z1-037041	
Bellevue Middle	3/8/2024 9:40	Williams	Sheet Metal	Z1-004599	POCA Dryer vent hose Line shall be cleaned and documented
Berclair Elementary	9/19/2024 8:24	SMITH	Audio Visual	Z2-033573	ck and repair the intercom. Per Principal Secretary the intercom keeps going out in classrooms at random times. Thanks
Berclair Elementary	12/2/2024 21:25	BURKE	Carpentry	Z2-042661	Please repair exterior door to the courtyard. Please see attached picture. Thanks
Berclair Elementary	11/19/2024 20:37	BURKE	Carpentry	Z2-041574	f over the front office. Pest Control cannot control access of the wasps. The wasps are swarming inside the front office. Thank you
Berclair Elementary	11/7/2024 8:40	ROY	Carpentry	Z2-040032	eck and repair front door entrance per Security the crash bar needs repair due to not releasing. Thanks
Berclair Elementary	10/22/2024 8:05	BURKE	Carpentry	Z2-037766	ise repair facial board behind the gutter. This will allow rodents to enter in the building. Thank you
Berclair Elementary	12/10/2024 14:37	POWELL	Electrical	Z2-044353	Please replace ballast in light fixture. Thanks
-					Please install electrical outlet in front of the stage to supply power for smart board and
					other electronics.
Berclair Elementary	12/2/2024 21:00	STAFFORD	Electrical	Z2-042656	No longer can used extension cords per Risk Management.
					Please replace broken light fixture cover(directed by Risk Management). Thanks
Berclair Elementary	12/2/2024 20:57	POWELL	Electrical	Z2-042655	
Berclair Elementary	11/7/2024 13:35	POWELL	Electrical	Z2-040158	Please replace ballast in light fixture. Thanks
Berclair Elementary	11/7/2024 8:54	POWELL	Electrical	Z2-040047	Please repair ballast in light fixture. Thanks
Berclair Elementary	10/24/2024 20:53	POWELL	Electrical	Z2-038276	Pre-K classroom#21 -Emergency lights combination #9 is not working. Thanks
Berclair Elementary	10/24/2024 20:51	POWELL	Electrical	Z2-038275	Emergency lights combination #1 is not working. Thanks
Berclair Elementary	10/24/2024 20:50	POWELL POWELL	Electrical	Z2-038274	Emergency lights combination#9 is not working. Thanks
Berclair Elementary	10/24/2024 20:48 10/24/2024 20:47	POWELL	Electrical Electrical	Z2-038273 Z2-038272	Emergency lights combination#6 is not working. Thanks
Berclair Elementary Berclair Elementary	10/15/2024 8:57	POWELL	Electrical	Z2-038272 Z2-037000	Emergency lights combination#5 is not working. Thanks the Emergency exit lights#10. Hanging by the wire only. (I tried to reattached and couldn't get it stay). Thanks
Berclair Elementary	9/13/2024 12:27	POWELL	Electrical	Z2-037000 Z2-032692	Please replace exterior lights, is not working. Thanks
Berclair Elementary	9/13/2024 12:25	POWELL	Electrical	Z2-032692 Z2-032691	Please replace exterior light bulbs, is not working. Thanks
Berclair Elementary	9/13/2024 9:40	POWELL	Flectrical	Z2-032091 Z2-032577	Please check and repair emergency lights combo#6 is not working, thanks.
Berclair Elementary	9/13/2024 9:38	POWELL	Electrical	Z2-032577 Z2-032571	Please check and repair emergency lights combo#5 is not working, thanks.
Berclair Elementary	8/20/2024 10:48	POWELL	Electrical	Z2-028633	Emergency lights combination #1 is not working. Thanks
Berclair Elementary	8/20/2024 10:46	POWELL	Electrical	Z2-028632	Emergency lights combination #9 is not working, thank you
Berclair Elementary	8/15/2024 10:58	POWELL	Electrical	Z2-027794	Please replace ballast in light fixture. Thanks
Berclair Elementary	8/7/2024 10:30	POWELL	Electrical	Z2-02/734 Z2-026089	Please replace ballast to 3 light fixtures in the cafeteria. Thank you
Berclair Elementary	8/6/2024 11:47	POWELL	Electrical	Z2-025679	It's about 5 light fixtures need ballast replace in new annex hallways please. Thanks
Berclair Elementary	7/24/2024 16:09	POWELL	Electrical	Z2-022463	Please check and repair vent hood in the back kitchen, it's stopped working. Thanks
Berclair Elementary	7/23/2024 8:19	POWELL	Electrical	Z2-022050	epair the bottle filler receptacle has no power (I reset and checked the breaker but still has no power). Thank you
					The A/C unit in my office has been failing for over a year. Multiple requests for service have
					been submitted by the plant manager. The system is no longer cooling at all. It blows air
					that is fan temperature. The office temperature is unacceptable. Please fix. Thank you!
					Principal Clint Davis of Berclair ES
Berclair Elementary	6/24/2024 10:39	WOOD	Energy Management System	Z2-019185	

Berclair Elementary	10/15/2024 9:14	Coleman	Fire Alarm System	Z2-037005	Please replace Main Panel Batteries. Thanks
Berclair Elementary	10/15/2024 9:14	Coleman	Fire Alarm System	Z2-037004	Please replace BPS Batteries in main office panel. Thanks
					Per Risk Management please schedule and manage annually inspection for fire sprinkler
					system. Last inspected 8/20/2022. Thank you
Berclair Elementary	12/2/2024 21:20	Coleman	Fire Sprinkler System	Z2-042660	System East imposted State Sta
bercian Elementary	12/2/2024 21.20	Coteman	Fire Sprinkler System	22-042000	Mr. Vinc (MO 0000) Brank in FO Brank and Anathra Heikhlaus sis but and had
					Ms. King (416 8800) Berclair ES Rm 18 not heating. Unit blows air but not heat
Berclair Elementary	12/4/2024 8:17	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-043136	
					UNIT NOT COOLING (2) GYM
					TROUBEL SIGNAL - CAB AIR ISSUE
					P/M 416-8800
Berclair Elementary	8/16/2024 8:56	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-028001	
Berclair Elementary	10/30/2024 12:15	MALONE	Key & Lock	Z2-038936	PLC Coach is requesting 5 keys for elevator to be use by SPED Assistants. Thanks
•					
Berclair Elementary	2/13/2024 16:32	SMITH	Key & Lock	Z2-001308	
Berclair Elementary	12/3/2024 19:03	BURCHETT	Masonry	Z2-043062	Please repair structural cracks in the corners of the classroom walls.
Berclair Elementary	12/2/2024 21:06	BURCHETT	Masonry	Z2-042658	Please repair structural cracks in the corners of the classroom walls. Thanks
Berclair Elementary	12/2/2024 21:04	BURCHETT	Masonry	Z2-042657	Please repair structural cracks in the corners of the classroom walls. Thanks
Berclair Elementary	12/8/2024 18:29	BURCHETT	Painting	Z2-043910	ding and gym. Several areas paint is chipping off. The walls in the hallway and restrooms is really need to be painted especially in the main building. Thank you.
Berclair Elementary	4/17/2024 8:37	BURCHETT	Painting	Z2-009812	Please re-paint Teachers and staff parking lot/ parking spaces is very faded. Thanks
Berclair Elementary	12/11/2024 20:47	STAFFORD	Plumbing	Z2-044517	
Deretan Etementary	12/11/2024 20.4/	OTAL TOTAL	i turnomg	22 044017	repair valve for HVAC
Develois Flancostons	40/40/0004 0:40	SEMLER	Diversión	70 044444	repair valve of Trans
Berclair Elementary	12/10/2024 6:49		Plumbing	Z2-044144	
Berclair Elementary	12/12/2024 9:22	STAFFORD	Roofing	Z2-044599	Roof leaking. Thanks
Berclair Elementary	12/3/2024 9:21	STEVENS	Roofing	Z2-042787	Roof leaking. Thanks
Berclair Elementary	9/16/2024 15:12	Bryant	Roofing	Z2-033030	Roof leaking. Thanks
Berclair Elementary	9/13/2024 6:36	Bryant	Roofing	Z2-032393	Roof leaking in 3 different areas. Thanks
Berclair Elementary	9/13/2024 6:33	Bryant	Roofing	Z2-032391	Roof leaking.
Berclair Elementary	9/13/2024 6:30	Bryant	Roofing	Z2-032390	Roof leaking.
Berclair Elementary	9/13/2024 6:29	,	Roofing	Z2-032389	Roof leaking.
,		Bryant	•		· · · · · · · · · · · · · · · · · · ·
Berclair Elementary	9/13/2024 6:28	Bryant	Roofing	Z2-032388	Roof leaking.
Berclair Elementary	9/13/2024 6:27	Bryant	Roofing	Z2-032386	Roof leaking.
Berclair Elementary	9/13/2024 6:27	Bryant	Roofing	Z2-032384	Roof leaking.
Berclair Elementary	9/13/2024 6:26	Bryant	Roofing	Z2-032383	Roof is leaking
Berclair Elementary	12/5/2024 8:18	CARLOS	Welding	Z2-043455	Please install handrails both side at the back of the stage per risk management. Thanks
ŕ			•		Window appears to be off track won't let completely down.
Bethel Grove Elementary	12/12/2024 16:06	FORD	Carpentry	Z4-044792	······································
Bethel Grove Elementary	12/11/2024 8:10	FORD	Carpentry	Z4-044732 Z4-044417	Door is broken and split on inside.
,					·
Bethel Grove Elementary	11/7/2024 19:38	FORD	Carpentry	Z4-040210	Wall has holes in it and appears to be deteriorating.
Bethel Grove Elementary	10/16/2024 10:02	FORD	Carpentry	Z4-037199	Window is off track and doesn't let up properly.
Bethel Grove Elementary	7/8/2024 7:49	LEWIS	Carpentry	Z4-020360	st PLC classroom floor to be repaired. Students are tripping and has become a hazard for students and staff.
Bethel Grove Elementary	5/17/2024 13:36	BENTON	Carpet Repair	WO967159	Replace carpet in Library
Bethel Grove Elementary	12/5/2024 11:22	HALL	Electrical	Z4-043578	None of the exterior lights around the building work.
Bethel Grove Elementary	11/8/2024 13:49	HALL	Electrical		ıtside lights around the building work. My lead person took pictures of the building last night with her phone.
,					Needs tamper seal.
Bethel Grove Elementary	10/16/2024 11:24	CALDWELL	Fire Sprinkler System	Z4-037223	recess camper seed
,			, ,		Compatible flow block product of the control of the
Bethel Grove Elementary	10/15/2024 8:02	CASEY	Flooring	Z4-036979	Some of the floor tiles have been ruined After a AC leak.
Bethel Grove Elementary	7/28/2024 19:06	CASEY	Flooring	Z4-023063	icipal request floor to be repaired as it has become a safety hazard for students, faculty and staff.
					HVAC UNIT PIPE IN THE CAFE CEILING IS LEAKING PM/BROWN 416-5012
Bethel Grove Elementary	10/31/2024 12:21	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-039111	
Bethel Grove Elementary	11/21/2024 11:21	BURCHETT	Masonry	Z4-041937	Entrance wall is wearing off at bottom.
Bethel Grove Elementary	10/28/2024 15:17	BURCHETT	Painting	Z4-038593	Bathroom needs painting.
Bethel Grove Elementary	10/16/2024 9:17	BURCHETT	Painting	Z4-037178	Room needs to be painted.
Bethel Grove Elementary	9/11/2024 15:19	BURCHETT	Painting	Z4-032052	Rm. 104 needs painting. Large pieces of paint are peeling off.
Bethet Grove Eternentary	3/11/2024 13:13	DONOTIETT	i diliting	24-032032	
					Prek Advisors advise that the girls restroom paint be touched up and repaired
Bethel Grove Elementary	8/26/2024 11:38	BURCHETT	Painting	Z4-029582	
					1st toilet is leaking from bottom. Toilet is cut off.
Bethel Grove Elementary	12/12/2024 16:00	JOHNSON	Plumbing	Z4-044789	
Bethel Grove Elementary	11/18/2024 14:04	JOHNSON	Plumbing	Z4-041344	Mop sink cannot be cut off all the way. May need a new washer.
Bethel Grove Elementary	11/18/2024 13:58	JOHNSON	Plumbing	Z4-041342	Urinal to the left is leaking from neck. Building engineer has cut it off so it won't flood.
Bethel Grove Elementary	11/13/2024 16:50	JOHNSON	Plumbing	Z4-040715	When the toilet is flushed it leaks from the handle and neck.
,	11/8/2024 8:56	JOHNSON	•	Z4-040713 Z4-040253	
Bethel Grove Elementary			Plumbing		Water faucet knob is broken off.
Bethel Grove Elementary	11/8/2024 8:52	JOHNSON	Plumbing	Z4-040248	Knob on water faucet is broken off.
Bethel Grove Elementary	11/8/2024 8:46	JOHNSON	Plumbing	Z4-040245	he knob on the water faucet is broken off. It needs to be fixed so school can be power washed.

The second toilet to the right has water coming out when flushed. It comes out of the neck. Bethel Grove Elementary 11/6/2024 9:51 JOHNSON Z4-039793 Plumhing 10/30/2024 12:37 Z4-038945 Bethel Grove Elementary JOHNSON Plumbing Drain has slow draining. Bolton High 8/28/2024 12:04 Bleachers and Seats Z2-030068 Coleman home side not working, no power Bolton High 9/18/2024 11:14 ROY Carpentry Z2-033439 garbage door is broken 12/11/2024 8:01 POWELL Flectrical 72-04/41/ Bolton High bad ballast 11/21/2024 8:25 Z2-041850 Bolton High POWELL Electrical multiple light are out. lift is needed plant manager with install light Upgrade gym lights to LED 11/1/2024 12:21 Z2-039280 Bolton High CHALK Electrical Upgrade gym lights to LED Bolton High 11/1/2024 12:20 CHALK Flectrical 72-039279 10/24/2024 8:17 POWELL Z2-038108 Bolton High Flectrical Lights are not working on the stage.

10/23/2024 14:04 POWELL Flectrical 72-038045 Score board is not working Bolton High 10/23/2024 14:04 POWELL Electrical Z2-038044 3 pole light is not working Bolton High Bolton High 9/16/2024 8:56 POWELL Electrical Z2-032834 exposed wires Bolton High 9/16/2024 7:45 POWELL Electrical Z2-032785 bad ballast 2 stall multiple bad ballast 1 floor hallway Bolton High 9/16/2024 7:44 POWELL Electrical Z2-032783 5/9/2024 12:04 POWELL 72-013901 Bolton High Flectrical Rad hallast 5/9/2024 11:34 POWELL Z2-013874 Bad ballast Electrical Bolton High Replace receptacles with GFIC where needed Bolton High 4/29/2024 12:00 CHALK Electrical Z2-012005

Fire Extinguishers

Flooring

Flooring

Flooring

Flooring

Flooring

Heating/Ventilation/Air Conditioning

Heating/Ventilation/Air Conditioning

Heating/Ventilation/Air Conditioning

Heating/Ventilation/Air Conditioning

Key & Lock

Painting

Painting

Painting

Painting

Painting

Painting

Painting

Plumbing

Carpentry

Carpet Repair

Electrical

3/27/2024 16:45

11/8/2024 17:11

10/15/2024 18:05

6/3/2024 10:08

5/9/2024 12:15

3/28/2024 15:43

12/5/2024 8:47

12/3/2024 11:52

12/3/2024 11:50

12/3/2024 11:49

11/8/2024 17:13

9/24/2024 11:55

9/18/2024 11:13

6/18/2024 11:02

4/18/2024 7:59

12/6/2024 9:33

12/5/2024 11:08

6/18/2024 10:54

5/9/2024 12:07

5/9/2024 12:02

5/9/2024 12:01

5/9/2024 11:59

6/12/2024 10:18

12/12/2024 13:39

9/24/2024 13:45

12/9/2024 13:49

Bolton High

Bond Building

Bond Building

Bond Building

LEWIS

CASEY

CASEY

CASEY

CASEY

CHASE

BRYSON

BRYSON

BRYSON

BRYSON

MALONE

MALONE

SMITH

SMITH

SMITH

BURCHETT

BURCHETT

BURCHETT

BURCHETT

BURCHETT

BURCHETT

BURCHETT

HARDWAY

FORD

LEWIS

HALL

Bolton High 3/5/2024 9:53 POWELL Electrical Z2-003963 Bad light ballast very dark area Bolton High 4/2/2024 15:02 CHALK Flectrical WO1012537 Please check northeast outside parking lot lights 4/2/2024 15:02 CHALK Electrical WO1010542 Please service outside light near greenhouses Bolton High Bolton High 4/2/2024 15:02 CHALK Flectrical WO994647 ase check lighting in the auditorium. There are a lot of light out in this area. Please convert to LED Bolton High 4/1/2024 10:11 LEWIS Fire Alarm System Z2-006970

Z2-006708

Z2-040335

Z2-037105

Z2-016907

Z2-013913

WO994635

Z2-043478

Z2-042930

72-042926

Z2-042925

Z2-034479

Z2-033438

Z2-018755

Z2-010100

Z2-043770

72-043571

Z2-018749

Z2-013904

Z2-013899

Z2-013897

Z2-013895

Z2-018139

Z4-044756

Z4-034518

Z4-044096

Fire alarm system are down! maintenance and install fire extinguishers

Requesting for gym floor to get serviced. The roof is fixed in this area please repair floor tile in the Service area Requesting for carpet removal for floor tile Please remove carpet very old Please remove carpet in the guidance office. Mrs Pirtle JAMES 61435

NOT COMING ON

Mr. james 61435 no heat

Mr. james 61435 no heat

Mr. james 61435 no heat

Z2-040336 : change classrooms door locked in the building. Building was closed for 8 year. Locks needs repairs

please change this lock in this area key cylinder is broken and needs repair Please re-key office storage area This is the principals request!
Cylinder replacement pleased paint the N building restrooms please paint E building restrooms Please paint field house restrooms Please paint locker room Please paint new gym Please paint the cafeteria Please paint the taffetial Please paint the plidling BUSTED PIPE - Baseball Field P/M JAMES 416-1435

The overhead cabinet door is broken off the hinges and needs to be repaired.

Can I possibly have carpet replaced in left 3rd floor hallway because of water damage?

One of the prongs to connect a light bulb is broken above the sink

The breaker number 10 trips continuously throughout the day

					The breaker number 10 trips continuously throughout the day
Bond Building	4/29/2024 14:15	HALL	Electrical	Z4-012080	
Bond Building	12/9/2024 13:52		Elevators	Z4-044101	The remaining elevator lift is starting to bounce and grind when getting to the 4th floor
Bond Building	9/24/2024 13:43	CALDWELL	Elevators	Z4-034517	When facing the elevators, the right lift isn't opening or responding.
Bond Building	9/19/2024 13:47	CASEY	Flooring	Z4-033817	arpet in office 211 removed due to mildew smell from slight water damage? Carpet has been shampooed twice.
Bond Building	3/18/2024 14:31	CASEY	Flooring	Z4-005265	re is loose carpet that could possibly have become a trip hazard in the 4th floor conference room.
Bond Building	10/7/2024 13:34	BURCHETT	Painting	Z4-036500	The ceiling on the hallway to the left of the elevator needs plastering and popcorn.
Bond Building	12/4/2024 8:51	JOHNSON	Plumbing	Z4-043172	faucet cut off leaks under sink
					toilet leaking from tank
Bond Building	12/4/2024 8:49	JOHNSON	Plumbing	Z4-043168	Color Southing Horn Carit
Bona Bananig	12/1/20210110	7011110011		21 010100	men's handicap single stall
Bond Building	10/24/2024 14:20	JOHNSON	Plumbing	Z4-038246	continues to lightly run after being flushed
Bond Building	10/23/2024 13:38	JOHNSON	Plumbing	Z4-038034	et in the last stall in the women's restroom needs to be replaced because pressure assist has broken.
Bond Building	10/23/2024 13:34	JOHNSON	Plumbing	Z4-038033	The stall before the last has a fill valve that needs to be replaced because of constant running.
Bond Building	8/20/2024 13:42	JOHNSON	Plumbing	Z4-028717	The 3rd stall toilet bowl has a cracked lid and could possibly cause injury.
Bond Building	5/20/2024 20:09	JOHNSON	Plumbing	Z4-015303	The handle on the 2nd stall toilet is broken and will not flush.
Brownsville Road Elementary	12/9/2024 20:13	POWELL	Electrical	Z2-044135	Receptacle doesn't have power and cover is broken on the stage located in the cafeteria.
Brownsville Road Elementary	12/9/2024 12:36	POWELL	Electrical	Z2-044076	The emergency light by classroom 126 is not working. Please repair.
Brownia Hodd Etomontary	12/0/2024 12:00		Elootifodi	22 011070	The receptacle outlet for the water fountain across from classroom 120 has a shortage. If
					you bump up against it the water fountain will shut off and on and the status light will
					change. I noticed while changing the filter. Please repair.
Brownsville Road Elementary	11/6/2024 12:30	POWELL	Electrical	Z2-039900	onanga matada mina ananging ata maan taada tapam
					The water fountain requires a 3-way adaptor plug for all the cords to work. It currently has
					only two cords plugged in which leaves one of the fountains not functioning. Please repair.
Brownsville Road Elementary	11/6/2024 12:24	POWELL	Electrical	Z2-039898	only the color proposed in miles to the color co
Brownsville Road Elementary	8/26/2024 12:55	POWELL	Electrical	Z2-029610	The exit sign in the west side stairwell first floor isn't working.
Brownsville Road Elementary	8/12/2024 17:56	POWELL	Electrical	Z2-023010 Z2-027102	Classroom 138 (music) has a bad ballast and broken fixture cover.
Brownsville Road Elementary	8/12/2024 17:14	POWELL	Electrical	Z2-027102 Z2-027098	Classroom 134 has a 4 bulb fixture but only 2 bulbs came on. Please replace bad ballast.
Brownsville Road Elementary	8/12/2024 17:14	POWELL	Electrical	Z2-027098 Z2-027097	Classroom 143 (computer)has 1 bad ballast.
Brownsville Road Elementary	8/12/2024 17:08	POWELL	Electrical	Z2-027096	Classroom 141 has 2 bad ballast.
Brownsville Road Elementary	8/12/2024 17:07	POWELL	Electrical	Z2-027095	Classroom 140 has a bad ballast.
Brownsville Road Elementary	8/12/2024 17:05	POWELL	Electrical	Z2-027093 Z2-027094	Bad ballast in office/classroom 108
Brownsville Road Elementary	8/12/2024 17:03	POWELL	Electrical	Z2-027094 Z2-027092	Bad ballast in oncerclassroom 102.
Brownsville Road Elementary	8/1/2024 20:44	POWELL	Electrical	Z2-02/092 Z2-024595	Please replace broken receptacle outlet and cover.
Brownsville Road Elementary	8/1/2024 19:58	POWELL	Electrical	Z2-024589	ceptacles. This classroom was the cool down room for Sped day treatment. It will now be a general ed classroom.
Brownsville Road Elementary	6/4/2024 8:40	POWELL	Electrical	Z2-017065	2 bad ballast
Brownsville Road Elementary	5/7/2024 16:08	POWELL	Electrical	Z2-017005 Z2-013535	he first light in the boys restroom has a shortage. Changed the bulb it will come on sometimes.
Brownsville Road Elementary	3/28/2024 15:41	POWELL	Electrical	WO1005545	
Brownsville Road Elementary	3/28/2024 15:41	POWELL	Electrical	WO1005546	
brownsvitte road Elementary	3/20/2024 13.41	TOWLLL	Liectificat	WO1003340	HEATING UNIT FOR THE KITC IS OVERHEATING SHOWING 80 DEGREES PM/BLAYDE 416-
					4300
Brownsville Road Elementary	12/10/2024 9:51	WILSON	Heating/Ventilation/Air Conditioning	Z2-044232	4000
Brownia Hodd Etomontary	12/10/2024 0:01	***************************************	ricating variations and contained in g	22 0 1 1 2 0 2	HEATING UNIT FOR RM 124 - BLOWING NOT HEATING PM/BLAYDE 416-4300
Brownsville Road Elementary	12/5/2024 10:08	WILSON	Heating/Ventilation/Air Conditioning	Z2-043547	
Browner noda Eternomary	12/0/2024 10:00	***************************************	ricating rentitudents in conditioning	22 0 100 17	UNIT NOT COMING ON (BACK) - CL-RM 143
					P/M BLAYDE 416-4300
Brownsville Road Elementary	12/4/2024 9:54	WILSON	Heating/Ventilation/Air Conditioning	Z2-043247	771321132 420 4000
Browner noda Eternomary	12/4/2024 0104	***************************************	riodanily ronaladonina conditioning	22 0 102 17	UNIT NOT COMING ON (FRONT) - CL-RM 143
					P/M BLAYDE 416-4300
Brownsville Road Elementary	12/4/2024 9:53	WILSON	Heating/Ventilation/Air Conditioning	Z2-043246	771321132 420 4000
Brownsvitte Hodd Eternentary	12/4/2024 0.00	WILDON	ricularly verticulations/air Containoning	22 040240	MS. BLAYDE 64300 BLOWING COLD AIR
Brownsville Road Elementary	12/3/2024 9:17	WILSON	Heating/Ventilation/Air Conditioning	Z2-042782	TIG. BENTAL CHOOL BESTING GOLD AIN
brownsvitte road Elementary	12/3/2024 3.17	WILSON	ricating/ventitation/Air Conditioning	22-042/02	Smokey Classroom 120 Mrs. Blayde (4300) Brownsville Elementary School
Brownsville Road Elementary	12/2/2024 7:43	WILSON	Heating/Ventilation/Air Conditioning	Z2-042230	Smokey classicom 120 Pils. Blayde (4500) Blownsville Elementary School
Drownsville Hodu Elementally	12/2/2024 / .40	MICOOM	nearing/ventiladon/An Conditioning	44-044430	I need keys for the new annex buildings
Brownsville Road Elementary	10/18/2024 9:05	MORRIS	Key & Lock	Z2-037465	. Hood hope for the field differ durings
Brownsville Road Elementary	3/28/2024 15:42	CORONADO	Masonry	WO1005537	cen ceramic floor tile in the kitchen in front of the ice machine. Please repair. This is a trip hazard.
Brownsville Road Elementary	12/9/2024 12:24	HARDWAY	Plumbing	Z2-044071	The mop sink isn't draining properly. I have already tried plunging. Please repair.
Jimomo noda Elementary	12.0.2027 12.27		· combing	LL 0770/1	fabricate strainer for mop sink
Brownsville Road Elementary	12/13/2024 7:24	WHITE	Sheet Metal	Z2-044805	labilitate strainer for map sink
Bruce Elementary	11/5/2024 7:24	RUSSELL	Carpentry	Z1-039555	I have stains on my high ceiling tiles in cafeteria that need changing
Di doo Etomoniai,	11.0.202-10.71		Carpona,	000000	2 my man obtains also in outstand distribute and most and many

					Discourse in community of first board Online and American
Bruce Elementary	5/7/2024 11:07	RUSSELL	Carpentry	Z1-013428	Riser room in counseling office has fire hazard. Ceiling needs closed
Bruce Elementary	5/7/2024 11:06	RUSSELL	Carpentry	Z1-013427	POCA riser room behind stage in cafeteria has a fire hazard. Ceiling needs to be close
Drade Etomentary	5772024 11.00	HOODELE	Surpondy	21 010127	POCA fire hazard in riser room behind stage, ceiling not closed
Bruce Elementary	3/18/2024 7:16	RUSSELL	Carpentry	Z1-005043	
•			. ,		POCA riser rooms has fire hazards, ceiling area not closed
Bruce Elementary	3/18/2024 7:15	RUSSELL	Carpentry	Z1-005042	
Bruce Elementary	9/13/2024 8:14	CHALK	Electrical	Z1-032467	Exterior light is out by the garden on side of school
Bruce Elementary	9/13/2024 7:58	CHALK	Electrical	Z1-032449	Exterior lights in front of school where front entrance is lights have blown
Bruce Elementary	2/3/2024 15:44	CHALK	Electrical	WO1026999	Some of the exterior light in front of school outside are blown not working
Bruce Elementary	4/2/2024 15:01	CHALK	Electrical	WO980221	have lights out Drop off where the children are being let out into school
Bruce Elementary	6/27/2024 8:17	GREER	Generators	Z1-019593	Fan not working on the generator compressor outside by green exit doors by the steps
					Me Irane
					Mr. Jones 64490
					bloowing cold air. Energy management said they would reset but it is still blowing cold air
Bruce Elementary	12/13/2024 8:20	WEBB	Heating/Ventilation/Air Conditioning	Z1-044834	blooming cold diff. Energy multiplement said diety moute reser but it is said blooming cold diff.
Drade Etomentary	12/10/2024 0:20	***	ricating remainders and continuous	21 011001	Mr. jOnes
					64495
					unit not operation correctily. heat is hot. energy management stated unit is not operation
					correctly
Bruce Elementary	12/11/2024 9:33	WEBB	Heating/Ventilation/Air Conditioning	Z1-044441	
					Mr. jones
					64495
					heat not working
Bruce Elementary	12/10/2024 11:23	WEBB	Heating/Ventilation/Air Conditioning	Z1-044267	
Bruce Elementary	11/21/2024 9:13	WEBB	Heating/Ventilation/Air Conditioning	Z1-041877	It is extremely hot in room 122. The air handler unit not working properly
Bruce Elementary	11/13/2024 7:19	WEBB	Heating/Ventilation/Air Conditioning	Z1-040544	Air handler is not working, will not come on
Bruce Elementary	12/10/2024 13:47	MALONE	Key & Lock	Z1-044335	Maine office storage room will not unlock, key would not fit all the way in
Bruce Elementary	12/9/2024 14:09	MALONE	Key & Lock	Z1-044105	Need a key for classrooms 115
Bruce Elementary	12/9/2024 9:27	MALONE	Key & Lock	Z1-043998	Need a master key for principal
Bruce Elementary	5/31/2024 12:51	SMITH	Key & Lock	Z1-016745	rs behind the stage in multipurpose room that need a lock change do to safety hazard lock that's on there now
Bruce Elementary	11/5/2024 8:49	BURCHETT	Painting	Z1-039556	Paint is chipping on the wall by room 106 where the vent is
Bruce Elementary	11/5/2024 6:39	BURCHETT	Painting	Z1-039516	nspection. I have a hole in the wall and chipped paint outside of boys restroom per PRE K inspection
Bruce Elementary	11/5/2024 6:36 7/9/2024 8:27	BURCHETT	Painting	Z1-039515 Z1-020509	PRE K inspection. I have a wall that is chipping paint badly by Pre K room 100
Bruce Elementary Bruce Elementary	6/5/2024 10:05	BURCHETT BURCHETT	Painting Painting	Z1-020509 Z1-017305	Classroom 122 walls needs painting Room 125 walls need painting
Bruce Elementary	6/4/2024 13:24	BURCHETT	Painting	Z1-017303 Z1-017154	Classroom 127 walls needs painting
Bruce Elementary	6/4/2024 13:24	BURCHETT	Painting	Z1-017153	Classroom 120 walls needs painting
Bruce Elementary	5/10/2024 9:46	BURCHETT	Painting	Z1-01/100	I the handicap sign, principal sign, and administrative sign repainted that's on the street pavement
Bruce Elementary	3/28/2024 15:41	BURCHETT	Painting	WO1011269	Classroom 118 need painting
Bruce Elementary	3/28/2024 15:41	BURCHETT	Painting	WO1011270	, ,
•			· ·		Please replace 2 windows on the front of building.
Caldwell Guthrie Elementary	9/6/2024 9:12	STEPHENS	Carpentry	Z1-031275	
Caldwell Guthrie Elementary	8/8/2024 9:53	ARNOLD	Carpentry	Z1-026344	ing for the seven stained ceiling tiles to be replaced. The tiles are located in the stairwell on the Chelsea side, and a scaffold is needed.
					We are having a Lu Interactive Playground installed in the Multipurpose Room and we need
					an ethernet drop installed in the designated area.
Caldwell Guthrie Elementary	10/18/2024 16:25		Electrical	Z1-037540	
					We are having a Lu Interactive Playground installed in the Multipurpose Room and we need
					an electrical outlet installed in the designated area.
Caldwell Guthrie Elementary	10/18/2024 16:22		Electrical	Z1-037539	
Caldwell Guthrie Elementary	10/2/2024 14:59	CHALK	Electrical	Z1-035961	Lights on pole not working in parking lot.
Caldwell Guthrie Elementary	10/2/2024 14:58	CHALK	Electrical	Z1-035960	Lights on pole not working in parking lot
Caldwell Guthrie Elementary	10/2/2024 14:56	CHALK	Electrical	Z1-035959	Lights on pole not working in parking lot.
Caldwell Guthrie Elementary	9/26/2024 10:38	ANDREWS	Electrical	Z1-034893	Ballast out in office closet BREAKER #8 - IN THE CAFE - KEEPS TRIPPING PM/HESTER - 236-0105
Caldwell Guthria Elementer	8/9/2024 8:49	ANDREWS	Electrical	Z1-026599	DILANCIN #0 - IIV THE CAFE - NEEFS TRIFFIING FINHESTER - 230-U103
Caldwell Guthrie Elementary Caldwell Guthrie Elementary	8/9/2024 8:49	ANDREWS	Electrical	Z1-026599 Z1-026462	ights within the Music Room need to be replaced. A lift is needed. Please see Plant Manger Hester
Caldwell Guthrie Elementary	7/29/2024 13:55	ANDREWS	Electrical	Z1-020402 Z1-023297	Emergency lights need to be installed in Pre-k classroom
Caldwell Guthrie Elementary	9/20/2024 10:32	ANDILLYS	Elevators	Z1-023297 Z1-033971	Elevator phone not working
Salawell Guillio Elementary	5.20/2024 10.24		Licrators	21 0000/1	Eletator priorie not working

Good morning. I'm sending a request to have 3 sets of keys made for our school. We have a new evening custodial lead who needs a set, a set for our outside lock box so security can have access to the building if needed, and a set to keep in the assistant principal lock box to have on hand. thank you so much and have a great day.

Arthur Hollingshed, Plant Manager

					Arthur Hollingshed, Plant Manager
Caldwell Guthrie Elementary	12/6/2024 8:10	MALONE	Key & Lock	Z1-043725	
					Good afternoon. I'm submitting a request for a broken window (glass) to be replaced in the
					boys restroom on the west hallway upstairs which is the middle school hallway. It's been
					temporarily covered but needs replacing. Thanks for your help.
					Arthur Hollingshed, Plant Manager
Caldwell Guthrie Elementary	12/10/2024 14:58		Shades/Blinds	Z1-044359	
					pick up used fluorescent bulbs
Central High	12/15/2024 19:12	CRUTCHER	Asbestos	Z1-044941	
Central High	5/15/2024 8:00	STOWE	Audio Visual	Z1-014608	Intercom system for this classroom isn't working.
					,
					Please provide electrical circuit and install heat trace on domestic water line in boiler room.
Central High	12/16/2024 8:04	STEPHENS	Electrical	Z1-044971	rease provide electrical circuit and install near race on domestic water line in botter room.
_					
Central High	12/2/2024 10:52	ANDREWS	Electrical	Z1-042448	Cafeteria manager's office light fixtures in the restroom needs a ballast.
Central High	11/25/2024 8:26	ANDREWS	Electrical	Z1-042153	Cab lights aren't working in elevator.
Central High	11/18/2024 11:15	ANDREWS	Electrical	Z1-041280	Risk Management Assessment, requesting ceiling panel to cover exposed lighting in the elevator.
Central High	11/18/2024 11:13	ANDREWS	Electrical	Z1-041276	Per Risk Management Assessment, requesting electrical panel in the utility closet be labeled.
Central High	11/18/2024 11:11	ANDREWS	Electrical	Z1-041273	Per Risk Management Assessment, requesting junction box cover for exposed wiring.
Central High	9/16/2024 7:26	ANDREWS	Electrical	Z1-032767	5 light fixtures have bad ballasts
oontract light	0/10/2024 / 120	7.11.011.2110	Etotriout	21 002/0/	o agriculturo da da datable
					PURCHASE AND REPLACE SURGE PROTECTOR FOR BREAKER PANEL ON 2ND FLOOR
					PURCHASE AND REPLACE SURGE PROTECTOR FOR BREAKER PAINEL ON 2ND FLOOR
Central High	3/26/2024 9:37	ANDREWS	Electrical	Z1-006319	
					Emergency light in gym at the south exit not working. Per POCA.
Central High	3/12/2024 9:24	ANDREWS	Electrical	Z1-004882	
Central High	2/3/2024 14:43	CHALK	Electrical	WO1030650	Control panel that controls the auditorium lights overheated due to hot water pipe burst.
					Requesting annual sprinkler system report per Fire Marshal poca
Central High	10/22/2024 10:05	GREER	Fire Alarm System	Z1-037800	., 0,,,,,
Central High	5/29/2024 9:59	CASEY	Flooring	Z1-016270	Missing floor tiles in this electroom
_					Missing floor tiles in this classroom.
Central High	5/29/2024 9:57	BENTON	Flooring	Z1-016269	Missing floor tiles in this classroom.
					HVAC UNIT IN RM C116 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:30	WEBB	Heating/Ventilation/Air Conditioning	Z1-043004	
					HVAC UNIT IN RM C115 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:30	WEBB	Heating/Ventilation/Air Conditioning	Z1-043003	
_					HVAC UNIT IN RM C114 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:29	WEBB	Heating/Ventilation/Air Conditioning	Z1-043001	
Centrat riigii	12/3/2024 13.23	WLDD	rieating/ventitation/All Conditioning	21-043001	HVAC UNIT IN RM C23 - NOT HEATING PM/CHANDLER 416-4500
	40/0/00044000	14/500		74 040000	NVAC UNIT IN KIM C23 - NOT REALING PM/CHANDLER 410-4300
Central High	12/3/2024 13:28	WEBB	Heating/Ventilation/Air Conditioning	Z1-043000	
					HVAC UNIT IN RM C21- NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:27	WEBB	Heating/Ventilation/Air Conditioning	Z1-042999	
					HVAC UNIT IN RM C22 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:26	WEBB	Heating/Ventilation/Air Conditioning	Z1-042997	
					HVAC UNIT IN RM C12 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:25	WEBB	Heating/Ventilation/Air Conditioning	Z1-042996	
Centratriigh	12/3/2024 13.23	WEDD	riedding/ventitation/Air Conditioning	21-042330	LIVAC LINIT IN DM C11 NOT LIFATING DM/CLIANIDI ED 410 4500
					HVAC UNIT IN RM C11 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:25	WEBB	Heating/Ventilation/Air Conditioning	Z1-042995	
					HVAC UNIT IN RM C10 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:24	WEBB	Heating/Ventilation/Air Conditioning	Z1-042994	
					HVAC UNIT IN RM D113 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:24	WEBB	Heating/Ventilation/Air Conditioning	Z1-042993	
0			0		HVAC UNIT IN RM D112 - NOT HEATING PM/CHANDLER 416-4500
Control High	10/0/0004 10:00	WEDD	Heating/Ventilation/Air Conditioning	71 042002	TIMO ON INTERPOLATION DE PROPERTIES AUGUSTA
Central High	12/3/2024 13:23	WEBB	Heating/Ventilation/Air Conditioning	Z1-042992	LIVAC LINIT IN DM DOC. NOT UEATING DM/CHANDLED 446 4700
					HVAC UNIT IN RM D36 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:23	WEBB	Heating/Ventilation/Air Conditioning	Z1-042991	
					HVAC UNIT IN RM D35 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:22	WEBB	Heating/Ventilation/Air Conditioning	Z1-042989	
					HVAC UNIT IN RM D34 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:22	WEBB	Heating/Ventilation/Air Conditioning	Z1-042987	
	-		0		



					UNIO UNIT IN DIVIDES AND UTFATING DAYOUAND FR. 440, 4500
Control High	12/3/2024 13:21	WEBB	Heating Montilation / Air Conditioning	Z1-042986	HVAC UNIT IN RM D33 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13.21	VVEDD	Heating/Ventilation/Air Conditioning	21-042980	HVAC UNIT IN RM D32 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:20	WEBB	Heating/Ventilation/Air Conditioning	Z1-042984	NVAC UNIT IN Nº DOZ - NOT REALING FINCHANDLES 410-4300
Ochtatriigh	12/0/2024 10:20	WEDD	ricadily ventuation/air conditioning	21 042504	HVAC UNIT IN RM D31 - NOT HEATING PM/CHANDLER 416-4500
Central High	12/3/2024 13:20	WEBB	Heating/Ventilation/Air Conditioning	Z1-042982	
22					PULL STRAINER
Central High	10/15/2024 6:49	WEBB	Heating/Ventilation/Air Conditioning	Z1-036947	
Central High	11/18/2024 11:16	BURCHETT	Masonry	Z1-041283	Risk Management Assessment, requesting repair of wall near water fountain with exposed pipes.
Central High	11/18/2024 11:06	BURCHETT	Masonry	Z1-041269	'er Risk Management Assessment, brick wall outside of kitchen is cracking and showing rebar.
Central High	11/18/2024 11:04	BURCHETT	Masonry	Z1-041267	isk Management Assessment, wall is cracking outside of band room building near Crump Stadium.
Central High	11/20/2024 10:55	BURCHETT	Painting	Z1-041713	Requesting wall be painted in this room
Central High	8/9/2024 8:17	BURCHETT	Painting	Z1-026572	Requesting walls be painted.
Central High	7/24/2024 8:50	BURCHETT	Painting	Z1-022273	Requesting wall behind the fire door near 106 be painted due to wall being repaired.
Central High	7/16/2024 9:02	BURCHETT	Painting	Z1-021333	Requesting wall outside of weight room be painted
Central High	2/3/2024 16:41	BURCHETT	Painting	WO1021779	Requesting the walls to be painted in this classroom due to the paint chipping on the walls.
Central High	5/17/2024 14:32	BURCHETT	Painting	WO1015360	Requesting the A hallway be painted.
					SINK DETACHED FROM WALL & BROKEN IN PIECES ON THE FLOORBOYS RESTROOM, 2ND
					FLOOR NEAR CL-RM 218,P/M JOHN CHANDLER 416-4500
Central High	10/8/2024 10:23	SINK	Plumbing	Z1-036608	Out to describ
On water of I like the	9/11/2024 8:48	JOHNSON	Dell He Deser	Z1-031898	Custom door unit
Central High	9/11/2024 8:48	JUHNSUN	Roll Up Doors	21-031898	mR. dAVIS, 65830 CEILING CAVED IN DUE TO RAIN
Charakaa Flamantan	11/14/2024 8:33	FORD	Coments	Z4-040771	IIIR. UAVIS, 0303U CEILING CAVED IN DUE 10 HAIIN
Cherokee Elementary	11/14/2024 6.33	FURD	Carpentry	24-040//1	column wood needs replaced at foundation
Cherokee Elementary	4/15/2024 10:15	FORD	Carpentry	Z4-009242	Column wood needs replaced at roundation
Cherokee Elementary	3/28/2024 15:41	SMITH	Key & Lock	WO1012525	lock not working properly admin keys will not open this exterior door
Cherokee Elementary	4/1/2024 10:52	CORONADO	Masonry	Z4-006988	Need hole filled in on brick wall
Onoroido Etomontary	-1/1/202-1 10:02	00110111100	,	24 000000	Need wood that was replaced on front door to be painted
Cherokee Elementary	10/30/2024 12:45	HARRIS	Painting	Z4-038950	Note and the operation of the first section of the
,					Need main hall painted
Cherokee Elementary	4/2/2024 13:29	HARRIS	Painting	Z4-007387	
ŕ			· ·		Need cafe painted
Cherokee Elementary	4/2/2024 13:29	HARRIS	Painting	Z4-007386	
					Prek room has chipped paint above door
Cherokee Elementary	2/29/2024 10:39	YOUNG	Painting	Z4-003379	
Cherokee Elementary	11/20/2024 10:39	JOHNSON	Plumbing	Z4-041701	Faucet need new washers water will not turn completely off
Cherokee Elementary	11/1/2024 11:09	JOHNSON	Plumbing	Z4-039255	Have three spouts washers need changing water will not shut off
Cherokee Elementary	10/24/2024 12:10	JOHNSON	Plumbing	Z4-038210	Urinal pipe has been pulled off of wall and at urinal
Cherokee Elementary	10/21/2024 13:26	JOHNSON	Plumbing	Z4-037692	Ice machine water line leaks when it is turned on
					annual testing of 2- backflow preventers
Cherokee Elementary	10/3/2024 13:43	WILSON	Plumbing	Z4-036153	
					COMMODE IS CONSTANTLY RUNNING & WATER IS OVER FLOWING ONTO THE FLOOR - BOYS RESTROOM NEAR CL-RM 145
					P/M LAMONT DAVIS 416-5028
Cherokee Elementary	9/10/2024 8:30	TEDDER	Plumbing	Z4-031660	THE ENTITY DAYS 410-0026
Cherokee Elementary	11/6/2024 11:51	GILL	Roofing	Z4-031000 Z4-039878	Roof leak in middle of floor
Cherokee Elementary	11/14/2024 13:02	GILL	Roofing	Z4-040887	Roof leak in this room
Cherokee Elementary	11/6/2024 11:52	GILL	Roofing	Z4-039879	Roof leak in this foyer area
Cherokee Elementary	11/6/2024 11:49	GILL	Roofing	Z4-039877	Roof leak in this room
Cherokee Elementary	11/6/2024 11:49	GILL	Roofing	Z4-039876	Roof leak in this office
Cherokee Elementary	11/1/2024 11:06	GILL	Roofing	Z4-039253	Roof leak
Cherokee Elementary	5/17/2024 14:30	BENTON	Shades/Blinds	WO1013492	need blinds brackets installed for black out roll up shades
Chickasaw Middle	6/17/2024 11:27	CALDWELL	Bleachers and Seats	Z4-018566	Bleachers need new inspection last inspected May/11/23 fire marshals request, 6/17/24
Chickasaw Middle	12/4/2024 8:29	ARNOLD	Carpentry	Z4-043143	Stall door needs to be replaced
Chickasaw Middle	12/4/2024 8:28	ARNOLD	Carpentry	Z4-043141	Need to replace the closer and adjust the door
Chickasaw Middle	9/4/2024 10:05	ARNOLD	Carpentry	Z4-030861	Stall door torn from the wall needs to be replaced
Chickasaw Middle	9/4/2024 10:01	ARNOLD	Carpentry	Z4-030859	Jim floor swelling up from water damage
Chickasaw Middle	11/1/2024 9:38	HALL	Electrical	Z4-039228	We have a light in the hallway that blinking on and off
Chickasaw Middle	9/6/2024 13:29	HALL	Electrical	Z4-031352	Like gas and water poles lights out 168901 pole number
	0.04.00		.	7	Drinking fountain outlet is out
Chickasaw Middle	3/21/2024 6:29	HALL	Electrical	Z4-005635	
Chickasaw Middle	9/27/2024 14:22	CALDWELL	Elevators	Z4-035211	Elevator door will not close

Chickasaw Middle	12/2/2024 10:41	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-042439	Chickasaw MS Rooms isn`t heating
Cilickasaw Middle	12/2/2024 10.41	MADUNATUM	neating/ventitation/Air Conditioning	24-042439	Chickasaw MS Rooms isn`t heating
Chickasaw Middle	12/2/2024 10:40	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-042437	Cilicadaw Pio Noullis Isli Ciledung
Cilickasaw Filadie	12/2/2024 10.40	PIADONATOP	rieating ventilation/Air Conditioning	24-042437	Chickasaw MS Rooms isn`t heating
Chickasaw Middle	12/2/2024 10:39	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-042435	Cilicadaw Pio Nooillo Isii Ciledung
Cilickasaw Filidate	12/2/2024 10:55	PIADONATOP	rieding/ventitation/Air Conditioning	24-042433	Chickasaw MS Rooms isn't heating
Chickasaw Middle	12/2/2024 10:38	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-042434	Citization Control of
Chickasaw Middle	12/10/2024 11:45	MALONE	Key & Lock		d keys cut for 202204. It is one wrong but we also need the keys cut for the closets for the PLC coach.
Sinchasan Finans	12,10,202411.40	1 11 120112	No, a 250N	2.7 0.7.1200	The Zone 4 Office Need Keys to the Following Schools Chickasaw MD, Oakhaven Hs/MD,
					Southwest CTC, Westhaven Elementary School,
Chickasaw Middle	10/3/2024 9:18	MALONE	Key & Lock	Z4-036032	
Chickasaw Middle	5/8/2024 7:07	SMITH	Key & Lock	Z4-013555	We need 4 classroom master keys
Chickasaw Middle	3/22/2024 6:20	CORONADO	Masonry	Z4-005822	We have missing wall tile that needs to be replaced
Chickasaw Middle	10/3/2024 7:57	BURCHETT	Painting	Z4-036006	
Chickasaw Middle	9/27/2024 8:59	BURCHETT	Painting	Z4-035041	The health department recommended that we paint the kitchen we have Peeling paint
Chickasaw Middle	5/20/2024 7:25	BURCHETT	Painting	Z4-015111	We have peeling paint in the stairwell that needs to be repainted
Chickasaw Middle	5/20/2024 7:24	BURCHETT	Painting	Z4-015109	We need that restroom painted
Chickasaw Middle	5/14/2024 7:53	BURCHETT	Painting	Z4-014363	We need a third floor hall painted
Chickasaw Middle	12/4/2024 9:55	HARRIS	Plumbing	Z4-043248	Toilet will not stop flushing flush valve
Chickasaw Middle	8/28/2024 8:20	HARRIS	Plumbing	Z4-029951	The faucet on the sink is loose. Had water when I cut off need to be repaired.
Chickasaw Middle	8/27/2024 6:26	HARRIS	Plumbing	Z4-029661	The kids have torn the water fountain from the wall
Chimneyrock Elementary	9/23/2024 8:23	BENTON	Apparent Mold Growth (AMG)		couple of years with the mold situation. Apparently the mold has begun to return. The smell is very noticeable inside of the classroom.
Chimneyrock Elementary	11/6/2024 9:24	SMITH	Audio Visual	Z2-039760	oom 52 isn't working and the volume in the building is low. Safety concern throughout the building.
Chimneyrock Elementary	12/13/2024 13:43	ROY	Carpentry	Z2-044920	Crash bar need repairing
Chimneyrock Elementary	10/7/2024 13:21	POWELL	Electrical	Z2-036494	Light ballet
Chimneyrock Elementary	10/2/2024 9:14	POWELL	Electrical	Z2-035853	The lights are not working properly outside entering the building.
Chimneyrock Elementary	10/2/2024 9:08	POWELL	Electrical	Z2-035849	The light switch isn't working.
Chimneyrock Elementary	10/2/2024 9:07	POWELL	Electrical	Z2-035848	I have three lights out here n the hallway
Chimneyrock Elementary	9/25/2024 6:38	POWELL	Electrical	Z2-034552	The back side of the annex is extremely dark.
Chimneyrock Elementary	7/26/2024 11:03	POWELL	Electrical	Z2-022894	Teacher's restroom, custodial closet lights isn't working.
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					HEATING UNIT FOR RM 31 - NOT HEATING PM/ATKINS 416-3781
Chimneyrock Elementary	12/12/2024 12:51	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044733	
					HEATING UNIT FOR RM 9 - NOT HEATING PM/ATKINS 416-3781
Chimneyrock Elementary	12/12/2024 12:50	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044732	
					UNIT NOT COMING ON - CL-RM 63
					P/M ATKINS 416-3781
Chimneyrock Elementary	12/6/2024 8:26	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043735	
					HEATING UNIT FOR RM 39 - NOT HEATING PM/ATKINS 416-3781
Chimneyrock Elementary	12/6/2024 7:46	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043715	
					HEATING UNIT FOR RM 44 - NOT HEATING PM/ATKINS 416-3781
Chimneyrock Elementary	12/6/2024 7:45	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043714	
					HEATING UNIT FOR RM 10 - NOT HEATING PM/ATKINS 416-3781
Chimneyrock Elementary	12/6/2024 7:45	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043713	
					HEATING UNIT FOR RM 35 - NOT HEATING PM/ATKINS 416-3781
Chimneyrock Elementary	12/6/2024 7:44	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043712	
					Mr. Atkins (416 3781) Chimney Rock 2 rms Blowing cold Air (Nursing Station)
Chimneyrock Elementary	12/3/2024 13:55	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043019	
Chimneyrock Elementary	10/2/2024 8:44	MALONE	Key & Lock	Z2-035838	I need a key to the plant manager's office, main office, room 21 and room 8
Chimneyrock Elementary	4/9/2024 7:22	CORONADO	Masonry	Z2-008258	There is still a hole in the wall since the first of last year. When new sinks were installed.
Chimneyrock Elementary	7/10/2024 15:37	BURCHETT	Painting	Z2-020818	The administration parking spots need repainting.
Colonial Hearing and Vision Center	10/29/2024 11:34	SCOTT	Electrical	Z3-038728	Lights are out making it hard for the employees in the back to work
Colonial Hearing and Vision Center	2/3/2024 16:42	Admin	Fire Alarm System		POCA- Replace missing sprinkler head rings in hallway in front of custodial door-Room H128.
Colonial Middle	9/26/2024 12:55	WEBB	Carpentry	Z3-034936	Ceiling tile needs replacing. Lift is required
Colonial Middle	9/26/2024 12:55	WEBB	Carpentry	Z3-034935	Ceiling tiles need replacing. A lift is needed
Colonial Middle	9/26/2024 12:53	WEBB	Carpentry	Z3-034934	Ceiling tile needs to be replaced. A lift is required
Colonial Middle	9/26/2024 10:26	BARNES	Carpentry	Z3-034880	Ceiling tiles in auditorium need to be replaced. A lift will be required.
					Ceiling tiles in the Auditorium needs to be replaced. A lift is required and there is a total of
Coloni-1Middle	7/15/0004 40:40	DADNES	Correction	70.004040	13 tiles that I can see needing replacing.
Colonial Middle Colonial Middle	7/15/2024 10:49 12/10/2024 10:11	BARNES SCOTT	Carpentry Electrical	Z3-021210 Z3-044245	Emergency lights need new bulbs. A lift is required
Colonial Middle	12/10/2024 10:11	SCOTT	Electrical	Z3-044245 Z3-044243	Emergency lights need new bulbs. A lift is required Emergency lights need new bulbs. A lift is required
Colonial Middle	12/10/2024 10:09	SCOTT	Electrical	Z3-044243 Z3-041449	Emergency lights are not working
Colonial Middle Colonial Middle	11/19/2024 9:22	SCOTT	Electrical	Z3-041449 Z3-041448	Emergency lights are not working Emergency lights are not working
Cotomat Plique	11/10/2024 3.20	30011	LIGGITUAL	£0-041440	Lines gency ugits are not working

Colonial Middle	11/19/2024 9:19	SCOTT	Flectrical	73-041445	Emergency lights are not working
Colonial Middle	11/7/2024 12:58	SCOTT	Electrical	Z3-041443	Lights need to be replaced. A lift is required
Colonial Middle	10/24/2024 9:35	SCOTT	Electrical	Z3-040142 Z3-038140	Bell System is not working
Colonial Middle	9/26/2024 13:15	SCOTT	Electrical	Z3-036140 Z3-034946	
					Lights need to be replaced. A lift is required
Colonial Middle	9/26/2024 13:13	SCOTT	Electrical	Z3-034944	Lights need to be replaced on an upper level. A lift or 12 ft ladder is required
Colonial Middle	9/26/2024 13:10	SCOTT	Electrical	Z3-034942	Lights need to be replaced. A lift is required
Colonial Middle	9/26/2024 12:52	SCOTT	Electrical	Z3-034933	Stairwell lights need to be replaced. A lift is required
Colonial Middle	9/26/2024 12:51	SCOTT	Electrical	Z3-034932	staircase lights need to be replaced. Lift is required
Colonial Middle	9/26/2024 10:28	SCOTT	Electrical	Z3-034884	Lights in gym need to be replaced. Requires a lift.
Colonial Middle	9/26/2024 10:27	SCOTT	Electrical	Z3-034882	Lights in auditorium need to be replaced. A lift is required.
Colonial Middle	9/12/2024 8:15	SCOTT	Electrical	Z3-032101	Small kitchen serving line won't turn on
Colonial Middle	8/15/2024 13:52	SCOTT	Electrical	Z3-027876	:kets go out in main office area. 1 in A133 and the other 2 in the main office behind the desk to the left.
					Auditorium lights flicker on and off. Some auditorium lights are also out and need changing.
					A lift is required.
Colonial Middle	8/1/2024 14:30	SCOTT	Electrical	Z3-024555	
					In the back area, there are multiple lights that don't work even when replaced with new
					butbs
Colonial Middle	8/1/2024 10:46	SCOTT	Electrical	Z3-024394	
					Pendant Light Needs to be changed in front of the main office.A104.
Colonial Middle	3/26/2024 8:06	SCOTT	Electrical	Z3-006280	
					Top floor elevator door button is not working but the bottom one is working normal
Colonial Middle	12/4/2024 10:18	SMALL	Elevators	Z3-043276	
Ootomat maato	12/1/2021 10/10	01 11 12 2	Elevatoro	20 040270	
					Elevator stopped working. Light comes on when button is pushed but nothing happens.
Colonial Middle	11/14/2024 9:58	SMALL	Elevators	Z3-040812	
Colonial Middle	9/16/2024 14:01	SMALL	Elevators	Z3-033008	Elevator is none operation
Colonial Middle	11/7/2024 10:09	SMALL	Fire Alarm System	Z3-040094	Fire Alarm Inspection is needed
Colonial Middle	9/27/2024 11:24	SMALL	Fire Alarm System	Z3-035136	y morning indicating that there's trouble in certain locations shown on the screen. Locations listed are in the photos.
Cotonial Middle	9/2//2024 11.24	SMALL	File Alailli System	23-033130	y morning mulcating that there is trouble in certain locations shown on the screen. Locations used are in the photos.
					Pull Station was accidentally pulled by vendors, and they pulled the whole case out the wall
					to shut it off. It needs to be replaced. Panel states: 07:02:00, A0020, D0000, n0001,
					Supervisory Act, Mb Duct Det Corr N Of Aud W End Supply, 0001 e Supervisory Act Mb Duct
					det Corr N Of Aud W End Supply, A000 S0001 T 018 M000, alarm panel was beeping had to
					be silenced, the Sup, trouble was blinking.
Colonial Middle	7/24/2024 9:41	SMALL	Fire Alarm System	Z3-022296	
					We are requesting a work order for Colonial Middle School. Our techs located (5) fire
					sprinkler heads in the kitchen, (2) fire sprinkler heads at room B131 and room B113, and (2)
					at B hallway and B107. All (9) fire sprinkler heads are ½" white 155-degree QR. Price to
					replace \$1,482.00.
Colonial Middle	4/8/2024 13:53	SMALL	Fire Alarm System	Z3-008218	
Colonial Middle	12/2/2024 9:36	WALLACE	Heating/Ventilation/Air Conditioning	Z3-042358	Vent is blowing Cold Air on Heat setting
Colonial Middle	12/2/2024 9:34	WALLACE	Heating/Ventilation/Air Conditioning	Z3-042355	Vent is blowing Cold Air on Heat setting
Colonial Middle	11/6/2024 11:23	WALLACE	Heating/Ventilation/Air Conditioning	Z3-039861	Room not cooling
					Heavy leak, water can be heard constantly hitting the ceiling tile (HVAC ROOF TOP UNIT
					LEAKING)
Colonial Middle	9/27/2024 12:12	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-035158	
					Water is leaking onto the floor (HVAC UNIT LEAKING)
Colonial Middle	9/13/2024 11:15	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-032662	
					HVAC UNIT FOR THE GYM - NOT COOLING PM/HOWARD 416-8980
Colonial Middle	8/5/2024 10:04	Solutions	Heating/Ventilation/Air Conditioning	Z3-025201	
					HVAC UNIT IN RM F232 - NOT COOLING PM/HOWARD 416-8980
Colonial Middle	8/5/2024 10:03	Solutions	Heating/Ventilation/Air Conditioning	Z3-025199	
					Thermostat not working
Colonial Middle	8/1/2024 11:27	JOHNSON	Heating/Ventilation/Air Conditioning	Z3-024422	· · · · · · · · · · · · · · · · · · ·
					Thermostat not working
Colonial Middle	8/1/2024 11:25	Waller	Heating/Ventilation/Air Conditioning	Z3-024420	• • • • •
Ootomatimatic	0/1/2024 11:20	Watter	ricading vendudonizar conditioning	20 024420	Check HVAC units operation
Colonial Middle	4/12/2024 7:40	Solutions	Heating/Ventilation/Air Conditioning	Z3-008953	onout the anno spoudon
Colonial Middle	11/15/2024 11:47	MALONE	Key & Lock	Z3-000333	Need locks changed & 5 keys to go along with it
Colonial Middle	10/25/2024 11.47	MALONE			
			Key & Lock	Z3-038317	er received new keys for this room. I need the locks changed with 5 keys to go with it. Previous work order number is #Z3-033824
Colonial Middle	10/25/2024 8:56	MALONE	Key & Lock	Z3-038313	I only received 1 key and it doesn't work to the dressing room door
Onlanda Middle	0/40/000440.50	MALONE	Key 0 Leads	70.000000	I need the lock changed on this door with 4 keys made to go with it
Colonial Middle	9/19/2024 13:59	MALONE	Key & Lock	Z3-033823	

					I need 2 keys made for this room
Colonial Middle	8/12/2024 8:03	SMITH	Key & Lock	Z3-026859	Tilleed 2 keys made for this foom
			, 2 2001		Main office right side door doesn't work properly. The push bar on door is stuck in which
					doesn't allow the door to be lock closed.
Colonial Middle	7/24/2024 8:45	SMITH	Key & Lock	Z3-022270	
					Locker 1363 doesn't close all the way properly. The locker is located on A hall in between
Colonial Middle	7/15/2024 9:28	SMITH	Key & Lock	Z3-021158	classes A138 and A137.
Cotomat Pildate	7/15/2024 5.20	Ji-IIIII	Rey & Lock	25-021150	got new equipment Principal is requesting locks to be rekeyed, need 4 keys
Colonial Middle	6/18/2024 8:36	SMITH	Key & Lock	Z3-018687	0
					requesting handrails be painted
Colonial Middle	6/18/2024 9:01	BURCHETT	Painting	Z3-018699	
					requesting front steps be painted
Colonial Middle Colonial Middle	6/18/2024 8:39 12/9/2024 10:49	BURCHETT PEARSON	Painting Plumbing	Z3-018690 Z3-044041	Water fountain isn't working
			_		0
Colonial Middle	8/26/2024 10:37	BARNES	Plumbing	Z3-029535	Water in fountain won't drain bottle filler ready for inspections
					bottle filler ready for hispections
Colonial Middle	6/8/2024 8:47	WILSON	Plumbing	Z3-017766	
			3		Power out on the left side of the hallways/classrooms
Cordova Elementary	11/8/2024 8:05	POWELL	Electrical	Z2-040235	
Cordova Elementary	9/13/2024 9:02	POWELL	Electrical	Z2-032524	Please fix
Cordova Elementary	8/20/2024 12:03	POWELL	Electrical	Z2-028668	Wall outlet doesn't work
Cordova Elementary	8/12/2024 12:40	POWELL	Electrical	Z2-027022	No power on one side of the classroom
-					elevator is constantly buzzing.
Cordova Elementary	5/2/2024 15:01	Coleman	Elevators	Z2-012867	
Cordova Elementary	10/15/2024 8:35	Coleman	Fire Alarm System	Z2-036992	Replace center NAC, Right NAC Batteries these NACS are above the FACP
					Replace FACP and Remote Power Panel Batteries
Cordova Elementary	10/15/2024 8:33	Coleman	Fire Alarm System	Z2-036990	
					Mr. jones 62700 no heat
Cordova Elementary	12/2/2024 13:54	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042577	
0	40/0/000440-50	DDVCON	Hanking Of antitution (Air One distance	70.040570	Mr. jones 62700 no heat
Cordova Elementary	12/2/2024 13:53	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042576	Mr. jones 62700
Cordova Elementary	12/2/2024 13:52	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042575	Fil. Julies 02700
Cordova Elomontary	12/2/2024 10/02	51110011	riodanily vonditudes in a conditioning	22 0 12070	Chilled water valve leaking
Cordova Elementary	11/15/2024 7:07	BRYSON	Heating/Ventilation/Air Conditioning	Z2-040984	•
•					HVAC UNIT FOR RM A203 - NOT COMING ON PM/JONES 416-1700
Cordova Elementary	11/6/2024 13:06	BRYSON	Heating/Ventilation/Air Conditioning	Z2-039910	
Cordova Elementary	12/13/2024 9:00	MALONE	Key & Lock	Z2-044850	Requesting for a replacement key for room D209
Cordova Elementary	8/28/2024 10:29	BURCHETT	Painting	Z2-030028	lines are very light in the front of the building but lines need to be also updated at the back parking lot as well.
Cordova Elementary	8/28/2024 7:26	BURCHETT	Painting	Z2-029914	Hole was patched now it needs to be painted
Cordova Elementary	3/28/2024 15:44	BURCHETT	Painting	WO1006504	Request for room D202 to be painted. Thanks!
Cordova Elementary	3/28/2024 15:44	BURCHETT	Painting	WO1006490	School needs a new paint job hallways and restrooms.
					test back flow
Cordova Elementary	6/4/2024 6:56	PILKINGTON	Plumbing	Z2-017010	
Cordova Elementary	11/6/2024 7:49	LEWIS	Roofing	Z2-039694	Roof back leaking
Cordova Elementary	9/16/2024 12:34	LEWIS	Roofing	Z2-032949	Ceiling leaking again (different spot)
					pipe leaking above ceiling
Cordova Elementary	11/14/2024 7:00	CARLOS	Welding	Z2-040734	Outstand and the second about the second and second about the second about
					Contact can't be made by the neither the main and attendance offices and the bells can't be heard in room.
Cordova High School	12/6/2024 13:43	SMITH	Audio Visual	Z2-043859	ilealu III Ioolii.
Cordova riigii School	12/0/2024 13.43	Simili	Addio Visual	22-043033	Microphone jack isn't working.
Cordova High School	7/30/2024 13:25	SMITH	Audio Visual	Z2-023804	,
0					Bleachers aren't letting in/out in a straight line. Plant mgr. noticed a broken screw wheel
					barring,
Cordova High School	8/24/2024 21:09	Coleman	Bleachers and Seats	Z2-029351	
					Replace ceiling tiles.
Cordova High School	9/24/2024 12:08	STAFFORD	Carpentry	Z2-034482	
					Electrical outlet needs to be repaired.
Cordova High School	11/21/2024 14:05	POWELL	Electrical	Z2-041985	
Orași a din	44 140 1000 1000	DOM:	Et	70.01100	Replace ballast in light fixture and the motion light switch isn't working.
Cordova High School	11/18/2024 9:31	POWELL	Electrical	Z2-041222	

Cordova High School	11/14/2024 13:58	POWELL	Electrical	Z2-040906	One of the goals won't let down.
Cordova High School	10/21/2024 11:11	POWELL	Electrical	Z2-037672	Outlet under steam table is damaged.
Cordova High School	9/9/2024 10:03	POWELL	Electrical	Z2-031484	Replace ballast in light fixture.
-		POWELL			Light switch to turn on/off lights is very hard to turn on.
Cordova High School	8/12/2024 7:33		Electrical	Z2-026835	Exposed wires under bleachers.
Cordova High School	8/9/2024 9:21	POWELL	Electrical	Z2-026628	Multiple light fixtures need bulbs/ballast Replaced. Light fixtures have special screws that
Cordova High School	7/16/2024 10:01	POWELL	Electrical	Z2-021352	plant mgr. doesn't have the tool to unlocked them.
Cordova High School	6/28/2024 12:44	POWELL	Electrical	Z2-019786	Replace the ballast in light fixture.
Cordova High School	5/23/2024 10:50	POWELL	Electrical	Z2-015837	Replace the ballasts in a few light fixtures.
Ů					Electrical outlet need repairs.
Cordova High School	5/23/2024 10:47	POWELL	Electrical	Z2-015835	Replace bulbs/ballasts in multiple light fixtures. A lift will be needed.
Cordova High School	5/22/2024 13:01	POWELL	Electrical	Z2-015695	Light cover fell off and broke as I was changing bulbs.
Cordova High School	5/2/2024 9:35	POWELL	Electrical	Z2-012720	Magnetic contact is broken and the door won't stay open.
Cordova High School	2/6/2024 13:04	POWELL	Electrical	Z2-000407	1st floor section d west sprinkler and card 2 power supply/charger keeps going to trouble on
					the alarm panel.
Cordova High School	12/13/2024 10:22		Fire Alarm System	Z2-044875	1st floor Section D Sprinkler showing trouble/no answer
					Northwest Outside Post Valve showing Abnormal Riser room stickers are needed
Cordova High School	11/6/2024 10:02	Coleman	Fire Alarm System	Z2-039807	A strobe light in each gym is broken.
Cordova High School	11/1/2024 13:22	Coleman	Fire Alarm System	Z2-039301	Strobe light is broken.
Cordova High School	8/21/2024 10:32	Coleman	Fire Alarm System	Z2-028879	Strobe light is broken.
Cordova High School	2/3/2024 17:01	Contractor	Fire Alarm System		irwell door near room 232 isn't releasing and door near room 152 isn't closing when the fire alarm is pulled. P.E. Gym strobe is hanging from the wall.
Cordova High School	11/4/2024 10:01	CASEY	Flooring	Z2-039425	Cracked and/or missing floor tile.
O a mala con I librato O a lo a a l	0/00/000440-00	04057	Floring	70 000070	Replace carpet with floor tile.
Cordova High School Cordova High School	2/20/2024 10:28 3/28/2024 15:44	CASEY CHASE	Flooring Flooring	Z2-002078 WO1011398	Replace carpet in the graduation coach office with new carpet or floor tile.
Cordova High School	3/28/2024 15:44	CHASE	Flooring	WO1011336 WO1001144	Replace carpet with floor tile.
			_		Yearly test is needed.
Cordova High School	10/22/2024 10:02	Coleman	Generators	Z2-037796	After inspection, generator battery had to be replaced.
Cordova High School	2/26/2024 7:09	Coleman	Generators	Z2-002761	UNIT NOT HEATING - CL-RM 106
Cordova High School	12/12/2024 9:55	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044663	P/M WHITELOW 416-2112
-					UNIT NOT HEATING - STAIRWELL AREA NEAR CL-RM 132 P/M WHITELOW 416-2112
Cordova High School	12/4/2024 8:58	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043183	UNIT NOT HEATING - STAIRWELL AREA NEAR CL-RM 123
					DNII NOI REATING - STAINWELL AREA NEAR CL-RIPI 123 P/M WHITELOW 416-2112
Cordova High School	12/4/2024 8:57	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043182	UNIT NOT HEATING - STAIRWELL AREA NEAR CL-RM 120
0 1 15101 /	40///000405-	2010011		70.04045	P/M WHITELOW 416-2112
Cordova High School	12/4/2024 8:56	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043181	UNIT NOT HEATING - STAIRWELL AREA NEAR CL-RM 108
Cordova High School	12/4/2024 8:55	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043180	P/M WHITELOW 416-2112

UNIT NOT HEATING - STAIRWELL AREA NEAR CL-RM 103 P/M WHITELOW 416-2112

					P/M WHITELOW 410-2112
Cordova High School	12/4/2024 8:54	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043177	UNIT NOT COOLING - ATTENDANCE OFFICE P/M WHITELOW 416-2112
Cordova High School	12/4/2024 8:37	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043153	Assistant principal lost her master key.
Cordova High School	7/22/2024 23:22	SMITH	Key & Lock	Z2-022032	, addition principal test for mester help.
Cordova High School	4/19/2024 16:33	SMITH	Key & Lock	Z2-010787	Change cylinder to z-key. Classroom is now an admin office and testing material storage.
Cordova High School	4/19/2024 10:55	SMITH	Key & LUCK	22-010/6/	A key is needed.
Cordova High School	4/18/2024 13:01	SMITH	Key & Lock	Z2-010427	Master key is needed for the fire dept. lock box near the main entrance
Cordova High School	2/23/2024 11:46	SMITH	Key & Lock	Z2-002664	Vent-a-hood isn't working
Cordova High School	11/4/2024 10:07	STAFFORD	Kitchen Hood	Z2-039426	Tone a nood for thomany.
Cordova High School	3/28/2024 15:44	CORONADO	Masonry	WO1010824	A piece of tile near the commode pipe is missing.
oordova riigii oonoot	0/20/2024 20:44	00110111100	· idoomy		Principal want areas painted and is willing to pay for an outside vendor if possible if an
					estimate can be provided.
Cordova High School	9/17/2024 13:15	BURCHETT	Painting	Z2-033251	
			g		Green and white paint is needed to paint over graffiti.
Cordova High School	5/16/2024 7:19	BURCHETT	Painting	Z2-014762	· · · · · · · · · · · · · · · · · · ·
0					Commode in the last stall is leaking water from underneath it.
Cordova High School	12/13/2024 13:09	HARDWAY	Plumbing	Z2-044912	·
-			-		Water is leaking from the pipe on the commode in the handicap stall.
Cordova High School	12/12/2024 14:06	HARDWAY	Plumbing	Z2-044765	
					Middle water fountain isn't working.
Cordova High School	12/12/2024 7:33	HARDWAY	Plumbing	Z2-044533	
					Commode handle is broken and won't flush commode.
Cordova High School	12/12/2024 7:28	HARDWAY	Plumbing	Z2-044531	
					Center section Row C and Seats 11 & 12 chair backs are broken.
Cordova High School	12/13/2024 12:47	WHITE	Sheet Metal	Z2-044904	
					Light sensory goes out extremely fast in this office area.
Cordova Middle	12/9/2024 10:13	POWELL	Electrical	Z2-044027	
					No power to the tvssa receptacle
Cordova Middle	11/21/2024 16:16	POWELL	Electrical	Z2-041997	
		BOWELL	F1 1	70.040444	Bells are not ringing like they suppose to.
Cordova Middle	11/7/2024 13:10	POWELL	Electrical	Z2-040144	4 Fixtures hallaste are out
Cordova Middle	11/5/2024 11:02	POWELL	Electrical	Z2-039605	4 Fixtures ballasts are out.
Cordova Midule	11/5/2024 11.02	POWELL	Electricat	22-039005	3 Fixtures with ballasts out.
Cordova Middle	11/5/2024 8:51	POWELL	Electrical	Z2-039559	3 Fixtures with ballasts out.
Cordova Pildute	11/5/2024 0.51	TOWLLL	Liectificat	22-033333	Ballast out in 4 fixtures in this office area
Cordova Middle	10/23/2024 12:46	POWELL	Electrical	Z2-038024	buttust out in 4 includes in this office area
Cordova i nadic	10/20/2024 12:40	TOWELL	Electricat	22 000024	Four light fixtures with Bad Ballast in this classroom area.
Cordova Middle	10/9/2024 10:56	POWELL	Electrical	Z2-036720	
					Two light fixtures with bad ballast in this classroom.
Cordova Middle	10/9/2024 10:54	POWELL	Electrical	Z2-036719	
					Lights blink constantly even with new bulbs in this fixture
Cordova Middle	9/13/2024 9:34	POWELL	Electrical	Z2-032566	
					Change out relay because lights will not shut off
Cordova Middle	8/1/2024 9:38	POWELL	Electrical	Z2-024322	
					Magnet doors will not latch
Cordova Middle	8/1/2024 9:32	POWELL	Electrical	Z2-024316	
					Ballast out
Cordova Middle	7/30/2024 14:09	POWELL	Electrical	Z2-023842	
O and a see Mill !!	4/00/00010 = 0	DOM/S:	en	70.041005	POCA 2 exit signs doesn't work
Cordova Middle	4/29/2024 8:50	POWELL	Electrical	Z2-011895	Lighte need to be conlessed asfety issue for stoff me
Cardous Middle	2/11/2024 11:25	DOWELL	Floatrical	70.004044	Lights need to be replaced safety issue for staff members
Cordova Middle	3/11/2024 11:35	POWELL	Electrical	Z2-004811	Neede hulke replaced
Cordova Middle	2/21/2024 21:58	POWELL	Electrical	Z2-002408	Needs bulbs replaced
Cordova Middle	2/21/2024 11:05	POWELL	Electrical	Z2-002309	Put in new light bulbs but lights still would not come on.
Cordova Middle	2/19/2024 13:30	POWELL	Electrical	Z2-001952	Ballast out in light Fixtures

Office person say the red Fire alarm located in the classroom area makes a beeping sound on and off.

					on and off.
Cordova Middle	10/21/2024 9:35	Coleman	Fire Alarm System	Z2-037630	
					Replace outdated batteries VAC-1
Cordova Middle	10/14/2024 19:53	Coleman	Fire Alarm System	Z2-036937	
					Replace outdated batteries NAC-1
Cordova Middle	10/14/2024 19:51	Coleman	Fire Alarm System	Z2-036936	
					Repair Line and Conduit that is snapped in half on the PIV.
Cordova Middle	11/19/2024 22:02	Coleman	Fire Sprinkler System	Z2-041575	
					Replaced battery and checked the charger.
Cordova Middle	2/26/2024 7:14	SAVAGE	Generators	Z2-002763	
					UNIT NOT HEATING -CL-RM M30
					P/M EDWARD HOWARD 416-2189
Cordova Middle	12/6/2024 11:14	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043817	
					UNIT NOT HEATING -CL-RM M6
					P/M EDWARD HOWARD 416-2189
Cordova Middle	12/6/2024 11:13	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043816	
			0		UNIT NOT HEATING -CL-RM M5
					P/M EDWARD HOWARD 416-2189
Cordova Middle	12/6/2024 11:13	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043815	
					UNIT NOT HEATING - PRINICIPALS (A8A) & SECRETARIES OFFICE (A8B)
					FEEDING OFF THE SAME UNIT
					P/M EDWARD HOWARD 416-2189
Cordova Middle	12/6/2024 11:11	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043813	THE ESTABLISHED AND ELECTRICAL PROPERTY OF THE
Coracva i nadio	12/0/2024 11/11	5	riouting renatation / at Containing	22 0 10010	Mr. Howard (416 2189) Cordova MS Unit is blowing air but not hot air Rm A8 (Principles
					Office)
Cordova Middle	12/4/2024 9:41	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043231	5.1155)
Cordova i fidale	12/4/2024 0.41	BITTOOIT	ricating ventilation//iii Contationing	22 040201	Mr. Howard (416 2189) Cordova MS Unit is blowing air but not hot air Rm M30
Cordova Middle	12/4/2024 9:39	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043227	The Howard (410 2100) Conduta Fito Chiefs blowing an adenochocal Hill Fito
Cordova i fidale	12/4/2024 0.00	BITTOOIT	ricating ventilation//iii Contationing	22 040227	Mr. Howard (416 2189) Cordova MS Unit is blowing air but not hot air Rm M28
Cordova Middle	12/4/2024 9:38	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043226	Fil. Howard (410 2103) Cordova Fib Officis blowing an buchochocal film Fi20
Cordova Pildute	12/4/2024 5.30	BNISON	neating/ventitation/Air Conditioning	22-043220	UNIT NOT COOLING - CL-RM A11
					P/M MILLER 416-2189
Cordova Middle	12/3/2024 11:13	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042893	F/M MILLER 410-2109
Cordova Pildute	12/3/2024 11.13	BNISON	neating/ventitation/Air Conditioning	22-042093	UNIT NOT COOLING PRINCIPALS OFFICE
					P/M MILLER 416-2189
Cordova Middle	12/3/2024 11:12	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042891	F/M MILLEN 410-2109
Cordova Pildute	12/3/2024 11.12	BNISON	neating/ventitation/Air Conditioning	22-042091	Ms. Miller (2189) blowing air no heat. Cordova MS Gym Area
Cordova Middle	12/2/2024 11:40	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042498	113. Piliter (2103) blowing all no neat. Cordova 113 Cynn Alea
Cordova Pilidite	12/2/2024 11:40	BNISON	neating/ventitation/Air Conditioning	22-042490	Plant Manager Miller reported the HVAC unit in classroom M30 is blowing cold air. 416-
					2189.
Cordova Middle	12/2/2024 9:43	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042368	2100.
Cordova Pilidite	12/2/2024 9.43	DNISON	Heating/Ventitation/All Conditioning	22-042300	Change Over
Cordova Middle	11/13/2024 9:07	BRYSON	Heating/Ventilation/Air Conditioning	Z2-040592	Change Over
Cordova Pilidite	11/13/2024 9.07	DNISON	Heating/Ventitation/All Conditioning	22-040392	I need a set of keys made for HVAC access
Cordova Middle	10/25/2024 7:21	MORRIS	Vau 9 Laak	Z2-038285	Theed a set of keys finade for fivac access
Cordova Pilidite	10/23/2024 /.21	MONNIS	Key & Lock	22-030203	Mondonainting
Cardova Middle	0/10/2024 12:11	DUDCUETT	Deinting	70 001700	Needs painting
Cordova Middle	9/10/2024 12:11	BURCHETT	Painting	Z2-031769	Lially on Area mand mainting throughout the coheal
	0/47/0004444	BUBBUETT		70.040504	Hallway Area need painting throughout the school
Cordova Middle	6/17/2024 11:19	BURCHETT	Painting	Z2-018564	Helboor Assessment data has referred
	F 100 1000 4 0 0 4	BUBBUETT		70.010051	Hallway Areas needs to be painted.
Cordova Middle	5/28/2024 8:24	BURCHETT	Painting	Z2-016051	
Cordova Middle	2/22/2024 13:50	BURCHETT	Painting	Z2-002521	Hallway Area needs painting
Cordova Middle	2/22/2024 13:48	BURCHETT	Painting	Z2-002520	Needs painting in a few Areas
On adams Ohadissas	0/07/000445-50	DOV	0	70 000000	Some sections have rotten wood inside and outside the press box.
Cordova Stadium	8/27/2024 15:53	ROY	Carpentry	Z2-029896	
					Ballasts needs replaced in two light fixtures. One is very so a tall ladder or lift will be
					needed.
Cordova Stadium	8/27/2024 15:47	POWELL	Electrical	Z2-029894	and the second second
	0.04.005		.	70.05	emergency exit light has been damaged
Cordova Stadium	8/21/2024 9:47	POWELL	Electrical	Z2-028859	
Covington Pike Head Start	11/18/2024 8:14	POWELL	Electrical	Z2-041189	Poca- the exit light is out by girls restroom 110.
Covington Pike Head Start	11/6/2024 9:31	POWELL	Electrical	Z2-039770	The 2 exterior lights are out in the front of school.
Covington Pike Head Start	11/6/2024 9:27	POWELL	Electrical	Z2-039764	The exterior light on the north end is out.

					Poca - records required of all inspections and test of fire protection systems.
Covington Pike Head Start	11/15/2024 14:49	Coleman	Fire Alarm System	Z2-041140	Toda - records required of all hispections and test of the protection systems.
0					Poca - Fire Sprinkler System annual service date.
Covington Pike Head Start	11/15/2024 14:15	Coleman	Fire Sprinkler System	Z2-041117	
					Mr. wakefield 69694 Door latch has been broken and door won't lock
Covington Pike Head Start	9/23/2024 10:43	MALONE	Key & Lock	Z2-034193	
Covington Pike Head Start	11/15/2024 14:09	Coleman	Kitchen Hood	Z2-041115	Poca - Hood Suppression Semi- annual service report , Hood and Duct.
Craigmont High	11/7/2024 11:04	STAFFORD	Carpentry	Z2-041115 Z2-040120	Ve need the windows sealed on the south east side of the building due to leaking when it rains.
Craigmont High	9/30/2024 8:14	ROY	Carpentry	Z2-040120 Z2-035319	We have a large cork board that needs to be installed on the wall inside of our data room.
Ordiginoneriign	3/30/2024 0.14	1101	Curpently	22 000010	Replace Gym lighting with new LED fixtures
Craigmont High	12/5/2024 8:03	CHALK	Electrical	Z2-043448	
Craigmont High	12/3/2024 6:21	POWELL	Electrical	Z2-042665	We have a bad receptacle inside of the principal office that needs replacing.
Craigmont High	12/3/2024 6:07	POWELL	Electrical	Z2-042662	The score board port has a shortage and needs to be repaired.
Craigmont High	11/5/2024 8:05	POWELL	Electrical	Z2-039544	Ne have a bad ballast that needs to be replaced inside of the cafeteria manager supply closet.
Craigmont High	10/3/2024 6:10	POWELL	Electrical	Z2-035976	ight switch or transformer replaced for all of the lights to work properly. Half of the classroom lights are out.
					3 lights out in this office
Craigmont High	9/23/2024 13:46	POWELL	Electrical	Z2-034297	
Craigmont High	8/28/2024 9:28	POWELL	Electrical	Z2-029984	Outlet very loose for the plug for ice maker
Craigmont High	8/21/2024 9:33	POWELL	Electrical	Z2-028852	Needs lights put up (floor to the ceiling is about 20ft or higher)
Craigmont High	7/12/2024 11:43	POWELL	Electrical	Z2-021041	Needs lights put in (5 lights out)
Craigmont High	6/20/2024 7:25	POWELL	Electrical	Z2-018840	7 lights out in the library Lights are very high up on the ceiling
Craigment High	4/29/2024 12:05	CHALK	Electrical	Z2-012012	Replace receptacles with GFIC where needed
Craigmont High Craigmont High	12/6/2024 12:49	Coleman	Elevators	Z2-012012 Z2-043835	The elevator is getting stuck in between floors again and not working properly.
Craigmont High	8/16/2024 11:28	Coleman	Fire Alarm System	Z2-043633 Z2-028119	LOCAL TRBL ACT 01020617 POWER Supply Failure
Ordiginoneriign	0/10/2024 11:20	Ooteman	The Admin dystem	22 020110	ECONE INDENOTOTOZOGIA I OWEROUPPRI TURINI
					Per Annual Sprinkler Inspection Report, provide the following:
					(1) Hydrant is seized up and leaking in front of the building.
					(2) Cover plate missing in Girls restroom.
					(3) Sprinkler head leaking in Cafeteria.
					(4) Put locks on all PIVs on property.
					PIV in front of playground is not reporting.
					(6) PIV on panel upon arrival need to be fixed.
					(7) Sprinkler head needs to be dropped in freezer and cooler needs to be changed.
					(8) Escutcheon missing in the kitchen.
					(9) Replace any missing sprinkler heads throughout the building.
Craigmont High	3/20/2024 13:21	Coleman	Fire Sprinkler System	Z2-005588	
Ordiginoneriigii	0/20/2024 10:21	Ooteman	The opinical dystem	22 000000	
					This work order is for the 1st Floor.
					Per State Systems technician (after onsite service work for previous work order): There are
					no drain valves on the fire sprinkler systems for the 3rd Floor or the 1st Floor for sprinkler
					drainage. A new pipes and drains are needed for each floor so they can drain the systems as
					needed. All valves, pipes and associated fittings will be provided for each floor.
Craigmont High	2/3/2024 15:20	Systems	Fire Sprinkler System	WO1029240	
Craigmont High	2/3/2024 17:03	Systems	Fire Sprinkler System	WO1017944	
Craigmont High	3/28/2024 15:36	Systems	Fire Sprinkler System	WO1004803	Replace missing sprinkler head rings throughout the building.
					AHU# 12 NOT HEATING - AFFECTING HALF OF MAIN OFFICE IN THE BACK & 6 CL-RMS
					FEEDING OFF THE SAME UNIT
					P/M ROGERS 416-3312
Craigmont High	12/13/2024 8:33	HAMMETT	Heating/Ventilation/Air Conditioning	Z2-044838	
Craigmont High	12/10/2024 14:24	WILSON	Heating/Ventilation/Air Conditioning	Z2-044348	Boiler pump not working
Craigmont High	11/18/2024 7:44	MALONE	Key & Lock	Z2-041181	We need the cylinder repaired on the door so that it will work properly.
Craigmont High	7/12/2024 12:04	SMITH	Key & Lock	Z2-021047	Locks needs changed (requested by principal)
Craigmont High	7/12/2024 12:02	SMITH	Key & Lock	Z2-021046	Locks needs to be changed (requested by principal)
Craigmont High	5/29/2024 9:57	SMITH	Key & Lock	Z2-016268	Needs a key hole place onto classroom door leads to outside
Craigmont High	11/13/2024 9:22	BURCHETT	Painting	Z2-040603	eteria manager requested that the mop closet be repainted due to pilling paint and health inspection.
Craigmont High	8/3/2024 18:49	BURCHETT	Painting	Z2-024935	Entire classroom need repainted
Craigmont High	7/30/2024 7:39	BURCHETT	Painting	Z2-023563	Classroom needs to be painted
Craigmont High	7/29/2024 14:36	BURCHETT	Painting	Z2-023473	Classroom needs to be painted
0	0/00/00011001	VOLUM	Del et e	70.00000	THE HEAD PRINCIPAL (DR KING) WANTS THE BUILDING PRESSURE WASH
Craigmont High	2/26/2024 13:31	YOUNG	Painting	Z2-002899	

Craigmont High	12/10/2024 11:20	STAFFORD	Plumbing	Z2-044264	We need the eyewash station replaced or repaired properly so that it can function.
Craigmont High	12/5/2024 11:59	STAFFORD	Plumbing	Z2-043604	We need the sink removed from the classroom. (This is a Sped classroom)
Craigmont High	12/5/2024 11:57	STAFFORD	Plumbing	Z2-043603	We need the sink removed from classroom.
Craigmont High	12/5/2024 11:54	PILKINGTON	Plumbing	Z2-043600	The water spout needs replacing outside of the classroom by the green house.
Craigmont High	11/14/2024 10:44	PILKINGTON	Plumbing		e a sink that is leaking inside of the restroom that needs repairing. (3rd floor across from the elevator)
Craigmont High	11/14/2024 10:44	STAFFORD	Plumbing	Z2-040033	We need the hot water repaired for the kids to shower.
Claigillolit High	11/14/2024 0.11	STAFFORD	Fullibilig	22-040727	test backflow
Craigmont High	10/15/2024 10:44	PILKINGTON	Plumbing	Z2-037046	test uduktiow
		PILKINGTON	9		Hattan to the state of the stat
Craigmont High	7/26/2024 14:48		Plumbing	Z2-023006	Hot water for showers
Craigmont High	11/13/2024 9:36	LEWIS	Roofing	Z2-040611	We have a roof leak that needs repairing located inside of the gym east end above bleachers.
Craigmont Middle	12/11/2024 7:02		Audio Visual	Z2-044399	The intercom push button on the wall is not working.
Craigmont Middle	12/11/2024 7:01		Audio Visual	Z2-044398	The intercom push button on the wall is not working.
Craigmont Middle	10/2/2024 6:52	Coleman	Bleachers and Seats	Z2-035794	Some one tore out a little section of the bleachers, and now it is a safety hazard.
Craigmont Middle	12/9/2024 12:07	STAFFORD	Carpentry	Z2-044065	Ve need the boards replace to walk on to take the garbage out to keep from walking in the mud.
Craigmont Middle	10/21/2024 6:46	ROY	Carpentry	Z2-037555	The ceiling needs fixing above the main stairway.
Craigmont Middle	4/12/2024 10:26	ROY	Carpentry	Z2-009016	The curtain wire is broken and hanging across the stage, tripping hazard.
Craigmont Middle	10/3/2024 9:26	BENTON	Carpet Repair	Z2-036040	The carpet in the guidance needs replacing with floor tile.
Craigmont Middle	10/3/2024 9:25	BENTON	Carpet Repair	Z2-036038	The carpet in the library needs to be replaced with floor tile .
Craigmont Middle	10/3/2024 9:24	BENTON	Carpet Repair	Z2-036037	The carpet in the main office needs to be replaced with floor tile.
Craigmont Middle	12/13/2024 6:22	POWELL	Electrical	Z2-044800	The exterior lights in the bus lane area are not working, dark.
Craigmont Middle	12/13/2024 6:20	POWELL	Electrical	Z2-044799	The exterior lights are not coming on outside the main doors by the gym, in the walkway area.
Craigmont Middle	9/4/2024 6:56	POWELL	Electrical	Z2-030762	Vocal music room needs lift high ceiling lights.
Craigmont Middle	9/4/2024 6:55	POWELL	Electrical	Z2-030761	Dark in room needs lift, string music room.
Craigmont Middle	9/4/2024 6:53	POWELL	Electrical	Z2-030760	High ceiling needs lift for lights.
Craigmont Middle	9/4/2024 6:50	POWELL	Electrical	Z2-030758	I have several big lights out in the gym, need lift.
orang.mont r maato	07472024 0100		Ellotinodi	22 000700	
					The smoke detector is hanging from the ceiling the screw holes on the detector is broken.
Craigmont Middle	11/15/2024 7:02	Coleman	Fire Alarm System	Z2-040983	
					The fire alarm panel has a trouble on it , bad duct.
Craigmont Middle	11/14/2024 14:20	Coleman	Fire Alarm System	Z2-040920	The first data in pariet lies a course of the pariet lies and the
orang.mont r maato	11/1-//2024 14/20	ootoman	i no mann byblom	22 040020	
					The fire breaker switch needs to be put on the breaker box south end downstairs.
Craigmont Middle	11/14/2024 14:17	Coleman	Fire Alarm System	Z2-040919	
oralginont i nadio	11/1-1/202-1-11/	ootoman	i no mann byblom	22 040010	Riser room missing the wrench to change the sprinkler heads.
Craigmont Middle	11/14/2024 14:10	Coleman	Fire Sprinkler System	Z2-040916	user room missing the wenter to change the sprinker neads.
Craigmont Middle	2/3/2024 17:02	Systems	Fire Sprinkler System	WO1018498	The fire hydrant will not shut off in the back of the school.
Craigmont Middle	12/12/2024 6:37	WILSON	Heating/Ventilation/Air Conditioning	Z2-044520	The room is to hot, temp 90 degrees.
Craigmont Middle	12/12/2024 0:37	WILSON	Heating/Ventilation/Air Conditioning	Z2-044320 Z2-044146	We need the heater installed in the ceiling to keep the pipes from freezing.
Craiginont Middle	12/10/2024 /.02	WILSON	Heating/Ventitation/Air Conditioning	22-044146	Plant Manager Wakefield reported the HVAC unit in the main office is blowing cold air. 416-
					1780
Craigmont Middle	12/2/2024 9:32	WILSON	Heating/Ventilation/Air Conditioning	Z2-042350	1/00
Craigmont Middle	12/2/2024 9:32	WILSON	Heating/Ventilation/Air Conditioning	22-042350	Next Manager Welgefield reported the best in the entire and band out to under
					Plant Manager Wakefield reported the heat in the entire north and south wings are not
Ovoidmont Middle	10/0/00010:07	WILL COST	Heating (Montileties (Alic Constitution)	70.04007	working. 416-1780
Craigmont Middle	12/2/2024 9:27	WILSON	Heating/Ventilation/Air Conditioning	Z2-042345	and a shifter
				70.0	service chiller
Craigmont Middle	11/13/2024 13:57	Kessler	Heating/Ventilation/Air Conditioning	Z2-040685	and a shift of
					service chiller
Craigmont Middle	11/13/2024 13:53	Kessler	Heating/Ventilation/Air Conditioning	Z2-040683	
Craigmont Middle	9/20/2024 10:06	MALONE	Key & Lock	Z2-033952	We need 10 locker keys, broken.
					The floor in boys restroom is coming up in front of the urinal, tripping hazard.
Craigmont Middle	4/11/2024 10:05	CORONADO	Masonry	Z2-008786	
Craigmont Middle	9/25/2024 8:11	BURCHETT	Painting	Z2-034581	The wall needs painting on both sides where a big section was repaired by carpenter.
Craigmont Middle	9/25/2024 8:09	BURCHETT	Painting	Z2-034580	The ceiling and the wall needs painting where the carpenter repaired, shower area.
Craigmont Middle	9/25/2024 8:07	BURCHETT	Painting	Z2-034579	The guidance wall needs painting where the carpenter repaired a big section.
Craigmont Middle	5/17/2024 14:25	BURCHETT	Painting	WO1008910	The ceiling by the main staircase needs repairing , in bad shape .
Craigmont Middle	12/11/2024 7:07	PILKINGTON	Plumbing	Z2-044400	The boys restroom by the auditorium the 2nd sink the cold water handle broke off.
					test backflows
Craigmont Middle	10/15/2024 10:47	PILKINGTON	Plumbing	Z2-037047	
			-		PIPE IN THE BACK OF THE KITC IN THE DISH RM - IN THE CEILING LEAKING PM/WAKEFIELD
					416-7780
Craigmont Middle	8/8/2024 7:01	HARDWAY	Plumbing	Z2-026205	
Craigmont Middle	11/13/2024 10:55	LEWIS	Roofing	Z2-040639	I have a leak at the door coming into the library.
Cromwell Elementary	4/2/2024 10:44	WEBB	Carpentry	Z3-007312	Need ceiling tile removed with ceiling tiles remover lift it at to the top of stairs
Cromwell Elementary	12/3/2024 9:38	SCOTT	Electrical	Z3-042797	Emergency lights need to be replaced front of cafeteria and back
•					

Cromwell Elementary	11/4/2024 10:42	SCOTT	Electrical	Z3-039434	Water fountain outlet not working
Cromwell Elementary	10/17/2024 10:10	SCOTT	Electrical	Z3-037350	Emergency lights wouldn't come on when it was tested
					The fan is broke in vent which sucks heat out the kitchen area
Cromwell Elementary	9/25/2024 9:59	SCOTT	Electrical	Z3-034628	
Cromwell Elementary	9/24/2024 10:13	SCOTT	Electrical	Z3-034446	Bad ballast by double doors
Cromwell Elementary	9/3/2024 8:23	SCOTT	Electrical	Z3-030603	Need a ballast in hallway
Cromwell Elementary	7/29/2024 13:34	SCOTT	Electrical	Z3-023415	Need light change bad ballast
Cromwell Elementary	7/29/2024 13:33	SCOTT	Electrical	Z3-023413	Need light change bad ballast
Cromwell Elementary	7/29/2024 13:32	SCOTT	Electrical	Z3-023412	Need light change out bad ballast
Cromwell Elementary					Bad ballast in storage room
	7/29/2024 13:20	SCOTT	Electrical	Z3-023401	
Cromwell Elementary	7/24/2024 8:50	SCOTT	Electrical	Z3-022272	Need a new ceiling light cover
Cromwell Elementary	7/24/2024 8:35	SCOTT	Electrical	Z3-022266	Ballast needs replacing
Cromwell Elementary	7/24/2024 8:34	SCOTT	Electrical	Z3-022265	Ballast need replace
Cromwell Elementary	7/24/2024 8:28	SCOTT	Electrical	Z3-022263	Ballast need replace
Cromwell Elementary	7/24/2024 8:26	SCOTT	Electrical	Z3-022261	Ballast need replace
Cromwell Elementary	7/24/2024 8:13	SCOTT	Electrical	Z3-022249	Cover are missing on ceiling lights in class room
Cromwell Elementary	7/24/2024 8:11	SCOTT	Electrical	Z3-022247	Ballast need replace
Cromwell Elementary	7/24/2024 8:10	SCOTT	Electrical	Z3-022243	Ballast need replace
Cromwell Elementary	7/24/2024 8:08	SCOTT	Electrical	Z3-022241	Ballast need replace
Cromwell Elementary	7/24/2024 8:07	SCOTT	Electrical	Z3-022238	Box location in back of library
Cromwell Elementary	7/24/2024 7:59	SCOTT	Electrical	Z3-022234	Down stairs main building E129 room ballast
Cromwell Elementary	7/24/2024 7:56	SCOTT	Electrical	Z3-022231	The box is located over vending machine and teacher lounge next to main office
Cromwell Elementary	7/24/2024 7:53	SCOTT	Electrical	Z3-022230	Ballast need replace
Cromwell Elementary	6/11/2024 11:42	SCOTT	Electrical	Z3-018028	Girls restroom has a bad ballast
Cromwell Elementary	5/10/2024 13:32	SCOTT	Electrical	Z3-014093	Emergency lights in back of cafeteria whanging off wall
Cromwell Elementary	4/26/2024 11:35	SCOTT	Electrical	Z3-011774	Need 5 lenses cover for lights
Croniwell Elementary	4/20/2024 11.33	30011	Electricat	23-011//4	fire alarm system is offline
	40/40/00044005		F. H. O.	70.044704	ille didilli system is onune
Cromwell Elementary	12/12/2024 16:05	SMALL	Fire Alarm System	Z3-044791	
					001 Maintenance Alert South Hall Smoke DR By Room CR8
Cromwell Elementary	11/25/2024 8:04		Fire Alarm System	Z3-042151	
Cromwell Elementary	5/10/2024 13:14	SMALL	Fire Alarm System	Z3-014089	Need a exit sign above door leading to outside
Cromwell Elementary	4/3/2024 11:24	SMALL	Fire Extinguishers	Z3-007587	Most of the fire extinguishers are expired
					The fire suppression tag is unreadable.
Cromwell Elementary	5/10/2024 13:49	SMALL	Kitchen Hood	Z3-014096	
Cromwell Elementary	10/15/2024 11:07	BURCHETT	Painting	Z3-037048	A compliance specialist ask if this could be done
Cromwell Elementary	9/5/2024 9:42	BURCHETT	Painting	Z3-031088	Lines are barely visible
Cromwell Elementary	9/20/2024 10:12	BARNES	Plumbing	Z3-033962	The floor drain needs to be u clogged
Cromwell Elementary	12/9/2024 9:45	BUFORD	Roofing	Z3-044007	Roof is still leaking water room 223 by teacher desk
					Requesting for someone to check the bleachers it's extremely difficult to open and close
					them at the staff request for games and different functions
Crump Elementary	9/20/2024 10:45	SMALL	Bleachers and Seats	Z3-033981	
. ,					Requesting for the bleachers to be inspected for (Polka)
Crump Elementary	5/10/2024 14:26	SMALL	Bleachers and Seats	Z3-014112	.,,
,					A stall door is needed for the Pre-k girls restroom (1st stall) for inspection
Crump Elementary	8/26/2024 11:11	BARNES	Carpentry	Z3-029557	Total about to house to the Fre Rights rection (200 state) for inspection
Crump Eternentary	0/20/2024 11.11	DAININES	Carpentry	25-025557	The Ballast is bad in the light fixture
Crump Flamenton	11/5/2024 0:20	CCOTT	Floatrical	72 020575	The ballast is bad in the light lixture
Crump Elementary	11/5/2024 9:29	SCOTT	Electrical	Z3-039575	The feart Fait sizes are at (Main office and automate between library and area)
	0/0/00044057		· · ·	70.005040	The front Exit signs are out (Main office and entrance between library and gym)
Crump Elementary	8/6/2024 10:57	SCOTT	Electrical	Z3-025642	
					Need bulbs replaced in the cafeteria
Crump Elementary	7/31/2024 8:53	SCOTT	Electrical	Z3-024013	·
					Need bulbs replaced in the cafeteria the outlets on the serving lines are not working
Crump Elementary Crump Elementary	7/31/2024 8:53 7/31/2024 8:38	SCOTT SCOTT	Electrical Electrical	Z3-024013 Z3-024001	·
					·
					the outlets on the serving lines are not working
Crump Elementary	7/31/2024 8:38		Electrical	Z3-024001	the outlets on the serving lines are not working
Crump Elementary	7/31/2024 8:38		Electrical	Z3-024001	the outlets on the serving lines are not working 001 maintenance Alert South Hall Smoke DR By Room CR8
Crump Elementary	7/31/2024 8:38		Electrical	Z3-024001	the outlets on the serving lines are not working 001 maintenance Alert South Hall Smoke DR By Room CR8 Panel reading 001 Supervisory Cafeteria Right RTU Supply Duct DET (unable to upload
Crump Elementary Crump Elementary	7/31/2024 8:38 12/5/2024 8:18	SCOTT	Electrical Fire Alarm System	Z3-024001 Z3-043454	the outlets on the serving lines are not working 001 maintenance Alert South Hall Smoke DR By Room CR8 Panel reading 001 Supervisory Cafeteria Right RTU Supply Duct DET (unable to upload
Crump Elementary Crump Elementary	7/31/2024 8:38 12/5/2024 8:18	SCOTT	Electrical Fire Alarm System	Z3-024001 Z3-043454	the outlets on the serving lines are not working 001 maintenance Alert South Hall Smoke DR By Room CR8 Panel reading 001 Supervisory Cafeteria Right RTU Supply Duct DET (unable to upload photo)
Crump Elementary Crump Elementary Crump Elementary	7/31/2024 8:38 12/5/2024 8:18 11/22/2024 8:52	SCOTT	Electrical Fire Alarm System Fire Alarm System	Z3-024001 Z3-043454 Z3-042036	the outlets on the serving lines are not working 001 maintenance Alert South Hall Smoke DR By Room CR8 Panel reading 001 Supervisory Cafeteria Right RTU Supply Duct DET (unable to upload photo)
Crump Elementary Crump Elementary Crump Elementary Crump Elementary	7/31/2024 8:38 12/5/2024 8:18 11/22/2024 8:52	SCOTT	Electrical Fire Alarm System Fire Alarm System Fire Alarm System	Z3-024001 Z3-043454 Z3-042036	the outlets on the serving lines are not working 001 maintenance Alert South Hall Smoke DR By Room CR8 Panel reading 001 Supervisory Cafeteria Right RTU Supply Duct DET (unable to upload photo) Need additional rescue window signage for required areas
Crump Elementary Crump Elementary Crump Elementary	7/31/2024 8:38 12/5/2024 8:18 11/22/2024 8:52 5/15/2024 9:48	SCOTT SMALL SMALL	Electrical Fire Alarm System Fire Alarm System	Z3-024001 Z3-043454 Z3-042036 Z3-014650	the outlets on the serving lines are not working 001 maintenance Alert South Hall Smoke DR By Room CR8 Panel reading 001 Supervisory Cafeteria Right RTU Supply Duct DET (unable to upload photo) Need additional rescue window signage for required areas panel reading 001 Supervisory, Cafeteria right RTU Supply Duct DET
Crump Elementary Crump Elementary Crump Elementary Crump Elementary	7/31/2024 8:38 12/5/2024 8:18 11/22/2024 8:52 5/15/2024 9:48	SCOTT SMALL SMALL	Electrical Fire Alarm System Fire Alarm System Fire Alarm System	Z3-024001 Z3-043454 Z3-042036 Z3-014650	the outlets on the serving lines are not working 001 maintenance Alert South Hall Smoke DR By Room CR8 Panel reading 001 Supervisory Cafeteria Right RTU Supply Duct DET (unable to upload photo) Need additional rescue window signage for required areas

Crump Elementary	5/15/2024 9:44	SMALL	Fire Extinguishers	Z3-014648	Inspection and new cards for fire extinguisher for K1, K2, K3, & K5 and Hallway Ms. burchett 61970
Crump Elementary	12/5/2024 10:06	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043544	blowing cold air Ms. burchett 61970
Crump Elementary	12/5/2024 10:05	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043543	blowing cold air Ms. burchett 61970
Crump Elementary Crump Elementary	12/5/2024 10:04	GOETHIE	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z3-043542 Z3-039717	blowing cold air Change over to heat 11-7-2024
Crump Elementary	9/26/2024 9:11	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-039717 Z3-034839	HVAC UNIT IN THE VICE PRIN OFC - BLOWING NOT COOLING PM/BURCHETT 416-1970
Crump Elementary	8/27/2024 9:13	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-029762	Plant Manager Burchett reported the ac unit in room 35 is blowing hot air. 416-1970. The lock is broken won't lock
Crump Elementary	10/18/2024 9:05	MALONE	Key & Lock	Z3-037466	Need back exterior doors rekeyed and the exterior door behind the Gym
Crump Elementary	5/22/2024 11:04	SMITH	Key & Lock	Z3-015641	
Crump Elementary	7/31/2024 8:36		Kitchen Hood	Z3-023999	The vent a hood in the kitchen need to be repaired
Crump Elementary	12/9/2024 14:42	BURCHETT	Masonry	Z3-044113	Restrooms are missing the tiles around the boarder
Crump Elementary	10/28/2024 9:15	BURCHETT	Painting	Z3-038475	the hallways need paintingor please send touchup paint
Crump Elementary	10/28/2024 9:13	BURCHETT	Painting	Z3-038473	The restrooms need paintingor please give me touch of paint
Crump Elementary	5/1/2024 14:10	BURCHETT	Painting	Z3-012613	The exterior doors at Crump Elem. are in dire need of paint inside and out, there very faded.
			v		The Principal was promised the outside to be painted (Per Norman Johnson)
Crump Elementary	2/28/2024 12:01	BURCHETT	Painting	Z3-003267	The release valve is leaking on the hot water tank
Crump Elementary	8/8/2024 14:31	WARREN	Plumbing	Z3-026493	Leaking around the HVAC vent
Crump Elementary	12/16/2024 8:20	BUFORD	Roofing	Z3-044975	Roof leaking in front of closet
Crump Elementary	12/9/2024 9:09	BUFORD	Roofing	Z3-043988	· ·
Crump Elementary	11/6/2024 11:41	BUFORD	Roofing	Z3-039869	Room #41 has a roof leak
Crump Stadium	12/5/2024 18:07	MORRIS	Key & Lock	Z1-043690	Change lock cylinders on stadium restrooms for winter to prevent vandalism. NEED 16-2 FEET CHAINS AND LOCKS FOR SOCCER GOALS IN STADIUMS - 2 CHAINS PER
Crump Stadium	11/1/2024 9:57	MALONE	Key & Lock	39236	SOCCER GOAL
Crump Stadium	11/14/2024 16:37	SHIPPS	Welding	Z1-040948	Guard rail is broken outside of the home side women's restroom.
Cummings School	11/18/2024 14:52	SMITH	Audio Visual	Z1-041355	
Cummings School	11/21/2024 7:19	ANDREWS	Electrical	Z1-041824	bad balance put new lights it blown
Cummings School	11/21/2024 7:17 11/14/2024 9:26	ANDREWS ANDREWS	Electrical Electrical	Z1-041823 Z1-040795	Bad balance change light but it blown
Cummings School Cummings School	11/14/2024 9:26 11/14/2024 9:25	ANDREWS	Electrical Electrical	Z1-040795 Z1-040794	Bad balance put new bulb in it blowed Bad balance put new bulb in it blowed
Cummings School	11/14/2024 9:23	ANDREWS	Electrical	Z1-040794 Z1-040792	Bad balance put new bulb in it blowed Bad balance put new bulb in it blowed
Cummings School	9/16/2024 13:44	ANDREWS	Electrical	Z1-040732 Z1-033002	Lights are out need a lift to assist with replacement
Cummings School	9/13/2024 10:25	ANDREWS	Electrical	Z1-032625	Change out light bulbs light still didn't come on
Cummings School	8/8/2024 8:45		Generators	Z1-026258	

HEATING UNIT IN RM 105B - COIL HAS BURST AND WTR IS RUNNING EVERYWHERE- ALSO
UNIT IS SMOKING PM/WILSON 416-7810

				UNIT IS SMOKING PM/WILSON 416-7810
12/12/2024 10:50	WEBB	Heating/Ventilation/Air Conditioning	Z1-044694	
0/14/2004 0:10	WEDD	Heating Mantilation (Air Conditioning	71 007000	REPAIR LEAK PLUMBERS HAVE VALVED OFF WATER LINES
				Manual Laure Announder announce for Africa Institution
		-		Need keys to certain areas in the building
		,		Employee fell due to step uneven
		•		Please stain door for room 210. Carpenter will bring it in to the paint shop.
7/12/2024 12:32	BURCHETT	Painting	Z1-021062	Refresh lines of the parking lot bottle fillers ready for inspections
5/28/2024 11:50	WILSON	Plumbing	Z1-016118	
8/8/2024 8:53	Williams	Sheet Metal	Z1-026267	dryer vent hose line shall be cleaned and documented fire inspection
				Place a 12-inch 74-foot threshold on the Cafeteria floor. The floor tile is separating due to a shift on the floor.
7/1/2024 13:05	JOHNSON	Sheet Metal	Z1-019964	used fluorescent bulb pick up
12/15/2024 19:14	LANE	Asbestos	Z1-044942	used tubiescent butti pick up
				Room 107 nine-inch tile in the door entrance is buckling up creating a trip hazard.
12/11/2024 13:09		Asbestos	Z1-044482	
				IDF closet in the gym water is leaking inside the building from pipes coming out of the wall.
				See William Stephens for additional instructions.
9/27/2024 14:47	WILSON	Carpentry	71-035226	
0/2//2024 1414/	***************************************	Surponary	21 000220	
				Window on East side of if building above hallway entrance needs to be replaced it is broken
2/28/2024 9:03	STEPHENS	Carnentry	71-003178	Time of the control o
				3 all asbestos ceiling tile was removed and a drop ceiling is needed. Ignore 977381 W.O. wrong school
3/28/2024 15.35	STEPHENS	Carpentry	WU9//384	Main floor breaker box by room 110 needs a lock out tag for the fire alarm breaker per Fire
12/2/2024 12:22	CMITH	Flootrical	71 040500	Marshall for Pre-k monthly check list.
12/2/2024 13:22	SMITH	Electrical	21-042560	Oissuels Habbarras for such as any O
				Circular light covers for rest rooms 3
9/5/2024 13:23	SMITH	Electrical	Z1-031178	
				Delano is in need of 6 light fixtures covers for 12x48 cover that wraps around the fixtures
9/5/2024 13:20	SMITH	Electrical	Z1-031172	
				Ballast needs to be replaced light fixture on second floor middle of the hallway
8/12/2024 7:16	SMITH	Electrical	Z1-026831	
8/12/2024 7:16	SMITH	Electrical	Z1-026831	Light fixture at the front entrance of the building by the office the ballast needs to be
8/12/2024 7:16 8/12/2024 7:11	SMITH SMITH	Electrical Electrical	Z1-026831 Z1-026830	Light fixture at the front entrance of the building by the office the ballast needs to be replaced
	SMITH		Z1-026830	Light fixture at the front entrance of the building by the office the ballast needs to be
				Light fixture at the front entrance of the building by the office the ballast needs to be replaced
8/12/2024 7:11	SMITH	Electrical	Z1-026830	Light fixture at the front entrance of the building by the office the ballast needs to be replaced
8/12/2024 7:11	SMITH	Electrical	Z1-026830	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204
8/12/2024 7:11 5/29/2024 14:24	SMITH SMITH	Electrical Electrical	Z1-026830 Z1-016336	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204
8/12/2024 7:11 5/29/2024 14:24	SMITH SMITH	Electrical Electrical	Z1-026830 Z1-016336	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA
8/12/2024 7:11 5/29/2024 14:24	SMITH SMITH	Electrical Electrical	Z1-026830 Z1-016336	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59	SMITH SMITH GREER	Electrical Electrical Fire Sprinkler System	Z1-026830 Z1-016336 Z1-036697	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59	SMITH SMITH GREER	Electrical Electrical Fire Sprinkler System	Z1-026830 Z1-016336 Z1-036697	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59	SMITH SMITH GREER	Electrical Electrical Fire Sprinkler System	Z1-026830 Z1-016336 Z1-036697	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45	SMITH SMITH GREER WILLIAMS	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning	Z1-026830 Z1-016336 Z1-036697 Z1-043536	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45	SMITH SMITH GREER WILLIAMS	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning	Z1-026830 Z1-016336 Z1-036697 Z1-043536	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45	SMITH SMITH GREER WILLIAMS	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning	Z1-026830 Z1-016336 Z1-036697 Z1-043536	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5 P/M DICKERSON 416-3932
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45 12/5/2024 9:44	SMITH SMITH GREER WILLIAMS WILLIAMS	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-026830 Z1-016336 Z1-036697 Z1-043536 Z1-043535	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5 P/M DICKERSON 416-3932 HVAC UNIT FOR THE TCHR'S LOUNGE - BLOWING NOT HEATING PM/DICKERSON 416-3932
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45 12/5/2024 9:44 12/4/2024 8:04	SMITH SMITH GREER WILLIAMS WILLIAMS WILLIAMS	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-026830 Z1-016336 Z1-036697 Z1-043536 Z1-043535	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5 P/M DICKERSON 416-3932
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45 12/5/2024 9:44	SMITH SMITH GREER WILLIAMS WILLIAMS	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-026830 Z1-016336 Z1-036697 Z1-043536 Z1-043535	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5 P/M DICKERSON 416-3932 HVAC UNIT FOR THE TCHR'S LOUNGE - BLOWING NOT HEATING PM/DICKERSON 416-3932 MR. DICKERSON 63932 HEAT OUT
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45 12/5/2024 9:44 12/4/2024 8:04 12/2/2024 11:09	SMITH SMITH GREER WILLIAMS WILLIAMS WILLIAMS WILLIAMS	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-026830 Z1-016336 Z1-036697 Z1-043536 Z1-043535 Z1-043122 Z1-042471	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5 P/M DICKERSON 416-3932 HVAC UNIT FOR THE TCHR'S LOUNGE - BLOWING NOT HEATING PM/DICKERSON 416-3932
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45 12/5/2024 9:44 12/4/2024 8:04	SMITH SMITH GREER WILLIAMS WILLIAMS WILLIAMS	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-026830 Z1-016336 Z1-036697 Z1-043536 Z1-043535	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5 P/M DICKERSON 416-3932 HVAC UNIT FOR THE TCHR'S LOUNGE - BLOWING NOT HEATING PM/DICKERSON 416-3932 MR. DICKERSON 63932 HEAT OUT C/O TO HEAT
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45 12/5/2024 9:44 12/4/2024 8:04 12/2/2024 11:09 11/12/2024 7:57	SMITH SMITH GREER WILLIAMS WILLIAMS WILLIAMS WILLIAMS WILLIAMS	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-026830 Z1-016336 Z1-036697 Z1-043536 Z1-043535 Z1-043122 Z1-042471 Z1-040371	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5 P/M DICKERSON 416-3932 HVAC UNIT FOR THE TCHR'S LOUNGE - BLOWING NOT HEATING PM/DICKERSON 416-3932 MR. DICKERSON 63932 HEAT OUT
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45 12/5/2024 9:44 12/4/2024 8:04 12/2/2024 11:09	SMITH SMITH GREER WILLIAMS WILLIAMS WILLIAMS WILLIAMS	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-026830 Z1-016336 Z1-036697 Z1-043536 Z1-043535 Z1-043122 Z1-042471	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5 P/M DICKERSON 416-3932 HVAC UNIT FOR THE TCHR'S LOUNGE - BLOWING NOT HEATING PM/DICKERSON 416-3932 MR. DICKERSON 63932 HEAT OUT C/O TO HEAT The Annex needs a master key cut for the new administrator
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45 12/5/2024 9:44 12/4/2024 8:04 12/2/2024 11:09 11/12/2024 7:57	SMITH SMITH GREER WILLIAMS WILLIAMS WILLIAMS WILLIAMS WILLIAMS	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-026830 Z1-016336 Z1-036697 Z1-043536 Z1-043535 Z1-043122 Z1-042471 Z1-040371	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5 P/M DICKERSON 416-3932 HVAC UNIT FOR THE TCHR'S LOUNGE - BLOWING NOT HEATING PM/DICKERSON 416-3932 MR. DICKERSON 63932 HEAT OUT C/O TO HEAT The Annex needs a master key cut for the new administrator Gym key I need two of them. The gym was built about 18 months ago no additional keys
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45 12/5/2024 9:44 12/4/2024 8:04 12/2/2024 11:09 11/12/2024 7:57 12/10/2024 14:15	SMITH SMITH GREER WILLIAMS WILLIAMS WILLIAMS WILLIAMS WILLIAMS MALONE	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Key & Lock	Z1-026830 Z1-016336 Z1-036697 Z1-043536 Z1-043535 Z1-043122 Z1-042471 Z1-040371 Z1-044344	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5 P/M DICKERSON 416-3932 HVAC UNIT FOR THE TCHR'S LOUNGE - BLOWING NOT HEATING PM/DICKERSON 416-3932 MR. DICKERSON 63932 HEAT OUT C/O TO HEAT The Annex needs a master key cut for the new administrator
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45 12/5/2024 9:44 12/4/2024 8:04 12/2/2024 11:09 11/12/2024 7:57	SMITH SMITH GREER WILLIAMS WILLIAMS WILLIAMS WILLIAMS WILLIAMS	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-026830 Z1-016336 Z1-036697 Z1-043536 Z1-043535 Z1-043122 Z1-042471 Z1-040371	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5 P/M DICKERSON 416-3932 HVAC UNIT FOR THE TCHR'S LOUNGE - BLOWING NOT HEATING PM/DICKERSON 416-3932 MR. DICKERSON 63932 HEAT OUT C/O TO HEAT The Annex needs a master key cut for the new administrator Gym key I need two of them. The gym was built about 18 months ago no additional keys have been made.
8/12/2024 7:11 5/29/2024 14:24 10/9/2024 8:59 12/5/2024 9:45 12/5/2024 9:44 12/4/2024 8:04 12/2/2024 11:09 11/12/2024 7:57 12/10/2024 14:15	SMITH SMITH GREER WILLIAMS WILLIAMS WILLIAMS WILLIAMS WILLIAMS MALONE	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Key & Lock	Z1-026830 Z1-016336 Z1-036697 Z1-043536 Z1-043535 Z1-043122 Z1-042471 Z1-040371 Z1-044344	Light fixture at the front entrance of the building by the office the ballast needs to be replaced Ballast need replaced room 204 need an annual sprinkler inspection POCA UNIT NOT HEATING - CL-RM 6 P/M DICKERSON 416-3932 UNIT NOT HEATING - CL-RM 5 P/M DICKERSON 416-3932 HVAC UNIT FOR THE TCHR'S LOUNGE - BLOWING NOT HEATING PM/DICKERSON 416-3932 MR. DICKERSON 63932 HEAT OUT C/O TO HEAT The Annex needs a master key cut for the new administrator Gym key I need two of them. The gym was built about 18 months ago no additional keys
	8/8/2024 8:53 7/1/2024 13:05 12/15/2024 19:14	7/9/2024 14:31 SMITH 11/18/2024 14:23 BURCHETT 7/17/2024 7:33 BURCHETT 7/12/2024 12:32 BURCHETT 5/28/2024 11:50 WILSON 8/8/2024 8:53 WILIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	7/9/2024 14:31 SMITH Key & Lock 11/18/2024 14:23 BURCHETT Masonry 7/17/2024 7:33 BURCHETT Painting 7/12/2024 12:32 BURCHETT Painting 5/28/2024 11:50 WILSON Plumbing 8/8/2024 8:53 Williams Sheet Metal 7/1/2024 13:05 JOHNSON Sheet Metal 12/15/2024 19:14 LANE Asbestos 12/11/2024 13:09 Asbestos 9/27/2024 14:47 WILSON Carpentry 2/28/2024 9:03 STEPHENS Carpentry 2/28/2024 9:03 STEPHENS Carpentry 12/28/2024 15:35 STEPHENS Carpentry 12/2/2024 13:22 SMITH Electrical	7/9/2024 14:31 SMITH Key & Lock Z1-020640 11/18/2024 14:23 BURCHETT Masonry Z1-041348 7/17/2024 7:33 BURCHETT Painting Z1-021467 7/12/2024 12:32 BURCHETT Painting Z1-021062 5/28/2024 11:50 WILSON Plumbing Z1-016118 8/8/2024 8:53 Williams Sheet Metal Z1-026267 7/1/2024 13:05 JOHNSON Sheet Metal Z1-019964 12/15/2024 19:14 LANE Asbestos Z1-044942 12/11/2024 13:09 Asbestos Z1-044482 9/27/2024 14:47 WILSON Carpentry Z1-035226 2/28/2024 9:03 STEPHENS Carpentry Z1-003178 3/28/2024 15:35 STEPHENS Carpentry W0977384 12/2/2024 13:22 SMITH Electrical Z1-042560 9/5/2024 13:23 SMITH Electrical Z1-031178

					NEED LIEUTED DOOM OU
Delano Elementary	9/26/2024 10:10	MALONE	Key & Lock	Z1-034871	NEED A KEY FOR ROOM G11
Delano Elementary	9/26/2024 10:09	MALONE	Key & Lock	Z1-034870	NEED A KEY CUT FOR G10 INSIDE THE GYM
•			,		NEED A KEY CUT FOR G9 INSIDE THE GYM
Delano Elementary	9/26/2024 10:08	MALONE	Key & Lock	Z1-034869	LOCK AND KEY NEEDS AN ADJUSTMENT OR NEW KEY LOCK, TAKES LONGER THAN 2 OR 3
Delano Elementary	9/19/2024 10:47	MALONE	Key & Lock	Z1-033717	MINUTES TO GET OPEN
•			,		Early childhood monthly inspection report indicates lots of areas in the cafeteria with chipped paint requesting a repaint of entire cafeteria.
Delano Elementary	10/24/2024 9:39	BURCHETT	Painting	Z1-038142	Crippeu paint requesting a repaint of entire careteria.
					Bottle filler next to entrance door in the gym is leaking only if you use the bottle filler but not
Delano Elementary	12/5/2024 7:49	Jordan	Plumbing	Z1-043441	if you use the drinking fountain, I unplugged it so kids could not use it.
					3rd stall from the window girls restroom 2nd floor the back of the toilet is leaking constantly
Delano Elementary	12/5/2024 7:46	Jordan	Plumbing	Z1-043439	
Delano Elementary	9/16/2024 13:33	Jordan	Plumbing	Z1-032989	HVAC UNIT IN RM 406 IS LEAKING FROM THE PIPE PM/DICKERSON 416-2932
Delano Elementary	12/4/2024 9:44	DIAZ	Roofing	Z1-043238	seal around pipe on exterior wall.
			_		Blinds need to be replaced in this room broken up blinds.
Delano Elementary	2/28/2024 9:01	BENTON	Shades/Blinds	Z1-003177	8 ft blinds need replacing. They are broken up and needs to be replaced
Delano Elementary Delano Elementary	2/28/2024 8:59 3/28/2024 15:35	BENTON BENTON	Shades/Blinds Shades/Blinds	Z1-003174 WO987709	9 window was vandalized and broken which resulted in the blinds being torn apart, blinds need replacing
					Bleachers are not coming out and not being able to be pushed back in. The floors in the gym
Dandan Middle	0/4/0004 0:00	0-1	Discolusion and Conta	70 000005	are being serviced this Saturday and Sunday so they will have to be pushed back by Friday.
Dexter Middle Dexter Middle	9/4/2024 9:08 12/9/2024 15:46	Coleman ROY	Bleachers and Seats Carpentry	Z2-030825 Z2-044124	A piece of wood was broken off. It is a safety hazards and needs to be repaired.
					Counselor in main office is wanting her carpet removed in her office. First door on the left when going towards the principals office.
Dexter Middle	9/10/2024 14:08	LEWIS	Carpet Repair	Z2-031811	mon going control to principals officer
					VP McGuire is requesting the carpet in her office be removed and replaced with tiles.
Dexter Middle	5/14/2024 8:11	BENTON	Carpet Repair	Z2-014376	Dellandia and
Dexter Middle	11/1/2024 10:17	POWELL	Electrical	Z2-039242	Ballast is out
Dexter Middle	10/24/2024 11:08	POWELL	Electrical	Z2-038190	The outlet cover is hanging on by a thread. It is a safety hazard due to it being metal.
Dexter Middle	8/8/2024 13:32	JOHNSON	Electrical	Z2-026461	WALK IN FREEZER REQUESTING ELECTRICIAN FOR REPAIR. THANKS
					One of the ballast in her office is out.
Dexter Middle	7/25/2024 7:16	POWELL	Electrical	Z2-022480	Every ballast in that room needs to be replaced. Only one set of lights work
Dexter Middle	7/25/2024 7:13	POWELL	Electrical	Z2-022479	The ballast in the cafeteria locker room is out.
Dexter Middle	5/21/2024 9:27	POWELL	Electrical	Z2-015385	
Dexter Middle	4/29/2024 12:03	CHALK	Electrical	Z2-012010	Replace receptacles with GFIC where needed
Dexter Middle	3/28/2024 15:34	POWELL	Electrical	WO1006469	In room 211 It needs a Light Panel, The Light Panel is Broken off.
					POCA
Dexter Middle	10/31/2024 9:04	Coleman	Fire Alarm System	Z2-039028	Strobe was ripped out of the wall. The missing strobe is causing the alarm panel go off.
Dexter Middle	9/24/2024 13:00	LEWIS	Flooring	Z2-034493	Floor is still buckled up.
Dexter Middle	3/28/2024 15:34	CHASE	Flooring	WO989933	ces that has carpet and the small health storage room carpet to be taken up. The carpet is dirty, smells and has stains. Principal request. UNIT NOT HEATING - CL-RM 127 PM STCYR 416-0360
Dexter Middle	12/12/2024 9:24	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044606	

					PM STCYR 416-0360
Dexter Middle	12/12/2024 9:23	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044603	
					UNIT NOT HEATING - CL-RM 123
					PM STCYR 416-0360
Dexter Middle	12/12/2024 9:23	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044601	
					UNIT NOT COMING ON - CL-RM 117
					PM STCYR 416-0360
Dexter Middle	12/12/2024 9:22	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044597	THE PART OF THE PA
					UNIT NOT HEATING - CL-RM 115
Danta Middle	40/40/0004 0:04	DDWCON	Heating Mantilation (Air Conditioning	70.044500	PM STCYR 416-0360
Dexter Middle	12/12/2024 9:21	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044596	UNIT NOT HEATING - CL-RM 114
					PM STCYR 416-0360
Dexter Middle	12/12/2024 9:20	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044595	111010111410 0000
DOMOIT III date	12,12,202,0120	51110011	riodanily romandoning	22 011000	HEATING UNIT FOR THE PLANT MGR'S OFC - ACROSS FROM THE GYM - BLOWING COLD AIR
					PM/STCYR 416-0360
Dexter Middle	12/9/2024 14:39	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044111	
					Ms. St Cyr 60355 no heat
Dexter Middle	12/4/2024 10:53	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043304	
					UNIT NOT HEATING - CL-RM 222, 2ND FLOOR - PM STCYR 416-0360
Dexter Middle	12/3/2024 12:18	WILSON	Heating/Ventilation/Air Conditioning	Z2-042955	
					UNIT NOT HEATING - CL-RM 125 - PM STCYR 416-0360
Dexter Middle	12/3/2024 12:17	WILSON	Heating/Ventilation/Air Conditioning	Z2-042953	
					UNIT NOT HEATING - CL-RM 124 - PM STCYR 416-0360
Dexter Middle	12/3/2024 12:16	WILSON	Heating/Ventilation/Air Conditioning	Z2-042952	
					UNIT NOT HEATING - CL-RM 120 - PM STCYR 416-0360
Dexter Middle	12/3/2024 12:15	WILSON	Heating/Ventilation/Air Conditioning	Z2-042950	
					Plant Wilson reported the unit in the Back Office is blowing cold air. 416-0355
Dexter Middle	12/2/2024 10:36	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042433	
					Plant Wilson reported the unit in the Main Office is blowing cold air. 416-0355
Dexter Middle	12/2/2024 10:34	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042430	D. 195
5	10/0/000110	2000001		70.040407	Plant Wilson reported the unit in room 215 is blowing cold air. 416-0355
Dexter Middle	12/2/2024 10:33	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042427	Plant Mileon reported the unit in room 200 is blowing and siz 410 0355
Dexter Middle	12/2/2024 10:32	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042425	Plant Wilson reported the unit in room 209 is blowing cold air. 416-0355
Dexter Middle	12/2/2024 10.32	BNISON	rieating/ventitation/Air Conditioning	22-042423	Plant Wilson reported the unit in room 208 is blowing cold air. 416-0355
Dexter Middle	12/2/2024 10:31	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042421	Talle Wildom reported the differin room 200 is blowing cold all. 420 0000
Dexter r liquite	12/2/2024 10:01	Bittooit	ricadily ventilation/All Conditioning	22 042421	Plant Wilson reported the unit in room 110 is blowing cold air. 416-0355
Dexter Middle	12/2/2024 10:30	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042419	
Dexter Middle	9/25/2024 13:16	BRYSON	Heating/Ventilation/Air Conditioning	Z2-034689	Mr. Bryson said it was a cool needed for the unit for the cafeteria
Dexter Middle	9/24/2024 8:28	MALONE	Key & Lock	Z2-034381	The lock is turning upside
			•		The teacher has a leak in the far corner above her black file cabinet.
Dexter Middle	11/14/2024 8:00	LEWIS	Roofing	Z2-040756	
					The bleachers are not able to be pushed back in or pulled all the way out.
Dexter School	10/14/2024 7:54	Coleman	Bleachers and Seats	Z2-036772	
Dexter School	10/21/2024 10:56	POWELL	Electrical	Z2-037666	Please install outlet cover
Dexter School	10/21/2024 10:54	POWELL	Electrical	Z2-037665	Please install junction box cover (POCA)
Dexter School	8/14/2024 9:47	POWELL	Electrical	Z2-027467	Please repair bad ballast in classroom restroom
Dexter School	7/29/2024 10:44	POWELL	Electrical	Z2-023295	Please repair electrical outlet in teacher lounge
Dexter School	7/29/2024 10:42	POWELL	Electrical	Z2-023291	Please replace bad ballast in green hallway
Dexter School	7/29/2024 10:41	POWELL	Electrical	Z2-023290	Please replace bad ballast in computer lab closet
Dexter School	7/29/2024 10:40	POWELL	Electrical	Z2-023286	Please replace bad ballast in PLC room
Dexter School	7/29/2024 10:39	POWELL	Electrical	Z2-023285	Please replace bad ballast in mail hall light
Dexter School	7/29/2024 10:21	POWELL	Electrical	Z2-023268	Please repair bad ballast in closet
Dexter School Dexter School	11/5/2024 9:04 10/21/2024 10:52	Coleman Coleman	Fire Alarm System	Z2-039567 Z2-037661	Please repair missing strobes causing trouble in system (POCA)
Dexter SCHOOL	10/21/2024 10.02	Cotelliali	Fire Alarm System	22-03/001	Please repair trouble on panel *POCA* Repair 3 Audio Visual Devices not Working
Dexter School	10/14/2024 15:52	Coleman	Fire Alarm System	Z2-036931	nepali 3 Audio visual Devices flot vvolklilg
Device ocupor	10/14/2024 10:02	Cotelliali	i iie Adilii əyəteili	22-030331	At the end of the 200 hall the strobe has been disconnected from the wall in the men's
					bathroom and the wires are just loose not hooked up to anything. The strobe in the women's
					next to it is not working and the horn/ strobe on the wall past the women's room near room
					222 is not working as well.
Dexter School	10/14/2024 15:51	Coleman	Fire Alarm System	Z2-036930	•
			· ·		

UNIT NOT HEATING - CL-RM 124

					neplace PACE 12V 7all Battery
Dexter School	10/14/2024 15:51	Coleman	Fire Alarm System	Z2-036929	
					FACP Batteries in secondary power supply. (Two 12V 12ah Batteries)
Dexter School	10/14/2024 15:50	Coleman	Fire Alarm System	Z2-036928	
Dexter School	11/5/2024 9:06	Coleman	Fire Extinguishers	Z2-039569	Annual inspection due (POCA)
			_		
Dexter School	11/5/2024 8:58	Coleman	Fire Sprinkler System	Z2-039565	Please replace missing Sprinkler tamper cover (POCA)
Dexter School	11/5/2024 8:56	Coleman	Fire Sprinkler System	Z2-039564	Please repair Sprinkler escutcheon dislodged from mount (POCA)
					HEATING UNIT IN THE MAIN OFC - BLOWING NOT HEATING PM/WILSON 416-0355
Dexter School	12/12/2024 9:46	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044650	
Dontor Corroct	12,12,202,40,40	5	riodang romadon, in Conditioning	22 011000	HEATING UNIT IN RM 315 - BLOWING NOT HEATING PM/WILSON 416-0355
Danton Caland	40/40/00040-44	DDVCON	Hanking Alfankilaking (Ain One dikinging	70.044047	TIEATING ONLY IN THE STO - DECIMING NOT THEATING 1 PH WIESON 410-0333
Dexter School	12/12/2024 9:44	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044647	
					HEATING UNIT IN RM 314 - BLOWING NOT HEATING PM/WILSON 416-0355
Dexter School	12/12/2024 9:44	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044645	
					HEATING UNIT IN RM 310 - BLOWING NOT HEATING PM/WILSON 416-0355
Dexter School	12/12/2024 9:43	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044643	
Dontor Corroct	12/12/2024 0140	51110011	riodang romadon, in Conditioning	22 011010	HEATING UNIT IN RM 305 - BLOWING NOT HEATING PM/WILSON 416-0355
	40/40/00040	BB1/0.011		70.011011	TIEATING GIVET IN THE 303 - DEGWING NOT TIEATING THE WIESON 410-0333
Dexter School	12/12/2024 9:43	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044641	
					HEATING UNIT IN RM 208 - BLOWING NOT HEATING PM/WILSON 416-0355
Dexter School	12/12/2024 9:42	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044640	
					HEATING UNIT IN RM 100 - BLOWING NOT HEATING PM/WILSON 416-0355
Dexter School	12/12/2024 9:42	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044636	
Dexter delidet	12/12/2024 5.42	DITIOOIT	ricating ventuation//ii Conditioning	22 044000	mS. STCLARE
					60355
					NO HEAT
Dexter School	12/5/2024 14:48	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043676	
					mS. STCLARE
					60355
					NO HEAT
					NO REAL
Dexter School	12/5/2024 14:48	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043675	
					Ms. Alexis St Cstyr (416 0355) Dexter ES Room208 Boiler air is coming out cold. no heat
Dexter School	12/5/2024 11:21	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043576	
					Ms. St Cyr 60355 no heat
Dexter School	12/4/2024 10:51	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043303	······································
Dexter School	12/4/2024 10.51	DITIOUN	rieating/ventitation/Air Conditioning	22-040000	M- 0-0 - 000FF b
					Ms. St Cyr 60355 no heat
Dexter School	12/4/2024 10:50	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043301	
					Ms. St Cyr 60355 no heat
Dexter School	12/4/2024 10:50	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043300	
					Ms. St Cyr 60355 no heat
Dexter School	12/4/2024 10:49	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043299	· · · · · · · · · · · · · · · · · · ·
Dexter Scrioot	12/4/2024 10.49	DNISON	Heating/Ventitation/All Conditioning	22-043233	M- 0-0-00055
					Ms. St Cyr 60355
Dexter School	12/4/2024 10:49	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043298	
					UNIT NOT COOLING - CL-RM 215 - P/M ST STR 416-0355
Dexter School	12/3/2024 12:30	WILSON	Heating/Ventilation/Air Conditioning	Z2-042966	
					Plant Wilson reported the unit in room 310 is blowing cold air. 416-0355
Dexter School	12/2/2024 10:26	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042408	·· · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · · ·
Dexter School	12/2/2024 10:20	DITIOUN	rieating/ventitation/All Conditioning	22-042400	Disabilities and the wife and the wife in the control of the contr
					Plant Wilson reported the unit in room 305 is blowing cold air. 416-0355
Dexter School	12/2/2024 10:26	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042404	
					Plant Wilson reported the unit in room 303 is blowing cold air. 416-0355
Dexter School	12/2/2024 10:24	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042402	
					Plant Wilson reported the unit in room 208 is blowing cold air. 416-0355
Dexter School	12/2/2024 10:21	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042400	Tank Moon reported the disk in room 250 to bloming out disk 410 0000
Dexter School	12/2/2024 10.21	DRISON	neaung/ventitation/Air Conditioning	22-042400	DI . 1151
					Plant Wilson reported the unit in room 100 is blowing cold air. 416-0355
Dexter School	12/2/2024 10:19	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042397	
					Principal Certion is requesting a master key for the Middle AND Elementary
Dexter School	10/14/2024 15:46	MALONE	Key & Lock	Z2-036927	
	=========		.,		Teacher's key was misplaced and she is requesting a new one to be made.
Doytor School	10/14/2024 15:44	MALONE	Kov 8 Look	72 026020	1, mad midplaced and one to requesting a new one to be made.
Dexter School	10/14/2024 15:44	MALONE	Key & Lock	Z2-036926	HOTHER THE RELIGION TO SERVICE A SERVICE OF THE RESERVE OF THE RES
					HOT WATER TANK BEHIND THE KITC - LEAKING BAD - HAS STEAM EVERYWHERE
					PM/WILSON 416-0355
Dexter School	10/1/2024 7:15	HARDWAY	Plumbing	Z2-035572	
Dexter School	10/25/2024 9:32	BENTON	Shades/Blinds	Z2-038326	Please replace broken blinds won't let down and stick is missing.

Replace FACP 12V 7ah Battery

POCA-exit door	do not close completely	
----------------	-------------------------	--

					POCA-exit door do not close completely
Double Tree Elementary	11/20/2024 10:43	ARNOLD	Carpentry	Z4-041705	
Double Tree Elementary	10/28/2024 6:10	TEDDER	Carpentry	Z4-038411	We need 6 inch tile replaced had to take down water pipe burst
Double Tree Elementary	8/28/2024 9:28	ARNOLD	Carpentry	Z4-029985	Door right now hard to close need replacing
Double Tree Elementary	11/22/2024 9:25	HALL	Electrical	Z4-042046	The eight battery clocks with two AA batteries
Double Tree Elementary	10/31/2024 11:46	HALL	Electrical	Z4-039095	Light pole light is too dim ,dark on side of building
Double Tree Elementary	10/31/2024 11:44	HALL	Electrical	Z4-039094	Too dark on stage lights are out
					Six lights not working under the canopy
Double Tree Elementary	10/31/2024 11:43	HALL	Electrical	Z4-039093	
Double Tree Elementary	10/1/2024 9:34	HALL	Electrical	Z4-035648	Exit lights come on for five seconds and shut off for the last two days
Double Tree Elementary	8/6/2024 13:14	HALL	Electrical	Z4-025752	Need master clock reset and bell times 8 AM and 3 PM
Double Tree Elementary	5/17/2024 10:00	HALL	Electrical	Z4-015004	Classroom lights do not cut off
Double Tree Elementary	4/30/2024 11:11	HALL	Electrical	Z4-012247	Cannot cut lights off on East and West hallways. With breaker and with no switch on wall
					Over 20 lightbulbs need to be changed out
Double Tree Elementary	3/25/2024 10:19	HALL	Electrical	Z4-006128	
Double Tree Elementary	2/19/2024 9:31	HALL	Electrical	Z4-001848	Need colorful stage lights replaced
Double Tree Elementary	2/3/2024 16:41	HALL	Electrical	WO1021704	lights don't come on and hood not coming on
Double Tree Elementary	11/21/2024 12:03		Fire Alarm System	Z4-041947	re panel in trouble reads auxiliary power, also magnetic doors is not working throughout the building
Double Tree Elementary	11/20/2024 10:40		Fire Alarm System	Z4-041704	tables need to be removed ,requested by Fire Marshall due to not connected to new fire panel system
Double Tree Elementary	11/20/2024 10:34		Fire Alarm System	Z4-041698	POCA -fire alarm need annual service date
Double Tree Elementary	11/20/2024 10:55		Fire Extinguishers	Z4-041714	Two fire extinguishers got missed. The date on the rest of them December 2023.
Double Tree Elementary	7/12/2024 7:45	CALDWELL	Fire Sprinkler System	Z4-020971	Sprinkler system is leaking water from on the outside cannot turn it off
Double Tree Elementary	4/2/2024 11:36	CASEY	Flooring	Z4-007343	The carpet remove and put tiles in its place
Double Tree Elementary	2/3/2024 15:40	CASEY	Flooring	WO1027784	Need 30yrs old carpet remove & replace with tile floor.(Safety hazard)
Double Tree Elementary	3/28/2024 15:34	CASEY	Flooring	W0992425	from the building. The carpet is located in the following areas Main office, guidance suite, music room, and conference room.
Double Tree Elementary	5/6/2024 9:56	SMITH	Key & Lock	Z4-013139	Need key and lock .3217 to put on new hvac covers
Double Tree Elementary	3/26/2024 9:08	CORONADO	Masonry	Z4-006303	Fill in holes
Double Tree Elementary	3/25/2024 10:17	CORONADO	Masonry	Z4-006126	Hole in wall
Double Tree Elementary	3/25/2024 10:16	CORONADO	Masonry	Z4-006125	Hole in wall
Double Tree Elementary	3/1/2024 7:59	BURCHETT	Painting	Z4-003476	The Emergency lines repainted, and parking lines repainted can't see them
Double Tree Elementary	3/28/2024 15:34	BURCHETT	Painting	WO998767	Paint all exit doors green
Double Tree Flamentons	10/7/2024 12:21	WILL CON	Diumbing	74 020402	replace 289- u gas relief valves
Double Tree Elementary	10/7/2024 13:21	WILSON	Plumbing	Z4-036493	paint around all bottle filler fountains
Double Tree Elementary	9/26/2024 7:35	WILSON	Plumbing	Z4-034797	paint around att bottle inter rountains
Double Tree Elementary	8/19/2024 8:26	HARRIS	Plumbing	Z4-034797 Z4-028284	Water fountain Spicket that fill the water bottle up and panel is broken
Double free Elementary	0/15/2024 0.20	HANNIS	Fluilibilig	24-020204	Drinking fountain is broken leaking and the hands-free fountain is broken needs to be
					repaired
Double Tree Elementary	8/16/2024 14:52	HARRIS	Plumbing	Z4-028198	теритеч
Douglas Headstart	4/2/2024 11:32	STEPHENS	Carpentry	Z1-007341	The window is craked, Shattered
Douglas ricaustart	4/2/2024 11.02	OTETTIENO	Ourpentry	21 00/041	MR. LUCKETT 69746
Douglas Headstart	12/2/2024 11:23	WEBB	Heating/Ventilation/Air Conditioning	Z1-042485	255, 257, 10
Douglas Headstart	9/26/2024 16:44	MALONE	Key & Lock	Z1-034981	Cylinder get keys stuck and won't lock sometimes
			, 2 200		-,
					Annual Health and Safety Screener for Douglass Head Start conducted on July 30th.Peeling
					and/or chipped wall paint is present in classes #1 and #2 and in the restroom of class #8.
Douglas Headstart	8/5/2024 13:37	BURCHETT	Painting	Z1-025345	
•			· ·		Bleachers will not go back in on the westside.
Douglass High	10/14/2024 12:04	STEPHENS	Bleachers and Seats	Z1-036860	
					The bleachers want go back. I checked the fuse box, and the fuses were tripped once I reset
					them the bleacher went in a little and I checked the fuse they tripped again
Douglass High	9/9/2024 12:12		Bleachers and Seats	Z1-031546	
					Repair workstation counter tops around the perimeter of the of the classroom
Douglass High	10/16/2024 12:53	ARNOLD	Carpentry	Z1-037240	
					Take down partitions in classroom the principal said that we have grant money to fund this
					project.
Douglass High	10/14/2024 12:08		Carpentry	Z1-036866	
					Demolition the old partisans in the classroom for new furniture
Douglass High	6/12/2024 15:16	ARNOLD	Carpentry	Z1-018221	
					The North bleacher on the top will not let back manually the knob broke off one level to
					release the bleachers
Douglass High	5/28/2024 14:58	SHIPPS	Carpentry	Z1-016176	

					Water leaking in from ceiling by door when it stormed!!
Douglass High	5/23/2024 6:29	ARNOLD	Carpentry	Z1-015741	
Douglass High	4/29/2024 7:21	SHIPPS	Carpentry	Z1-011841	North basketball goal want go up.
Douglass High	12/2/2024 15:15	SMITH	Electrical	Z1-042634	lights out ballast
					Back of door magnet broke off
Douglass High	11/20/2024 8:33	SIMMONS	Electrical	Z1-041627	
Douglass High	2/3/2024 17:03	CHALK	Electrical	WO1017959	, , ,
Douglass High	5/17/2024 14:30	CHALK	Electrical	WO1013674	Non working light above door Elevator door getting stuck.
Douglass High	12/2/2024 15:10		Elevators	Z1-042629	
Douglass High	2/3/2024 13:46	CASEY	Flooring	WO1032814	Worn carpet removed and replaced with tile.
	3/28/2024 15:34	CHASE	=	W0996974	·
Douglass High	3/26/2024 15.34	CHASE	Flooring	W0996974	Carpet removal and replaced with tile. Thermostat not working
Douglass High	12/5/2024 7:00	WEBB	Heating/Ventilation/Air Conditioning	Z1-043417	heat not working
Douglass High	12/4/2024 8:27	WEBB	Heating/Ventilation/Air Conditioning	Z1-043140	heat not warding
Douglass High	12/3/2024 14:41	WEBB	Heating/Ventilation/Air Conditioning	Z1-043042	heat not working
Douglass High	12/3/2024 11:56	WEBB	Heating/Ventilation/Air Conditioning	Z1-042939	Heat not working
		WEBB			heat not working
Douglass High	12/3/2024 11:53		Heating/Ventilation/Air Conditioning	Z1-042933	Heat not working
Douglass High	12/3/2024 11:53	WEBB	Heating/Ventilation/Air Conditioning	Z1-042932	Heat not working
Douglass High	12/3/2024 11:52	WEBB	Heating/Ventilation/Air Conditioning	Z1-042931	
Douglass High	12/3/2024 11:46	WEBB	Heating/Ventilation/Air Conditioning	Z1-042922	Heat not working
Douglass High	12/3/2024 11:46	WEBB	Heating/Ventilation/Air Conditioning	Z1-042921	Heat not working
Douglass High	12/3/2024 11:45	WEBB	Heating/Ventilation/Air Conditioning	Z1-042920	Heat not working
	12/3/2024 11:44	WEBB		Z1-042918	Heat not working
Douglass High			Heating/Ventilation/Air Conditioning		Heat not working
Douglass High	12/3/2024 11:44	WEBB	Heating/Ventilation/Air Conditioning	Z1-042917	unit not cooling
Douglass High	8/7/2024 10:20	WEBB	Heating/Ventilation/Air Conditioning	Z1-026014	unit not cooling
Douglass High	8/7/2024 10:18	WEBB	Heating/Ventilation/Air Conditioning	Z1-026011	RTU #19 - PLUMBING LINE DRAIN IS BROKE - PM/LUCKETT 416-0990
Douglass High	8/6/2024 14:07	WEBB	Heating/Ventilation/Air Conditioning	Z1-025778	
Douglass High	8/6/2024 14:05	WEBB	Heating/Ventilation/Air Conditioning	Z1-025777	RTU #10 - WON'T COME ON - PM/LUCKETT 416-0990
Douglass High	9/4/2024 13:44	BURCHETT	Masonry	Z1-030952	need to be replaced look at pictures
			•		graffition the head antroppe of grand point are a manage pood to point before fall broad
Douglass High	9/25/2024 18:43	BURCHETT	Painting	Z1-034775	graffiti on the back entrance of gym I need paint, or someone need to paint before fall break
					classroom 2,4,6 chipped paint in classroom closet. classroom 8 chipped paint in restroom and class closet this from health inspection done 09/03/2024
Douglass High	9/4/2024 12:25	BURCHETT	Painting	Z1-030919	painting in hallway we cleaned some of the walls and they still are dirty
Douglass High	5/20/2024 10:23	BURCHETT	Painting	Z1-015188	
Douglass High	3/28/2024 15:34	MYERS	Painting	WO983756	Need Wall repainted in office space.
Douglass High	11/7/2024 10:47	Jordan	Plumbing	Z1-040116	The 5th toilet from the door will not stop running when flushed, I turned water off.
	22772927 20:77 Jordan Lumbung				LADDER INSTALL ROOF HATCH IN PLANT MANAGERS OFFICE FROM THAT ROOF TO
Douglass High	10/8/2024 11:07	SHIPPS	Welding	Z1-036612	AUDITORIUM ROOF NEAR RTU #6 SEE MIKE SIMMONS

					POCA Install all missing corridor doors on the 2nd floor
Douglass School	4/2/2024 10:51	ARNOLD	Carpentry	Z1-007318	-
Douglass School	12/12/2024 12:54	SMITH	Electrical	Z1-044735	Sockets out
Douglass School	12/10/2024 14:55	SMITH	Electrical	Z1-044358	Ballast needs replacing
					Ballast needs replacing not working
Douglass School	12/10/2024 14:55	SMITH	Electrical	Z1-044357	Ballast bad
Douglass School	12/4/2024 8:50	SMITH	Electrical	Z1-043170	Socket blown out
Douglass School	12/4/2024 8:48	SMITH	Electrical	Z1-043166	Ballast needs replacing
Douglass School	12/3/2024 11:29	SMITH	Electrical	Z1-042906	
Douglass School	12/2/2024 14:28	SMITH	Electrical	Z1-042598	Sockets blown out
Douglass School	12/2/2024 9:31	SMITH	Electrical	Z1-042348	Ballast won't stop blinking
Douglass School	11/18/2024 10:01	SMITH	Electrical	Z1-041232	Ballast out
					Ballast out
Douglass School	11/18/2024 9:57	SMITH	Electrical	Z1-041230	Ballast needs replacing no power connection
Douglass School	11/14/2024 14:37	SMITH	Electrical	Z1-040926	Sockets are out only two working
Douglass School	10/4/2024 13:46	SMITH	Electrical	Z1-036335	Ballast is needed for light fixture.
Douglass School	9/9/2024 14:09	SMITH	Electrical	Z1-031589	
Douglass School	5/14/2024 8:35	SMITH	Electrical	Z1-014392	Stage lights are not working.
Douglass School	5/7/2024 15:21	SMITH	Electrical	Z1-013529	Exit sign is hanging from the ceiling.
Douglass School	2/3/2024 16:43	CHALK	Electrical	WO1021472	VERY HIGH need for lighting. Very dark upon arrival.
Douglass School	9/16/2024 15:15	GREER	Fire Alarm System	Z1-033031	The Fire alarm continues to beep after pressing the reset button. Remove carpet for tile flooring
Douglass School	6/18/2024 14:32	CASEY	Flooring	Z1-018814	
					Not receiving heat
Douglass School	12/4/2024 8:50	WEBB	Heating/Ventilation/Air Conditioning	Z1-043171	Room not getting hot
Douglass School	12/2/2024 14:46	WEBB	Heating/Ventilation/Air Conditioning	Z1-042608	
Douglass School	12/2/2024 14:45	WEBB	Heating/Ventilation/Air Conditioning	Z1-042606	Room not getting hot
Douglass School	12/11/2024 10:45	MALONE	Key & Lock	Z1-044461	Need a key made for instructional coach room
Douglass School	10/23/2024 14:28	MALONE		Z1-038052	in need of 5 keys to teachers classroom
-			Key & Lock		Paint chipping
Douglass School	11/8/2024 8:29	BURCHETT	Painting	Z1-040240	Restrooms on the first and second floors need painting.
Douglass School	8/20/2024 11:03	BURCHETT	Painting	Z1-028642	
Douglass School	7/12/2024 12:29	BURCHETT	Painting	Z1-021061	Entire area is in need of painting.
Douglass School	3/28/2024 15:34	BURCHETT	Painting	WO1007391	Paint is peeling on walls and ceiling
Downtown Elementary	11/22/2024 16:40	STEPHENS	Carpentry	Z1-042129	Requesting classroom window replacement
-					Reinstall Ceiling Tile (2)
Downtown Elementary	2/9/2024 11:42	BALLARD	Carpentry	Z1-000861	carpet needs to be removed
Downtown Elementary	6/7/2024 9:53	LEWIS	Carpet Repair	Z1-017685	MOVE LIFT FROM KEYSTONE ES TO DOWNTOWN ES
Downtown Elementary	12/12/2024 14:47	SMITH	Electrical	Z1-044781	
Doumtoum Flomente-	11/07/2024 0:24	CDEED	Floristers	71 040100	Elevator do not operate
Downtown Elementary	11/27/2024 9:24	GREER	Elevators	Z1-042189	Populacting fire clarm inspection
Downtown Elementary	12/9/2024 11:21		Fire Alarm System	Z1-044050	Requesting fire alarm inspection

	44/5/0004054	0.1057	5	74 000504	
Downtown Elementary	11/5/2024 8:54	CASEY	Flooring	Z1-039561	Stainwell stairs flooring coming off.
Downtown Elementary Downtown Elementary	3/28/2024 15:34 12/10/2024 11:51	CHASE WEBB	Flooring Heating/Ventilation/Air Conditioning	Z1-044281	ce(ASAP) Rug needs gluing: Currently an emergency cone has been placed on top of an area on the Library. This is a Liability/ hazard if a student parent or staff would fall and Hurt themselves. Noise coming from ceiling vents
Downtown Elementary	12/9/2024 13:11	WEBB	Heating/Ventilation/Air Conditioning	Z1-044281 Z1-044081	Requesting heat temperature adjustment. Temperature in classrooms reading 89 degrees.
Downtown Elementary	12/9/2024 13.11	VVEDD	neating/ventitation/Air Conditioning	21-044081	nequesting near temperature adjustment, reimperature in citassionins reading es degrees. RESET LTD ON AHU 1
Downtown Elementary	12/5/2024 18:41	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-043694	neset LID ON AND 1
Downtown Elementary	12/3/2024 10.41	WILLIAIIG	riedding/veriddadoll/Air Colluidolling	21-043034	MR. JOHNSON 68400 ROOF TOP UNITS 1 2 AND 3 ARE ALL IN ERROR MODE
Downtown Elementary	12/2/2024 12:24	WEBB	Heating/Ventilation/Air Conditioning	Z1-042533	THE SOURCE OF THE STATE OF THE PERIOD OF THE STATE OF THE
Downtown Elementary	11/5/2024 12:25	WEBB	Heating/Ventilation/Air Conditioning	Z1-039616	Classroom stat 66, request AC unit switch to off mode.
Downtown Elementary	11/5/2024 8:34	BURCHETT	Masonry	Z1-039554	Walts tiles missing and coming off wall.
Zomiomi ziomomary	11/0/20210101	BOHOHEH	· idddin,	21 000004	building needs painting
Downtown Elementary	6/7/2024 9:02	BURCHETT	Painting	Z1-017664	
Downtown Elementary	3/28/2024 15:34	BURCHETT	Painting	WO1006950	Boys restroom on 1st. floor by Library needs to be painted. Thanks
ŕ			· ·		replace 5-1/4 -289 u relief valves
Downtown Elementary	9/10/2024 12:20	WILSON	Plumbing	Z1-031772	
Downtown Elementary	11/6/2024 9:06	STEPHENS	Roofing	Z1-039745	Water leaking from rooftop above east entrance/exit doors inside of building.
Downtown Elementary	10/31/2024 10:43	WILSON	Roofing	Z1-039076	Bad water leaks from rooftop.
Dunbar Elementary	7/29/2024 9:27	TEDDER	Carpentry	Z4-023207	Install door knobs on west side bathroom doors of Melrose Stadium
Dunbar Elementary	7/29/2024 9:24	TEDDER	Carpentry	Z4-023203	Install bathroom stall dividers on west side of Melrose stadium
					Lights out. Changed, but still out
					One has exposed wires(see photo)
Dunbar Elementary	11/6/2024 9:31	HALL	Electrical	Z4-039771	
Dunbar Elementary	7/29/2024 9:44	HALL	Electrical	Z4-023232	Outdoor outlet covers for west side of Melrose Stadium
Dunbar Elementary	6/11/2024 8:13	HALL	Electrical	Z4-017967	Exposed wiring needs to be capped off and removed from kitchen.
					Requesting an electrician to come out remove any hanging or expose power. And also add a
					208v on the wall where the dishwasher once was. Sending attachments call me if you have
					questions Darryl Hunt 901-626-1546
Dunbar Elementary	6/7/2024 7:44	HALL	Electrical	Z4-017647	
Dunbar Elementary	5/6/2024 9:59	HALL	Electrical	Z4-013141	Light guard missing 5/6/24
Dunbar Elementary	4/22/2024 9:21	HALL	Electrical	Z4-010866	Light guards needed on some of them 4/22/24
Dunbar Elementary	4/18/2024 13:38	HALL	Electrical	Z4-010485	Light fixtures falling down 4/18/24
					4/8/24 balance in beam after being changed
Dunbar Elementary	4/8/2024 14:28	HALL	Electrical	Z4-008227	
					Elevator has randomly stopped working. Tried turning off at power switch, still no
Develop Flores store	40/40/000440-40		Florenteen	74.044057	movement.
Dunbar Elementary	12/10/2024 10:46		Elevators	Z4-044257	Keys needed
					keys needed
					208
					208
					313
					312
					110
					1048
Dunbar Elementary	9/30/2024 9:10	MALONE	Key & Lock	Z4-035364	
					Locks need to be changed to match master key set
Dunbar Elementary	7/11/2024 7:49	SMITH	Key & Lock	Z4-020854	Or a key made for teachers lounge
Dunbar Elementary	4/25/2024 13:17	SMITH	Key & Lock	Z4-011582	4/25/24 door in room key gets stuck
					Floor needs patching. Students peeing in hole
Dunbar Elementary	11/15/2024 8:32	BURCHETT	Masonry	Z4-041014	
Dunbar Elementary	8/7/2024 15:14	BURCHETT	Painting	Z4-026182	Main hallway paint is chipping and peeling
Dunbar Elementary	6/18/2024 11:15	BURCHETT	Painting	Z4-018765	Peeling paint on walls and ceilings of the stairwells
Dunbar Elementary	6/18/2024 11:14	BURCHETT	Painting	Z4-018763	Peeling paint from kitchen ceiling
					Sinks in hallway won't turn off completely
Dunbar Elementary	10/1/2024 9:36	JOHNSON	Plumbing	Z4-035652	
					Bottle filler on first floor has broken bottle sensor
Dunbar Elementary	7/10/2024 14:07	JOHNSON	Plumbing	Z4-020797	
					4/30/24 1st stall bowl is leaking cracked
Dunbar Elementary	4/30/2024 7:09	JOHNSON	Plumbing	Z4-012126	
					Ceiling leaking
Dunbar Elementary	11/14/2024 8:09	GILL	Roofing	Z4-040758	
Dunbar Elementary	11/13/2024 13:11	GILL	Roofing	Z4-040666	Ceiling leaking
Dunbar Elementary	11/13/2024 12:51	GILL	Roofing	Z4-040659	Ceiling leaking left side of cafeteria

E.E Jeter School	12/12/2024 9:24	ARNOLD	Carpentry	Z1-044605	Boys restroom door handle installed upside down
E.E Jeter School	11/20/2024 9:56	STEPHENS	Carpentry	Z1-041673	Please assist delivery truck hit and ruined our down spout on the rear of gym
					please assist with window in room 200 has a bad leak
E.E Jeter School	10/8/2024 7:59	RUSSELL	Carpentry	Z1-036571	
E.E Jeter School	12/12/2024 9:28	SMITH	Electrical	Z1-044616	Please assist with new light fixtures
E.E Jeter School	11/21/2024 11:23	SMITH	Electrical	Z1-041939	Bad ballast in kitchen
F.F Jeter School	11/20/2024 9:27	SMITH	Electrical	Z1-041655	Ban hallast
E.E Jeter School	8/8/2024 8:27	SMITH	Electrical	Z1-026245	Bad ballast in cafe
E.E Jeter School	8/8/2024 7:58	SMITH	Electrical	Z1-026231	Bad ballast
E.E Jeter School	8/8/2024 7:58	SMITH	Electrical	Z1-026230	Bad ballast
E.E Jeter School	3/26/2024 8:36	SMITH	Electrical	Z1-006293	Bad ballast in restroom
E.E Jeter School	2/29/2024 10:44	SMITH	Electrical	Z1-003382	Please assist with 5 bad ballast in cafe
E.E Jeter School	2/3/2024 17:14	CHALK	Electrical	W01023933	please assist with light out in parking lot area its on a pole
L.L Jetel School	2/3/2024 17.14	CHALK	Liectricat	WO1023333	Please assist magnet on fire door not holding POCA
E.E Jeter School	10/2/2024 8:21	GREER	Fire Alarm System	Z1-035827	r lease assist magnet on the door not not ding r OCA
					Places essist with replacing tile in grow labby during the placing break if pessible
E.E Jeter School	6/27/2024 11:01	CASEY	Flooring	Z1-019652	Please assist with replacing tile in gym lobby during thanksgiving break if possible
F. F. Jahan Oak and	0.107.1000.4.44.00	OAREV	Floring	74 040050	Please assist with replacing ruined office tile, during fall break if possible
E.E Jeter School	6/27/2024 11:00	CASEY	Flooring	Z1-019650	
E.E Jeter School	4/26/2024 7:53	CASEY	Flooring	Z1-011648	Please assist with removing carpet that has been ruined due to several floods
E.E Jeter School	7/9/2024 9:34	GREER	Generators	Z1-020541	Please assist with getting our generator up and running
					HEATING UNIT IN RM 209 - NOT HEATING SHOWING 65 DEGREES PM/TOLIVER 416-2955
E.E Jeter School	12/6/2024 10:26	WEBB	Heating/Ventilation/Air Conditioning	Z1-043798	
					PER ENERGY MNGT - RM 213- NOT HEATING PM/TRUESDALE 416-2955
E.E Jeter School	12/4/2024 12:48	WEBB	Heating/Ventilation/Air Conditioning	Z1-043371	
					PER ENERGY MNGT - RM 102 - HAS A GAS VALVE ISSUE - NOT HEATING PM/TRUESDALE 416-
					2955
E.E Jeter School	12/4/2024 12:47	WEBB	Heating/Ventilation/Air Conditioning	Z1-043370	
					Ms. Sutton (60568) EE Jeeters Ms Gym is not heating at all
E.E Jeter School	12/4/2024 11:00	WEBB	Heating/Ventilation/Air Conditioning	Z1-043308	
					Ms. Sutton (60568) EE Jeeters Ms D101 is not heating at all
E.E Jeter School	12/4/2024 10:59	WEBB	Heating/Ventilation/Air Conditioning	Z1-043307	
					Mr. Trusdale (416 2955) Units not heating Gym EE Jeeter ES
E.E Jeter School	12/2/2024 11:49	WEBB	Heating/Ventilation/Air Conditioning	Z1-042516	, ,
					Mr. Trusdale (416 2955) Units not heating Principles Office EE Jeeter ES
E.E Jeter School	12/2/2024 11:48	WEBB	Heating/Ventilation/Air Conditioning	Z1-042513	
					HVAC UNIT IN RM 206 - FAN IS NOT BLOWING - NOT COOLING - PM/TRUESDALE 416-2955
E.E Jeter School	8/9/2024 9:33	WEBB	Heating/Ventilation/Air Conditioning	Z1-026639	
					RTU FOR THE GYM OFC - BLOWING HOT AIR PM/TRUESDALE 416-2955
E.E Jeter School	7/9/2024 9:34	WEBB	Heating/Ventilation/Air Conditioning	Z1-020539	
E.E Jeter School	12/12/2024 9:26		Painting	Z1-044611	Please assist with painting walls in gym that are peeling due to age
Lie Jeter deliloot	12/12/2024 5.20		running	21 044011	please assist with painting red door in gym near gym office it has peeling paint
E.E Jeter School	2/22/2024 9:31	BURCHETT	Painting	Z1-002444	please assist with painting red door in gynn hear gynn onice it has peeding paint
E.E Jetel School	2/22/2024 5.31	BUNCHETT	Failiting	21-002444	please assist with peeling paint in gym storage
E.E Jeter School	2/22/2024 9:31	BURCHETT	Painting	Z1-002443	please assist with peening paint in gynn storage
E.E Jetel School	2/22/2024 5.31	BUNCHETT	Failiting	21-002443	places assist with pointing stairwell hand rails
F F later Cahaal	2/20/2024 15:24	BUTLER	Dointing	14/0000000	please assist with painting stairwell hand rails
E.E Jeter School	3/28/2024 15:34	BUILER	Painting	WO999020	Ma Tarradalla (MAC 000F) Controllada anticada actual acceptata
					Mr. Truesdelle (416 2965) Gas testing meter need. possible gas leak
E.E Jeter School	12/13/2024 10:44	AVANZI	Plumbing	Z1-044882	
E.E Jeter School	12/12/2024 14:18	AVANZI	Plumbing	Z1-044768	Flush water heater
E.E Jeter School	12/11/2024 9:04	STEPHENS	Plumbing	Z1-044434	Both toilets will not flush properly causing flooding all day please assist
E.E Jeter School	11/20/2024 9:31	Jordan	Plumbing	Z1-041658	We have a sink handle that is making a whistle noise
E.E Jeter School	2/3/2024 14:49	HATCH	Sheet Metal	WO1029980	GYM UNIT NEED ACCESS CUT INTO DUCT WORK(SEE MIKE SIMMONS)
E.E Jeter School	8/26/2024 8:42	STEPHENS	Welding	Z1-029436	Please assist with a 2foot piece of chain, and 3358 lock
E.E Jeter School	2/3/2024 17:14	SHIPPS	Welding	WO1022463	please assist with basketball goal that is in need of repair, please assist
East CTC	6/28/2024 10:36	POWELL	Electrical	Z2-019759	4 lights are out in the hallway
East CTC	2/3/2024 16:13	Systems	Fire Sprinkler System	WO1024066	Per State Systems Sprinkler technician need to have a painted fire sprinkler head replaced
East High	9/12/2024 13:10	Coleman	Bleachers and Seats	Z2-032295	Repair bleachers. They also won't go all the in
East High	5/28/2024 14:50	LEWIS	Bleachers and Seats	Z2-016171	Bleachers in the gym have disconnected off the track
					Bleachers are malfunctioning
East High	3/4/2024 10:50	LEWIS	Bleachers and Seats	Z2-003727	
East High	12/2/2024 10:10	BURKE	Carpentry	Z2-003727 Z2-042389	Please repair damage in ceiling
East High	12/2/2024 10:10	BURKE	Carpentry	Z2-042369 Z2-042347	Repair damage in Ceiting
Lastrigii	121212024 3.23	DOUVE	Carpentry	LL-04234/	nepan damaged wall I

Mr. Ward (901 607 2072) 3 lights are out.

					141. Walu (901 007 2072) 3 lights are out.
East High	12/16/2024 8:39		Electrical	Z2-044982	
East High	12/10/2024 11:38	POWELL	Electrical	Z2-044276	Replace the ballast please
East High	12/6/2024 7:44	POWELL	Electrical	Z2-043711	No electricity sockets work(3) on west wall please fix
East High	11/19/2024 9:08	POWELL	Electrical	Z2-041435	Install new exit light by double doors that leads to the outside per state fire marshal
East High	11/19/2024 9.08	POWELL	Electricat	22-041435	
					ELECTRICAL OUTLETS ON (10) TABLES ARE NOT WORKING PM/WOODS 416-6104
East High	11/14/2024 13:26	POWELL	Electrical	Z2-040897	
East High	11/7/2024 9:20	POWELL	Electrical	Z2-040064	ne two lights on the west wall above the doors. Perhaps there is a bad ballast. I tried new bulbs, none worked.
East High	11/6/2024 12:22	POWELL	Electrical	Z2-039896	Please check ballasts on 6 lights above bleachers and get them working.
East High	10/29/2024 7:05	POWELL	Electrical	Z2-038604	Install light bulbs please
					Install lightbulbs
Free Librate	40/00/00047-00	DOMELI	Florida	70 000000	instate agricultus
East High	10/29/2024 7:00	POWELL	Electrical	Z2-038602	
East High	10/21/2024 11:07	POWELL	Electrical	Z2-037670	Please fix lights
East High	10/21/2024 10:03	POWELL	Electrical	Z2-037644	Needs light in ceiling please
East High	9/27/2024 11:10	POWELL	Electrical	Z2-035126	Stage lighting needs repair
East High	12/6/2024 6:50	Coleman	Fire Alarm System	Z2-043696	Magnets on fire doors are not working
			,		FA- Circuit Breaker Identifier Install
East High	12/5/2024 15:55	Coleman	Fire Alarm System	Z2-043686	
Lustriigii	12/0/2024 10:00	Cottinui	The Authir Dystein	22 040000	Troubles on Fire Alarm Panel
E	10/5/00011101		F. 41	70.010071	froubles on Fife Atariii Paliet
East High	12/5/2024 14:01	Coleman	Fire Alarm System	Z2-043671	
East High	11/19/2024 10:39	Coleman	Fire Alarm System	Z2-041490	Excursion ring replacement and excursion ring need to be adjusted
East High	10/23/2024 6:37	Coleman	Fire Alarm System	Z2-037907	Sensor needs to be re-installed
East High	9/27/2024 15:32	Coleman	Fire Alarm System	Z2-035241	Reattach detector to ceiling
			,		Replace missing Escutcheon
East High	12/5/2024 15:51	Coleman	Fire Sprinkler System	72-043684	,
Lustriigii	12/0/2024 10:01	Cottinui	The opinical dystem	22 040004	Need Annual Sprinkler Inspection
Free Hillian	40/5/000445:44	0-1	Fire Orninday Contact	70.040070	Need Aimthat Spiritter hispection
East High	12/5/2024 15:11	Coleman	Fire Sprinkler System	Z2-043679	
					Inspect riser please
East High	11/19/2024 11:04	LEWIS	Fire Sprinkler System	Z2-041503	
East High	11/19/2024 10:44	Coleman	Fire Sprinkler System	Z2-041492	Clean sprinkler heads
					Repair 2 PIV's
East High	10/7/2024 10:12	Coleman	Fire Sprinkler System	Z2-036451	
East High	9/25/2024 13:16	Coleman	Fire Sprinkler System	Z2-034688	Replace electrical components
East High	5/9/2024 10:34	Coleman	Fire Sprinkler System	Z2-013835	POCA-Missing sprinkler head
-					
East High	2/3/2024 14:50	Coleman	Fire Sprinkler System	WO1029764	
East High	2/3/2024 15:50	Systems	Fire Sprinkler System	WO1025832	, ,
					Mr. Ward, 901-340-0277 tunnel from building to building
					tile is in air. dangerous for kids to walk in area from each building, kids walk through the
					tunnel everyday
East High	11/7/2024 9:58	BENTON	Flooring	Z2-040083	
East High	12/12/2024 10:50	HANSON	Heating/Ventilation/Air Conditioning	Z2-044693	The thermostat is not working properly, please fix
East High	12/12/2024 8:45	HANSON	Heating/Ventilation/Air Conditioning	Z2-044570	Thermostat not working properly
East High	12/12/2024 8:43	HANSON	Heating/Ventilation/Air Conditioning	Z2-044568	Heater blowing cold air; please fix
-			_		
East High	12/10/2024 9:30	HANSON	Heating/Ventilation/Air Conditioning	Z2-044207	Heater blows only cold air please fix
					MR. BOYD
					901-607-2072
East High	12/5/2024 8:35	HANSON	Heating/Ventilation/Air Conditioning	Z2-043465	
					looks like drip pan installed incorrectly water falling like niagara falls Mr.ward 607-2072
East High	12/4/2024 7:42	HANSON	Heating/Ventilation/Air Conditioning	Z2-043109	
East High	12/2/2024 11:09	HANSON	Heating/Ventilation/Air Conditioning	Z2-042469	Room is really cold and after adjusting the thermostat it still is not coming on
-		HANSON		Z2-042469 Z2-042282	Wall units do not work properly
East High	12/2/2024 8:33		Heating/Ventilation/Air Conditioning		
East High	9/13/2024 9:49	CASEY	Heating/Ventilation/Air Conditioning	Z2-032589	Ceiling leaking
East High	8/21/2024 10:22	HANSON	Heating/Ventilation/Air Conditioning	Z2-028875	Ac Unit drainage pan needs to be replaced
East High	8/1/2024 14:14	SMITH	Key & Lock	Z2-024544	Can this lock be rekeyed to the same key for room 108
East High	8/1/2024 9:09	SMITH	Key & Lock	Z2-024294	need of all exterior doors rekeyed under a new key and 6 of those keys will be needed to be made
East High	5/6/2024 8:32	SMITH	Key & Lock	Z2-013085	A key is not working on the door for 105
o			. 7		.,
					AWNING ON THE HOLMES STREET ENTRANCE AREA - IS COMING DOWN - HAZARDOUS TO
					THE STUDENTS - PLEASE CONTACT PLANT - 607-2072 PM/WARR 416-5160
En est titule	44/40/00040	DUDOUETT	Manager	70.040400	THE STODE INTO - FLEMSE CONTINUT FLAINT - 00/-20/2 PM/WARK 410-3100
East High	11/12/2024 9:47	BURCHETT	Masonry	Z2-040422	
					Repair wall please
East High	11/4/2024 12:17	BURCHETT	Masonry	Z2-039471	
East High	5/17/2024 8:27	BURCHETT	Masonry	Z2-014979	Outer window ledge needs repair

East High	5/21/2024 9:29	DIXON	Painting	Z2-015390	Back Wall and window trim needs a repaint
East High	5/21/2024 9:27	MYERS	Painting	Z2-015386	Back Wall needs a repaint
					Back Wall needs a repaint
East High	5/21/2024 9:27	MYERS	Painting	Z2-015384	
East High	5/21/2024 9:27	MYERS	Painting	Z2-015383	Back Wall needs a repaint
					Back Wall needs a repaint
East High	5/21/2024 9:26	MYERS	Painting	Z2-015382	
•			· ·		Back Wall needs a repaint
East High	5/21/2024 9:25	DIXON	Painting	Z2-015379	
East High	5/21/2024 9:25	DIXON	Painting	Z2-015377	Back Wall needs a repaint
					Back Wall needs a repaint
East High	5/21/2024 9:25	DIXON	Painting	Z2-015376	
					Back Wall needs a repaint
East High	5/21/2024 9:24	DIXON	Painting	Z2-015375	
					Back Wall needs a repaint
East High	5/21/2024 9:23	DIXON	Painting	Z2-015374	
East High	5/21/2024 9:09	DIXON	Painting	Z2-015365	Back wall needs a repaint
East High	9/20/2024 13:15	BENTON	Shades/Blinds	Z2-034043	7 blinds need replacing
Egypt Elementary	12/9/2024 15:31	SMITH	Audio Visual	Z1-044119	Mic isn't being heard out side of cafeteria
Egypt Elementary	11/14/2024 13:01	ARNOLD	Carpentry	Z1-040886	Damaged wood needs to be replaced and repaired
Egypt Elementary	10/1/2024 7:27	ARNOLD	Carpentry	Z1-035580	Window cracked found on Pre-K inspection
Egypt Elementary	7/18/2024 8:52	STEPHENS	Carpentry	Z1-021601	Stairs. Ramp and deck need replacing
Egypt Elementary	3/28/2024 8:04	STEPHENS	Carpentry	Z1-006719	Damaged wood needs to be replaced per principal
Egypt Elementary	2/21/2024 11:33	STEPHENS	Carpentry	Z1-002320	
Egypt Elementary	2/21/2024 11:30 2/13/2024 11:00	STEPHENS JOHNSON	Carpentry	Z1-002317 Z1-001217	
Egypt Elementary Egypt Elementary	2/3/2024 11:00	ARNOLD	Carpentry	WO1025629	, , , , , , , , , , , , , , , , , , , ,
Egypt Elementary	5/17/2024 14:03	ARNOLD	Carpentry Carpentry	WO1023029 WO993785	
Egypt Elementary	5/17/2024 13:39	ARNOLD	Carpentry	WO993763 WO978159	
Egypt Elementary	10/1/2024 7:24	SMITH	Electrical	Z1-035578	Light bulbs out in cafeteria unable to reach Pre-K inspection
Egypt Elementary	9/24/2024 14:21	SMITH	Electrical	Z1-034531	Light ballast is burnt on one end
Egypt Elementary	9/17/2024 9:29	SMITH	Electrical	Z1-033111	Light Ballast is bad
Egypt Elementary	8/8/2024 13:52	SMITH	Electrical	Z1-026467	Hallway ballast need replacing broken piece on end of ballast
Egypt Elementary	7/24/2024 11:27	SMITH	Electrical	Z1-022379	Only one light switch is working on a double switch post
0,1					Replace missing plate cover
Egypt Elementary	4/17/2024 11:18	SMITH	Electrical	Z1-009917	
Egypt Elementary	4/12/2024 11:13	SMITH	Electrical	Z1-009027	Emergency light hanging from base
Egypt Elementary	4/8/2024 15:01	SMITH	Electrical	Z1-008233	No power / water fountain
					HEATING UNIT IN THE MAIN BLDG - RM 301 - NOT COMING ON PM/NELSON 416-4150
Egypt Elementary	12/3/2024 8:34	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042738	
					HEATING UNIT IN THE ANNEX BLDG - RM 8- NOT COMING ON PM/NELSON 416-4150
Egypt Elementary	12/3/2024 8:33	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042737	
					HEATING UNIT IN THE ANNEX BLDG - RM 5- NOT COMING ON PM/NELSON 416-4150
Egypt Elementary	12/3/2024 8:33	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042735	
					HEATING UNIT IN THE ANNEX BLDG - RM 4 - NOT COMING ON PM/NELSON 416-4150
Egypt Elementary	12/3/2024 8:32	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042734	REALING UNIT IN THE ANNEX BLUG - RM 4 - NOT COMING ON PM/NELSON 410-4130
Egypt Elementary	12/3/2024 11:20	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042/34 Z1-042483	esting a portable heater for Interventionist teacher room. Room has been without heat for 2 years.
Egypt Elementary	12/2/2024 11:16	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042463 Z1-042479	Gym heater is not coming on using the thermostats
Egypt Eternentary	12/2/2024 11.10	WILLIAM	riedung/ventitation/Air Conditioning	21-042473	Water leaking from unit. Please see action taken. wds
Egypt Elementary	10/24/2024 10:06	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-038154	Water leaking normalist. Fleader See dedict Autor. Was
Egypt Elementary	9/25/2024 15:35	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-034772	A/C unit has stopped completely not cooling
Egypt Elementary	9/23/2024 11:44	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-034247	Unit not cooling. Installed 2 months ago
Egypt Elementary	9/23/2024 11:43	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-034245	Unit not cooling unit installed 2 months ago
Egypt Elementary	9/5/2024 9:25	SMITH	Key & Lock	Z1-031079	Keyway and cylinder is spinning when trying to lock and unlock door
Egypt Elementary	4/11/2024 14:30	CORONADO	Masonry	Z1-008911	Brick wall has been knocked down
Egypt Elementary	2/21/2024 12:44	CORONADO	Masonry	Z1-002351	
Egypt Elementary	8/12/2024 9:20	BURCHETT	Painting	Z1-026910	
Egypt Elementary	11/14/2024 13:00	Jordan	Plumbing	Z1-040885	Water constantly running water has been cutoff
Egypt Elementary	2/21/2024 11:50	SHIPPS	Welding		
Evans Elementary	10/28/2024 11:34	SCOTT	Electrical	Z3-038536	4 dock lights replaced

Evans Elementary	10/28/2024 11:33	SCOTT	Electrical	Z3-038535	Ballast Replacement
Evans Elementary	9/27/2024 7:46	SCOTT	Electrical	Z3-035011	Ballast Replacement
Evans Elementary	9/20/2024 10:15	SCOTT	Electrical	Z3-033969	Ballast replacement
Evans Elementary	8/2/2024 10:13	SCOTT	Electrical	Z3-033303 Z3-024781	Light needs a new receptical
Evans Elementary	8/2/2024 12:03	SCOTT	Electrical	Z3-024781 Z3-024780	Light needs a new receptical
Evans Elementary	6/17/2024 9:25	SCOTT	Electrical	Z3-024780 Z3-018520	Ballast out
	6/4/2024 13:02	SCOTT	Electrical	Z3-018320 Z3-017149	
Evans Elementary Evans Elementary	4/25/2024 10:16	SMALL	Fire Alarm System	Z3-017149 Z3-011483	Ballast out in the cafeteria Fire Alarm panel showing Trouble
Evans Elementary	4/25/2024 10.16	SMALL	File Alailli Systeili	23-011463	HVAC UNIT FOR RM 202 - NOT COOLING - PM/GRAHAM 416-2504
F	4/40/0004 0:40	WHITWORTH	Handing Mandiladian (Ain Oan didiania	70.040474	TVAC UNIT FOR RM 202 - NOT COOLING - PM/GRAHAM 416-2504
Evans Elementary	4/18/2024 9:13		Heating/Ventilation/Air Conditioning	Z3-010171	
Evans Elementary	10/29/2024 9:57	MALONE	Key & Lock	Z3-038689	Door lock repair
Evans Elementary	10/29/2024 9:55	MALONE	Key & Lock	Z3-038688	Lock added to door to secure testing materials
Evans Elementary	6/11/2024 9:21	BURCHETT	Painting	Z3-017985	Stalls need to be painted
Evans Elementary	5/30/2024 11:34	BURCHETT	Painting	Z3-016505	Room needs be painting
Evans Elementary	5/30/2024 11:27	BURCHETT	Painting	Z3-016500	Room need to be painting
Evans Elementary	5/30/2024 10:52	BURCHETT	Painting	Z3-016474	Room needs to be painted
Evans Elementary	12/2/2024 13:39	PEARSON	Plumbing	Z3-042572	Urinal clogged. PM ran auger down it but was unsuccessful.
					bleachers
Fairley High School	10/15/2024 6:32	HALL	Bleachers and Seats	Z4-036944	
					need 1 white board
Fairley High School	12/9/2024 8:37	ARNOLD	Carpentry	Z4-043971	
					need 1 cork board
Fairley High School	12/9/2024 8:35	ARNOLD	Carpentry	Z4-043970	
					Need 1 cork board and 1 white board
Fairley High School	12/9/2024 8:33	ARNOLD	Carpentry	Z4-043969	
					need door glass replaced
Fairley High School	11/12/2024 9:37	ARNOLD	Carpentry	Z4-040415	
					Need 2 electrical receptacles installed
Fairley High School	12/2/2024 13:20	HALL	Electrical	Z4-042559	
					Back parking lot lights are out
Fairley High School	12/2/2024 5:48		Electrical	Z4-042201	
					#76 through # 83 need repaired
Fairley High School	11/4/2024 6:19	HALL	Electrical	Z4-039334	·
, ,					#66 through #75 need repaired
Fairley High School	11/4/2024 6:15	HALL	Electrical	Z4-039332	·
, ,					#60 through #65 need repaired
Fairley High School	11/4/2024 6:13	HALL	Electrical	Z4-039331	
, .					#50 through #59 need repaired
Fairley High School	11/4/2024 6:10	HALL	Electrical	Z4-039330	
					#26 through #30 need repaired
Fairley High School	11/4/2024 5:58	HALL	Electrical	Z4-039326	
r unto y riigir contoct	11/4/2024 0.00		Elootiloat	21 000020	Exit lights #18 through #25 need repaired
Fairley High School	11/4/2024 5:55	HALL	Electrical	Z4-039325	Entragno #10 through #20 nood repaired
r antey riigh School	11/4/2024 3.33	TIALL	Liectricat	24-033323	11,12,13,14, kitchen,15,16,17 need repaired
Fairley High School	10/31/2024 9:35	HALL	Electrical	Z4-039042	11,12,10,14, McHell,10,10,17 Heed repulled
runtey riigii ocnoot	10/01/2024 0.00	TIMEE	Electricat	24 003042	Elevator not working need repaired
Fairley High School	12/2/2024 6:54	CALDWELL	Elevators	Z4-042210	Elevator not working need repaired
rantey riigii School	12/2/2024 0.04	CALDWELL	Elevators	24-042210	Duct 14 trouble gym RTU 2 Supply
Fairley High Cahaal	10/0/2024 5:42	CALDWELL	Fire Alexan Custom	Z4-043913	Duct 14 flouble gyill KTO 2 Supply
Fairley High School	12/9/2024 5:43	CALDWELL	Fire Alarm System	24-043913	Carinida drinaing water in main hallway 1 at floor
Fairland Bak Oak and	8/27/2024 7:03	CALDWELL	Fire Controller Control	Z4-029671	Sprinkle dripping water in main hallway 1st floor
Fairley High School			Fire Sprinkler System		Floorilla mondanaland
Fairley High School	7/19/2024 21:21	CASEY	Flooring	Z4-021765	Floor tile need replaced
Fairley High School	7/10/2024 21:36	CASEY	Flooring	Z4-020828	Need floor tile replaced
					UNIT NOT HEATING - GYM
Fallet and Color	40/40/0001 = 10	DOM:55	Handing Of a skillaki (M. O. 1991)	74.044616	P/M HULL S 416-1517
Fairley High School	12/13/2024 7:42	DOWNER	Heating/Ventilation/Air Conditioning	Z4-044818	
					ms. Hull 61517 UNITS NOT COMING ON/NOT HEATING
Fairley High School	12/4/2024 9:24	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043204	
					ms. Hull 61517 UNITS NOT COMING ON/NOT HEATING
Fairley High School	12/4/2024 9:22	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043201	
					HEATING UNIT FOR THE MAIN OFC - NOT HEATING PM/HULL 416-1517
Fairley High School	12/4/2024 9:48	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043242	
Fairley High School	11/13/2024 8:44	MALONE	Key & Lock	Z4-040582	1st set of doors not locking need repaired
Fairley High School	9/24/2024 5:59	MALONE	Key & Lock	Z4-034334	Concession stand key broke

Fairley High Cahaal	0/22/2024 12:10	MALONE	Vou 9 Look	Z4-034261	Principal requesting 4 (B) keys for exterior doors.
Fairley High School	9/23/2024 12:18	MALONE	Key & Lock	24-034261	Polovontiro huilding
Fairley High School	9/5/2024 15:51	SMITH	Key & Lock	Z4-031205	Rekey entire building
					These well needs to be renaized
Fairley High School	9/4/2024 11:39	BURCHETT	Masonry	Z4-030907	These wall needs to be repaired Support columns need repaired
Fairley High School	8/28/2024 11:06	BURCHETT	Masonry	Z4-030051	очерного очению посе гориное
Fairley High School	9/18/2024 7:37	BURCHETT	Painting	Z4-033341	Need painted
,			. .		Need painted
Fairley High School	9/17/2024 8:35	BURCHETT	Painting	Z4-033080	
, ,			· ·		Computer lab need painted
Fairley High School	9/11/2024 11:10	BURCHETT	Painting	Z4-031981	
Fairley High School	7/18/2024 20:52	BURCHETT	Painting	Z4-021748	Need painted
Fairley High School	7/11/2024 19:39	BURCHETT	Painting	Z4-020961	Need pressure wash
Fairley High School	7/10/2024 21:39	BURCHETT	Painting	Z4-020829	Need painted
Fairley High School	7/10/2024 21:28	BURCHETT	Painting	Z4-020825	Need painted
					BUSTED PIPE ON THE FRONT LAWN OF THE SCHOOL
					P/M HULL 416-3274
Fairley High School	12/12/2024 13:46	HARRIS	Plumbing	Z4-044758	
Fairley High School	12/10/2024 7:54	HARRIS	Plumbing	Z4-044163	Last stall toilet stopped up
Fairley High School	12/10/2024 7:52	HARRIS	Plumbing	Z4-044161	Toilet has a hole on the side water shooting out when flushing
					Sink pipe leaking water
Fairley High School	10/30/2024 10:36	HARRIS	Plumbing	Z4-038892	
					Sink leaking water from the pipe
Fairley High School	10/25/2024 11:50	HARRIS	Plumbing	Z4-038366	
Fairley High School	10/16/2024 8:04	HARRIS	Plumbing	Z4-037144	Sink hanging off the wall
					3rd stall need a toilet bowl big hold on the side
Fairley High School	9/10/2024 14:17	HARRIS	Plumbing	Z4-031816	
Fairley High School	11/6/2024 12:15	STEVENSON	Roofing	Z4-039891	Roof leak
Farmville Bus Lot	11/12/2024 10:47	ARNOLD	Carpentry	Z1-040448	You got a wall in the break room on the backside that need to be fixed
Farmville Bus Lot	11/21/2024 12:54	SMITH	Electrical	Z1-041963	Need balance change or replaced over it bus station building a in front of Mr. Bridget office
Farmville Bus Lot	11/12/2024 10:45	SMITH	Electrical	Z1-040444	You got two lights on building a that need to be replaced
Farmville Bus Lot	11/12/2024 10:39	SMITH	Electrical	Z1-040442	its four lights on the shop building that need to be replaced because they are out That's on B building
Farmville Bus Lot	4/2/2024 14:58	CHALK	Electrical	WO1012194	
Farmville Bus Lot	4/2/2024 14:58	CHALK	Electrical	WO1012196	,
Farmerilla Broad at	0/00/000440-04	WEDD	Heating 0 / antilation (Air Oam distance	74 000075	HVAC UNIT IN THE OFFICE HAS FROZEN UP PM/NELSON 416-4679
Farmville Bus Lot Farmville Bus Lot	8/22/2024 10:04 11/12/2024 11:17	WEBB BURCHETT	Heating/Ventilation/Air Conditioning Painting	Z1-029075 Z1-040460	Bathroom need to be painted in the men's bathroom and building a
raillivitte bus Lot	11/12/2024 11.1/	BUNCHETT	Failung	21-040460	bautroom need to be painted in the men's bautroom and building a
					MONTHLY DRAW FOR AUDIO VISUAL SUPPLIES FOR THE MONTH OF DECEMBER 2024
Farmville Maintenance Warehouse	11/25/2024 7:30	SMITH	Audio Visual	Z1-042140	Hormer States of Model 2001 Elect of the Horm of Section 2020
Tamming Tiaming Translation	11/20/202-77100	0	Addio Visual	21 0-121-10	
					MONTHLY DRAW FOR AUDIO VISUAL SUPPLIES FOR THE MONTH OF DECEMBER 2024
Farmville Maintenance Warehouse	11/25/2024 7:28	SMITH	Audio Visual	Z1-042139	
					CUT STENCIL FOR PAINTERS
Farmville Maintenance Warehouse	10/30/2024 14:51	TEDDER	Carpentry	Z1-038969	
					secure the wheel stops to keep them from moving or being pushed out of place
Farmville Maintenance Warehouse	8/2/2024 8:06	JOHNSON	Carpentry	Z1-024633	
					Remove old director door signs to be replaced with new signs.
Farmville Maintenance Warehouse	7/24/2024 10:41	RUSSELL	Carpentry	Z1-022347	
					Need Door Installed To Enclose Cage
Farmville Maintenance Warehouse	4/19/2024 9:41	JOHNSON	Carpentry	Z1-010690	
Farmville Maintenance Warehouse	5/17/2024 13:38	STEPHENS	Carpentry	WO975944) ROOM REINFORCE FLOORING ACCESS TO HVAC UNIT (SEE ZONE 1 HVAC FOR LOCATION OF UNIT)
Farmville Maintenance Warehouse	11/21/2024 14:56	ANDREWS	Electrical	Z1-041992	Got a balance out in Mr. Eddie small room over his desk
					REPAIR LIGHTS
Farmville Maintenance Warehouse	9/10/2024 7:49	SMITH	Electrical	Z1-031644	
					Purchase replacement cable and ends to replace power cables for temporary chillers due
					to vandalism and theft
Farmville Maintenance Warehouse	8/29/2024 11:42	CHALK	Electrical	Z1-030283	
				74 0	Purchase of (3) 5 Port Ethernet Switches for Energy Management
Farmville Maintenance Warehouse	10/14/2024 7:17	WOOD	Energy Management System	Z1-036765	DOI! ED INODECTION
Formuillo Mointenance Wor-	10/7/2024 10:02	WILL CON	Francis Managament Curt	71 000455	BOILER INSPECTION
Farmville Maintenance Warehouse	10/7/2024 10:22	WILSON	Energy Management System	Z1-036455	

					Lay carpet squares
Farmville Maintenance Warehouse	12/5/2024 13:35	LEWIS	Flooring	Z1-043657	Install carpet squares
Farmville Maintenance Warehouse	11/12/2024 11:11	CASEY	Flooring	Z1-040454	Please provide 6 pad locks for new hire. Larry Williams sheet metal tech.
Farmville Maintenance Warehouse	12/13/2024 10:24	MORRIS	Key & Lock	Z1-044877	
					MONTHLY DRAW FOR LOCKSMITH MATERIALS/SUPPLIES FOR THE MONTH OF DECEMBER - 2024 HW
Farmville Maintenance Warehouse	12/3/2024 8:54	SMITH	Key & Lock	Z1-042760	MONTHLY DRAW FOR LOCKSMITH MATERIALS/SUPPLIES FOR THE MONTH OF November -
Farmville Maintenance Warehouse	11/15/2024 15:44	SMITH	Key & Lock	Z1-041145	2024 KW
			, 2 200		MONTHLY DRAW FOR LOCKSMITH MATERIALS/SUPPLIES FOR THE MONTH OF October - 2024 KW
Farmville Maintenance Warehouse	9/30/2024 15:40	SMITH	Key & Lock	Z1-035549	
					MONTHLY DRAW - MASONARY MATERIALS/SUPPLIES FOR THE MONTH OF DECEMBER - 2024 HW
Farmville Maintenance Warehouse	11/25/2024 7:58	BURCHETT	Masonry	Z1-042150	MONTHLY DRAW - MASONARY MATERIALS/SUPPLIES FOR THE MONTH OF OCTOBR - 2024
Farmville Maintenance Warehouse	10/1/2024 7:25	BURCHETT	Masonry	Z1-035579	HW
rannvide Plantenance Warehouse	10/1/2024 / .23	BONGIETI	riasoniy	21-033373	MONTHLY DRAW FOR PAINTERS MATERIALS/SUPPLIES FOR THE MONTH OF DECEMBER -
Farmville Maintenance Warehouse	11/25/2024 7:53	BURCHETT	Painting	Z1-042149	2024 HW
					MONTHLY DRAW FOR PAINTERS MATERIALS/SUPPLIES FOR THE MONTH OF OCTOBER - 2024 HW
Farmville Maintenance Warehouse	10/1/2024 7:22	BURCHETT	Painting	Z1-035577	Test RP device as noted on letter.
Farmville Maintenance Warehouse	12/10/2024 10:09	OWENS	Plumbing	Z1-044244	
Farmville Maintenance Warehouse	9/30/2024 7:52	STEPHENS	Roll Up Doors	Z1-035310	Please repair main entry door auto shop west.
Farmville Maintenance Warehouse	5/17/2024 14:27	SMITH	Sheet Metal	WO1012157	Remove excess scrap metal replace defective pads and rotors
Farmville Maintenance Warehouse	12/16/2024 6:32	DAVIS	Vehicle Maintenance	Z1-044957	fix heat
Farmville Maintenance Warehouse	12/13/2024 12:03	DAVIS	Vehicle Maintenance	Z1-044894	
Farmville Maintenance Warehouse	12/13/2024 10:00	DAVIS	Vehicle Maintenance	Z1-044867	repair shifter
Farmville Maintenance Warehouse	12/12/2024 10:13	DAVIS	Vehicle Maintenance	Z1-044677	repair fuel leak
					Truck #1318 Ford F-150 Possibly in need of a fuel pump, will crank but won't start.
Farmville Maintenance Warehouse	12/10/2024 7:56	NASH	Vehicle Maintenance	Z1-044164	
Farmville Maintenance Warehouse	12/10/2024 7:23	DAVIS	Vehicle Maintenance	Z1-044153	CHANGE OIL IN TRUCK 1931
Farmville Maintenance Warehouse	12/10/2024 7:15	DAVIS	Vehicle Maintenance	Z1-044150	CHANGE OIL IN TRUCK 1930
Farmville Maintenance Warehouse	12/5/2024 7:16	DAVIS	Vehicle Maintenance	Z1-043422	repair vehicle
rummae rumenance warehouse	12/3/2024 7.10	DAVIO	Verificial Humberlands	21 040422	Dump Trailer has four (4) worn tires. Need to replace ASAP for crucial operations. Tire Sze
Farmville Maintenance Warehouse	12/4/2024 10:51	DAVIS	Vehicle Maintenance	Z1-043302	ST235/85R16
Farmville Maintenance Warehouse	11/20/2024 7:09	DAVIS	Vehicle Maintenance	Z1-041591	SERVICE VEHICLE NUMBER 2905 FOR NEW EMPLOYEE
Farmville Maintenance Warehouse	11/13/2024 8:51	DAVIS	Vehicle Maintenance	Z1-040584	get back running
					check oil leak heat stuck in heat and rear tire bald
Farmville Maintenance Warehouse	11/5/2024 9:26	DAVIS	Vehicle Maintenance	Z1-039571	Need a new tire size 265/70R17
Farmville Maintenance Warehouse	11/1/2024 8:37	DAVIS	Vehicle Maintenance	Z1-039192	replace bcm and reprogram
Farmville Maintenance Warehouse	10/16/2024 9:57	DAVIS	Vehicle Maintenance	Z1-037198	

Please replace the rear parking lot lights this area is very dark. This repair will require the bucket truck.

Flicker St. Clinic	10/16/2024 /:31	POWELL	Electrical	22-03/131	
					Please investigate electrical issue in room 200 Plant Manager thinks there may be a problem with the light switch. (Plant Manager has to turn the switch off and on for the lights to turn on) This is a problem with several light switches on the 2nd floor.
Flicker St. Clinic	9/13/2024 6:48	POWELL	Electrical	Z2-032399	to turn only this is a problem with several agrit switches on the ziru itool.
T HOROT OLI GUING	0/10/2024 0:40		Libbinout	22 002000	Please replace the ballast in a 2-tube light.
Flicker St. Clinic	7/9/2024 8:24	POWELL	Electrical	Z2-020508	
					Mrs. Karmeisha Johnson is requesting Master Keys made for all doors in the flicker St location. I will forward the e-mail I reconceived.
Flicker St. Clinic	9/30/2024 9:13	MALONE	Key & Lock	Z2-035368	
					Mrs. Karmeisha Johnson Manger of the Flicker St Clinic is requesting the entire Clinic located on the lower floor be painted.
Flicker St. Clinic	5/16/2024 9:55	BUTLER	Painting	Z2-014822	
Ford Road Elementary	12/12/2024 11:43	ARNOLD	Carpentry	Z4-044711	Classroom 8 which is located in the annex the classroom lock will not lock.
Ford Road Elementary	12/11/2024 14:58	ARNOLD	Carpentry	Z4-044512	The door coming out of the story is off of the bracket.
Ford Road Elementary	10/23/2024 9:43	ARNOLD	Carpentry	Z4-037965	rten hallway floor needs repair subfloor is coming up. It's a trip hazard for staff, children, and parents. Disconnect Wiring for pick up
Ford Road Elementary	12/13/2024 6:04	HALL	Electrical	Z4-044797	
Ford Road Elementary	10/2/2024 8:13	HALL	Electrical	Z4-035819	Riser room behind cafeteria needs wires to be covered back up.
					A wrench is needed in the red box in the riser room behind the cafeteria.
Ford Road Elementary	10/2/2024 8:14	CALDWELL	Fire Sprinkler System	Z4-035820	
Ford Road Elementary	11/21/2024 11:56	LEWIS	Flooring	Z4-041946	Sub flooring needs replacing in classroom 14 in the main building on the 2nd grade hallway.
Ford Road Elementary	3/13/2024 12:10	CASEY	Flooring	Z4-005008	Principal requested floor tile in the hallways main and two-story building to be replaced.
1 ord Hoad Elementary	3/13/2024 12.10	CASET	rtoomig	24-003000	Classroom 3 in the annex the unit is not coming on.
Ford Road Elementary	12/11/2024 7:55	DOWNER	Heating/Ventilation/Air Conditioning	Z4-044412	Catalogon o in the annotate and to locationing on
Ford Road Elementary	12/4/2024 9:34	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043220	Classroom 15 in the main building on the 2nd grade hallway unit will not come on.
Ford Road Elementary	12/4/2024 9:32	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043218	Classroom 13 in the main building on the 2nd grade hallway heat is blowing cool air.
Ford Road Elementary	12/2/2024 7:20	DOWNER	Heating/Ventilation/Air Conditioning	Z4-042218	Classroom 44 in the two story building unit is humming and not coming on.
Ford Road Elementary	11/6/2024 7:55	MALONE	Key & Lock	Z4-039696	These classrooms need keys to get their classrooms.
Ford Road Elementary	10/2/2024 7:59	BURCHETT	Masonry	Z4-035813	Boy's restroom in the main building needs repair for safety.
Ford Road Elementary	10/2/2024 7:58	BURCHETT	Masonry	Z4-035812	Girls restroom on 3rd grade hallway/2nd floor in the two-story building.
,			,		The girls restroom on the second floor the last stall tile need to be replaced.
Ford Road Elementary	2/21/2024 15:03	CORONADO	Masonry	Z4-002390	
Ford Road Elementary	3/28/2024 15:33	CORONADO	Masonry	WO999568	oys restroom in the main building in front of the main office need tile put down due to a trip hazard.
Ford Road Elementary	12/9/2024 10:58	BURCHETT	Painting	Z4-044044	Principal request the conference room in the main office to be repainted. The request that the walls and rails in the two-story building to be painted.
Ford Road Elementary	5/1/2024 8:47	BUTLER	Painting	Z4-012465	
					The principal request the lines outside in the front on the building where the staff parks repainted.
Ford Road Elementary	4/19/2024 9:17	BUTLER	Painting	Z4-010683	
Ford Road Elementary	4/19/2024 8:51	BUTLER	Painting	Z4-010664	The 1st/2nd grade hallway wall needs painting
Ford Road Elementary	5/17/2024 14:29	BURCHETT	Painting	WO1013287	The bus lanes have to be repainted in the back area of the school. Boys restroom in the two story building on the 2nd/3rd grade hallway needs do not flush and water not going down.
Ford Road Elementary	11/20/2024 10:47	HARRIS	Plumbing	Z4-041707	· ·
Ford Road Elementary	11/22/2024 8:04	STEVENSON	Roofing	Z4-042011	By the exit door on the kindergarten hallway the ceiling is leaking water.
Ford Road Elementary	11/13/2024 13:22	STEVENSON	Roofing	Z4-040673	Classroom 4 in the annex is leaking water from the ceiling.
Ford Road Elementary	11/13/2024 13:17	FORD	Roofing	Z4-040671	Classroom 7 in the annex is leaking water from the light fixture.
Ford Road Elementary	10/28/2024 12:46	STEVENSON	Roofing	Z4-038553	Classroom 2 in annex leaking water in the back of the classroom.
Ford Road Elementary	10/28/2024 12:44	TEDDER	Roofing	Z4-038552	Classroom 1 in annex leaking in the back of the classroom.
- w	40/04/00040	14/500		70.000040	pre-k window stuck an is a safety hazard
Fox Meadows Elementary	10/31/2024 8:22	WEBB	Carpentry	Z3-039013	exit windows in PRE-K wont go up and down safety hazard
Fox Meadows Elementary	10/31/2024 8:21	WEBB	Carpentry	Z3-039012	
					WINDOW STUCK SAFETY HAZZARD
Fox Meadows Elementary	9/24/2024 10:22	WEBB	Carpentry	Z3-034452	WINDOW STUCK SAFETY HAZZARD
Fox Meadows Elementary	9/24/2024 10:21	WEBB	Carpentry	Z3-034451	

Flicker St. Clinic

10/16/2024 7:31

POWELL

Electrical

Z2-037131

WINDOW STUCK SAFETY HAZZARD

Fox Meadows Elementary	9/24/2024 10:19	WEBB	Carpentry	Z3-034450	mileon diodical El mazza de
Fox Meadows Elementary	5/16/2024 14:38	CROUSE	Carpentry	Z3-014929	POCA ALL BATHROOM DOORS REMOVED SHALL BE REINSTALLED. (6 doors Total CB)
Tox Freadows Elementary	3/10/2024 14.30	CHOUSE	Carpentry	25-014525	BAD BALLAST
Fox Meadows Elementary	12/10/2024 9:50	SCOTT	Electrical	Z3-044230	
					BAD BALLAST
Fox Meadows Elementary Fox Meadows Elementary	12/10/2024 9:49 12/2/2024 8:07	SCOTT SCOTT	Electrical Electrical	Z3-044229 Z3-042248	Bad Ballast
Fox Meadows Elementary	11/18/2024 8:34	SCOTT	Electrical	Z3-042246 Z3-041201	Bad ballast
Tox Toddon's Elementary	11/10/2021 0101	555.1	Elocurous	20 0 1202	bad ballast
Fox Meadows Elementary	11/14/2024 10:24	SCOTT	Electrical	Z3-040832	
					BAD BALLAST
Fox Meadows Elementary	11/14/2024 10:21	SCOTT	Electrical	Z3-040829	242 244 497
Fox Meadows Elementary	11/14/2024 10:17	SCOTT	Electrical	Z3-040825	BAD BALLAST
FOX Meduows Elementary	11/14/2024 10.1/	30011	Electricat	23-040023	NEEDS NEW LIGHTS UNDER THE CANOPY
Fox Meadows Elementary	10/30/2024 12:34	SCOTT	Electrical	Z3-038943	
					light fixture broken
Fox Meadows Elementary	10/28/2024 9:15	SCOTT	Electrical	Z3-038476	
					electrical outlet not working outlet by file cabinet
Fox Meadows Elementary	7/30/2024 8:50	SCOTT	Electrical	Z3-023625	POCA NEED BREAKER BLANKS/FILLER PLATES FOR EMPTY SLOTS IN ELECTRICAL BREAKER
					BOXES
Fox Meadows Elementary	5/16/2024 14:27	SCOTT	Electrical	Z3-014920	BONES
					POCA-B200B Need Electrical Plate covering outlet
Fox Meadows Elementary	5/13/2024 11:55	SCOTT	Electrical	Z3-014256	
					POCA C207M Need Electrical Plate Cover
Fox Meadows Elementary	5/13/2024 11:49	SCOTT	Electrical	Z3-014253	
Fox Meadows Elementary	5/13/2024 11:33	WHITWORTH	Electrical	Z3-014246	POCA-B102J Breaker outlets missing from electrical box
Fox Meadows Elementary	4/9/2024 19:53	SCOTT	Electrical	Z3-008477	Kitchen Vent Not Functioning Properly
•					· ,
					POCA SCHOOL SHALL MAINTAIN CLEAR PATH TO ALL EMERGENCY EXITS IMMEDIATELY
Fox Meadows Elementary	5/16/2024 14:34	SMALL	Fire Alarm System	Z3-014926	
Fox Meadows Elementary	5/16/2024 14:14	SMALL	Fire Alarm System	Z3-014908	POCA REMOVE DECORATIONS FROM ALL FIRE RATED DOORS
Fox Meadows Elementary	5/16/2024 14:12	SMALL	Fire Alarm System	Z3-014906	POCA remove open flame candles from the building immediately
Fox Meadows Elementary	5/13/2024 11:58	SMALL	Fire Alarm System	Z3-014257	POCA-Records of all required inspections
FOX Meadows Elementary	5/13/2024 11.56	SMALL	Fire Atarin System	23-014257	POCA-Fire extinguishers need inspections. C118, Pre-k Classrooms.
Fox Meadows Elementary	5/13/2024 11:53	SMALL	Fire Alarm System	Z3-014254	1 CONTING CALANGUISTICS INCOME INSPECTATION CITES, 1 TO A CALCUSTOSING.
•			•		POCA-Riser Room needs signage
Fox Meadows Elementary	5/13/2024 11:32	SMALL	Fire Alarm System	Z3-014245	
			- · · · · · · · ·	70.044004	POCA-Art work and teaching materials does not exceed over 50%
Fox Meadows Elementary	5/13/2024 10:52	SMALL	Fire Alarm System	Z3-014224	POCA-Annual and 5 year inspection Report
Fox Meadows Elementary	5/13/2024 10:49	SMALL	Fire Alarm System	Z3-014223	1 OGA-Allituat and 3 year inspection neport
,			· · · · · · · · · · · · · · · · · · ·		POCA REPLACE MISSING SPRINKLER HEAD RING/COVERS
Fox Meadows Elementary	5/16/2024 14:24	SMALL	Fire Sprinkler System	Z3-014917	
					NO HEAT
Fox Meadows Elementary	12/8/2024 11:11	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043900	NOTIFAT
Fox Meadows Elementary	12/8/2024 11:10	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043899	NO HEAT
Tox ricadows Elementary	12/0/2024 11:10	OOLITIIL	ricumy vendudon/An Conditioning	20 040000	NO HEAT
Fox Meadows Elementary	12/8/2024 11:10	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043898	
					NO HEAT IN KITCHEN AREA OR RESTROOMS
Fox Meadows Elementary	12/6/2024 10:54	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043809	
Fox Meadows Elementary	12/2/2024 15:03	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-042621	No heat
Fox Meadows Elementary	12/2/2024 15:02	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-042619	No heat
Fox Meadows Elementary	12/2/2024 15:01	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-042618	No heat
Fox Meadows Elementary	10/0/000110	OOFTLUE		Z3-042563	No heat
	12/2/2024 13:28	GUETHIE	Heating/ventilation/Air Conditioning	Z3-U4Z303	INU HEAL
Fox Meadows Elementary	12/2/2024 13:28 12/2/2024 13:27	GOETHIE GOETHIE	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z3-042562	No heat

					NEED KEY
Fox Meadows Elementary	9/19/2024 10:44	MALONE	Key & Lock	Z3-033715	
					NEED KEY TO ROOM
Fox Meadows Elementary	9/19/2024 10:43	MALONE	Key & Lock	Z3-033714	
Fox Meadows Elementary	5/20/2024 20:32	SMITH	Key & Lock	Z3-015304	Need door knob
Fox Meadows Elementary	5/17/2024 14:32	SMITH	Key & Lock	WO1015482	Room 34 in the two story need a key made.
Fox Meadows Elementary	11/12/2024 8:15	BURCHETT	Painting	Z3-040380	Chipped paint on ceiling possibly fall into food safety hazard
Fox Meadows Elementary	10/31/2024 10:34	BURCHETT	Painting	Z3-039073	chipped paint on ceiling keep taken hits on PRE-K inspections
TOX Pleadows Elementary	10/31/2024 10:54	DONOTIETT	1 anung	23-033073	SAFETY HAZZARDROOF OF KITCHEN PAINT CHIPPED REALLY BAD
Fox Meadows Elementary	10/1/2024 9:22	BURCHETT	Painting	Z3-035643	GREET THE BUILDING OF MICHELY AND GREET GREET GREET
· · · · · · · · · · · · · · · · · · ·					
					CEILING PAINT CHIPPING AND ITS A HEALTH DEPT HAZZARD MAY FALL IN SOME FOOD
Fox Meadows Elementary	9/3/2024 9:21	BURCHETT	Painting	Z3-030644	
Fox Meadows Elementary	6/10/2024 10:15	BURCHETT	Painting	Z3-017842	Need touch up paint
Fox Meadows Elementary	2/7/2024 14:00	BURCHETT	Painting	Z3-000583	Can we get the bathroom stalls painted if it's not too much trouble
Fox Meadows Elementary	2/7/2024 9:07	BURCHETT	Painting	Z3-000521	the bus lane. Can we have a painter come and paint BUS LANE with NO PARKING written as well the nobody can tell it's bus lane
					Have three backflows tested at this location (progressive Plbg.)
Fox Meadows Elementary	12/6/2024 9:39	WILSON	Plumbing	Z3-043773	
Fox Meadows Elementary	12/2/2024 15:16	TOLES	Plumbing	Z3-042635	Possible busted pipe
Fox Meadows Elementary	11/21/2024 8:06	BARNES	Plumbing	Z3-041837	Dripping faucet inside classroom
Fox Meadows Elementary	11/18/2024 10:32	WILSON	Plumbing	Z3-041242	P.O.E water flow needs to be tested per MLG&W
FOX Meadows Elementary	11/10/2024 10.32	WILSON	Fluitibilig	23-041242	POCA FIRE ROLL UP DOORS SHALL ANNUAL INSPECTION AND REPAIRED IF NOT
					OPERATIONAL
Fox Meadows Elementary	5/16/2024 14:19	SMALL	Roll Up Doors	Z3-014913	of Elements.
· · · · · · · · · · · · · · · · · · ·					used fluorescent bulb pick up
Frayser-Corning Elementary	12/15/2024 19:15	LANE	Asbestos	Z1-044943	·
					There is a stained ceiling tile in this stairwell that 14ft or higher needs replaced
Frayser-Corning Elementary	8/13/2024 10:33	ARNOLD	Carpentry	Z1-027254	
					There is a stained ceiling tile with a sprinkler head in it that's 14ft or higher needs replaced.
Frayser-Corning Elementary	8/13/2024 10:30	ARNOLD	Carpentry	Z1-027253	
Frances Corning Flamentons	0/20/2024 14:20	DUCCELL	Cornentry	71 010040	There are 20 ceiling tiles in the auditorium that is 14ft. or higher that need replacing.
Frayser-Corning Elementary	6/20/2024 14:38	RUSSELL	Carpentry	Z1-018940	
					The ceiling tiles in this area needs replacing, these ceiling tiles are not like the ones I have.
Frayser-Corning Elementary	4/4/2024 10:28	ARNOLD	Carpentry	Z1-007738	The celling thes in this thea needs replacing, these celling thes are not the ones mare.
,,			22.62,		The window in this area is leaking from the heavy rain.
Frayser-Corning Elementary	4/2/2024 8:28	ARNOLD	Carpentry	Z1-007176	
Frayser-Corning Elementary	3/28/2024 15:32	LEWIS	Carpet Repair	WO1003044	Prinicipal has moved her office and requesting the carpet removed from this office.
					The lights are not coming on in this restroom. High Priority
Frayser-Corning Elementary	12/6/2024 7:32	SMITH	Electrical	Z1-043706	
					The light fixture above Mr. Watson desk needs to be changed to the regular T8 lights, the
					lihgts in this fixture are the big ones.
Frayser-Corning Elementary	12/2/2024 9:42	SMITH	Electrical	Z1-042367	
					For any contribute the contribute of the contrib
Frayser-Corning Elementary	11/5/2024 8:01	SMITH	Electrical	Z1-039543	Emergency light #5 needs to be replaced with a newer light, located above employee table.
Frayser-Corning Elementary	11/5/2024 8.01	SMILL	Electricat	21-039543	Wall plate cover is needed in this room to cover hole.
Frayser-Corning Elementary	11/1/2024 15:20	SMITH	Electrical	Z1-039316	wall plate cover is needed in this footh to cover note.
Trayser-Corning Elementary	11/1/2024 15.20	Ji-IIIII	Electricat	21-033310	The 7th light fixture has bad sockets
Frayser-Corning Elementary	9/30/2024 12:11	SMITH	Electrical	Z1-035473	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					The bulb in this outside fixture is blown.
Frayser-Corning Elementary	9/6/2024 15:37	SMITH	Electrical	Z1-031382	
• •					The bulb in this fixture is blown
Frayser-Corning Elementary	9/6/2024 15:36	CHALK	Electrical	Z1-031381	
					The lights in this restroom keeps going out. I changed the same two bulbs last week.
Frayser-Corning Elementary	8/19/2024 7:37	SMITH	Electrical	Z1-028247	T
		0.071		74 000440	There is a light fixture with a bad Ballester.

Z1-008142

Electrical

SMITH

4/8/2024 9:58

Frayser-Corning Elementary

					There is a light with a bad socket in this room.
Frayser-Corning Elementary	4/3/2024 10:30	SMITH	Electrical	Z1-007562	There is a light with a bad socket in this footh.
5 0 1 5		0.477.1		74 00 4005	The lights has a bad ballast
Frayser-Corning Elementary	3/12/2024 9:50	SMITH	Electrical	Z1-004885	This classroom has a set of lights with bad socket, tried to change bulbs and they are flickering.
Frayser-Corning Elementary	2/22/2024 9:17	SMITH	Electrical	Z1-002433	There are one set of lights with a bad socket.
Frayser-Corning Elementary	2/14/2024 8:04	SMITH	Electrical	Z1-001346	
Frayser-Corning Elementary	4/2/2024 14:58	CHALK	Electrical	WO1012169	The exterior light above the door entrance is blinking about to blow.
Francis Organizat Florescenters	40/40/00047-00		Fire Manne Contains	74 044000	Fire Alarm panel reads: Trouble Waterflow Boiler RM Riser Open 04:13A 121324 1M010
Frayser-Corning Elementary Frayser-Corning Elementary	12/13/2024 7:26 12/12/2024 15:23		Fire Alarm System Fire Alarm System	Z1-044808 Z1-044784	When alarm panel shows (water flow)it should say this
					Alarm panel reads: Trouble Waterflow Boiler RM Riser Open 06:13a 120624 1M10
Frayser-Corning Elementary	12/6/2024 7:11	GREER	Fire Alarm System	Z1-043700	(POCA) sprinkler head rings are needed in the office.
Frayser-Corning Elementary	4/25/2024 11:44	GREER	Fire Sprinkler System	Z1-011525	-
Frayser-Corning Elementary	11/7/2024 7:58	CASEY	Flooring	Z1-040001	Replace chipped floor tile in this area.
Frayser-Corning Elementary	11/7/2024 7:56	CASEY	Flooring	Z1-040000	Replace chipped floor tiles in this classroom.
			_		Replace chipped floor tiles in this classroom.
Frayser-Corning Elementary	11/7/2024 7:54	CASEY	Flooring	Z1-039997	Ms. Williams (416 3840 (901 5310095)) Water in the Boiler in pump # 1 is below 65degrees.
5 0 1 5				74 044054	Located in the lower level of the building
Frayser-Corning Elementary	12/10/2024 14:39	WEBB	Heating/Ventilation/Air Conditioning	Z1-044354	Ac unit leaks.
Frayser-Corning Elementary	11/14/2024 7:29	WEBB	Heating/Ventilation/Air Conditioning	Z1-040745	Ac unit leaking and teacher says that it smells like mold in her room.
Frayser-Corning Elementary	10/31/2024 14:54	WEBB	Heating/Ventilation/Air Conditioning	Z1-039149	······································
					The door lock needs to be changed for the Assistant Principal to make this his office.
Frayser-Corning Elementary	12/6/2024 7:35	MALONE	Key & Lock	Z1-043707	
Frayser-Corning Elementary	12/9/2024 12:51	BURCHETT	Masonry	Z1-044079	Grout between ceramic tiles are missing The principal is requesting that this part of the building needs painting.
Frayser-Corning Elementary	8/28/2024 12:12	BURCHETT	Painting	Z1-030071	
Frayser-Corning Elementary	8/28/2024 12:08	BURCHETT	Painting	Z1-030069	The principal is requesting the first floor of this building to be painted.
					The principal is asking for this location to be painted classrooms, office, auditorium. The whole building.
Frayser-Corning Elementary	5/30/2024 15:09	BURCHETT	Painting	Z1-016572	
Frayser-Corning Elementary	3/28/2024 15:32	BRYANT	Painting	WO1006157	The partitions in this restroom have peeling paint and rusted metal exposed. The stall next to the urinals does not flush properly, used the snake on it.
Frayser-Corning Elementary	12/13/2024 14:52	Jordan	Plumbing	Z1-044935	
					The fifth stall toilet does not flush properly, I have used the snake several times to make sure nothing is left in it.
Frayser-Corning Elementary	12/13/2024 14:50	Jordan	Plumbing	Z1-044934	
Frayser-Corning Elementary	9/26/2024 10:59	Jordan	Plumbing	Z1-034899	The AC unit is leaking, turned unit off
France Corning Flamenton	10/29/2024 10:23	GREER	Dell He Deere	Z1-038704	Roll up doors needs annual inspection.
Frayser-Corning Elementary Frayser-Corning Elementary	3/7/2024 9:54	Williams	Roll Up Doors Sheet Metal	Z1-038704 Z1-004408	n old work order (1006157), the exposed metal the kids are touching it. This metal needs to be removed
Trayser coming Eternemary	0///2024 0.04	Wittidins	Sheet Fletat	21 004400	Need Bleacher Inspection
G.W. Carver College & Career Academy	6/10/2024 12:41	CALDWELL	Bleachers and Seats	Z4-017879	3 big outdoor lights want come on to dark people be hiding out when I get there in the morning.
G.W. Carver College & Career Academy	12/9/2024 23:30	HALL	Electrical	Z4-044138	
G.W. Carver College & Career Academy	12/9/2024 23:23	HALL	Electrical	Z4-044137	2 light needs a balance in them bells
G.W. Carver College & Career Academy	7/31/2024 6:27	HALL	Electrical	Z4-023910	ההווצ

G.W. Carver College & Career Academy	6/10/2024 13:56	HALL	Electrical	Z4-017918	Exit lights need to be working.
G.W. Carver College & Career Academy	3/28/2024 15:41	HALL	Electrical	WO995067	Emergency lights not working in old gym. Thanks
G.W. Carver College & Career Academy	11/19/2024 23:28	CALDWELL	Elevators		ator is down doors want close the elevator floor has drop 2 inches this elevator going to cafeteria .
G.W. Carver College & Career Academy	12/2/2024 18:16	CALDWELL	Fire Alarm System	Z4-042652	ial , the system trouble disable point an alarm silence main office/ cafeteria. Could you have someone to come out here and check the fire alarm system and reset it. HVAC UNIT IN THE MECHANICAL RM 303 - LEAKING DOWN IN THE SCIENCE LAB PM/SMITH 416-7424
G.W. Carver College & Career Academy	11/21/2024 9:26	WRIGHT	Heating/Ventilation/Air Conditioning	Z4-041880	
G.W. Carver College & Career Academy	12/12/2024 8:38	TEDDER	Masonry	Z4-044564	cover needs to be replaced the concrete around it is all broke up and the health department lady said something about it
G.W. Carver College & Career Academy	11/19/2024 23:33	JOHNSON	Plumbing	Z4-041577	Sink hanging off the wall in girls shower.
					NEED WATER TURNED ON IN THE GYM G RR - PM/SMITH
G.W. Carver College & Career Academy	9/24/2024 10:54	TEDDER	Plumbing	Z4-034460	
					Pick up A/c Condenser Unit
G.W. Carver College & Career Academy	12/13/2024 7:08	SMITH	Sheet Metal	Z4-044803	
	40/40/0004700	0.071		7	Pick up Condenser Unit
G.W. Carver College & Career Academy	12/13/2024 7:06	SMITH	Sheet Metal	Z4-044802	Pick up A/c Condenser Unit
G.W. Carver College & Career Academy	12/13/2024 7:03	SMITH	Sheet Metal	Z4-044801	Pick up AC Conductiser Onlic
O.W. Carver College & Career Academy	12/15/2024 7.05	Ji-IIIII	Sileet Hetat	24-044001	relace fade sign
Gardenview Elementary	12/12/2024 12:02	FORD	Carpentry	Z4-044720	reace ade sign
curaciment Eternomany	12/12/2024 12:02	. 01.5	Carponary	2.7 0.1.7.20	THE VENT HOOD WANT TURN ON
Gardenview Elementary	7/23/2024 13:17	HALL	Electrical	Z4-022161	
•					The blower on the unit stopped working
Gardenview Elementary	12/12/2024 9:34	DOWNER	Heating/Ventilation/Air Conditioning	Z4-044624	
					The blew on the unit stopped working
Gardenview Elementary	12/12/2024 9:33	DOWNER	Heating/Ventilation/Air Conditioning	Z4-044623	
					unit makes loud noise from motor
Gardenview Elementary	12/5/2024 15:37	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043683	
					unit want turn on
Gardenview Elementary	12/5/2024 15:36	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043682	
					no heat
Gardenview Elementary	12/5/2024 15:35	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043681	No heat blowing cold air
Gardenview Elementary	12/3/2024 10:47	DOWNER	Heating/Ventilation/Air Conditioning	Z4-042880	NO HEAL DOWING COLD AIR
Cardenview Liementary	12/3/2024 10.4/	DOWNER	rieating/ventitation/Air Conditioning	24-042000	unit turn on and off no heat
					unctum of the or no field
Gardenview Elementary	12/3/2024 10:45	DOWNER	Heating/Ventilation/Air Conditioning	Z4-042879	
•					Unit stop working want turn on
Gardenview Elementary	9/19/2024 9:36	DOWNER	Heating/Ventilation/Air Conditioning	Z4-033654	
					Unite motor start making loud noises.
Gardenview Elementary	8/19/2024 9:02	DOWNER	Heating/Ventilation/Air Conditioning	Z4-028304	
					Unit stop running motor just hums
Gardenview Elementary	8/15/2024 13:41	DOWNER	Heating/Ventilation/Air Conditioning	Z4-027865	
					unit want turn on just hums.
Gardenview Elementary	8/6/2024 15:30	DOWNER	Heating/Ventilation/Air Conditioning	Z4-025822	need a legislar many Earth and any facility
Gardenview Elementary	11/7/2024 15:57	MALONE	Vau 9 Laak	Z4-040206	need a key for room 5 and need new for 8
Gardenview Elementary	11///2024 15.5/	MALUNE	Key & Lock	24-040206	need a key
Gardenview Elementary	9/19/2024 9:31	SMITH	Key & Lock	Z4-033643	need a ney
,			, 2 223		Need a new key
Gardenview Elementary	8/3/2024 12:14	SMITH	Key & Lock	Z4-024908	•
•			,		Paint peeling off hallway wall near P-K rooms
Gardenview Elementary	6/24/2024 14:56	BURCHETT	Painting	Z4-019241	
					faucet want turn off
Gardenview Elementary	11/4/2024 9:15	JOHNSON	Plumbing	Z4-039401	
					Remove hot water tank
Gardenview Elementary	10/31/2024 11:18	JOHNSON	Plumbing	Z4-039089	
Oznaka najeve Elemente	44 (40 (000 4 40 00	OTEVENIOON	Destina	74.04074	Water leaking from ceiling over manager desk.
Gardenview Elementary	11/13/2024 16:06	STEVENSON	Roofing	Z4-040714	roof look
Gardenview Elementary	7/5/2024 10:36	STEVENSON	Roofing	Z4-020287	roof leak
Galuenview Elementary	77372024 10.30	STEVENSON	nooning	4-02028/	Pick up A/c units
Gardenview Elementary	11/20/2024 7:51	SMITH	Sheet Metal	Z4-041608	- Shap to a ma
Geeter School	11/7/2024 9:32	ARNOLD	Carpentry	Z4-040073	Entry door on left side not able to push bar to open door
Geeter School	8/29/2024 9:00	ARNOLD	Carpentry	Z4-030190	Door off hinges
			* *		

Geeter School	8/1/2024 9:24	ARNOLD	Carpentry	Z4-024302	Pre-K need a small bulletin, board outside hallway between classrooms B101 and B106
Geeter School	11/14/2024 9:48	CASEY	Carpet Repair	Z4-024302 Z4-040808	Carpet need a small bulletin, board outside natiway between classrooms blot and bloo
Geeter School	12/16/2024 8:50	CASET	Electrical	Z4-040006	Outside light not coming on dark in area.
		HALL			
Geeter School	12/13/2024 8:56		Electrical	Z4-044848	Fuse will not reset
Geeter School	12/13/2024 8:51	HALL	Electrical	Z4-044847	Flipped fuse switch will not stay on located in teachers lounge electrical closet.
Geeter School	11/14/2024 9:52	HALL	Electrical	Z4-040810	Need lighting (dark in area)
Geeter School	11/14/2024 8:54		Fire Extinguishers	Z4-040781	Need recharged
Geeter School	11/14/2024 8:53		Fire Extinguishers	Z4-040780	Need recharged
Geeter School	11/14/2024 8:53		Fire Extinguishers	Z4-040779	Need recharged
Geeter School	12/4/2024 11:44	LEWIS	Flooring	Z4-043342	Floor tile buckling
Geeter School	12/4/2024 11:43	LEWIS	Flooring	Z4-043341	Floor tile buckling
Geeter School	12/4/2024 11:37	LEWIS	Flooring	Z4-043339	Floor tile bucking
Geeter School	12/4/2024 11:25	LEWIS	Flooring	Z4-043335	Tile buckled up
Geeter School	12/4/2024 11:14	CASEY	Flooring	Z4-043324	Numerous floor tile buckled up from floor
					MS. SUTTON 60568 UNIT NOT HEATING
Geeter School	12/3/2024 10:09	WILSON	Heating/Ventilation/Air Conditioning	Z4-042844	
Geetel School	12/3/2024 10:09	WILSON	riedding/ventitation/Air Conditioning	24-042044	MS. SUTTON 60568 UNIT NOT COMING ON
Contar Cohool	12/2/2024 10:07	WILCOM	Llasting Montilation / Air Conditioning	74 040041	PIS. SULTON GUSGO UNIT NOT COPING ON
Geeter School	12/3/2024 10:07	WILSON	Heating/Ventilation/Air Conditioning	Z4-042841	NO 01/2701/01/2017 10/27 00/2017 00/
					MS. SUTTON 60568 UNIT NOT COMING ON
Geeter School	12/3/2024 10:06	WILSON	Heating/Ventilation/Air Conditioning	Z4-042839	
					MS. SUTTON 60568 UNIT NOT COMING ON
Geeter School	12/3/2024 10:04	WILSON	Heating/Ventilation/Air Conditioning	Z4-042836	
					MS. SUTTON 60568 UNIT NOT COMING ON
Geeter School	12/3/2024 10:04	WILSON	Heating/Ventilation/Air Conditioning	Z4-042835	
					MS. SUTTON 60568 UNIT NOT COMING ON
Geeter School	12/3/2024 10:02	WILSON	Heating/Ventilation/Air Conditioning	Z4-042830	
			0		MS. SUTTON 60568 UNIT NOT COMING ON
Geeter School	12/3/2024 9:59	WILSON	Heating/Ventilation/Air Conditioning	Z4-042824	
Occici ociloot	12/0/2024 0.00	WILDON	ricuting ventuation//ai contationing	24 042024	MS. SUTTON 60568 UNIT NOT COMING ON
Geeter School	12/3/2024 9:59	WILSON	Heating/Ventilation/Air Conditioning	Z4-042822	PIS. SETTON GESGE CIVIT NOT COPING ON
Geetel School	12/3/2024 9.59	WILSON	neating/ventitation/Air Conditioning	24-042022	MO CUITTON COSTOC UNIT NOT COMPING ON
	40/0/0004050			74.040004	MS. SUTTON 60568 UNIT NOT COMING ON
Geeter School	12/3/2024 9:58	WILSON	Heating/Ventilation/Air Conditioning	Z4-042821	
Geeter School	9/19/2024 13:11	BURCHETT	Masonry	Z4-033807	Floor tile need replacing
Geeter School	4/19/2024 14:59	BURCHETT	Masonry	Z4-010780	Cracked walls
Geeter School	4/18/2024 16:17	BURCHETT	Masonry	Z4-010591	Cracks down all 4 corners of wall.
Geeter School	4/18/2024 16:13	BURCHETT	Masonry	Z4-010590	Crack down wall
Geeter School	4/18/2024 16:11	BURCHETT	Masonry	Z4-010589	Crack down wall and hole need filled
Geeter School	4/17/2024 12:17	BURCHETT	Masonry	Z4-009948	Replace concrete floor tile.
Geeter School	4/5/2024 10:10	CORONADO	Masonry	Z4-007888	Cracked down wall.
Geeter School	4/5/2024 10:04	CORONADO	Masonry	Z4-007885	Hallway at classroom E102 crack down side wall.
Geeter School	4/5/2024 9:58	CORONADO	Masonry	Z4-007882	Down side of wall at classroom E102
Geeter School	4/5/2024 9:55	CORONADO	Masonry	Z4-007881	Down side of wall at classroom E102
Geeter School	4/5/2024 9:51	CORONADO	Masonry	Z4-007872	Classroom open cracks around door of walls
			· · · · · · · · · · · · · · · · · · ·		
Geeter School	3/27/2024 11:39	CORONADO	Masonry	Z4-006611	Replace floor tile.
Geeter School	3/28/2024 15:31	CORONADO	Masonry	WO999856	eas on wall need calking. Rainwater comes in from cracked walls and pipes. Have video of areas if needed for locations.
Geeter School	10/30/2024 10:10	BURCHETT	Painting	Z4-038880	Walls need change of color. (Fading)
Geeter School	9/13/2024 10:14	DIXON	Painting	Z4-032614	Paint fading and chipping. Request color change
Geeter School	4/29/2024 14:10	BURCHETT	Painting	Z4-012077	Principal request for stage to be painted black
Geeter School	4/29/2024 14:07	BURCHETT	Painting	Z4-012073	Principal request for stage area to be painted black.
Geeter School	4/26/2024 8:52	BURCHETT	Painting	Z4-011672	Principle request for painting and color change
Geeter School	5/17/2024 14:32	BURCHETT	Painting	WO1016022	Need a No Parking sign at loading dock area.
Geeter School	12/6/2024 13:23	HARRIS	Plumbing	Z4-043852	Need running water. No comming on
Geeter School	11/20/2024 10:33	HARRIS	Plumbing	Z4-041697	1st sink pipe has and hole underneath and water has been cut off.
Geeter School	11/20/2024 10:30	HARRIS	Plumbing	Z4-041693	Last sink @ wall constantly running not able to cut off.
Geeter School	11/20/2024 10:24	HARRIS	Plumbing	Z4-041687	When flushing water comes from pipe area of flush valve
Geeter School	9/17/2024 13:06	HARRIS	Plumbing	Z4-033250	Water fountain on the right. When pushed no water return from it.
Geeter School	9/10/2024 13:47	HARRIS	Plumbing	Z4-031801	Floor drain needs replaced off hinges.
			=		
Geeter School	8/12/2024 9:22	HARRIS	Plumbing	Z4-026911	Last stall need toilet seat replaced
Geeter School	6/25/2024 12:01	HARRIS	Plumbing	Z4-019385	toilets need changed out from Pre-k size to original size. Pre-K has been moved to new building.
Geeter School	6/25/2024 11:58	HARRIS	Plumbing	Z4-019384	1 toilet need changed out from Pre-k size to original size.
Geeter School	4/17/2024 12:15	HARRIS	Plumbing	Z4-009947	Floor drain needs replaced. Hazard
Geeter School	11/14/2024 7:11	STEVENSON	Roofing	Z4-040741	Small set of stair roof leaking
Geeter School	11/14/2024 7:07	STEVENSON	Roofing	Z4-040739	Roof leaking
Geeter School	11/6/2024 12:07	STEVENSON	Roofing	Z4-039884	2 roof leaks. Leaking on classroom supplies

Geeter School	11/6/2024 12:05	STEVENSON	Roofing	Z4-039882	Roof leaking at door(slip and fall hazard)
Geeter School	3/28/2024 15:31	LEWIS	Shades/Blinds	WO1009168	Need 40 shades. 37x62 Need 8 shades. 45x 80
Geeter School	12/11/2024 10:52	SMITH	Sheet Metal	Z4-044464	Some seating areas need replaced. (Hazard)
Geeter School	10/30/2024 10:36	SMITH	Sheet Metal	Z4-038890	Numerous of seats I coming up from base. Nails is a hazard, need security
					used fluorescent bulb pick up
Georgian Hills Elementary	12/15/2024 19:17	LANE	Asbestos	Z1-044944	
Georgian Hills Elementary	12/12/2024 14:30	ARNOLD	Carpentry	Z1-044776	Door needs replacing or repair
Georgian Hills Elementary	12/12/2024 10:54	ARNOLD	Carpentry	Z1-044697	Wholes in the walls
Georgian Hills Elementary	12/9/2024 9:13	STEPHENS	Carpentry	Z1-043990	Whole in the wall needs repair
Georgian Hills Elementary	10/30/2024 14:26	SHIPPS	Carpentry	Z1-038967	Whole in the wall needs repair
Georgian Hills Elementary	9/12/2024 10:31	ARNOLD	Carpentry	Z1-032216	Wood needs repairing rampway next to pre-K boys restroom
Georgian Hills Elementary	2/22/2024 9:31	ARNOLD	Carpentry	Z1-002445	Classroom #10 reset room needs a door on the storage room to block off electrical room
Georgian Hills Elementary	3/28/2024 15:31	LEWIS	Carpet Repair	WO992627	removing carpet in the main office replace with tile
Georgian Hills Elementary	5/17/2024 13:37	LEWIS	Carpet Repair	WO974246	removing the carpet in the library replace with floor tiles
Georgian Hills Elementary	12/16/2024 7:26	SMITH	Electrical	Z1-044964	Hotbox socket outlet is not working properly needs repairing
Georgian Hills Elementary	10/23/2024 6:58	SMITH	Electrical	Z1-037908	Pre-K boys restroom exhaust fan needs new motor
Georgian Hills Elementary	8/19/2024 10:54	SMITH	Electrical	Z1-028390	In need of light covers
Georgian Hills Elementary	2/5/2024 10:46	SMITH	Electrical	Z1-000181	Classroom #1 needs a light cover
					discard wiring (Fire devices)
Georgian Hills Elementary	9/25/2024 7:10	GREER	Fire Alarm System	Z1-034564	
Georgian Hills Elementary	12/2/2024 10:59	LEWIS	Flooring	Z1-042454	Tripping hazard flooring needs repairing and replacing with tiles
Georgian Hills Elementary	10/22/2024 9:04	LEWIS	Flooring	Z1-037786	Wooden floors need replacing with floor tiles hazard whole in floor
Georgian Hills Elementary	9/24/2024 7:36	CASEY	Flooring	Z1-034346	Remove carpet replace with floor tiles
Georgian Hills Elementary	9/17/2024 11:04	LEWIS	Flooring	Z1-033190	Flooring is a tripping hazard wooden floors needs replacing
Georgian Hills Elementary	7/24/2024 10:25	CHASE	Flooring	Z1-022343	Principles request for carpet to be removed and replace with floor tiles
Georgian Hills Elementary	7/23/2024 15:44	CASEY	Flooring	Z1-022214	Floor needs repairing
8					Wooden floors need repair trip hazard
Georgian Hills Elementary	7/23/2024 15:20	CASEY	Flooring	Z1-022207	, , , , , , , , , , , , , , , , , , ,
,			3		Safety hazard flooring needs repairing bulking up
Georgian Hills Elementary	6/12/2024 12:30	BENTON	Flooring	Z1-018177	, , , , , , , , , , , , , , , , , , , ,
Georgian Hills Elementary	6/5/2024 7:53	BENTON	Flooring	Z1-017235	Floor is a tripping hazard in need of floor tile put down
Georgian Hills Elementary	4/9/2024 10:38	LEWIS	Flooring	Z1-008363	Has wooden floors needs floor tiles put down tripping hazard
Georgian Hills Elementary	3/25/2024 12:56	LEWIS	Flooring	Z1-006187	Floor is a tripping hazard wooden floors classroom #21
Georgian Hills Elementary	3/19/2024 11:27	CHASE	Flooring	Z1-005384	Classroom #7 has bad flooring trip hazard
Georgian Hills Elementary	2/9/2024 11:08	CASEY	Flooring		wood floors in hallways main entrance to kindergarten hallways too fifth grade hallways shellacking floors as well
Georgian Hills Elementary	2/3/2024 13:49	LEWIS	Flooring	WO1032565	Principles request that the carpet to be removed in the main office Replaced with floor tiles
Georgian Hills Elementary	2/3/2024 13:49	LEWIS	Flooring		or all classrooms to be replaced with floor tiles kindergarten through fifth grade classrooms storage rooms as well
Georgian Hills Elementary	2/3/2024 13:49	LEWIS	Flooring	WO1032573	Principles request for the hallways to be floor tiled kindergarten through fifth Gary highways
Georgian Hills Elementary	2/3/2024 15:20	MALONE	Flooring	WO1029350	Principles request that the carpet to be removed in the main office
Georgian Hills Elementary	2/3/2024 15:19	MALONE	Flooring	WO1029351	Principles request for the carpet to be removed in library
Georgian Hills Elementary	2/3/2024 15:41	MALONE	Flooring	WO1027725	Classroom #16 flooring needs repairing
,			· ·		
					tripping hazard carpet damaged needs replacing in the main office replace with floor tiling
Georgian Hills Elementary	2/3/2024 15:53	CHASE	Flooring	WO1024918	
Georgian Hills Elementary	2/3/2024 16:14	CHASE	Flooring	WO1023961	Flooring in classroom #24 needs repairing next to the A/C unit
Georgian Hills Elementary	2/3/2024 16:14	MALONE	Flooring	WO1023920	Flooring in classroom #24 needs repairing
Georgian Hills Elementary	5/17/2024 14:27	STEPHENS	Flooring	WO1012511	wooden floor needs repairing in classroom #8 replace with tiles
Georgian Hills Elementary	5/17/2024 14:17	BENTON	Flooring	WO998949	Removing carpet in the library and replacing with floor tiles
Georgian Hills Elementary	5/17/2024 14:17	BENTON	Flooring	WO998951	Removing carpet in the main office and replacing with floor tiles
Georgian Hills Elementary	5/17/2024 14:00	BENTON	Flooring	WO992555	classroom #1 baseboards needs repairing
Georgian Hills Elementary	3/28/2024 15:31	Ewing	Flooring	WO992553	classroom #18 wooden floor is wearing out can the floors be repaired with tile instead
					Mr. Bedford 63750no heat
Georgian Hills Elementary	12/2/2024 9:00	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042322	
					Mr. Bedford 63750no heat
Georgian Hills Elementary	12/2/2024 8:58	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042320	
					Mr. Bedford 63750no heat
Georgian Hills Elementary	12/2/2024 8:57	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042319	
					Mr. Bedford 63750no heat
Georgian Hills Elementary	12/2/2024 8:55	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042317	
					Mr. Bedford 63750no heat
Georgian Hills Elementary	12/2/2024 8:54	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042316	
					Mr. Bedford 63750no heat
Georgian Hills Elementary	12/2/2024 8:54	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042315	

		40/0/0004050			74 040044	Mr. Bedford 63750
Ge	orgian Hills Elementary	12/2/2024 8:53	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042314	Mr. Bedford 63750
Ge	orgian Hills Elementary	12/2/2024 8:52	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042313	rii. bealola 03/30
-	orgram muo Etomontury	12/2/2024 0102	WILLS II 10	roading romandom and conditioning	21 0 12010	HVAC UNIT FOR RM 5 - NOT COMING ON PM/BAFFORD 416-3750
Ge	orgian Hills Elementary	11/18/2024 9:19	WEBB	Heating/Ventilation/Air Conditioning	Z1-041216	
						UNT NOT COMING ON - PRINCIPAL'S OFFICE P/M BAFFORD 416-3750
Ge	orgian Hills Elementary	10/25/2024 10:16	WEBB	Heating/Ventilation/Air Conditioning	Z1-038338	
						AC shows sensor problem. Reads F1
	orgian Hills Elementary	9/17/2024 9:36	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-033117	Online and a second respective distance in the facility of the second
	orgian Hills Elementary	10/23/2024 9:04	BURCHETT	Masonry	Z1-037944	Ceiling needs repairing in the boiler room
	orgian Hills Elementary	11/5/2024 13:02 10/28/2024 10:23	BURCHETT BURCHETT	Painting Painting	Z1-039623 Z1-038499	In need of painting Wall needs painting
	orgian Hills Elementary	10/22/2024 10:23	BURCHETT	•	Z1-038499 Z1-037856	
	orgian Hills Elementary orgian Hills Elementary	10/22/2024 12:17	BURCHETT	Painting Painting	Z1-037830 Z1-037847	Paint the board on the wall that has been repaired Painting the wall cover board
	orgian Hills Elementary	9/23/2024 6:59	BURCHETT	Painting	Z1-03/84/ Z1-034087	Painting the wall cover board Painting the rails is needed
Ge	orgian rinus Eterneritary	9/23/2024 0.39	BUNCHETT	Failtung	21-034067	repainting the hallways & doors navy blue
Ge	orgian Hills Elementary	8/15/2024 14:21	BURCHETT	Painting	Z1-027893	ropainting the naturally a desire harf state
	orgian Hills Elementary	7/30/2024 9:48	BURCHETT	Painting	Z1-023681	Repaint girls restroom fifth grade
	orgian Hills Elementary	7/11/2024 14:48	BURCHETT	Painting	Z1-020950	Walls need painting next to classroom #9
	orgian Hills Elementary	5/15/2024 9:45	BURCHETT	Painting	Z1-014649	Main entrance paint is peeling need touch up
	,					repainting the marquee board located outside on the school grounds is needed principals
						request navy blue
Ge	orgian Hills Elementary	5/9/2024 9:38	BURCHETT	Painting	Z1-013801	
Ge	orgian Hills Elementary	4/23/2024 14:12	BURCHETT	Painting	Z1-011114	Painting the hallways from pre-K hallways throu fifth grade hallways navy blue
Ge	orgian Hills Elementary	2/3/2024 16:15	BURCHETT	Painting	WO1023489	Ceiling in the boiler room needs repairing plaster
Ge	orgian Hills Elementary	12/13/2024 14:24	Jordan	Plumbing	Z1-044929	Men's restroom flush valve needs to be replaced constantly running
Ge	orgian Hills Elementary	12/11/2024 13:51	Jordan	Plumbing	Z1-044495	Hot water heater is leaking
Ge	orgian Hills Elementary	12/10/2024 8:40	Jordan	Plumbing	Z1-044177	Urinal needs repairing leaking
	orgian Hills Elementary	11/14/2024 9:55	Jordan	Plumbing	Z1-040811	Water fountain filter has been replaced red light
	orgian Hills Elementary	9/20/2024 10:48	BENTON	Shades/Blinds	Z1-033983	In need of blinds put in classroom
	orgian Hills Elementary	2/3/2024 16:16	BENTON	Shades/Blinds	WO1022862	blinds needed in sped classroom #15
	orgian Hills Elementary	5/17/2024 14:25	BENTON	Shades/Blinds	WO1008406	classroom #14 needs shades
	orgian Hills Elementary	5/17/2024 14:25	BENTON	Shades/Blinds	WO1008405	classroom #2 needs shades
	orgian Hills Elementary	5/17/2024 14:25	BENTON	Shades/Blinds	WO1008404	classroom #5 needs shade put in
	orgian Hills Elementary	8/7/2024 12:50	HATCH	Sheet Metal	Z1-026109	Rain gutters need repairing
	orgian Hills Elementary	4/25/2024 13:46	HATCH	Sheet Metal	Z1-011594	The rain gutter is broken needs replaced
Ge	orgian Hills Elementary	2/14/2024 10:23	HATCH	Sheet Metal	Z1-001392	Courtyard area outside of classroom #7 rain, gutters, needs repairing
	Georgian Hills Middle	12/16/2024 7:57	RUSSELL	Carpentry	Z1-044969	Replace missing ceiling tiles in the gym.
	Georgian Hills Middle	11/22/2024 12:07	ARNOLD	Carpentry	Z1-044303	Whole in the wall needs repairing
	Georgian Hills Middle	7/30/2024 13:10	SHIPPS	Carpentry	Z1-042005 Z1-023795	Principal is requesting that 2 bulletin boards be replaced.
	Georgian Hills Middle	12/6/2024 10:27	SMITH	Electrical	Z1-043800	2 light fixture in front of of window needs ballast replaces. Tried changing bulb still no light
	Georgian Hills Middle	11/22/2024 8:45	SMITH	Electrical	Z1-042033	Main hallway light needs balance
	•					the emergency sign hanging on the 6th grade hallway right before you get to CR 108 has fell
						down and broke needs to be replaced.
(Georgian Hills Middle	11/4/2024 8:57	SMITH	Electrical	Z1-039390	
						Upgrade gym lights to LED
(Georgian Hills Middle	11/1/2024 12:17	CHALK	Electrical	Z1-039277	
						room 102 socket not working on the side wall not getting power
(Georgian Hills Middle	10/29/2024 8:35	SMITH	Electrical	Z1-038652	
						the boys' restrooms in the basement needs the balance replaced in the light fixture over the
		0/5/00044540	014771	E	74 005005	sink.
(Georgian Hills Middle	8/5/2024 15:13	SMITH	Electrical	Z1-025395	the power socket in the far back of the room where the refrigerator and air conditioner is
						hooked up does not work.
	Georgian Hills Middle	7/11/2024 10:26	SMITH	Flectrical	Z1-020906	nooked up does not work.
,	200-Blair Fillia Pillante	//11/2024 10.20	OI IIIII	Literior	21 020000	inside of the teachers lounge the power socket near the door needs to be replaced. it's a 4-
						socket outlet and only 2 works.
(Georgian Hills Middle	7/11/2024 10:14	SMITH	Electrical	Z1-020896	
				2 22		the power socket outside of the principals office is very loose. when trying to plug anything
						up the cords are falling back out
(Georgian Hills Middle	7/11/2024 10:13	SMITH	Electrical	Z1-020893	

					power. balance needs to be replaced.
Georgian Hills Middle	4/25/2024 15:24	SMITH	Electrical	Z1-011623	needs assistance with 2 lights fixture in coaches office. tried changing bulbs but still no lights.
Georgian Hills Middle	3/4/2024 10:39	SMITH	Electrical	Z1-003720	POCA reported by the fire marshal that the emergency lights located in the gym lobby area
Georgian Hills Middle	3/25/2024 12:24	LARKIN	Fire Alarm System	Z1-006181	is not property working. will be back to conduct a follow up.
Georgian Hills Middle	3/25/2024 12:22	LARKIN	Fire Alarm System	Z1-006179	POCA reported by the fire marshal that the emergency exit light on the 6th grade hallway near the emergency exit door is not properly working, will be back to conduct a follow up.
Georgian Hills Middle	3/25/2024 12:21	LARKIN	Fire Alarm System	Z1-006178	POCA reported by the fire marshal that the emergency exit light on the 6th grade hallway outside of classroom 108 is not properly working, will be back to conduct a follow up.
Georgian Hills Middle	3/25/2024 12:20	LARKIN	Fire Alarm System	Z1-006177	POCA reported by the fire marshal that the emergency exit light on the 2nd floor 8th grade hallway is not properly working, will be back to conduct a follow up.
Georgian Hills Middle	11/14/2024 8:24	CASEY	Flooring	Z1-040766	requesting that the gym floor be refinish. Principal can't recall when it was lastly done.
Georgian Hills Middle	12/9/2024 9:18	WEBB	Heating/Ventilation/Air Conditioning	Z1-043995	HEATING UNIT IN RM 111 - NOT HEATING PM/REID 416-3740
-					HEATING UNIT IN RM 102 - NOT HEATING PM/REID 416-3740
Georgian Hills Middle	12/9/2024 9:18	WEBB	Heating/Ventilation/Air Conditioning	Z1-043994	HEATING UNIT IN RM 101 - NOT HEATING PM/REID 416-3740
Georgian Hills Middle	12/9/2024 9:17	WEBB	Heating/Ventilation/Air Conditioning	Z1-043993	HEATING UNIT IN RM 112 - NOT HEATING - PM/REED 416-3740
Georgian Hills Middle	12/5/2024 12:26	WEBB	Heating/Ventilation/Air Conditioning	Z1-043621	HEATING UNIT IN RM 216 - NOT HEATING - PM/REED 416-3740
Georgian Hills Middle	12/5/2024 12:25	WEBB	Heating/Ventilation/Air Conditioning	Z1-043619	
Georgian Hills Middle	12/5/2024 12:23	WEBB	Heating/Ventilation/Air Conditioning	Z1-043616	HEATING UNIT IN RM 208 - NOT HEATING - PM/REED 416-3740
					ms.reid 63740
Georgian Hills Middle	12/4/2024 11:53	WEBB	Heating/Ventilation/Air Conditioning	Z1-043345	no heat
-					Ms. Reed, 63740 no heat
Georgian Hills Middle	12/2/2024 8:48	WEBB	Heating/Ventilation/Air Conditioning	Z1-042307	Ms. Reed, 63740 no heat
Georgian Hills Middle	12/2/2024 8:47	WEBB	Heating/Ventilation/Air Conditioning	Z1-042305	Ms. Reed. 63740
Georgian Hills Middle	12/2/2024 8:46	WEBB	Heating/Ventilation/Air Conditioning	Z1-042302	PURCHASE AND REPLACE PUMP #4
Georgian Hills Middle	11/20/2024 7:11	WEBB	Heating/Ventilation/Air Conditioning	Z1-041594	
Georgian Hills Middle	11/20/2024 7:10	WEBB	Heating/Ventilation/Air Conditioning	Z1-041593	PURCHASE AND REPLACE PUMP #3
Georgian Hills Middle	11/20/2024 7:07	WEBB	Heating/Ventilation/Air Conditioning	Z1-041588	PURCHASE AND REPLACE PUMP #2
Georgian Hills Middle	11/19/2024 10:28	Solutions	Heating/Ventilation/Air Conditioning	Z1-041484	Replace damaged Coil
-					Replace damaged Coil
Georgian Hills Middle	11/19/2024 10:25	Solutions	Heating/Ventilation/Air Conditioning	Z1-041482	Replaced damaged Coil
Georgian Hills Middle	11/19/2024 10:23	Solutions	Heating/Ventilation/Air Conditioning	Z1-041481	Replace damaged Coil
Georgian Hills Middle	11/19/2024 10:14	Solutions	Heating/Ventilation/Air Conditioning	Z1-041480	Replace Leaking Coil
Georgian Hills Middle	11/19/2024 9:51	Solutions	Heating/Ventilation/Air Conditioning	Z1-041467	OVERHEAD UNIT LEAKING - KITCHEN AREA P/M PARIS REED 416-3740
Georgian Hills Middle	9/16/2024 14:28	SIMMONS	Heating/Ventilation/Air Conditioning	Z1-033021	5. Zameno omi edinino miorientimenti i i iniciale e 420-3/40



Georgian Hills Middle	8/5/2024 8:12	WEBB	Heating/Ventilation/Air Conditioning	Z1-025058	Plant Manager Reed reported the ac unit in room 103 is blowing warm air. 416-3740
					Plant Manager Reed reported the ac unit in room 229 is blowing warm air. 416-3740
Georgian Hills Middle	8/5/2024 8:11	WEBB	Heating/Ventilation/Air Conditioning	Z1-025052	
	40/00/000440			74 000774	Principal is requesting a copy of the A Master Key for the use of the SRO Greer.
Georgian Hills Middle	10/29/2024 13:39	MALONE	Key & Lock	Z1-038774	requesting that the lines out in the parking lot of the front and back of the building be
					repainted or sprayed. NO lines are visible.
Georgian Hills Middle	11/14/2024 8:20	BURCHETT	Painting	Z1-040764	repainted of sprayed. No uned are visited.
9			9		
					inside the classroom the teacher had the wall covered with wallpaper. we were written up
					for this violation and I'm requesting that the wall be painted because it looks terrible.
Georgian Hills Middle	7/11/2024 10:24	BURCHETT	Painting	Z1-020905	
Georgian Hills Middle	7/3/2024 9:46	BURCHETT	Painting	21-020158	eleft be painted. The bricks in the wall was repaired from the goal coming out of the wall & wall needs to be painted to cover repairs that were made. the health inspector inspected the kitchen area and indicated we have several rust spots in
					the concrete ceiling that needs to be painted.
Georgian Hills Middle	2/3/2024 16:57	DIXON	Painting	WO1019620	
Georgian Hills Middle	12/11/2024 8:29	Jordan	Plumbing	Z1-044424	s not flushing like it should. Tried plunging several times and still nothing as if something is caught in it.
					there are 2 water fountains installed on the 6th grade hallway that does not have a water
					line hook up.
Georgian Hills Middle	10/4/2024 8:31	OWENS	Plumbing	Z1-036234	
					the water fountain near the 8th grade RR has a water fountain that was installed without a
					water line hooked up. so, there for the students are not able to get water and we are experiencing a lot of HVAC issues here at GHM
Georgian Hills Middle	8/5/2024 10:29	OWENS	Plumbing	Z1-025226	operation. General Control of Con
8					kitchen has a active roof leak right in front of can opener
Georgian Hills Middle	12/9/2024 16:22	STEPHENS	Roofing	Z1-044127	
Georgian Hills Middle	12/5/2024 18:02	DIAZ	Roofing	Z1-043689	Inspect and Blow leaves from roof.
					GHM is in of a total of 28 shades/blinds throughout the building
Georgian Hills Middle	8/20/2024 8:25	BENTON SHIPPS	Shades/Blinds Welding	Z1-028540	AND CATMALIKE LEADING TO CHINNACES IN ATTIC ARE LINEARS. TECHNOLOGY ARE DESIGNED TO LIST LINTH FIVED
Georgian Hills Middle Germanshire Elementary	5/17/2024 13:49 9/6/2024 17:01	BARNES	Welding Carpentry	WO986606 Z3-031400	AND CATWALKS LEADING TO FURNACES IN ATTIC ARE UNSAFE TECH'S ARE REFUSING TO USE UNTIL FIXED The wall divider in the Multi-purpose is damaged and deteriorated
Germanshire Elementary	5/17/2024 14:03	BENTON	Carpet Repair	W0994046	Principal Knapp, AP Addison, and PLC Miller all offices have carpet that is stained badly and is requesting to be removed.
Germanshire Elementary	10/15/2024 9:02	SCOTT	Electrical	Z3-037001	Can the battery for the emergency light #3 be changed. It is out
ŕ					The fore alarm circuit breaker did not have a branch circuit over current protection device
					permanently identified at the fire control unit
Germanshire Elementary	12/12/2024 15:46	SMALL	Fire Alarm System	Z3-044788	
Orange and him Elementers	40/40/0004 45:40	SMALL	Fire Alexan Contains	70.044707	The fire alarm is not free and clear of troubles
Germanshire Elementary	12/12/2024 15:43	SMALL	Fire Alarm System	Z3-044787	
					Classrooms pre-k A3, G401 and F402 fire extinguishers will need to be updated before May
Germanshire Elementary	3/25/2024 9:44	SMALL	Fire Extinguishers	Z3-006107	,
Germanshire Elementary	9/6/2024 15:42	SMALL	Fire Sprinkler System	Z3-031384	Fire sprinkler rise has expired.In need of a annually inspection and trip tested
Germanshire Elementary	9/6/2024 15:38	SMALL	Fire Sprinkler System	Z3-031383	Update the fire sprinkler riser
Germanshire Elementary	5/14/2024 10:10	SMALL	Fire Sprinkler System	Z3-014458	POCA — The Riser room across from classroom C203 needs to have its 5 year inspection
					POCA — Replace missing sprinkler head cover inside YMCA CLOSET. Classroom C200
Germanshire Elementary	5/13/2024 14:42	SMALL	Fire Sprinkler System	Z3-014322	closet need a sprinkler head cover
Germanshire Elementary	9/6/2024 16:49	LEWIS	Flooring	Z3-031397	Pre-K flooring is damaged and has deteriorated
,					Mr. mason 63733 room extremely cold
Germanshire Elementary	12/3/2024 11:27	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-042905	
					Mr. mason 63733 room extremely cold
Germanshire Elementary	12/3/2024 11:26	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-042904	
	40/0/00044040	00571115		70.010115	MR. MASON 63733 NO HEAT
Germanshire Elementary	12/2/2024 10:46	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-042445	MR. MASON 63733 NO HEAT
Germanshire Elementary	12/2/2024 10:43	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-042444	Fill Fill Industry of the File I
			gg		MR. MASON 63733 NO HEAT
Germanshire Elementary	12/2/2024 10:39	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-042436	
Germanshire Elementary	11/12/2024 9:26	MALONE	Key & Lock	Z3-040410	Can we have 2 copies of the fire alarm key for the pull stations.
Germanshire Elementary	9/18/2024 11:35	SMITH	Key & Lock	Z3-033443	ssroom because the door will not lock and the lock just constantly turns without securing the door. It is a safety concern for the building.
Germanshire Elementary	9/30/2024 10:49	BURCHETT	Masonry	Z3-035437	on the outside of the building and it comes into the building through the brick wall. Can this be checked out.

Germanshire Elementary Germanshire Elementary	9/6/2024 16:40 5/17/2024 14:26	BARNES BURCHETT	Painting Painting	Z3-031396 WO1010191	There's no lines and directional arrows on the crosswalk an area in the boy's restroom that need to be painted. it was mudded and now ready for to be painted. inside of classroom D314 at the window, it needs to be painted. there has been work done due to rain damage and the window sill/frame needs painting, there was chipped paint and old paint coming off because of the water damage.
Germanshire Elementary Germanshire Elementary	5/17/2024 14:04 12/2/2024 9:46	DIXON WARREN	Painting Plumbing	WO995001 Z3-042370	There is water coming out of the top where you cut the water on and off of the custodial sink Backflow Testing
Germanshire Elementary	10/3/2024 12:50	WILSON	Plumbing	Z3-036129	prep bottle fillers for inspections
Germanshire Elementary Germanshire Elementary	6/8/2024 9:11 5/13/2024 14:14	WILSON SMALL	Plumbing Roll Up Doors	Z3-017775 Z3-014314	POCA Roll up door need to be inspected per Fire Marshal inside
					Seal bottom of the wall to prevent water from coming in
Germanshire Elementary	10/8/2024 14:42	BUFORD	Roofing	Z3-036652	Check/Clean gutters around building
Germanshire Elementary	10/8/2024 14:37	BUFORD	Roofing	Z3-036650	the exit light is out by room 134 in the annex
Germantown Elementary	11/14/2024 8:41	SCOTT	Electrical	Z3-040775	the exit light is out by room 173 in the main building
Germantown Elementary	11/14/2024 8:40	SCOTT	Electrical	Z3-040774	the exit light is out by mrs chambers room 178
Germantown Elementary	9/4/2024 11:11	SCOTT	Electrical	Z3-030891	the doorbell is working to buzz to come inside the kitchen from the outside
Germantown Elementary	8/6/2024 14:39	SCOTT	Electrical	Z3-025802	
Germantown Elementary	8/5/2024 12:11	SCOTT	Electrical	Z3-025289	the exit sign is out on the 5th grade hall by chambers room
					the light fixtures are old and i need some new balance to replace bulbs because it breaks when i try to replace the bulbs
Germantown Elementary	7/24/2024 9:26	SCOTT	Electrical	Z3-022290	vent hood wasn't coming on
Germantown Elementary	4/3/2024 8:33	SCOTT	Electrical	Z3-007500	The fire alarm panel is constantly beeping reading silence alarm in progress and the panel in the lobby is blank , the double doors will not stay open the metal on the back will not hold
Germantown Elementary	6/27/2024 8:49	SMALL	Fire Alarm System	Z3-019608	them open anymore.
Germantown Elementary	9/20/2024 8:41	SMALL	Fire Extinguishers	Z3-033907	POCA -the room next to the mechanical room needs a fire extinguisher inside it. POCA-THE FIRE EXT IN THE CAFETERIA ON THE WALL BY THE TABLES NEEDS RECHARGE.
Germantown Eternentary	9/20/2024 6.41	SMALL	riie Extiliguisileis	23-033907	IN THE ANNEX BUILDING IN SPED ROOM IN THE CLOSET THE INSPECTOR CAME IN AND HE
Germantown Elementary	3/11/2024 8:52	SMALL	Fire Extinguishers	Z3-004777	MISSED THAT ONE
					in the boy's restroom gym area, they have been kicking the floor up and all of the small tiles are coming up all over the floor
Germantown Elementary	11/15/2024 12:13	LEWIS	Flooring	Z3-041093	the office has a leak above the secretary desk its coming from the air condition per Dennis
Germantown Elementary	12/10/2024 11:27	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-044268	the roofer
Germantown Elementary	12/10/2024 11:36	MALONE	Key & Lock	Z3-044274	we need 4 keys to the library door it's a yale key per Newborn an admin.
•			•		on the outside of the brick wall by the dumpster has a leak coming from the inside the wall through the bricks per Dennis the roofer
Germantown Elementary	12/10/2024 11:30		Masonry	Z3-044272	the boys restroom in the gym has concrete missing and they could fall and hurt themselves
		DUDOUSTT.		70.040005	by the plant manager office
Germantown Elementary	6/20/2024 9:49	BURCHETT	Masonry	Z3-018885	by the boys urinal the bricks are coming off, so when they step on it they could hurt them
Germantown Elementary	6/7/2024 8:54	BURCHETT	Masonry	Z3-017658	selves
					the back wall outside the kitchen area needs to be brick masonary close by door nu8mber 153
Germantown Elementary	4/29/2024 11:03	BURCHETT	Masonry	Z3-011970	

the column by the double doors on the 4th grade hall needs brick masonary it has a crack going down it.

					going down it.
Germantown Elementary	4/29/2024 11:01	BURCHETT	Masonry	Z3-011968	
Germantown Elementary	10/24/2024 17:16	BRYANT	Deinting	Z3-038269	ALL REPAIRS OUT SIDE BUILDING
Germantown Eternentary	10/24/2024 17.10	DRIANI	Painting	23-038209	The gym needs painting
Germantown Elementary	8/8/2024 14:43	BURCHETT	Painting	Z3-026501	0,
					The cafeteria needs painting in spots
Germantown Elementary	6/27/2024 9:12	BURCHETT	Painting	Z3-019614	
Germantown Elementary	5/22/2024 10:02	BURCHETT	Painting	Z3-015621	RED DOOR PAINT IS PEELING OFF ON THE 3RD GRADE HALL
Germantown Eternemary	3/22/2024 10:02	BUNCHETT	Faillung	23-013021	PAINT ON THE DOOR ANNEX PEEL OFF RED PAINT
Germantown Elementary	5/22/2024 10:01	BURCHETT	Painting	Z3-015620	THE STATE SOOT WEST ELECTRICS THE
					PAINT ON THE DOOR HAS PEEL OFF RED PAINT
Germantown Elementary	5/22/2024 10:00	BURCHETT	Painting	Z3-015619	
Cormantown Flomenton	5/22/2024 9:59	BURCHETT	Painting	Z3-015618	the door in room SR2paint has peel off the door RED PAINT
Germantown Elementary	5/22/2024 9.59	BURGHEII	Painting	23-013018	
					the are some areas that needs painting they have a lot of green spots around the gym
Germantown Elementary	5/22/2024 9:57	BURCHETT	Painting	Z3-015615	, , , , , , , , , , , , , , , , , , , ,
					the girls bathroom needs painting the walls in the stalls are wrote on with crayons
Germantown Elementary	5/6/2024 11:02	BURCHETT	Painting	Z3-013187	
Germantown Elementary	5/6/2024 11:00	BURCHETT	Painting	Z3-013186	needs painting the first stall they wrote on the walls
Germantown Eternentary	5/6/2024 11.00	BURGHEII	Palliung	23-013180	the annex girls bathroom needs painting they have wrote all over the walls
Germantown Elementary	4/29/2024 13:58	BURCHETT	Painting	Z3-012067	the annex give butting in the state whole at ever the water
					inside the cafeteria manager has a leak coming from the roof
Germantown Elementary	12/9/2024 10:00	BUFORD	Roofing	Z3-044020	
					in the main office has a leak
Germantown Elementary	12/9/2024 9:55	BARNES	Roofing	Z3-044014	
O	3/12/2024 10:04	CONNED	Shades/Blinds	Z3-004893	no shades in the annex
Germantown Elementary	3/12/2024 10:04	CONNER	Snades/Bunds	23-004893	no shades in the annex
Germantown Elementary	3/12/2024 10:03	CONNER	Shades/Blinds	Z3-004892	no strates in the unitex
					no shades in the annex building
Germantown Elementary	3/12/2024 10:02	CONNER	Shades/Blinds	Z3-004891	
					ON THE 5TH GRADE HALL
Germantown Elementary	3/11/2024 15:01	BENTON	Shades/Blinds	Z3-004851	
Cormontour Flomenton	3/11/2024 15:00	DENTON	Shades/Blinds	72 004050	ON THE 4TH GRADE HALL
Germantown Elementary	3/11/2024 15.00	BENTON	Silades/bullus	Z3-004850	NO SHADES ON THE 4TH GRADE HALL
Germantown Elementary	3/11/2024 15:00	BENTON	Shades/Blinds	Z3-004849	NO STADES ON THE 41TO NADE TIALE
,					ON THE 3RD GRADE HALL
Germantown Elementary	3/11/2024 14:59	BENTON	Shades/Blinds	Z3-004848	
					NO SHADES ACROOS FROM THE OFFICE IN THE COMFERENCE ROOM
Germantown Elementary	3/11/2024 14:58	BENTON	Shades/Blinds	Z3-004847	
Germantown Elementary	5/17/2024 14:23	BENTON	Shades/Blinds	WO1005017	129 IN THE ANNEX HAVE A NEW PULL DOWN WINDOW SHADE. THE CURRENT ONE IS TORN AND BROKEN
Germantown Elementary	10/24/2024 6:20	BARNES	Sheet Metal	Z3-038073	Upright Handicap sign.
Comunical Elementary	10/24/2024 0.20	DAINIVEO	oneer retar	20 000070	The intercom Not working S building and C building office either
Germantown High	11/12/2024 11:02	TUNSTALL	Audio Visual	Z3-040452	, , , , , , , , , , , , , , , , , , ,
Germantown High	12/13/2024 11:54	CROUSE	Carpentry	Z3-044892	Crush bar replace
Germantown High	11/6/2024 12:14	CROUSE	Carpentry	Z3-039890	Water runs under doors when rains
Germantown High	6/13/2024 9:18	BARNES	Carpentry	Z3-018259	Door get jams can not open on the inside of the classroom
Germantown High	5/13/2024 8:16	BENTON	Carpet Repair	Z3-014168	Remove carpet
Germantown High	12/16/2024 6:25	SCOTT	Electrical	Z3-044954	Outlet behind drink machine needs change bad outlet.
Germantown High	12/4/2024 6:17	SCOTT	Electrical	Z3-043070	Outlet coming off wall
Germantown High	11/25/2024 9:07	SCOTT	Electrical	Z3-042164	Ballast are needed
Germantown High	11/25/2024 9:05	SCOTT	Electrical	Z3-042163	Ballast are needed
Germantown High	11/4/2024 6:26	SCOTT	Electrical	Z3-039337	Change light fixtures one working
Germantown High	11/1/2024 9:11	SCOTT	Electrical	Z3-039215	Blinking light replace
Germantown High	11/1/2024 9:02	SCOTT	Electrical	Z3-039208	Light replacing
Germantown High	10/29/2024 12:59	SCOTT	Electrical	Z3-038759	Need 220 installed in shop area

Germantown High	10/29/2024 12:56	SCOTT	Electrical	Z3-038757	Exhaust fans not working
Germantown High	10/22/2024 7:08	SCOTT	Electrical	Z3-037745	Light out on side of building
Germantown High	10/7/2024 9:16	WHITWORTH	Electrical	Z3-036414	Emergency light didn't work when tested
Germantown High	10/7/2024 9:09	SCOTT	Electrical	Z3-036407	Emergency lights in front of room B 204 battery backup didn't work
Germantown High	10/7/2024 9:04	SCOTT	Electrical	Z3-036404	Exit light battery backup did not work when tested
_					
Germantown High	10/4/2024 9:00	SCOTT	Electrical	Z3-036248	Due: to fire marshal exit lights needs changing
Germantown High	9/25/2024 6:49	SCOTT	Electrical	Z3-034553	Ballast needed
					Repair 5 non-working stadium lights
Germantown High	8/27/2024 13:23	CHALK	Electrical	Z3-029865	
Germantown High	8/19/2024 9:50	WHITWORTH	Electrical	Z3-028343	Have on power
Germantown High	8/13/2024 8:16	SCOTT	Electrical	Z3-027182	Back office two light fixture needs ballast
					Two lights needs ballast change
Germantown High	8/9/2024 9:13	SCOTT	Electrical	Z3-026619	
Germantown High	8/8/2024 6:05	SCOTT	Electrical	Z3-026197	two lights out pole light and the corner of gym needs replacing
Germantown High	8/1/2024 6:23	SCOTT	Electrical	Z3-024166	2 poles lights out
Germantown High	7/10/2024 8:15	SCOTT	Electrical	Z3-020684	Ballast needed
Germantown High	7/9/2024 13:25	SCOTT	Electrical	Z3-020626	Ballast out
Germantown High	7/9/2024 13:24	SCOTT	Electrical	Z3-020625	Ballast out
Germantown High	7/9/2024 13:23	SCOTT	Electrical	Z3-020623	Ballast out
Germantown High	7/9/2024 13:22	SCOTT	Electrical	Z3-020621	Ballast out
					Need ballast
Germantown High	6/13/2024 12:15	SCOTT	Electrical	Z3-018297	Trood bullabl
Germantown High	5/22/2024 6:47	WHITWORTH	Electrical	Z3-015522	Remove electrical strip along the ceiling
Germantown High	5/14/2024 9:42	SCOTT	Electrical	Z3-013322 Z3-014439	Power line coming off wall
-					· · · · · · · · · · · · · · · · · · ·
Germantown High	5/7/2024 10:30	SCOTT	Electrical	Z3-013406	Equipment room need ballast
Germantown High	4/30/2024 6:06	SCOTT	Electrical	Z3-012113	Light flickering
Germantown High	4/11/2024 10:31	WHITWORTH	Electrical	Z3-008799	Outlet box coming off wall
Germantown High	7/9/2024 13:21	SCOTT	Elevators	Z3-020620	Ballast out
Germantown High	12/16/2024 6:27		Fire Alarm System	Z3-044955	Pull station is disable due to the front panel is broke need replacing
Germantown High	12/10/2024 6:23		Fire Alarm System	Z3-044141	Trouble
Germantown High	12/10/2024 6:21		Fire Alarm System	Z3-044140	Continues to go off
Germantown High	12/10/2024 6:20		Fire Alarm System	Z3-044139	Trouble continues to go off
Germantown High	12/4/2024 6:30	SCOTT	Fire Alarm System	Z3-043081	Emergency light making noise
Germantown High	10/3/2024 9:30	SMALL	Fire Alarm System	Z3-036044	Cover missing
Germantown High	6/24/2024 8:26	SMALL	Fire Alarm System	Z3-019139	Trouble alarm
Germantown High	10/7/2024 9:14	SMALL	Fire Extinguishers	Z3-036412	Air handling room fire extinguisher out of date
Germantown High	10/7/2024 9:28	SMALL	Fire Watch	Z3-036424	Fire Watch was established, tell system is back in service
Germantown High	4/15/2024 7:40	CASEY	Flooring	Z3-009112	Replace carpet or tiles
Germantown High	4/11/2024 6:45	CASEY	Flooring	Z3-008698	Remove carpet or replace carpet
Germantown High	2/26/2024 17:35	CASEY	Flooring	Z3-002936	Remove old carpet and replace with tiles floor
Germantown High	5/17/2024 13:36	CASEY	Flooring	WO969948	remove carpet out of three offices in guidance. And replace. With floor tiles
oomantom mgn	0/1//2024 10:00	0/1021	1 10011116	***************************************	UNIT NOT COOLING - B200, 2ND FLOOR
					P/M CHAMBERS 416-7625
Germantown High	8/20/2024 10:57	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-028637	1711 GIANIBERS 410-7023
Germantown riigh	0/20/2024 10.37	FIVEASH	Heating/ventilation/All Conditioning	23-020037	Diek un novierates
O 115 et-	8/14/2024 8:20	WHITWORTH	Linear and antituding this Conditioning	Z3-027403	Pick up navigator
Germantown High	8/14/2024 8:20	WHIIWOKIH	Heating/Ventilation/Air Conditioning	23-02/403	DTILEOD THE ODLDO. BLOWING NOT COOLING DWOLLANDEDS 440 7005
					RTU FOR THE S BLDG - BLOWING NOT COOLING PM/CHAMBERS 416-7625
Germantown High	7/30/2024 8:14	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-023589	
					UNIT NOT COOLING - CL-RM B100 & B10
					FEEDING OFF THE SAME UNIT
					P/M CHMBERS 416-7625
Germantown High	5/14/2024 7:54	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-014364	
Germantown High	5/17/2024 13:53	JOHNSON	Heating/Ventilation/Air Conditioning	WO989663	anager Chambers reported the ac unit rooom 216 in the A building blowing but not cooling. 416-7825.
Germantown High	12/10/2024 12:51	MALONE	Key & Lock	Z3-044313	Take cylinder off master key
Germantown High	11/4/2024 6:24	MALONE	Key & Lock	Z3-039336	The assistant principal requested a master key GM Ms Fayne
Germantown High	10/29/2024 11:52	MALONE	Key & Lock	Z3-038733	Door will not open with key when latch
Germantown High	5/2/2024 5:10	BURCHETT	Masonry	Z3-012660	Repair wall tiles
Germantown High	5/17/2024 13:51	SMALL	Masonry	WO987082	hole and the floor (missing floor tiles) boys restroom 2nd stall
Germantown High	5/17/2024 13:36	CORONADO	Masonry	WO970700	The walk-in freezer flood when rainwater is coming in around the walls.
Germantown High	5/17/2024 13:36	CORONADO	Masonry	WO967895	floor tiles missing in kitchen need brick mason to come and replace red clay tile
Communitown Flight	0/1//2024 10:00	CONONADO	i idaolii y	110307033	All repairs out side
Germantown High	10/24/2024 16:19	BRYANT	Painting	Z3-038264	naticpans outside
Germantown High	10/4/2024 10:19	BURCHETT	Painting	Z3-036267	Needs painting it a administration office
_	7/12/2024 7:29	BURCHETT	=	Z3-030267 Z3-020966	
Germantown High	111212024 1.28	DUNUMETT	Painting	23-020906	FDC sign needs replacing

Germantown High	7/10/2024 7:44	BURCHETT	Painting	Z3-020672	The FDC sign needs replacing
Germantown High	6/26/2024 15:28	BURCHETT	Painting	Z3-019555	Need painting
Germantown High	12/16/2024 6:34	WARREN	Plumbing	Z3-044958	Urinal flush valve is bad was not completed.
Germantown High	11/25/2024 11:14	WARREN	Plumbing	Z3-042175	Water fountain leaking
Germantown High	11/25/2024 10:43	WARREN	Plumbing	Z3-042172	Sink leaking
•			•		· ·
Germantown High	8/26/2024 8:26	WARREN	Plumbing	Z3-029426	Water fountain leaking
Germantown High	8/19/2024 6:54	WARREN	Plumbing	Z3-028229	Water fountain leaking
Germantown High	6/26/2024 14:55	WILSON	Plumbing	Z3-019548	Water fountain leaking
Germantown High	6/11/2024 7:37	WILSON	Plumbing	Z3-017955	Water fountain leaking
Germantown High	2/28/2024 5:59	WARREN	Plumbing	Z3-003116	Back flow leaking
Germantown High	2/7/2024 8:17	WILSON	Plumbing	Z3-000493	Fire hydrant leaking
_					
Germantown High	12/16/2024 6:29	BUFORD	Roofing	Z3-044956	Roof leaking
Germantown High	11/6/2024 12:16	BUFORD	Roofing	Z3-039894	Girls restroom roof leak around sun window
Germantown High	11/6/2024 11:38	BUFORD	Roofing	Z3-039866	Roof leak
Germantown High	11/1/2024 11:12	BUFORD	Roofing	Z3-039256	Roof leak
Germantown High	10/31/2024 13:14	BUFORD	Roofing	Z3-039125	Boys restroom leaking from the skylight when rain
Germantown High	9/12/2024 15:53	WILSON	Roofing	Z3-032343	Roof leak
		DIAZ	_		Roof leak
Germantown High	9/12/2024 13:11		Roofing	Z3-032296	
Germantown High	2/13/2024 12:04	BARNES	Roofing	Z3-001239	Leaking roof
Germantown High	11/20/2024 6:41		Shades/Blinds	Z3-041585	Need a shade
Germantown High	10/28/2024 12:55	BENTON	Shades/Blinds	Z3-038558	Shades (2) needs replacing
Germantown High	5/17/2024 13:53	BENTON	Shades/Blinds	WO989806	room 105 shades
Germantown High	5/17/2024 13:53	BENTON	Shades/Blinds	WO989804	room 103 need shades
-					
Germantown High	5/17/2024 13:53	BENTON	Shades/Blinds	WO989802	room216 need a window shade.
Germantown High	9/3/2024 14:59	HATCH	Welding	Z3-030741	On the south side of the stadium the barb wire was cut needed repairs
Germantown Middle	8/22/2024 10:00	SMITH	Audio Visual	Z3-029072	om speaker reinstalled on the wall in the gym. It is located high up on the wall and will need a lift in order to service it.
					Can we have the annual bleacher inspection for Germantown middle
Germantown Middle	8/5/2024 14:34	SMALL	Bleachers and Seats	Z3-025377	
					the light is out by side the front door entrance the second light
Germantown Middle	12/10/2024 9:35	SCOTT	Electrical	Z3-044214	are agreed out by side are from about chalance are second agree
Germantown Middle	12/10/2024 9.35	30011	Electricat	23-044214	
					in the front of the building the overnight light is out
Germantown Middle	12/10/2024 9:34	SCOTT	Electrical	Z3-044213	
					by the gym door the light is out outside
Germantown Middle	12/10/2024 9:31	SCOTT	Electrical	Z3-044208	
					on the wall by the yeare door the light is out
Germantown Middle	12/10/2024 9:30	SCOTT	Electrical	Z3-044205	on the Hull by the fedicates the agent to det
Germantown Pridute	12/10/2024 9.30	30011	Electricat	23-044203	
					lights out by yeare outside dropoff and pickup door
Germantown Middle	12/10/2024 9:29	SCOTT	Electrical	Z3-044203	
					the clocks in the hallways do not work
Germantown Middle	12/4/2024 10:25	SCOTT	Electrical	Z3-043284	
					The magnetic lock is broken and will not keep the door open. This may be due to the door
					being prompt open. There is no trouble showing on the FAP. The opposite side of the door is
					actually working.
Germantown Middle	12/4/2024 10:24	SMALL	Electrical	Z3-043283	
					Spark from ceiling fan PM Davita Fawkner (9017369197) 1st floor
Germantown Middle	11/21/2024 10:22	SCOTT	Electrical	Z3-041909	
					POCA- THE CORD IS HANGING FROM THE CEILING IS NEEDING TO BE HARDWIRE TO THE
					PROJECTOR THEY IS USING AN EXTENSION CORD NOT SAFE
Germantown Middle	10/21/2024 14:10	SCOTT	Electrical	Z3-037712	
Germantown Middle	7/8/2024 8:06	CHALK	Electrical	Z3-020366	the bell panel with the lcd screen replaced that is located on the back wall to the left of the main office
					Can we have the bell system in the main office checked because it is not working and the
					electrician has confirmed that is has power.
Germantown Middle	6/21/2024 11:54	SMITH	Electrical	Z3-019058	
Germantown Middle	4/11/2024 13:42	SCOTT	Electrical	Z3-008885	We need two 12 volt 7ah batteries replaced that are dead in the fire panel
Joinnamo Millindado		55511	Liberious	20 000000	the fire extinguisher needs recharging on the 8th grade hall
Cormontou Middle	11/00/000444:40	CMALL	Fire Futire trials	70.044700	are the extinguisher needs recharging on the oth glade flatt
Germantown Middle	11/20/2024 11:16	SMALL	Fire Extinguishers	Z3-041732	
					Needs recharge by the water fountain
Germantown Middle	11/20/2024 11:15	SMALL	Fire Extinguishers	Z3-041731	
					by room 140 the fire ext needs recharge on the 8th grade hall
Germantown Middle	10/21/2024 8:42	SMALL	Fire Extinguishers	Z3-037605	- •
					Can we have our fire extinguisher replaced on the west side of the Oth grade due to it being
					Can we have our fire extinguisher replaced on the west side of the 8th grade due to it being
					knocked down and being sprayed completely out due to the handle bending
Germantown Middle					
Germantown Middle	4/24/2024 8:06	SMALL	Fire Extinguishers	Z3-011190	

Germantown Middle	7/18/2024 13:00	CASEY	Flooring	Z3-021704	ere was water that got on it and caused the floor the become wavy and uneven under the basketball goal on the East side of the gymnasium. It is on the R on the baseline
					the 8th grade hall room 134 is cold
Germantown Middle	12/2/2024 12:44	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-042541	
					The air is out in room 129 on the 7th grade hall
Germantown Middle	9/20/2024 9:45	SIMS	Heating/Ventilation/Air Conditioning	Z3-033948	
					needs an S key made per Mr.Thorns
Germantown Middle	12/2/2024 12:50	MALONE	Key & Lock	Z3-042549	
					on the 8th grade hall needs a key for room 139 it is an A key
Germantown Middle	12/2/2024 12:48	MALONE	Key & Lock	Z3-042548	
					ALL REPAIRS OUT SIDE BUILDING
Germantown Middle	10/24/2024 16:49	BRYANT	Painting	Z3-038265	
Germantown Middle	6/26/2024 13:42	BURCHETT	Painting	Z3-019533	Can we have the wall repainted due to the wall peeling and flaking off
					the middle water fountain valve is broken, and the water line is broke we had to turn it off
					completely because water is constantly running.
Germantown Middle	12/5/2024 8:27	WARREN	Plumbing	Z3-043458	
					the boy's restroom faucet has a leak
Germantown Middle	12/3/2024 12:06	WARREN	Plumbing	Z3-042943	
					in the room where the hot water tank is the pressure relief value needs replaced
Germantown Middle	10/3/2024 11:40	WARREN	Plumbing	Z3-036102	
					the computer lab is leaking in 2 spots
Germantown Middle	12/9/2024 10:05	BUFORD	Roofing	Z3-044024	
					classroom 125 on the 7th grade hall has a leak from the ceiling
Germantown Middle	12/9/2024 10:04	BUFORD	Roofing	Z3-044023	
					on the wall close to the gray tables that are standing up
Germantown Middle	12/9/2024 10:02	BUFORD	Roofing	Z3-044022	
					room 136 has a leak by the phone cord on the wall that says media
Germantown Middle	11/20/2024 11:10	BUFORD	Roofing	Z3-041724	
					it has a leak coming by the computer area
Germantown Middle	11/19/2024 12:42	BUFORD	Roofing	Z3-041523	
					the teachers lounge has a leak by the table
Germantown Middle	11/19/2024 12:40	BUFORD	Roofing	Z3-041522	
Getwell Bus Lot	11/14/2024 14:02	SCOTT	Electrical	Z3-040911	Balance replacement
Getwell Bus Lot	11/14/2024 13:30	SCOTT	Electrical	Z3-040899	Upstairs hallway need balance
Getwell Bus Lot	11/14/2024 13:14	SCOTT	Electrical	Z3-040894	The back hall has balance replacement
Getwell Bus Lot	11/14/2024 13:13	SCOTT	Electrical	Z3-040892	Balance replacement
Getwell Bus Lot	11/14/2024 13:12	SCOTT	Electrical	Z3-040890	DDs supervisor need balance replaced
Getwell Bus Lot	11/14/2024 13:11	SCOTT	Electrical	Z3-040889	2 sets of lights need replacing
Getwell Bus Lot	10/28/2024 11:42	SCOTT	Electrical	Z3-038541	All way around the shop
Getwell Bus Lot	10/23/2024 14:28	SCOTT	Electrical	Z3-038051	Shop need outlets fixed
Getwell Bus Lot	8/7/2024 10:45	SCOTT	Electrical	Z3-026030	Fan not so in lounge restroom
Getwell Elementary	9/25/2024 8:28	WEBB	Carpentry	Z3-034587	Window broken needs to be replaced
Getwell Elementary	9/17/2024 14:05	BARNES	Carpentry	Z3-033275	Window broken needs to be replaced
Getwell Elementary	5/17/2024 14:30	BENTON	Carpet Repair	WO1013303	in the main office, front office, and her personal office as well. she all so would like all of the carpet in the guidance counselor offices also (suit 100a)
Getwell Elementary	5/17/2024 14:05	BENTON	Carpet Repair	WO996228	the principal would like the carpet in the office pulled up
Getwell Elementary	12/2/2024 10:42	WHITWORTH	Electrical	Z3-042442	Lights out in the cafe to high to change
Getwell Elementary	10/3/2024 7:57	SCOTT	Electrical	Z3-036005	Ballast out
Getwell Elementary	8/21/2024 9:02	WHITWORTH	Electrical	Z3-028832	Van hood fan not working properly
Getwell Elementary	8/7/2024 12:57	SCOTT	Electrical	Z3-026112	Ballast out on the entry way
Getwell Elementary	8/6/2024 14:46	SCOTT	Electrical	Z3-025813	Need a ballast
Getwell Elementary	7/31/2024 11:26	SCOTT	Electrical	Z3-024090	Light balance out
Getwell Elementary	6/10/2024 9:08	SCOTT	Electrical	Z3-017824	Replace balance in front entry
Getwell Elementary	6/6/2024 9:39	SCOTT	Electrical	Z3-017518	Light ballad
Getwell Elementary	9/20/2024 10:47	SMALL	Fire Alarm System	Z3-033982	Pull sation needs to be replaced the pk625 key is not functioning properly when trying to use.
Getwell Elementary	5/6/2024 18:43	SMALL	Fire Extinguishers	Z3-013282	K extinguisher needed in kitchen
Getwell Elementary	3/5/2024 10:04	CASEY	Flooring	Z3-003969	Principal requests carpet to be removed
					Room A117 Blower Motor inoperable.
Getwell Elementary	7/26/2024 8:34	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-022770	···
			g		UNIT NOT COOLING - MAIN OFFICE AREA - C-BLDG
					P/M CHAMBERS 416-7625
Getwell Elementary	4/18/2024 7:43	SCOTT	Heating/Ventilation/Air Conditioning	Z3-010085	***************************************
Getwell Elementary	12/12/2024 10:51	MALONE	Key & Lock	Z3-044695	Needs new key for her office door
Getwell Elementary	8/14/2024 7:22	SMITH	Key & Lock	Z3-044095	Need keys for pull stations
Getwell Elementary	7/24/2024 8:15	SMITH	Key & Lock	Z3-02/3/0	School need new locks on several classroom doors
Getwell Elementary	7/17/2024 8:19	SMITH	Key & Lock	Z3-022233	Need a new key lock
Cowell Liementary	771772024 0.10	0111111	ncy a Lock	20 021-04	Code d now noy box

Getwell Elementary	2/23/2024 11:55	SMITH	Key & Lock	Z3-002667	tried to fix it screws are stripped and Admin restroom is doing the same I had to take the knob apart to get an administrator out of the restroom
Getwell Elementary	2/19/2024 8:04	SMITH	Key & Lock	Z3-001823	Door isn't locking as needs to be assessed soon as there is an availability
Getwell Elementary	11/14/2024 14:24	BURCHETT	Painting	Z3-040925	Needs to be painted next to b133
Getwell Elementary	11/14/2024 14:22	BURCHETT	Painting	Z3-040924	Needs to be painted near the cafe
Getwell Elementary	11/14/2024 14:21	BURCHETT	Painting	Z3-040922	Needs to be painting
Getwell Elementary	11/1/2024 13:00	BURCHETT	Painting	Z3-039296	te lines need to be repainted. And also Principal, Finical secretary, Assistant principal, plc coach
Getwell Elementary	9/30/2024 9:08	BURCHETT	Painting	Z3-035363	Need to be painted
Getwell Elementary	9/18/2024 10:07	BURCHETT	Painting	Z3-033407	Wall need to be painted next to B133
Getwell Elementary	9/18/2024 10:05	BURCHETT	Painting	Z3-033405	Wall need to be painted near cafeteria across from B137J
Getwell Elementary	9/10/2024 9:03	BURCHETT	Painting	Z3-031677	Ceiling needs to be painted in front of the cafeteria in the hallway
Getwell Elementary	7/18/2024 12:06	BURCHETT	Painting	Z3-021687	School halls paint is chip severely
Getwell Elementary	7/17/2024 8:25	BURCHETT	Painting	Z3-021485	Paint peeling/ Need to be painted
Getwell Elementary	6/17/2024 9:12	BURCHETT	Painting	Z3-018514	Paint baseboards
Getwell Elementary	6/17/2024 9:12	BURCHETT	Painting	Z3-018513	Baseboards need painting
Getwell Elementary	6/17/2024 9:11	BURCHETT	Painting	Z3-018512	Paint ceiling n baseboard
Getwell Elementary	6/11/2024 23:56	BURCHETT	Painting	Z3-018081	Walls are need of painting throughput Getwell Elm please
•			· ·		Children have peeled paint off the wall
Getwell Elementary	5/14/2024 9:21	BURCHETT	Painting	Z3-014421	
Getwell Elementary	10/18/2024 8:01	BENTON	Shades/Blinds	Z3-037438	Blinds needs to be replaced
Gordon Achievement Academy	4/3/2024 10:17		Carpet Repair	Z1-007550	Need 6 court building board
Gordon Achievement Academy	5/17/2024 14:05	BENTON	Carpet Repair	WO996226	Principal requesting to have all carpet removed and replaced with floor tile. Thanks
Gordon Achievement Academy	10/16/2024 8:35	ANDREWS	Electrical	Z1-037159	Lights out in the cafeteria
Gordon Achievement Academy	2/7/2024 7:41	ANDREWS	Electrical	Z1-000473	Light out
Gordon Achievement Academy	5/17/2024 14:23	CHASE	Flooring	WO1005340	hat all the carpet in His office the Asst. Principal an the main office have all the carpet removed an put down all floor tile. Thanks
Gordon Achievement Academy	7/3/2024 8:40	GREER	Generators	Z1-020142	Tile need to be replaced in the main lobby ceiling is up high
					HEATING UNIT IN RM 181 - BLOWING NOT HEATING PM/ANDERSON 416-3212
Gordon Achievement Academy	12/3/2024 7:56	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042718	
					HEATING UNIT IN RM 179 - BLOWING NOT HEATING PM/ANDERSON 416-3212
Gordon Achievement Academy	12/3/2024 7:55	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042717	
					HEATING UNIT IN RM 126 - BLOWING NOT HEATING PM/ANDERSON 416-3212
Gordon Achievement Academy	12/3/2024 7:55	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042716	
					HEATING UNIT IN RM 114 - BLOWING NOT HEATING PM/ANDERSON 416-3212
Gordon Achievement Academy	12/3/2024 7:54	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042714	
Gordon Achievement Academy	11/6/2024 13:13	SIMMONS	Heating/Ventilation/Air Conditioning	Z1-039916	onnect power from hvac unit and remove so wall can be accessed to repair piping and install new valves.
Gordon Achievement Academy	9/16/2024 8:48	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-032831	188 AC making a noise is not coming on
					HVAC UNIT FOR THE MUSIC HALL - MAKING LOUD HAD TO CUT OFF PM/WASHING 416-
					3212
Gordon Achievement Academy	9/11/2024 14:28	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-032044	
					UNIT NOT COOLING - CL-RM 132
					P/M WASHINGTON 416-3212
Gordon Achievement Academy	8/28/2024 9:48	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-030003	
					HVAC UNIT - IN RM 136 -BLOWING HOT AIR - PM/WASHINGTON 416-3212
Gordon Achievement Academy	8/28/2024 7:38	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-029921	LINES IN THE PROPERTY OF THE P
					HVAC UNIT - IN RM 134 - KEEPS TURNING ON & OFF SHORTAGE PM/WASHINGTON 416-
Cardon Ashiousmant Asadamu	0/20/2024 7:27	WILLIAMS	Heating Montilation / Air Conditioning	71 020020	3212
Gordon Achievement Academy	8/28/2024 7:37	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-029920	
					Plant Manager Washington reported the ac unit in room 106 is blowing hot air. 416-3412.
Gordon Achievement Academy	8/8/2024 12:13	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-026428	Frank Hanager washington reported the act tills in 100m 100 is blowing not all. 410-3412.
Cordon Achievement Academy	0/0/2024 12.13	WILLIAM	ricating/ventitation/Air Conditioning	21-020420	Plant Manager Washington reported the ac unit in the front Teacher's Lounge is not
					powering on. 416-3412.
Gordon Achievement Academy	8/5/2024 11:04	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-025261	ponog on. 120 0121.
Gordon Achievement Academy	7/22/2024 15:10	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-022009	Ac out in room 179
Gordon Achievement Academy	5/29/2024 8:10	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-016233	Ac out in room 190
Gordon Achievement Academy	5/29/2024 8:07	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-016230	Ac out in room 129
Gordon Achievement Academy	5/29/2024 8:05	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-016229	Ac out in room 128
Gordon Achievement Academy	7/18/2024 9:42	BURCHETT	Masonry	Z1-021619	Need tiles replacing in the girls bathroom on the green mile By the toilets
Gordon Achievement Academy	5/31/2024 9:10	BURCHETT	Painting	Z1-021013 Z1-016667	Carpet replacement in principles, office system, principal and regular
Gordon Achievement Academy	5/29/2024 8:22	BURCHETT	Painting	Z1-016239	Need room painting and 109
Gordon Achievement Academy	5/14/2024 8:27	BURCHETT	Painting	Z1-014386	Billboard to go on the hallway, the elementary hallway
Gordon Achievement Academy	5/14/2024 8:26	BURCHETT	Painting	Z1-014384	Billboard to go on the hallway, the elementary hallway
, , , , , , , , , , , , , , , , , , , ,					Hook water back up to hvac unit in classroom
Gordon Achievement Academy	9/6/2024 8:43	Jordan	Plumbing	Z1-031250	·
Gordon Achievement Academy	7/18/2024 9:44	Williams	Sheet Metal	Z1-021620	Have a metal sleeve that's pulled up in the boys bathroom right by the stall
ŕ					•

	8/13/2024 11:04	SMITH	Electrical	Z1-027275	Repair or replace emergency light #16
Gragg-TTC Gragg-TTC	8/13/2024 11:04	SMITH	Electrical	Z1-027275 Z1-027272	Repair or replace emergency light #10 Repair or replace emergency light #17
Gragg-TTC	8/13/2024 8:06	SMITH	Electrical	Z1-027175	Light in front of the boys and girls bathroom on the middle school hallway balance is out
Gragg-TTC	8/8/2024 15:00	SMITH	Electrical	Z1-026508	Replace emergency light
Gragg-TTC	8/8/2024 14:58	SMITH	Electrical	Z1-026506	Repair or replace emergency light #16
					Generator did not kick in when power was lost
Gragg-TTC	5/7/2024 9:06	GREER	Generators	Z1-013364	
					Ms. cox
					65904
					PAU1 NOT HEATING
Gragg-TTC	12/10/2024 14:29	WEBB	Heating/Ventilation/Air Conditioning	Z1-044350	
Gragg-TTC	8/15/2024 10:56	BURCHETT	Painting	Z1-027792	I lines repay, and the principal signs, assistant, principal, and those signs need to be repainted too on the parking lot
					HEATING MAKEUP WATER POPOFF NEEDS TO BE PIPED TO FLOOR DRAIN
Gragg-TTC	11/14/2024 6:08	SINK	Plumbing	Z1-040723	
Gragg-TTC	11/12/2024 9:51	WILSON	Roofing	Z1-040425	Roof leaking in room Lab 1
Gragg-TTC	10/15/2024 15:49	Williams	Sheet Metal	Z1-037101	repair or replace down spout
Gragg-TTC	9/30/2024 15:07	HATCH	Sheet Metal	Z1-035542	Replace down spout with large hole
					teacher is requesting to have cabinets removed from wall area so that wall area can be
					treated for termites
Grahamwood Elementary	12/3/2024 15:19	BURKE	Carpentry	Z2-043052	
Ordinarii Wood Eterneritary	12/0/2024 10:10	DOTINE	Curpentry	22 040002	there is a ballast out in the Assistant Principals office in room 224
	40/5/0004055	DOLLIE!	· · ·	70.040500	there is a battast out in the Assistant Principals office in footin 224
Grahamwood Elementary	12/5/2024 9:55	POWELL	Electrical	Z2-043538	
					POCA Cafeteria exit signs not lighting
Grahamwood Elementary	11/14/2024 12:36	POWELL	Electrical	Z2-040866	
					POCA Cafeteria Emergency lights need new batteries
Grahamwood Elementary	11/14/2024 12:32	POWELL	Electrical	Z2-040863	
•					Main office clock needs to be adjusted because of the time change
Grahamwood Elementary	11/6/2024 14:41	POWELL	Electrical	Z2-039945	
Ordinarii Wood Eterneritary	11/0/2024 14.41	TOWELL	Electricat	22 000040	the electrical outlet box is coming away from the wall
Crahamusad Flamenton	11/4/2024 12:00	DOWELL	Floatrical	70.000464	the electrical outlet box is coming away from the wait
Grahamwood Elementary	11/4/2024 12:06	POWELL	Electrical	Z2-039464	
					The water fountains on the 2nd floor are tripping the breaker and will not stay on
Grahamwood Elementary	8/9/2024 8:12	POWELL	Electrical		
Grananiwood Elementary	0/3/2024 0.12	TOWLLL	Licotricut	Z2-026568	
Granamwood Eternentary	0/3/2024 0.12	TOWLLL	Electrical	22-026568	stairwell light leading to playground needs a ballast replaced
Grahamwood Elementary	4/25/2024 12:29	POWELL	Electrical	Z2-026568 Z2-011550	stainwell light leading to playground needs a ballast replaced
					stairwell light leading to playground needs a ballast replaced cafeteria light needs new ballast
Grahamwood Elementary	4/25/2024 12:29		Electrical		
		POWELL		Z2-011550	cafeteria light needs new ballast
Grahamwood Elementary	4/25/2024 12:29	POWELL	Electrical	Z2-011550	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new
Grahamwood Elementary Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43	POWELL	Electrical Electrical	Z2-011550 Z2-008713	cafeteria light needs new ballast
Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57	POWELL POWELL	Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries
Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40	POWELL POWELL POWELL	Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 WO1028154	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room
Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30	POWELL POWELL POWELL POWELL POWELL	Electrical Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom
Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40	POWELL POWELL POWELL	Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 WO1028154	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room
Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30	POWELL POWELL POWELL POWELL POWELL	Electrical Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom
Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30 5/17/2024 14:29	POWELL POWELL POWELL POWELL POWELL POWELL	Electrical Electrical Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out.
Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30 5/17/2024 14:29	POWELL POWELL POWELL POWELL POWELL POWELL	Electrical Electrical Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location.
Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30 5/17/2024 14:29 5/17/2024 14:06	POWELL POWELL POWELL POWELL POWELL POWELL POWELL	Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location.
Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30 5/17/2024 14:29 5/17/2024 14:06	POWELL POWELL POWELL POWELL POWELL POWELL POWELL	Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 14:30 5/17/2024 14:29 5/17/2024 14:06 10/15/2024 8:41	POWELL POWELL POWELL POWELL POWELL POWELL Coleman	Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location.
Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30 5/17/2024 14:29 5/17/2024 14:06	POWELL POWELL POWELL POWELL POWELL POWELL POWELL	Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30 5/17/2024 14:29 5/17/2024 14:06 10/15/2024 8:41 9/24/2024 9:45	POWELL POWELL POWELL POWELL POWELL POWELL Coleman	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 14:30 5/17/2024 14:29 5/17/2024 14:06 10/15/2024 8:41	POWELL POWELL POWELL POWELL POWELL POWELL Coleman	Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly POCA there is a trouble alert of Dirty Duct Detector
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30 5/17/2024 14:29 5/17/2024 14:06 10/15/2024 8:41 9/24/2024 9:45	POWELL POWELL POWELL POWELL POWELL POWELL Coleman	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30 5/17/2024 14:29 5/17/2024 14:06 10/15/2024 8:41 9/24/2024 9:45	POWELL POWELL POWELL POWELL POWELL POWELL Coleman	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly POCA there is a trouble alert of Dirty Duct Detector
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30 5/17/2024 14:29 5/17/2024 14:06 10/15/2024 8:41 9/24/2024 9:45 11/14/2024 12:13	POWELL POWELL POWELL POWELL POWELL POWELL Coleman Coleman	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Flevators Elevators Fire Alarm System	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994 Z2-034440 Z2-040859	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly POCA there is a trouble alert of Dirty Duct Detector
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30 5/17/2024 14:29 5/17/2024 14:06 10/15/2024 8:41 9/24/2024 9:45 11/14/2024 12:13	POWELL POWELL POWELL POWELL POWELL POWELL Coleman Coleman	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrisal Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994 Z2-034440 Z2-040859	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly POCA there is a trouble alert of Dirty Duct Detector POCA The Red Box in the Riser Room needs a spare sprinkler
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30 5/17/2024 14:29 5/17/2024 14:06 10/15/2024 8:41 9/24/2024 9:45 11/14/2024 12:13 11/14/2024 12:22	POWELL POWELL POWELL POWELL POWELL POWELL Coleman Coleman Coleman	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Flevators Elevators Fire Alarm System	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994 Z2-034440 Z2-040859 Z2-040861	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly POCA there is a trouble alert of Dirty Duct Detector POCA The Red Box in the Riser Room needs a spare sprinkler Mr. Joy (416 5952) Grahamwood ES Boiler is out Rm250
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 14:30 5/17/2024 14:30 5/17/2024 14:06 10/15/2024 8:41 9/24/2024 9:45 11/14/2024 12:13 11/14/2024 12:22 12/3/2024 10:31	POWELL POWELL POWELL POWELL POWELL POWELL Coleman Coleman Coleman Coleman HANSON	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Flevators Elevators Fire Alarm System Fire Sprinkler System Heating/Ventilation/Air Conditioning	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994 Z2-034440 Z2-040859 Z2-040861 Z2-042868	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly POCA there is a trouble alert of Dirty Duct Detector POCA The Red Box in the Riser Room needs a spare sprinkler
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30 5/17/2024 14:29 5/17/2024 14:06 10/15/2024 8:41 9/24/2024 9:45 11/14/2024 12:13 11/14/2024 12:22	POWELL POWELL POWELL POWELL POWELL POWELL Coleman Coleman Coleman	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrisal Electrical Electrical	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994 Z2-034440 Z2-040859 Z2-040861	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly POCA there is a trouble alert of Dirty Duct Detector POCA The Red Box in the Riser Room needs a spare sprinkler Mr. Joy (416 5952) Grahamwood ES Boiler is out Rm250
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 14:30 5/17/2024 14:30 5/17/2024 14:06 10/15/2024 8:41 9/24/2024 9:45 11/14/2024 12:13 11/14/2024 12:22 12/3/2024 10:31	POWELL POWELL POWELL POWELL POWELL POWELL Coleman Coleman Coleman Coleman HANSON	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Flevators Elevators Fire Alarm System Fire Sprinkler System Heating/Ventilation/Air Conditioning	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994 Z2-034440 Z2-040859 Z2-040861 Z2-042868	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly POCA there is a trouble alert of Dirty Duct Detector POCA The Red Box in the Riser Room needs a spare sprinkler Mr. Joy (416 5952) Grahamwood ES Boiler is out Rm250 Mr. Joy (416 5952) Grahamwood ES Boiler is out Rm239
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 14:30 5/17/2024 14:30 5/17/2024 14:06 10/15/2024 8:41 9/24/2024 9:45 11/14/2024 12:13 11/14/2024 12:22 12/3/2024 10:31 12/3/2024 10:26	POWELL POWELL POWELL POWELL POWELL POWELL Coleman Coleman Coleman HANSON HANSON	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Elevators Elevators Fire Alarm System Fire Sprinkler System Heating/Ventilation/Air Conditioning	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994 Z2-034440 Z2-040859 Z2-040861 Z2-042868 Z2-042859	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly POCA there is a trouble alert of Dirty Duct Detector POCA The Red Box in the Riser Room needs a spare sprinkler Mr. Joy (416 5952) Grahamwood ES Boiler is out Rm250
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 14:30 5/17/2024 14:30 5/17/2024 14:06 10/15/2024 8:41 9/24/2024 9:45 11/14/2024 12:13 11/14/2024 12:22 12/3/2024 10:31	POWELL POWELL POWELL POWELL POWELL POWELL Coleman Coleman Coleman Coleman HANSON	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Flevators Elevators Fire Alarm System Fire Sprinkler System Heating/Ventilation/Air Conditioning	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994 Z2-034440 Z2-040859 Z2-040861 Z2-042868	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly POCA there is a trouble alert of Dirty Duct Detector POCA The Red Box in the Riser Room needs a spare sprinkler Mr. Joy (416 5952) Grahamwood ES Boiler is out Rm250 Mr. Joy (416 5952) Grahamwood ES Boiler is out Rm239
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 15:40 5/17/2024 14:30 5/17/2024 14:06 10/15/2024 8:41 9/24/2024 9:45 11/14/2024 12:13 11/14/2024 12:22 12/3/2024 10:31 12/3/2024 10:26 8/8/2024 15:03	POWELL POWELL POWELL POWELL POWELL POWELL Coleman Coleman Coleman Coleman HANSON HANSON	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Elevators Elevators Fire Alarm System Fire Sprinkler System Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994 Z2-034440 Z2-040859 Z2-040861 Z2-042868 Z2-042868 Z2-042859	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly POCA there is a trouble alert of Dirty Duct Detector POCA The Red Box in the Riser Room needs a spare sprinkler Mr. Joy (416 5952) Grahamwood ES Boiler is out Rm250 Mr. Joy (416 5952) Grahamwood ES Boiler is out Rm239
Grahamwood Elementary	4/25/2024 12:29 4/11/2024 7:43 4/2/2024 14:57 2/3/2024 14:30 5/17/2024 14:30 5/17/2024 14:06 10/15/2024 8:41 9/24/2024 9:45 11/14/2024 12:13 11/14/2024 12:22 12/3/2024 10:31 12/3/2024 10:26	POWELL POWELL POWELL POWELL POWELL POWELL Coleman Coleman Coleman HANSON HANSON	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Elevators Elevators Fire Alarm System Fire Sprinkler System Heating/Ventilation/Air Conditioning	Z2-011550 Z2-008713 Z2-007428 W01028154 W01013856 W01012943 W0996854 Z2-036994 Z2-034440 Z2-040859 Z2-040861 Z2-042868 Z2-042859	cafeteria light needs new ballast Emergency lights in main building did not come on during power outage. Could need new batteries replace ballast in light fixture in front of Main Boiler room we need a light cover for the lights in the kitchen restroom outlet to the left of the doorway is shorting out. CA Per Fire Inspectors: Remove wires from sprinkler branch line. See plant manager for location. The elevator in the new building is not working properly The elevator in the new building is getting stuck and the door is not closing properly POCA there is a trouble alert of Dirty Duct Detector POCA The Red Box in the Riser Room needs a spare sprinkler Mr. Joy (416 5952) Grahamwood ES Boiler is out Rm250 Mr. Joy (416 5952) Grahamwood ES Boiler is out Rm239

					room 243 needs the door lock replaced
Grahamwood Elementary	8/29/2024 8:32	SMITH	Key & Lock	Z2-030178	100111 240 needs the door took reptaced
Grandview Heights Middle School	12/11/2024 8:45	G	Audio Visual	Z1-044430	Intercom not working
g					IN ROOM #12 THERE'S WATER & TERMITE DAMAGE TO THE ROOM. THE TOP OF THE
					CEILING, WINDOW SILLS, & VARIOUS OTHER AREAS. ALSO IT'S BEEN SPRAYED. THANK
					YOU, STL
Grandview Heights Middle School	10/8/2024 8:52	ARNOLD	Carpentry	Z1-036580	
Grandview Heights Middle School	9/24/2024 8:34	ARNOLD	Carpentry	Z1-034390	Wood needs replaced due to rain damage
Grandview Heights Middle School	6/21/2024 13:55	ARNOLD	Carpentry	Z1-019084	Needs Special cut ceiling tile
Grandview Heights Middle School	6/5/2024 13:24	ARNOLD	Carpentry	Z1-017366	Baseboard needs replaced
Grandview Heights Middle School	3/27/2024 7:03	ARNOLD	Carpentry	Z1-006502	Special cut ceiling tile needs replacing
Grandview Heights Middle School	2/20/2024 8:27	ARNOLD	Carpentry	Z1-002004	Special cut ceiling tile
Grandview Heights Middle School	2/16/2024 12:48	ARNOLD	Carpentry	Z1-001750	Special cut ceiling tiles
					Special cut ceiling tile needs replaced
Grandview Heights Middle School	2/13/2024 10:01	ARNOLD	Carpentry	Z1-001170	
					Special cut ceiling tile needs replaced
Grandview Heights Middle School	2/13/2024 8:05	ARNOLD	Carpentry	Z1-001096	
					Special cut ceiling tile needs replaced
Grandview Heights Middle School	2/13/2024 8:03	ARNOLD	Carpentry	Z1-001095	
Grandview Heights Middle School	12/3/2024 8:44	SMITH	Electrical	Z1-042750	Socket is push down needs replaced
Grandview Heights Middle School	11/20/2024 10:09	SIMMONS	Electrical	Z1-041678	Ballist needs change
Grandview Heights Middle School	10/29/2024 8:19	SMITH	Electrical	Z1-038642	One side wall socket out
Grandview Heights Middle School	10/1/2024 11:50	SMITH	Electrical	Z1-035724	Needs co2 reader
Grandview Heights Middle School	9/25/2024 12:28	SMITH	Electrical	Z1-034671	Right wall socket doesn't work
Grandview Heights Middle School	9/13/2024 5:29	CHALK	Electrical	Z1-032365	Outside light needs change
Grandview Heights Middle School	9/13/2024 5:28	CHALK	Electrical	Z1-032364	Needs 5 lights replaced around left side and left back of building
Grandview Heights Middle School	9/5/2024 8:51	SMITH	Electrical	Z1-031056	Emergency light need replacing
Grandview Heights Middle School	9/3/2024 9:55	SMITH	Electrical	Z1-030672	5ballist out
Grandview Heights Middle School	2/3/2024 16:57	SMITH	Electrical		E LIGHT BY THE CHILLER AT THE BACKSIDE DOOR NEED TO BE REPAIRED. ASAP THANK YOU, STL
Grandview Heights Middle School	2/3/2024 16:57	SMITH	Electrical		HT NEAR THE BOILER ROOM DOOR ON THE OUTSIDE NEEDS TO BE REPLACED. ASAP THANK YOU, STL
Grandview Heights Middle School	5/17/2024 14:25	CHALK	Electrical		SCHOOL THE LARGE LIGHT FIXTURE BULB IS CONTINOUSLY BLINKING. NEED CHECKED OUT ASAP THANK YOU, STL
Grandview Heights Middle School	5/17/2024 14:25	CHALK	Electrical		HT FIXTURE NEAR TRASH DUMPSTER BULB IS NOT WORKING. NEED CHECKED OUT ASAP THANK YOU, STL
Grandview Heights Middle School	5/17/2024 13:49	CHALK	Electrical	WO986390	Light on back parking lot flashing
Grandview Heights Middle School	5/17/2024 13:47	CHALK	Electrical	W0983404	parking lot light on corner of building in the rear out
Grandview Heights Middle School	12/9/2024 14:39		Energy Management System	Z1-044112	Needs to be back on line for you guys to see hvac system ms. white
					63940
					needs thermostat put on heater
Grandview Heights Middle School	12/12/2024 10:03	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044665	needs thermostat put on heater
Grandview Heights Middle School	12/3/2024 12:45	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042977	Thermostat needs replaced kids tore it off wall
Granaviow Froignics Finance Control	12/0/2024 12/40	***************************************	riodang rendadon/in conditioning	21 0 12077	HVAC UNIT FOR RM 107 - BLOWING NOT HEATING PM/WHITE 416-3940
Grandview Heights Middle School	12/3/2024 12:51	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042980	
			0		HVAC UNIT FOR RM 16 - BLOWING NOT HEATING PM/WHITE 416-3940
Grandview Heights Middle School	12/3/2024 12:50	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042979	
Grandview Heights Middle School	9/9/2024 13:03	SMITH	Key & Lock	Z1-031567	Key for lights operation is broken in lock
Grandview Heights Middle School	2/29/2024 8:37	SMITH	Key & Lock	Z1-003343	Needs new lock key gets stuck when trying to open
Grandview Heights Middle School	12/4/2024 8:45	BURCHETT	Masonry	Z1-043160	Shaft door needs replaced
Grandview Heights Middle School	9/9/2024 13:08	BURCHETT	Masonry	Z1-031570	1 wall tile needs replaced
Grandview Heights Middle School	7/25/2024 8:58	BURCHETT	Masonry	Z1-022519	Ceramic tile needs replaced
Grandview Heights Middle School	10/28/2024 9:58	BURCHETT	Painting	Z1-038490	Security spot and cafeteria manager spot needs labeled
Grandview Heights Middle School	9/16/2024 15:27	BURCHETT	Painting	Z1-033033	Columns needs paint from grafetti
Grandview Heights Middle School	6/11/2024 7:58	BURCHETT	Painting	Z1-017960	Restroom paint has chip off bad needs painted
Grandview Heights Middle School	6/11/2024 7:57	BURCHETT	Painting	Z1-017959	Paint is chipped off walls need painted
Grandview Heights Middle School	2/26/2024 12:06	BURCHETT	Painting	Z1-002860	Needs painted
Grandview Heights Middle School	2/15/2024 8:28	BURCHETT	Painting	Z1-001505	Ceiling needs painted paint peeling Health department said needs painted took a point
					The cafeteria entrance doors need painting. Please help
Grandview Heights Middle School	5/17/2024 14:23	HARRIS	Painting	WO1005441	
Grandview Heights Middle School	12/9/2024 9:19	DIAZ	Roofing	Z1-043996	Leaks when raining in room
Grandview Heights Middle School	2/3/2024 17:03	BENTON	Shades/Blinds	WO1018045	FFICE THAT HAS BEEN REDONE OVER ALL THE BLINDS NEED TO BE REPLACED. NEED ASAP THANK YOU, STL
					I need some to come out and take a look at fire alarm system it keeps going off (smoke
					detector is in default)
Grays Creek (Operations Center)	11/19/2024 14:02	Coleman	Fire Alarm System	Z2-041550	
Grays Creek (Operations Center)	2/3/2024 15:20	Contractor	Fire Alarm System	WO1029245	Fire Alarm Supervisory Issue, send a technician.
Grays Creek (Operations Center)	4/22/2024 10:34	LEWIS	Fire Sprinkler System	Z2-010892	I have sprinkler that going off and water is running need someone to come out to shut it off.

Per State Systems Sprinkler- Part 2 After January Frozen Sprinkler Pipes Issue.

					rei State Systems Sprinker- rait 2 Arter January Prozent Sprinker Pipes Issue.
Grays Creek (Operations Center)	3/18/2024 10:18	LEWIS	Fire Sprinkler System	Z2-005154	
					Per State Systems Sprinkler technician-The air compressor for the dry pipe system suffered
					freeze damage and needs replacement, cost \$1,725.00.
Grays Creek (Operations Center)	2/13/2024 13:12	LEWIS	Fire Sprinkler System	Z2-001274	
Grays Creek (Operations Center)	2/3/2024 16:46	Systems	Fire Sprinkler System		rinkler Inspection for 7 Wet-Pipe Fire Sprinkler systems and (1) Dry -Pipe Fire Sprinkler System, cost \$5,840.00.
Grays Creek (Operations Center)	2/3/2024 10.40	Systems	riie Spilliktei Systelli	WO1020603	
					test backflows
Grays Creek (Operations Center)	12/12/2024 7:20	SEMLER	Plumbing	Z2-044529	
Halle Stadium	7/18/2024 8:17	SMALL	Bleachers and Seats	Z3-021589	Repair the damage on the stadium seating for the home and visitor sections
					REPLACE GLASS IN PRESSBOX BOTH SIDES - CANNOT SEE OUT OF
Halle Stadium	10/28/2024 13:29	CROUSE	Cornentry	Z3-038569	2 2
nalle Stauluili	10/28/2024 13.29	CHOUSE	Carpentry	23-036369	
					Window inside concession stand needs replacing
Halle Stadium	7/18/2024 8:36	CROUSE	Carpentry	Z3-021598	
					NEED A 110 OUTLET INSTALLED FOR TRACK AND FIELD
Halle Stadium	11/21/2024 13:56	SCOTT	Electrical	Z3-041981	
riate otadiani	11/21/2024 10:00	00011	Electricat	20 041501	lights not working
					ughts not working
Halle Stadium	9/30/2024 10:45	SCOTT	Electrical	Z3-035434	
					lights not coming on
Halle Stadium	9/6/2024 10:56	SCOTT	Electrical	Z3-031304	
Tiddo otdardiii	0/0/2024 10:00	00011	Etootriout	20 00100	
					ELECTRICITY IN THE TICKET BOOTH ON EAST SIDE OF STADIUM - NEED LIGHTS TO WORK
Halle Stadium	8/5/2024 11:07	TAYLOR	Electrical	Z3-025262	
					KEYS TO ALL LOCKS FOR STADIUM GATES
					KEYS TO PRESS BOX CONCESSION STAND TICKET BOOTH
					KEYS TO ALL STADIUM DOORS MECHANICAL ROOM AND ETC.
					KETS TO ALL STADIOM DOORS MECHANICAL ROOM AND ETC.
Halle Stadium	8/5/2024 11:18	TAYLOR	Key & Lock	Z3-025267	
					NEED 2 SET KEYS FOR ALL LOCKS TO PRESSBOX
Halle Stadium	7/1/2024 14:23	SMITH	Key & Lock	Z3-019993	
			, 2. 2.2		Fabricate brackets for space heaters
Halla Ota dissa	40/0/00040-54	LIATOLI	Observa Manage	70.040005	l'ablicate brackets for space fleaters
Halle Stadium	12/9/2024 6:51	HATCH	Sheet Metal	Z3-043925	
Hamilton High	8/8/2024 8:30	SMITH	Audio Visual	Z4-026250	Intercom not working in room 204. Respectfully request repair.
Hamilton High	6/11/2024 10:10	CALDWELL	Bleachers and Seats	Z4-017995	Respectfully request bleacher inspection.
Hamilton High	11/19/2024 9:37	FORD	Carpentry	Z4-041462	Vandalism/ hole in the wall
riamitton riigii	11/10/2024 0.07	TOND	Culpentry	24 041402	Vandalism/ hole in wall
					validatishi/ note in watt
Hamilton High	11/13/2024 7:19	FORD	Carpentry	Z4-040545	
					Mr. Smith 67838 score board won't come on
Hamilton High	11/20/2024 10:12	HALL	Electrical	Z4-041681	
					Mr. Smith 67838 exterior lights don't cut on at night
			F1	7	The officer of occupants agree a conference of the major
Hamilton High	11/20/2024 10:11	HALL	Electrical	Z4-041679	
Hamilton High	11/15/2024 8:31	HALL	Electrical	Z4-041013	Exterior lights not working properly at night
					PARTIAL POWER OUTAGE - CAFETERIA & ALL THE CL-RMS ON THE 1ST FLOOR
					P/M LONTE SMITH 416-7838
Hamilton High	11/6/2024 7:26	HALL	Electrical	Z4-039688	
naiiittoii nigii	11/0/2024 /.20	HALL	Electricat	24-033000	
					Sockets not getting power
Hamilton High	10/24/2024 6:57	HALL	Electrical	Z4-038082	
Hamilton High	10/15/2024 6:56	HALL	Electrical	Z4-036948	Light bulbs need to be changed too high to reach
Hamilton High	4/18/2024 9:53	HALL	Electrical	Z4-010213	have an electrical cord hanging in the gym from the ceiling. Respectfully request cord moved.
Hamilton High	4/10/2024 9:55	TIALL	Liectificat	24-010213	have an electrical cord hanging in the gym norm the certaing, respectfully request cord moved.
					I have 6 lights out in the gym. Need pole to get to lights. Respectfully request lights changed.
Hamilton High	3/27/2024 9:37	HALL	Electrical	Z4-006558	
Hamilton High	12/16/2024 6:47	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-044960	Entire side is cold and isn't getting heat
Hamilton High	12/4/2024 9:42	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-043236	AHU 15 is not on
naiiiilloii nigii	12/4/2024 9.42	MADUNATUM	neating/ventitation/Air Conditioning	24-043236	
					Plant Manager Smith reported Energy Management instructed him to call in the hot water
					pumps are showing in alarm status. 416-7838.
Hamilton High	12/2/2024 11:34	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-042490	
Hamilton High	12/2/2024 7:58	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-042243	Heat isn't working properly and rooms are cold
	12.2.20247.00			2. 072270	
					System pump #7 not operating
Hamilton High	11/7/2024 6:30	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-039969	
					System pump 8 not operating
Hamilton High	11/7/2024 6:26	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-039967	- -
Hamilton High	12/5/2024 8:48	MALONE	Key & Lock	Z4-043480	Door needs lock cylinder
Hamilton High	11/13/2024 7:25	MALONE	Key & Lock	Z4-040549	Door lock needs to be replaced; Teacher needs to be able to access and lock door
Hamilton High	10/4/2024 11:11	MALONE	Key & Lock	Z4-036296	Key hole cover needs to be removed from door
Hamilton High	9/20/2024 11:06	MALONE	Key & Lock	Z4-033993	Door won't lock
<u> </u>			•		

Door lock needs to be replaced/ repaired

					Door lock needs to be replaced/ repaired
Hamilton High	8/23/2024 11:34	SMITH	Key & Lock	Z4-029299	
Hamilton High	6/25/2024 12:30	SMITH	Key & Lock	Z4-019395	Respectfully request 3 AH master keys for gym.
Hamilton High	6/25/2024 9:44	SMITH	Key & Lock	Z4-019333	Respectfully request concession stand key
Hamilton High	6/25/2024 8:39	SMITH	Key & Lock	Z4-019295	Respectfully request 3 BA-1 keys or 3 keys to get in the gym from outside.
Hamilton High	5/17/2024 14:16	BURCHETT	Masonry	WO997866	First stall on left hand side has broken tile around it. Please fix. Thanks
					GANG GRAFFITI - ON THE WALLS, FLOORS & WINDOWS - CL-RM 133 & 134 (ONE LARGE
					AREA)
					P/M LONTE SMITH 416-7838
Hamilton High	11/13/2024 12:57	BURCHETT	Painting	Z4-040660	
Hamilton High	11/13/2024 7:22	BURCHETT	Painting	Z4-040546	Vandalism/ gang graffiti and profanity painted on to walls
Hamilton High	9/23/2024 7:54	BURCHETT	Painting	Z4-034110	Vandalized walls need repainting
Hamilton High	8/19/2024 10:00	BURCHETT	Painting	Z4-028358	Hallway near main office needs to be painted
Hamilton High	7/8/2024 10:20	BURCHETT	Painting	Z4-020421	Respectfully request wall painted to match room.
Hamilton High	6/12/2024 9:25	BURCHETT	Painting	Z4-018113	Respectfully request wall painted in main lobby were bulletin board was.
Hamilton High	5/17/2024 14:22	BURCHETT	Painting	WO1004569	be all in uniform. Asst principal painted over some graffiti now we have two different colors on one wall and we need the wall opposite of that painted as well. Thanks
					Wall needs to be painted that the carpenters replaced. Thanks
Hamilton High	5/17/2024 14:18	DIXON	Painting	WO1001766	
Hamilton High	12/5/2024 12:40	TEDDER	Plumbing	Z4-043629	Leak and noise coming from a piping line
Hamilton High	9/27/2024 15:43	JOHNSON	Plumbing	Z4-035246	Pipe leaking
Hamilton High	9/25/2024 7:54	JOHNSON	Plumbing	Z4-034576	Pipe structure has water in it
Hamilton High	8/9/2024 16:57	JOHNSON	Plumbing	Z4-026810	Water fountain leaking in band room
Hamilton School	6/6/2024 8:42	CALDWELL	Bleachers and Seats	Z4-017496	POCA- annual bleacher inspection is needed
					Stephenson (6178) Hamilton School Main entry door to the school will not engage (panic
					bar)
Hamilton School	12/10/2024 11:40	STAFFORD	Carpentry	Z4-044278	
Hamilton School	7/15/2024 10:50	FORD	Carpentry	Z4-021212	RM 216 window jammed won't let up
					Tile near cafe entrance need replaced
Hamilton School	7/1/2024 7:18	FORD	Carpentry	Z4-019832	
Hamilton School	12/9/2024 14:00	HALL	Electrical	Z4-044103	Lights near entryway don't come on at night
Hamilton School	8/13/2024 13:46	HALL	Electrical	Z4-027335	Kitchen needs 2 ballast near steamer
Hamilton School	6/4/2024 9:59	HALL	Electrical	Z4-017090	Pipe near water fountain in gym needs to be removed
Hamilton School	12/11/2024 10:50	CALDWELL	Elevators	Z4-044462	North side elevator doesn't call
					Elevator on south side of building won't move after floor number is assigned & Need key
					entry installed for access
Hamilton School	8/28/2024 12:50	CALDWELL	Elevators	Z4-030080	
					Fire panel error code PIV CAFE kitchen causing panel to come on
Hamilton School	7/11/2024 8:06	CALDWELL	Fire Sprinkler System	Z4-020859	
					POCA- riser room in cafe missing tamper switch cover
Hamilton School	6/6/2024 8:15	CALDWELL	Fire Sprinkler System	Z4-017485	
					POCA- need 2 sprinkler heads in RM 126
Hamilton School	6/6/2024 8:11	CALDWELL	Fire Sprinkler System	Z4-017483	
Hamilton School	6/6/2024 8:10	CALDWELL	Fire Sprinkler System	Z4-017482	POCA- PIV near Kerr street missing wrench and padlock
Hamilton School	7/3/2024 11:41	CASEY	Flooring	Z4-020202	Gym floor is missing wood pieces in several areas
Hamilton School	10/25/2024 12:34	MALONE	Key & Lock	Z4-038372	Need GMA key I have broken key in hand
Hamilton School	5/28/2024 10:01	SMITH	Key & Lock	Z4-016075	Need lock cylinder changed to SA key
Hamilton School	4/23/2024 11:55	SMITH	Key & Lock	Z4-011078	Boys locker room missing lock cylinder
Hamilton School	4/22/2024 8:39	SMITH	Key & Lock	Z4-010836	Teacher needs key to ROTC portable
Hamilton School	3/7/2024 9:47	SMITH	Key & Lock	Z4-004405	attendance office private for testing materials. Respectfully request lock changed on attendance office to privacy lock.
Hamilton School	8/19/2024 7:43	BURCHETT	Painting	Z4-028249	Classroom needs to be painted
Hamilton School	7/15/2024 7:43	BURCHETT	Painting	Z4-021126	Parking lot stripes need to be painted
Hamilton School	11/18/2024 8:15	JOHNSON	Plumbing	Z4-041191	Commode in girls restroom near RM 203 leaking from control stop
Hamilton School	10/29/2024 11:34	JOHNSON	Plumbing	Z4-038727	Boys restroom near 301 urinal continuous flush
Hamilton School	9/30/2024 12:15	JOHNSON	Plumbing	Z4-035474	PREK boys restroom near RM 104 commode leaking
Hamilton School	9/11/2024 11:31	JOHNSON	Plumbing	Z4-031997	Janitor closet near RM 104 drain clogged
Hamilton School	8/26/2024 12:32	JOHNSON	Plumbing	Z4-029602	PreK girls restroom commode near entrance needs to caulked to wall
					Need wash truck for gutter near main entrance
Hamilton School	7/11/2024 9:55	JOHNSON	Plumbing	Z4-020887	
Hanley Head Start	5/17/2024 14:27	SMITH	Key & Lock	WO1012472	nd keys for middle school 1st and 2nd floor boys and girls bathroom, students are vandalizing and smoking in the restroom.
Hanley Head Start	5/17/2024 14:19	CORONADO	Masonry	WO1002914	floor tile needs to be repaired in the kitchen near floor drain
Hanley School	11/14/2024 18:25	CALDWELL	Bleachers and Seats	Z4-040953	uest to have 1 guard rail replaced missing and 1 fixed very loose safety concerns for the students
Hanley School	10/9/2024 7:18	TEDDER	Carpentry	Z4-036683	Request to have shade replaced it is broken. You can see through window from street.

Request to have board replaced around window. It is coming apart. Safety concerns v	hen it
rains water comes through the window	

Hanley School	5/30/2024 9:14	FORD	Carpentry	Z4-016431	
Hanley School	6/17/2024 18:09	HALL	Electrical	Z4-018620	Request to have lights on stage overhead fixed Lights in back row will not come on

Magnetic doors throughout school will not stay open

001 Supervisory Aux Supply-Signal Riser Power

Strobe lights did not activate during fire drill in the main hallway by principal office

Horns did not sound on main hallway nor 2nd grade hallway

Hanley School	11/19/2024 4:22	CALDWELL	Fire Alarm System	Z4-041371	
Hanley School	12/2/2024 8:45	WILSON	Heating/Ventilation/Air Conditioning	Z4-042299	Request to have heating check the teachers lounge is very, very cool
Hanley School	12/2/2024 8:43	WILSON	Heating/Ventilation/Air Conditioning	Z4-042295	Request to have heating and air unit unit checked there is no heat coming out
Hanley School	12/2/2024 8:42	WILSON	Heating/Ventilation/Air Conditioning	Z4-042292	Heating and air unit is blowing out cold air
Hanley School	5/16/2024 9:37	SMITH	Key & Lock	Z4-014812	Request to have doors knobs replace they fall off cannot lock boiler room per fire Marshall
Hanley School	5/17/2024 14:29	SMITH	Key & Lock	WO1013052	locks on 2nd floor girls middle school bathroom doors, students are vandalizing. stall doors toilets and sinks.
Hanley School	9/13/2024 10:19	BURCHETT	Painting	Z4-032620	Request to have replaced door painted
Hanley School	5/23/2024 10:27	BURCHETT	Painting	Z4-015819	it to have office Ceiling paint, chippings scraped and painted Paint is chipped and falling from ceiling
Hanley School	5/17/2024 14:30	BURCHETT	Painting	WO1013709	Walls and doors around school needs touchup,
					Request to have nozzle replaced on faucet water will not cut off when twisting
Hanley School	12/2/2024 17:24	JOHNSON	Plumbing	Z4-042650	
Hanley School	11/19/2024 12:55	JOHNSON	Plumbing	Z4-041525	Request to have leak fixed when it rains it leaks from the ceiling, causing the ceiling tile
Hanley School	11/19/2024 4:25	JOHNSON	Plumbing	Z4-041372	Request to have nozzles fixed Water runs even when turned off
Hanley School	11/7/2024 19:49	JOHNSON	Plumbing	Z4-040212	Replace water faucet, nozzles drips water when turned off
Hanley School	10/3/2024 18:52	JOHNSON	Plumbing	Z4-036196	water fountain fixed, change filter when replace cover turned everything back on fountain is still showing red
Hanley School	10/3/2024 18:50	JOHNSON	Plumbing	Z4-036195	Request to have water fountain fixed, I have changed the filter, but the light is still red
Hanley School	9/24/2024 17:45	JOHNSON	Plumbing	Z4-034546	Request to have style one and two replace water is coming from crack toilet bowl
Hanley School	9/17/2024 19:41	JOHNSON	Plumbing	Z4-033309	equest to have pre-K bathroom toilet one and two replaced water leaks from the side of the bowl
Hanley School	8/5/2024 12:47	JOHNSON	Plumbing	Z4-025301	Request to have kitchen three compartment sink fixed. It is leaking water from the bottom.
Hanley School	8/2/2024 9:12	JOHNSON	Plumbing	Z4-024674	Request to have nozzles fixed only one fosett has running water
Hanley School	3/21/2024 19:45	TEDDER	Plumbing	Z4-005820	Request to have water, Fountain filters change they are in the red
Havenview Middle	4/16/2024 13:50	CALDWELL	Bleachers and Seats	Z4-009680	Yearly inspection
Havenview Middle	10/17/2024 12:56	ARNOLD	Carpentry	Z4-037395	The 7th stall from the entrance door needs to be repaired.
Havenview Middle	8/5/2024 8:24	ARNOLD	Carpentry	Z4-025075	Bathrooms doors need to be installed per Dr. Berry, Principal
Havenview Middle	5/15/2024 9:11	ARNOLD	Carpentry	Z4-014637	Need door replacement asap
					Sent image to Mike Hall. (S 13W CF13DS/835)
Havenview Middle	12/13/2024 13:17	HALL	Electrical	Z4-044913	
					2 lights are out and many are very dim.
Havenview Middle	11/25/2024 11:59	HALL	Electrical	Z4-042180	Need brighter lights in some areas.
Havenview Middle	11/19/2024 15:40	HALL	Electrical	Z4-041561	Carbon monoxide detector
Havenview Middle	10/28/2024 6:59	HALL	Electrical	Z4-038419	Needs ballast
Havenview Middle	10/24/2024 9:45	TEDDER	Electrical	Z4-038146	Need 3 electrical outlets for x ray machine and computer
Havenview Middle	10/24/2024 9:41	TEDDER	Electrical	Z4-038144	Need electrical drops for 24 computers
Havenview Middle	10/21/2024 10:12	HALL	Electrical	Z4-037648	Light needs ballast
Havenview Middle	10/17/2024 7:24	TEDDER	Electrical	Z4-037292	2 recess lights are blinking (need boom to change) very high, about 20ft.
					Lights do not work. Bulbs has been replaced.
Havenview Middle	4/9/2024 10:52	HALL	Electrical	Z4-008375	
Havenview Middle	2/6/2024 11:33	HALL	Electrical	Z4-000388	Repair pole lights
Havenview Middle	2/6/2024 11:29	HALL	Electrical	Z4-000385	Repair light
Havenview Middle	2/3/2024 16:13	HALL	Electrical	WO1024500	Exterior light out for rear parking lot on the upper right side of building.
Havenview Middle	12/6/2024 10:19	CALDWELL	Fire Alarm System	Z4-043796	Bps Strobes code showing
			,		RTU FOR THE C BLDG - FOR SPED CLASSES - BLOWING NOT HEATING PM/CLARK 416-
					3092
Havenview Middle	12/12/2024 12:54	WILSON	Heating/Ventilation/Air Conditioning	Z4-044734	
			<u> </u>		HEATING UNIT FOR THE MAIN HALLWAY - NOT COMING ON PM/CLARK 416-3092
Havenview Middle	12/12/2024 10:12	WILSON	Heating/Ventilation/Air Conditioning	Z4-044676	
			0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		

RTU THAT COVERS D HALLWAY B & G RR; PLNT MGR'S OFC; BREAK RM - BLOWING NOT	
HEATING PM/CLARK 416-3092	

					HEATING PM/CLARK 416-3092
Havenview Middle	12/12/2024 10:10	WILSON	Heating/Ventilation/Air Conditioning	Z4-044673	
					HEATING UNIT FOR B HALLWAY - NOT COMING ON PM/CLARK 416-3092
Havenview Middle	12/12/2024 10:07	WILSON	Heating/Ventilation/Air Conditioning	Z4-044668	
					HEATING UNIT FOR A HALLWAY - NOT COMING ON PM/CLARK 416-3092
Havenview Middle	12/12/2024 10:06	WILSON	Heating/Ventilation/Air Conditioning	Z4-044667	
					HEATING UNIT FOR RM E101 - NOT COMING ON PM/CLARK 416-3092
Havenview Middle	12/12/2024 10:05	WILSON	Heating/Ventilation/Air Conditioning	Z4-044666	
					MR. CLARK
					63092
					NO HEAT NOT BLOWING
Havenview Middle	12/5/2024 9:05	WILSON	Heating/Ventilation/Air Conditioning	Z4-043491	N. Jan.
Havenview Middle	40/0/000440-50	MALONE	V 0 1 I-	74.044000	Need 2 B keys
Havenview Middle Havenview Middle	12/9/2024 13:50 8/15/2024 8:42	SMITH	Key & Lock	Z4-044098	
			Key & Lock	Z4-027695	to be changed to regular classroom key, so teacher can use the same key to access the teacher's lounge.
Havenview Middle	10/7/2024 14:29	BURCHETT	Masonry	Z4-036532	Need tiles replaced on wall
Havenview Middle	5/8/2024 12:52	BURCHETT	Manager	Z4-013690	Need center piece replaced on urinal Bad smell coming from area.
Havenview Middle	3/27/2024 7:27	CORONADO	Masonry Masonry	Z4-013090 Z4-006506	Several glass blocks broken
Havenview Middle	5/17/2024 14:03	CORONADO	Masonry	W0994038	Boys restroom on D Hall has missing tiles
Havenview Middle	8/19/2024 9:58	BURCHETT	Painting	Z4-028357	Cinder blocks needs painting
Havenview Middle	8/14/2024 11:06	BURCHETT	Painting	Z4-020557 Z4-027505	Need painting
Havenview Fliddle	0/14/2024 11:00	DONOTIETT	raniung	24-02/303	D Hall Hallway needs painting. Preferably when school is out for the year.
Havenview Middle	5/7/2024 11:58	BURCHETT	Painting	Z4-013448	2 Haw having hoods painting hoods by monochis sacron are your
Havenview Middle	5/17/2024 14:25	BURCHETT	Painting	WO1008327	Need custodial closet painted on main hall.
Havenview Middle	5/17/2024 14:04	BURCHETT	Painting	W0994809	Need paint in lobby ceiling in front of cafeteria (Water stains)
Havenview Middle	12/2/2024 13:57	HARRIS	Plumbing	Z4-042581	Repair leak
		-			FLOOR DRAINS BACKING UP - BOYS & GIRLS RESTROOM - A HALL
					P/M CHARLES CLARK 416-3092
Havenview Middle	10/18/2024 12:37	TEDDER	Plumbing	Z4-037516	
			· ·		Lower water bottle filler needs be unclogged
Havenview Middle	8/29/2024 7:02	JOHNSON	Plumbing	Z4-030143	-
Havenview Middle	7/9/2024 11:09	TEDDER	Plumbing	Z4-020565	Leak when toilet is flushed (3rd toilet)
Havenview Middle	11/6/2024 7:01	STEVENSON	Roofing	Z4-039674	Hole in roof
Havenview Middle	11/6/2024 6:59	STEVENSON	Roofing	Z4-039670	Roof leak
Havenview Middle	10/31/2024 12:12	STEVENSON	Roofing	Z4-039109	Roof leak
Havenview Middle	10/31/2024 12:08	STEVENSON	Roofing	Z4-039106	Leak
					I have 2 rows of lights on the stage that's not coming on. I tried the breaker box.
Hawkins Mill Elementary	12/3/2024 10:17	SMITH	Electrical	Z1-042849	
					I have tiles coming in the hallway by room A1
Hawkins Mill Elementary	12/5/2024 8:44	LEWIS	Flooring	Z1-043474	
					HEATING UNIT IN PREK- A8 - NOT HEATING PM/HARRIS 416-0947
Hawkins Mill Elementary	12/3/2024 8:44	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042749	
					HEATING UNIT IN PREK- G3 - NOT HEATING PM/HARRIS 416-0947
Hawkins Mill Elementary	12/3/2024 8:43	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042748	
					ms. harris 60947 unit not heating
Hawkins Mill Elementary	12/2/2024 14:25	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042596	NO LURDIO COO (TAVO UESTE
					MS. HARRIS 60947 NO HEAT
Hawkins Mill Elementary	12/2/2024 10:58	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042453	Onfetering and applicat
Hambina Mill Flancastan	0/47/0004 40:00	14/11 14 140	Linearing of Continue (Air Constitution in a	74 000450	Cafeteria no cooling
Hawkins Mill Elementary	9/17/2024 10:22	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-033158	LIMAGUNIT FOR THE OAFE, MOT OCCURNO DAWLARDIO 440, 0044
Hawkins Mill Elementary	9/4/2024 8:05	WILLIAMS	Heating Montilation / Air Conditioning	Z1-030793	HVAC UNIT FOR THE CAFE - NOT COOLING PM/HARRIS 416-3944
Hawkins Mill Elementary	9/4/2024 8.05	WILLIAMS	Heating/Ventilation/Air Conditioning	21-030/93	HVAC UNIT IN THE KITC - NOT COOLING PM/HARRIS 416-3944
Hawkins Mill Elementary	9/4/2024 8:04	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-030792	HVAC UNIT IN THE KITC - NOT COOLING FITHARNS 410-3944
nawkiiis Mill Elementary	9/4/2024 0.04	WILLIAMS	Heating/Ventitation/Air Conditioning	21-030/92	A4 is not cooling.
Hawkins Mill Elementary	8/15/2024 10:36	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-027779	A+13 Hot cooling.
nawkiiis Mill Elementary	6/13/2024 10.30	WILLIAMS	Heating/Ventitation/Air Conditioning	21-02///9	Per Tech, A2 needs a condenser and wiring
Hawkins Mill Elementary	8/15/2024 10:34	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-027777	r or room, 72 needs a condensed and wiring
	0/10/2024 10:04	THELIANI		21 02////	Per Tech, G7 need a condenser coil.
Hawkins Mill Elementary	8/2/2024 7:26	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-024608	t of footing of mood a conduction cond
			g		Per Technician, the condenser motor needs to be replaced.
Hawkins Mill Elementary	6/26/2024 10:01	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-019504	
, , , , , , , , , , , , , , , , , , , ,					

					HVAC UNIT IN RM 3 - BLOWING NOT COOLING PM/HARRIS 416-3944
Hawkins Mill Elementary	5/20/2024 14:02	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-015277	
Hawkins Mill Elementary	5/21/2024 10:21	SMITH	Key & Lock	Z1-015435	The lock is loose. When I pull the key out, the lock comes out too.
					The lock needs to be replaced. Someone can get stuck in there if door closes all the way.
Hawkins Mill Elementary	4/30/2024 12:19	SMITH	Key & Lock	Z1-012281	The key is getting stuck when trying to lock it.
Hawkins Mill Elementary	4/23/2024 12:32	SMITH	Key & Lock	Z1-011083	
Hawkins Mill Elementary	4/18/2024 11:52	SMITH	Key & Lock	Z1-010363	I need keys made to 3 custodial closets.
		DUDOUETT.		74 004445	Per Principal, we need the lines repainted and the spots to be numbered.
Hawkins Mill Elementary Hawkins Mill Elementary	9/23/2024 8:07 2/14/2024 10:22	BURCHETT BUTLER	Painting Painting	Z1-034115 Z1-001389	Paint peeling from the ceiling
Hawkins Mill Elementary	3/28/2024 15:40	BUTLER	Painting	WO1004440	Outside in the hallway first floor across from room G6 wall needs painting
nawkins Pill Elementary	3/20/2024 13.40	BUILEN	ralliulig	WO1004440	I need four drain covers for the urinals.
Hawkins Mill Elementary	10/14/2024 10:41	Jordan	Plumbing	Z1-036828	
Handina Mill Elamantan	40/44/000440-40	landan	Discontinue	74 000007	I need one drain cover for the urinal.
Hawkins Mill Elementary	10/14/2024 10:40	Jordan	Plumbing	Z1-036827	rusted pipes on the hot water heaters needs repairing corroded.
Hawkins Mill Elementary	10/8/2024 10:44	OWENS	Plumbing	Z1-036611	rusteu pipes on the not water heaters needs repairing corroded.
Hawkins Pill Elementary	10/0/2024 10:44	OWENS	i tullibling	21-030011	I have a window that needs a shade put up.
Hawkins Mill Elementary	7/3/2024 14:23	BENTON	Shades/Blinds	Z1-020222	That of Williams and Though a Shade part api
					Ceiling is higher than 6 feet ceiling tiles changed
Hickory Ridge Elementary	7/26/2024 11:06	CROUSE	Carpentry	Z3-022896	
					TIMER FOR THE PARKING LOT - IS OFF- NEEDS TO BE RESET - HAVING AN EVENT TONIGHT
					PM/GRAGG 416-1195
Hickory Ridge Elementary	12/13/2024 12:50	SCOTT	Electrical	Z3-044907	Lights out pood you hulbs
Hielen, Didge Flementen,	12/5/2024 10:23	COOTT	Electrical	72 042550	Lights out need new bulbs
Hickory Ridge Elementary	12/5/2024 10.23	SCOTT	Electricat	Z3-043556	Has 4 lights blown making the room dark
Hickory Ridge Elementary	8/14/2024 9:47	SCOTT	Electrical	Z3-027466	rias 4 agrics blown making the room dark
,,					It 3 lights blown in there making it dark
Hickory Ridge Elementary	8/14/2024 9:44	SCOTT	Electrical	Z3-027462	
					Need 9 light bulbs replaced
Hickory Ridge Elementary	7/26/2024 11:11	SCOTT	Electrical	Z3-022905	
Hickory Ridge Elementary	6/3/2024 12:07	WHITWORTH	Electrical	Z3-016964	2 emergency lights are continuously buzzing.
HICKOTY NIUGE Elementary	0/3/2024 12.07	WHITWORTH	Electricat	23-010904	13 bulbs out
Hickory Ridge Elementary	5/30/2024 10:09	SCOTT	Electrical	Z3-016443	10 5003 000
,,					Only flashing lights no sound to indicate there is a fire
Hickory Ridge Elementary	8/19/2024 14:28	SMALL	Fire Alarm System	Z3-028455	
					POCA Need fire door tag
Hickory Ridge Elementary	5/20/2024 12:13	SMALL	Fire Alarm System	Z3-015228	DOOL COME DIGIT TO CHECK DUCT DECETED
Hickory Ridge Elementary	5/20/2024 12:11	SMALL	Fire Alarm System	Z3-015226	POCA COME BACK TO CHECK DUCT DECTER
nickory Ridge Elementary	5/20/2024 12.11	SMALL	Fire Atarin System	23-015226	POCA FIRE EXTINGUISHER OUTDATED
Hickory Ridge Elementary	5/20/2024 12:43	SMALL	Fire Extinguishers	Z3-015248	TOOM THE ENTHOUGH ENGLISHED
, ,			· ·		
					tech is here now working on the 8 but he said there 17 more that need to be fixed as well
Hickory Ridge Elementary	4/22/2024 8:54	SMALL	Fire Extinguishers	Z3-010845	
					Need 8 fire extinguishers storage boxes repaired.
Hickory Ridge Elementary	4/17/2024 13:39	SMALL	Fire Extinguishers	Z3-009968	ALLIERA NOT COOLING. AFFECTING ENTIRE MAIN OFFICE 9 OF DMC ON 10T CRADE HALL 9
					AHU#1 NOT COOLING - AFFECTING ENTIRE MAIN OFFICE & CL-RMS ON 1ST GRADE HALL & NURSES STATION
					FEEDING OFF SAME UNIT
					P/M ROBIN GRAGG 416-1195
Hickory Ridge Elementary	8/19/2024 10:26	Solutions	Heating/Ventilation/Air Conditioning	Z3-028373	
,,			<u> </u>		Pick up And install Condenser
Hickory Ridge Elementary	7/22/2024 6:38	Solutions	Heating/Ventilation/Air Conditioning	Z3-021787	
					building needs to be painted
Hickory Ridge Elementary	6/3/2024 12:05	BURCHETT	Painting	Z3-016963	
	40.00.005		- · · ·	70.0	testing of backflow preventors
Hickory Ridge Elementary	10/3/2024 12:53	WILSON	Plumbing	Z3-036131	

					water tirle teaking in office ceiting
Hickory Ridge Elementary	9/6/2024 8:33	WILSON	Plumbing	Z3-031246	
					Transport lift from Belle Forest to Hickory Ridge ES
Hickory Ridge Elementary	12/16/2024 6:46	KINARD	Welding	Z3-044959	
Hickory Ridge Middle	11/7/2024 14:11	SMITH	Audio Visual	Z3-040182	Speakers need install in the gym
Hickory Ridge Middle	9/11/2024 9:19	SMALL	Bleachers and Seats	Z3-031914	Bleachers need align
Hickory Ridge Middle	7/30/2024 10:11	SMALL	Bleachers and Seats	Z3-023705	Flooring need repairing on bleachers
Thekory Huge Fludic	770072024 10:11	OFFICE	bleachers and ocats	20 020700	Wood on bottom bleachers need repairing near entrance
Hickory Ridge Middle	7/30/2024 10:08	SMALL	Bleachers and Seats	Z3-023700	Wood on bottom bledeners need repairing near entrance
Hickory Ridge Middle	8/16/2024 10:58	CROUSE	Carpentry	Z3-023700 Z3-028104	Chall lanks need repairing
					Stall locks need repairing
Hickory Ridge Middle	7/25/2024 10:30	BARNES	Carpentry	Z3-022562	Rain coming through windows
Hickory Ridge Middle	6/20/2024 13:28	CROUSE	Carpentry	Z3-018930	Multiple seats need repairing
					on stage behind curtains in ceiling need special cut around pipe.
Hickory Ridge Middle	5/29/2024 16:27	CROUSE	Carpentry	Z3-016376	
					n106 cabinet need latch will not close shut.
Hickory Ridge Middle	5/29/2024 15:46	CROUSE	Carpentry	Z3-016361	
Hickory Ridge Middle	9/30/2024 9:42	SCOTT	Electrical	Z3-035396	Outside light need replacing
Hickory Ridge Middle	9/30/2024 9:35	SCOTT	Electrical	Z3-035393	Multiple lights need changing in high reach
Hickory Ridge Middle	9/12/2024 9:21	SCOTT	Electrical	Z3-032161	Several lights need replacing in high reach area
Hickory Ridge Middle	9/12/2024 7:31	SCOTT	Electrical	Z3-032077	Globe light bulbs need changing in lobby area
Hickory Ridge Middle	8/16/2024 9:22	SCOTT	Electrical	Z3-028019	Light fixture need repairing
Hickory Ridge Middle	7/30/2024 10:04	SCOTT	Electrical	Z3-023697	Light fixture need replacing
					Light fixture broken . Need repair
Hickory Ridge Middle	7/3/2024 15:29	SCOTT	Electrical	Z3-020249	
					100c need ballast replaced
Hickory Ridge Middle	5/31/2024 16:41	SCOTT	Electrical	Z3-016788	
Hickory Ridge Middle	9/30/2024 9:23	SMALL	Fire Alarm System	Z3-035373	Panel in trouble (Comm. Fault Heat _Kit_Sw)
, ,			•		Service Fire Alarm per Teneshia Lewis. POCA- Fire Alarm Panel Fault- all doors are not
					postive latching and the panel is in fault.
Hickory Ridge Middle	5/16/2024 13:15	SMALL	Fire Alarm System	Z3-014879	F
		CASEY	-	Z3-014673 Z3-043563	Need floor renair on Discobers
Hickory Ridge Middle	12/5/2024 10:35		Flooring		Need floor repair on Bleachers
Hickory Ridge Middle	3/28/2024 15:40	CASEY	Flooring	WO995248	Floor tile need replacing in Main office , Due to tile damage from renovation
					UNIT NOT COOLING - CL-RM N215, 2ND FLOOR
					P/M LADD 416-9337
Hickory Ridge Middle	9/6/2024 9:01	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-031269	
					UNIT NOT COOLING - CL-RM N210, 2ND FLOOR
					P/M LADD 416-9337
Hickory Ridge Middle	9/6/2024 8:59	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-031263	
, ,			0		HVAC UNIT IN RM S216 - NOT COOLING PM/LADD 416-9337
Hickory Ridge Middle	8/1/2024 7:43	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-024220	
Thickory Huge Phadie	0/1/2024 / .43	TIVEAGIT	rieating ventilation/All Conditioning	25-024220	HVAC UNIT IN RM N216 - NOT COOLING PM/LADD 416-9337
Life Issue Did as Middle	0/4/00047-40	EN/EAGLI	Handing Of and Hading (Air One diding in a	70.004040	NVAC UNIT IN KM N210 - NOT COOLING PM/LADD 410-933/
Hickory Ridge Middle	8/1/2024 7:42	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-024219	
					HVAC UNIT IN RM N208 - NOT COOLING PM/LADD 416-9337
Hickory Ridge Middle	8/1/2024 7:42	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-024217	
					HVAC UNIT ON THE 1ST FLR - RM N114 - NOT COOLING PM/LADD 416-9337
Hickory Ridge Middle	7/30/2024 9:59	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-023692	
					HVAC UNIT ON THE 2ND FLR - RM N215 - NOT COOLING PM/LADD 416-9337
Hickory Ridge Middle	7/30/2024 9:57	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-023691	
, ,			0		HVAC UNIT ON THE 2ND FLR - RM N214 - NOT COOLING PM/LADD 416-9337
Hickory Ridge Middle	7/30/2024 9:57	FIVEASH	Heating/Ventilation/Air Conditioning	73-023690	
HICKOTY Nidge Middle	7/30/2024 9.37	FIVEASH	Heating/Ventitation/All Conditioning	23-023090	HVAC UNIT ON THE 2ND FLR - RM N212 - NOT COOLING PM/LADD 416-9337
Life Issue Didge Middle	7/00/00040-50	EN/EACH	I I Ai Ai	70 000000	HVAC UNIT ON THE 2ND FER - NOT N212 - NOT COOLING FIT/LADD 410-933/
Hickory Ridge Middle	7/30/2024 9:56	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-023689	
					HVAC UNIT ON THE 2ND FLR - RM N211 - NOT COOLING PM/LADD 416-9337
Hickory Ridge Middle	7/30/2024 9:56	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-023686	
					HVAC UNIT ON THE 2ND FLR - RM N209 - NOT COOLING PM/LADD 416-9337
Hickory Ridge Middle	7/30/2024 9:55	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-023684	
					MASTER KEY STUCK IN DOOR - CL-RM N107
					P/M LADD 416-9337
Hickory Ridge Middle	10/30/2024 13:46	MALONE	Key & Lock	Z3-038960	
Hickory Ridge Middle	10/14/2024 8:19	MALONE	Key & Lock	Z3-036960 Z3-036785	Main office
, ,					
Hickory Ridge Middle	7/15/2024 11:47	SMITH	Key & Lock	Z3-021226	I need duplicate key for 117 B
Hickory Ridge Middle	9/23/2024 8:39	DIXON	Painting	Z3-034130	Need painting . Rust coming off on staff hands when touching
Hickory Ridge Middle	6/27/2024 11:01	BURCHETT	Painting	Z3-019653	Office need painting
Hickory Ridge Middle	6/20/2024 10:31	BURCHETT	Painting	Z3-018905	Outside entrance doors need painting

water line leaking in office ceiling

					c200 need pointing
Hickory Ridge Middle	5/31/2024 16:23	BURCHETT	Painting	Z3-016784	s209 need painting
,					106e need painting
Hickory Ridge Middle	5/31/2024 16:15	BURCHETT	Painting	Z3-016783	
					n214 classroom need painting
Hickory Ridge Middle	5/31/2024 16:13	BURCHETT	Painting	Z3-016782	
					n215 classroom need painting
Hickory Ridge Middle	5/31/2024 16:11	BURCHETT	Painting	Z3-016781	
Hickory Ridge Middle	5/31/2024 16:10	BURCHETT	Painting	Z3-016780	n213 classroom needs painting
nickory Riuge Middle	5/51/2024 10.10	BUNCHETT	ralliulig	23-010/00	office 100h need painting and wall repair.
Hickory Ridge Middle	5/31/2024 15:19	BURCHETT	Painting	Z3-016777	omoo 2001 nood pantang and nata opani
, , ,					n205 bathrooms need painting
Hickory Ridge Middle	5/30/2024 15:47	BURCHETT	Painting	Z3-016591	
					n210 classroom need painting
Hickory Ridge Middle	5/30/2024 15:38	BURCHETT	Painting	Z3-016586	
	E 100 1000 1 1 E 0 1			70.040500	s213 classroom needs painting
Hickory Ridge Middle	5/30/2024 15:24	BURCHETT	Painting	Z3-016582	n206 classroom needs painting
Hickory Ridge Middle	5/30/2024 14:20	BURCHETT	Painting	Z3-016559	11200 Classiconi needs painting
Thekery Huge Findic	0/00/2024 14.20	BONOTIETT	ramang	20 010000	s115 classroom need painting.
Hickory Ridge Middle	5/30/2024 14:02	BURCHETT	Painting	Z3-016552	
, ,			· ·		n109 classroom need painting.
Hickory Ridge Middle	5/30/2024 13:47	BURCHETT	Painting	Z3-016547	
					n111 classroom need painting
Hickory Ridge Middle	5/30/2024 13:45	BURCHETT	Painting	Z3-016546	
History Didge Middle	F (00 (000 4 40 40	PUROUETT	Deletions	70.040540	s111 classroom need painting
Hickory Ridge Middle Hickory Ridge Middle	5/30/2024 13:42 2/3/2024 16:44	BURCHETT BURCHETT	Painting Painting	Z3-016543 WO1021252	Classroom 113 walls need painting, Due to renovations
Hickory Ridge Middle	3/28/2024 15:40	BURCHETT	Painting	WO1021232 WO998846	Restrooms need painting, Due to removations
	7/30/2024 10:10	HATCH	_	Z3-023702	
Hickory Ridge Middle			Sheet Metal		End of Bleachers near entrance need safety guard rail, safety hazard
Highland Oaks Elementary	12/12/2024 11:54	CROUSE	Carpentry	Z3-044716	Handle is broken want lock
Highland Oaks Elementary	12/2/2024 10:15	SCOTT	Electrical	Z3-042394	Have 4pole lights not working
					Please disconnect power to the electric water heater so it can be replaced by plumbers
Highland Oaks Elementary	8/8/2024 14:15	SCOTT	Electrical	Z3-026478	rease disconnect power to the electric water heater so it can be replaced by plumbers
riiginaria oano Etomoniary	0.0,202-11-110	000	Elocurous	20 020 770	
					We have 5 troubles on panel alarm going off every few seconds. Duct detectors abnormal
Highland Oaks Elementary	7/1/2024 7:24	SMALL	Fire Alarm System	Z3-019839	
Highland Oaks Elementary	5/17/2024 13:37	CHASE	Flooring	WO972969	The Kitchen Manager needs her carpet removed in her office and tiled
Highland Oaks Elementary	3/28/2024 15:40	CHASE	Flooring	WO972964	
Highland Oaks Elementary	12/13/2024 12:57	BRYSON	Heating/Ventilation/Air Conditioning		
Highland Oaks Elementary					Main Office Area Has a small area of carpet that needs to be remove and tiled No heat
Highland Oaks Elementary	10/25/2024 9:21	SCOTT		Z3-044909	No heat
	10/25/2024 9:21 9/12/2024 11:50	SCOTT BURCHETT	Heating/Ventilation/Air Conditioning	Z3-044909 Z3-038321	No heat Unit blowing hot air
riightand Oaks Elementary	9/12/2024 11:50	SCOTT BURCHETT		Z3-044909	No heat
Highland Oaks Elementary			Heating/Ventilation/Air Conditioning	Z3-044909 Z3-038321	No heat Unit blowing hot air Floor repair
	9/12/2024 11:50	BURCHETT	Heating/Ventilation/Air Conditioning Masonry	Z3-044909 Z3-038321 Z3-032268	No heat Unit blowing hot air Floor repair
Highland Oaks Elementary	9/12/2024 11:50 10/3/2024 12:54	BURCHETT	Heating/Ventilation/Air Conditioning Masonry Plumbing	Z3-044909 Z3-038321 Z3-032268 Z3-036135	No heat Unit blowing hot air Floor repair testing of backflow preventors
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28	BURCHETT WILSON TOLES WARREN	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/1/2024 11:15	BURCHETT WILSON TOLES WARREN TOLES	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Plumbing	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422 Z3-024412	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28	BURCHETT WILSON TOLES WARREN	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater Please repair lights in Gym two lights are out over the bleachers both sides
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Middle	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/1/2024 11:15 12/10/2024 7:12	BURCHETT WILSON TOLES WARREN TOLES SCOTT	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Plumbing Plumbing Electrical	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422 Z3-024412 Z3-044149	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Middle Highland Oaks Middle	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/1/2024 11:15 12/10/2024 7:12 12/9/2024 14:13	BURCHETT WILSON TOLES WARREN TOLES SCOTT CHALK	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Plumbing Electrical	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422 Z3-024412 Z3-044107	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater Please repair lights in Gym two lights are out over the bleachers both sides Repuil 480 volt feeders to 400 hall
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Middle	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/1/2024 11:15 12/10/2024 7:12	BURCHETT WILSON TOLES WARREN TOLES SCOTT	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Plumbing Plumbing Electrical	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422 Z3-024412 Z3-044149	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater Please repair lights in Gym two lights are out over the bleachers both sides Repull 480 volt feeders to 400 hall Please repair the water cooler in the gym looks like there is no power to them
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Middle Highland Oaks Middle	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/1/2024 11:15 12/10/2024 7:12 12/9/2024 14:13	BURCHETT WILSON TOLES WARREN TOLES SCOTT CHALK	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Plumbing Electrical	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422 Z3-024412 Z3-044107	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater Please repair lights in Gym two lights are out over the bleachers both sides Repull 480 volt feeders to 400 hall Please repair the water cooler in the gym looks like there is no power to them poca please repair the #3 exits sign at the Exits door end of 300 hallway and the #1 exits
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Middle Highland Oaks Middle Highland Oaks Middle	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/1/2024 11:15 12/10/2024 7:12 12/9/2024 14:13 12/4/2024 13:34	BURCHETT WILSON TOLES WARREN TOLES SCOTT CHALK SCOTT	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Plumbing Electrical Electrical	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422 Z3-024412 Z3-044149 Z3-044107 Z3-044387	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater Please repair lights in Gym two lights are out over the bleachers both sides Repull 480 volt feeders to 400 hall Please repair the water cooler in the gym looks like there is no power to them
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Middle Highland Oaks Middle Highland Oaks Middle	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/1/2024 11:15 12/10/2024 7:12 12/9/2024 14:13 12/4/2024 13:34	BURCHETT WILSON TOLES WARREN TOLES SCOTT CHALK SCOTT	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Plumbing Electrical Electrical Electrical	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422 Z3-024412 Z3-044107 Z3-04387 Z3-038636	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater Please repair lights in Gym two lights are out over the bleachers both sides Repull 480 volt feeders to 400 hall Please repair the water cooler in the gym looks like there is no power to them poca please repair the #3 exits sign at the Exits door end of 300 hallway and the #1 exits sign at the entrance and eixts doors to the 300 and 400 hallway.
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Middle Highland Oaks Middle Highland Oaks Middle Highland Oaks Middle	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/1/2024 11:15 12/10/2024 7:12 12/9/2024 14:13 12/4/2024 13:34 10/29/2024 8:11 10/9/2024 6:48	BURCHETT WILSON TOLES WARREN TOLES SCOTT CHALK SCOTT SCOTT SCOTT	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Electrical Electrical Electrical Electrical	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422 Z3-024412 Z3-044107 Z3-04387 Z3-038636 Z3-036679	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater Please repair lights in Gym two lights are out over the bleachers both sides Repull 480 volt feeders to 400 hall Please repair the water cooler in the gym looks like there is no power to them poca please repair the #3 exits sign at the Exits door end of 300 hallway and the #1 exits sign at the entrance and eixts doors to the 300 and 400 hallway. Please repair the wall unit near room 108
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Middle	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/1/2024 11:15 12/10/2024 7:12 12/9/2024 14:13 12/4/2024 13:34 10/29/2024 8:11 10/9/2024 6:48 10/8/2024 15:26	BURCHETT WILSON TOLES WARREN TOLES SCOTT CHALK SCOTT SCOTT SCOTT SCOTT	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422 Z3-024412 Z3-044107 Z3-04387 Z3-036656 Z3-036659 Z3-036656	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater Please repair lights in Gym two lights are out over the bleachers both sides Repull 480 volt feeders to 400 hall Please repair the water cooler in the gym looks like there is no power to them poca please repair the #3 exits sign at the Exits door end of 300 hallway and the #1 exits sign at the entrance and eixts doors to the 300 and 400 hallway. Please repair the wall unit near room 108 Please repair the wall unit at front entrance.
Highland Oaks Elementary Highland Oaks Middle	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/1/2024 11:15 12/10/2024 7:12 12/9/2024 14:13 12/4/2024 13:34 10/29/2024 6:48 10/8/2024 15:26 10/8/2024 15:26	BURCHETT WILSON TOLES WARREN TOLES SCOTT CHALK SCOTT SCOTT SCOTT SCOTT SCOTT	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422 Z3-024412 Z3-044107 Z3-043387 Z3-0366679 Z3-036656 Z3-036655	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater Please repair lights in Gym two lights are out over the bleachers both sides Repull 480 volt feeders to 400 hall Please repair the water cooler in the gym looks like there is no power to them poca please repair the #3 exits sign at the Exits door end of 300 hallway and the #1 exits sign at the entrance and eixts doors to the 300 and 400 hallway. Please repair the wall unit near room 108 Please repair the wall unit at front entrance. Please repair the outside wall unit by room 104.
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Middle	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/1/2024 11:15 12/10/2024 7:12 12/9/2024 14:13 12/4/2024 13:34 10/29/2024 8:11 10/9/2024 6:48 10/8/2024 15:26 10/8/2024 15:23 8/16/2024 6:12	BURCHETT WILSON TOLES WARREN TOLES SCOTT CHALK SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z3-044909 Z3-038321 Z3-032268 Z3-035954 Z3-030422 Z3-024412 Z3-044149 Z3-044107 Z3-04387 Z3-036636 Z3-036659 Z3-036655 Z3-027947	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater Please repair lights in Gym two lights are out over the bleachers both sides Repull 480 volt feeders to 400 hall Please repair the water cooler in the gym looks like there is no power to them poca please repair the #3 exits sign at the Exits door end of 300 hallway and the #1 exits sign at the entrance and eixts doors to the 300 and 400 hallway. Please repair the wall unit near room 108 Please repair the wall unit at front entrance. Please repair the outside wall unit by room 104. Please repair exits light #20
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Middle	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/1/2024 11:15 12/10/2024 7:12 12/9/2024 14:13 12/4/2024 13:34 10/29/2024 8:11 10/9/2024 6:48 10/8/2024 15:26 10/8/2024 6:12 8/13/2024 7:08	BURCHETT WILSON TOLES WARREN TOLES SCOTT CHALK SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Electrical	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422 Z3-024412 Z3-044107 Z3-04387 Z3-036656 Z3-036656 Z3-036656 Z3-036656 Z3-027947 Z3-027144	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater Please repair lights in Gym two lights are out over the bleachers both sides Repull 480 volt feeders to 400 hall Please repair the water cooler in the gym looks like there is no power to them poca please repair the #3 exits sign at the Exits door end of 300 hallway and the #1 exits sign at the entrance and eixts doors to the 300 and 400 hallway. Please repair the wall unit near room 108 Please repair the wall unit at front entrance. Please repair the vall unit by room 104. Please repair exits light #20 Please repair the light in the boys restroom 300 hallway
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Middle	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/11/2024 11:15 12/10/2024 7:12 12/9/2024 14:13 12/4/2024 13:34 10/29/2024 8:11 10/9/2024 6:48 10/8/2024 15:26 10/8/2024 15:23 8/16/2024 6:12 8/13/2024 7:08 7/3/2024 9:26	BURCHETT WILSON TOLES WARREN TOLES SCOTT CHALK SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Electrical Electrical Electrical	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422 Z3-024412 Z3-044107 Z3-04387 Z3-036656 Z3-036656 Z3-036656 Z3-027947 Z3-027947 Z3-020155	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater Please repair lights in Gym two lights are out over the bleachers both sides Repull 480 volt feeders to 400 hall Please repair the water cooler in the gym looks like there is no power to them poca please repair the #3 exits sign at the Exits door end of 300 hallway and the #1 exits sign at the entrance and eixts doors to the 300 and 400 hallway. Please repair the wall unit near room 108 Please repair the wall unit at front entrance. Please repair the utside wall unit by room 104. Please repair the light in the boys restroom 300 hallway Please end wall receptacle cover for room 112.
Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Elementary Highland Oaks Middle	9/12/2024 11:50 10/3/2024 12:54 10/2/2024 14:33 8/30/2024 8:28 8/1/2024 11:15 12/10/2024 7:12 12/9/2024 14:13 12/4/2024 13:34 10/29/2024 8:11 10/9/2024 6:48 10/8/2024 15:26 10/8/2024 6:12 8/13/2024 7:08	BURCHETT WILSON TOLES WARREN TOLES SCOTT CHALK SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT	Heating/Ventilation/Air Conditioning Masonry Plumbing Plumbing Plumbing Electrical	Z3-044909 Z3-038321 Z3-032268 Z3-036135 Z3-035954 Z3-030422 Z3-024412 Z3-044107 Z3-04387 Z3-036656 Z3-036656 Z3-036656 Z3-036656 Z3-027947 Z3-027144	No heat Unit blowing hot air Floor repair testing of backflow preventors The hot water tank has to be reset every day Water spigot is leaking Is leaking real bad Hot Water Heater Please repair lights in Gym two lights are out over the bleachers both sides Repull 480 volt feeders to 400 hall Please repair the water cooler in the gym looks like there is no power to them poca please repair the #3 exits sign at the Exits door end of 300 hallway and the #1 exits sign at the entrance and eixts doors to the 300 and 400 hallway. Please repair the wall unit near room 108 Please repair the wall unit at front entrance. Please repair the vall unit by room 104. Please repair exits light #20 Please repair the light in the boys restroom 300 hallway

Highland Oaks Middle Highland Oaks Middle	5/3/2024 8:10 4/1/2024 7:11	SCOTT SCOTT	Electrical Electrical	Z3-012911 Z3-006866	Please repair the light fixture in the 300 hallway boys restroom. Please repair wall pack light fixture by room 104 it is blinking
Highland Oaks Middle	40/00/00047-40	OMALI	Fire Fedinatelehara	70 000005	poca please update fire extinguishers tag, Gym elerical room.
Highland Oaks Middle	10/29/2024 7:48	SMALL	Fire Extinguishers	Z3-038625	Please repair the gate valve leaking by Riser room
Highland Oaks Middle	10/28/2024 10:52	SMALL	Fire Sprinkler System	Z3-038522	
Highland Oaks Middle	11/22/2024 14:00	CASEY	Flooring	Z3-042101	Please resurface the stage floor
Highland Oaks Middle	10/4/2024 15:12	CASEY	Flooring	Z3-036348	Please resurface(shellac)gym floor
Highland Oaks Middle	12/16/2024 7:28		Heating/Ventilation/Air Conditioning		lease check and repair the thermostat in all but two classrooms 400 hallway and in room 300. Mr vernardo
					60340
					unit not communicating with energy management
Highland Oaks Middle	12/13/2024 9:40	BRYSON	Heating/Ventilation/Air Conditioning	Z3-044864	
Highland Oaks Middle	11/6/2024 11:42	MALONE	Key & Lock	Z3-039871	ter key the Gym entrance door, coaches office, storage room next to coaches office and basketball storage room.
Highland Oaks Middle	10/30/2024 14:12	MALONE	Key & Lock	Z3-038963	Please repair the hall door entrance to main office, hallway entrance door catch needs work.
Highland Oaks Middle	5/31/2024 8:08	BURCHETT	Painting	Z3-016636	Please fill in the hole in the wall and paint the wall in room 510
Highland Oaks Middle	5/29/2024 9:31	BURCHETT	Painting	Z3-016259	all in room 110., looks like someone used liquid nail on the walls and cannot be removed by conventional ways.
Highland Oaks Middle	4/17/2024 7:33	BURCHETT	Painting	Z3-009760	Please repaint all the school hallway and restrooms
Highland Oaks Middle	4/1/2024 9:50	BURCHETT	Painting	Z3-006965	Please repaint the lines for parking spaces front entrance and teacher parking lot
Highland Oaks Middle	4/1/2024 9:45	BURCHETT	Painting	Z3-006962	Please paint the fire lane curve and stencil the fire lane drive.
Highland Oaks Middle	12/16/2024 8:29	WARREN	Plumbing	Z3-044978	Please repair the second and last stall toilets.
Highland Oaks Middle	12/10/2024 11:57	WARREN	Plumbing	Z3-044282	se check and repair the hot water tank, replacing or repair water outlet pipe and check relief valve.
Highland Oaks Middle	12/4/2024 7:51	WARREN	Plumbing	Z3-043115	ise repair the handicap stall girls restroom 200 hallway it's leaking around the base of the fill pipe
Highland Oaks Middle	10/28/2024 6:23	BARNES	Plumbing	Z3-038413	Please repair the water cooler on the right side when facing the restroom it is leaking.
9			· ·		testing of the backflow preventors*(4 Devices at this location)
Highland Oaks Middle	10/3/2024 13:04	WILSON	Plumbing	Z3-036140	
					repair 1-289u 1/4 relief valve
Highland Oaks Middle	9/10/2024 12:25	WILSON	Plumbing	Z3-031775	·
Highland Oaks Middle	11/13/2024 7:25	BUFORD	Roofing	Z3-040548	Please repair the leak in room 212 in the corner by the teacher desk.
riigitana oaks riidate	11/10/2024 / .20	DOI OND	riconing	20 040040	Room 129 has water seeping through the floor
Holmes Road Elementary	10/31/2024 10:32	TEDDER	Carpentry	Z4-039070	noom 129 has water seeping through the noor
Houries Hoad Elementary	10/31/2024 10.32	TEDDEN	Carpentry	24-033070	Can I have all cubbies removed from B HALLWAY CLASSROOMS
Holmes Road Elementary	10/24/2024 7:25	SMITH	Carpentry	Z4-038094	Call Have all Cubbles removed from D HALLWAY CLASSINOOPIS
Hottiles Road Elementary	10/24/2024 /.25	SHIIII	Carpentry	24-030094	Fine clayer in appetantly triggered it ages LOOD 1 CADD FAULT
Holmes Road Elementary	12/2/2024 7:41	CALDWELL	Fire Alarm System	Z4-042229	Fire alarm is constantly triggered it says LOOP 1 CARD FAULT
Hollies Road Elementary	12/2/2024 /.41	CALDWELL	Fire Alarm System	24-042229	Carialdes In Missing Ding Inside Multinumpeer seem
Halman Band Flammatan	44/40/00047-04	OAL DWELL	Fire Ornigldon Contact	74.044470	Sprinkler Is Missing Ring Inside Multipurpose room
Holmes Road Elementary	11/18/2024 7:21	CALDWELL	Fire Sprinkler System	Z4-041173	Fig. 16 denotes to be designed as a second to a billion of the second
Halman Band Flammatan	40/44/000444-00	OAL DWELL	Fire Ornigldon Contact	74 000000	Fire Hydrant is leaking water near the chillerValve is broken
Holmes Road Elementary	10/14/2024 14:00	CALDWELL	Fire Sprinkler System	Z4-036899	WITTHEFT VETTILE OF THE PARTY.
					UNIT NOT HEATING - CL-RM B101
					P/M DONTARIO HARRIS 416-2530
Holmes Road Elementary	12/12/2024 8:48	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-044572	
					Mr Harris (416 2530) Holmes Road ES RmB100 Heat isn`t coming on at all
Holmes Road Elementary	12/6/2024 10:26	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-043799	
					Mr Harris (416 2530) Holmes Road ES RmB101 Heat isn't coming on at all
Holmes Road Elementary	12/6/2024 8:59	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-043753	
					Mr Harris (416 2530) Holmes Road ES rm128 Heat isn`t coming on at all
Holmes Road Elementary	12/6/2024 8:57	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-043751	
					Mr Harris (416 2530) Holmes Road ES rm124 Heat isn`t coming on at all
Holmes Road Elementary	12/6/2024 8:56	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-043750	
					Mr Harris (416 2530) Holmes Road ES rm138 Heat isn`t coming on at all
Holmes Road Elementary	12/6/2024 8:55	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-043749	
					Mr Harris (416 2530) Holmes RoadD ES rmB101 Heat isn`t coming on at all
Holmes Road Elementary	12/6/2024 8:54	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-043746	
					Chill Water Pumps 6 and 7 are not Operating
Holmes Road Elementary	8/16/2024 11:48	Mechanical Solutions	Heating/Ventilation/Air Conditioning	Z4-028131	
,			0		Need lock cylinder replace in room 124 storage key has issues turning.
Holmes Road Elementary	10/15/2024 11:57	MALONE	Key & Lock	Z4-037062	
			, 2.2001		ROOM 145 Needs to be RE-KEYED
Holmes Road Elementary	10/3/2024 14:22	MALONE	Key & Lock	Z4-036170	TOOT I INDICATE TO THE TELED
ouncs nous Elementary	10/0/2024 14.22	INCOME	NOy & LUCK	2- 0001/0	Finacial Secretary Office Needs To Be RE-KEYED
Holmes Road Elementary	10/3/2024 14:21	MALONE	Key & Lock	Z4-036169	Timucial occidenty office recess to be NETRETED
nounes noau Elementary	10/3/2024 14.21	MALUNE	Ney & LUCK	24-030109	Principle Office needs to be RE-KEYED
Holmes Road Elementary	10/3/2024 14:20	MALONE	Key & Lock	Z4-036167	I fillelipte office freeds to be fitRETED
nomics noau Elementary	10/3/2024 14.20	PIALUNE	NEY & LUCK	24-03010/	

I have two doors inside pre-k 124 the lock cylinder is broken and will take any key at this time

Holmes Road Elementary	10/1/2024 11:42	MALONE	Key & Lock	Z4-035722	diffe
riotines rioda Eternemary	10/1/2024 11.42	TIALONE	Key a Lock	24 000/22	Room 143 Needs Painting
Holmes Road Elementary	6/12/2024 10:52	BURCHETT	Painting	Z4-018149	
riotines rioda Eternemary	0/12/2024 10:02	DOMONETT	runing	24 010140	Can entire parking lot be painted
Holmes Road Elementary	5/30/2024 8:21	BURCHETT	Painting	Z4-016416	our state parting to so painted
riotines rioda Eternemary	0/00/2024 0.21	DOMONETT	runing	24 010410	If possible can Holmes Rd Elementary School be painted on the inside of the building all
					way around
Holmes Road Elementary	5/30/2024 8:19	BURCHETT	Painting	Z4-016415	way around
Hounes Hour Eternemary	0/00/2024 0.10	DOMONETT	runing	24 010410	I have a toilet that will not flush after pulling the handle multiple times. I have closed the
					stall off to prevent students from using.
Holmes Road Elementary	12/11/2024 13:25	HARRIS	Plumbing	Z4-044488	Statt on to prevent students norm using.
Hounes Hoad Elementary	12/11/2024 15:25	TIANNIS	rtumbing	24-044400	MR. HARRIS
					62530
					PIPE BURSTED ON OUTSIDE OF CHILLER ROOM
Holmes Road Elementary	12/6/2024 9:55	TEDDER	Plumbing	Z4-043783	THE BONSTED ON OUTSIDE OF CHILLERTHOOF
Holmes Road Elementary	11/8/2024 13:45	HARRIS	Plumbing		Toilet in classroom leaks from the bottom of unit unable to controlmold forming on wall area
Hottiles Road Eterilentary	11/0/2024 13.43	HANNIS	Fluilibilig	24-040311	
Halmas Daad Flamenton	10/24/2024 15:02	LIADDIC	Dlumbing	74 020250	sink constantly leaks in PRE-K 131
Holmes Road Elementary	10/24/2024 15:02	HARRIS	Plumbing	Z4-038256	annual teating of 2 healflour
Halman Band Flamman	10/3/2024 13:50	MIII CON	Diversión	Z4-036154	annual testing of 2- backflows
Holmes Road Elementary	10/3/2024 13:50	WILSON	Plumbing	24-036154	
					RM 143 asst principal's office women's bathroom leaks while flushing
Holmes Road Elementary	6/17/2024 8:13	HARRIS	Plumbing	Z4-018477	
5 .5	= 10.0 10.0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		D	7	sink constantly running inside room 124PreK handles are both in the off position
Holmes Road Elementary	5/30/2024 8:26	HARRIS	Plumbing	Z4-016418	THE PROPERTY OF THE PROPERTY O
Humes Middle School	12/13/2024 13:04	SINK	Plumbing	Z1-044911	HUMES MIDDLE SCHOOL. Turn off water and gas to property.
					Repair Door & Frame.
Ida B. Wells Academy	10/8/2024 14:03	ARNOLD	Carpentry	Z1-036647	
					POCA ALL fire and smoke doors have poitsive lactching automatic closures
Ida B. Wells Academy	4/2/2024 9:17	STEPHENS	Carpentry	Z1-007233	
					POCA THE boiler room door needs a panic bar on it
lda B. Wells Academy	3/27/2024 14:09		Carpet Repair	Z1-006663	
					the boiler room door needs a panic door lock on it
lda B. Wells Academy	3/27/2024 12:08		Carpet Repair	Z1-006624	
					lights are out on the parking lot very dark
lda B. Wells Academy	12/10/2024 9:55	CHALK	Electrical	Z1-044236	
					Outside lights at Ida B Wells need replaced currently very dim lighting
lda B. Wells Academy	9/12/2024 10:46	CHALK	Electrical	Z1-032232	
					Light needs ballast
lda B. Wells Academy	8/21/2024 15:05	ANDREWS	Electrical		
				Z1-028975	
				21-0289/5	the exhaust fan in the restroom, 2nd floor.
Ida B. Wells Academy	3/11/2024 11:22	ANDREWS	Electrical	Z1-028975 Z1-004805	the exhaust fan in the restroom, 2nd floor.
lda B. Wells Academy	3/11/2024 11:22	ANDREWS	Electrical		the exhaust fan in the restroom, 2nd floor. the boys exhaust has went out on the first floor by room 114
Ida B. Wells Academy Ida B. Wells Academy	3/11/2024 11:22 3/8/2024 13:40	ANDREWS	Electrical Electrical		
				Z1-004805	
				Z1-004805	the boys exhaust has went out on the first floor by room 114
Ida B. Wells Academy	3/8/2024 13:40	ANDREWS	Electrical	Z1-004805 Z1-004699	the boys exhaust has went out on the first floor by room 114
Ida B. Wells Academy	3/8/2024 13:40	ANDREWS	Electrical	Z1-004805 Z1-004699	the boys exhaust has went out on the first floor by room 114
Ida B. Wells Academy	3/8/2024 13:40	ANDREWS	Electrical	Z1-004805 Z1-004699	the boys exhaust has went out on the first floor by room 114 the girls exhaust has went out on the first floor by room 116
Ida B. Wells Academy	3/8/2024 13:40 3/8/2024 13:35	ANDREWS	Electrical Electrical	Z1-004805 Z1-004699 Z1-004698	the boys exhaust has went out on the first floor by room 114 the girls exhaust has went out on the first floor by room 116
Ida B. Wells Academy	3/8/2024 13:40 3/8/2024 13:35	ANDREWS	Electrical Electrical	Z1-004805 Z1-004699 Z1-004698	the boys exhaust has went out on the first floor by room 114 the girls exhaust has went out on the first floor by room 116 IN room 108 its to set of lights out in that room needs balance in them never been fixed
Ida B. Wells Academy Ida B. Wells Academy Ida B. Wells Academy	3/8/2024 13:40 3/8/2024 13:35 2/28/2024 9:27	ANDREWS ANDREWS	Electrical Electrical	Z1-004805 Z1-004699 Z1-004698 Z1-003197	the boys exhaust has went out on the first floor by room 114 the girls exhaust has went out on the first floor by room 116 IN room 108 its to set of lights out in that room needs balance in them never been fixed
Ida B. Wells Academy Ida B. Wells Academy Ida B. Wells Academy Ida B. Wells Academy	3/8/2024 13:40 3/8/2024 13:35 2/28/2024 9:27 2/19/2024 7:31	ANDREWS ANDREWS ANDREWS CHALK	Electrical Electrical Electrical Electrical	Z1-004805 Z1-004699 Z1-004698 Z1-003197 Z1-001815	the boys exhaust has went out on the first floor by room 114 the girls exhaust has went out on the first floor by room 116 IN room 108 its to set of lights out in that room needs balance in them never been fixed those 7 lights in the courtyard the sockets needs to replaced
Ida B. Wells Academy	3/8/2024 13:40 3/8/2024 13:35 2/28/2024 9:27 2/19/2024 7:31 2/3/2024 14:50	ANDREWS ANDREWS ANDREWS CHALK CHALK	Electrical Electrical Electrical Electrical Electrical	Z1-004805 Z1-004699 Z1-004698 Z1-003197 Z1-001815 W01029934	the boys exhaust has went out on the first floor by room 114 the girls exhaust has went out on the first floor by room 116 IN room 108 its to set of lights out in that room needs balance in them never been fixed those 7 lights in the courtyard the sockets needs to replaced there are 7 out out side in the middle of the landing out side the parking lot been out for ever
Ida B. Wells Academy	3/8/2024 13:40 3/8/2024 13:35 2/28/2024 9:27 2/19/2024 7:31 2/3/2024 14:50 2/3/2024 14:49	ANDREWS ANDREWS ANDREWS CHALK CHALK CHALK	Electrical Electrical Electrical Electrical Electrical Electrical	Z1-004805 Z1-004699 Z1-004698 Z1-003197 Z1-001815 W01029934 W01029940	the boys exhaust has went out on the first floor by room 114 the girls exhaust has went out on the first floor by room 116 IN room 108 its to set of lights out in that room needs balance in them never been fixed those 7 lights in the courtyard the sockets needs to replaced there are 7 out out side in the middle of the landing out side the parking lot been out for ever ITS ONE BIG LIGHT OUT IN THE COURTYARD NEEDS TO BE REPLACED
Ida B. Wells Academy	3/8/2024 13:40 3/8/2024 13:35 2/28/2024 9:27 2/19/2024 7:31 2/3/2024 14:50 2/3/2024 14:49 2/3/2024 15:49	ANDREWS ANDREWS CHALK CHALK CHALK CHALK	Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z1-004805 Z1-004699 Z1-004698 Z1-003197 Z1-001815 W01029934 W01029940 W01026383 W01025946	the boys exhaust has went out on the first floor by room 114 the girls exhaust has went out on the first floor by room 116 IN room 108 its to set of lights out in that room needs balance in them never been fixed those 7 lights in the courtyard the sockets needs to replaced there are 7 out out side in the middle of the landing out side the parking lot been out for ever ITS ONE BIG LIGHT OUT IN THE COURTYARD NEEDS TO BE REPLACED there are lights out out side the cafeteria out side needs to be replaced
Ida B. Wells Academy	3/8/2024 13:40 3/8/2024 13:35 2/28/2024 9:27 2/19/2024 7:31 2/3/2024 14:50 2/3/2024 14:49 2/3/2024 15:50	ANDREWS ANDREWS CHALK CHALK CHALK CHALK CHALK CHALK CHALK	Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z1-004805 Z1-004699 Z1-004698 Z1-003197 Z1-001815 W01029934 W01029940 W01026383 W01025946	the boys exhaust has went out on the first floor by room 114 the girls exhaust has went out on the first floor by room 116 IN room 108 its to set of lights out in that room needs balance in them never been fixed those 7 lights in the courtyard the sockets needs to replaced there are 7 out out side in the middle of the landing out side the parking lot been out for ever ITS ONE BIG LIGHT OUT IN THE COURTYARD NEEDS TO BE REPLACED there are lights out out side the cafeteria out side needs to be replaced THERE are out lights out on the out side of the cafeteria needs to be replaced
Ida B. Wells Academy	3/8/2024 13:40 3/8/2024 13:35 2/28/2024 9:27 2/19/2024 7:31 2/3/2024 14:50 2/3/2024 14:49 2/3/2024 15:50 2/3/2024 15:50 2/3/2024 16:40	ANDREWS ANDREWS CHALK CHALK CHALK CHALK CHALK CHALK CHALK CHALK	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z1-004805 Z1-004699 Z1-004698 Z1-003197 Z1-001815 W01029934 W01029940 W01026383 W01025946	the boys exhaust has went out on the first floor by room 114 the girls exhaust has went out on the first floor by room 116 IN room 108 its to set of lights out in that room needs balance in them never been fixed those 7 lights in the courtyard the sockets needs to replaced there are 7 out out side in the middle of the landing out side the parking lot been out for ever ITS ONE BIG LIGHT OUT IN THE COURTYARD NEEDS TO BE REPLACED there are lights out out side the cafeteria out side needs to be replaced THERE are out lights out on the out side of the cafeteria needs to be replaced ts out in front of the school the warehouse u need to those 70 watt high pressure sodiom med base lights bluds
Ida B. Wells Academy	3/8/2024 13:40 3/8/2024 13:35 2/28/2024 9:27 2/19/2024 7:31 2/3/2024 14:50 2/3/2024 14:49 2/3/2024 15:50	ANDREWS ANDREWS CHALK CHALK CHALK CHALK CHALK CHALK CHALK	Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z1-004805 Z1-004699 Z1-004698 Z1-003197 Z1-001815 W01029934 W01029940 W01026383 W01025946 W01022148	the boys exhaust has went out on the first floor by room 114 the girls exhaust has went out on the first floor by room 116 IN room 108 its to set of lights out in that room needs balance in them never been fixed those 7 lights in the courtyard the sockets needs to replaced there are 7 out out side in the middle of the landing out side the parking lot been out for ever ITS ONE BIG LIGHT OUT IN THE COURTYARD NEEDS TO BE REPLACED there are lights out out side the cafeteria out side needs to be replaced THERE are out lights out on the out side of the cafeteria needs to be replaced its out in front of the school the warehouse u need to those 70 watt high pressure sodiom med base lights bluds C/O TO HEAT
Ida B. Wells Academy	3/8/2024 13:40 3/8/2024 13:35 2/28/2024 9:27 2/19/2024 7:31 2/3/2024 14:50 2/3/2024 14:49 2/3/2024 15:50 2/3/2024 15:50 2/3/2024 16:40	ANDREWS ANDREWS CHALK CHALK CHALK CHALK CHALK CHALK CHALK CHALK	Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z1-004805 Z1-004699 Z1-004698 Z1-003197 Z1-001815 W01029934 W01029940 W01026383 W01025946 W01022148	the boys exhaust has went out on the first floor by room 114 the girls exhaust has went out on the first floor by room 116 IN room 108 its to set of lights out in that room needs balance in them never been fixed those 7 lights in the courtyard the sockets needs to replaced there are 7 out out side in the middle of the landing out side the parking lot been out for ever ITS ONE BIG LIGHT OUT IN THE COURTYARD NEEDS TO BE REPLACED there are lights out out side the cafeteria out side needs to be replaced THERE are out lights out on the out side of the cafeteria needs to be replaced ts out in front of the school the warehouse u need to those 70 watt high pressure sodiom med base lights bluds

UNIT NOT COMING ON - CL-RM 114 P/M DOUGLASS 416-3210

					P/M DOUGLASS 416-3210
Ida B. Wells Academy	8/21/2024 14:53	WEBB	Heating/Ventilation/Air Conditioning	Z1-028973	
					Door needs painted blue, front and back
lda B. Wells Academy	8/21/2024 15:09	BURCHETT	Painting	Z1-028978	
Ida D. Walla Asadama	F (4 (000 4 7: 4F	DUDQUETT	Delinking	74 040400	THE school needs to be painted all the way around the building outside of the building
Ida B. Wells Academy	5/1/2024 7:45	BURCHETT	Painting	Z1-012429	THE hold school needs to painted out all the way around the school
Ida B. Wells Academy	5/1/2024 7:39	BURCHETT	Painting	Z1-012422	THE Hold School fleeds to painted out all the way around the School
Ida B. Wells Academy	2/3/2024 17:04	YOUNG	Painting	WO1017771	All my classroom doors needs to be painted
ida B. Wells Academy	2/3/2024 17.04	TOUNG	Failtung	WO101///1	the paint is chipping on the scond floor stairway needs to painted
Ida B. Wells Academy	2/3/2024 17:04	HARRIS	Painting	WO1017782	the paint is chipping on the scond foot stall way needs to painted
ida b. Wells Academy	2/3/2024 17:04	TIAMING	i anung	WO1017702	Door frame is damaged causing safety issues, needs fixed
Ida B. Wells Academy	8/21/2024 15:13	STEPHENS	Sheet Metal	Z1-028981	bool name is damaged edusing surely issues, needs ince
ida Si Wella Aleddolliy	0/21/2024 10:10	0121112110	onder retail	21 020001	the gate is broken
Ida B. Wells Academy	12/11/2024 8:42	SHIPPS	Welding	Z1-044429	110 <u>6</u> 410 10 5101011
Idlewild Elementary	2/28/2024 8:33	LEWIS	Asbestos	Z1-003148	Replace floor in the building
Idlewild Elementary	4/15/2024 15:04	CHALK	Electrical	Z1-009408	Lights for parking area
Idlewild Elementary	2/23/2024 8:29	ANDREWS	Electrical	Z1-002581	Need covers for lights in the lunch room
Idlewild Elementary	2/3/2024 15:52	CHALK	Electrical	WO1025421	THERE are lights out on the out side of the building that needs to be replaced
,					power source for fire panel
Idlewild Elementary	12/3/2024 14:31	GREER	Fire Alarm System	Z1-043038	·
ŕ			•		Replace wires that touching fire sprinkler system
Idlewild Elementary	10/23/2024 9:49	GREER	Fire Alarm System	Z1-037969	
Idlewild Elementary	10/23/2024 9:35		Fire Sprinkler System	Z1-037958	Fire marshal has requested our ceiling to be replaced in our rieser room floor.
Idlewild Elementary	10/23/2024 9:39	GREER	Fire Watch	Z1-037962	New panel being installed in gym
					HEATING UNIT ON THE 1ST FLR MAIN BLDG IN RM 104 - WALL UNIT FELL OUT OF THE WALL
					PM/MILAN 416-4566
Idlewild Elementary	12/5/2024 12:30	WEBB	Heating/Ventilation/Air Conditioning	Z1-043623	
Idlewild Elementary	12/4/2024 12:15	WEBB	Heating/Ventilation/Air Conditioning	Z1-043360	Needs new thormostat
					RTU FOR THE KITC - IS NOT COMING ON PM/MILAN 416-4566
Idlewild Elementary	11/4/2024 11:01	SIMMONS	Heating/Ventilation/Air Conditioning	Z1-039440	
					UNIT NOT COOLING - TEACHERS LOUNGE, 2ND FLOOR
					P/M MILAN 416-4566
Idlewild Elementary	8/19/2024 7:42	WEBB	Heating/Ventilation/Air Conditioning	Z1-028248	
					HVAC UNIT FOR THE KITC - NOT COMING ON -PM/WILSON 416-4566
Idlewild Elementary	4/16/2024 13:33	WEBB	Heating/Ventilation/Air Conditioning	Z1-009675	
					Replace tile for the floor
Idlewild Elementary	2/28/2024 8:38	CORONADO	Masonry	Z1-003152	
Idlewild Elementary	2/28/2024 8:35	BURCHETT	Masonry	Z1-003149	Replace wall tile in the cafeteria are
	40/40/0004045	011/51/0		74 044004	Test RP device as noted on letter.
Idlewild Elementary	12/10/2024 9:45 11/18/2024 8:39	OWENS RUSSELL	Plumbing	Z1-044224 Z1-041204	Leaking roof in the entire classroom.
Idlewild Elementary Idlewild Elementary	9/27/2024 11:39		Roofing	21-041204	Leaking foot in the entire classroom.
idlewild Elementary				71 025142	Looking cailing in back of class room
	9/2//2024 11.39	WILSON	Roofing	Z1-035143	Leaking ceiling in back of class room
Idlowild Flomonton			_		Leaking ceiling in back of class room Major concern about gutters falling where kids walk outside of cafeteria doors
Idlewild Elementary	5/10/2024 10:48	HATCH	Sheet Metal	Z1-014064	Major concern about gutters falling where kids walk outside of cafeteria doors
Idlewild Elementary	5/10/2024 10:48 4/29/2024 15:56	HATCH SHIPPS	Sheet Metal Welding	Z1-014064 Z1-012109	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids.
	5/10/2024 10:48	HATCH	Sheet Metal	Z1-014064	Major concern about gutters falling where kids walk outside of cafeteria doors
Idlewild Elementary	5/10/2024 10:48 4/29/2024 15:56	HATCH SHIPPS	Sheet Metal Welding	Z1-014064 Z1-012109	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids. Outside lights in front entrance are out.
Idlewild Elementary Invictus Academy at Airways	5/10/2024 10:48 4/29/2024 15:56 2/3/2024 17:06	HATCH SHIPPS HALL	Sheet Metal Welding Electrical	Z1-014064 Z1-012109 WO1017174	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids.
Idlewild Elementary	5/10/2024 10:48 4/29/2024 15:56	HATCH SHIPPS	Sheet Metal Welding	Z1-014064 Z1-012109	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids. Outside lights in front entrance are out. Fire watch in progress until new fire panel is installed. Estimate completion: 12-2024
Idlewild Elementary Invictus Academy at Airways Invictus Academy at Airways	5/10/2024 10:48 4/29/2024 15:56 2/3/2024 17:06	HATCH SHIPPS HALL	Sheet Metal Welding Electrical Fire Watch	Z1-014064 Z1-012109 WO1017174	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids. Outside lights in front entrance are out.
Idlewild Elementary Invictus Academy at Airways Invictus Academy at Airways Invictus Academy at Airways	5/10/2024 10:48 4/29/2024 15:56 2/3/2024 17:06 9/10/2024 8:23	HATCH SHIPPS HALL CALDWELL	Sheet Metal Welding Electrical Fire Watch Heating/Ventilation/Air Conditioning	Z1-014064 Z1-012109 WO1017174 Z4-031655	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids. Outside lights in front entrance are out. Fire watch in progress until new fire panel is installed. Estimate completion: 12-2024 hvac unit not working
Idlewild Elementary Invictus Academy at Airways Invictus Academy at Airways	5/10/2024 10:48 4/29/2024 15:56 2/3/2024 17:06 9/10/2024 8:23 12/11/2024 17:42	HATCH SHIPPS HALL CALDWELL WRIGHT	Sheet Metal Welding Electrical Fire Watch	Z1-014064 Z1-012109 W01017174 Z4-031655 Z4-044515	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids. Outside lights in front entrance are out. Fire watch in progress until new fire panel is installed. Estimate completion: 12-2024
Idlewild Elementary Invictus Academy at Airways	5/10/2024 10:48 4/29/2024 15:56 2/3/2024 17:06 9/10/2024 8:23 12/11/2024 17:42 12/3/2024 10:36	HATCH SHIPPS HALL CALDWELL WRIGHT WRIGHT	Sheet Metal Welding Electrical Fire Watch Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-014064 Z1-012109 W01017174 Z4-031655 Z4-044515 Z4-042874	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids. Outside lights in front entrance are out. Fire watch in progress until new fire panel is installed. Estimate completion: 12-2024 hvac unit not working room isn't heating up room is cold
Idlewild Elementary Invictus Academy at Airways	5/10/2024 10:48 4/29/2024 15:56 2/3/2024 17:06 9/10/2024 8:23 12/11/2024 17:42 12/3/2024 10:36	HATCH SHIPPS HALL CALDWELL WRIGHT WRIGHT	Sheet Metal Welding Electrical Fire Watch Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-014064 Z1-012109 W01017174 Z4-031655 Z4-044515 Z4-042874	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids. Outside lights in front entrance are out. Fire watch in progress until new fire panel is installed. Estimate completion: 12-2024 hvac unit not working room isn't heating up room is cold Sciaa needs 26 2/1/2 or 3 inch chains and 26 locks
Idlewild Elementary Invictus Academy at Airways	5/10/2024 10:48 4/29/2024 15:56 2/3/2024 17:06 9/10/2024 8:23 12/11/2024 17:42 12/3/2024 10:36	HATCH SHIPPS HALL CALDWELL WRIGHT WRIGHT	Sheet Metal Welding Electrical Fire Watch Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-014064 Z1-012109 W01017174 Z4-031655 Z4-044515 Z4-042874	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids. Outside lights in front entrance are out. Fire watch in progress until new fire panel is installed. Estimate completion: 12-2024 hvac unit not working room isn't heating up room is cold Sciaa needs 26 2/1/2 or 3 inch chains and 26 locks NEED 13 LONG CHAINS AND 13 LOCKS TO SECURE SOCCER GOALS AT ALL DISTRICT
Idlewild Elementary Invictus Academy at Airways	5/10/2024 10:48 4/29/2024 15:56 2/3/2024 17:06 9/10/2024 8:23 12/11/2024 17:42 12/3/2024 10:36 7/11/2024 10:32	HATCH SHIPPS HALL CALDWELL WRIGHT WRIGHT SMITH	Sheet Metal Welding Electrical Fire Watch Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Key & Lock	Z1-014064 Z1-012109 W01017174 Z4-031655 Z4-044515 Z4-042874 Z4-020907	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids. Outside lights in front entrance are out. Fire watch in progress until new fire panel is installed. Estimate completion: 12-2024 hvac unit not working room isn't heating up room is cold Sciaa needs 26 2/1/2 or 3 inch chains and 26 locks NEED 13 LONG CHAINS AND 13 LOCKS TO SECURE SOCCER GOALS AT ALL DISTRICT
Idlewild Elementary Invictus Academy at Airways	5/10/2024 10:48 4/29/2024 15:56 2/3/2024 17:06 9/10/2024 8:23 12/11/2024 17:42 12/3/2024 10:36 7/11/2024 10:32	HATCH SHIPPS HALL CALDWELL WRIGHT WRIGHT SMITH	Sheet Metal Welding Electrical Fire Watch Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Key & Lock Key & Lock	Z1-014064 Z1-012109 W01017174 Z4-031655 Z4-044515 Z4-042874 Z4-020907	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids. Outside lights in front entrance are out. Fire watch in progress until new fire panel is installed. Estimate completion: 12-2024 hvac unit not working room isn't heating up room is cold Sciaa needs 26 2/1/2 or 3 inch chains and 26 locks NEED 13 LONG CHAINS AND 13 LOCKS TO SECURE SOCCER GOALS AT ALL DISTRICT STADIUMS
Idlewild Elementary Invictus Academy at Airways	5/10/2024 10:48 4/29/2024 15:56 2/3/2024 17:06 9/10/2024 8:23 12/11/2024 17:42 12/3/2024 10:36 7/11/2024 10:32 5/17/2024 9:38 10/20/2024 13:14	HATCH SHIPPS HALL CALDWELL WRIGHT WRIGHT SMITH SMITH BURCHETT	Sheet Metal Welding Electrical Fire Watch Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Key & Lock Key & Lock Painting	Z1-014064 Z1-012109 W01017174 Z4-031655 Z4-044515 Z4-042874 Z4-020907 Z4-014997 Z4-037546	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids. Outside lights in front entrance are out. Fire watch in progress until new fire panel is installed. Estimate completion: 12-2024 hvac unit not working room isn't heating up room is cold Sciaa needs 26 2/1/2 or 3 inch chains and 26 locks NEED 13 LONG CHAINS AND 13 LOCKS TO SECURE SOCCER GOALS AT ALL DISTRICT STADIUMS Principal wants parking lot lines painted.
Idlewild Elementary Invictus Academy at Airways	5/10/2024 10:48 4/29/2024 15:56 2/3/2024 17:06 9/10/2024 8:23 12/11/2024 17:42 12/3/2024 10:36 7/11/2024 10:32 5/17/2024 9:38 10/20/2024 13:14 7/1/2024 14:14	HATCH SHIPPS HALL CALDWELL WRIGHT WRIGHT SMITH SMITH BURCHETT BURCHETT	Sheet Metal Welding Electrical Fire Watch Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Key & Lock Rey & Lock Painting Painting	Z1-014064 Z1-012109 W01017174 Z4-031655 Z4-044515 Z4-042874 Z4-020907 Z4-014997 Z4-037546 Z4-019992	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids. Outside lights in front entrance are out. Fire watch in progress until new fire panel is installed. Estimate completion: 12-2024 hvac unit not working room isn't heating up room is cold Sciaa needs 26 2/1/2 or 3 inch chains and 26 locks NEED 13 LONG CHAINS AND 13 LOCKS TO SECURE SOCCER GOALS AT ALL DISTRICT STADIUMS Principal wants parking lot lines painted. Complete 2nd floor and lockers needs to be painted
Idlewild Elementary Invictus Academy at Airways	5/10/2024 10:48 4/29/2024 15:56 2/3/2024 17:06 9/10/2024 8:23 12/11/2024 17:42 12/3/2024 10:36 7/11/2024 10:32 5/17/2024 9:38 10/20/2024 13:14 7/1/2024 14:14 7/1/2024 14:13	HATCH SHIPPS HALL CALDWELL WRIGHT WRIGHT SMITH SMITH BURCHETT BURCHETT BURCHETT	Sheet Metal Welding Electrical Fire Watch Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Key & Lock Key & Lock Painting Painting Painting	Z1-014064 Z1-012109 WO1017174 Z4-031655 Z4-044515 Z4-042874 Z4-020907 Z4-014997 Z4-014997 Z4-019992 Z4-019989	Major concern about gutters falling where kids walk outside of cafeteria doors Please fix fence along playground area it is a danger to kids. Outside lights in front entrance are out. Fire watch in progress until new fire panel is installed. Estimate completion: 12-2024 hvac unit not working room isn't heating up room is cold Sciaa needs 26 2/1/2 or 3 inch chains and 26 locks NEED 13 LONG CHAINS AND 13 LOCKS TO SECURE SOCCER GOALS AT ALL DISTRICT STADIUMS Principal wants parking lot lines painted. Complete 2nd floor and lockers needs to be painted Complete 1st floor and lockers needs to painted to match school colors.

					POCAneed bleachers inspection
J. P. Freeman School	6/1/2024 11:09	CALDWELL	Bleachers and Seats	Z4-016803	POCAneed bleachers hispection
J. P. Freeman School	6/1/2024 11:07	CALDWELL	Bleachers and Seats	Z4-016802	POCAneed gym bleacher inspection
J. P. Freeman School	11/20/2024 9:58	ARNOLD	Carpentry	Z4-041676	Bug guard on exit door needs replacing insects are entering classroom area.
J. P. Freeman School	11/13/2024 16:00	ARNOLD	Carpentry	Z4-040710	Entry door not securing properly
J. P. Freeman School	10/31/2024 10:06	ARNOLD	Carpentry	Z4-039051	Broken tile under the serving line
			22.52,		Mr. Campbell (416 98 43) John P Freeman MS Power outage in Gym
J. P. Freeman School	12/9/2024 8:26		Electrical	Z4-043961	,
J. P. Freeman School	11/13/2024 16:03	HALL	Electrical	Z4-040712	Canopy lights not coming ontimer need setting
J. P. Freeman School	11/13/2024 16:02	HALL	Electrical	Z4-040711	Lights not coming on
J. P. Freeman School	11/12/2024 12:29	HALL	Electrical	Z4-040479	Broken exit signs (2x)
J. P. Freeman School	5/9/2024 15:13	HALL	Electrical	Z4-013967	Fire marshal is requesting for clocks with exposed wire be took down from walls
J. P. Freeman School	6/6/2024 9:52	CALDWELL	Fire Sprinkler System	Z4-017526	POCA tamper switch cover missing
					Mr. Campbell
					67654
					no heat
J. P. Freeman School	12/4/2024 10:17	WILSON	Heating/Ventilation/Air Conditioning	Z4-043274	
					Mr. Campbell, 67658 Mechanical room is locked and PM and tech needs to enter to do a
					repair to breaker box
J. P. Freeman School	11/5/2024 10:24	MALONE	Key & Lock	Z4-039597	
					Requesting for the words "do not block and staff parking " painted down on to ground by
					cafe.
J. P. Freeman School	5/20/2024 10:15	WHITE	Painting	Z4-015180	
J. P. Freeman School	12/5/2024 8:38	HARRIS	Plumbing	Z4-043468	Urinal on west wall not working properlybad flush valve
					Intercom cannot be heard in these areas, speakers located in the hallways does not work
Jackson Elementary	8/16/2024 11:00	SMITH	Audio Visual	Z2-028106	
Jackson Elementary	11/12/2024 10:13	STAFFORD	Carpentry	Z2-040433	replace electric crash bar on gate
					Replace broken vandalized window
Jackson Elementary	11/12/2024 9:41	ROY	Carpentry	Z2-040418	
Jackson Elementary	12/5/2024 10:46	POWELL	Electrical	Z2-043565	No lights or power sensor for automatic lights may need replacing
Jackson Elementary	11/13/2024 14:28	POWELL	Electrical	Z2-040696	Replace bad ballast
Jackson Elementary	11/4/2024 8:38	POWELL	Electrical	Z2-039381	Repair or replace exit light #5
Jackson Elementary	10/21/2024 8:31	POWELL	Electrical	Z2-037601	Reinstall emergency light #4
Jackson Elementary	9/5/2024 9:18	POWELL	Electrical	Z2-031072	Replace 3 old broken light fixtures
					AHU IN RM 210 - NOT HEATING PM/COX 416-5904
Jackson Elementary	12/12/2024 12:56	WILSON	Heating/Ventilation/Air Conditioning	Z2-044737	
					Ms Cox (65904) Heating unit is functioning properly but Rm112 isnt heating
Jackson Elementary	12/12/2024 9:22	WILSON	Heating/Ventilation/Air Conditioning	Z2-044600	
					Ms.Cox (5904) Jackson ES Rm201 Unit isn`t blowing heat at all
Jackson Elementary	12/4/2024 10:20	WILSON	Heating/Ventilation/Air Conditioning	Z2-043279	
					Jackson ES Marlo Cox (65904) Air handling Unit needs factory reset
Jackson Elementary	12/2/2024 11:32	WILSON	Heating/Ventilation/Air Conditioning	Z2-042488	
					AHU OVERHEATING (78 DEGREES) PRE-K CL-RM 107
					P/M MARLO COX 416-5904
Jackson Elementary	11/19/2024 12:39	WILSON	Heating/Ventilation/Air Conditioning	Z2-041521	
					Repair or replace bottle filler display board, it's not working at all
Jackson Elementary	9/27/2024 9:53	PILKINGTON	Plumbing	Z2-035086	
					prep bottle filler for inspection
Jackson Elementary	6/11/2024 7:07	WILSON	Plumbing	Z2-017953	
					Bottle Filler Corrections And inspections
Jackson Elementary	4/24/2024 9:01	WILSON	Plumbing	Z2-011220	
					hand sink leaking
John P. Freeman Stadium	12/4/2024 7:01	HARRIS	Plumbing	Z4-043085	
W . B . IFI		0.47		70.011001	Inter come in this rm is not working. Teacher says she can't hear announcements in her rm.
Kate Bond Elementary School	11/15/2024 12:31	SMITH	Audio Visual	Z2-041094	No Estate and a substitute of the control of the co
					No lights came on when the switch was turned on and the emergency lights all came on and
Kata Band Flamentani Calina	10/10/0004 11/00	CTAFFORD	Floatrical	70.044707	did not cut off. One emergency light just hummed.
Kate Bond Elementary School	12/12/2024 11:29	STAFFORD	Electrical	Z2-044707	
					Emergency flood lights came on but did not cut off when light switch was turned on
Kate Bond Elementary School	12/12/2024 11:27	STAFFORD	Electrical	Z2-044706	Emergency room agins came on but aid not cut on when agin switch was turned on
rate bond Etementary School	12/12/2024 11.2/	SIAFFURD	Electricat	ZZ-U44/Ub	

					All the lights are flashing when the switch is turned on and the emergency lights come on and stayed on
Kate Bond Elementary School	12/12/2024 11:25	STAFFORD	Electrical	Z2-044705	None of the emergency lights are coming on
Kate Bond Elementary School	12/12/2024 11:23	STAFFORD	Electrical	Z2-044703	Have 2 receptacles that are nor working in this rm. Breaker have been checked.
Kate Bond Elementary School	10/28/2024 13:15	POWELL	Electrical	Z2-038565	Outside bulb blown in kitchen dock area. Over 8 ft. high
Kate Bond Elementary School	10/14/2024 7:57	POWELL	Electrical	Z2-036774	Pole light by dumpsters is blown
Kate Bond Elementary School	9/27/2024 9:35	POWELL	Electrical	Z2-035065	Have a blow light outside on back porch of orange hall
Kate Bond Elementary School	9/20/2024 10:30	POWELL	Electrical	Z2-033974	Have 1 blown light on the bldg outside the back of Library.
Kate Bond Elementary School	9/20/2024 10:28	POWELL	Electrical	Z2-033973	Pre K Rm #4 needs an exit sign above the door and the emergency window.
Kate Bond Elementary School	9/4/2024 13:40	POWELL	Electrical	Z2-030950	Need (1) Riser Rm Door Sign
Kate Bond Elementary School	10/29/2024 13:39	Coleman	Fire Alarm System	Z2-038773	Need Emergency Exit Window Stickers (50).
Kate Bond Elementary School	10/29/2024 13:37	Coleman	Fire Alarm System	Z2-038772	
					 Replace Master Controller Circuit Card in FACP (Main Building). Program Master Controller Circuit Card (Main Building). Replace Simplex 566-071 Main Power Supply.
Kata Danid Flamonton Oakaal	40/7/000445:00	0.1	Fire Many Outland	70 000500	Replace Simplex 566-025 Alternate Power Supply.
Kate Bond Elementary School	10/7/2024 15:02	Coleman	Fire Alarm System	Z2-036536	Have a smoke detector in this rm that is hanging by the wires from the ceiling tile,. that
Kate Bond Elementary School	9/23/2024 11:14	Coleman	Fire Alarm System	Z2-034226	needs reattaching.
Kate Bond Elementary School	2/5/2024 15:25	SAVAGE	Fire Alarm System	Z2-000268	POCA- Need an Annual Bleacher Inspection.
Kate Bond Elementary School	12/4/2024 10:57	Coleman	Fire Extinguishers	Z2-043305	All of the fire extinguisher tags are due for re inspection, out dated this month.
					Need 77 emergency escape window stickers to put on outside of classroom windows and
Kate Bond Elementary School	11/21/2024 15:02	Coleman	Fire Extinguishers	Z2-041993	inside and outside of cafe and lobby windows that were omitted from last request.
Kate Bond Elementary School	9/10/2024 8:00	LEWIS	Fire Watch	Z2-031649	Fire watch
					Generator needs insspecting. Had a power outage throughout the entire bldg, on 4-2-24, and the generator never came on.
Kate Bond Elementary School	4/2/2024 12:32	LEWIS	Generators	Z2-007365	Ms. Hurd
					60020 no heat
Kate Bond Elementary School	12/13/2024 10:18	HAMMETT	Heating/Ventilation/Air Conditioning	Z2-044873	Ms. Hurd (416 0020) Roof unit is blowing but No heat in room19 (Code 59)
Kate Bond Elementary School	12/12/2024 10:15	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-044678	Ms. Hurd
					60020 not heating . energy management states unit is blowing at 60 degrees
Kate Bond Elementary School	12/11/2024 13:44	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-044492	Ms. Hurd(9014160020) Kate Bond ES blowing cold air
Kate Bond Elementary School	12/3/2024 10:57	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-042885	Heat is not working in this portable.
Kate Bond Elementary School	10/18/2024 11:36	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-037500	ms. hurd 60020 can't get into room. key won't go in key hhole
Kate Bond Elementary School	11/15/2024 11:59	MORRIS	Key & Lock	Z2-041091	
					Have a trash can that was bolted to the brick but has been knocked off creating a hole where the bricks were and the bricks are still bolted to the bottom of the can. Please repair.
Kate Bond Elementary School	10/28/2024 13:19	BURCHETT	Masonry	Z2-038567	Install ceramic tile on the 2 RR floors in this lounge
Kate Bond Elementary School	4/5/2024 9:34	CORONADO	Masonry	Z2-007866	-

Kate Bond Elementary School	4/5/2024 9:33	CORONADO	Masonry	Z2-007865	Install ceramic tile on the 2 small RR floors in this lounge.
,			,		Paint RR in Clinic.and patch holes
Kate Bond Elementary School	10/14/2024 9:58	BURCHETT	Painting	Z2-036818	
					There is a Ig hole of putty dug our from around the badge swipe on the brick, that needs to be filled in.
Kate Bond Elementary School	9/23/2024 14:14	BURCHETT	Painting	Z2-034317	
Kata Danid Elamantan Oaka al	0/5/000445-07	041/405	Delli He De ess	70 000000	POCARoll up bookstore door needs to be repaired and operable.
Kate Bond Elementary School	2/5/2024 15:27	SAVAGE	Roll Up Doors	Z2-000269	
					LIGHTS - THE RELAY SWITCH IS NOT WORKING - HAS NO LIGHTS PM/OLLIE 416-7584
Kate Bond Middle School	12/3/2024 13:37	POWELL	Electrical	Z2-043006	
Kate Bond Middle School	10/24/2024 10:18	POWELL	Electrical	Z2-038166	Request to replace one bulb and will also need a speciality wrench/key to remove light cover.
Kate Bond Middle School	3/27/2024 9:41	POWELL	Electrical	Z2-006559	est to replace two lights inside chandelier a lift is required and also was submitted on SchoolDude
Kate Bond Middle School	3/27/2024 9:15	POWELL	Electrical	Z2-006544	
Kate Bond Middle School	3/26/2024 14:25	POWELL	Electrical	Z2-006472	Request to have eight lights in the main lobby replaced.* also submitted on SchoolDude*
Kate Bond Middle School	3/26/2024 13:57	POWELL	Electrical	Z2-006457	Request to change nine fixtures with two bulbs apiece*was submitted in SchoolDude*
Kate Bond Middle School	3/26/2024 12:53	POWELL	Electrical	Z2-006431	lequest to change all broken clocks without a face in the hallways to regular classroom clocks.
Kate Bond Middle School	3/28/2024 15:38	POWELL	Electrical	WO998501	Request to replace missing the exit sign by the auditorium.
Kate Bond Middle School	3/28/2024 15:38	POWELL	Electrical	WO991182	Request to replace 4 specialty lights inside girls shower area.
Kate Bond Middle School	12/13/2024 10:16		Elevators	Z2-044871	Request to have elevator repair, the button is lighting up blue but the doors are not opening.
					Ollie 67584 room not coolin
Kate Bond Middle School	11/19/2024 9:16	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-041444	Ollie 67584 room not coolin
Kate Bond Middle School	11/19/2024 9:15	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-041442	Ottle 07304 TOUTH HOL COULIN
Kate Bond Middle School	11/19/2024 8:23	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-041442 Z2-041411	repair the air inside the main IDF closet, the thermostat is blank and it is extremely hot inside the closet.
					hallway light out bad balance near plc room
Keystone Elementary	12/12/2024 13:36	SMITH	Electrical	Z1-044755	
					RECEPTACLES (3) HAS NO POWER - CL-RM C119 - WILL NOT RESET
					KALEB ADIL 416-3924
Keystone Elementary	12/11/2024 12:51	SMITH	Electrical	Z1-044475	POCA All Portable buildings within 30 ft. are tied to the building fire alarm.
Keystone Elementary	3/8/2024 12:41	GREER	Fire Alarm System	Z1-004680	FOCK All Portable buildings within 50 ft. are tied to the building life atain.
,			•		
					Mr. Adil (9012919239) Keith Stone ES Hvac unit isn`t cooling properly in room B126
Keystone Elementary	12/9/2024 10:52	WEBB	Heating/Ventilation/Air Conditioning	Z1-044042	classroom is 79 degrees
Keystone Elementary	12/5/2024 9:55	WEBB	Heating/Ventilation/Air Conditioning	Z1-043539	classionii is 73 degrees
,,					rooms is 74 degrees
Keystone Elementary	12/4/2024 13:10	WEBB	Heating/Ventilation/Air Conditioning	Z1-043381	
					classroom reading 63 degrees
Keystone Elementary	12/3/2024 11:16	WEBB	Heating/Ventilation/Air Conditioning	Z1-042896	classroom reading 93 degrees
Keystone Elementary	12/3/2024 11:15	WEBB	Heating/Ventilation/Air Conditioning	Z1-042895	Classiouii readiiig 93 degrees
Rojotono Etomontary	12/0/2024 11:10	***************************************	riodaling Foliatacions in Containening	21 0 12000	is reading 79 degrees
Keystone Elementary	9/23/2024 14:08	WEBB	Heating/Ventilation/Air Conditioning	Z1-034316	
					reading 80 degrees in PreK class
Keystone Elementary	9/23/2024 14:06	WEBB	Heating/Ventilation/Air Conditioning	Z1-034312	DED TO THE STATE OF THE STATE O
Keystone Elementary	9/4/2024 9:41	WEBB	Heating/Ventilation/Air Conditioning	Z1-030848	REPAIR MAKEUP WATER FOR COOLING TOWER
Reystone Elementary	9/4/2024 9.41	WEDD	Heating/ventitation/Air Conditioning	21-030646	
					Plant Manager Douglas reported the ac unit in room A153 is blowing hot air. 416-3924.
Keystone Elementary	8/1/2024 13:30	WEBB	Heating/Ventilation/Air Conditioning	Z1-024519	
					Unit not cooling
Keystone Elementary	8/1/2024 8:55	WEBB	Heating/Ventilation/Air Conditioning	Z1-024279	
					key for room b104a
Keystone Elementary	10/23/2024 8:28	MALONE	Key & Lock	Z1-037922	
Keystone Elementary	7/25/2024 14:17	BURCHETT	Painting	Z1-022694	Paint railings in front of the school peeling bad
					Back gym wall needs painted where the was damage from leaking water
Keystone Elementary	5/13/2024 12:54	BURCHETT	Painting	Z1-014276	
	E4404005 : :	BUBO:			Wall needs painted in the middle of the hall where masonry work was done
Keystone Elementary	5/13/2024 12:53	BURCHETT	Painting	Z1-014275	Cafataria antranca area noode pointed
Keystone Elementary	5/13/2024 12:50	BURCHETT	Painting	Z1-014273	Cafeteria entrance area needs painted
Regione Elementary	0/10/2024 12.00	DOMOTILIT	i ulliulig	21 0142/3	

The gym needs to be painted. Brown residue is still let on the wall due to roof leaks. Entire side painting. Requested beginning of the year. (Principal Brooks)

Keystone Elementary	5/13/2024 12:12	BURCHETT	Painting	Z1-014263	
Keystone Elementary	3/28/2024 15:36	BURCHETT	Painting	WO1000164	Pillar/Collin at from of the school entrance needs re painted white
•			ŭ .		Pipe leak inside boiler room
Keystone Elementary	10/7/2024 9:32	OWENS	Plumbing	Z1-036428	• • • • • • • • • • • • • • • • • • • •
Reystone Etementary	10///2024 5.02	OWEND	rambing	21 000-20	Both cells are out on wht pole
Kingsbury Career & Technology Center	9/13/2024 5:05	POWELL	Electrical	Z2-032361	both cetts are out on whit pote
Kingsbury Career & reclinology Center	9/13/2024 3.03	FOWELL	Electricat	22-032301	Discount of the second of the
					Please replace cell lights mounted at top of back side of bldg/very dark & safety/security
					concern
Kingsbury Career & Technology Center	9/13/2024 5:03	POWELL	Electrical	Z2-032360	
					POCA: please cover empty slots inside ele panel boxes 1st/2nd floor closets
Kingsbury Career & Technology Center	4/25/2024 13:22	POWELL	Electrical	Z2-011585	
Kingsbury Career & Technology Center	4/1/2024 11:50	POWELL	Electrical	Z2-007025	'lease address exhaust fan not working causing shop to fill up with smokewill set off alarms.
					Panel Deemed ""Unreliable".
Kingsbury Career & Technology Center	11/4/2024 9:30	Coleman	Fire Alarm System	Z2-039412	
kingsbury ourcer a recimology ochier	11/4/2024 5.00	Ooternan	The Admin bystem	22 000412	Please address: system will not reset or stop beeping/ panel states, "ACTIVE NON FIRE
					TROUBLE"
					IKOUBLE"
					Per Vendor, System needs to be replaced.
Kingsbury Career & Technology Center	8/13/2024 6:50	Coleman	Fire Alarm System	Z2-027139	
					(POCA) Fire alarm service date has expired
Kingsbury Career & Technology Center	5/8/2024 14:00	Coleman	Fire Alarm System	Z2-013701	
<i>o</i> ,			•		Please send two riser rm signs
Kingsbury Career & Technology Center	4/25/2024 13:24	LEWIS	Fire Sprinkler System	Z2-011587	
Kingsbury Career & Technology Center	6/5/2024 16:24	BURCHETT	Masonry	Z2-017437	Please replace mortar that has deteriorated causing bricks to fall away. *safety concerns*
		POWELL	,		
Kingsbury Elementary	12/3/2024 7:32	POWELL	Electrical	Z2-042693	please replace ballast/ out lights out & 1 twinkling
					Plt Mgr has cked all known breakers, but can't get current to this receptacle
Kingsbury Elementary	10/15/2024 6:18	POWELL	Electrical	Z2-036942	
					Please change bulbs in small fixtures mounted at ceiling on wall in stairwell & (1) ballast on
					landing
Kingsbury Elementary	8/8/2024 11:44	POWELL	Electrical	Z2-026410	
Kingsbury Elementary	8/5/2024 7:10	POWELL	Electrical	Z2-025004	please replace the battery inside the Emer combo light
Kingsbury Elementary	8/2/2024 10:38	POWELL	Electrical	Z2-024721	please replace the battery in Emer combo light
Kingsbury Eternentary	0/2/2024 10:00	TOWELL	Etectricat	22 024/21	please replace (1) ballast 2nd fl hallway @ rm #30E
Kingshun, Elementen,	8/2/2024 9:33	POWELL	Electrical	Z2-024696	
Kingsbury Elementary					(1) ballast inside entrance of 1st fl boys rest rm
Kingsbury Elementary	6/26/2024 15:44	POWELL	Electrical	Z2-019559	please replace (1) ballast
					Please replace (1) ballast in fixture
Kingsbury Elementary	5/8/2024 14:09	POWELL	Electrical	Z2-013706	
					POCA: Per Fire Marshall/replace plate on panel box
Kingsbury Elementary	4/25/2024 13:10	POWELL	Electrical	Z2-011579	
Kingsbury Elementary	4/2/2024 8:41	POWELL	Electrical	Z2-007196	Please replace 1 ballast in single tube fixture causing two tubes outage
Kingsbury Elementary	4/2/2024 8:37	POWELL	Electrical	Z2-007189	Please replace battery in combo light #3
g,,					Please replace (1) ballast in light fixture
Kingsbury Elementary	2/14/2024 14:22	POWELL	Electrical	Z2-001446	1 todos roptuos (2) sutuat in agricimato
	2/3/2024 14:22	POWELL	Electrical	WO1020833	Diagon rankana hattarias in amar samba lighta #2\s 9.2\s aver antranas dasra
Kingsbury Elementary					·
Kingsbury Elementary	2/3/2024 17:05	POWELL	Electrical		place wht plastic insert for tubes/middle portion missing causes tube to running with twinkling actions.
Kingsbury Elementary	2/3/2024 17:06	POWELL	Electrical	WO1017460	Please replace (1) single fixture ballast
					Please repair manual Pull Stations (not reporting to the panel)
Kingsbury Elementary	10/17/2024 11:24	Coleman	Fire Alarm System	Z2-037374	
					Please repair out of sync Strobes
Kingsbury Elementary	10/17/2024 11:18	Coleman	Fire Alarm System	Z2-037372	
g,,			· · · · · · · · · · · · · · · · · · ·		Please replace secondary power supply batteries, (1 set 12V 12ah) & replace Left FCPS
					battery
Via dalama Flancastani	40/47/000444-45	0-1	Fire Manne Outland	70 007070	battery
Kingsbury Elementary	10/17/2024 11:15	Coleman	Fire Alarm System	Z2-037370	
					Please have yrly extinguisher inspection performed
Kingsbury Elementary	9/13/2024 9:32	Coleman	Fire Extinguishers	Z2-032562	
					Mr. dean
					64080
					unit not coming on
Kingsbury Elementary	12/10/2024 9:07	WILSON	Heating/Ventilation/Air Conditioning	Z2-044191	· ·
		25011			

UNIT NOT HEATING - CL-RM 35E P/M SNERLLING 416-6020

					P/M SNERLLING 416-6020
Kingsbury Elementary	12/6/2024 12:01	WILSON	Heating/Ventilation/Air Conditioning	Z2-043827	THE ORLINE AND SOLD
Kingsbury Eternentary	12/0/2024 12:01	WILDON	ricating ventitudon//air contationing	22 040027	UNIT NOT HEATING - CL-RM 32E
					P/M SNERLLING 416-6020
Kingsbury Elementary	12/6/2024 12:00	WILSON	Heating/Ventilation/Air Conditioning	Z2-043826	F/FI SNEELLING 410-0020
Kingsbury Elementary	12/0/2024 12.00	WILSON	Heating/Ventitation/Air Conditioning	22-043820	
					N. C. W. (1994) 1994 1994 1994 1994 1994 1994 1994
					Ms. Snerlling (5984554) Kingsbury ES 416 (6020) Classroom 13E blowing cold air no heat
Kingsbury Elementary	12/5/2024 10:17	WILSON	Heating/Ventilation/Air Conditioning	Z2-043552	
Kingsbury Elementary	11/20/2024 14:06	WILSON	Heating/Ventilation/Air Conditioning	Z2-041770	Zone pump 7 not working
Kingsbury Elementary	5/9/2024 13:59	SMITH	Key & Lock	Z2-013942	Please change out locks
Kingsbury Elementary	8/12/2024 17:27	BURCHETT	Masonry	Z2-027099	Please repair/deteriorated mortar between bricks
Kingsbury Elementary	5/23/2024 7:05	BURCHETT	Painting	Z2-015747	water leaking through expansion joint & middle of hallway causing paint chips to drop from ceiling
Kingsbury High	10/21/2024 14:25	BURKE	Carpentry	Z2-037720	Classroom window shattered from bullet fragments
					Requesting doors be replaced in gym multi-purpose area.
Kingsbury High	4/24/2024 11:57	BURKE	Carpentry	Z2-011314	
Kingsbury High	4/11/2024 9:38	BURKE	Carpentry	Z2-008771	Damage ceiling drywall needs repairing and painting.
Kingsbury High	4/11/2024 9:11	BURKE	Carpentry	Z2-008763	Rotting and missing wood on building support columns.
Kingsbury High	11/22/2024 13:20	POWELL	Electrical	Z2-042089	when I reported to work 11/22 they were both out again but the bulbs weren't blown. I'm not sure if a balance is needed or not.
Kingsbury High	10/4/2024 6:58	POWELL	Electrical	Z2-036210	Light bulbs have been replaced. Lights are flickering. Balance needs replacing.
Kingsbury High	10/4/2024 6:51	POWELL	Electrical	Z2-036209	Next to room 276
Kingsbury High	10/4/2024 6:27	POWELL	Electrical	Z2-036207	Light bulbs have been changed. Lights will not illuminate. Balance replacement is required.
Kingsbury High	10/4/2024 6:24	POWELL	Electrical	Z2-036206	Balance replacement. Light bulbs has been changed lights still do not illuminate.
Kingsbury High	8/2/2024 13:50	POWELL	Electrical	Z2-030200 Z2-024852	Receptacle will not power on water fountain
		POWELL			
Kingsbury High	6/28/2024 12:02		Electrical	Z2-019783	Electrical fixtures broken and hanging from building
Kingsbury High	6/28/2024 12:00	POWELL	Electrical	Z2-019782	Broken electrical fixtures is hanging from building
Kingsbury High	6/18/2024 9:35	POWELL	Electrical	Z2-018715	Damage light switch covers. Practice rooms.
Kingsbury High	6/18/2024 9:31	POWELL	Electrical	Z2-018711	Damage sockets and no plate covers.
Kingsbury High	6/18/2024 9:20	POWELL	Electrical	Z2-018706	Outlet sockets are loose and missing plate covers.
Kingsbury High	6/18/2024 9:18	POWELL	Electrical	Z2-018705	East wall outlets do not work.
Kingsbury High	6/17/2024 12:08	POWELL	Electrical	Z2-018576	noval of two electrical outlets protruding from classroom floor. Safety hazard for students, faculty, and staff.
Kingsbury High	5/9/2024 10:59	POWELL	Electrical	Z2-013857	Light fixtures and ceiling damage exposed wiring need repairs.
					emergency lighting in the library needs a battery
Kingsbury High	4/24/2024 13:06	POWELL	Electrical	Z2-011351	
					Requesting missing electrical plate covers.
Kingsbury High	4/24/2024 12:18	POWELL	Electrical	Z2-011327	
					Exit signs lights do not work.
Kingsbury High	3/27/2024 15:36	POWELL	Electrical	Z2-006698	
					Exit signs lights do not work.
Kingsbury High	3/27/2024 15:33	POWELL	Electrical	Z2-006695	
0 , 0					Exit signs lights do not work
Kingsbury High	3/27/2024 15:32	POWELL	Electrical	Z2-006694	
Kingsbury High	2/22/2024 15:49	POWELL	Electrical	Z2-002549	Expose electrical wiring casing is torn away from building.
Kingsbury High	8/19/2024 6:41	Coleman	Fire Alarm System	Z2-028223	
Kingsbury riigii	0/13/2024 0.41	Ooteman	The Authorstein	22 020220	Requesting fire alarm inspection.
Kingsbury High	4/24/2024 12:35	LEWIS	Fire Alarm System	Z2-011337	requesting the dark inspection.
Kingsbury riigii	4/24/2024 12:00	LLWIS	The Alaim System	22-011337	Requesting replacing missing pull station.
Kingahun, High	4/24/2024 12:03	LEWIS	Fire Alexan Custom	Z2-011317	nequesting replacing missing put station.
Kingsbury High	4/24/2024 12:03	LEWIS	Fire Alarm System	22-011317	
					Fire alarm did not activate and doors did not automatically release during fire drill.
Kingsbury High	3/22/2024 7:55	LEWIS	Fire Alarm System	Z2-005847	
					Requesting all fire extinguishers are mounted and are installed every 75 ft.
Kingsbury High	4/24/2024 12:07	LEWIS	Fire Extinguishers	Z2-011319	
					Requesting replacing missing sprinkler head rings.
Kingsbury High	4/24/2024 12:16	LEWIS	Fire Sprinkler System	Z2-011323	
					State Systems Sprinkler: requesting a work order for Kingsbury High School. During the
					Annul fire sprinkler inspection our tech noted the water motor gong failed to operate during
					testing. (6) missing escutcheons by room 124 and (1) missing near rm. 267. The (PIV)
					supervisory tamper switch at auditorium failed to report to FACP during testing. We will
					need to trouble shoot WMG clean out nest / debris from gong housing and retest for proper
					operation. Replace (7) missing escutcheons and (1) (PIV) Supervisory tamper switch. Price
					to perform \$975.00
10 . 1 . 10 4	0/00/000445-05		F: 0 : 11 0 .		

WO1008959

Kingsbury High

3/28/2024 15:35 Systems

Fire Sprinkler System

Kingsbury High	12/3/2024 10:53	WILSON	Heating/Ventilation/Air Conditioning	Z2-042884	Heat not working . Motor hot but not running.
Kingsbury High	12/3/2024 9:19	WILSON	Heating/Ventilation/Air Conditioning	Z2-042784	No Heat In Room. Temp is 65
Kingsbury High	12/10/2024 10:48	MALONE	Key & Lock	Z2-044258	2Keys Needed For Rm 253 (Key#AF3)
Kingsbury High	11/5/2024 12:10	MALONE	Key & Lock	Z2-039614	Key Needed For Storage Closet (KeyA11)
Kingsbury High	11/5/2024 12:08	MALONE	Key & Lock	Z2-039613	Key Need For Storage Closet (Key A10)
Kingsbury High	11/5/2024 12:07	MALONE	Key & Lock	Z2-039611	Key Needed For Storage Closest (Key A9)
Kingsbury High	10/21/2024 10:54	MALONE	Key & Lock	Z2-037664	Requesting two office door keys for school secretaries. For office room #157-B
Kingsbury High	10/21/2024 10:10	MALONE	Key & Lock	Z2-037646	Requesting key #AA16 classroom F220 for teacher
Kingsbury High	4/12/2024 13:41	SMITH	Key & Lock	Z2-009051	Requesting office restroom lock to be changed over to teachers restroom key and lock.
Kingsbury High	9/30/2024 8:20	BURCHETT	Masonry	Z2-035322	Large cracks in exterior walls where rodents are entering interior areas of building
Kingsbury High	10/21/2024 6:31	BURCHETT	Painting	Z2-037553	Restroom ceiling need painting.
Kingsbury High	10/8/2024 12:13	BURCHETT	Painting	Z2-036619	PE/Coach Office needs painting. Peeling paint inside of entire gymnasium
					paint wood for column repairs
Kingsbury High	9/30/2024 13:36	HARRIS	Painting	Z2-035507	
Kingsbury High	8/2/2024 13:11	BURCHETT	Painting	Z2-024820	Requesting hallway walls need painting
Kingsbury High	8/2/2024 12:49	BURCHETT	Painting	Z2-024813	Requesting girls restroom needs painting.
Kingsbury High	7/31/2024 10:24	BURCHETT	Painting	Z2-024077	Wall need painting
					Requesting parking spaces markings for principal, assistant principal, secretary, and other
					school officials.
Kingsbury High	7/11/2024 14:23	BURCHETT	Painting	Z2-020948	
Kingsbury High	7/10/2024 11:59	BURCHETT	Painting	Z2-020768	Handicap entrance exit sign needs replacing
Kingsbury High	6/28/2024 11:57	BURCHETT	Painting	Z2-019781	Exterior railings need painting
Kingsbury High	6/18/2024 11:24	BURCHETT	Painting	Z2-018769	equesting painting of windows headers and seals from the repairs made due to water damage.
Kingsbury High	6/17/2024 12:05	BURCHETT	Painting	Z2-018575	Peeling paint inside of classroom.
Kingsbury High	6/17/2024 11:47	BURCHETT	Painting	Z2-018572	Peeling paint inside of entire classroom.
Kingsbury High	5/1/2024 14:26	BURCHETT	Painting	Z2-012619	Requesting administration titles painted in individual parking spaces.
Kingsbury High	3/7/2024 8:42	BURCHETT	Painting	Z2-004360	Majority of lockers needs painting.
Kingsbury High	3/7/2024 8:40	BURCHETT	Painting	Z2-004356	Majority of doors needs painting.
Kingsbury Middle	8/20/2024 8:27	POWELL	Electrical	Z2-028541	Electrical Outlet Has Stopped Working. Or The water fountain plug has went out.
					TWO RECEPTACLES HAS EXPOSED WIRES - CL-RM 106 - SAFETY ISSUE
					P/M JOSHUA TAYLOR 416-6040
Kingsbury Middle	7/31/2024 14:25	POWELL	Electrical	Z2-024143	
Kingsbury Middle	11/18/2024 13:33	MALONE	Key & Lock	Z2-041335	Key Needed For Assistant Principal. Key Number Unknown.
Kingsbury Middle	7/22/2024 10:40	BURCHETT	Painting	Z2-021872	Painting Requested By Principal. The Color Gray Is Requested if possible
Kingsbury Middle	7/22/2024 9:28	BURCHETT	Painting	Z2-021847	nting of Lockers requested by principal. The Color Of Burgundy to match the colors of the school.
Kingsbury Middle	7/22/2024 9:28	BURCHETT	Painting	Z2-021846	nting of Lockers requested by principal. The Color Of Burgundy to match the colors of the school.
					A204 Intercom is not working in classroom
Kirby High	11/14/2024 8:12	SMITH	Audio Visual	Z3-040761	
					bleachers inspection for front and back gym
Kirby High	8/9/2024 9:48	SMALL	Bleachers and Seats	Z3-026651	
					Back Gym bleachers on first roll are missing screws need securing.
Kirby High	7/3/2024 11:32	SMALL	Bleachers and Seats	Z3-020200	
					Back Gym the 1st row of bleachers are leaning down on the left side.
Kirby High	8/20/2024 12:13	HATCH	Carpentry	Z3-028673	
					requesting for the windows to be replaced at the concession stand on the football field.
					(RISK MANAGEMENT
Kirby High	7/23/2024 15:40	CROUSE	Carpentry	Z3-022213	
					classroom C121 need ballast replaced
Kirby High	11/6/2024 9:47	SCOTT	Electrical	Z3-039788	
, .o					
					classroom C129 need ballast replaced next to unit ventilator
Kirby High	11/6/2024 8:37	SCOTT	Electrical	Z3-039729	
Kirby High	11/6/2024 8:37				classroom C129 need ballast replaced next to unit ventilator classroom C130 need ballast (2) over teacher's desk.
		SCOTT SCOTT	Electrical Electrical	Z3-039729 Z3-039727	classroom C130 need ballast (2) over teacher's desk.
Kirby High Kirby High	11/6/2024 8:37 11/6/2024 8:35	SCOTT	Electrical	Z3-039727	
Kirby High	11/6/2024 8:37				classroom C130 need ballast (2) over teacher's desk.
Kirby High Kirby High	11/6/2024 8:37 11/6/2024 8:35	SCOTT	Electrical	Z3-039727	classroom C130 need ballast (2) over teacher's desk. Upgrade gym lights to LED on stage in Auditorium lights are not coming on. May need bulbs replaced to high up for
Kirby High Kirby High Kirby High	11/6/2024 8:37 11/6/2024 8:35 11/1/2024 12:22	SCOTT CHALK	Electrical Electrical	Z3-039727 Z3-039281	classroom C130 need ballast (2) over teacher's desk. Upgrade gym lights to LED
Kirby High Kirby High	11/6/2024 8:37 11/6/2024 8:35	SCOTT	Electrical	Z3-039727	classroom C130 need ballast (2) over teacher's desk. Upgrade gym lights to LED on stage in Auditorium lights are not coming on. May need bulbs replaced to high up for
Kirby High Kirby High Kirby High	11/6/2024 8:37 11/6/2024 8:35 11/1/2024 12:22	SCOTT CHALK	Electrical Electrical	Z3-039727 Z3-039281	classroom C130 need ballast (2) over teacher's desk. Upgrade gym lights to LED on stage in Auditorium lights are not coming on. May need bulbs replaced to high up for ladder.
Kirby High Kirby High Kirby High Kirby High	11/6/2024 8:37 11/6/2024 8:35 11/1/2024 12:22 10/31/2024 8:48	SCOTT CHALK SCOTT	Electrical Electrical Electrical	Z3-039727 Z3-039281 Z3-039024	classroom C130 need ballast (2) over teacher's desk. Upgrade gym lights to LED on stage in Auditorium lights are not coming on. May need bulbs replaced to high up for
Kirby High Kirby High Kirby High	11/6/2024 8:37 11/6/2024 8:35 11/1/2024 12:22	SCOTT CHALK	Electrical Electrical	Z3-039727 Z3-039281	classroom C130 need ballast (2) over teacher's desk. Upgrade gym lights to LED on stage in Auditorium lights are not coming on. May need bulbs replaced to high up for ladder. on loading dock there are (2) lights are out on building outside kitchen area, need replacing
Kirby High Kirby High Kirby High Kirby High	11/6/2024 8:37 11/6/2024 8:35 11/1/2024 12:22 10/31/2024 8:48	SCOTT CHALK SCOTT	Electrical Electrical Electrical	Z3-039727 Z3-039281 Z3-039024	classroom C130 need ballast (2) over teacher's desk. Upgrade gym lights to LED on stage in Auditorium lights are not coming on. May need bulbs replaced to high up for ladder. on loading dock there are (2) lights are out on building outside kitchen area, need replacing across from tennis court outside of exit doors on school building has (2) packing light bulbs
Kirby High Kirby High Kirby High Kirby High	11/6/2024 8:37 11/6/2024 8:35 11/1/2024 12:22 10/31/2024 8:48	SCOTT CHALK SCOTT	Electrical Electrical Electrical	Z3-039727 Z3-039281 Z3-039024	classroom C130 need ballast (2) over teacher's desk. Upgrade gym lights to LED on stage in Auditorium lights are not coming on. May need bulbs replaced to high up for ladder. on loading dock there are (2) lights are out on building outside kitchen area, need replacing

					405B classroom needs (1) ballast replaced
Kirby High	9/9/2024 14:25	SCOTT	Electrical	Z3-031596	400b classiourii necus (1) uaitast repiaceu
Kirby High	8/6/2024 9:05	SCOTT	Electrical	Z3-025538	Library need socket cover plate
					workshop classroom is missing a socket cover plate
Kirby High	8/1/2024 11:58	SCOTT	Electrical	Z3-024444	
					in the back gym the ventilation switch does not open vents for ventilation need repaired.
Kirby High	7/31/2024 9:30	SCOTT	Electrical	Z3-024057	
Kirby High	7/16/2024 7:45	SCOTT	Electrical	Z3-021305	Chiller Room needs (4) bulbs replaced.
KilbyTilgii	7/10/2024 7:43	30011	Liectificat	25-021505	custodial closet 413a has a broken socket needs replacing
Kirby High	7/15/2024 8:23	SCOTT	Electrical	Z3-021140	
Kirby High	7/12/2024 14:56	SCOTT	Electrical	Z3-021089	c/r c-119 socket cracked on right side of wall
KilbyTilgii	7/12/2024 14.00	30011	Liectificat	25-021005	in attendance office there are (2) missing phone jack cover plate
Kirby High	7/11/2024 15:05	SCOTT	Electrical	Z3-020952	
Kirby High	7/3/2024 15:11	SCOTT	Electrical	Z3-020242	missing cover plate on b-hall on wall across from b-416
Kilby High	7/3/2024 15.11	30011	Electrical	23-020242	3 ballast on the ramp
Kirby High	6/5/2024 13:15	SCOTT	Electrical	Z3-017364	Nood lister
Kirby High	4/29/2024 8:38	SCOTT	Electrical	Z3-011891	Need lights
, ,					System Status Off-Normal Supervisory SW North PIV L1M063TROUBLE ACK
Kirby High	12/6/2024 8:30		Fire Alarm System	Z3-043737	
					SHORT Trouble ACK (SLC1). Heat SE Boiler Room. Stroll lights and Siren was not working during Fire Drill on 8/15/2024. Located in Band room. Stroll light and Siren was not working
					during Fire Drill on 8/15/2024. Located in Kitchen.
Kirby High	5/14/2024 14:35	SMALL	Fire Alarm System	Z3-014537	
Kirby High	10/21/2024 9:31	SMALL	Fire Extinguishers	Z3-037623	across from 421k fire extinguisher need servicing
2 y 1g.1	10/21/2024 0101	OI II LEE	r no Examplionoio	20 007020	back gym has (2) fire extinguishers need servicing
Kirby High	10/21/2024 9:29	SMALL	Fire Extinguishers	Z3-037621	
Kirby High Kirby High	2/15/2024 14:02 5/17/2024 14:03	CASEY Power	Flooring Generators	Z3-001635 W0003605	Carpet need repaired epairs were completed, the generator is running, but the generator engine needs a lot of repairs (2 cylinders down etc.) and after generator work the transfer switch will need repair/replacement. A quote was requested on behalf of Zone 3.
KilbyTilgii	3/1//2024 14.03	i owei	Generators	***************************************	C136 heat is not coming on.
Kirby High	12/13/2024 7:24	BRYSON	Heating/Ventilation/Air Conditioning	Z3-044806	
					HEATING UNIT THAT COVERS THE ASSIST PRIN OFC & THE ATTENDANCE OFC - IS BLOWING COLD AIR PM/BROWN 416-1960
Kirby High	12/11/2024 10:01	BRYSON	Heating/Ventilation/Air Conditioning	Z3-044450	COLD AIRT PRINTONIA 420-2400
					MS, BROWN 61960 BLOWING OUT COLD AIR
Kirby High	12/3/2024 8:57	BRYSON	Heating/Ventilation/Air Conditioning	Z3-042762	MS. BROWN 61960 BLOWING COLD AIR
Kirby High	12/2/2024 11:06	BRYSON	Heating/Ventilation/Air Conditioning	Z3-042465	No. Diomito 2500 Beomino Gold Ain
					MS. BROWN 61960 BLOWING COLD AIR
Kirby High	12/2/2024 11:05	BRYSON	Heating/Ventilation/Air Conditioning	Z3-042462	MS. BROWN 61960 BLOWING COLD AIR
Kirby High	12/2/2024 11:04	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-042459	No. DROWN 01900 BLOWING COLD AIN
					Install coil in classroom #102
Kirby High	10/7/2024 7:17	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-036372	
					Plant Manager Brown reported the ac unit in room A116 is blowing hot air. 416-1960
Kirby High	7/11/2024 11:18	BRYSON	Heating/Ventilation/Air Conditioning	Z3-020921	
Kirby High	5/17/2024 14:24	SCOTT	Heating/Ventilation/Air Conditioning	WO1006226	exhaust fans in gym
Kirby High	12/10/2024 11:21	MALONE	Key & Lock	Z3-044266	Kitchen exit door has a broken key in cylinder need copy of keys AA (1) and A (2)
Kirby High	9/25/2024 11:00	MALONE	Key & Lock	Z3-034651	
Vielas J. II -d-	14/4/0004 7:00	DUDGUETT	D-i-si	70 000400	requesting for main office exit doors to be painted
Kirby High	11/1/2024 7:32	BURCHETT	Painting	Z3-039180	
					requesting for exterior doors to be painted in front of school by Attendance Office
Kirby High	11/1/2024 7:30	BURCHETT	Painting	Z3-039179	

					across from a117 girl's restroom last stall the wall needs to be painted has large graffiti
Kirby High	8/13/2024 8:05	BURCHETT	Painting	Z3-027174	drawing on wall
Kirby High	7/22/2024 13:31	BURCHETT	Painting	Z3-021975	cafeteria wall front entrance and right wall need touch up painting
Kirby High	7/22/2024 13:29	BURCHETT	Painting	Z3-021973	requesting for wall to be painted in hallway next to b-416
Kirby High	7/22/2024 13:27	BURCHETT	Painting	Z3-021971	All gym double doors need painting
					back hallway across from 421k next to equipment room wall needs to be painted
Kirby High	7/22/2024 12:05	BURCHETT	Painting	Z3-021924	in hallway across from b-403 wall needs repainting
Kirby High	7/22/2024 11:59	BURCHETT	Painting	Z3-021919	in hallway next to b-401 (chorus) wall needs repainting
Kirby High	7/22/2024 11:57	BURCHETT	Painting	Z3-021915	requesting for Boy's Restroom to be painted across from Cafeteria.
Kirby High	7/22/2024 11:07	BURCHETT	Painting	Z3-021895	requesting for Girl's Restroom to be painted across from Cafeteria
Kirby High	7/22/2024 11:04	BURCHETT	Painting	Z3-021892	B-hall behind front gym girl's restroom 2nd stall toilet is not flush to the floor, can be move
Kirby High	12/13/2024 12:57	PEARSON	Plumbing	Z3-044910	by hand
Kirby High	12/9/2024 9:41	BUFORD	Plumbing	Z3-044005	there is a leak in principal office in the closet puddle of water in floor
Kilby Filgi	12/0/2024 3.41	BOLOND	T CONTROLLED	20 044000	boys restroom across from cafeteria toilet is leaking along back of toilet were pipes are located when flush
Kirby High	12/2/2024 13:45	BARNES	Plumbing	Z3-042574	tocated when itusii
Kirby High	10/29/2024 13:42	PEARSON	Plumbing	Z3-038777	Sink floods hallway if water is turned on. (equipment room next to Building Engineer)
KIIDY FIIGH	10/29/2024 15.42	PEARSON	Fullbling	23-030777	girls locker room change bottle, tried to cut water supply on water shut off. need plumber to find source of water
Kirby High	10/16/2024 6:57	BARNES	Plumbing	Z3-037120	
Kirby High	10/14/2024 12:07	BARNES	Plumbing	Z3-036864	across from B411 water fountain push button are broken, need button replaced
Kirby High	10/3/2024 13:12	WILSON	Plumbing	Z3-036143	testing backflow preventers
					inside of football locker room hand washing sink water won't shut off but is contained
Kirby High	9/18/2024 12:46	BARNES	Plumbing	Z3-033468	A224 sink faucet is leaking on hot side
Kirby High	9/18/2024 9:54	BARNES	Plumbing	Z3-033399	leaking in attendance over employees work area in front office in right corner
Kirby High	11/14/2024 8:09	BUFORD	Roofing	Z3-040759	
Kirby High	11/14/2024 8:04	BUFORD	Roofing	Z3-040757	equipment room next to building engineer the vent/ pipe in equipment room is leaking
Kirby High	9/13/2024 11:15	BENTON	Shades/Blinds	Z3-032663	blinds in attendance office need replacing 60x60
					american flag on front lawn is tangle up by the high winds, need someone to untangle rope
Kirby High	12/12/2024 14:22	KINARD	Welding	Z3-044771	Install water spigot for greenhouse bypass underground water leak in slab
Kirby Stadium	7/8/2024 7:30	TOLES	Plumbing	Z3-020352	
Knight Road Elementary	7/26/2024 9:35	BARNES	Carpentry	Z3-022852	Sandbags needed to prevent water from entering the building
Knight Road Elementary	12/5/2024 8:54	SCOTT	Electrical	Z3-043484	Bad ballast in the hallway across from room 7
Knight Road Elementary	12/5/2024 8:54	SCOTT	Electrical	Z3-043483	Bad ballast in the hallway across from room 5
Knight Road Elementary	12/2/2024 12:23	SCOTT	Electrical	Z3-042532	Bad ballast located in the hallway across from classroom 3
Knight Road Elementary	12/2/2024 12:20	SCOTT	Electrical	Z3-042531	Bad ballast in the VEL Center
Knight Road Elementary	12/2/2024 12:19	SCOTT	Electrical	Z3-042530	Bad ballast located in the hallway across from room 23
Knight Road Elementary	12/2/2024 12:17	SCOTT	Electrical	Z3-042528	Bad ballast in the hallway across from room 14
Knight Road Elementary	11/20/2024 8:46	SCOTT	Electrical	Z3-041638	Need lights replaced on the stage in the VEL center
Knight Road Elementary	11/20/2024 8:45	SCOTT	Electrical	Z3-041637	Bad ballast in the VEL center

					Electric socket in the VEL center located beside the water fountain is not working
Knight Road Elementary	11/18/2024 12:23	SCOTT	Electrical	Z3-041313	
Knight Road Elementary	9/19/2024 11:51	SCOTT	Electrical	Z3-033748	Ballast out
					exit sign in cafeteria on right side by stage needs a new battery
Knight Road Elementary	5/16/2024 10:12	SCOTT	Electrical	Z3-014830	
Vnight Dood Flomentons	5/16/2024 10:09	SCOTT	Electrical	Z3-014829	exit sign in cafeteria to the left near stage need a new battery.
Knight Road Elementary	5/16/2024 10:09	50011	Electrical	23-014829	BOILER INSPECTION
Knight Road Elementary	10/4/2024 11:09		Energy Management System	Z3-036293	BOILER INSPECTION
Kilight Hoad Elementary	10/4/2024 11:05		Lifetgy Planagement System	25-030293	griffin 62514 system showing denied /failed
Knight Road Elementary	12/2/2024 10:04	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-042381	grilli ded 1 djetom endring demod raked
					griffin 62514 system showing denied /failed
Knight Road Elementary	12/2/2024 10:02	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-042378	0
,					No air in room
Knight Road Elementary	9/19/2024 12:22	JOHNSON	Heating/Ventilation/Air Conditioning	Z3-033775	
					No air in room
Knight Road Elementary	9/19/2024 12:10	JOHNSON	Heating/Ventilation/Air Conditioning	Z3-033764	
					No air in room
Knight Road Elementary	9/19/2024 12:08	JOHNSON	Heating/Ventilation/Air Conditioning	Z3-033760	
					No air in room
Knight Road Elementary	9/19/2024 12:07	JOHNSON	Heating/Ventilation/Air Conditioning	Z3-033759	
Kaiaha Baad Elamana	7/05/00040-54	MUTAKORTU	Linearing of Continue of the Control of the Control	70 000540	cafeteria unit is down and is very hot.
Knight Road Elementary Knight Road Elementary	7/25/2024 8:54 11/7/2024 15:29	WHITWORTH MALONE	Heating/Ventilation/Air Conditioning	Z3-022516 Z3-040203	Lock on classroom door 35 is not working. Need lock replace in order to lock and unlock door
Knight Road Elementary	9/19/2024 10:45	MALONE	Key & Lock Key & Lock	Z3-040203 Z3-033716	MCA key due to the fact prior administration had a lot of locks changed, and the master key does not work to those doors.
Knight Road Elementary	10/21/2024 11:39	BARNES	Plumbing	Z3-033710 Z3-037675	From located across from the teacher lounge is not working correctly. There is no pipe connected to the sink
Kilight Hoad Elementary	10/21/2024 11.55	DAMINES	i tullibling	25-05/0/5	Prep Bottle Fillers for inspections
Knight Road Elementary	2/14/2024 6:26	CHALK	Plumbing	Z3-001319	· · · · · · · · · · · · · · · · · · ·
0			3		Roof is leaking in room 30
Knight Road Elementary	11/15/2024 9:14	BUFORD	Roofing	Z3-041027	· ·
Knight Road Elementary	7/29/2024 8:07	BUFORD	Roofing	Z3-023125	There is leak in the main hallway running from the boiler room down to Room 11
Knight Road Elementary	7/29/2024 7:53	BUFORD	Roofing	Z3-023108	There is a leak traveling across from Room 8 to Room 7
Knight Road Elementary	2/3/2024 16:39	CHASE	Shades/Blinds	WO1022263	Room # 34 needs 8 blinds installed.
					used fluorescent bulb pick up
LaRose Elementary	12/15/2024 19:19	LANE	Asbestos	Z1-044946	
LaRose Elementary	10/7/2024 9:21	RUSSELL	Carpentry	Z1-036419	Ceiling tiles needs to be repaired
	511100011000	BURGELL		74 040504	Ceiling Tiles need to be replaced in cafeteria.
LaRose Elementary	5/1/2024 10:32	RUSSELL	Carpentry	Z1-012524	
LaDaga Flamentoni	10/0/2024 0:17	ANIDDEIME	Electrical	Z1-036546	balance is bad and need to be replace in cafeteria
LaRose Elementary	10/8/2024 6:17	ANDREWS	Electricat	21-030346	Main Office bathroom vent is broken
LaRose Elementary	4/22/2024 15:02	ANDREWS	Electrical	Z1-010966	Plant Office Datificon Vent is broken
Euriose Eternentary	4/22/2024 10:02	ANDREWO	Electricat	21 010000	Balance bad and need to be replaced in library.
LaRose Elementary	4/9/2024 11:19	ANDREWS	Electrical	Z1-008386	,
					FALLING WIRE - TCHR' PARKING LOT AREA - PM/ADIL 416-7848
LaRose Elementary	3/22/2024 12:27	CHALK	Electrical	Z1-005966	
LaRose Elementary	2/3/2024 16:41	CHALK	Electrical	WO1021846	exterior light outside near kitchen are out
					fire alarm box is reading bad battery
LaRose Elementary	12/2/2024 9:48	GREER	Fire Alarm System	Z1-042371	
					PULL PUMP AND REPLACE LEAKING SEAL AND CHECK BEARINGS
LaRose Elementary	12/11/2024 8:55	JOHNSON	Heating/Ventilation/Air Conditioning	Z1-044433	
					BOILER PUMP IS LEAKING - BOILER ROOM, 1ST FLOOR NEAR THE CAFETERIA
	40/0/0004044	14/500		74 040050	P/M JOSEPH STANDSBURY 4167848
LaRose Elementary	12/9/2024 8:14	WEBB	Heating/Ventilation/Air Conditioning	Z1-043953	Cafataria Office dear lay need to be replaced. Office dear in leaked and Managar nurse in
					Cafeteria Office door key need to be replaced. Office door is locked and Manager purse is inside.
LaRose Elementary	10/2/2024 13:19	MALONE	Key & Lock	Z1-035931	ilisiue.
Euriose Eternentary	10/2/2024 10:10	TIALONE	KCY & EUCK	21 000001	requesting keys for 2 first floor cafeteria closets
LaRose Elementary	7/1/2024 13:20	SMITH	Key & Lock	Z1-019970	
			,		tn ready key for principle
LaRose Elementary	6/27/2024 10:38	SMITH	Key & Lock	Z1-019639	
					4 custodial closet keys for each room in school
LaRose Elementary	3/25/2024 8:06	SMITH	Key & Lock	Z1-006072	

					requesting baseboard be painted
LaRose Elementary	7/11/2024 10:35	BURCHETT	Painting	Z1-020909	requesting baseboard be painted
Euriooo Etomontary	7711202410.00	5011011211	. unung	21 020000	Test RP device as noted on letter. 2
LaRose Elementary	12/10/2024 10:21	OWENS	Plumbing	Z1-044249	
LaRose Elementary	5/17/2024 13:37	Pro	Roll Up Doors	WO973869	Need roll door inspection.
					leaking from the ceiling
LaRose Elementary	9/13/2024 12:13	WILSON	Roofing	Z1-032684	
LaRose Elementary	5/17/2024 14:26	BENTON	Shades/Blinds	WO1009815	needed for pre-k class
LaRose Elementary	5/17/2024 14:04	BENTON	Shades/Blinds	WO995050	Need shades made for those rooms.
					Need bleachers Inspection Report-POCA
Levi Elementary	6/6/2024 11:21	CALDWELL	Bleachers and Seats	Z4-017550	
Levi Elementary	12/3/2024 9:55	ARNOLD	Carpentry	Z4-042816	The swing arm rubs against door when opening and closing.
Levi Elementary	11/5/2024 9:54	ARNOLD	Carpentry	Z4-039585	Right side crash bar not functioning properly, can't open door, from outside
					replace tile
Levi Elementary	8/27/2024 13:09	ANDERSON	Carpentry	Z4-029852	
					Mr. Feilds (416 8166) Levi ES PreK rm 1F Boiler not responding. no air or heat
Levi Elementary	12/6/2024 8:21	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043734	THE CONTROL BY AN AND AND AND AND AND AND AND AND AND
Levá Flancantonia	40/4/0004 0:40	DOMNIED	Heating Of antilation (Air Oan distance	74.040400	HVAC UNIT FOR RM 6E - NOT COMING ON PM/MORGANFIELD 416-8166
Levi Elementary	12/4/2024 8:12	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043130	New Manager Manager Edd and a state of the UNIO with in the angle of the 140 0000
Levi Elementary	12/2/2024 8:59	DOWNER	Heating/Ventilation/Air Conditioning	Z4-042321	Plant Manager Morganfield reported the HVAC unit in the main office. 416-8166.
Levi Elementary	11/13/2024 12:00	MALONE	Key & Lock	Z4-042321 Z4-040657	No lock on restroom door, lock is needed.
Levi Elementary	11/5/2024 12:00	MALONE	Key & Lock	Z4-040037 Z4-039583	Lock was removed keys wasn't working, tech needed to work on internet, new lock needed.
Levi Elementary	11/5/2024 9.51	MALONE	key & Lock	24-039363	Lock was removed keys wash t working, tech needed to work on internet, new tock needed.
					Principal Patton is requesting that 3 A keys be made to give to new admin staff members.
Levi Elementary	8/30/2024 8:59	SMITH	Key & Lock	Z4-030437	This part attent to requesting that of the job of made to give to not a damin stain members.
			,		
					Principal Patton is request that 3 keys be made for room 5A, to give to new staff members.
Levi Elementary	8/30/2024 8:57	SMITH	Key & Lock	Z4-030435	
Levi Elementary	7/29/2024 11:34	SMITH	Key & Lock	Z4-023320	sting Admin building keys for our new Dean of Students. Outer doors, classroom room and Administration office doors.
					Cracks between walls and floors, floor tiles replaced a year ago, are broken and cracked,
					spiders are coming in through these cracks .
Levi Elementary	10/31/2024 10:03	CORONADO	Masonry	Z4-039049	
Levi Elementary	10/21/2024 10:43	BURCHETT	Masonry	Z4-037656	Water getting under restroom tile and grout flowing into hallway
					Water fountain not draining and water is overflowing onto the floor.
Levi Elementary	12/12/2024 7:22		Plumbing	Z4-044530	
					First sink as you enter the restroom, facet won't turn off, and there is a leak from under the
Levá Flancantonia	40/40/00047-00	LIADDIO	Discontinue	74.044450	sink.
Levi Elementary	12/10/2024 7:20	HARRIS	Plumbing	Z4-044152	no water company to finite ide water anial at when turned an
Loui Flamenton	0/7/2024 12:00	LIADDIC	Dismbing	74 000110	no water comes out of outside water spicket when turned on.
Levi Elementary	8/7/2024 13:08	HARRIS	Plumbing	Z4-026118	room 312 book shelves install for book bags
Lowrance School	12/11/2024 9:51	CROUSE	Carpentry	Z3-044443	TOURI STE BOOK SHEWES HISTORICAL OF BOOK BASS
LOWI direct School	12/11/2024 5.51	CHOUSE	Carpentry	25-044445	2 broken two-tone tile need replaced
Lowrance School	12/5/2024 7:38	CROUSE	Carpentry	Z3-043433	2 biologistic total tita nood repaded
					(SBE) Garage door manual operating door is harder that the weather is cold oil the rollers
					will have no effect of the weight and operating.
Lowrance School	12/4/2024 9:53	BARNES	Carpentry	Z3-043245	
					repair balance
Lowrance School	12/13/2024 7:34	SCOTT	Electrical	Z3-044814	
					repair balance
Lowrance School	12/13/2024 7:33	SCOTT	Electrical	Z3-044813	
					replace light balance
Lowrance School	12/13/2024 7:32	SCOTT	Electrical	Z3-044812	
					light balance replace
Lowrance School	12/13/2024 7:30	SCOTT	Electrical	Z3-044810	
					Light fixture is very high for me to reach
Lowrance School	12/5/2024 7:36	SCOTT	Electrical	Z3-043432	
Lowrance School	11/14/2024 16:55	SCOTT	Electrical	Z3-040951	Gym install switch for lowering and raising the goals
Lowrance School	10/17/2024 10:53	SCOTT	Electrical	Z3-037367	Office behind the stage need a Electrical outlet installed
Lowrance School	10/7/2024 8:50	SCOTT	Electrical	Z3-036398	Bad ballast in the electrical closet on the 6th grade hall next door to the plant manager office
Lowrance School	10/7/2024 8:49 10/7/2024 8:48	SCOTT SCOTT	Electrical Electrical	Z3-036396 Z3-036394	Bad ballast in the 4th grade hallway 2 bad ballast in room 302
Lowrance School Lowrance School	10/7/2024 8:48	SCOTT	Electrical	Z3-036394 Z3-036393	2 dad ballast in room 302 3 Bad ballast in room 303
FOMIQUE SCHOOL	10///2024 5.4/	30011	Electricat	23-030393	o dau narrast ili nonii ono

Lowrance School	10/7/2024 8:47	SCOTT	Electrical	Z3-036392	2 bad ballast in room 304
Lowrance School	10/7/2024 8:46	SCOTT	Electrical	Z3-036391	Bad ballast in the boiler room
Lowrance School	10/7/2024 8:45	SCOTT	Electrical	Z3-036390	2 bad ballast in room 305
Lowrance School	9/20/2024 11:35	SCOTT	Electrical	Z3-034004	On the side where the car rider lane is located the lights are not coming on in the parking lot
Lowrance School	9/20/2024 11:31	SCOTT	Electrical	Z3-034003	Socket in the kitchen area is broke
Lowrance School	9/13/2024 15:39	SCOTT	Electrical	Z3-032740	Back of the school outside lights are not coming on
Lowrance School	9/13/2024 9:23	SCOTT	Electrical	Z3-032555	Bad ballast in room 105 located on the eighth floor
Lowrance School	9/3/2024 10:44	SCOTT	Electrical	Z3-030691	Need key switch replace in the Gym
Lowrance School	8/28/2024 14:23	SCOTT	Electrical	Z3-030118	Bad ballast in the A.P. Office that's located in the main office
Lowrance School	8/28/2024 8:04	SCOTT	Electrical	Z3-030110 Z3-029939	Magnet on the back door of the fifth grade halls is not holding
Lowrance School	4/17/2024 9:34	CASEY			
LOWIAIICE SCHOOL	4/1//2024 9.34	CASET	Flooring	Z3-009856	Tiles need replacement in room 403 HVAC UNIT IN RM 308 - HAS A BAD COMPRESSOR - NOT COMING ON PM/GRIFFIN 416-
	7/00/0004000			70 00000	2330
Lowrance School	7/30/2024 8:32	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-023609	LINUT NOT COMPANY ON PRINCIPLE OFFICE
					UNIT NOT COMING ON - PRINCIPALS OFFICE
					P/M GRIFFIN 416-2330
Lowrance School	7/22/2024 11:02	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-021887	
					Room 214 Relocation of Building Engineer office
					Re-Key due to items missing personnel belongings
Lowrance School	11/6/2024 12:54	MALONE	Key & Lock	Z3-039908	Z3 039902 is same request
Lowrance School	11/6/2024 12:32	MALONE	Key & Lock	Z3-039902	Principal request two L keys
Lowrance School	11/6/2024 12:31	MALONE	Key & Lock	Z3-039901	Rekey door please someone took my personal item it's missing
Lowrance School	9/20/2024 10:58	MALONE	Key & Lock	Z3-033988	Classroom 311 located on the fifth grade hall window is not locking
Lowrance School	9/20/2024 10:57	MALONE	Key & Lock	Z3-033987	Classroom 306 located on the fifth grade hall window is not locking
Lowrance School	8/9/2024 9:27	SMITH	Key & Lock	Z3-026634	Window need a secure lock
Lowrance School	8/6/2024 12:34	SMITH	Key & Lock	Z3-025708	Principal is requesting 3 L keys for the new AP
Lowrance School	7/30/2024 9:18	SMITH	Key & Lock	Z3-023649	Room 309 located on the fifth grade hall has no lock on the classroom window
Lowrance School	7/25/2024 10:52	SMITH	Key & Lock	Z3-022575	Room 402 need locked on door fix
Lowrance School	3/18/2024 10:07	SMITH	Key & Lock	Z3-005142	Employee master key to open classroom is broke need a replacement
Lowrance School	2/20/2024 12:49	SMITH	Key & Lock	Z3-002132	Teacher need a key for classroom 414
Lowrance School	6/5/2024 9:35	BURCHETT	Painting	Z3-002132 Z3-017297	Principal is requesting that all enter doors to the school be painted
			•		
Lowrance School	5/17/2024 14:21	BURCHETT	Painting	WO1003989	, ,
					testing of 4 backflow preventers at this location
Lowrance School	10/3/2024 13:17	WILSON	Plumbing	Z3-036144	
Lowrance School	10/3/2024 10:07	WARREN	Plumbing	Z3-036068	Leaks at the boiler
Lowrance School	10/3/2024 9:13	BENTON	Shades/Blinds	Z3-036029	Room 407 need blinds/shades replaced
Lowrance School	10/3/2024 9:07	BENTON	Shades/Blinds	Z3-036027	Room 404 on the third grade hall need blinds replace
Lowrance School	10/3/2024 9:05	BENTON	Shades/Blinds	Z3-036026	Room 405 that's located on the third grade hall need shades /blinds replaced
Lowrance School	9/30/2024 13:51	BENTON	Shades/Blinds	Z3-035519	Room 202 located on the 7th grade hall need blind replace
Lowrance School	9/30/2024 13:49	BENTON	Shades/Blinds	Z3-035518	Room 205 need blinds replaced with Shades
					Room 103 need blinds replaced.
Lowrance School	4/9/2024 11:04	LEWIS	Shades/Blinds	Z3-008377	
					The ceiling tile grid bracket is missing needs replaced.
Lucie E. Campbell Elementary	3/26/2024 12:19	ARNOLD	Carpentry	Z1-006423	
					There are several stained ceiling tiles in this area with a camera or sprinkler head in it that
					needs replacing.
Lucie E. Campbell Elementary	3/21/2024 13:51	ARNOLD	Carpentry	Z1-005769	
,			,		There is a hole in drywall by the gate that rats are entering . This hole needs patching via
					pest control technician.
Lucie E. Campbell Elementary	2/22/2024 13:45	ARNOLD	Carpentry	Z1-002517	F
Lucie E. Campbell Elementary	5/17/2024 14:26	BENTON	Carpet Repair	WO1009420	In plant manager area door need be fix on my custodial Closet
Lucie E. Campbell Elementary	12/13/2024 7:59	SMITH	Electrical	Z1-044830	18 ballast bulbs blown needs lift.
Lucie E. Campbell Elementary	12/13/2024 7:31	SMITH	Electrical	Z1-044811	t 72 blown bulbs causing cafeteria to be dark. In all 16 ballast. All bulbs are blown not the ballast needs lift.
Lucie E. Campbell Elementary	5/17/2024 14:25	CHASE	Flooring	WO1008100	
					Mr. Hart (901 416 4000) Lucy E Campbell ES Entire A hallway (A100 A113)
Lucie E. Campbell Elementary	12/6/2024 13:15	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-043845	
					UNIT NOT COMING ON - CL-RM S100
					P/M HART 416-1000
Lucie E. Campbell Elementary	8/14/2024 11:54	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-027521	
Lucie E. Campbell Elementary	8/14/2024 9:11	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-027442	1 of the children broke the thermostat of wall can not get a temperature reading in this room
					HVAC UNIT - PREK RM A111 NOT COMING ON PM/HART 416-1000
Lucie E. Campbell Elementary	8/9/2024 13:54	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-026772	
Lucie E. Campbell Elementary	12/13/2024 7:37	MALONE	Key & Lock	Z1-044816	MRS BOOTH didn't get keys to her file cabinet give keys to PM

					I need 3 inside keys made for this location.
Lucie E. Campbell Elementary	2/26/2024 14:03	SMITH	Key & Lock	Z1-002907	···
Lucie E. Campbell Elementary	5/17/2024 14:23	BURCHETT	Painting	WO1005154	need the building pressure wash it have lot writing on it, need it remove soon
Lucie E. Campbell Elementary	11/20/2024 7:09	Jordan	Plumbing	Z1-041590	3 compartment sink 2 won't hold water and 1 won't drain water duplicate ticket Install new domestic water heater.
Lucie E. Campbell Elementary	11/15/2024 14:09	Jordan	Plumbing	Z1-041114	
Lucie E. Campbell Elementary	5/17/2024 13:38	Pro	Roll Up Doors	WO975831	POCAFire roll up door needs Inspection Wood needs replaced on roof outside room 300
Lucy Elementary	10/8/2024 9:18	ARNOLD	Carpentry	Z1-036595	
					Areas have been checked for termite presence, they said that it's clear. I'm requesting these areas be repaired when possible
Lucy Elementary	9/6/2024 10:11	ARNOLD	Carpentry	Z1-031290	
Lucy Elementary	5/17/2024 14:25	BENTON	Carpet Repair	WO1008315	baseboards need repair back wall.
Lucy Elementary	5/17/2024 13:50	BENTON	Carpet Repair	WO986730	Carpet needs removed for pre k classroom
Lucy Elementary	5/17/2024 13:48	BENTON	Carpet Repair	WO985474	Carpet needs removed
					The ballast in both of the lights in the girls restroom on the 200 hall is out.
Lucy Elementary	12/12/2024 13:34	SMITH	Electrical	Z1-044754	We have blown ballast in the cafeteria lights. Located in front of the stage
Lucy Elementary	10/29/2024 13:21	SMITH	Electrical	Z1-038766	
					The ballast in the 4th light first row in the teacher's lounge is out. I have tried to change them and discovered that the ballast is out.
Lucy Elementary	10/24/2024 13:09	SIMMONS	Electrical	Z1-038225	
					The ballast is out in the girls restroom 1st floor last stall. I tried changing bulbs didn't that didn't work
Lucy Elementary	10/22/2024 11:31	SMITH	Electrical	Z1-037839	
					We have a ceiling light that ballast is out located in front of room 213
Lucy Elementary	10/4/2024 12:11	SMITH	Electrical	Z1-036316	I have two lights that are out in the gym and they are too high to reach with my ladder. They
					are location on the back right side of the gym.
Lucy Elementary	10/1/2024 12:48	SMITH	Electrical	Z1-035741	The elevator lights are not working I contacted the elevator contractor and was told that I needed to put in a electrical ticket for it
Lucy Elementary	9/30/2024 14:46	SMITH	Electrical	Z1-035539	needed to put in a electrical dicket for it
					Outlets are not working in the main office on both sides
Lucy Elementary	9/30/2024 9:02	SMITH	Electrical	Z1-035360	
					Two of the four in the outlet along the window wall are not working along with all four on the front wall with the Promethean board.
Lucy Elementary	8/7/2024 10:47	SMITH	Electrical	Z1-026035	
					The transfer switch says power down error and the main switchboard has a service needed
					signal on the surge logic panel.
Lucy Elementary	7/30/2024 16:51	SMITH	Electrical	Z1-023889	
					We have a new AV system located in the cafeteria but we need some outlets installed in the ceiling in order to power on the system. Pics included below.
Lucy Elementary	7/10/2024 14:25	CHALK	Electrical	Z1-020805	Celting in order to power on the system. Fics included below.
Lucy Elementary	5/24/2024 9:56	SMITH	Electrical		cipal Edwards requesting for a outlet to be placed on the cafeteria's ceiling for an projector thanks
zao, ziomentar,	0/2-1/2024 0100	0	Libbinodi	21 010007	Light fixture needs shade on it
Lucy Elementary	4/16/2024 21:24	MALONE	Electrical	Z1-009744	•
Lucy Elementary	4/16/2024 21:22	MALONE	Electrical	Z1-009743	Light fixture needs an shade on it
					I have a system supervisory alert that shows the basement has an abnormal hi/low pressure (M2-71) on the sprinkler monitor. Could not upload a photo due to one already existing on here in a different work order.
Lucy Elementary	11/25/2024 8:46	GREER	Fire Sprinkler System	Z1-042157	
					The art room storage closet flooring is crumbling up and the flooring is very unstable seems to be about to cave in. Comes from a leak which is also located in the art room in two separate areas.
Lucy Elementary	7/10/2024 13:01	CASEY	Flooring	Z1-020786	
					The Music Room isn't heating. Tried to see would it rise overnight but it only went down.
Lucy Elementary	12/13/2024 9:05	WEBB	Heating/Ventilation/Air Conditioning	Z1-044851	
			3		The library is not getting heat
Lucy Elementary	12/5/2024 15:08	WEBB	Heating/Ventilation/Air Conditioning	Z1-043678	
Lucy Flore	10/0/00010-14	MEDD	Lipoting Montiletine 18:- One district	74 040000	Gym is not heating, heat it switched on but it's not getting warm in gym.
Lucy Elementary	12/2/2024 9:11	WEBB	Heating/Ventilation/Air Conditioning	Z1-042330	

HVAC UNIT IN RM 201 - HAS A BURNING SMELL COMING OUT - THE HAS BEEN SHUT OFF -STILL HAS THE SMELL PM/SAYLES 416-2610

					STILL HAS THE SMELL PM/SAYLES 416-2610
Lucy Elementary	9/13/2024 8:39	WEBB	Heating/Ventilation/Air Conditioning	Z1-032496	
					HVAC UNIT FOR THE WORKROOM 2ND FLR - BLOWING HOT AIR PM/TRUESDALE 416-2610
Lucy Elementary	6/27/2024 10:48	WEBB	Heating/Ventilation/Air Conditioning	Z1-019642	
					We have chipped paint in the hallway on the first floor outside of a pre-k classroom.
Lucy Elementary	10/29/2024 13:28	BURCHETT	Painting	Z1-038768	
					We have rust present on the boys bathroom stalls on the first floor.
Lucy Elementary	10/29/2024 13:18	BURCHETT	Painting	Z1-038765	
Lucy Elementary	6/14/2024 11:58	BURCHETT	Painting	Z1-018407	Walls need to be painted for the up coming school year. (the gray part of wall)
					Test RP device as noted on letter. 3 ea.
Lucy Elementary	12/10/2024 9:58	OWENS	Plumbing	Z1-044239	
Lucy Elementary	5/17/2024 13:47	HATCH	Sheet Metal	WO983660	Gutters needs replaced
Macon-Hall Elementary	5/17/2024 14:17	BENTON	Carpet Repair	WO999297	carpet is coming up in the middle of room needs to be repaired
-					out door light area lights do not come on area very dark
Macon-Hall Elementary	11/2/2024 17:46	POWELL	Electrical	Z2-039322	
•					water fountains have no power tried to reset
Macon-Hall Elementary	9/20/2024 13:35	POWELL	Electrical	Z2-034052	
•					elevator is producing a loud beeping noise needs to be addressed
Macon-Hall Elementary	12/11/2024 10:38	Coleman	Elevators	Z2-044460	
,					elevator making constant beeping noise
Macon-Hall Elementary	11/1/2024 11:34	Coleman	Elevators	Z2-039264	
•					Replace missing smoke head near room 116.
					Repair NAC panel in the annex building.
Macon-Hall Elementary	11/20/2024 8:53	Coleman	Fire Alarm System	Z2-041641	
Macon-Hall Elementary	3/25/2024 17:03	LEWIS	Fire Alarm System	WO1033253	pipe leaking in riser room please repair poca
,					Fire hydrant is leaking needs to be repaired
Macon-Hall Elementary	7/31/2024 11:52	Coleman	Fire Sprinkler System	Z2-024097	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
					Mr. Mathis
					62625
					5th grade annex building blowing cool air
Macon-Hall Elementary	12/12/2024 9:02	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044578	
,					HEATING UNIT IN RM 532 - NOT HEATING PM/MATHIS 416-2625
Macon-Hall Elementary	12/6/2024 12:15	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043829	
,					HEATING UNIT IN RM 202 - NOT HEATING PM/MATHIS 416-2625
Macon-Hall Elementary	12/6/2024 12:14	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043828	
,					mr.mathis
					62625
					not heating
Macon-Hall Elementary	12/4/2024 13:09	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043380	· ·
,					mr.mathis
					62625
					not heating
Macon-Hall Elementary	12/4/2024 13:09	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043379	· · · · · · ·
,					mr.mathis
					62625
					not heating
Macon-Hall Elementary	12/4/2024 13:08	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043378	a a g
,					mr.mathis
					62625
					not heating
Macon-Hall Elementary	12/4/2024 13:07	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043377	
,					mr.mathis
					62625
					not heating
Macon-Hall Elementary	12/4/2024 13:06	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043375	nothodally
acon rida Eterrioritary	12, 2027 10.00	55014	. Journal Continued of the Continued of	22 040070	master key needed for building master for these two buildings are the same
Macon-Hall Elementary	8/27/2024 8:04	SMITH	Key & Lock	Z2-029701	
acon rida Eterrioritary	3,2,,2324 0.04	S	no, a Lock	LL 020/01	master key to main building needed
Macon-Hall Elementary	8/27/2024 8:03	SMITH	Key & Lock	Z2-029700	matter to y to main balanty needed
	3,2,,202, 0.00	J	noj a zoon	0_0,00	room key needed
Macon-Hall Elementary	8/27/2024 8:02	SMITH	Key & Lock	Z2-029697	y noodod
300 riak Elementary	3.22324 0.02	S	no, a Look	LL 02000/	

Macon-Hall Elementary Macon-Hall Elementary	6/11/2024 10:41 3/22/2024 8:24	SMITH SMITH	Key & Lock Key & Lock	Z2-018009 Z2-005858	Storage closet lock needs to be changed to fit room key along with master key Supplies closet in room needs to be keyed to fit master key
Macon-Hall Elementary	2/22/2024 13:56	SMITH	Key & Lock	Z2-002524	Key gets stuck when locking or unlocking locking mechanism is also loose please repair
Macon-Hall Elementary	12/12/2024 9:19	HARDWAY	Plumbing	Z2-044593	sink will not turn off
			_		restroom sink will not stop running
Macon-Hall Elementary	12/12/2024 9:17	HARDWAY	Plumbing	Z2-044590	inspection of bottle fillers
Macon-Hall Elementary	5/3/2024 7:48	WILSON	Plumbing	Z2-012904	MONTHLY DRAW - ASBESTOS MATERIALS/SUPPLIES FOR THE MONTH OF DECEMBER - 2024 HW
Mallory Warehouse	11/25/2024 7:33	AMOS	Asbestos	Z1-042141	Build short wall for bottle filler.
Mallory Warehouse	12/11/2024 15:08	ARNOLD	Carpentry	Z1-044514	Install Reserved Parking sign for Textbook Advisor. Located by Asset Management parking
Mallory Warehouse	9/18/2024 12:43	SHIPPS	Carpentry	Z1-033464	on the fenced area
Mallory Warehouse	6/6/2024 16:07	OLIVER	Carpentry	Z1-017632	Installed Reserved Parking Signs West of Building
Mallory Warehouse	5/17/2024 14:04	BENTON	Carpet Repair	WO995091	s very old and has a very strong mildew smell. Location is Asset Management office. Contact Keshia Pigues 901.416.3562
Mallory Warehouse	12/12/2024 14:29	ANDREWS	Electrical	Z1-044775	reposition electrical outlet for bottle filler in the warehouse area by the office. See Franklin Owens. LIGHTS HAS GONE OUT ON THE BACK END OF THE BLDG - PM/WASHINGTON
Mallory Warehouse	12/3/2024 9:34	ANDREWS	Electrical	Z1-042794	
					Pump room one over Mallory building is constantly going off the alarm system (riser 4)
Mallory Warehouse	11/22/2024 13:46	GREER	Fire Alarm System	Z1-042095	RTU NOT HEATING
Mallory Warehouse	12/6/2024 12:41	WEBB	Heating/Ventilation/Air Conditioning	Z1-043833	MONOTHEANNO
					The Heating and A/C unit is not working
Mallory Warehouse Mallory Warehouse	12/2/2024 14:24 10/30/2024 15:46	OLIVER SIMMONS	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-042595 Z1-038977	ias gone completely out. I spoke with Director Charles Finnie and said he had a unit that he oicked up from a school that I could use. Replace AC / Heating Units. Heater does not work on one unit, and one has a short and blows out black dust. Contact Reggie Oliver 901.659.2627
Mallory Warehouse	9/25/2024 10:32	WEBB	Heating/Ventilation/Air Conditioning	Z1-034641	Suns du Back dasa Contact (Loggie Care Socios).
Mallory Warehouse	6/26/2024 15:44	CLARK	Key & Lock	Z1-019558	mallory warehouse end by bus lot, need the lock removed from the men's bathroom The conference room door will not stay closed in Director's office at 1384 Farmville. The
MallamaManahassa	0/00/00044440	CMITH	Kara O. Landa	74 000477	latch may need to be replaced
Mallory Warehouse	3/26/2024 14:46	SMITH	Key & Lock	Z1-006477	Step to entrance needs to be repaired.
Mallory Warehouse	9/4/2024 10:38	BURCHETT	Masonry	Z1-030875	D 571
Mallory Warehouse	10/30/2024 11:02	OWENS	Plumbing	Z1-038902	Bottle Filler Installation have fire hydrant temp meters read by MLGW
Mallory Warehouse	6/14/2024 10:42	WILSON	Plumbing	Z1-018388	
Mallory Warehouse	10/24/2024 13:12	HATCH	Sheet Metal	Z1-038226	Please fabricate flashing for roofer. See Ramon Diaz for measurements.
Mallory Warehouse	12/10/2024 7:48	OLIVER	Vehicle Maintenance	Z1-044159	Change oil, engine need service light is on dashboard and check transmission.
Mallory Warehouse	12/10/2024 7:46	OLIVER	Vehicle Maintenance	Z1-044157	Needs oil change and check transmission fluid
riationy wateriouse	12/10/2024 7.40		venicle Plantenance	21-044137	MONTHLY DRAW - AUTO SHOP MATERIALS/SUPPLIES FOR THE MONTH OF DECEMBER - 2024 HW
Mallory Warehouse	11/25/2024 8:38	DAVIS	Vehicle Maintenance	Z1-042156	Weld the dock plate to metal pole on dock
Mallory Warehouse	6/26/2024 7:27	OLIVER	Welding	Z1-019456	drop off boxes and pick up used fluorescent bulbs
Manassas High	12/15/2024 19:24	LANE	Asbestos	Z1-044950	מוסף אוז סטמבט מווע פופא עף מטבע וועטובטבטווג טענטט
Manassas High	12/12/2024 9:17		Carpentry	Z1-044591	The back of the door needs a door holder
Manassas High	3/18/2024 13:43	ARNOLD	Carpentry	Z1-005242	The ceiling towel grit is fall down in the ceiling. Needs to be fixed.
Manassas High	2/23/2024 13:59	RUSSELL	Carpentry	Z1-002723	The principal won't the desk cubbies removed out of this room.
Manassas High	5/17/2024 13:54	BENTON	Carpet Repair		he auditorium needs to come out the carpet is wet and molded i have have 3 water leaks in there. its smells.

Manassas High	12/12/2024 9:14	SMITH	Electrical	Z1-044588	A balance needs to be fixed
Manassas High	12/12/2024 9:04	SMITH	Electrical	Z1-044580	A balance needs to be fixed.
Manassas High	12/5/2024 8:05	SIMMONS	Electrical	Z1-043450	The latch on the back of the door has came off .
Manassas High	6/18/2024 9:45	WOOD	Energy Management System	Z1-018724	The Ems needs to be reset. The whole building is hot.
Manassas High	12/12/2024 9:52	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044661	Not heating
Manassas High	12/12/2024 9:51	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044660	Not heating
Manassas High	12/12/2024 9:50	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044659	Not heating
-	12/12/2024 9:50	WILLIAMS	-	Z1-044659 Z1-044657	
Manassas High Manassas High	12/12/2024 9:30	WILLIAMS	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z1-044654	Not heating
•			· ·		Not heating
Manassas High	12/12/2024 9:47	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044653	Not heating
Manassas High	12/12/2024 9:46	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044651	Not heating
Manassas High	12/12/2024 9:45	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044648	Not heating
Manassas High	12/12/2024 9:44	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044646	Not heating
Manassas High	12/12/2024 9:44	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044644	Not heating
Manassas High	12/12/2024 9:43	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044642	Not heating
Manassas High	12/12/2024 9:42	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044639	Not heating
Manassas High	12/12/2024 9:42	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044635	Not heating
Manassas High	12/12/2024 9:41	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044634	Not heating
Manassas High	12/12/2024 9:39	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044628	Not heating
Manassas High	12/12/2024 9:37	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044627	Not heating
Manassas High	12/4/2024 7:40		Heating/Ventilation/Air Conditioning	Z1-043108	We need the school to be changed to heat
Manassas High	12/3/2024 8:47	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042753	Need Heat
Manassas High	8/8/2024 8:21	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-026239	Cafeteria serving line so hot it's 95 degrees
Manassas High	8/5/2024 8:37	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-025098	85 degrees
Manassas High	8/5/2024 8:37	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-025095	90 degrees
Manassas High	8/5/2024 8:33	SIMMONS	Heating/Ventilation/Air Conditioning	Z1-025090	90 degrees
Manassas High	8/5/2024 8:31	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-025087	85 degrees
Manassas High	8/5/2024 8:30	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-025085	86 degrees
Manassas High	8/5/2024 8:23	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-025074	84 degrees
Manassas High	8/5/2024 8:16	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-025069	85 degrees
Manassas High	8/5/2024 8:15	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-025066	85 Degrees
Manassas High	8/5/2024 8:12	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-025055	83 degrees
Manassas High	8/5/2024 8:11	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-025050	88 degrees
Manassas High	8/5/2024 8:07	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-025046	86 degrees
Manassas High	8/5/2024 8:05	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-025043	85 degrees
Manassas High	7/11/2024 14:17	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-020943	84 degrees hot
Manassas High	6/24/2024 7:45	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-019117	82 degrees
Manassas High	6/24/2024 7:41	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-019115	83 degrees
Manassas High	6/24/2024 7:40	SIMMONS	Heating/Ventilation/Air Conditioning	Z1-019113	84 degrees hot
Manassas High	6/24/2024 7:39	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-019112	85 degrees
					REPAIR RTU #67
Manassas High	6/21/2024 7:52	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-018983	ner minion of
rianassas riigii	0/21/2024 / .02	WILLIAM	ricuting ventuation/air contaitioning	21 010000	RFPAIR RTU #66
Manassas High	6/21/2024 7:51	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-018982	TEL TITLE OF THE STATE OF THE S
rianassas riigii	0/21/2024 /.51	WILLIAMS	rieating ventitation/All Conditioning	21-010302	REPAIR RTU #65
Manassas High	6/21/2024 7:49	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-018976	NEI AIN NIO #03
Manassas High	5/15/2024 7:44	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-016576 Z1-014597	Room 85 degrees
-		WILLIAMS	_		
Manassas High	4/24/2024 9:07		Heating/Ventilation/Air Conditioning	Z1-011225	It's 85 degrees in this room
Manassas High	4/16/2024 8:10	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-009479	85 degrees hot
Manassas High	12/4/2024 9:36	BURCHETT	Painting	Z1-043223	The boys bathroom needs painting
Manassas High	12/4/2024 9:35	BURCHETT	Painting	Z1-043222	Needs painting
Manassas High	10/4/2024 11:04	BURCHETT	Painting		I painting bad. Manassas never had the restrooms painted someone came out but never painted them.
Manassas High	10/4/2024 11:00	BURCHETT	Painting	Z1-036281	The principal meeting room
Manassas High	7/31/2024 9:01	BURCHETT	Painting	Z1-024021	The bathrooms need painting they never painted them and the principal office
Manassas High	2/3/2024 16:41	BRYANT	Painting	WO1021801	the bathrooms needs to be painted
Manassas High	12/12/2024 9:36	SINK	Plumbing	Z1-044625	The commode is running over.
Manassas High	12/12/2024 9:18	SINK	Plumbing	Z1-044592	The 3rd sink is leaking
					POCA/ Dryer vent hose line shall be cleaned and documented
Manassas High	6/17/2024 10:23	STEPHENS	Sheet Metal	Z1-018543	
					Need annual bleacher inspection
Melrose High	6/21/2024 9:01	CALDWELL	Bleachers and Seats	Z4-018998	
Melrose High	2/3/2024 16:15	TEDDER	Bleachers and Seats	WO1023116	bleachers walkway needs repairing flooring has buckled up

shower in between football locker room and basketball locker room has a hole in the ceiling that needs to be covered and repaired

					that needs to be covered and repaired
Melrose High	12/11/2024 9:29	SMITH	Carpentry	Z4-044439	
Malvaca High	11/12/2024 7:40	FORD	Cornentny	74.040200	Mr. Harrison, 67706 exterior door henges are broken. Door won't completely close
Melrose High	11/12/2024 7:46	FORD	Carpentry	Z4-040366	lights in the auditorium need to be checked for Christmas program
Melrose High	12/12/2024 17:30	HALL	Electrical	Z4-044795	ugnes in the additional infeed to be checked for Christinas program
rieti ose riigii	12/12/2024 17.30	HALL	Electricat	24-044/93	5 bad ballost in the cafeteria
Melrose High	12/12/2024 11:19	HALL	Electrical	Z4-044702	o bad battost in the caretena
. 10.1 000 1 11g.1	12/12/2024 11/10		Etotilout	24 044702	3 bad ballost in the basketball locker room
Melrose High	6/4/2024 12:29	HALL	Electrical	Z4-017141	
0					Replace receptacles with GFIC where needed
Melrose High	4/29/2024 11:52	CHALK	Electrical	Z4-011995	
· ·					8 bad ballost in the library
Melrose High	2/20/2024 12:43	HALL	Electrical	Z4-002130	
Melrose High	2/3/2024 16:14	HALL	Electrical	WO1023925	lights on the west and north parking lots lights need to be replaced its very dark and cant see
					annual 5 year inspection needs to be done for sprinkler system
Melrose High	6/18/2024 12:00	CALDWELL	Fire Sprinkler System	Z4-018774	
					6 broken floor tiles needs to be replaced
Melrose High	12/11/2024 9:51	LEWIS	Flooring	Z4-044444	
					display cases near rooms 139 and 137 needs the locks changed so admin can change the
					displays
Melrose High	11/12/2024 8:49	MALONE	Key & Lock	Z4-040388	
Melrose High	5/17/2024 14:17	CORONADO	Masonry	WO999049	peice of concrete in the courtyard needs repairing its cracked ans looks like its gonna fall
					paint is chipping on the wall near classroom 218
Melrose High	9/17/2024 8:55	BURCHETT	Painting	Z4-033094	
					room 233 needs to be painted the wall are peeling
Melrose High	5/30/2024 13:16	BURCHETT	Painting	Z4-016530	
					SHOWER RUNNING WILL NOT CUT OFF - KNOB MAY BE STRIPPED - CAN'T CONTAIN IT
					BETWEEN THE FOOTBALL LOCKER ROM & BASKETBALL LOCKER ROOM
					P/M HARRISON 416-7706
Melrose High	12/6/2024 15:37	JOHNSON	Plumbing	Z4-043889	
		1011110011	B	74.044700	only one side of the stall in the boys restroom is working
Melrose High	11/20/2024 14:28	JOHNSON	Plumbing	Z4-041788	
					3rd toilet in boys restroom is leaking and needs to be glued down to keep from moving
Melrose High	11/20/2024 14:12	JOHNSON	Plumbing	Z4-041778	Sid tottet in boys restroom is teaking and needs to be guide down to keep from moving
rieti ose riigii	11/20/2024 14.12	JOHNSON	Fluilibilig	24-041//0	water fountain has water coming back up through drain
Melrose High	11/20/2024 14:09	JOHNSON	Plumbing	Z4-041773	water rountain has water coming back up through drain
rieti ose riigii	11/20/2024 14.09	JOHNSON	Fluilibilig	24-041//3	first toilet in girls restroom is leaking when flushed
Melrose High	11/20/2024 14:03	JOHNSON	Plumbing	Z4-041766	institutet in girs restroom is teaking when itusired
rieu ose riigii	11/20/2024 14.03	JOHNSON	rumbing	24-041/00	first toilet in girls restroom won't flush properly
Melrose High	11/20/2024 14:01	JOHNSON	Plumbing	Z4-041765	inst toller in girts restroom won't hash property
ricadocriigii	11/20/2024 14.01	3011140014	rumbing	24 041/00	second sink in girls restroom won't stop running
Melrose High	11/20/2024 13:57	JOHNSON	Plumbing	Z4-041764	occord control gree received mon cotop running
					second toilet in boys restroom is leaking when flushed
Melrose High	11/20/2024 13:47	JOHNSON	Plumbing	Z4-041763	
					first toilet in girl's restroom has a bad leak when flushed
Melrose High	11/19/2024 9:27	JOHNSON	Plumbing	Z4-041453	······································
					sink needs to be put back on the wall
Melrose High	11/19/2024 9:11	JOHNSON	Plumbing	Z4-041436	
Melrose Stadium	4/25/2024 13:24	HALL	Electrical	Z4-011586	Light out in Melrose's Women's Restroom. Thanks!
					outside lights
Messick Training Center	11/8/2024 7:28	HALL	Electrical	Z4-040230	······ v
Messick Training Center	9/18/2024 9:30	TEDDER	Electrical	Z4-033386	Lights outside B building in alley and outside front entrance door are out. Safety issue for staff.
Messick Training Center	8/26/2024 7:49	HALL	Electrical	Z4-029388	Bad ballast in women's restroom.
9 · · ·					Need a Carbon Monoxide detector in boiler room.
Messick Training Center	4/2/2024 9:42	HALL	Electrical	Z4-007252	
Messick Training Center	6/6/2024 9:34	CALDWELL	Elevators	Z4-017517	Door not closing to elevator consistently.
Messick Training Center	3/25/2024 14:59	SMITH	Key & Lock	Z4-006220	is sets of stadium master keys for Memphis Shelby County Schools Custoddial and Grounds Management
Messick Training Center	2/27/2024 10:47	SMITH	Key & Lock	Z4-003023	pies of the following keys for Messick Building B -2 Keys RM 105 Key Code AE4; 1 Key RM 203 Key Code AC4.
		-	.,		, , , , , , , , , , , , , , , , , , , ,

					Install Bottle Filler for training
Messick Training Center	5/7/2024 9:10	WILSON	Plumbing	Z4-013369	
Messick Training Center	11/7/2024 8:53	GILL	Roofing	Z4-040044	Roof leaking in classroom 2 , Training center Front of Gym.
Messick Training Center	9/23/2024 9:54	GILL	Roofing	Z4-034169	Roof leaking in B building 2nd floor hallway.
Messick Training Center	11/4/2024 12:09	DAVIS	Vehicle Maintenance	Z4-039465	of an Oil Change and a Windshield Replacement. Also plug rear driver side tire. Additionally, please top all fluids off.
Middle College High	12/13/2024 10:15	BURKE	Carpentry	Z2-044870	; the door to unsupported when opening and closing I have the piece to insert but no smaller screw to keep it from coming again
Middle College High	12/6/2024 14:16	BURKE	Carpentry	Z2-043868	outside resting area. Door isn't securing. Requires pressure to close manually door pump may needs adjusting
Middle College High	12/4/2024 10:02	BURKE	Carpentry	Z2-043259	Center bar is freelancing no brace at bottom to stabilize
Middle College High	11/1/2024 13:27	BURKE	Carpentry	Z2-039303	Replace baseboard that was demoed due to termite damage
Middle College High	12/13/2024 10:35	STAFFORD	Electrical	Z2-044881	Power socket behind ice maker is not working.
Middle College High	12/3/2024 12:28	POWELL	Electrical	Z2-042961	Light bulb need to be replaced. It's about 20 feet high
Middle College High	12/3/2024 10:40	POWELL	Electrical	Z2-042875	Bad light ballast
Middle College High	10/24/2024 14:34	POWELL	Electrical	Z2-038249	Bad L E D bulb or ballast
Middle College High	10/16/2024 10:31	POWELL	Electrical	Z2-037210	Bad motion light switch. Constantly goes off
Middle College High	8/6/2024 9:18	POWELL	Electrical	Z2-025547	Bad light ballast
Middle College High	8/2/2024 9:25 4/30/2024 10:24	POWELL	Electrical Electrical	Z2-024684	Wall sockets on central side isn't working. Breaker will not allow me to reset it.
Middle College High Middle College High	4/25/2024 10:24	POWELL	Electrical	Z2-012231 Z2-011546	Lost power lights, sockets Automatic light switch continues to go out 2mins tops. Need motion to stay on!
Middle College High	4/24/2024 12:54	POWELL	Electrical		Zephyr ceiling fan due to loud aggressive noise when light is turned on. Be mindful light and fan runs together.
Middle College High	11/13/2024 9:33	Coleman	Elevators	Z2-011544 Z2-040607	Elevator is not responding to floors. Doors are barely opening.
Middle College High	5/17/2024 14:32	Flevator	Elevators	WO1016089	Elevator is not responding to rooms boards are barely opening. Elevator is not responding to commands. Not operable!
Middle College High	2/21/2024 9:26	SAVAGE	Fire Extinguishers	Z2-002253	New fire extinguisher needed the one that's here is damaged
Middle College High	3/7/2024 13:15	CASEY	Flooring	Z2-004494	Please repair carpet where new book shelves was installed. Please see pics for clarity
Middle College High	2/3/2024 14:44	CASEY	Flooring	WO1030579	Please remove carpet from entire main office due to a flood.
					Mr. Holmes
					66197
					no air blowing
Middle College High	12/5/2024 11:14	HANSON	Heating/Ventilation/Air Conditioning	Z2-043574	
					UNIT NOT HEATING - WEIGHT ROOM IN THE GYM
					P/M HOLMES 416-6197
Middle College High	12/4/2024 12:01	HANSON	Heating/Ventilation/Air Conditioning	Z2-043351	
Middle College High	11/20/2024 13:16	MALONE	Key & Lock	Z2-041759	Center bars not allowing A to unlock them
Middle College High	11/20/2024 13:11	MALONE	Key & Lock	Z2-041757	Broken key in cylinder
Middle College High	2/12/2024 12:26	SMITH	Key & Lock	Z2-001013	Install replacement lock on glass access window.
Middle College High	10/3/2024 9:53	BURCHETT	Painting	Z2-036060	Please repaint office
Middle College High	7/10/2024 10:19	BURCHETT	Painting	Z2-020724	lease repaint office walls are holding moisture and moldy. Paint is chipping and flaking all over
Middle College High	7/10/2024 10:17	BURCHETT	Painting	Z2-020723	Please repaint office area
Middle College High	7/10/2024 10:15	BURCHETT	Painting	Z2-020722	Please scrape and repaint wall
Middle College High	7/9/2024 13:57	BURCHETT	Painting	Z2-020630	Paint rails back brown
Middle College High	2/22/2024 10:39	BURCHETT	Painting	Z2-002468	ng to have moisture damaged paint scraped and removed and repainted. Please see pictures for clarity.
Middle College High Middle College High	2/3/2024 17:03 5/17/2024 14:27	BRYANT BRYANT	Painting Painting	WO1018145 WO1011962	some painting near pipes and 1st floor needs painting. Please see plant manager for specific touch-up areas. Please paint main entry doors.
Middle College High	5/17/2024 14:27	BURCHETT	Painting	WO1011302 WO1000303	Please paint main end y doors. Please paint outside railing.
Middle College High	10/22/2024 13:24	WHITE	Sheet Metal	Z2-037879	adjusted. Causing all water from 3rd floor roofing to run to 2nd floor roofing causing flooding sitting on top of cafeteria
Mitchell High	11/7/2024 8:47	ARNOLD	Carpentry	Z4-040038	Have to slam door to secure it please send assistance asap.
Mitchell High	11/18/2024 8:31	HALL	Electrical	Z4-041199	On top of main building lights are blinking nonstop, needs assistance asap.
					MR. STREETER 68174 UNIT BLOWING COLD AIR
Mitchell High	12/3/2024 8:33	DOWNER	Heating/Ventilation/Air Conditioning	Z4-042736	
· ·			· ·		Mr. Streeter 68174 units not coming on
Mitchell High	12/2/2024 9:20	DOWNER	Heating/Ventilation/Air Conditioning	Z4-042337	
					Mr. streeter 68174 water running out of hot water pump non stop
Mitchell High	11/19/2024 8:55	DOWNER	Heating/Ventilation/Air Conditioning	Z4-041426	
Mitchell High	8/19/2024 16:07	SMITH	Key & Lock	Z4-028483	The Principal wants the room rekeyed to a SKD6 asap.
Mitchell High	11/18/2024 8:43	BURCHETT	Painting	Z4-041205	main building needs to be pressure washing BADLY this is first impression looks very bad please advise
Mitchell High	7/30/2024 9:55	BURCHETT	Painting	Z4-023685	d asked me did I have a work order on getting the top of main building pressure wash I didn't have one PLEASE HELP and assist me in this matter asap.
Mitchell High	6/12/2024 9:13	BURCHETT	Painting	Z4-018112	On the left side rear of cafeteria pipe has been repaired wall needs painting asap looks bad ect.
Mitchell High	11/21/2024 8:23	HARRIS	Plumbing	Z4-041848	: handicap commode has water pouring out the back when flushed please send assistance asap.
Mitchell High	11/21/2024 8:18	HARRIS	Plumbing	Z4-041844	ll three commode came completely up and flooded the entire area please send assistance asap.
Mitchell High	11/5/2024 9:33	HARRIS	Plumbing	Z4-039578	In the boiler room there are two none stop leaks above head please assist me in this matter.
Mitchell High	10/30/2024 8:21	HARRIS	Plumbing	Z4-038835	Sink is falling off the wall could be hazardous.
Mitchell High	10/16/2024 17:28	HARRIS	Plumbing	Z4-037272	ty water fountains in cafeteria are stopped up can't used them at all please send assistance asap
Mitchell High	10/15/2024 13:47	HARRIS	Plumbing	Z4-037082	oys restroom 1st stall is so stopped up my snake won't unstop it please send assistance asap.
Mitchell High	9/4/2024 20:57	HARRIS	Plumbing	Z4-030991	re leaking water from the bottom of commode every time you flush needs over rings and they are very lose PLEASE send assistance asap.

					MLGW just left wanted the back flow to be tested asap
Mitchell High	5/29/2024 12:04	PILKINGTON	Plumbing	Z4-016312	Picow just left wanted the back now to be tested asap
Mitchell High	11/19/2024 9:27	STEVENSON	Roofing	Z4-041454	Roof leaks when raining and after raining please send assistance asap.
Mitchell High	9/12/2024 16:18	STEVENSON	Roofing	Z4-032346	Locker room area is flooded from leaking roof please advise
Ü			· ·		I have a outside intercom is not working right it is making muffle sound need someone to
					take a look at it
Mt. Pisgah Middle/High	10/7/2024 8:38	SMITH	Audio Visual	Z2-036388	
					the intercom in room is not working need someone to take a look at it
Mt. Pisgah Middle/High	9/4/2024 14:24	SMITH	Audio Visual	Z2-030969	
					I need someone to come out and repair my bleacher, we are having the district basketball
					games at the school on 17th.
Mt. Pisgah Middle/High	12/6/2024 10:50	Coleman	Bleachers and Seats	Z2-043807	
					I need someone to come out to restore power to my bleacher on the southside of the gym
					and can we have a switch install on the wall with a key to it so it could control it my the
					coaches and plant manager.
Mt. Pisgah Middle/High	4/4/2024 11:37	LEWIS	Bleachers and Seats	Z2-007755	
					Land and the control of the late Bake Bake and the State of the State
MA Disease Middle (Link	40/0/000440-07	DOWELL	Floring	70.040004	I need someone to come out and check the lights on stage we are having a holiday concert.
Mt. Pisgah Middle/High	12/6/2024 10:37	POWELL	Electrical	Z2-043801	Land and the same of a same of the standards and the standards at the standards and the standards at the sta
Mt Diogob Middle / Lligh	11/7/2024 10:17	ROY	Electrical	70.040100	I need someone to come out and check my basketball goal it will not operate.
Mt. Pisgah Middle/High	11///2024 10:1/	RUY	Electrical	Z2-040100	I have two hallway lights that is not working the balance is not working need someone to
					come out and take a look
Mt. Pisgah Middle/High	10/14/2024 9:22	POWELL	Electrical	Z2-036804	Come out and take a took
Mt. Pisgah Middle/High	10/8/2024 13:16	POWELL	Electrical	Z2-036634	ıllway that will not come on I have changed out the light but it still won't come on need someone to take a look at it
Tit. Tisgair naate/riigii	10/0/2024 10:10	TOWLLL	Electricat	22 000004	I have several outlets in the cafeteria that is not working I check the breaker box and one of
					the breaker keep tripping out need some one to take a look at it
Mt. Pisgah Middle/High	9/17/2024 7:49	POWELL	Electrical	Z2-033067	
					the area of refuge sing battery needs to be replace
Mt. Pisgah Middle/High	8/27/2024 9:01	POWELL	Electrical	Z2-029754	
					the exit sing up stairs the battery needs to be replaced (1)
Mt. Pisgah Middle/High	8/27/2024 8:58	POWELL	Electrical	Z2-029748	
					the exit sing in the library battery needs to be replaced (2)
Mt. Pisgah Middle/High	8/27/2024 8:55	POWELL	Electrical	Z2-029745	
					the exit sing in the library needs to be replace (1)
Mt. Pisgah Middle/High	8/27/2024 8:53	POWELL	Electrical	Z2-029742	
					the spot light on the exit sing is not working
Mt. Pisgah Middle/High	8/27/2024 8:50	POWELL	Electrical	Z2-029739	
	0.000.000.000	DOLLIE I	E	70 000707	the exit light battery needs to be replaced (2)
Mt. Pisgah Middle/High	8/27/2024 8:48	POWELL	Electrical	Z2-029737	a sea era i
MA Disease Middle (Litely	0.07.0004.0.40	DOWELL	Flootrical	70 000700	the exit light spot light needs to be replaceed
Mt. Pisgah Middle/High	8/27/2024 8:42	POWELL	Electrical	Z2-029733	the suit light and light needs to be replaced (#5)
Mt. Pisgah Middle/High	8/27/2024 8:39	POWELL	Electrical	Z2-029730	the exit light spot light needs to be replaced (#5)
Pit. Flagari Piludie/Fligii	0/2//2024 0.39	TOWLLL	Liectricat	22-023730	I have a exit light need battery replace
Mt. Pisgah Middle/High	8/27/2024 8:30	POWELL	Electrical	Z2-029719	Thave a care agreenced bactery reptace
Titt iogair nadic/riigh	0.27.2024 0.00		2.001.1001	22 020710	
					I a electrician to come out and on the power to a A/C unit the breaker keep tripping out
Mt. Pisgah Middle/High	8/22/2024 9:27	POWELL	Electrical	Z2-029060	
Mt. Pisgah Middle/High	8/15/2024 23:10	POWELL	Electrical	Z2-027940	I have an outlet that need to be replaced so sparks come from it
Mt. Pisgah Middle/High	2/14/2024 7:47	POWELL	Electrical	Z2-001340	I have five lights that is not working need to be completely changed out
					I have two lights on the right side out that is not working need someone to take a look at
					them
Mt. Pisgah Middle/High	2/13/2024 11:22	POWELL	Electrical	Z2-001228	
					Light fixtures need to be replaced
Mt. Pisgah Middle/High	2/5/2024 13:18	POWELL	Electrical	Z2-000236	
					the fire alarm it is showing bad smoke detector
Mt. Pisgah Middle/High	12/9/2024 8:28	Coleman	Fire Alarm System	Z2-043963	
					Per State Fire InspecReplace smoke detector in Rm. 109 that is not working properly.
Mt. Pisgah Middle/High	3/19/2024 14:47	Coleman	Fire Alarm System	Z2-005446	The second secon
Mt Diogob Middle / Lligh	12/13/2024 8:30	BRYSON	Hooting//ontilation/Air Conditioning	70 044027	I need someone to come out to take a look at the unit to the cafeteria
Mt. Pisgah Middle/High	12/13/2024 8:30	NUCTAD	Heating/Ventilation/Air Conditioning	Z2-044837	

					I need room 137 painted requested by the principal please
Mt. Pisgah Middle/High	6/3/2024 8:36	BURCHETT	Painting	Z2-016857	mod toom 20% painted requested by the principal product
Newberry Elementary	11/6/2024 10:21	BARNES	Carpentry	Z3-039822	Doors not closing has to be pulled to close
Newberry Elementary	10/18/2024 16:03	WEBB	Carpentry	Z3-037538	Divider door in between urinal is off
Newberry Elementary	6/27/2024 13:39	BENTON	Carpet Repair	Z3-019670	Carpet removed per principal request
Newberry Elementary	11/22/2024 12:51	SCOTT	Electrical	Z3-042086	Ballast out
Newberry Elementary	10/16/2024 20:18	SCOTT	Electrical	Z3-037274	Lights need to be replaced
Newberry Elementary	9/16/2024 7:03	SCOTT	Electrical	Z3-032758	Need power to the sinks
Newberry Elementary	4/4/2024 6:17	SCOTT	Electrical	Z3-007658	Ventahood not working
Newberry Elementary	4/3/2024 13:36	WHITWORTH	Electrical	Z3-007632	Clock need to changed
					Resolution:
					Upon arrival, the panel had 18 troubles. All devices except 1 are known to be located in
					Annex 1 Bldg. The last device does not have a location or anything in the custom label. Went
					to Annex 1 and checked the wiring. The data wiring does not have power. I could not find the
					location of the power loss or disconnect. Upon departure the panel had 18 troubles.
Newberry Elementary	12/9/2024 8:55	SMALL	Fire Alarm System	Z3-043980	totalion of the portor total of the apparture the partornal 20 totalion.
Newberry Elementary	11/21/2024 12:40	0111122	Fire Alarm System	Z3-041958	Panel is constantly beeping NAC1 /Non compliance
Newberry Elementary	3/12/2024 8:10	SMALL	Fire Alarm System	Z3-004863	Fire inspection and safety sheets.POCA
Newberry Elementary	11/14/2024 12:56	CASEY	Flooring	Z3-040881	Carpet removal per principal request
Newberry Elementary	11/14/2024 12:00	ONOLI	rtoomig	20 040001	HVAC UNIT IN THE CAFE - BLOWING NOT COOLING PM/TERRELL 416-2518
Newberry Elementary	4/18/2024 10:03	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-010223	THAO ONLY IN THE OALE DEOMINO NOT GOODING THAT EMILEE 410 2010
Newberry Elementary	10/16/2024 9:29	MALONE	Key & Lock	Z3-037184	Key needed for bars on doors to the Annex2 building
Newberry Elementary	9/19/2024 10:54	MALONE	Key & Lock	Z3-037104 Z3-033725	Needs extra key per principal request
Newberry Elementary	9/19/2024 10:53	MALONE	Key & Lock	Z3-033723	Need extra keys for PLC room
Newberry Elementary	5/31/2024 7:14	BURCHETT	Masonry	Z3-033723 Z3-016619	Tiles needed around base of wall
Newberry Elementary	3/7/2024 11:22	CORONADO	Masonry	Z3-010015	Floors holding moisture safety hazard
Newberry Elementary	12/4/2024 13:30	BURCHETT	Painting	Z3-0443385	Touch up paint for cafeteria per principal request for programs
Newberry Elementary	11/18/2024 15:00	BURCHETT	Painting	Z3-043363	Classrooms doors paint faded very badly
Newberry Elementary	10/18/2024 9:13	BURCHETT	Painting	Z3-041337 Z3-037471	Paint is faded and peeling
Newberry Elementary	10/18/2024 9:13	BURCHETT	Painting	Z3-037471 Z3-037457	Paint is faded and peeling Paint is faded and peeling
Newberry Elementary	10/17/2024 12:19	BURCHETT	Painting	Z3-037437	Painting is faded and peeling
Newberry Elementary	10/17/2024 12:17	BURCHETT	Painting	Z3-037387	Paint peeling and faded
Newberry Elementary	10/9/2024 13:49	BURCHETT	Painting	Z3-03/36/	Outside entry and exit doors
Newberry Elementary	5/31/2024 7:25	BURCHETT	Painting	Z3-036745 Z3-016625	Painting is needed
Newberry Elementary	5/31/2024 7:23	BURCHETT	Painting	Z3-016624	Painting is needed
Newberry Elementary	4/25/2024 9:42	BURCHETT	Painting	Z3-010024 Z3-011468	Need painting per principal request
Newberry Elementary	2/28/2024 11:21	BURCHETT	Painting	Z3-011466 Z3-003251	Labeled parking spaces per principal request
Newberry Elementary	5/17/2024 14:03	BURCHETT	Painting	W0994177	main building room 10 need painted pre- principle
Newberry Eternemany	0/1//2024 14.00	DONONETT	Landing	110004177	annual testing of the backflow preventers
Newberry Elementary	10/3/2024 13:25	WILSON	Plumbing	Z3-036147	
Newberry Elementary	9/9/2024 15:31	BARNES	Plumbing	Z3-031615	Water fountain is leaking from underneath
Newberry Elementary	8/7/2024 13:07	BARNES	Plumbing	Z3-026115	Water fountain is leaking
Newberry Elementary	11/13/2024 11:26	BARNES	Roofing	Z3-040651	Awning is leaking bad
Newberry Elementary	11/8/2024 8:52	BENTON	Shades/Blinds	Z3-040249	Blind needed window empty
Newberry Elementary	3/6/2024 9:14	BENTON	Shades/Blinds	Z3-004178	Need blinds don't have any up
Newberry Elementary	2/16/2024 15:45	BENTON	Shades/Blinds	Z3-001785	Replace blinds
					Girls' restroom door need adjusting.
Norris Achievement Academy MS	10/15/2024 10:04	FORD	Carpentry	Z4-037031	
Norris Achievement Academy MS	10/7/2024 15:57	FORD	Carpentry	Z4-036539	Ceiling Grid has rusted out need to be replaced and the pipe above the leaks.
					Floor tiles need to be replaced from HVAC unit leaking. 1 box
Norris Achievement Academy MS	7/11/2024 14:00	FORD	Carpentry	Z4-020939	
					Exterior light is out on the back side of the building. Need bucket truck.
Norris Achievement Academy MS	10/29/2024 12:18	HALL	Electrical	Z4-038741	
					When pressing the button, the emergency light blinks red and green in the band room # Rm.
					14
Norris Achievement Academy MS	9/16/2024 10:00	HALL	Electrical	Z4-032891	
					Wall outlet does not work. The outlets on the wall is at lease 4ft tall on the wall and I believe
	= 10.4 10.0 · · · · · · ·			74.0	that both are tied together.
Norris Achievement Academy MS	7/31/2024 9:06	HALL	Electrical	Z4-024029	
	40/5/005 : :				Mr. Reid (416 5006) Norris Achievement Rm206 Unit blowing cold air but no heat
Norris Achievement Academy MS	12/5/2024 13:38	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-043662	No Poid (440 F000) Nomic Autison work P. 200
Namic Achieves	40/5/00011007	MARILINATION	Handing Official Co. Co. Co.	74.01000	Mr. Reid (416 5006) Norris Achievement Rm203 Unit blowing cold air but no heat
Norris Achievement Academy MS	12/5/2024 13:37	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-043660	

					Mr. Daid (440 5000) Navia Ashiousmant Academy ym 200 Unit is yngenenaige
Norris Achievement Academy MS	12/4/2024 11:19	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-043328	Mr. Reid (416 5006) Norris Achievement Academy rm 202 Unit is unresponsive
Norris Achievement Academy MS	12/4/2024 11:18	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-043327	Mr. Reid (416 5006) Norris Achievement Academy rm 205 Unit is unresponsive
					Key made for Rm. 201.
Norris Achievement Academy MS	10/29/2024 10:30	MALONE	Key & Lock	Z4-038705	Key made for storage closet in the teacher's lounge next to the main office.
Norris Achievement Academy MS	10/29/2024 9:25	MALONE	Key & Lock	Z4-038669	Key made for the storage closet in the main office.
Norris Achievement Academy MS	10/29/2024 9:18	MALONE	Key & Lock	Z4-038666	Key made for the Secretary office inside the main office.
Norris Achievement Academy MS	10/29/2024 9:15	MALONE	Key & Lock	Z4-038665	
Norris Achievement Academy MS	2/23/2024 15:24	CORONADO	Masonry	Z4-002749	The Principal's Office has 2 windows that need to be sealed. Wasp and various other insects are coming into the building at that the top of the window ledge which is concrete.
					Rm. 304,305 and 306 has cracks in the concrete ceiling. Cracks need to be sealed with some type of sealant. Wasp and insects are coming into the building through the cracks into the class rooms when it gets warm outside. Per Pest Control Techs they are reporting that it's a building structure issue. WO #1032421
Norris Achievement Academy MS	2/22/2024 14:47	CORONADO	Masonry	Z4-002540	POCA Visible address need to be painted in front of the school.
Norris Achievement Academy MS	10/28/2024 13:22	BURCHETT	Painting	Z4-038568	Girl's restroom near the main office on the 2nd floor toilet seat is broken.
Norris Achievement Academy MS	12/12/2024 14:38	JOHNSON	Plumbing	Z4-044777	
Norris Achievement Academy MS	10/29/2024 15:30	JOHNSON	Plumbing	Z4-038796	2nd stall toilet do not flush properly.
Navia Ashia amant Asadamu MC	11/13/2024 15:33	GILL	Doofing	Z4-040705	Rm. 303 has 2 leaks from the ceiling tile.
Norris Achievement Academy MS North Area Office	10/28/2024 10:50	SIMMONS	Roofing Electrical	Z1-038520	replace 3 light fixture covers
					Ms. Cox (5904) North Area Office Rooftop Unit blows air but not heating
North Area Office North Area Office	12/3/2024 13:35 2/20/2024 15:12	WEBB SMITH	Heating/Ventilation/Air Conditioning Key & Lock	Z1-043005 Z1-002163	I need 2 SKD 25 keys
North Area Office	2/20/2024 15.12	SMILL	Key & LOCK	21-002163	Tilleeu 2 SKD 25 keys
North East Regional Office	7/26/2024 10:17	POWELL	Electrical	Z2-022867	Please replace battery in emergency exit light/sign A3 located in old kitchen/storage room.
North East negional office	772072024 10.17	TOWELL	Electrical	22 022007	Please replace (2) two ballasts in hallway.
North East Regional Office	7/23/2024 18:03	POWELL	Electrical	Z2-022219	Please replace ballast in director's office.
North East Regional Office	7/23/2024 18:02	POWELL	Electrical	Z2-022218	
Northaven Elementary	8/1/2024 14:47	ARNOLD	Carpentry	Z1-024562	to replace fallen ceiling tile. I was told someone from HVAC damaged the tile and left it hanging. Please help.
Northaven Elementary	2/15/2024 8:11	CASEY	Carpet Repair	Z1-001498	nen loading dock door needs new door sweep on bottom to help prevent rodent activity in kitchen.
Northaven Elementary	12/5/2024 18:16	SMITH	Electrical	Z1-043692	out for washer that has been roughed in. Had to move from original electrical drop. See Daniel Avanzi for exact location.
Northaven Elementary	10/28/2024 13:48	SMITH	Electrical	Z1-038575	Canopy lights not working
Northaven Elementary	9/3/2024 9:09	CHALK	Electrical	Z1-030631	Canopy walk way lights not working tripping breaker
Northaven Elementary	3/27/2024 9:21	CHALK	Electrical	Z1-006550	Outside wall light 2
Northaven Elementary	3/27/2024 9:19	CHALK	Electrical	Z1-006549	Outside wall lights 2 on the front side 1 on rear
Northaven Elementary	3/27/2024 9:16	CHALK	Electrical	Z1-006546	4 high wall lights out 2 on the front 1 on parking lot 1 on teachers entry
Northaven Elementary	2/3/2024 17:14	CHALK	Electrical	WO1023381	Front entry walk way has 3 fixtures out 1 has burned out HEATING UNIT IN RM 30 - NOT COMING ON PM/TRUESDALE 416-2800
Northaven Elementary	12/3/2024 10:02	WEBB	Heating/Ventilation/Air Conditioning	Z1-042832	HEATING UNIT IN RM 25 - NOT COMING ON PM/TRUESDALE 416-2800
Northaven Elementary	12/3/2024 10:02	WEBB	Heating/Ventilation/Air Conditioning	Z1-042829	HEATING UNIT IN RM 22 - NOT COMING ON PM/TRUESDALE 416-2800
Northaven Elementary	12/3/2024 10:01	WEBB	Heating/Ventilation/Air Conditioning	Z1-042827	HEATING UNIT IN RM 17 - NOT COMING ON PM/TRUESDALE 416-2800
Northaven Elementary	12/3/2024 10:00	WEBB	Heating/Ventilation/Air Conditioning	Z1-042826	UNIT NOT COMING ON - CL-RM 28
					P/M CHARLES TRUESDALE 416-2800
Northaven Elementary	8/26/2024 8:45	WEBB	Heating/Ventilation/Air Conditioning	Z1-029440	UNIT NOT COMING ON - CL-RM 26
Northaven Elementary	8/26/2024 8:44	WEBB	Heating/Ventilation/Air Conditioning	Z1-029439	P/M CHARLES TRUESDALE 416-2800

HVAC UNIT IN RM 21 - NOT COMING ON PM/TRUESDALE 416-2800

					HVAC UNIT IN RM 21 - NOT COMING ON PM/TRUESDALE 416-2800
Northaven Elementary	8/15/2024 8:28	WEBB	Heating/Ventilation/Air Conditioning	Z1-027679	
					Paint peeling on walls
Northaven Elementary	9/30/2024 8:27	BURCHETT	Painting	Z1-035323	
Northaven Elementary	5/3/2024 7:29	BURCHETT	Painting	Z1-012900	2 supply closet doors need painted
Northaven Elementary	5/3/2024 7:25	BURCHETT	Painting	Z1-012897	Custodial closet door need painted
,					REMOVE 9X9 CEILING TILES THROUGHOUT BUILDING
Northeast Prep Academy	11/6/2024 13:06	AMOS	Asbestos	Z2-039909	
Northeast Prep Academy	10/23/2024 9:08	POWELL	Electrical	Z2-037946	all outlets that have randomly went out and I have checked every breaker box in the school to try to solve this issue.
Northeast Prep Academy	9/25/2024 10:40	POWELL	Electrical	Z2-03/540 Z2-034644	acoutes that have randomly when our and make disease over pleases book in the source of the state. rical socket under the water fountain is not working by the Women's restroom downstairs hallway.
	4/29/2024 14:16	POWELL	Electrical		
Northeast Prep Academy				Z2-012082	Light switch in cafeteria located by the lunch line area is not working correctly
Northeast Prep Academy	4/24/2024 11:37	POWELL	Electrical	Z2-011303	Light fixture not working at all
Northeast Prep Academy	4/24/2024 8:46	POWELL	Electrical	Z2-011208	2 unbalanced light fixtures, hallway upstairs
Northeast Prep Academy	4/24/2024 8:14	POWELL	Electrical	Z2-011193	2 Unbalanced light fixture and 1 light fixture not working at all
Northeast Prep Academy	10/29/2024 10:19	Coleman	Fire Alarm System	Z2-038701	Emergency Exit Window Sticker
Northeast Prep Academy	10/15/2024 10:31	Coleman	Fire Alarm System	Z2-037042	Replace FACP batteries (12v 18ah)
Northeast Prep Academy	10/29/2024 9:50	LEWIS	Fire Extinguishers	Z2-038684	We need Fire Extinguisher Stickers
Northeast Prep Academy	8/15/2024 12:11	SMITH	Key & Lock	Z2-027826	ist from principal Dickerson, and we need one master key, as well as several classroom keys for rooms 200, 107, 210, 208
Northeast Prep Academy	12/3/2024 10:26	BURCHETT	Painting	Z2-042856	teacher that starts on the 16 this month. The kids have written inappropriate gang graffiti all over the walls in bright since it was a sub throughout this school year
					Down stairs boys restroom leaking from pipe
Northeast Prep Academy	12/12/2024 13:10	PILKINGTON	Plumbing	Z2-044743	
			_		Heaters for boiler room
Northeast Prep Academy	12/12/2024 6:46	WHITE	Sheet Metal	Z2-044524	
,					Requesting hoisting cord replacement, not able to raise flag
Nutrition Services	7/2/2024 6:35	WILSON	Carpentry	Z1-020015	
Natificial Scivices	77272024 0.00	WILDOIT	Garpenay	21 020010	Requesting damage low bearing wall replaced ,hit by forklift
Nutrition Services	4/19/2024 9:59	RUSSELL	Comentn	Z1-010698	nequesting damage tow bearing water-praced , int by fortain
Nutrition Services	4/19/2024 9.59	KUSSELL	Carpentry	21-010098	Receptionist phone when depressing open gate will not work. Technician came and
	40/00/000445 40	50.005	E	7	replaced the phone but gate still won't open
Nutrition Services	10/23/2024 15:48	FINNIE	Electrical	Z1-038064	
					Emergency lights not working
Nutrition Services	9/24/2024 9:10	CHALK	Electrical	Z1-034424	
					Requesting replacing bad light ballast
Nutrition Services	9/23/2024 12:10	SMITH	Electrical	Z1-034255	
					Requesting burned out ballast replaced.
Nutrition Services	9/16/2024 8:07	SMITH	Electrical	Z1-032802	
					Requesting burned out bulbs replaced, 23 poles
Nutrition Services	9/16/2024 8:04	CHALK	Electrical	Z1-032798	
					Requesting 4 burned out high ceiling lights replacement. We have bulbs available. Scissor
					lift on sit.
Nutrition Services	8/15/2024 7:52	SMITH	Electrical	Z1-027648	
					Requesting bad light ballast replacement
Nutrition Services	8/15/2024 7:47	SMITH	Electrical	Z1-027645	
Nutrition Services	4/2/2024 15:02	CHALK	Electrical	WO985740	t working, located at Annex building rear double side Exit Door (on the wall). 3176 Jackson Ave. Memphis Tn 38112. Contact: Alonso Araujo
Nutrition Services	4/2/2024 15:02	CHALK	Electrical	W0985751	
Nutrition Services	4/2/2024 15:02	CHALK	Electrical	W0985734	
Nutrition Services	4/2/2024 13:02	CHALK	Liectricat	W0303734	Trouble in system showing A044 D000 001 Supervisory
Nutrition Services	10/29/2024 8:11	GREER	Fire Alarm System	Z1-038635	House III system showing Above book out supervisory
Nutrition Services	10/25/2024 0.11	GNEEN	File Aldilli System	21-030033	
					nonel abouting trouble in queton due to 4004 D000 004 Supervisory Tompay 2 Discs Dec 2
Notation Complete	40/00/0004044	OPEED	Fire Controller Control	74 000 447	panel showing trouble in system due to A004 D000 001 Supervisory Tamper 3 Riser Rm 3
Nutrition Services	10/28/2024 8:14	GREER	Fire Sprinkler System	Z1-038447	
					HVAC UNIT - ANNEX KITC PREP AREA - NOT COOLING & FILTERS NEEDS TO BE CHANGED
					PM/PARKS 416-1998
Nutrition Services	10/31/2024 8:24	WEBB	Heating/Ventilation/Air Conditioning	Z1-039015	
					Requesting 2sets of keys A 7A7B084
Nutrition Services	12/10/2024 18:28	MALONE	Key & Lock	Z1-044367	
					Requesting 2sets of keys see photos B 7A7B084
Nutrition Services	12/10/2024 18:25	MALONE	Key & Lock	Z1-044366	
					Need keys made for door 101A (4 keys)
Nutrition Services	10/30/2024 11:06	HUNT	Key & Lock	Z1-038904	
					Unable to lock door with key
Nutrition Services	7/15/2024 9:10	SMITH	Key & Lock	Z1-021153	
			• • • • •		

Requesting new keys in the entire kitchen previous supervisor is in the hospital with no contact

Nutrition Services	7/12/2024 14:50	SMITH	Key & Lock	Z1-021088	Doom 1004 Dispetars office requiresting new love he made. Once complete contact David
					Room 102A-Directors office requesting new keys be made. Once complete contact Darryl Hunt
Nutrition Services	7/10/2024 15:15	SMITH	Key & Lock	Z1-020817	Tunt
Nation Controls	77107202-4 10110	G	Noy a 200K	21 020017	See attachment
Nutrition Services	3/12/2024 8:37	SMITH	Key & Lock	Z1-004869	
			-		Requesting new locks and keys for deck
Nutrition Services	2/16/2024 13:17	SMITH	Key & Lock	Z1-001762	
					Requesting masonry repair around walkway railings
Nutrition Services	8/7/2024 11:34	BURCHETT	Masonry	Z1-026072	
No. desidei O i	0/00/000444-00	DUDOUETT	M	74 040540	Requesting tile repair in break room/Men restroom.See image
Nutrition Services	6/26/2024 11:23	BURCHETT	Masonry	Z1-019518	Requesting masonry repair around stairs
Nutrition Services	6/13/2024 9:49	BURCHETT	Masonry	Z1-018270	nequesting masonity repair around stairs
					Masonry repair around door frame and wall
Nutrition Services	2/12/2024 8:30	CORONADO	Masonry	Z1-000947	
					Requesting parking area stripes to be repainted with numbers.
Nutrition Services	9/25/2024 8:27	BURCHETT	Painting	Z1-034586	
					Requesting stair railings painted in bad shape, see photos.
Nutrition Services	8/7/2024 11:40	BURCHETT	Painting	Z1-026080	
No. desidei O i	0/7/000444-00	DUDOUETT	Deliable	74 000077	Requesting stair railings painted ,see photos.
Nutrition Services	8/7/2024 11:38	BURCHETT	Painting	Z1-026077	Storm drain clog/back up, overflowing
Nutrition Services	11/13/2024 8:13	SINK	Plumbing	Z1-040566	Storm drain ctogroack up, overflowing
Nutrition octoices	11/10/2024 0:10	OHAK	i turnomy	21 040000	Requesting roof inspection per Safety Manager.
Nutrition Services	6/26/2024 8:57		Roofing	Z1-019493	
			· ·		
					Requesting sheet metal work on roof to prevent water damage. Check with Mr. Hosea for
					more details. Plant Manager WARDIE Parks contact cell 901-571-0674
Nutrition Services	4/17/2024 8:14	HATCH	Sheet Metal	Z1-009790	
					The leasting is 0070 to the approximate the second
					The location is 2970 Jackson Bayer Bldg 7 warehouse: Requesting a welder to work on
					shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer
Nutrition Services	6/7/2024 10:32	STAFFORD	Welding	71-017710	
Nutrition Services	6/7/2024 10:32	STAFFORD	Welding	Z1-017710	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer
Nutrition Services Oak Forest Elementary	6/7/2024 10:32 12/9/2024 12:28	STAFFORD SCOTT	Welding Electrical	Z1-017710 Z3-044074	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534
			_		shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534
			_		shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143
Oak Forest Elementary	12/9/2024 12:28	SCOTT	Electrical	Z3-044074	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler
Oak Forest Elementary Oak Forest Elementary	12/9/2024 12:28 5/14/2024 11:52	SCOTT SCOTT	Electrical Electrical	Z3-044074 Z3-014486	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library
Oak Forest Elementary	12/9/2024 12:28	SCOTT	Electrical	Z3-044074	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5.
Oak Forest Elementary Oak Forest Elementary Oak Forest Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00	SCOTT SCOTT SMALL	Electrical Electrical Fire Sprinkler System	Z3-044074 Z3-014486 Z3-044790	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler
Oak Forest Elementary Oak Forest Elementary	12/9/2024 12:28 5/14/2024 11:52	SCOTT SCOTT	Electrical Electrical	Z3-044074 Z3-014486	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling
Oak Forest Elementary Oak Forest Elementary Oak Forest Elementary Oak Forest Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57	SCOTT SCOTT SMALL WALLACE	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning	Z3-044074 Z3-014486 Z3-044790 Z3-024854	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5.
Oak Forest Elementary Oak Forest Elementary Oak Forest Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00	SCOTT SCOTT SMALL	Electrical Electrical Fire Sprinkler System	Z3-044074 Z3-014486 Z3-044790	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling
Oak Forest Elementary Oak Forest Elementary Oak Forest Elementary Oak Forest Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57	SCOTT SCOTT SMALL WALLACE	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning	Z3-044074 Z3-014486 Z3-044790 Z3-024854	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling Key needed for room #143 A Cafeteria/Kitchen door
Oak Forest Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57 9/19/2024 9:29	SCOTT SCOTT SMALL WALLACE SMITH	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock	Z3-044074 Z3-014486 Z3-044790 Z3-024854 Z3-033641	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling Key needed for room #143 A Cafeteria/Kitchen door
Oak Forest Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57 9/19/2024 9:29 9/19/2024 9:26 9/19/2024 9:24	SCOTT SCOTT SMALL WALLACE SMITH SMITH SMITH	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock Key & Lock Key & Lock	Z3-044074 Z3-014486 Z3-044790 Z3-024854 Z3-033641 Z3-033636 Z3-033629	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling Key needed for room #143 A Cafeteria/Kitchen door (Plant Manager) GMA key needed for school. Broken key Key needed for room #155 B . No bitting number available
Oak Forest Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57 9/19/2024 9:29 9/19/2024 9:26 9/19/2024 9:24 12/5/2024 8:56	SCOTT SCOTT SMALL WALLACE SMITH SMITH SMITH SMITH	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock Key & Lock Key & Lock Audio Visual	Z3-044074 Z3-014486 Z3-044790 Z3-024854 Z3-033641 Z3-033636 Z3-033629 Z4-043486	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling Key needed for room #143 A Cafeteria/Kitchen door (Plant Manager) GMA key needed for school. Broken key Key needed for room #155 B. No bitting number available Per Principal Davis the teachers can't hear the announcements from intercom
Oak Forest Elementary Oakhaven Elementary Oakhaven Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57 9/19/2024 9:29 9/19/2024 9:26 9/19/2024 9:24 12/5/2024 8:56 11/6/2024 13:58	SCOTT SCOTT SMALL WALLACE SMITH SMITH SMITH SMITH SMITH ARNOLD	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock Key & Lock Key & Lock Audio Visual Carpentry	Z3-044074 Z3-014486 Z3-044790 Z3-024854 Z3-033641 Z3-033629 Z4-043486 Z4-039936	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling Key needed for room #143 A Cafeteria/Kitchen door (Plant Manager) GMA key needed for school. Broken key Key needed for room #155 B . No bitting number available Per Principal Davis the teachers can't hear the announcements from intercom Repair Library Window
Oak Forest Elementary Oakhaven Elementary Oakhaven Elementary Oakhaven Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57 9/19/2024 9:29 9/19/2024 9:26 9/19/2024 9:24 12/5/2024 8:56 11/6/2024 13:58 11/2/2024 9:25	SCOTT SCOTT SMALL WALLACE SMITH SMITH SMITH SMITH ARNOLD HALL	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock Key & Lock Key & Lock Audio Visual Carpentry Electrical	Z3-044074 Z3-014486 Z3-044790 Z3-024854 Z3-033641 Z3-033636 Z3-033629 Z4-043486 Z4-039936 Z4-042045	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling Key needed for room #143 A Cafeteria/Kitchen door (Plant Manager) GMA key needed for school. Broken key Key needed for room #155 B. No bitting number available Per Principal Davis the teachers can't hear the announcements from intercom Repair Library Window Bad balance in hallway
Oak Forest Elementary Oakhaven Elementary Oakhaven Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57 9/19/2024 9:29 9/19/2024 9:26 9/19/2024 9:24 12/5/2024 8:56 11/6/2024 13:58	SCOTT SCOTT SMALL WALLACE SMITH SMITH SMITH SMITH SMITH ARNOLD	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock Key & Lock Key & Lock Audio Visual Carpentry	Z3-044074 Z3-014486 Z3-044790 Z3-024854 Z3-033641 Z3-033629 Z4-043486 Z4-039936	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling Key needed for room #143 A Cafeteria/Kitchen door (Plant Manager) GMA key needed for school. Broken key Key needed for room #155 B . No bitting number available Per Principal Davis the teachers can't hear the announcements from intercom Repair Library Window Bad balance in hallway Elevator doesn't move. Can't go up nor down.
Oak Forest Elementary Oakhaven Elementary Oakhaven Elementary Oakhaven Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57 9/19/2024 9:29 9/19/2024 9:26 9/19/2024 9:24 12/5/2024 8:56 11/6/2024 13:58 11/2/2024 9:25	SCOTT SCOTT SMALL WALLACE SMITH SMITH SMITH SMITH ARNOLD HALL	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock Key & Lock Key & Lock Audio Visual Carpentry Electrical	Z3-044074 Z3-014486 Z3-044790 Z3-024854 Z3-033641 Z3-033636 Z3-033629 Z4-043486 Z4-039936 Z4-042045	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling Key needed for room #143 A Cafeteria/Kitchen door (Plant Manager) GMA key needed for school. Broken key Key needed for room #155 B . No bitting number available Per Principal Davis the teachers can't hear the announcements from intercom Repair Library Window Bad balance in hallway Elevator doesn't move. Can't go up nor down. Per Siemens-Site has bad sprinkler switch that is under ground and is causing a ground
Oak Forest Elementary Oakhaven Elementary Oakhaven Elementary Oakhaven Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57 9/19/2024 9:29 9/19/2024 9:26 9/19/2024 9:24 12/5/2024 8:56 11/6/2024 13:58 11/2/2024 9:25	SCOTT SCOTT SMALL WALLACE SMITH SMITH SMITH SMITH ARNOLD HALL	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock Key & Lock Key & Lock Audio Visual Carpentry Electrical	Z3-044074 Z3-014486 Z3-044790 Z3-024854 Z3-033641 Z3-033636 Z3-033629 Z4-043486 Z4-039936 Z4-042045	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling Key needed for room #143 A Cafeteria/Kitchen door (Plant Manager) GMA key needed for school. Broken key Key needed for room #155 B . No bitting number available Per Principal Davis the teachers can't hear the announcements from intercom Repair Library Window Bad balance in hallway Elevator doesn't move. Can't go up nor down.
Oak Forest Elementary Oakhaven Elementary Oakhaven Elementary Oakhaven Elementary Oakhaven Elementary Oakhaven Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57 9/19/2024 9:29 9/19/2024 9:26 9/19/2024 9:24 12/5/2024 8:56 11/6/2024 13:58 11/22/2024 9:25 8/20/2024 9:42	SCOTT SCOTT SMALL WALLACE SMITH SMITH SMITH SMITH ARNOLD HALL CALDWELL	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock Key & Lock Key & Lock Audio Visual Carpentry Electrical Elevators	Z3-044074 Z3-014486 Z3-044790 Z3-024854 Z3-033641 Z3-033629 Z4-043486 Z4-039936 Z4-042045 Z4-028589	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling Key needed for room #143 A Cafeteria/Kitchen door (Plant Manager) GMA key needed for school. Broken key Key needed for room #155 B. No bitting number available Per Principal Davis the teachers can't hear the announcements from intercom Repair Library Window Bad balance in hallway Elevator doesn't move. Can't go up nor down. Per Siemens-Site has bad sprinkler switch that is under ground and is causing a ground fault. 5.13.24 SC
Oak Forest Elementary Oakhaven Elementary Oakhaven Elementary Oakhaven Elementary Oakhaven Elementary Oakhaven Elementary Oakhaven Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57 9/19/2024 9:29 9/19/2024 9:26 9/19/2024 9:24 12/5/2024 8:56 11/6/2024 13:58 11/22/2024 9:25 8/20/2024 9:42 5/13/2024 7:56 2/3/2024 16:57	SCOTT SCOTT SMALL WALLACE SMITH SMITH SMITH SMITH ARNOLD HALL CALDWELL	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock Key & Lock Audio Visual Carpentry Electrical Elevators Fire Sprinkler System Painting	Z3-044074 Z3-014486 Z3-044790 Z3-024854 Z3-033641 Z3-033629 Z4-043486 Z4-039936 Z4-042045 Z4-028589 Z4-014160 W01019746	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling Key needed for room #143 A Cafeteria/Kitchen door (Plant Manager) GMA key needed for school. Broken key Key needed for room #155 B . No bitting number available Per Principal Davis the teachers can't hear the announcements from intercom Repair Library Window Bad balance in hallway Elevator doesn't move. Can't go up nor down. Per Siemens-Site has bad sprinkler switch that is under ground and is causing a ground fault. 5.13.24 SC I need 1 can of tan paint for touch up
Oak Forest Elementary Oakhaven Elementary Oakhaven Elementary Oakhaven Elementary Oakhaven Elementary Oakhaven Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57 9/19/2024 9:29 9/19/2024 9:26 9/19/2024 9:24 12/5/2024 8:56 11/6/2024 13:58 11/22/2024 9:25 8/20/2024 9:42	SCOTT SCOTT SMALL WALLACE SMITH SMITH SMITH ARNOLD HALL CALDWELL BURCHETT	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock Key & Lock Key & Lock Audio Visual Carpentry Electrical Elevators	Z3-044074 Z3-014486 Z3-044790 Z3-024854 Z3-033641 Z3-033629 Z4-043486 Z4-039936 Z4-042045 Z4-028589 Z4-014160	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling Key needed for room #143 A Cafeteria/Kitchen door (Plant Manager) GMA key needed for school. Broken key Key needed for room #155 B. No bitting number available Per Principal Davis the teachers can't hear the announcements from intercom Repair Library Window Bad balance in hallway Elevator doesn't move. Can't go up nor down. Per Siemens-Site has bad sprinkler switch that is under ground and is causing a ground fault. 5.13.24 SC
Oak Forest Elementary Oakhaven Elementary	12/9/2024 12:28 5/14/2024 11:52 12/12/2024 16:00 8/2/2024 13:57 9/19/2024 9:29 9/19/2024 9:26 9/19/2024 9:24 12/5/2024 8:56 11/6/2024 13:58 11/22/2024 9:25 8/20/2024 9:42 5/13/2024 7:56 2/3/2024 16:57 9/11/2024 9:31	SCOTT SCOTT SMALL WALLACE SMITH SMITH SMITH SMITH ARNOLD HALL CALDWELL BURCHETT HARRIS	Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock Key & Lock Audio Visual Carpentry Electrical Elevators Fire Sprinkler System Painting Plumbing	Z3-044074 Z3-014486 Z3-0144790 Z3-024854 Z3-033636 Z3-033629 Z4-043486 Z4-039936 Z4-042045 Z4-028589 Z4-014160 W01019746 Z4-031921	shrink wrap plate. The base plate has pulled up from the floor I need a someone to hammer down the plate. SEE ATTACHMENT Call Earnest with any questions 901-553-5534 There is a bad ballast in electrical closet #E143 several lights need replacing in back hallway by library The school is equipped with over 300 sprinkler throughout the building, but the fire sprinkler head box contained only 5. (RTU) for room #161 not cooling Key needed for room #143 A Cafeteria/Kitchen door (Plant Manager) GMA key needed for school. Broken key Key needed for room #155 B. No bitting number available Per Principal Davis the teachers can't hear the announcements from intercom Repair Library Window Bad balance in hallway Elevator doesn't move. Can't go up nor down. Per Siemens-Site has bad sprinkler switch that is under ground and is causing a ground fault. 5.13.24 SC I need 1 can of tan paint for touch up 2nd Stall isn't operable

Bleachers inspected(POCA)

					bleachers hispected(FOCA)
Oakhaven High	6/4/2024 15:44	CALDWELL	Bleachers and Seats	Z4-017200	
Oakhaven High	12/13/2024 11:36	ARNOLD	Carpentry	Z4-044891	Door arm broken
			,		lights
Onlike was 115 de	40/40/0004 0:00		Florence	74.04440	ugits
Oakhaven High	12/10/2024 6:36	HALL	Electrical	Z4-044143	
Oakhaven High	12/3/2024 7:54	HALL	Electrical	Z4-042713	Sockets don't work on right side of room
Oakhaven High	10/28/2024 11:28	HALL	Electrical	Z4-038534	1dead balance
Oakhaven High	10/28/2024 11:27	HALL	Electrical	Z4-038533	Sockets not working no breakers are tripped
Oakhaven High	10/24/2024 12:57	HALL	Electrical	Z4-038219	Sockets not working on right side
Oakhaven High	10/24/2024 8:52	HALL	Electrical	Z4-038123	Dead balance
Oakhaven High	10/24/2024 8:40	HALL	Electrical	Z4-038118	Dead balance
•					
Oakhaven High	10/17/2024 9:15	HALL	Electrical	Z4-037329	3 dead balances
Oakhaven High	10/14/2024 8:17	HALL	Electrical	Z4-036783	Front door fire exit lights don't work
Oakhaven High	10/14/2024 8:15	HALL	Electrical	Z4-036782	Front doors on left side by seats exit sign lights don't work
Oakhaven High	10/14/2024 8:13	HALL	Electrical	Z4-036781	Left side doors exit lights don't work
Oakhaven High	10/14/2024 8:12	HALL	Electrical	Z4-036780	Front door exit fire lights don't work
Oakhaven High	10/14/2024 8:10	HALL	Electrical	Z4-036778	exit sign light don't work
•		HALL	Electrical		
Oakhaven High	10/14/2024 8:08			Z4-036777	Back door exit lights don't work
Oakhaven High	10/14/2024 7:50	HALL	Electrical	Z4-036769	Exit lights do not work on right side double doors
Oakhaven High	12/3/2024 7:53	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-042712	Heat will turn on
Oakhaven High	12/2/2024 10:28	WILSON	Heating/Ventilation/Air Conditioning	Z4-042413	Heat not working
Oakhaven High	10/1/2024 15:59	MALONE	Key & Lock	Z4-035784	Needs 3 extra keys
Oakhaven High	5/22/2024 9:47	SMITH	Key & Lock	Z4-015606	Rekeying of building
Oakhaven High	4/4/2024 9:00	SMITH	Key & Lock	Z4-007706	Need 2 gma keys
Oakhaven High	4/4/2024 7:10	SMITH	Key & Lock	Z4-007667	Need keys for side goals so they can let up
Oakilaveli riigii	4/4/2024 /.10	SPIIITI	key a Lock	24-00/00/	
					Stage
Oakhaven High	12/10/2024 8:41	CORONADO	Masonry	Z4-044180	
Oakhaven High	9/13/2024 9:44	BURCHETT	Masonry	Z4-032582	Leak from brick wall
Oakhaven High	9/13/2024 8:37	BURCHETT	Masonry	Z4-032492	Leak coming from brick wall
					Stage painting
Oakhaven High	12/10/2024 8:41	HARRIS	Painting	Z4-044179	
Oakhaven High	9/19/2024 8:05	BURCHETT	Painting	Z4-033566	Main hallway walls and doors need touch up
Oakhaven High	9/9/2024 11:52	BURCHETT	Painting	Z4-031538	Please paint the ceiling in the damage room on stage to the left from ceiling falling in. Thanks
•					
Oakhaven High	8/20/2024 11:43	BURCHETT	Painting	Z4-028661	Please paint ceiling of plant managers office on stage. Thanks
Oakhaven High	12/10/2024 11:09	HARRIS	Plumbing	Z4-044262	Bottom of toilets are loose(the last 2 stalls) on left side of wall
					Sink will not stop running all handles are off
Oakhaven High	12/5/2024 15:53	HARRIS	Plumbing	Z4-043685	
Oakhaven High	10/4/2024 13:15	HARRIS	Plumbing	Z4-036325	Sink has fallen
Oakhaven High	9/27/2024 9:13	HARRIS	Plumbing	Z4-035049	Left Toilet is loose and leaking
Oakhaven High	9/16/2024 8:39	HARRIS	Plumbing	Z4-032824	Pipe leak
Oakhaven Middle	11/5/2024 14:53	HALL	Electrical	Z4-039639	Electrical outlet is detached from box. Please fix. Thanks
Oakhaven Middle	11/5/2024 7:15	HALL	Electrical	Z4-039519	Light switch cover is broken, outlet is exposed. Please fix. Thanks
Oakhaven Middle	10/16/2024 7:51	HALL	Electrical	Z4-037135	We have 3 exterior lights on the front side of the building that are out. Please fix. Thanks.
Oakhaven Middle	10/9/2024 12:14	HALL	Electrical	Z4-036737	Emergency Light attached not working. Please fix. Thanks
Oakhaven Middle	10/9/2024 12:14	HALL	Electrical	Z4-036736	Emergency Light attached not working. Please fix. Thanks
Oakhaven Middle	10/9/2024 12:13	HALL	Electrical	Z4-036735	Emergency Light attached not working. Please fix. Thanks
Oakhaven Middle	10/9/2024 12:12	HALL	Electrical	Z4-036734	Emergency Light attached not working. Please fix. Thanks
					Two bad ballast need fixed. Thanks
Oakhaven Middle	10/8/2024 8:04	HALL	Electrical	Z4-036573	THE DAY DAMAGE HOLD HAVE. HIGHE
Oakhaven Middle		HALL	Electrical	Z4-036573 Z4-017164	Draken alcaled accord bath aidea It has amaged wiring 2004
	6/4/2024 13:50				Broken clocked covered both sides. It has exposed wiring. POCA
Oakhaven Middle	5/14/2024 7:11	CALDWELL	Elevators	Z4-014352	The cover for the firefighters operation to recall elevator needs to be replaced. It is missing.
					install rubber floor tile in the auditorium
Oakhaven Middle	12/2/2024 14:19	CONNER	Flooring	Z4-042594	
Oakhaven Middle	12/12/2024 6:46	WILSON	Heating/Ventilation/Air Conditioning	Z4-044525	Heater is out, fan still blowing but no heat or visible flame. Please fix. Thanks
					UNIT NOT COMING - MAIN OFFICE AREA & PRINCIPAL'S OFFICE
					FEEDING OFF THE SAME UNIT
					P/M MOORE 416-2300
Oakhaven Middle	12/6/2024 9:02	WILSON	Heating/Ventilation/Air Conditioning	Z4-043755	
			9		Heat is blewing and Disease fix Thanks
Oakhaven Middle	12/6/2024 7:16	WILSON	Heating/Ventilation/Air Conditioning	Z4-043702	Heat is blowing cool. Please fix. Thanks
Oakhaven Middle	12/5/2024 7:35	WILSON	Heating/Ventilation/Air Conditioning	Z4-043431	Unit is blowing out cold air. Please fix. Thanks
Oakhaven Middle	11/22/2024 10:00	MALONE	Key & Lock	Z4-042056	Key Cylinder broke. Please replace. Thanks
Oakhaven Middle	9/12/2024 13:14	BURCHETT	Masonry	Z4-032298	When it rains water is running down window. Please fix. Thanks
Oakhaven Middle	7/25/2024 13:14	BURCHETT	Masonry	Z4-022641	Bricks are missing under the window and needs replaced. Thanks
Oakhaven Middle	6/28/2024 15:07	BURCHETT	Painting	Z4-019804	Principal would like for the lines in lot redone as well as marked parking spaces. Thanks

Oakhaven Middle	11/14/2024 7:08	HARRIS	Plumbing	Z4-040740	Water is constantly running from water hose in the shower. Please fix. Thanks Please fix toilet, whenever you flush the water rises and is overflowing out. The toilet isn't clogged up either. Thanks
Oakhaven Middle	11/14/2024 7:06	HARRIS	Plumbing	Z4-040738	Please replace toilet seat, it is broken. Thanks
Oakhaven Middle	11/14/2024 7:04	HARRIS	Plumbing	Z4-040736	
Oakhaven Middle	11/8/2024 6:41	HARRIS	Plumbing	Z4-040217	Sink is becoming detached from wall. Please fix. Thanks
Oakhaven Middle	10/24/2024 7:14	HARRIS	Plumbing	Z4-038088	Please fix first toilet, it is leaking from bottom. Thanks
Cumaron i madio	10/2-0/2024 / 114		· tamoning	24 000000	pump out elevator pit
Oakhaven Middle	9/30/2024 7:08	HARRIS	Diversión d	74 005000	pullip out elevator pit
			Plumbing	Z4-035282	
Oakhaven Middle	9/24/2024 10:29	HARRIS	Plumbing	Z4-034454	Please replace bar that goes across urinals. Urinals are not operable. Thanks
Oakhaven Middle	8/26/2024 7:32	HARRIS	Plumbing	Z4-029369	Please replace the toilet seat. Thanks
					TICKETBOOTH GLASS BROKEN AND NEED CLEANING
Oakhaven Stadium	8/5/2024 11:27	TAYLOR	Carpentry	Z4-025271	
Oakhaven Stadium	8/15/2024 10:04	HALL	Electrical	Z4-027756	Outlets are not working. Please fix. Thanks
					Please install light inside ticket booth. The last one appears to be broken. Thanks
Oakhaven Stadium	8/15/2024 8:09	HALL	Electrical	Z4-027662	
Oakshire Elementary	10/31/2024 10:32	FORD	Carpentry	Z4-039069	Need 6x4 cork board installed on hallway
,			,		need grid for ceiling tile put back in light fixture felled in ap office
Oakshire Elementary	8/1/2024 9:10	FORD	Carpentry	Z4-024297	
outomo Etementary	0/1/202-4 0:10	10115	Carponay	21 021207	light fixture fell need grids put back in thanks
Oakshire Elementary	7/29/2024 18:42	FORD	Carpentry	Z4-023536	agric include learneed grids put back in thanks
Oaksille Eterilentary	7/29/2024 16.42	FUND	Carpentry	24-023330	light fell from ceiling in ap office
Ookshira Flamentanı	7/22/2024 0:25	HALL	Floatrical	74 000005	agric leat from certaing in ap office
Oakshire Elementary	7/23/2024 9:35	HALL	Electrical	Z4-022085	and a seculiar transfer to
	0.000.000.1.1.10		- · · ·	7	need some light coverings
Oakshire Elementary	3/20/2024 11:13	HALL	Electrical	Z4-005548	and the second second
					leaking in room 5 in the annex
Oakshire Elementary	12/3/2024 9:54	DOWNER	Heating/Ventilation/Air Conditioning	Z4-042815	
					ceiling leak in annex room 4 and 11
Oakshire Elementary	12/3/2024 8:37	DOWNER	Heating/Ventilation/Air Conditioning	Z4-042740	
					MR. CLARK 63140 CEILING LEAK COMING FROM UNIT
Oakshire Elementary	12/2/2024 10:56	DOWNER	Heating/Ventilation/Air Conditioning	Z4-042452	
					UNIT NOT COMING ON - PORTABLE 172
					P/M CHARLES CLARK 416-3140
Oakshire Elementary	8/23/2024 10:55	DOWNER	Heating/Ventilation/Air Conditioning	Z4-029285	
					Lock to door needs to be changed to S key. Commissioner Murphy came over to inquire
					about the lock to secure allocations she gave to school.
Oakshire Elementary	11/15/2024 13:24	MALONE	Key & Lock	Z4-041100	
					need lock change back to the original lock
Oakshire Elementary	7/25/2024 7:36	SMITH	Key & Lock	Z4-022498	
					reset room in annex door needs changing back
Oakshire Elementary	7/22/2024 8:48	SMITH	Key & Lock	Z4-021830	
					two keys for room for testing for tcap
Oakshire Elementary	3/18/2024 11:04	SMITH	Key & Lock	Z4-005177	
					need painting in the cafeteria bathroom
Oakshire Elementary	11/18/2024 9:28	BURCHETT	Painting	Z4-041219	
					hook up gas to oven
Oakshire Elementary	12/13/2024 11:08	TEDDER	Plumbing	Z4-044888	
			3		first stall and the last stall wont stop flushing, the first one i turn it off but the second one
					still running, thanks
Oakshire Elementary	11/14/2024 13:36	HARRIS	Plumbing	Z4-040900	0
					Requesting a plumber to install pipe in a convection oven
Oakshire Elementary	11/13/2024 14:07	WILSON	Plumbing	Z4-040688	· · · · · · · · · · · · · · · · · · ·
v	11, 10, 202 - 1 0 /				Requesting a plumber for installation of convection oven
Oakshire Elementary	9/4/2024 13:39	WILSON	Plumbing	Z4-030949	0 - F
Overton High	12/5/2024 9:30	WEBB	Carpentry	Z3-043520	Door latche broken needs replacing
Overton High	12/5/2024 9:28	WEBB	Carpentry	Z3-043518	Lock and handle need replacing
Oversteen I II als	44 (05 (000 4 0.50	COOTT	Florida	70.040450	bad ballast bulbs were changed entire fixture might need changing.
Overton High	11/25/2024 8:50	SCOTT	Electrical	Z3-042159	light fighter needs replacing
Overten III-l-	0/20/2024 40:40	COCTT	Fig4-i	70 005 400	light fixture needs replacing
Overton High	9/30/2024 10:48	SCOTT	Electrical	Z3-035436	

					had belless
Overten High	0/00/0004 0:10	SCOTT	Floatrical	72 020475	bad ballast
Overton High Overton High	8/26/2024 9:16 8/9/2024 10:17	SCOTT	Electrical Electrical	Z3-029475 Z3-026671	Bad ballast
Overton right	8/9/2024 10.1/	30011	Electricat	23-0200/1	switch in breaker box is broken
Overton High	8/2/2024 14:02	SCOTT	Electrical	Z3-024857	SWITCH III DIEBREI DOX IS DIOREII
Overton riigii	0/2/2024 14.02	30011	Liectificat	25-024057	breaker switch broken needs repairing
Overton High	8/2/2024 14:00	WHITWORTH	Electrical	Z3-024856	breaker switch broken needs repairing
Overton High	7/30/2024 14:49	SCOTT	Electrical	Z3-023853	Replace broken exit sign
Overton High	7/29/2024 14:38	SCOTT	Electrical	Z3-023475	Broken light fixture
Overton High	7/29/2024 14:35	SCOTT	Electrical	Z3-023472	Change ballast in light fixture
Overton High	5/24/2024 9:16	SCOTT	Electrical	Z3-015926	House light bulbs need changing
Overton High	5/23/2024 9:22	SCOTT	Electrical	Z3-015792	Light for parking lot broken
Overton High	5/1/2024 8:22	SCOTT	Electrical	Z3-012454	Light fixture has bad ballast
Overton High	4/3/2024 9:20	SCOTT	Electrical	Z3-007527	We need power outlets to be installed in walls of classroom
Overton High	10/3/2024 18:53	SMALL	Fire Alarm System	Z3-036198	Post indicator valve needs to be replaced
Overton High	7/10/2024 10:54		Fire Alarm System	Z3-020742	Fire system is down not signaling anything to fire panel
Overton High	5/22/2024 7:36		Fire Alarm System	Z3-015539	Must provide annual report
Overton High	5/22/2024 7:30		Fire Alarm System	Z3-015534	Repair fire system panel
Overton High	6/3/2024 11:36		Fire Sprinkler System	Z3-016952	POCA SPINKLER System need inspected
Overton High	5/22/2024 7:32		Fire Sprinkler System	Z3-015535	Need testing done
Overton High	10/3/2024 19:00	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-036202	Pump leaking rapidly
					Install new vent a hood on roof
Overton High	9/17/2024 7:03	SCOTT	Heating/Ventilation/Air Conditioning	Z3-033046	
					Deliver portables
Overton High	8/7/2024 6:56	BARNES	Heating/Ventilation/Air Conditioning	Z3-025842	
					UNIT NOT COMING ON - GYM
					P/M WOODS 416-2136
Overton High	6/17/2024 14:59	SCOTT	Heating/Ventilation/Air Conditioning	Z3-018608	
					replace leaking pump
Overton High	2/27/2024 6:54	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-002943	
Overton High	6/3/2024 11:38		Kitchen Hood	Z3-016955	POCA Hood suppression test needed
Overton High	7/15/2024 13:33	BURCHETT	Painting	Z3-021249	Requesting for all walls inside of school to be painted , that are not already!
Overton High	6/18/2024 15:45	BURCHETT	Painting	Z3-018831	Requesting entire floor to be painted if possible gray
Overton High	5/17/2024 14:32	BURCHETT	Painting	WO1015430	plastered ceiling on 400 hallway in front trophy case need to be repaired
Overton High	5/17/2024 14:32	BURCHETT	Painting	WO1015429	plastered ceiling in breezeway from 300 hallway to main hallway need to be repaired
Overton High	5/17/2024 10:39	TOLES	Plumbing	Z3-015018	Shower won't stop running
Parkway Village Elementary	12/10/2024 9:39	SCOTT	Electrical	Z3-044218	Sockets for hot boxes not working properly
Design Village Florester	10/16/2024 10:11	SCOTT	Florenical	Z3-037202	Smart lighting system malfunctioning and needs attention.
Parkway Village Elementary	10/16/2024 10:11	50011	Electrical	23-03/202	Full aidea not working are noth, and people to be tooked
Parkway Village Elementary	5/21/2024 7:11	SCOTT	Electrical	Z3-015310	Exit signs not working properly and needs to be tested.
Parkway Village Elementary	2/26/2024 6:04	SCOTT	Electrical	Z3-015310 Z3-002758	Automatic fan over door not working
Parkway Village Elementary	2/26/2024 6:03	SCOTT	Electrical	Z3-002757	Breaker to water fountain not working properly.
i arkway vittage Eterneritary	2/20/2024 0.03	30011	Liectificat	25-002737	Multiple troubles showing on the FAP
Parkway Village Elementary	3/28/2024 11:51	SMALL	Fire Alarm System	Z3-006791	Tradapte troubles showing on the FAI
r annuay vinago ziomontary	0/20/2024 11/01	01 17 12 2	The Marin System	20 000,01	Low coolant alarm and common fault alarm
Parkway Village Elementary	11/14/2024 7:29	SMALL	Generators	Z3-040746	
,g,					UNIT NOT COOLING - CL-RM D123
					P/M RODNEY PARKER 416-0870
Parkway Village Elementary	7/29/2024 10:19	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-023266	
, , ,					HVAC UNIT IN RM D119 - NOT COOLING PM/PARKER 416-0870
Parkway Village Elementary	4/16/2024 8:14	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-009483	
Parkway Village Elementary	12/2/2024 10:41	MALONE	Key & Lock	Z3-042440	Room key for new teacher
					Damage fire hydrant that is leaking and damaging the grounds.
Parkway Village Elementary	8/20/2024 9:54	JOHNSON	Plumbing	Z3-028599	
Parkway Village Elementary	12/10/2024 9:40	BUFORD	Roofing	Z3-044220	Roof leak upstairs classroom k210
Peabody Elementary	11/19/2024 8:04	SMITH	Audio Visual	Z1-041397	Intercom not working correctly
Peabody Elementary	11/12/2024 14:21	RUSSELL	Carpentry	Z1-040494	Top window slipping down about 2 inches needs to be secured.
Peabody Elementary	10/15/2024 10:21	STEPHENS	Carpentry	Z1-037038	Right side top window dropped about 2 inches and will not go back up.
					Right storm window has two holes in it and is cracked.
Peabody Elementary	10/8/2024 9:44	STEPHENS	Carpentry	Z1-036599	
	4010105	D. 105 -: :		74 06	Old school banner needs taking down and new banner put up with metal brads.
Peabody Elementary	10/8/2024 9:36	RUSSELL	Carpentry	Z1-036597	

Peabody Elementary	9/24/2024 14:31	RUSSELL	Carpentry	Z1-034535	Wall around vent is broken. replace damaged ceiling tiles.
Peabody Elementary	9/10/2024 15:14	ARNOLD	Carpentry	Z1-031831	
Peabody Elementary	6/7/2024 9:50	SHIPPS	Carpentry	Z1-017683	One of the steps on the slide is broken and one is worn. I have the parts here to replace them.
Peabody Elementary	12/3/2024 8:26	ANDREWS	Electrical	Z1-042729	Wall outlet not working
Peabody Elementary	11/18/2024 15:25	ANDREWS	Electrical	Z1-041361	Electrical wall outlet not working.
Peabody Elementary	8/12/2024 16:44	ANDREWS	Electrical	Z1-027089	POCA Three sockets by the windows don't work.
,					Needs lockout device on fire alarm circuit. POCA
Peabody Elementary	8/8/2024 7:33	ANDREWS	Electrical	Z1-026217	KITC VENT-A-HOOD - NOT WORKING PM/BROWN 416-4606
Peabody Elementary	7/29/2024 13:01	ANDREWS	Electrical	Z1-023391	
Peabody Elementary	7/11/2024 11:49	ANDREWS	Electrical	Z1-020925	Electrical socket is damaged and has no power.
Peabody Elementary	7/10/2024 9:24	ANDREWS	Electrical	Z1-020704	Electrical socket is hanging from wall.
Peabody Elementary	5/17/2024 13:39	CHALK	Electrical	WO977721	ting to have an electrical receptacle put outside at the back of the building for the gardening area use.
Peabody Elementary	12/10/2024 11:28	GREER	Elevators	Z1-044269	Elevator will not reset/door open/not responding
, ,					Smoke detectors need to be installed in elevator shaft. Need technician to move it
Peabody Elementary	12/4/2024 10:11	GREER	Elevators	Z1-043270	
Peabody Elementary	8/19/2024 13:20		Fire Alarm System	Z1-028438	Fire alarm flasher hanging off wall.
Peabody Elementary	8/8/2024 15:55		Fire Alarm System	Z1-026520	POCO Records are need for all required inspections and test of fire systems.
Peabody Elementary	8/8/2024 15:37		Fire Alarm System	Z1-026514	POCA exposed wire needs fixed. Socket near desk
Peabody Elementary	8/8/2024 15:05		Fire Alarm System	Z1-026511	Socket damaged.
	8/8/2024 15:02			Z1-026509	· · · · · · · · · · · · · · · · · · ·
Peabody Elementary			Fire Alarm System		Two light switches need cover.
Peabody Elementary	8/8/2024 14:56		Fire Alarm System	Z1-026505	Two light switches need cover.
Peabody Elementary	8/8/20247:50	2255	Fire Alarm System	Z1-026223	Bushes need to be trimmed in front of emergency escape window. Fire system down.
Peabody Elementary	8/6/2024 10:46	GREER	Fire Alarm System	Z1-025632	
Peabody Elementary	9/10/2024 10:06	GREER	Fire Watch	Z1-031710	Fire watch
Deele de Flancestan	40/40/000440-50	WEDD	Hanking (Manakilanian (Air Oan dikirain d	74 044740	Mr. Hester (416 4606) Library Air Unit heat coil isn`t responsive.
Peabody Elementary	12/12/2024 12:59	WEBB	Heating/Ventilation/Air Conditioning	Z1-044740	John 64606
					fan not blowing energy management can't get o respond
Peabody Elementary	12/12/2024 10:47	WEBB	Heating/Ventilation/Air Conditioning	Z1-044691	ian not blowing energy management can't get o respond
readout Elementary	12/12/2024 10.4/	WEBB	rieating/ventitation/Air Conditioning	21-044091	HEATING UNIT FOR RM 205 - HAS BEEN RUNNING HOT - HAD TO SHUT UNIT OFF -
					PM/HESTER 416-4606
Peabody Elementary	12/9/2024 12:30	WEBB	Heating/Ventilation/Air Conditioning	Z1-044075	
					HEATING UNIT FOR RM 311 - HAS BEEN RUNNING HOT - HAD TO SHUT UNIT OFF- PM/HESTER 416-4606
Peabody Elementary	12/9/2024 10:45	WEBB	Heating/Ventilation/Air Conditioning	Z1-044039	
					mr. hester
					64606
					unit not working
Peabody Elementary	12/4/2024 13:31	WEBB	Heating/Ventilation/Air Conditioning	Z1-043386	
					HEATING UNIT FOR RM 204 - NOT COMING ON PM/HESTER 416-4606
Peabody Elementary	12/3/2024 12:38	WEBB	Heating/Ventilation/Air Conditioning	Z1-042973	
,					John 64606 room is too hot
Peabody Elementary	12/2/2024 13:30	WEBB	Heating/Ventilation/Air Conditioning	Z1-042564	
r caboay Etomontary	12/2/2024 10:00		riodang rendaden in Gendadening	21 0 1200 1	Peabody ES John Fester (416 4606) Room 303. Unit is blowing cold air
Peabody Elementary	12/2/2024 13:16	WEBB	Heating/Ventilation/Air Conditioning	Z1-042557	reabody Ed John rester (410 4000) Noon 300. One is blowing cold all
reabouy Elementary	12/2/2024 13.10	WEDD	Heating/Verititation/Air Conditioning	21-042557	MR HESTER 64606 HEAT NOT WORKING
Peabody Elementary	12/2/2024 12:28	WEBB	Heating/Ventilation/Air Conditioning	Z1-042536	PINTESTER 04000 TEAT NOT WORKING
reabouy Elementary	12/2/2024 12.20	WEDD	Heating/Verititation/Air Conditioning	21-042550	HVAC UNIT IN RM 120 - BLOWING TOO HOT PM/HESTER 416-4606
	44/00/0004005	14/500		74 040000	HVAC UNIT IN RM 120 - BLOWING TOO HOT PM/HESTER 410-4606
Peabody Elementary	11/22/2024 9:05	WEBB	Heating/Ventilation/Air Conditioning	Z1-042039	LINARO LINIT IN THE CASE OF LINIO IN THE CERVINIO LINE AREA. LEAVING WATER
					HVAC UNIT IN THE CAFE CEILING IN THE SERVING LINE AREA - LEAKING WATER -
					PM/HESTER 416-4606
Peabody Elementary	11/21/2024 12:29	WEBB	Heating/Ventilation/Air Conditioning	Z1-041953	
					John 64606 unit won't shut off
Peabody Elementary	11/21/2024 8:58	WEBB	Heating/Ventilation/Air Conditioning	Z1-041867	
					HVAC UNIT FOR THE KITC - LEAKING PM/HESTER 416-4606
Peabody Elementary	10/29/2024 7:02	WEBB	Heating/Ventilation/Air Conditioning	Z1-038603	
					John, 64606 unit is blowing warm air,
Peabody Elementary	10/28/2024 8:59	WEBB	Heating/Ventilation/Air Conditioning	Z1-038467	
•					

					james brown 416-4606 ac unit leaking has flooded classroom
Peabody Elementary	10/1/2024 8:03	WEBB	Heating/Ventilation/Air Conditioning	Z1-035600	James Stown 420 4000 at anic teating has recorded etassiconn
					HVAC UNIT IN RM 308- BLOWING NOT COOLING PM/BROWN 416-4606
Peabody Elementary	9/12/2024 9:04	WEBB	Heating/Ventilation/Air Conditioning	Z1-032149	
Peabody Elementary	11/12/2024 8:59	BURCHETT	Masonry	Z1-040393	Tile missing in boys bathroom needs to be replaced for quality inspection report.
			•		Please repair tile walls where plumbers made repairs to piping
Peabody Elementary	10/7/2024 12:59	CORONADO	Masonry	Z1-036489	
Peabody Elementary	9/27/2024 10:55	BURCHETT	Masonry	Z1-035119	There is crack wall tiles and some of the brick tiles have come off.
Peabody Elementary	9/12/2024 13:29	BURCHETT	Masonry	Z1-032305	Rain water is leaking through the wall.
					Please repair tile wall where plumbers has to make repairs to pipe.
Peabody Elementary	9/12/2024 8:31	CORONADO	Masonry	Z1-032113	
Peabody Elementary	7/11/2024 13:17	BURCHETT	Masonry	Z1-020933	Holes in wall tiles.
Peabody Elementary	10/9/2024 12:03	BURCHETT	Painting	Z1-036733	Please paint wall where carpenter made drywall repairs.
					Test RP device as noted on letter.
Peabody Elementary	12/10/2024 9:54	OWENS	Plumbing	Z1-044235	
Peabody Elementary	12/11/2024 13:24	DIAZ	Roofing	Z1-044487	Leak on East side of cafeteria building by the steps of the stage
Peabody Elementary	5/17/2024 14:01	BENTON	Shades/Blinds	WO993548	The library is missing 3 shades and needs 4 shades replaced.
Peabody Elementary	5/17/2024 14:01	BENTON	Shades/Blinds	WO993545	Room 316 needs 6 shades replaced.
Raleigh-Bartlett Meadows Elementary	12/13/2024 10:52	CARLOS	Carpentry	Z2-044883	Stall door broken
Raleigh-Bartlett Meadows Elementary	12/11/2024 13:55	CARLOS	Carpentry	Z2-044498	Last stall door hinges broken
					Replace shade covers on light fixtures (hanging and broken) safety hazard
Raleigh-Bartlett Meadows Elementary	11/14/2024 11:40	POWELL	Electrical	Z2-040854	riopado dilado do foto di agricimado (rianging ana di oxon) daloty nazara
Raleigh-Bartlett Meadows Elementary	10/16/2024 7:26	POWELL	Electrical	Z2-037128	Exit Lights very dimmed (3 Exit Lights in area 3)
Raleigh-Bartlett Meadows Elementary	10/16/2024 7:23	POWELL	Electrical	Z2-037126 Z2-037126	Exit Lights very dimmed (3 Exit Lights in area 3)
Raleigh-Bartlett Meadows Elementary	10/15/2024 12:15	POWELL	Electrical	Z2-037120 Z2-037065	Light fixtures covers (2 cases)
Raleigh-Bartlett Meadows Elementary	10/15/2024 7:25	POWELL	Electrical		room light ballast isn't working I change lights bulbs and lights didn't work (2 out in the classroom)
-	10/15/2024 7:23	POWELL	Electrical		
Raleigh-Bartlett Meadows Elementary				Z2-036956	Light ballast isn't working I change the lights and lights didn't work (3 out by girls restroom)
Raleigh-Bartlett Meadows Elementary	9/29/2024 22:57	POWELL	Electrical	Z2-035255 Z2-035107	stroom light ballast doesn't work anymore I have already tried putting a light bulbs in lights wasn't working
Raleigh-Bartlett Meadows Elementary	9/27/2024 10:39	POWELL	Electrical		8 lights out in cafeteria (different ticket from the first) these are other lights (PreK)
Raleigh-Bartlett Meadows Elementary	9/27/2024 10:35	POWELL	Electrical	Z2-035104	Lights out in cafeteria needs replaced (Too high up needs lift)
					Requesting for the ballast to be replaced in light fixture in area 3 hallway in front of the girl's
					restroom. tape is on light f
Raleigh-Bartlett Meadows Elementary	7/11/2024 9:12	POWELL	Electrical	Z2-020873	
					Requesting for the socket in light fixture be repaired, the light is not blown, but the light bulb
					is slipping out of the socket because the two prongs that are too be on the side of the socket
					is missing.
Raleigh-Bartlett Meadows Elementary	7/3/2024 15:16	POWELL	Electrical	Z2-020245	
					Requesting for ballast to be replaced in Ms. Johson classroom area 3. tape on light fixture.
Raleigh-Bartlett Meadows Elementary	7/3/2024 15:12	POWELL	Electrical	Z2-020243	
					Requesting for the ballast to be replaced in light fixture in girl's restroom area 1. tape is on
					light fixtures.
Raleigh-Bartlett Meadows Elementary	6/27/2024 8:44	POWELL	Electrical	Z2-019605	
Raleigh-Bartlett Meadows Elementary					Requesting for ballast to be replaced in Ms. ray classroom area 2. room202.
	6/24/2024 11:12	POWELL	Electrical	Z2-019193	
	6/24/2024 11:12	POWELL	Electrical	Z2-019193	Requesting for ballast to be replaced in Ms. ray classroom area 2. room202. Requesting for ballast to be replaced.
Raleigh-Bartlett Meadows Elementary	6/24/2024 11:12 6/24/2024 11:10	POWELL	Electrical Electrical	Z2-019193 Z2-019191	
Raleigh-Bartlett Meadows Elementary					
Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary					Requesting for ballast to be replaced.
	6/24/2024 11:10	POWELL	Electrical	Z2-019191	Requesting for ballast to be replaced.
Raleigh-Bartlett Meadows Elementary	6/24/2024 11:10 2/29/2024 13:03	POWELL	Electrical Electrical	Z2-019191 Z2-003417	Requesting for ballast to be replaced. repair cafe lights
Raleigh-Bartlett Meadows Elementary	6/24/2024 11:10 2/29/2024 13:03	POWELL	Electrical Electrical	Z2-019191 Z2-003417	Requesting for ballast to be replaced. repair cafe lights Replaced NAC1 Batteries
Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary	6/24/2024 11:10 2/29/2024 13:03 10/18/2024 7:21	POWELL POWELL Coleman	Electrical Electrical Fire Alarm System	Z2-019191 Z2-003417 Z2-037427	Requesting for ballast to be replaced. repair cafe lights Replaced NAC1 Batteries
Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary	6/24/2024 11:10 2/29/2024 13:03 10/18/2024 7:21	POWELL POWELL Coleman	Electrical Electrical Fire Alarm System	Z2-019191 Z2-003417 Z2-037427	Requesting for ballast to be replaced. repair cafe lights Replaced NAC1 Batteries
Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary	6/24/2024 11:10 2/29/2024 13:03 10/18/2024 7:21	POWELL POWELL Coleman	Electrical Electrical Fire Alarm System	Z2-019191 Z2-003417 Z2-037427	Requesting for ballast to be replaced. repair cafe lights Replaced NAC1 Batteries Fire Marshal request repair fire alarm notification device in boiler room.
Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary	6/24/2024 11:10 2/29/2024 13:03 10/18/2024 7:21 2/27/2024 16:00	POWELL Coleman LINDSEY	Electrical Electrical Fire Alarm System Fire Alarm System	Z2-019191 Z2-003417 Z2-037427 Z2-003103	Requesting for ballast to be replaced. repair cafe lights Replaced NAC1 Batteries Fire Marshal request repair fire alarm notification device in boiler room.
Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary	6/24/2024 11:10 2/29/2024 13:03 10/18/2024 7:21 2/27/2024 16:00 2/6/2024 16:02	POWELL POWELL Coleman LINDSEY SAVAGE	Electrical Electrical Fire Alarm System Fire Alarm System Fire Alarm System	Z2-019191 Z2-003417 Z2-037427 Z2-003103 Z2-000453	Requesting for ballast to be replaced. repair cafe lights Replaced NAC1 Batteries Fire Marshal request repair fire alarm notification device in boiler room. during fire drill the strobe light did not come on and the horn did not sound in portable 199. Monthly inspection / fire extinguishers stickers
Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary	6/24/2024 11:10 2/29/2024 13:03 10/18/2024 7:21 2/27/2024 16:00 2/6/2024 16:02	POWELL POWELL Coleman LINDSEY SAVAGE	Electrical Electrical Fire Alarm System Fire Alarm System Fire Alarm System Fire Extinguishers	Z2-019191 Z2-003417 Z2-037427 Z2-003103 Z2-000453	Requesting for ballast to be replaced. repair cafe lights Replaced NAC1 Batteries Fire Marshal request repair fire alarm notification device in boiler room. during fire drill the strobe light did not come on and the horn did not sound in portable 199.
Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary	6/24/2024 11:10 2/29/2024 13:03 10/18/2024 7:21 2/27/2024 16:00 2/6/2024 16:02 10/3/2024 9:19	POWELL POWELL Coleman LINDSEY SAVAGE Coleman	Electrical Electrical Fire Alarm System Fire Alarm System Fire Alarm System	Z2-019191 Z2-003417 Z2-037427 Z2-003103 Z2-000453 Z2-036033	Requesting for ballast to be replaced. repair cafe lights Replaced NAC1 Batteries Fire Marshal request repair fire alarm notification device in boiler room. during fire drill the strobe light did not come on and the horn did not sound in portable 199. Monthly inspection / fire extinguishers stickers Requesting for floor tile to be replaced in portable 244.
Raleigh-Bartlett Meadows Elementary	6/24/2024 11:10 2/29/2024 13:03 10/18/2024 7:21 2/27/2024 16:00 2/6/2024 16:02 10/3/2024 9:19 7/12/2024 15:20	POWELL POWELL Coleman LINDSEY SAVAGE Coleman CASEY	Electrical Electrical Fire Alarm System Fire Alarm System Fire Alarm System Fire Extinguishers Flooring	Z2-019191 Z2-003417 Z2-037427 Z2-003103 Z2-000453 Z2-036033 Z2-021093	Requesting for ballast to be replaced. repair cafe lights Replaced NAC1 Batteries Fire Marshal request repair fire alarm notification device in boiler room. during fire drill the strobe light did not come on and the horn did not sound in portable 199. Monthly inspection / fire extinguishers stickers
Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary Raleigh-Bartlett Meadows Elementary	6/24/2024 11:10 2/29/2024 13:03 10/18/2024 7:21 2/27/2024 16:00 2/6/2024 16:02 10/3/2024 9:19	POWELL POWELL Coleman LINDSEY SAVAGE Coleman	Electrical Electrical Fire Alarm System Fire Alarm System Fire Alarm System Fire Extinguishers	Z2-019191 Z2-003417 Z2-037427 Z2-003103 Z2-000453 Z2-036033	Requesting for ballast to be replaced. repair cafe lights Replaced NAC1 Batteries Fire Marshal request repair fire alarm notification device in boiler room. during fire drill the strobe light did not come on and the horn did not sound in portable 199. Monthly inspection / fire extinguishers stickers Requesting for floor tile to be replaced in portable 244. HEATING UNIT IN AREA 2 - NOT HEATING COVERS (6) RM - PM/TIDWELL 416-4336
Raleigh-Bartlett Meadows Elementary	6/24/2024 11:10 2/29/2024 13:03 10/18/2024 7:21 2/27/2024 16:00 2/6/2024 16:02 10/3/2024 9:19 7/12/2024 15:20	POWELL POWELL Coleman LINDSEY SAVAGE Coleman CASEY	Electrical Electrical Fire Alarm System Fire Alarm System Fire Alarm System Fire Extinguishers Flooring	Z2-019191 Z2-003417 Z2-037427 Z2-003103 Z2-000453 Z2-036033 Z2-021093	Requesting for ballast to be replaced. repair cafe lights Replaced NAC1 Batteries Fire Marshal request repair fire alarm notification device in boiler room. during fire drill the strobe light did not come on and the horn did not sound in portable 199. Monthly inspection / fire extinguishers stickers Requesting for floor tile to be replaced in portable 244. HEATING UNIT IN AREA 2 - NOT HEATING COVERS (6) RM - PM/TIDWELL 416-4336 Requesting for the rusted floor tile to be replaced in the cafeteria serving line. Please pass
Raleigh-Bartlett Meadows Elementary	6/24/2024 11:10 2/29/2024 13:03 10/18/2024 7:21 2/27/2024 16:00 2/6/2024 16:02 10/3/2024 9:19 7/12/2024 15:20	POWELL POWELL Coleman LINDSEY SAVAGE Coleman CASEY	Electrical Electrical Fire Alarm System Fire Alarm System Fire Alarm System Fire Extinguishers Flooring	Z2-019191 Z2-003417 Z2-037427 Z2-003103 Z2-000453 Z2-036033 Z2-021093	Requesting for ballast to be replaced. repair cafe lights Replaced NAC1 Batteries Fire Marshal request repair fire alarm notification device in boiler room. during fire drill the strobe light did not come on and the horn did not sound in portable 199. Monthly inspection / fire extinguishers stickers Requesting for floor tile to be replaced in portable 244. HEATING UNIT IN AREA 2 - NOT HEATING COVERS (6) RM - PM/TIDWELL 416-4336

Requesting for missing floor tile to be replace in classroom 201. Masonry, please pass on to flooring. Flooring is not listed under the problem section. Thanks. Z2-020543 Raleigh-Bartlett Meadows Elementary 7/9/2024 9:35 BURCHETT Masonry Requesting for the stones/bricks on the back of the building, located in area 3, of the has cracks/gap between them that needs filling in. Raleigh-Bartlett Meadows Elementary 5/8/2024 15:15 BURCHETT Z2-013721 Masonry Requesting for broken floor tile to be replaced. The floor is uneven in the middle also. flooring is not listed Raleigh-Bartlett Meadows Elementary 5/7/2024 10:56 BURCHETT 72-013421 Masonry Raleigh-Bartlett Meadows Elementary 9/27/2024 10:57 BURCHETT Painting Z2-035121 Girls restroom need repainted (PreK) Raleigh-Bartlett Meadows Elementary 8/3/2024 18:41 RURCHETT Painting 72-02/933 Doors need painted. Raleigh-Rartlett Meadows Flementary 6/11/2024 10:25 BURCHETT Painting 72-018000 Requesting parking lot gets re-striped Raleigh-Egypt High 12/12/2024 11:55 Ashestos Z1-044717 Pipes on Gym wall need to be re-insulated "pictures attached" Raleigh-Egypt High 12/13/2024 9:27 STEPHENS Carpentry Z1-044859 Two stall partitions are down and need to be repaired Raleigh-Egypt High 9/20/2024 7:30 ARNOLD Carpentry Z1-033874 Window needs to be sealed Raleigh-Egypt High 9/17/2024 10:51 ARNOLD Carpentry Z1-033181 Wall/ceiling needs repair, leaks when it rains We have a window that needs repaired by stairwell by room 228. Raleigh-Egypt High 7/12/2024 9:54 ARNOLD Z1-021012 Carnentry Raleigh-Egypt High 4/24/2024 11:43 ARNOLD Carpentry Z1-011306 e windows and doors unbolted in annex building 1st floor and made as a fire exit per fire marshal. (POCA) WINDOW IN RM 118 - HAS BEEN KICK OUT - CAN'T SECURE BLDG PM/ROGERS 416-4108 Raleigh-Egypt High 3/27/2024 10:06 ARNOI D 71-006578 Carpentry ARNOI D Raleigh-Egypt High 2/20/2024 5:51 Carpentry Z1-001976 We need the ceiling tiles replaced due to vandalism. It also has special cuts. Raleigh-Egypt High 12/12/2024 11:49 SMITH Flectrical 71-044714 2 exit signs down Raleigh-Egypt High 12/12/2024 11:45 SMITH Electrical Z1-044712 3 exits signs are out 12/12/2024 9:06 SMITH Flectrical 71-044582 Raleigh-Egypt High receptacles are not powering in this room Raleigh-Egypt High 12/5/2024 8:01 SMITH Flectrical 71-043444 Lights are out on top of the gym stage Z1-041849 11/21/2024 8:23 SMITH Electrical Raleigh-Egypt High Receptacles are not receiving power Raleigh-Egypt High 11/19/2024 11:01 SMITH Flectrical 71-041502 Light fixture needs ballast or drawer replaced lights continuously flickers Raleigh-Egypt High 11/19/2024 10:47 SMITH Electrical Z1-041494 Light flicking may need new hallast or drawer Raleigh-Egypt High 11/19/2024 9:34 SMITH Electrical Z1-041460 Receptacle in bleachers does no have power Raleigh-Egypt High 10/29/2024 8:48 SMITH Electrical Z1-038656 5 receptacles not powering in classroom SMITH Raleigh-Egypt High 9/24/2024 8:25 Electrical Z1-034377 Light fixture needs a new ballast, light flickers on and off throughout the day SMITH Z1-033627 Raleigh-Egypt High 9/19/2024 9:23 Flectrical Exposed wires hanging from wall in classroom 9/19/2024 9:22 SMITH Z1-033624 Raleigh-Egypt High Electrical Conduit pipe has exposed wires Raleigh-Egypt High 9/19/2024 9:20 SMITH Electrical Z1-033620 Light switch is not working Raleigh-Egypt High 8/28/2024 11:07 SMITH Electrical Z1-030053 We have a bad light switch that needs replacing in room 128. Raleigh-Egypt High 8/27/2024 6:15 SMITH Electrical Z1-029660 We have a broken receptacle that needs replacing. 8/8/2024 9:13 SMITH Raleigh-Egypt High Flectrical 71-026297 We need the lights checked inside of the restrooms due to flickering. (boys and girls) Raleigh-Egypt High 4/11/2024 11:57 SMITH Flectrical Z1-008836 We need a breaker lock put on the Fire alarm circuit control breaker in the panel. (POCA) 4/11/2024 11:22 SMITH Flectrical 71-008815 Raleigh-Egypt High We have 2 exit signs that are not working and needs replacing. (POCA) 3/2/2024 10:15 Raleigh-Egypt High CHALK Electrical Z1-003623 n corridor between gym and lower level of annex area. This stretch between the building is extremely dark and are very dangerous spots. Raleigh-Egypt High 5/17/2024 13:54 CHALK Electrical WO990743 We need the lights repaired in the stadium restrooms boys and girls. Raleigh-Egypt High 12/3/2024 8:52 Fire Alarm System Z1-042758 Alarm will not reset, lights are flashing nonstop, panel reads "Gym East unit duct return" 10/3/2024 9:29 GREEF Z1-036041 Raleigh-Egypt High Fire Alarm System Trouble on panel reading Supervisory 0255 Wall_Piv_C_Bldg Fire alarm is not sounding on 1st floor annex, 2nd floor annex, and basement/Smoke Detector Duct AHU 6 is being shown on alarm panel in trouble Raleigh-Egypt High 9/19/2024 9:18 GREER Fire Alarm System Z1-033613 Panel is in alarm, supervisor is lite as well as trouble and the screen is coded in error Raleigh-Egypt High 12/5/2024 7:10 GREER Fire Sprinkler System Z1-043421 Raleigh-Egypt High 5/17/2024 13:54 CHASE Flooring WO990742 sed the old carpet pulled up and replaced with floor tile. The carpet has smell and can't be cleaned. Raleigh-Egypt High 11/6/2024 11:54 MALONE Key & Lock Z1-039880 In need of 4 stadium keys Raleigh-Egypt High 10/18/2024 11:06 MALONE Key & Lock 71-037495 Classroom is inaccessible when doors closed, needs a whole new door handle and lock MALONE Z1-034829 Raleigh-Egypt High 9/26/2024 8:44 Kev & Lock Does not lock and needs to be rekeyed to a GM 8/16/2024 7:29 SMITH Z1-027965 Raleigh-Egypt High Key & Lock We need the cylinder replaced on the classroom door.(129) Raleigh-Egypt High 8/14/2024 6:17 SMITH Kev & Lock Z1-027371 We need the cylinder repaired on door. The GM and classroom keys are getting stuck inside. 5/17/2024 14:26 CORONADO Raleigh-Egypt High Masonry WO1010254 have some holes in the floor inside the boys restroom entrance by room 209 that needs repairing. Raleigh-Egypt High 6/21/2024 7:08 BURCHETT Painting Z1-018955 We need the ares inside the cafeteria where the holes were repaired repainted. Raleigh-Egypt High 12/13/2024 11:14 STEPHENS Plumbing 71-044890 Kitchen sinks are leaking from the bottom pan

71-044880

Z1-044876

Sinks are stopped up and overflowing into the floor

Middle stall not flushing properly

Raleigh-Egypt High

Raleigh-Egypt High

12/13/2024 10:33

12/13/2024 10:24

AVAN7I

AVANZI

Plumbing

Plumhing

Raleigh-Egypt High	12/13/2024 9:28	SINK	Plumbing	Z1-044860	First toilet stall not flushing properly
					Investigate & Resolve gas Smell in Gym.
Raleigh-Egypt High	12/16/2024 8:25	OWENS	Plumbing	Z1-044976	
Raleigh-Egypt High	12/5/2024 8:21	OWENS	Plumbing	Z1-043456	Middle stall when flushed water spews at the top
B E			B	74 044470	Saddle cable needs to be replaced on water fountain
Raleigh-Egypt High	11/19/2024 10:13	Jordan	Plumbing	Z1-041479	Hadron and rights the critical like
Doloigh Front High	10/8/2024 10:25	OWENS	Plumbing	Z1-036609	Unstop mop sink in the science lab.
Raleigh-Egypt High		SHIPPS	· ·		Disease install about and EO leaks are easilized to year
Raleigh-Egypt High	11/12/2024 11:22		Welding	Z1-040461	Please install chain and 58 locks on cooling tower gates.
Raleigh-Egypt High	8/8/2024 9:51	SHIPPS	Welding	21-020342	need the gate repaired in between our main building and the ROTC building for security purposes. Repair/Fix Gym Floor
Raleigh-Egypt Middle	12/11/2024 7:13	CROUSE	Carpentry	Z1-044403	Repair ix Oyin Looi
Raleigh-Egypt Middle	12/3/2024 9:34	CHOUSE	Carpentry	Z1-044403 Z1-042793	We need a bulletin board put up on the main entrance hallway wall
Raleigh-Egypt Middle	9/12/2024 8:32	RUSSELL	Carpentry	Z1-032115	ming through the window seal leaking onto the floor from the third floor to the second floor stairwell area
Raleigh-Egypt Middle	7/9/2024 13:20	ARNOLD	Carpentry	Z1-020619	When it rains water is coming through the window seals
nateign Egypt made	77072024 10.20	AITITOLD	Carpentry	21 020013	replace sink countertop it's in even worse shape, thanks
Raleigh-Egypt Middle	4/18/2024 13:30	ARNOLD	Carpentry	Z1-010474	repare similar and resident and
					replace the sink countertop it's in bad shape, thanks
Raleigh-Egypt Middle	4/18/2024 13:28	ARNOLD	Carpentry	Z1-010469	
Raleigh-Egypt Middle	2/12/2024 13:36	ARNOLD	Carpentry	Z1-001043	bridge on the 3rd floor window needs resealing leaking water on the 2nd floor skyline bridge when it rains
Raleigh-Egypt Middle	5/17/2024 13:45	BENTON	Carpet Repair	WO981596	carpet needs deep cleaning in auditorium
Raleigh-Egypt Middle	12/13/2024 15:47	SMITH	Electrical	Z1-044938	Light fixture is bad
Raleigh-Egypt Middle	12/13/2024 15:26	SMITH	Electrical	Z1-044937	X fit panel light is out
Raleigh-Egypt Middle	12/13/2024 15:09	SMITH	Electrical	Z1-044936	This room has four light fixtures with bad ballast
Raleigh-Egypt Middle	11/8/2024 10:44	SMITH	Electrical	Z1-040275	The auditorium stage lights isn't working at all
Raleigh-Egypt Middle	11/6/2024 8:18	SMITH	Electrical	Z1-039713	only two bulbs work in the fixture
Raleigh-Egypt Middle	11/6/2024 8:16	SMITH	Electrical	Z1-039712	Light fixture over the PLC coaches. Desk has a bad ballast,
					PURCHASE ABB DRIVE FOR AHU #5 IN ANNEX
Raleigh-Egypt Middle	10/22/2024 7:57	SIMMONS	Electrical	Z1-037759	
Raleigh-Egypt Middle	9/27/2024 9:36	SIMMONS	Electrical	Z1-035066	Emergency light number one isn't working
Raleigh-Egypt Middle	9/25/2024 13:34	SMITH	Electrical	Z1-034696	Emergency light number 2 isn't working
Raleigh-Egypt Middle	9/18/2024 13:30	SMITH	Electrical	Z1-033488	Equipment room has three light fixtures with bad ballast
Raleigh-Egypt Middle	9/18/2024 13:25	SMITH	Electrical	Z1-033486	light fixture that's bad
Raleigh-Egypt Middle	9/17/2024 14:17	SMITH	Electrical	Z1-033281	Light fixture by emergency light number 11 is bad
Raleigh-Egypt Middle	9/17/2024 10:07	SMITH	Electrical	Z1-033149	I have a bad light fixture
Raleigh-Egypt Middle	9/16/2024 6:41	SIMMONS	Electrical	Z1-032752	magnetic door is missing it's magnetic attachment.
Raleigh-Egypt Middle	7/15/2024 15:54	SMITH	Electrical	Z1-021266	Three light fixtures with bad ballast,
					REPAIR DRIVE FOR AHU #5
Raleigh-Egypt Middle	7/15/2024 7:11	ANDREWS	Electrical	Z1-021117	
Raleigh-Egypt Middle	9/16/2024 11:11	GREER	Fire Alarm System	Z1-032928	anel display is reading, active supervisory for the second third gym auditorium and it has a supervisory signal
Raleigh-Egypt Middle	6/24/2024 6:20	GREER	Fire Alarm System	Z1-019100	ystem was just going off The panel says it's in supervisory mode i've tried to reset it, but it won't reset. and it's still beeping. We need some help.
Raleigh-Egypt Middle	6/25/2024 11:08	CASEY	Flooring	Z1-019369	Assistant principal Brown wants her old carpet taken out and putting floor towel down
					Mr. elfie 64141 not communicating with energy management
Raleigh-Egypt Middle	12/3/2024 13:22	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042990	Market Court of the Court of th
Doloigh Fromt Middle	10/0/0004 10:00	MILLIAMO	Heating Montilation / Air Conditioning	71 042000	Mr. elfie 64141 not communicating with energy management
Raleigh-Egypt Middle	12/3/2024 13:22	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042988	Mr. elfo C4444 not communicating with anomy management
Doloigh Fromt Middle	12/3/2024 13:21	WILLIAMS	Heating Montilation / Air Conditioning	Z1-042985	Mr. elfie 64141 not communicating with energy management
Raleigh-Egypt Middle	12/3/2024 13.21	WILLIAMS	Heating/Ventilation/Air Conditioning	21-042985	Mr. elfie 64141 not communicating with energy management
Raleigh-Egypt Middle	12/3/2024 13:20	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042983	rii. etile 04.141 ilot communicating with energy management
nateign-Egypt Middle	12/3/2024 13.20	WILLIAMS	Heating/Ventitation/All Conditioning	21-042903	Mr. elfie 64141 not communicating with energy management
Raleigh-Egypt Middle	12/3/2024 13:19	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042981	rii. etile 04.141 ilot communicating with energy management
nateign-Egypt Middle	12/3/2024 13.19	WILLIAMS	Heating/Ventitation/All Conditioning	21-042501	Mr. Elcy. 64141 room to cold. thermostat won't communicate with energy mgmt.
Raleigh-Egypt Middle	11/8/2024 14:31	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-040323	rii. Etcy. 04141 footii to cott. tierinostat won communicate war energy night.
nateign-Egypt Fillute	11/0/2024 14.51	WILLIAM	riedding/veridiadon/Air Condidoning	21-040323	Mr. Elcy. 64141 room to cold. thermostat won't communicate with energy mgmt.
Raleigh-Egypt Middle	11/8/2024 14:30	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-040321	
					HVAC UNIT IN RM 305 - LEAKING PM/ELLZEY 416-4141 Please see comment section. wds
Raleigh-Egypt Middle	10/24/2024 10:14	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-038163	
			_		HVAC UNIT IN RM 204 - TOO COLD PM/ELLZEY 416-4141
Raleigh-Egypt Middle	8/7/2024 12:28	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-026098	
•			· ·		
					Plant Manager Elzey reported the ac unit in the cafeteria is blowing warm air. 206-7731
Raleigh-Egypt Middle	8/2/2024 12:30	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-024801	

Raleigh-Egypt Middle	8/2/2024 12:29	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-024800	Plant Manager Elzey reported the ac unit in room 307 is blowing warm air. 206-7731
Raleigh-Egypt Middle	8/2/2024 12:28	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-024799	Plant Manager Elzey reported the ac unit in room 305 is blowing warm air. 206-7731
Raleigh-Egypt Middle	8/2/2024 12:24	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-024792	Plant Manager Elzey reported the ac unit in room 207 is blowing warm air. 206-7731
Raleigh-Egypt Middle	8/2/2024 12:24	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-024791	Plant Manager Elzey reported the ac unit in room 206 is blowing warm air. 206-7731
Raleigh-Egypt Middle	8/2/2024 12:23	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-024790	Plant Manager Elzey reported the ac unit in room 203 is blowing warm air. 206-7731
Raleigh-Egypt Middle	8/2/2024 12:22	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-024789	Plant Manager Elzey reported the ac unit in room 202 is blowing warm air. 206-7731
					Plant Manager Elzey reported the ac unit in room 201 is blowing warm air. 206-7731
Raleigh-Egypt Middle	8/2/2024 12:21	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-024787	ages and appears to place flear tiles in house restrains any early, the grown on the 1st flear thanks
Raleigh-Egypt Middle	5/17/2024 14:24	BENTON	Masonry	WO100/435	ease send someone to place floor tiles in boy's restroom nearby the gym on the 1st floor thanks. Please paint doors
Raleigh-Egypt Middle	12/3/2024 7:38	BURCHETT	Painting	Z1-042702	
Raleigh-Egypt Stadium	6/14/2024 9:22	WILSON	Carpentry	Z1-018370	There is a broken Flag Pole rope
Raleigh-Egypt Stadium	12/5/2024 18:10	MORRIS	Key & Lock	Z1-043691	Change cylinders on stadium restrooms to prevent vandalism .
					A request is to have a breaker repaired in the breaker box in the cafeteria due to it have tripped several times this breaker controls several security panels in the main office like the A phone for the secretary at the front desk.
					Thank you
Richland Elementary	12/12/2024 13:03	STAFFORD	Electrical	Z2-044741	A request is to have 3 four bulb light fixtures repaired due to there's only 1 light fixture working in the area where the freezer is located.
Richland Elementary	12/3/2024 12:08	POWELL	Electrical	Z2-042945	Thank you
Richland Elementary	11/19/2024 9:31	POWELL	Electrical	Z2-041456	A request is to have the light fixture repaired in the pre-k classroom near the Techers Desk. Thanks,
,					
					A request is to have Light ballast repaired in the light fixture that has a new light fixture. Thank you
Richland Elementary	10/21/2024 14:48	POWELL	Electrical	Z2-037727	·
Richland Elementary	9/13/2024 9:20	POWELL	Electrical	Z2-032552	A request is to have the floor receptacle repaired due to a short in the outlet. Thank you
					girls bathroom lights not coming on, switch is defective
Richland Elementary	6/18/2024 10:43	POWELL	Electrical	Z2-018743	Light in annexy pp. 117
Richland Elementary	5/29/2024 17:44	POWELL	Electrical	Z2-016390	Light in annex rm 117 A Request is to have a light ballast to be put in the Assistant office of her desk.
Richland Elementary	5/13/2024 14:03	POWELL	Electrical	Z2-014309	Thank you handicap elevator not working just blinking
Richland Elementary	7/26/2024 11:28	Coleman	Elevators	72-022919	Handicap elevator was never fixed! It was left open exposing the wires
Richland Elementary	6/13/2024 15:12	LEWIS	Elevators	Z2-018326	
Richland Elementary	5/22/2024 9:19	LEWIS	Elevators	Z2-015582	handicap elevator malfunctioned. Pole sticking out creating hazard Replace Fire Control Panel Board
Richland Elementary	12/3/2024 15:44	Coleman	Fire Alarm System	Z2-043058	первасе гне Сонног ганес воани

A request is to have the Batteries replaced in the fire alarm panel due to troubles.

rroquost is to mare	the batteries replaced in the me atarii panet add to	٦
	001 Trouble Pull LL East Wing Exit South	

					001 Trouble Pull LL East Wing Exit South
					Thank you
Richland Elementary	10/16/2024 14:40	Coleman	Fire Alarm System	Z2-037268	
					The fire alarm panel is reading A001 D000
					001 Trouble NAC 1
					Thank you
Richland Elementary	6/24/2024 15:44	LEWIS	Fire Alarm System	Z2-019247	··· ··········
Nicitalia Elementary	0/24/2024 15.44	LEVVIS	File Aldilli System	22-019247	DOOA NAO4
					POCA NAC1 error on panel
Richland Elementary	5/8/2024 8:41	LEWIS	Fire Alarm System	Z2-013599	
					doors not latching to electric door stoppers
Richland Elementary	4/15/2024 8:15	LEWIS	Fire Alarm System	Z2-009133	
-			-		Mr. Hughes
					62148
					no heat
B: 11 151 .	40/40/0004000	070101/1110		70.011010	no neat
Richland Elementary	12/12/2024 9:29	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-044619	
					Mr. Hughes
					62148
					no heat
Richland Elementary	12/12/2024 9:28	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-044618	
ruentana Eternentary	12/12/2024 5.20	OTHIORDIND	ricating ventuation//ii contationing	22 044010	Mr. Hughes
					62148
					no heat
Richland Elementary	12/12/2024 9:28	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-044617	
					Mr. Hughes
					62148
					no heat
Dishland Flamentan	40/40/00040-07	OTDIOWI AND	Handing Alfondiladian (Air One didinala	70.044045	no neat
Richland Elementary	12/12/2024 9:27	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-044615	
					Mr. Hughes
					62148
					no heat
Richland Elementary	12/12/2024 9:27	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-044614	
,			0		Mr. Hughes
					62148
					no heat
Richland Elementary	12/12/2024 9:26	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-044612	
					Mr. Hughes
					62148
					no heat
Richland Elementary	12/12/2024 9:25	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-044609	To House
Nicitalia Elementary	12/12/2024 9.25	STRICKLAND	Heating/Ventilation/All Conditioning	22-044009	THE RESERVE THE PROPERTY OF TH
					HVAC UNIT IN RM 215 - BLOWING HOT AIR - PM/HUGHES 416-2148
Richland Elementary	11/19/2024 9:31	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-041458	
					door needs special lock due to tcap materials being stored
Richland Elementary	7/24/2024 13:46	SMITH	Key & Lock	Z2-022421	
•			ŕ		A request is to have the Counselors office wall painter due to holes.
					Thank you
Dishland Flamentan	40/0/000444-04	DUDOUETT	Deinting	70.040004	mank you
Richland Elementary	12/6/2024 14:01	BURCHETT	Painting	Z2-043864	
					Per request by the principal is to have 5 reserve signs painted on the ground that says
					reserved in the parking spaces near the dumpsters in the back of the school.
					Thank you
Richland Elementary	11/7/2024 10:11	BURCHETT	Painting	Z2-040095	······································
montana Etenientaly	11///2024 10.11	DUNCTIETT	i aniung	22-040000	A request is to have the office outsian deers pointed
					A request is to have the office exterior doors painted.
					Thank you
Richland Elementary	11/6/2024 10:00	BURCHETT	Painting	Z2-039806	
					A request is to have the wall painted over the sink in the assistant principal office over the
					sink the leak have been repaired by the roofer.
					Thank you
Richland Elementary	10/15/2024 12:51	BURCHETT	Dainting	Z2-037071	you
montanu Elementary	10/13/2024 12.31	DUNCHEII	Painting	22-03/0/1	

Parking lot in the rear of the school Per request by the principal to have 6 reserved signs painted in the parking spaces next to the Assistant principal parking space in the back

parking lot. Thank you

					I nank you
Richland Elementary	10/3/2024 11:30	BURCHETT	Painting	Z2-036097	
					re enamel large sink very bad discoloration
Richland Elementary	6/12/2024 8:08	BURCHETT	Painting	Z2-018090	
					urinal with bag on overflowing when flushed
Richland Elementary	12/13/2024 10:16	STAFFORD	Plumbing	Z2-044872	
,					
					A request is to have the sink in the restroom next to classroom 103 needs to be repaired
					Thank you
Richland Elementary	11/18/2024 11:47	PILKINGTON	Plumbing	Z2-041298	mank you
Ridgeway Annex	8/9/2024 7:01	SCOTT	Electrical	Z3-026533	2 bad ballast that need repairing
• ,					
Ridgeway Annex	8/8/2024 6:48	SCOTT	Electrical	Z3-026202	tside light blown in southeast corner of school near dock parking area needs repairing, thanks
Ridgeway Annex	7/12/2024 11:35	SMITH	Key & Lock	Z3-021037	Need GMB Master key to replace broken key, thanks
Ridgeway Early Learning Center	12/12/2024 12:55	SMITH	Audio Visual	Z3-044736	The microphone is not working we are trying to get it fixed
					Evaluate the cracked ceiling that was cause by the sprinkler head that erupted on last
					Thursday in the back storage/garage area. Repair if possible.
Ridgeway Early Learning Center	4/1/2024 7:49	JOHNSON	Carpentry	Z3-006885	
					Power outage caused sockets to not work in multiple areas throughout the school
Ridgeway Early Learning Center	5/13/2024 9:03	SCOTT	Electrical	Z3-014182	
Ridgeway Early Learning Center	4/24/2024 14:04	SCOTT	Electrical	Z3-011377	We need a CO Detector installed and it has be five feet from the ground
					Fire alarm not free of troubles
Ridgeway Early Learning Center	12/12/2024 16:17	SMALL	Fire Alarm System	Z3-044793	The diamnet nee of deapter
rilugeway Larty Learning Center	12/12/2024 10:1/	SIMALL	The Alaini System	25-044755	missing sprinkler head
Diddourou Forby Loorning Contor	12/12/2024 16:19	SMALL	Fire Sprinkler System	Z3-044794	missing sprinker nead
Ridgeway Early Learning Center	12/12/2024 16.19	SMALL	File Spillikler System	23-044/94	
					Replace Damaged Sprinkler Head.
Ridgeway Early Learning Center	3/28/2024 14:35	Systems	Fire Sprinkler System	Z3-006824	
					Paint inside gym door
Ridgeway Early Learning Center	4/24/2024 12:30	BURCHETT	Painting	Z3-011334	Superintendent be here May 1, 2024
Ridgeway High	5/23/2024 13:05	SMALL	Bleachers and Seats	Z3-015874	Need inspection for upper level bleachers in gymnasium
Ridgeway High	12/4/2024 9:27	CROUSE	Carpentry	Z3-043213	Need door handle repaired at entrance of library
Ridgeway High	11/15/2024 10:39	CROUSE	Carpentry	Z3-041060	Need key lock and crash bar installed at south east entrance door of school, thanks
Ridgeway High	7/29/2024 7:11	WEBB	Carpentry	Z3-023071	Need large whiteboard installed in Administrator's office
Ridgeway High	5/23/2024 11:44	CROUSE	Carpentry	Z3-015863	e latching, automatic closures, and rated frame for doors entering the school through gym lobby, thanks
Ridgeway High	3/18/2024 6:45	KINARD	Carpentry	Z3-005038	Need basketball banners hung "high" on gym walls requiring a scissor lift, thanks
Ridgeway High	5/17/2024 13:39	BENTON	Carpet Repair	WO977961	Need ripped carpeting repaired in front of librarian's station, thanks
range ray raga	0/1//2024 10:00	BEITTOIT	Carpornopan		Several bulbs out in rear gym that need replacing
Piddoway High	12/9/2024 10:44	SCOTT	Electrical	Z3-044038	Several builds out in real gym that need replacing
Ridgeway High		SCOTT			O had bell and the transfer of the order
Ridgeway High	12/3/2024 11:13		Electrical	Z3-042892	9 bad ballast that need repairing, thanks
Ridgeway High	11/15/2024 10:34	SCOTT	Electrical	Z3-041059	1 bad ballast needs repairing, thanks
Ridgeway High	11/15/2024 10:33	SCOTT	Electrical	Z3-041058	1 bad ballast needs repairing, thanks
Ridgeway High	11/15/2024 10:31	SCOTT	Electrical	Z3-041056	Need electrical panel cover reattached to cover exposed wiring, thanks
Ridgeway High	11/1/2024 11:18	SCOTT	Electrical	Z3-039258	2 lights out with bad ballast need repairing, thanks
					Upgrade gym lights to LED
Ridgeway High	11/1/2024 12:14	CHALK	Electrical	Z3-039276	
Ridgeway High	10/30/2024 11:39	SCOTT	Electrical	Z3-038918	d electrical outlet drop installed on wall where signage/infomational smart board is installed asap
Ridgeway High	10/28/2024 14:20	SCOTT	Electrical	Z3-038582	Need light switch repaired
Ridgeway High	10/22/2024 13:47	SCOTT	Electrical	Z3-037885	Bad ballast
Ridgeway High	10/7/2024 9:12	SCOTT	Electrical	Z3-036411	Bad light switch needs replacing, thanks
Ridgeway High	9/26/2024 9:45	SCOTT	Electrical	Z3-034857	ght out at entrance/exit door near classroom 141 on 1st floor needs repairing per POCA), thanks
Ridgeway High	9/4/2024 7:54	SCOTT	Electrical	Z3-030787	Need lights repaired that require a scissor lift
Ridgeway High	8/12/2024 8:14	SCOTT	Electrical	Z3-026875	Need 1 bad ballast repaired in classroom 145
Ridgeway High	8/12/2024 8:12	SCOTT	Electrical	Z3-026872	2 bad ballast in classroom need repairing, thanks
Ridgeway High	7/31/2024 9:12	SCOTT	Electrical	Z3-020072 Z3-024040	Need ballasts repaired, thanks
					• •
Ridgeway High	7/31/2024 9:11	SCOTT	Electrical	Z3-024038	4 bad ballast in classroom need repairing, thanks
Ridgeway High	7/18/2024 12:13	SCOTT	Electrical	Z3-021689	al outlet installed or dropped through ceiling for new X-ray scanner and metal detector placement, thanks
Ridgeway High	6/18/2024 7:19	SCOTT	Electrical	Z3-018640	Bad ballast in hallway of Main office
					Repair receptacle for sump pump the pump has been replaced but needs power to prevent
					water from over filling the condensate pit and submerging the electrical under water
Ridgeway High	6/7/2024 6:32	SCOTT	Electrical	Z3-017642	

Ridgeway High	5/31/2024 9:25	SCOTT	Electrical	Z3-016669	Z3-016668 is per POCA, thanks
Ridgeway High	5/31/2024 9:19	SCOTT	Electrical	Z3-016668	eed wall plate cover for exposed wiring near clock on 2nd floor hallway where classroom 225 is
					Bad ballast in storage closet inside classroom 323 that needs repairing, thanks
Ridgeway High	5/21/2024 11:12	SCOTT	Electrical	Z3-015454	
Ridgeway High	5/21/2024 8:14	SCOTT	Electrical	Z3-015337	Need blown light repaired to light up dark area, thanks
Ridgeway High	5/21/2024 8:11	SCOTT	Electrical	Z3-015336	Need light repaired in dark area, thanks
Ridgeway High	5/21/2024 8:09	SCOTT	Electrical	Z3-015335	Need overhead light above dock area repaired, thanks
Ridgeway High	5/10/2024 13:41	SCOTT	Electrical	Z3-014094	Bad ballast
Ridgeway High	5/10/2024 6:50	SCOTT	Electrical	Z3-013978	2 bad ballast in classroom need repairing, thanks
Ridgeway High	5/9/2024 14:34	SCOTT	Electrical	Z3-013958	Need light cover
Ridgeway High	5/9/2024 14:28	SCOTT	Electrical	Z3-013955	Light flickers
Ridgeway High	3/12/2024 8:23	SCOTT	Electrical	Z3-004864	Bad ballast in classroom near storage closet needs repairing, thanks
Ridgeway High	11/21/2024 14:23	SMALL	Elevators	Z3-041990	Elevator is completely out of order and needs repairing
Ridgeway High	11/20/2024 10:40		Elevators	Z3-041703	Need light cover replaced inside elevator
Ridgeway High	11/12/2024 7:20	SMALL	Elevators	Z3-040361	ator is still malfunctioning and is in dyer need of repairs. It doesn't open or close properly either!
					Elevator has not been serviced in over 2 months and needs servicing. It continues to bypass
					, ,
					a the floor that is selected.
Ridgeway High	10/29/2024 8:31	SMALL	Elevators	Z3-038648	
					Elevator is not working and needs repairing asap, thanks
Ridgeway High	6/3/2024 8:19	GREER	Elevators	Z3-016848	
Ridgeway High	5/29/2024 7:33	SMALL	Elevators	Z3-016210	Need updated certificate for elevator
. , .					
Ridgeway High	5/23/2024 14:51	SMALL	Elevators	Z3-015896	Need looped through wiring properly wired in elevator equipment room per POCA
Ridgeway High	4/1/2024 13:44	SMALL	Elevators	Z3-007059	Need elevator inspection certificate updated due to expiration out dated, thanks
Ridgeway High	5/23/2024 13:28		Fire Alarm System	Z3-015879	fire alarm inspection report from Siemens states the fire alarm devices are not operational per POCA
Ridgeway High	6/3/2024 9:39	CASEY	Flooring	Z3-016891	Need carpet removed and replaced with floor tile, thanks
					HEATING UNIT FOR RM 254 - OVERHEATING SHOWING 80 DEGREES PM/WILSON 416-1816
Diddowood lidh	12/5/2024 10:50	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043567	
Ridgeway High	12/5/2024 10.50	GUETHIE	nearing/ventitation/All Conditioning	23-043367	_
					mr. wilson
					68216
					not blowing. very little heat is coming out
Ridgeway High	12/4/2024 11:11	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043322	
radoray raga	12/-//202-11/11	00211112	ricating ventications in Conditioning	20 0 10022	Mr. Wilson 61816 RTU unit 2 no gas in rear gym
B	40/0/00040	0.0571115		70 0 100 10	Pil. Wilson 01010 Kilo unit 2 ilo gas il real gyin
Ridgeway High	12/2/2024 9:28	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-042346	
					Mr. Wilson 61816 air handler 17 and 19 are not heating
Ridgeway High	12/2/2024 9:26	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-042344	
					Mr. Wilson, 61816 blowing but not cooling
Ridgeway High	11/7/2024 11:17	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-040124	
radoray raga	11//2024 11/1/	00211112	ricating ventications in Conditioning	20 0 1012 1	Mr. Wilson, 61816 blowing but not cooling
B		0.0571115		70 010100	MI. WILSON, 01018 blowing but not cooling
Ridgeway High	11/7/2024 11:15	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-040123	
					AHU#5 UNIT NOT COOLING - CL-RM 308, 310, 312, 320, 322, 325, 327, & 329, 3RD FLOOR
					FEEDING OFF THE SAME UNIT
					P/M WILSON 416-1916
Diddowood lidh	10/31/2024 11:51	GOETHIE	Heating Montilation (Air Conditioning	Z3-039097	
Ridgeway High	10/31/2024 11.51	GUETHIE	Heating/Ventilation/Air Conditioning	23-039097	
					AHU#5 UNIT NOT COOLING (THERMOSTAT) - AFFECTING THE ENTIRE 3RD FLOOR
					P/M WILSON 416-1816
Ridgeway High	10/4/2024 12:08	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-036315	
Ridgeway High	11/20/2024 10:54	MALONE	Key & Lock	Z3-041711	Need lock keyed to master key. It was never keyed to Master Key.
Ridgeway High	11/5/2024 12:08	MALONE	Key & Lock	Z3-039612	Need door key for classroom, thanks
Ridgeway High	11/5/2024 12:07	MALONE	Key & Lock	Z3-039610	Need classroom door key, thanks
Ridgeway High	9/23/2024 9:21	MALONE	Key & Lock	Z3-034155	nder turns over and over, but doesn't unlock mechanical room door that needs repairing asap, thanks
Ridgeway High	7/18/2024 11:47	SMITH	Key & Lock	Z3-021682	Library entrance door will not lock and needs repairing, thanks
Ridgeway High	7/12/2024 11:36	SMITH	Key & Lock	Z3-021039	Need 2 Master Keys for Principal, thanks
Ridgeway High	4/4/2024 8:06	SMITH	Key & Lock	Z3-007681	Need key SKD6 for financial secretary's storage closet in main office, thanks
Ridgeway High	5/8/2024 9:18	BURCHETT	Masonry	Z3-013633	Need ceramic tile pieces repaired at bottom of stall doors
Ridgeway High	5/8/2024 7:08	BURCHETT	Masonry	Z3-013556	Same area leaking at rear of cafeteria that needs repairing
Ridgeway High	4/9/2024 11:45	CORONADO	Masonry	Z3-008399	ill continues to leak at rear of cafeteria and in the custodial supply closet that's in the cafeteria
Ridgeway High	4/9/2024 7:23	CORONADO	Masonry	Z3-008262	Continues to leak
Ridgeway High	2/3/2024 14:26	CORONADO	Masonry	WO1031422	ater is still leaking (worse) in same areas in custodial storage closet area in cafeteria, thanks
Ridgeway High	2/3/2024 14:26	CORONADO	Masonry	WO1031423	
	2/3/2024 14:30	CORONADO	Masonry		t rear of gym lobby which is the floor of the mechanical room sealed to prevent future ceiling leaks, thanks
Ridgeway High			•		
Ridgeway High	2/3/2024 15:19	CORONADO	Masonry	WO1029389	Same area leaking in cafeteria, thanks

Ridgeway High	2/3/2024 15:19	CORONADO	Masonry	WO1029394	Same area leaking in custodial closet in cafeteria area, thanks	
Ridgeway High	5/17/2024 14:26	CORONADO	Masonry	WO1010771	odial closet located in cafeteria area, thanks The water is coming in through the concrete slab above (WALKWAY)	
Ridgeway High	12/9/2024 10:46	BURCHETT	Painting	Z3-044040	Need rear gym painted including lockers in locker rooms, thanks	
Ridgeway High	12/3/2024 8:28	BURCHETT	Painting	Z3-042732	Need KILZ "Attn Mr. Burchett/Quentin Harris)	
Ridgeway High	11/14/2024 9:45	BURCHETT	Painting	Z3-040806	All floor tile is being removed and will need entire floor painted with EPOXY asap, thanks	
	7/30/2024 7:38	BURCHETT	=			
Ridgeway High			Painting	Z3-023561	Classroom needs painting	
Ridgeway High	7/30/2024 7:36	BURCHETT	Painting	Z3-023560	Classroom needs painting	
Ridgeway High	5/17/2024 10:13	BURCHETT	Painting	Z3-015008	Need several exterior doors around school building painted, thanks	
Ridgeway High	5/9/2024 14:22	BURCHETT	Painting	Z3-013953	Ceiling is peeling and needs painting, thanks	
Ridgeway High	5/17/2024 14:23	BURCHETT	Painting	WO1005799	Need cattle-gates painted on south side of school that enters to rear parking lot	
Ridgeway High	5/17/2024 14:19	BURCHETT	Painting	WO1002790	Need stairwell railing painted due to rusting, thanks	
Ridgeway High	5/17/2024 13:48	MYERS	Painting	WO985251	d 6 classroom exterior doors on the south side of school painted as they are very faded, thanks	
Ridgeway High	11/20/2024 9:57	BARNES	Plumbing	Z3-041674	Same issue with toilet overflowing in 3rd stall	
0 , 0			· ·		test three backflows	
Ridgeway High	9/27/2024 10:39	WILSON	Plumbing	Z3-035106		
Ridgeway High	9/19/2024 9:16	WILSON	Plumbing	Z3-033609	Fire hydrant leaking	
	2/3/2024 15:42	BENTON	Shades/Blinds	WO1027525		
Ridgeway High						
Ridgeway High	5/17/2024 14:00	BENTON	Shades/Blinds	WO992882	Need blinds replaced in classroom 320, thanks	
Ridgeway High	5/17/2024 13:59	BENTON	Shades/Blinds	WO991819	Need shades replaced/repaired in classroom 329, thanks	
Ridgeway High	5/17/2024 13:59	BENTON	Shades/Blinds	WO991818	Need shades repaired/replaced in classroom 327, thanks	
Ridgeway High	7/9/2024 17:21	HATCH	Sheet Metal	Z3-020651	Need rooftop hatch in rear gym repaired to close properly	
Ridgeway Middle	5/30/2024 11:11	SMALL	Bleachers and Seats	Z3-016486	Bleacher inspection	
Ridgeway Middle	12/9/2024 7:44	SCOTT	Electrical	Z3-043936	Bad light ballast	
Ridgeway Middle	11/20/2024 12:43	SCOTT	Electrical	Z3-041754	Ground prong stuck in socket	
Ridgeway Middle	8/15/2024 8:06	WHITWORTH	Electrical	Z3-027657	Breaker keep flipping off	
					Restore Lighting in Parking Lot	
Ridgeway Middle	7/17/2024 13:43	Electric	Electrical	Z3-021549		
Ridgeway Middle	8/23/2024 9:40	SMALL	Elevators	Z3-029253	Piece of metal came off. Elevator won't open on the 2nd flr	
Ridgeway Middle	10/29/2024 7:48	SCOTT	Fire Alarm System	Z3-038624	Strobe light (fire alarm light) hanging from wall	
radgeway raddic	10/20/2024 / .40	00011	riic Admi dystem	20 000024	otrobe tight (the daint agit,) runging from wat	
					Buildings within 30ft should be tied into fire alarm. Need to follow up with this. Eddie	
B	F 10.4 10.00 4 4 4 0.0		- u o .	70 040745	Buildings within 30it should be theu into the alahii. Need to lottow up with this, Edule	
Ridgeway Middle	5/31/2024 11:06	SMALL	Fire Alarm System	Z3-016715		
Ridgeway Middle	2/25/2024 13:31	JOHNSON	Fire Alarm System	Z3-002756	Fire alarm panel 001 supervisory power supply N104M	
					Relocate Sprinkler away from Fan Coil Unit to perform repairs.	
Ridgeway Middle	8/16/2024 15:02	Systems	Fire Sprinkler System	Z3-028201		
					5 year sprinkler inspection	
Ridgeway Middle	5/31/2024 11:03	SMALL	Fire Sprinkler System	Z3-016714		
					Sprinkler head cover needs to be adjusted closer to ceiling tile. (POCA)	
Ridgeway Middle	5/29/2024 11:27	SMALL	Fire Sprinkler System	Z3-016305		
Ridgeway Middle	12/16/2024 8:30		Heating/Ventilation/Air Conditioning	Z3-044979	Burning plastic smell coming from unit	
,					Mr. blue	
					61588	
					no heat	
Ridgeway Middle	12/5/2024 13:27	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043650	no neat	
Hugeway Flidute	12/5/2024 15.2/	OOLIIIL	riedding Veriddadoll/All Colluddolling	25-045050	Mr. blue	
					61588	
					no heat	
Ridgeway Middle	12/5/2024 13:26	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043648		
					Mr. blue	
					61588	
					no heat	
Ridgeway Middle	12/5/2024 13:25	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043647		
					Mr. blue	
					61588	
					no heat	
Ridgeway Middle	12/5/2024 13:25	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043646		
		00E		_0 0.0040	Mr. blue	
					61588	
Distance Mill !	40/5/000011001	0055	Handing Managhas (1970)	70.01001	no heat	
Ridgeway Middle	12/5/2024 13:24	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043643		
					Mr. blue	
					61588	
					no heat	
Ridgeway Middle	12/5/2024 13:24	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043642		

					61588
					no heat
Ridgeway Middle	12/5/2024 13:23	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043641	
					Mr. blue
					61588
					no heat
Ridgeway Middle	12/5/2024 13:22	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043640	
Ridgeway Middle	11/5/2024 9:25	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-039570	Condensation buildup from ac damaging the gym floor
					Pipes leaks and damage gym floor.
Ridgeway Middle	10/2/2024 15:42	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-035969	
Ridgeway Middle	9/26/2024 9:47	MALONE	Key & Lock	Z3-034858	No access
Ridgeway Middle	9/13/2024 9:47	SMITH	Key & Lock	Z3-032586	Need keys for room no access
Ridgeway Middle	7/10/2024 8:40	SMITH	Key & Lock	Z3-020689	New key for room. Rekey
Ridgeway Middle	2/13/2024 9:37	SMITH	Key & Lock	Z3-001154	Principal Ragg Washington request exterior door to be rekeyed.
Ridgeway Middle	5/17/2024 14:17	BURCHETT	Painting	WO999078	Please repaint rails in stairwells
Ridgeway Middle	11/20/2024 12:22	WARREN	Plumbing	Z3-041747	1 and 1/4 cup off for gas line
Ridgeway Middle	4/26/2024 14:21	WARREN	Plumbing	Z3-011800	Pipe leaking
Ridgeway Middle	4/23/2024 14:22	BARNES	Plumbing	Z3-011120	Water fountain no power showing. No lights
Ridgeway Middle	5/31/2024 11:00	SMALL	Dell He Deere	Z3-016712	Inspection (roll up doors)
• ,	11/5/2024 11:00	HATCH	Roll Up Doors	Z3-016/12 Z3-039574	Shoot motal coming from the wall
Ridgeway Middle Riverview School	12/10/2024 9:28	FORD	Sheet Metal	Z4-044175	Sheet metal coming from the wall
Riverview School	11/15/2024 10:12	FORD	Carpentry Carpentry	Z4-044175 Z4-041050	Partition needs to be replaced Plunger is not sucking Chrisbar is not functioning
Riverview School	10/3/2024 7:46	HALL	Carpentry	Z4-041030 Z4-036002	Electrical
Niverview Scrioot	10/3/2024 /.40	HALL	Carpentry	24-030002	Has a hole in the ceiling need to be fixed
Riverview School	6/17/2024 10:51	FORD	Carpentry	Z4-018548	rias a note in the celling need to be inced
Riverview School	6/10/2024 13:48	FORD	Carpentry	Z4-017912	Lock need to be changed off the door
THE VIEW SCHOOL	0/10/2024 10.40	TOND	Curpentry	24 01/012	Cafe Ahu Main power goes in and out.
Riverview School	12/9/2024 6:28	HALL	Electrical	Z4-043917	Culto filla Fialli portoli godo ili alila cult
Riverview School	12/4/2024 11:04	HALL	Electrical	Z4-043314	Exit sign the door need to be replaced
Riverview School	12/2/2024 15:35	HALL	Electrical	Z4-042646	Wall sockets are not working in classrooms on the whole back wall
					Chiller keep tripping the main breaker
Riverview School	11/1/2024 6:22	HALL	Electrical	Z4-039161	
Riverview School	10/21/2024 8:21	HALL	Electrical	Z4-037597	Light is not working need balancer right in front of room 226 electrical room
Riverview School	9/5/2024 8:24	CALDWELL	Elevators	Z4-031041	Both sense of elevators, not working in school
					No heat in entire building
Riverview School	12/12/2024 7:57	Controls	Heating/Ventilation/Air Conditioning	Z4-044540	
Riverview School	12/6/2024 9:55	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-043781	Pipe is leaking
Riverview School	12/2/2024 13:57	MALONE	Key & Lock	Z4-042579	Doorhandle need to be replaced for lock
Riverview School	10/30/2024 18:08	MALONE	Key & Lock	Z4-038981	Need A key for school building
Riverview School	7/26/2024 8:05	SMITH	Key & Lock	Z4-022750	Need to have lock replaced for door with key
Riverview School	7/16/2024 10:54	SMITH	Key & Lock	Z4-021371	Main office need key for desk key number CR145
Riverview School	12/13/2024 8:00	JOHNSON	Plumbing	Z4-044831	Boys toilet is not working
Riverview School	12/13/2024 7:58	JOHNSON	Plumbing	Z4-044829	Boys urinal is not working
Riverview School	11/15/2024 6:59	JOHNSON	Plumbing	Z4-040980	Boys urinal is overflowing water just to run has been shut off
Riverview School	10/18/2024 10:46	JOHNSON	Plumbing	Z4-037494	Sink by the door is not draining for cafeteria
Riverview School	8/8/2024 13:30	JOHNSON	Plumbing	Z4-026460	Toilet has broke need to be replaced
Riverview School	2/3/2024 16:44	BENTON	Shades/Blinds	WO1021074	Kindergarten class need blind room 109
					The lights on the side of the building where teacher and kids enter/exit are out! Very
					dangerous during daylight savings
Riverwood Elementary School	11/21/2024 14:09	POWELL	Electrical	Z2-041986	
					clock setting on top of building
Riverwood Elementary School	9/25/2024 7:37	POWELL	Electrical	Z2-034571	dist. Circular 4000 0744 Datasta
Discoursed Flores and a second	44/04/00040-00	0-1	Fire Manus Contains	70.044050	dirty Simplex 4098-9714 Detector
Riverwood Elementary School	11/21/2024 8:30	Coleman	Fire Alarm System	Z2-041852	
Discoursed Flores and a second	10/18/2024 14:39	Coleman	Fire Manus Contains	70.007504	dirty smoke detector making trouble signals
Riverwood Elementary School	10/18/2024 14:39	Coteman	Fire Alarm System	Z2-037534	describes and final and bear as for
Divonuod Flomentani School	11/25/2024 7:42	Coleman	Generators	Z2-042144	generator making loud beep noise
Riverwood Elementary School	11/25/2024 /:42	Coteman	Generators	ZZ-U4Z144	Per technician- generator needs fuel.
Riverwood Elementary School	2/9/2024 11:19	Coleman	Generators	Z2-000856	rei teciniician-generator neeus tuet.
Taverwood Elementary School	21312024 11.13	Cotellidii	Generators	22-000000	NO HEAT cool air blowing
Riverwood Elementary School	12/11/2024 8:54	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044432	NO TIENI COOLGII DIOMING
111VC1WOOD Elementary School	12/11/2024 0.04	DITIOUN	ricating/ventilation/Air Conditioning	22-044402	

Mr. blue

					science lab no heat. reading 60. stagnant air
Riverwood Elementary School	12/10/2024 13:46	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044334	colonica and no notal rotaling co. caughtain an
					Busted thermostat making temperature all over
Riverwood Elementary School	12/9/2024 14:21	BRYSON	Heating/Ventilation/Air Conditioning	Z2-044109	Air stagnant no heat blowing
Riverwood Elementary School	12/5/2024 13:35	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043656	All Stagnant no near blowing
, , , , , , , , , , , , , , , , , , , ,					Cool air blowing out
Riverwood Elementary School	12/5/2024 13:34	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043655	
Riverwood Elementary School	12/5/2024 10:08	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043546	NO HEAT kindergarten reaching 50 degrees
Riverwood Elementary School	12/3/2024 10.06	BRISON	neating/ventitation/Air Conditioning	22-043340	No heat. Stagnant air
Riverwood Elementary School	12/4/2024 9:10	BRYSON	Heating/Ventilation/Air Conditioning	Z2-043191	· ·
Riverwood Elementary School	12/2/2024 14:08	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042587	Plant Manager Rutherford reported the unit in the Science Lab is blowing cold air.
Riverwood Elementary School	12/2/2024 14.06	BRISON	neating/ventitation/Air Conditioning	22-042307	Plant Manager Rutherford reported the unit in the cafeteria is blowing cold air.
Riverwood Elementary School	12/2/2024 14:06	BRYSON	Heating/Ventilation/Air Conditioning	Z2-042586	
					classroom needs new key. Current key does not work
Riverwood Elementary School	12/12/2024 10:22	MALONE	Key & Lock	Z2-044684	3 A keys
Riverwood Elementary School	9/19/2024 9:26	SMITH	Key & Lock	Z2-033637	3 A keys
THIOTHOUGH Elementary contest	0,10,20240120	O	Noy a 200k	22 000007	3 keys made for vault door
Riverwood Elementary School	9/19/2024 9:25	SMITH	Key & Lock	Z2-033633	
					need parking lot re-striped lines. faded and non visible lines creating confusion and chaos
Riverwood Elementary School	9/26/2024 10:54	BARNES	Painting	Z2-034897	after school
Riverwood Elementary School	8/8/2024 12:04	BURCHETT	Painting	Z2-026427	Bricks need repaired (Hazard when kids outside playing)
Riverwood Elementary School	7/19/2024 18:11	BURCHETT	Painting	Z2-020427 Z2-021759	Per principal Micheal Lowe hallways
Riverwood Elementary School	7/19/2024 18:08	BURCHETT	Painting	Z2-021758	per principal Dr.Micheal Lowe request for his office to be paint.
Riverwood Elementary School	9/12/2024 9:40	Bryant	Roofing	Z2-032181	Leaking in the cafeteria
Riverwood Elementary School	9/12/2024 9:39	Bryant	Roofing	Z2-032181 Z2-032180	Leaking in the gym
THIVETWOOD Elementary democr	3/12/2024 3:00	Dryunt	riconing	22 002100	Request for ceiling tile to be replaced. It has a sprinkler and exit sign attached
Robert R. Church Elementary	8/5/2024 9:51	BENTON	Carpentry	Z4-025187	
					The outside wall pack light is out at this entry
Robert R. Church Elementary	10/1/2024 8:30	HALL	Electrical	Z4-035619	
Robert R. Church Elementary	9/11/2024 8:13	TEDDER	Electrical	Z4-031883	the walk pack lighting is not working in the back of the building .
Robert R. Church Elementary	9/11/2024 8:12	HALL	Electrical	Z4-031880	The two pole lights are not working
Robert R. Church Elementary	3/19/2024 8:57	HALL	Electrical	Z4-005342	The outside parking lighting will not come on in the evenings due to a power outage.
Robert R. Church Elementary	12/4/2024 11:15		Fire Alarm System	Z4-043326	Fire alarm has system ground on panel
Robert R. Church Elementary	2/3/2024 14:24	CASEY	Flooring	WO1031579	Request for a the carpet to be removed. It has taken on lots of water from ceiling leaks.
Robert R. Church Elementary	12/4/2024 8:08	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043127	HVAC UNIT FOR THE CAFE - BLOWING COLD AIR PM/HARDMAN 416-0198
nobert it. Onarch Elementary	12/4/2024 0.00	DOWNER	ricumg vendudon/ai conditioning	24 040127	HVAC UNIT FOR THE MAIN LIBRARY - BLOWING COLD AIR PM/HARDMAN 416-0198
Robert R. Church Elementary	12/4/2024 8:07	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043126	
					UNIT NOT HEATING - PRINCIPALS OFFICE
					P/M HARDMAN 416-0198
Robert R. Church Elementary	12/3/2024 8:14	DOWNER	Heating/Ventilation/Air Conditioning	Z4-042726	LIVACUINIT IN DALEAGO, MOTOR LIAG LOGICER LIR. NOT COMINIO ON RAVILLARITMAN, 440
					HVAC UNIT IN RM E116 - MOTOR HAS LOCKED UP - NOT COMING ON PM/HARTMAN 416- 0198
Robert R. Church Elementary	9/25/2024 12:58	DOWNER	Heating/Ventilation/Air Conditioning	Z4-034680	0130
Robert R. Church Elementary	11/15/2024 7:37	MALONE	Key & Lock	Z4-034000 Z4-040991	A pencil was broken off in the lock cylinder
Robert R. Church Elementary	10/23/2024 12:19	MALONE	Key & Lock	Z4-038019	Request two AB classroom master key #563876
Robert R. Church Elementary	9/9/2024 10:21	SMITH	Key & Lock	Z4-031499	Request one A Grand master key As per principle fifer 4160198
Robert R. Church Elementary	9/9/2024 10:19	SMITH	Key & Lock	Z4-031497	Request one CB-1 key
Robert R. Church Elementary	9/9/2024 10:15	SMITH	Key & Lock	Z4-031492	Request a classroom key for this room, key bit# 343236 AB-18
Robert R. Church Elementary	9/25/2024 12:18	BURCHETT	Masonry	Z4-031452 Z4-034669	Request for the broken off tiles to be replaced.
Robert R. Church Elementary	7/23/2024 10:32	BURCHETT	Painting	Z4-034003 Z4-022103	Request to have the parking lot lines stenciled
Robert R. Church Elementary	6/18/2024 13:12	BURCHETT	Painting	Z4-022103 Z4-018785	Request for the exterior entry doors to be painted
Robert R. Church Elementary	12/5/2024 8:01	HARRIS	Plumbing	Z4-010765 Z4-043445	The toilet will not flush
Robert R. Church Elementary	11/21/2024 8:55	HARRIS	Plumbing	Z4-043445 Z4-041865	The handicap commode will splash water from the neck when flush
Robert R. Church Elementary	8/5/2024 10:45	HARRIS	Plumbing	Z4-041665 Z4-025244	The hot water handle has broken off.
nobert it. Offuren Eternelitäry	3/3/2024 10.43	HAINIS	i tullibilig	24-020244	prep bottle fillers for inspections
Robert R. Church Elementary	6/8/2024 9:03	WILSON	Plumbing	Z4-017773	prop bottle intera for inappeditions
Ross Elementary	12/5/2024 9:24	SMITH	Audio Visual	Z3-043516	HDMI/USB port is malfunctioning on stage
1.000 Etomontary	12.0.2027 0.27	S. 2011	, add vidut	20 0 40010	The time does post to manufactioning on dauge

Ross Elementary	6/20/2024 11:27	BARNES	Carpentry	Z3-018914	Back door latch is broke going outside. Door keep popping open leading outside
Ross Elementary	11/18/2024 10:13	SCOTT	Electrical	Z3-041236	Exit lights not working in gym
Ross Elementary	11/18/2024 10:12	SCOTT	Electrical	Z3-041235	Pole light are not coming on when it get dark
Ross Elementary	11/18/2024 10:11	SCOTT	Electrical	Z3-041234	Exit lights need to be fixed in cafeteria
*					Please reconnect electrical power to newly installed water heater
Ross Elementary	10/15/2024 6:16	SCOTT	Electrical	Z3-036939	, , , , , , , , , , , , , , , , , , , ,
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,					Please reconnect Power to new electric water heater
Ross Elementary	10/7/2024 6:27	SCOTT	Electrical	Z3-036362	
Ross Elementary	7/26/2024 8:53	SCOTT	Electrical	Z3-022806	2 balancer
Ross Elementary	7/26/2024 8:50	SCOTT	Electrical	Z3-022795	1 balancer
Ross Elementary	7/26/2024 8:50	SCOTT	Electrical	Z3-022794	2 balancer up stairs by elevator
Ross Elementary	7/26/2024 8:49	SCOTT	Electrical	Z3-022794 Z3-022792	2 balancer
Ross Elementary	7/26/2024 8:49	SCOTT	Electrical	Z3-022792 Z3-022790	1 balancer
,		SCOTT		Z3-022787	1 balancer
Ross Elementary	7/26/2024 8:48		Electrical		
Ross Elementary	7/24/2024 10:54	SCOTT	Electrical	Z3-022356	1 balancer
Ross Elementary	7/24/2024 10:15	SCOTT	Electrical	Z3-022323	One balancer needed
Ross Elementary	7/24/2024 10:12	SCOTT	Electrical	Z3-022317	One balancer
Ross Elementary	7/24/2024 10:11	SCOTT	Electrical	Z3-022314	1 balancer needed
					Correct plumbing and electrical issues with Bottle Fillers
Ross Elementary	4/16/2024 6:26	CHALK	Electrical	Z3-009430	
Ross Elementary	5/21/2024 16:19		Fire Alarm System	Z3-015511	Exit sign facing the wrong way
Ross Elementary	12/6/2024 10:01	LEWIS	Flooring	Z3-043787	tball season for elementary starts next month and I have a few floor times that need to be replaced
Ross Elementary	6/10/2024 14:38	CASEY	Flooring	Z3-017939	Cafe eating area has a lot of tile coming up in different spots
					HEATING UNIT FOR THE 2ND GRADE HALLWAY - COVERS (5) RMS - NOT COMING ON
					PM/SHELLY 416-1990
Ross Elementary	12/6/2024 9:53	BRYSON	Heating/Ventilation/Air Conditioning	Z3-043779	
					UNIT NOT COMING ON - MUSIC ROOM (3-48)
					P/M GREG SHELLEY 416-1990
Ross Elementary	12/3/2024 8:40	BRYSON	Heating/Ventilation/Air Conditioning	Z3-042747	
•					
					Plant Manager Shelly reported the HVAC unit in room 1-05 is blowing cold air. 416-1990
Ross Elementary	12/2/2024 11:11	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-042474	
•					unit not getting cold blowing and making noise
Ross Elementary	9/17/2024 9:44	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-033125	0.000
nood Etomontary	0/1//2024 0144	***************************************	riodalily volidiadilinal conditioning	20 000120	air not coming on
Ross Elementary	7/26/2024 11:51	JOHNSON	Heating/Ventilation/Air Conditioning	Z3-022929	an not conning on
noss Etementary	772072024 11:01	3011140014	ricading vendudonizar donardoning	20 022020	HVAC UNIT IN RM 105 - NOT COMING PM/SHELLY 416-1990
Ross Elementary	7/23/2024 12:50	SCOTT	Heating/Ventilation/Air Conditioning	Z3-022152	THAO ON IN THE 150 NOT OUT INCT PROTECT 410 1000
11033 Eternemary	772372024 12.30	30011	rieating ventilation/Air Conditioning	25-022152	AC Unit in Room W24 is not coming on at all. PM. Shelley. 416-1990.
Ross Elementary	4/16/2024 11:08	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-009587	AC Official room w24 is not confining on at all. 1 Pt. Shelley, 410-1330.
noss Elementary	4/10/2024 11.00	WHIIWOKIH	Heating/Ventitation/Air Conditioning	23-009367	HVAC UNIT FOR RM 205 - NOT COMING ON PM/SHELLY 416-1990
Dana Flammana	4/0/00040-57	WHITWORTH	Handing Of and Hading (Air One diding in a	Z3-008319	NVAC UNIT FOR KIM 203 - NOT COMING ON PM/SHELLT 410-1990
Ross Elementary	4/9/2024 8:57	WHIIWORIH	Heating/Ventilation/Air Conditioning	23-008319	LINIT NOT LIFETING. OF DAGG 44 0 G 46FFFDING OFF THE CAME UNITDIA CUELLY 440
					UNIT NOT HEATING - CL-RMS 3-41 & 3-43FEEDING OFF THE SAME UNITP/M SHELLY 416-
					1990
Ross Elementary	2/3/2024 14:30	BRYSON	Heating/Ventilation/Air Conditioning	WO1031205	
Ross Elementary	5/21/2024 16:14	SMALL	Kitchen Hood	Z3-015510	POCA Hood and duct annual cleaning date
Ross Elementary	8/14/2024 9:46	CORONADO	Masonry	Z3-027465	Tile on boys bathroom floor red hall is coming up
					Red brick floor tiles coming up in the kitchen
Ross Elementary	6/10/2024 14:36	BURCHETT	Masonry	Z3-017934	1/3 of the floor has came up
Ross Elementary	2/3/2024 13:47	CORONADO	Masonry	WO1032835	Kitchen tiles coming up
Ross Elementary	7/1/2024 12:01	BURCHETT	Painting	Z3-019955	Need parking lot lines repainted
Ross Elementary	6/21/2024 7:47	BURCHETT	Painting	Z3-018974	We need our parking lot lines repainted
					Water Heater is leaking beyond repair
Ross Elementary	12/12/2024 7:55	PEARSON	Plumbing	Z3-044539	
Ross Elementary	12/10/2024 9:41	WARREN	Plumbing	Z3-044221	Hot water tank leaking a lot of water down stairs annex across from room 120
					annual testing of 2- backflow preventers
Ross Elementary	10/3/2024 13:30	WILSON	Plumbing	Z3-036149	
Ross Elementary	11/6/2024 13:09	BUFORD	Roofing	Z3-039912	Several leaks in Rm 1-05 blue hall 1st grade
Ross Elementary	11/6/2024 10:32	BUFORD	Roofing	Z3-039833	Roof leak blue hall in front of girls bathroom
Ross Elementary	11/6/2024 10:31	BUFORD	Roofing	Z3-039830	Roof leak bottom of green hall
Ross Elementary		BUFORD	-	Z3-039829	
	11/6/2024 10:30 11/6/2024 10:30	BUFORD	Roofing		Roof leak gym
Ross Elementary			Roofing	Z3-039828	Roof leak out side Prek boys bathroom red hall
Ross Elementary	10/28/2024 11:45	BUFORD	Roofing	Z3-038544	Leak in cafeteria by serving line
Ross Elementary	9/18/2024 15:23	WILSON	Roofing	Z3-033522	Bottom of green hall has serveal leaks

Ross Elementary	9/13/2024 9:12	WILSON	Roofing	Z3-032543	Room e-49 is leaking
Ross Elementary	9/13/2024 9:12	BUFORD	Roofing	Z3-032545 Z3-032536	Bottom of green hall by back door is leaking
Ross Elementary	9/13/2024 9:04	WILSON	Roofing	Z3-032528	Leak first grade blue hall by girls bathroom
Ross Elementary	3/8/2024 15:34	BARNES	Roofing	Z3-004732	Roof is leaking
					1 half of the room lights are out. and students cant see there work.
Rozelle Elementary	12/4/2024 9:13	ANDREWS	Electrical	Z1-043193	There is an alarm that keeps going off in the fire panel and it reads NAC 1 open. Batteries
					needed
Rozelle Elementary	10/15/2024 12:30	GREER	Fire Alarm System	Z1-037067	
Rozelle Elementary	2/10/2024 14:59	CASEY	Flooring	Z1-000915	Test General S Carpet Repair with Pre-K Cause HEATING UNIT IN RM 25 - NOT HEATING PM/HAYES 416-8775
Rozelle Elementary	12/3/2024 8:40	WEBB	Heating/Ventilation/Air Conditioning	Z1-042746	REALING ONLY IN N.Y 25 - NOT REALING PRIVATES 410-07/5
,					HEATING UNIT IN RM 30 - NOT HEATING PM/HAYES 416-8775
Rozelle Elementary	12/3/2024 8:40	WEBB	Heating/Ventilation/Air Conditioning	Z1-042745	
					HEATING UNIT IN RM 34 - NOT HEATING PM/HAYES 416-8775
Rozelle Elementary	12/3/2024 8:39	WEBB	Heating/Ventilation/Air Conditioning	Z1-042743	
Decelle Floreseters	40/0/0004 0:00	WEDD	He sain and famalitation (Air Occadition in a	74 040740	HEATING UNIT IN RM 12 - NOT HEATING PM/HAYES 416-8775
Rozelle Elementary	12/3/2024 8:38	WEBB	Heating/Ventilation/Air Conditioning	Z1-042742	HEATING UNIT IN RM 17 - NOT HEATING PM/HAYES 416-8775
Rozelle Elementary	12/3/2024 8:38	WEBB	Heating/Ventilation/Air Conditioning	Z1-042741	REALING ONLY IN NOT 17 - NOT REALING PRIVATES 410-07/5
nozotto ztomontary	12,0,20240.00	***************************************	ricating volutions and contains	21 0-127-12	Plant Manager hayes reported the unit in room 20 on the second floor is blowing cold air.
					378-2478.
Rozelle Elementary	12/2/2024 12:48	WEBB	Heating/Ventilation/Air Conditioning	Z1-042546	
					Mr. Hayes 378-2478 unit not heating
Rozelle Elementary	11/22/2024 14:15	WEBB	Heating/Ventilation/Air Conditioning	Z1-042103	HVAC UNIT FOR THE KITC - NOT COOLING PM/HAYES 416-8775
Rozelle Elementary	10/31/2024 10:10	WEBB	Heating/Ventilation/Air Conditioning	Z1-039056	HVAC UNIT FOR THE KITC - NOT COOLING FIFTHATES 410-67/3
nozotto ztomontary	10/01/2024 10/10	***************************************	ricularly volume conditioning	21 000000	HVAC UNIT IN THE KITC - NOT COOLING PM/HAYES 416-8775
Rozelle Elementary	10/2/2024 12:26	WEBB	Heating/Ventilation/Air Conditioning	Z1-035929	
					HVAC UNIT IN RM 6 - NOT COOLING PM/HAYES 416-8775
Rozelle Elementary	10/2/2024 12:25	WEBB	Heating/Ventilation/Air Conditioning	Z1-035928	
Dezelle Flementen	10/2/2024 12:25	WEBB	Heating Montilation / Air Conditioning	Z1-035927	HVAC UNIT IN RM 34 - NOT COOLING PM/HAYES 416-8775
Rozelle Elementary	10/2/2024 12:25	WEBB	Heating/Ventilation/Air Conditioning	21-035927	Dr. Hines says there has been a security breach and he is requesting his office and the outer
					office locks be changed and only the Plant manager and and he be the only 2 people to have
					keys to this area because of the breach of security and missing items. He wants a total of 4
					keys be given to plant manager,
Rozelle Elementary	4/30/2024 18:47	SMITH	Key & Lock	Z1-012398	
					in preparations for a visit from the Govenor and the Superintendent The office counters
					were moved to the new main office and it lefts a really ugly hole in the wall that needs to be
					fixed and painted. Dr. Hines have meetings in this conference room.
Rozelle Elementary	9/11/2024 11:03	BURCHETT	Painting	Z1-031977	
					In preparations for a visit from the Govenor and the Superintendent on Next week Dr. Hines
	0/44/00044040	BUBBUETT		74 004050	is requesting Room 33 Be painted.
Rozelle Elementary	9/11/2024 10:13	BURCHETT	Painting	Z1-031953	In preparation for the visit from the Governor and the Superintendent next week Dr. Hines is
					requesting Room 32 be painted
Rozelle Elementary	9/11/2024 10:11	BURCHETT	Painting	Z1-031951	
					In preparations for the Govenor and Superintendent visit on next week, Dr. Hines is
					requesting All 3 stairwells be painted
Rozelle Elementary	9/11/2024 10:07	BURCHETT	Painting	Z1-031949	in propagation for the Coupage and Conscipton dentities a next week Dr. Hings is requesting
					in preparation for the Govenor and Superintendent visit on next week Dr. Hines is requesting the cafeteria be painted.
Rozelle Elementary	9/11/2024 10:04	BURCHETT	Painting	Z1-031947	are careteria de parinca.
,					In preparation for the Govenor and Superintendent visit on next week Dr. Hines is requesting
					the 3rd floor hallway to be painted
Rozelle Elementary	9/11/2024 9:58	BURCHETT	Painting	Z1-031939	
					In preparation for the Govenor and Superintendent visit to Rozelle next thursday Dr. Hines is
Rozelle Elementary	9/11/2024 9:54	BURCHETT	Painting	Z1-031937	requesting the 2nd floor hallway be painted
	0,11,2024 0,04	DOMONIEN	. among	21 00100/	
					The lockers were moved today and Dr. hines is requesting the affected area be painted
Rozelle Elementary	7/31/2024 16:22	BURCHETT	Painting	Z1-024159	

					Dr. Hines is requesting this room be painted.
Rozelle Elementary	7/23/2024 18:39	BURCHETT	Painting	Z1-022221	Sit times to requesting time room se painted.
					peeling paint on north west wall and crumbling of the wall also.
Rozelle Elementary	7/23/2024 18:38	BURCHETT	Painting	Z1-022220	
Scenic Hills Elementary	12/15/2024 19:20	LANE	Asbestos	Z1-044947	used fluorescent bulb pick up
Scenic mills Elementary	12/15/2024 19.20	LAINE	ASDESIOS	21-044947	Mr. Smith 64342 blowing cold air
Scenic Hills Elementary	12/2/2024 14:00	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042583	
					REPLACE BUTTERFLY VALVE FOR PUMP #2
Scenic Hills Elementary	3/21/2024 12:59	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-005748	
Scenic Hills Elementary	11/7/2024 12:45	MALONE	Key & Lock	Z1-040140	Principal requesting a gm master for service partners
Scenic Hills Elementary	11/7/2024 12:41	MALONE	Key & Lock	Z1-040139	Need lock changed
Scenic Hills Elementary Scenic Hills Elementary	5/20/2024 12:42 5/20/2024 12:40	BURCHETT BURCHETT	Painting Painting	Z1-015247 Z1-015245	Painting Painting
Scenic Hills Elementary	5/20/2024 12:40	BURCHETT	Painting	Z1-015245 Z1-015244	Painting
Scenic Hills Elementary	5/20/2024 12:31	BURCHETT	Painting	Z1-015244 Z1-015233	Painting
Scenic Hills Elementary	5/20/2024 12:12	BURCHETT	Painting	Z1-015227	Painting (can we pick a color)
Scenic Hills Elementary	5/20/2024 12:07	BURCHETT	Painting	Z1-015225	Paint
Scenic Hills Elementary	5/20/2024 12:06	BURCHETT	Painting	Z1-015224	Paint
Scenic Hills Elementary	5/20/2024 12:04	BURCHETT	Painting	Z1-015223	Painting
Scenic Hills Elementary	5/20/2024 12:03	BURCHETT	Painting	Z1-015222	Painting
Scenic Hills Elementary	5/20/2024 12:01	BURCHETT	Painting	Z1-015221	Painting
Scenic Hills Elementary	5/20/2024 12:01	BURCHETT	Painting	Z1-015220	Painting
Scenic Hills Elementary	5/2/2024 12:00	BURCHETT	Painting	Z1-012811	Need signs painted or get parking area restenciled
Scenic Hills Elementary	3/22/2024 10:42	BURCHETT	Painting	Z1-005925	Paint columns outside at entrance ways
Scenic Hills Elementary	5/17/2024 13:55 10/30/2024 10:40	BURCHETT	Painting	W0991461 Z1-038894	Ceiling in kitchen paint peeling
Scenic Hills Elementary Scenic Hills Elementary	5/17/2024 13:54	Jordan BENTON	Plumbing Shades/Blinds	W0990143	Water fountain leaking Need new shades for pre k rooms in annex building
Scenic rius Elementary	3/1//2024 13.34	BEINTOIN	Sildues/bullus	W0990143	Need new shades for pre k rooms in annex building
					Install accordion gates in aisles by mail room. Contact Reggie Oliver 901.659.2627
SCS HQ Admin BLDG	12/12/2024 14:19	OLIVER	Carpentry	Z1-044770	
					Large mirror needs to be glued back up on the wall
SCS HQ Admin BLDG	12/3/2024 13:57	STEPHENS	Carpentry	Z1-043023	
					Metal Panels are coming loose. Building exposed to weather and potential for door to come
					off track and not be secured. Roll up doors
SCS HQ Admin BLDG	10/21/2024 13:42	SHIPPS	Carpentry	Z1-037701	
SCS HQ Admin BLDG	12/4/2024 13:46	ANDREWS	Electrical	Z1-043391	replace ballast in 2 light fixtures
3C3 HQ AUIIIII BLDG	12/4/2024 13.40	ANDREWS	Electricat	21-043391	Service elevator outer is stuck and will not close properly
SCS HQ Admin BLDG	12/2/2024 11:39	GREER	Elevators	Z1-042495	Service elevator outer is stuck and with not close property
00011Q /\dillillilli D2D0	12/2/2024 11:00	OHEEN	Lievatore	21 0 12 100	BEHIND THE BEAR BLDG IN THE GUARD SHACK - HEATS NOT COMING ON PM/WALKER -
					692-4755
SCS HQ Admin BLDG	11/21/2024 7:05	WEBB	Heating/Ventilation/Air Conditioning	Z1-041820	
					Entire Building HVAC Blower Intermitting (Wardy Parks; 9012187117)
SCS HQ Admin BLDG	11/15/2024 14:00	SIMMONS	Heating/Ventilation/Air Conditioning	Z1-041109	
COCULO A desira PLDO	0/04/000440-04	WEDD	Hanking 8 (analikation (Air Oan ditioning	74 004507	Tonia Nelson, 901-416-4679 thermostat is blank, Long radiator looking not blowing air
SCS HQ Admin BLDG	9/24/2024 13:24	WEBB	Heating/Ventilation/Air Conditioning	Z1-034507	coil burst on a pipe in the unit vent
SCS HQ Admin BLDG	9/24/2024 7:33	WEBB	Heating/Ventilation/Air Conditioning	Z1-034344	contiburst on a pipe in the unit vent
303 FIQ Admini DEDO	3/24/2024 7.33	WEDD	rieating/ventitation/Air Conditioning	21-034344	Repair Liebert A/C Unit
SCS HQ Admin BLDG	8/1/2024 15:45	JOHNSON	Heating/Ventilation/Air Conditioning	Z1-024575	Tiopan Elobortive of Sinc
			0		Need 3 SH -10 locks
SCS HQ Admin BLDG	2/22/2024 9:30	SMITH	Key & Lock	Z1-002442	
					Need key for individual offices on the north side of this area
SCS HQ Admin BLDG	2/8/2024 10:44	SMITH	Key & Lock	Z1-000686	
					Need a key for the door
SCS HQ Admin BLDG	2/8/2024 10:43	SMITH	Key & Lock	Z1-000684	
COC 110 Admir- DI DO	0/0/000440:44	CMITI	Vou 0 11-	71 000000	Need keys made for desk key# ZG0038, ZG 0120 and ZG 0125
SCS HQ Admin BLDG	2/8/2024 10:41	SMITH	Key & Lock	Z1-000683	Contribute requesting for the gate to be renaized so that it may engrete and function
					Security is requesting for the gate to be repaired so that it may operate and function properly.
SCS HQ Admin BLDG	11/7/2024 8:58	STEPHENS	Sheet Metal	Z1-040049	proporty.
		3121112110	ondot i lotat	_1 0.0040	

					Test RP device as noted on letter. 11 ea.
SCS HQ BLDG #1	12/10/2024 10:18	OWENS	Plumbing	Z1-044248	
SCS HQ BLDG #1	11/15/2024 9:18	Jordan	Plumbing	Z1-041028	Gas leak Repair lighting on bldg 7 & 10
SCS HQ BLDG #7	12/9/2024 9:40	CHALK	Electrical	Z1-044004	nopuli agricing on bady 7 a 10
					ms. nelson
					64679
SCS HQ BLDG #7	12/9/2024 13:51	WEBB	Heating/Ventilation/Air Conditioning	Z1-044100	heat over heating
3C3 11Q DLDO #7	12/5/2024 15:51	WEDD	rieding/ventitation/Air Conditioning	21-044100	WAREHOUSE #7 - HEATING UNIT IN THE BACK AREA WHERE THE DEVICES AREAND FEED
					THE NEEDY - HEAT IS NOT COMING ON PM/NELSON 416-4679
SCS HQ BLDG #7	12/3/2024 10:21	WEBB	Heating/Ventilation/Air Conditioning	Z1-042852	
SCS HQ BLDG #7	3/5/2024 12:30	WEBB	Heating/Ventilation/Air Conditioning	Z1-004043	Replace window unit
00011Q 0200 117	0/0/2024 12:00		ricularly volume of the contraction in g	21 00 10 10	Repair exhaust hose
SCS HQ BLDG #7	10/22/2024 6:33	HATCH	Sheet Metal	Z1-037738	
000 110 01 00 117		OTEDUENO.		74 005004	dock 11 dock plate is stuck in the down position and needs repairing
SCS HQ BLDG #7 SCS Welcome Center (Drivers Ed)	3/18/2024 14:29 11/20/2024 9:43	STEPHENS SMITH	Welding Audio Visual	Z1-005264 Z2-041667	Need bulb for overhead projector,
SCS Welcome Center (Drivers Ed)	3/18/2024 11:53	POWELL	Electrical	Z2-041007 Z2-005202	Bad ballast
ood welcome denter (brivers Eu)	0/10/2024 11:00	TOWLLL	Licetical	22 000202	mR. WOODS 64840 HEAT NOT WORKING
SCS Welcome Center (Drivers Ed)	11/21/2024 10:33	HANSON	Heating/Ventilation/Air Conditioning	Z2-041910	The troops of th
					ceiling grid in classroom 233 need to be replaced, will not stay in place
Sea Isle Elementary	12/11/2024 14:13	WEBB	Carpentry	Z3-044504	de contrara in decembra 000 harban anada ha consider
Sea Isle Elementary	12/11/2024 13:15	WEBB	Carpentry	Z3-044485	door closer in classroom 232 broken need to be repaired
oca iste Eternemary	12/11/2024 10:10	WEDD	Guipentry	20 044400	Double doors next to classroom 202, no positive latch
Sea Isle Elementary	12/11/2024 13:13	WEBB	Carpentry	Z3-044484	
					panic bar in hallway next to classroom 216 stuck, end pieces missing
Sea Isle Elementary	12/11/2024 13:08	WEBB	Carpentry	Z3-044481	double doors cross from classroom 123 has no positive latch
Sea Isle Elementary	12/11/2024 13:05	WEBB	Carpentry	Z3-044479	double doors closs from classroom 123 has no positive tater
,					exterior light ballast needs to be replaced
Sea Isle Elementary	12/11/2024 8:47	SCOTT	Electrical	Z3-044431	
Sea Isle Elementary	11/6/2024 9:55	SCOTT	Electrical	Z3-039802	ballast in classroom 128 need to be replaced
Jea Isle Elementary	11/0/2024 5.55	30011	Electrical	23-033002	need ballasts replaced
Sea Isle Elementary	11/5/2024 12:54	SCOTT	Electrical	Z3-039621	
					need ballasts replaced
Sea Isle Elementary	11/5/2024 12:52	SCOTT	Electrical	Z3-039620	need 3 ballasts replaced
Sea Isle Elementary	11/5/2024 12:50	SCOTT	Electrical	Z3-039619	need 3 ballasts replaced
,					Bulbs blown need to be replaced
Sea Isle Elementary	11/1/2024 7:18	SCOTT	Electrical	Z3-039177	
Sea Isle Elementary	9/25/2024 13:46	SCOTT	Flectrical	Z3-034708	ballasts need to be replaced in classroom
Jea Isle Elementary	3/23/2024 13.40	30011	Electricat	23-034700	emergency light bulb or unit need to be replaced
Sea Isle Elementary	9/12/2024 14:19	SCOTT	Electrical	Z3-032325	
					emergency light bulb or unit needs to be replaced
Sea Isle Elementary	9/12/2024 14:17	SCOTT	Electrical	Z3-032322	emergency light bulb or unit need to be replaced
Sea Isle Elementary	9/12/2024 14:15	SCOTT	Electrical	Z3-032321	energency against and or unitriced to be repeated
•					Ballast needs to be replaced in hallway in front of room 223
Sea Isle Elementary	8/22/2024 11:28	SCOTT	Electrical	Z3-029126	
Sea Isle Elementary	8/13/2024 10:55	SCOTT	Electrical	Z3-027267	exit sign cross from classroom 236 bulbs or unit need to be replaced
oca iste Eternemary	0/10/2024 10:00	00011	Electricat	20 02/20/	exit sign next to classroom 210 bulbs or unit need to be replaced
Sea Isle Elementary	8/13/2024 10:54	SCOTT	Electrical	Z3-027265	
0.11.51	0.000.000.000.000			70.04006:	ballast need to be replaced
Sea Isle Elementary	6/25/2024 8:01	SCOTT	Electrical	Z3-019284	double blank plate broken need to be replaced
Sea Isle Elementary	6/12/2024 15:07	SCOTT	Electrical	Z3-018216	addition and a second record to be reputed
•					ballast need to be replaced.
Sea Isle Elementary	4/11/2024 9:42	WHITWORTH	Electrical	Z3-008774	

	44 = 1000 4 = 00		- ·	70.00000	key sometime works and sometimes not
Sea Isle Elementary	11/7/2024 7:30	SMALL	Elevators	Z3-039988	HEATING UNIT FOR THE 2ND FLR TCHR'S LOUNGE (RM 226) - NOT HEATING
Sea Isle Elementary	12/3/2024 10:31	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-042867	PM/SCURLOCK 416-2104 SCURLOCK 62104 NOT HEATING
Sea Isle Elementary	12/2/2024 10:31	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-042420	SCURLOCK 62104 NOT HEATING SCURLOCK 62104 NOT HEATING
Sea Isle Elementary	12/2/2024 10:16	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-042395	Ms. Scurlock 901-416-2104 AC unit leaking
Sea Isle Elementary	10/1/2024 8:24	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-035614	HVAC UNIT IN THE ASSIST PRIN OFC - NOT COOLING - PM/SCURLOCK 416-4104
Sea Isle Elementary	9/13/2024 12:30	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-032696	HVAC UNIT IN RM 205 - BLOWING NOT COOLING PM/SCURLOCK 416-2104
Sea Isle Elementary	8/21/2024 12:53	FIVEASH	Heating/Ventilation/Air Conditioning	Z3-028918	
Sea Isle Elementary	8/2/2024 11:50	SCOTT	Heating/Ventilation/Air Conditioning	Z3-024768	Plant Manager Scurlock reported the ac unit in room 213 is blowing warm air. 416-2104.
Sea Isle Elementary	11/19/2024 11:46	MALONE	Key & Lock	Z3-041513	requesting 4 short master keys, principal's request
Sea Isle Elementary	11/19/2024 11:44	MALONE	Key & Lock	Z3-041512	long master key, requesting 3 keys, per Principal
Sea Isle Elementary	11/19/2024 11:41	MALONE	Key & Lock	Z3-041510	Requesting 2 keys to the principal's office 48AA
Sea Isle Elementary	11/18/2024 8:07	MALONE	Key & Lock	Z3-041185	requesting 3 elevator keys
Sea Isle Elementary	11/18/2024 8:06	MALONE	Key & Lock	Z3-041184	got a broken master key that needs to be replaced
					door handle hanging,
Sea Isle Elementary	6/12/2024 15:04	SMITH	Key & Lock	Z3-018215	unable to use key in get into storage room cross from classroom 235
Sea Isle Elementary	3/5/2024 12:55	SMITH	Key & Lock	Z3-004051	damaged floor tile in restroom needs to be repaikred
Sea Isle Elementary	9/30/2024 15:31	BURCHETT	Masonry	Z3-035547	concrete pieces falling from underneath canopy, safety hazard
Sea Isle Elementary	8/20/2024 15:04	BURCHETT	Masonry	Z3-028757	
					requesting holes in wall tile be filled in thru-out building, 1st floor south end next to fuse box, next to water fountains, 2nd floor cross from cr 233, 223, 228, 213, 209
Sea Isle Elementary	8/19/2024 9:56	BURCHETT	Masonry	Z3-028355	holes in wall need to be filled
Sea Isle Elementary	6/18/2024 8:25	BURCHETT	Masonry	Z3-018680	repair cinderblock in custodial closet next to boy's restroom
Sea Isle Elementary	5/17/2024 12:50	BURCHETT	Masonry	Z3-015070	
					have several pieces of broken/cracked floor ceramic tile in kitchen that need to be replaced
Sea Isle Elementary	5/17/2024 10:45	BURCHETT	Masonry	Z3-015019	the handrail to the steps in the boiler room is damaged missing concrete at the base, needs
Sea Isle Elementary	5/17/2024 10:32	BURCHETT	Masonry	Z3-015014	to be repaired
Sea Isle Elementary	4/3/2024 14:15	CORONADO	Masonry	Z3-007639	Have cracked/stressed walls in building that need to be looked at
Sea Isle Elementary	3/26/2024 10:44	CORONADO	Masonry	Z3-006373	step corner broken need to be filled in
Sea Isle Elementary	9/9/2024 8:23	BURCHETT	Painting	Z3-031447	requesting classroom 228 be painted
Sea Isle Elementary	6/18/2024 8:21	BURCHETT	Painting	Z3-018679	classroom 245 need to be painted
Sea Isle Elementary	5/20/2024 14:46	BURCHETT	Painting	Z3-015290	need parking slots blacked out
Sea Isle Elementary	5/17/2024 12:12	BURCHETT	Painting	Z3-015060	recommended by Risk Management, be repaired and painted

water n	r running from pipe fixture underneath sink in boy's restroom next to classroom 209
Sea Isle Elementary 12/12/2024 9:42 PEARSON Plumbing Z3-044637	
dea die Etelliellerig 12/12/2014 Endoth Fallionia Co 044007	
yesterda	ghts outside the cafeteria did not appear to be working. Director states at 5:45pm rday the lights were not on and the parking lot was completely dark. Could we please have someone come out to service the lights as it may become a safety hazard?
Shady Grove Elementary 11/21/2024 10:05 STAFFORD Electrical Z2-041903	
Shady Grove Elementary 11/15/2024 11:05 Coleman Electrical Z2-041074	Number label & E Lock-FA needed on breaker box per Fire Safety inspector.
Shady Grove Elementary 10/17/2024 9:38 Coleman Fire Alarm System Z2-037339	Repair Strobes on the main hallway near main office .
Shady Grove Elementary 10/17/2024 9:34 Coleman Fire Alarm System Z2-037336	Repair Strobes on the right side of the Cafeteria and the main Hallway.
Siliaty Grove Eternetical 10/17/2024 9:34 Coleman File Alanin System 22-037330	Rooms are in need of emergency exit stickers for walls/windows- Qty 4
Shady Grove Elementary 10/1/2024 10:43 Coleman Fire Extinguishers Z2-035703	NOUTIS are in need of entergency exit suckers for walls/willdows- Qty 4
	Need 24 wall stickers for area above extinguishers.
Shady Grove Elementary 10/1/2024 10:40 Coleman Fire Extinguishers Z2-035699	
Low/Me	Medium/High switch is not working. Unit continuously blows on high causing it to be extremely hot in the room.
Shady Grove Elementary 12/12/2024 8:55 STRICKLAND Heating/Ventilation/Air Conditioning Z2-044576	
Low/Me	Medium/High switch is not working. Unit continuously blows on high causing it to be extremely hot in the room.
Shady Grove Elementary 12/12/2024 8:10 STRICKLAND Heating/Ventilation/Air Conditioning Z2-044543	
Building	ng has been switched to heat but unit in room 15 is still blowing cold air. Attempted to change setting from low to high and unit only blows cool air.
Shady Grove Elementary 12/2/2024 7:44 STRICKLAND Heating/Ventilation/Air Conditioning Z2-042234	
Br	Broken tile in boy pre-K restroom near sink area. Tile will need to be replaced.
Shady Grove Elementary 8/21/2024 10:15 CORONADO Masonry Z2-028870	
Shady Grove Elementary 7/12/2024 9:47 BURCHETT Painting Z2-021010	Discoloration on outside trimming.
Shady Grove Elementary 5/21/2024 10:21 BURCHETT Painting Z2-015436 Outside	de brick wall and walk way spray painted with graffiti. Needs to be pressure washed. test backflow
Shady Grove Elementary 10/15/2024 8:01 PILKINGTON Plumbing Z2-036978	
Shady Grove Elementary 5/17/2024 14:32 BENTON Shades/Blinds WO1015788 Requ	questing shades to be installed in the following Pre-K classrooms 4,5,6,8,9,10,11.
Sharpe Elementary 12/13/2024 8:18 FORD Carpentry Z4-044833	Window handle broken need to be fixed.
Sharpe Elementary 12/9/2024 10:30 FORD Carpentry Z4-044035	Window broke out of exterior door leading into courtyard
	net base need to be replaced due to water damage causing to buckle and fall apart.
Sharpe Elementary 2/19/2024 19:44 FORD Carpentry Z4-001974	
Sharpe Elementary 12/12/2024 9:41 HALL Electrical Z4-044633	Two orange outlets needs replaced
Sharpe Elementary 11/19/2024 10:48 HALL Electrical Z4-041495	Ventahood is not coming on
Sharpe Elementary 4/8/2024 8:28 HALL Electrical Z4-008073	Light fixture not working.need working due to break in.
	Change over valve needs to be replaced
Sharpe Elementary 12/9/2024 11:38 MADUNATUM Heating/Ventilation/Air Conditioning Z4-044056	
Sharpe Elementary 10/17/2024 7:25 MADUNATUM Heating/Ventilation/Air Conditioning Z4-037293	A/c unit pipe leaking.
Sharpe Elementary 7/29/2024 11:28 SMITH Key & Lock Z4-023316	Lock need to be charged.
Sharpe Elementary 9/4/2024 8:42 BURCHETT Masonry Z4-030809	Tiles need to be replaced.
Sharpe Elementary 10/18/2024 7:46 BURCHETT Painting Z4-037431	Requesting parking lot to be re stripped.
Sharpe Elementary 6/27/2024 7:48 BURCHETT Painting Z4-019583	Requesting hallway to be painted
Sharpe Elementary 6/27/2024 7:45 BURCHETT Painting Z4-019581	Need to be painted
Sharpe Elementary 6/27/2024 7:43 BURCHETT Painting Z4-019580	Need to be painted.
Sharpe Elementary 6/27/2024 7:41 BURCHETT Painting Z4-019578	Office counter to be painted.
Sharpe Elementary 12/12/2024 13:59 JOHNSON Plumbing Z4-044761	Toilet will not stop running
Sharpe Elementary 12/11/2024 7:25 JOHNSON Plumbing Z4-044405	Water fountain can not be turned off continuously runs
Sharpe Elementary 12/9/2024 10:28 JOHNSON Plumbing Z4-044033	Faucet needs washer can't turn water off
Sharpe Elementary 12/9/2024 10:27 JOHNSON Plumbing Z4-044032	Urinal not working
Sharpe Elementary 10/14/2024 14:09 JOHNSON Plumbing Z4-036906	Sink p-trap broken leaking need to be replaced.
Sharpe Elementary 10/14/2024 14:06 JOHNSON Plumbing Z4-036903	Sink faucet handle stripped can not turn water off.
Sharpe Elementary 9/23/2024 7:36 JOHNSON Plumbing Z4-034096	Water fountain is not working.
Sharpe Elementary 9/17/2024 10:39 JOHNSON Plumbing Z4-033171	Ice machine drain stoped up need repairs.

Water drainage system is full of dirt and debris that's causing flooding on the sidewalk, which hinders students' transits to and from school during heavy rains. Request to have drainage area cleaned and unclogged. Urgent!!!

					drainage area cleaned and unclogged. Urgent!!!
Sharpe Elementary	8/20/2024 11:29	JOHNSON	Plumbing	Z4-028657	
Sharpe Elementary	7/29/2024 8:45	TEDDER	Plumbing	Z4-023171	Water leaking from a/c unit
Sharpe Elementary	6/28/2024 10:55	JOHNSON	Plumbing	Z4-019768	Water fountain is not working #11
Sharpe Elementary	6/28/2024 10:42	JOHNSON	Plumbing	Z4-019761	Water fountain not working #1
Sheffield Career & Technology Center	12/10/2024 9:18	WEBB	Carpentry	Z3-044196	oom 112 is requesting that two cabinets be mounted on the wall in the back (for supplies need)
Sheffield Career & Technology Center	9/19/2024 10:59	HATCH	Carpentry	Z3-033731	Door frames are cracking breaking
					EXTERIOR DOORS RM 112 & RM 124 - CAN'T SECURE - REP/REPL HARDWARE PM/HILLIARD
					416-2340
Sheffield Career & Technology Center	8/29/2024 7:09	WEBB	Carpentry	Z3-030145	
Sheffield Career & Technology Center	12/9/2024 6:48	SCOTT	Electrical	Z3-043924	Bad ballast in both stairway
Sheffield Career & Technology Center	12/9/2024 6:47	SCOTT	Electrical	Z3-043923	Bad ballast in room 204
Sheffield Career & Technology Center	12/9/2024 6:46	SCOTT	Electrical	Z3-043922	Bad ballast in room 202
Sheffield Career & Technology Center	12/9/2024 6:45	SCOTT	Electrical	Z3-043921	Bad ballast in room 203
Sheffield Career & Technology Center	11/21/2024 8:52	SCOTT	Electrical	Z3-041863	In the computer lab in room 124 the power pole is not working properly
Sheffield Career & Technology Center	11/21/2024 8:50	SCOTT	Electrical	Z3-041861	Computer lab 124 is requesting two power pole
Sheffield Career & Technology Center	10/22/2024 17:28	SCOTT	Electrical	Z3-037901	In room 117 explores wire is coming out the ceiling
.,					Explores light wires in room 202
Sheffield Career & Technology Center	10/21/2024 9:45	SCOTT	Electrical	Z3-037635	
Sheffield Career & Technology Center	10/21/2024 9:42	SCOTT	Electrical	Z3-037633	Outside lights on all side of the building are not working .Light is sparking
Sheffield Career & Technology Center	9/19/2024 10:56	WHITWORTH	Electrical	Z3-033727	Wire hanging and exposed
Sheffield Career & Technology Center	7/18/2024 16:51	SCOTT	Electrical	Z3-021737	Need a socket installed on the wall in the lobby area for the new scanners
chomota carcor a recimetogy conter	77107202-4 10:01	00011	Elootiioat	20 021707	Replace missing cover in Yellow Room
Sheffield Career & Technology Center	6/24/2024 12:07	SCOTT	Electrical	Z3-019205	
Sheffield Career & Technology Center	8/2/2024 15:10	SMALL	Elevators	Z3-024887	Elevator doors will not open when button is pressed
chomota carcor a recimetogy conter	0/2/2024 10:10	0111122	Elevatore	20 02 1007	Ms. Griffin 62340 no heat energy management can't read
Sheffield Career & Technology Center	12/4/2024 8:54	BRYSON	Heating/Ventilation/Air Conditioning	Z3-043178	13. Online accept no near chargy management can thead
onemed ourcer a recimology ochier	12/4/2024 0.04	Bittooit	ricuting ventuation//ai contationing	20 040170	Ms. Griffin 62340 no heat energy management can't read
Sheffield Career & Technology Center	12/4/2024 8:54	BRYSON	Heating/Ventilation/Air Conditioning	Z3-043175	. In Common of the Control of the Co
onemed ourcer a recimology ochier	12/4/2024 0.04	Bittooit	ricuting ventuation//ai contationing	20 040170	Ms. Griffin 62340 no heat energy management can't read
Sheffield Career & Technology Center	12/4/2024 8:53	BRYSON	Heating/Ventilation/Air Conditioning	Z3-043173	ris. Online 02040 ito iteat energy management can creat
Shellieta Gareer & reciliology Genter	12/4/2024 0.55	DIVISON	rieating ventilation/Air Conditioning	25-045175	Ms. Griffin 62340 room not heating up. energy mgmt show no code
Sheffield Career & Technology Center	11/21/2024 9:11	BRYSON	Heating/Ventilation/Air Conditioning	Z3-041873	PIS. Offilm 02340 footh for fleating up. energy fight show no code
Sheffield Career & Technology Center	11/6/2024 7:01	MALONE	Key & Lock	Z3-041673 Z3-039675	Building Engineer need keys to the clinic
	11/6/2024 7:01	MALONE		Z3-039673	
Sheffield Career & Technology Center Sheffield Career & Technology Center	10/23/2024 12:11	MALONE	Key & Lock Key & Lock	Z3-039673 Z3-038016	Building Engineer need keys to the east hallway door Need key for the clinic area
•			,		
Sheffield Career & Technology Center	10/23/2024 12:11	MALONE	Key & Lock	Z3-038015	Need light switch keys to turn on the lights
Ob -46 -14 O 0 Tb1- 4 O4-	4/05/000444-45	DUDTON	Manager	70.044500	wall in shop has hole around socket need filling with concrete.
Sheffield Career & Technology Center	4/25/2024 11:15	BURTON	Masonry	Z3-011506	
Sheffield Career & Technology Center	11/7/2024 10:04	BURCHETT	Painting	Z3-040090	Clinic needs to be painted due to chip paint
Sheffield Career & Technology Center	9/19/2024 10:48	BURCHETT	Painting	Z3-033718	on board for the packing department and is on taking the rooms upstairs and is requesting that all three rooms be repainted due to peeling paint
Sheffield Career & Technology Center	12/9/2024 8:11	TOLES	Plumbing	Z3-043948	Water fountain leaking from the bottom in the clinic area .
Sheffield Career & Technology Center	10/22/2024 17:23	TOLES	Plumbing	Z3-037900	In the Culinary room 151 water is backing up in the sinks
					Request for superintendent, warehouse supply chain program Be back up to for students to
0. 77	0/00/000444 50	0.40450		70.001010	use
Sheffield Career & Technology Center	9/20/2024 11:52	BARNES	Plumbing	Z3-034013	
Sheffield Career & Technology Center	12/9/2024 8:11	BARNES	Roofing	Z3-043949	Roof is leaking in the clinic area
Sheffield Elementary	12/5/2024 13:28	WEBB	Carpentry	Z3-043652	Door closure is broken
Sheffield Elementary	12/5/2024 12:16	WEBB	Carpentry	Z3-043612	Boys restroom by library door closure is broken
Sheffield Elementary	12/5/2024 12:14	WEBB	Carpentry	Z3-043611	Girls restroom by the library door closure is broken
Sheffield Elementary	7/10/2024 11:11	BENTON	Carpet Repair	Z3-020748	Principal is requesting for the carpet to be removed from the library
Sheffield Elementary	7/10/2024 11:10	BENTON	Carpet Repair	Z3-020747	Principal is asking for the carpet to be removed from the classroom upstairs
					hallway light by conference room light needs a new ballast
Sheffield Elementary	12/10/2024 9:00	SCOTT	Electrical	Z3-044187	
					Second floor 2 floor need light covers (its a glare through out the classroom kids can't see
					board)
Sheffield Elementary	12/5/2024 11:45	SCOTT	Electrical	Z3-043590	
Sheffield Elementary	11/6/2024 10:41	SCOTT	Electrical	Z3-039840	Main office needs a new ballast for lights
Sheffield Elementary	11/6/2024 10:40	SCOTT	Electrical	Z3-039839	First Grade hall near plant managers office needs a new ballast for the first light
Sheffield Elementary	10/29/2024 8:17	SCOTT	Electrical	Z3-038639	Sheffield Elementary needs two cases of H20 lights
					needs two new ballasts
Sheffield Elementary	8/14/2024 8:03	SCOTT	Electrical	Z3-027395	

Sheffield Elementary	7/23/2024 14:24	SCOTT	Electrical	Z3-022182	Needs two new ballasts
Sheffield Elementary	6/20/2024 8:02	SCOTT	Electrical	Z3-018850	Put new lightbulbs in, but the lights are still not coming on
Sheffield Elementary	6/18/2024 7:40	SCOTT	Electrical	Z3-018654	Ballast out
Sheffield Elementary	6/18/2024 7:39	SCOTT	Electrical	Z3-018653	Ballast out
Sheffield Elementary	6/17/2024 20:52	SCOTT	Electrical	Z3-018630	Light lenses need throughout the school
	6/17/2024 20:32		Electrical		
Sheffield Elementary		SCOTT		Z3-018629	The light are out
Sheffield Elementary	5/3/2024 10:01	SMITH	Electrical	Z3-012968	A phone will not open doors
0	40/40/00040 50		F. W. O.	70.044404	class room 3 fire alarm is reading INV REP witch causes the panel to go off.
Sheffield Elementary	12/10/2024 8:50		Fire Alarm System	Z3-044181	
					POCA fire alarm is reading error smoke in boilers room. The door are not remaining open
					due to the magnets, not working because the system is in trouble mode
Sheffield Elementary	5/6/2024 9:42	SMALL	Fire Alarm System	Z3-013131	
Sheffield Elementary	5/17/2024 14:05	CHASE	Flooring	WO996329	Need 25year old carpet remove. Safety hazard. Can go around partial panels. Principal request
					HVAC UNIT ON THE PREK HALL - RM 101 - BLOWING COLD AIR SHOWING 63 DEGREES
					PM/ALEXANDER 416-2360
Sheffield Elementary	12/4/2024 7:52	BRYSON	Heating/Ventilation/Air Conditioning	Z3-043116	
					Hvac
Sheffield Elementary	10/28/2024 15:32	BRYSON	Heating/Ventilation/Air Conditioning	Z3-038595	
Sheffield Elementary	9/18/2024 13:48	BARNES	Heating/Ventilation/Air Conditioning	Z3-033496	et sink is stopped up and stuff is coming from the pipe inside of the sink and it's not nature, nature Sanitary.
Sheffield Elementary	8/16/2024 11:27	SMITH	Key & Lock	Z3-028118	The financial secretary office needs two keys copied for plant manager, and principal
Sheffield Elementary	8/16/2024 11:22	SMITH	Key & Lock	Z3-028116	Records room needs 2 keys made
Sheffield Elementary	6/27/2024 10:10	SMITH	Key & Lock	Z3-019630	Door safety hazard
	11/22/2024 11:40	BURCHETT		Z3-013030	Broken brick wall
Sheffield Elementary			Masonry		
Sheffield Elementary	9/27/2024 14:59	BURCHETT	Masonry	Z3-035235	Bonjour room has missing pieces on the floor
Sheffield Elementary	9/27/2024 14:38	BURCHETT	Masonry	Z3-035219	Girls restroom missing floor pieces
Sheffield Elementary	9/6/2024 14:55	CORONADO	Masonry	Z3-031378	Floor tile is missing
Sheffield Elementary	6/18/20247:43	BURCHETT	Masonry	Z3-018659	Floor is missing tile. Also buckling up around drain.
Sheffield Elementary	6/17/2024 20:47	BURCHETT	Masonry	Z3-018628	Crack in the cement
Sheffield Elementary	12/5/2024 12:38	BURCHETT	Painting	Z3-043627	Sink by SPE and building engineer room needs painting
Sheffield Elementary	12/5/2024 12:13	BURCHETT	Painting	Z3-043610	Sink needs to be painted
Sheffield Elementary	11/22/2024 11:12	BURCHETT	Painting	Z3-042065	Paint is peeling from the wall by behind the toilets
Sheffield Elementary	9/4/2024 11:29	BURCHETT	Painting	Z3-030901	Room 103 has chip paint on walls
Sheffield Elementary	7/18/2024 11:14	BURCHETT	Painting	Z3-021674	Principal is requesting that boys /girls restroom be painted
Sheffield Elementary	7/18/2024 11:12	BURCHETT	Painting	Z3-021673	Principal is requesting a parking spot that has principal on it
Sheffield Elementary	3/22/2024 6:59	BURCHETT	Painting	Z3-021073 Z3-005834	Need restroom repainted
Sheffield Elementary	5/17/2024 14:24	BURCHETT	Painting	WO1006985	The stainwell by the principal office wall need fresh paint
Silemeta Etementary	3/1//2024 14.24	BUNCHETT	Failtuilg	WO1000963	POCA TELESCOPIC SEATING
Sheffield High	6/4/2024 8:38	SMALL	Bleachers and Seats	Z3-017064	POGA TELESCOPIC SEATING
•					La casa south transition and a
Sheffield High	10/14/2024 12:11	WEBB	Carpentry	Z3-036867	Loose push handle main entry
Sheffield High	8/8/2024 14:19	WEBB	Carpentry	Z3-026487	Hang banner next to 2022
					requesting for (2) banners to be put up in gym over the bleachers.
Sheffield High	2/12/2024 10:27	BARNES	Carpentry	Z3-000987	
Sheffield High	11/21/2024 6:31	SCOTT	Electrical	Z3-041813	Outside the gym and parking lot does not have lights to see
Sheffield High	11/19/2024 8:44	SCOTT	Electrical	Z3-041417	Need the clocks updated
Sheffield High	10/30/2024 10:21	SCOTT	Electrical	Z3-038884	Exterior outside lights installed around facility
Sheffield High	10/30/2024 10:20	SCOTT	Electrical	Z3-038883	East stairway install light
Sheffield High	10/22/2024 7:59	SCOTT	Electrical	Z3-037761	Room 215 outlet by the front door is not operating. I reset the breaker still no power.
Sheffield High	10/22/2024 7:55	SCOTT	Electrical	Z3-037758	Replace balance outside of 215 in hallway
Sheffield High	10/22/2024 7:18	SCOTT	Electrical	Z3-037747	207 I change lights but balance need replace
Sheffield High	10/17/2024 12:27	SCOTT	Electrical	Z3-037391	Room 317 outside of it in the hallway, third-floor check balance
Sheffield High	10/17/2024 12:15	SCOTT	Electrical	Z3-037386	Life blanking outside of, 303
Sheffield High	10/16/2024 9:27	SCOTT	Electrical	Z3-037182	201 Repair wiring for power pool
Shemeta riigii	10/10/2024 3.2/	30011	Liectricat	25-05/102	309 sockets none working by teachers desk
Sheffield High	10/15/20247:29	SCOTT	Electrical	Z3-036959	Previously space heater was plugged in
•					, , , , , , , , , , , , , , , , , , , ,
Sheffield High	10/9/2024 11:08	SCOTT	Electrical	Z3-036724	Room 304 balance replaced
Sheffield High	10/9/2024 10:51	SCOTT	Electrical	Z3-036717	317 I changed bulb balance replaced
					113 light balance replace
Sheffield High	10/9/2024 9:48	SCOTT	Electrical	Z3-036705	I replaced bulb today
Sheffield High	8/7/2024 10:08	SCOTT	Electrical	Z3-026003	Some lights I install others need balance
					Teacher request surge to be removed
Sheffield High	8/2/2024 8:20	SCOTT	Electrical	Z3-024641	Due to his panic of safety hazard
Sheffield High	7/30/2024 15:18	SCOTT	Electrical	Z3-023862	School bell need setting
Sheffield High	6/25/2024 8:25	SCOTT	Electrical	Z3-019290	Main cafeteria and kitchen lights replace
ű.					• •

Sheffield High	6/17/2024 7:49	SCOTT	Electrical	Z3-018466	Replace lights POCA exposed wire in room 101m
Sheffield High	6/4/2024 8:20	SCOTT	Electrical	Z3-017055	library needs (20) bulbs replace.
Sheffield High	5/24/2024 14:52	SCOTT	Electrical	Z3-016020	uurary neeus (20) uuus reprace.
Sheffield High	5/24/2024 14:38	SCOTT	Electrical	Z3-016018	in ROTC the range room need 45 lens replaced from water stain and water leaks.
Sheffield High	5/21/2024 9:38	SCOTT	Electrical	Z3-015402	need ballast replace in main lobby to the left of wall over counter
					1st floor hallway across from c/r 110 ballast need to be replaced.
Sheffield High	5/21/2024 7:52	SCOTT	Electrical	Z3-015329	serving line needs ballast replaced
Sheffield High	4/19/2024 8:21	SCOTT	Electrical	Z3-010638	cafeteria seating area back light wont come on.
Sheffield High	4/18/2024 12:23	SCOTT	Electrical	Z3-010399	custom seeming and seem up. it work come on
					It is stuck open on the first floor will not close. I attempted to reset it. It is still not closing.
Sheffield High	12/2/2024 12:38	SMALL	Elevators	Z3-042538	Elevator stuck on first floor
Sheffield High	11/12/2024 13:17	SMALL	Elevators	Z3-040486	
Sheffield High	12/2/2024 14:58		Fire Alarm System	Z3-042615	Continues to set off, saying shit down Trouble heat fix basement boiler room INVREP
Sheffield High	10/21/2024 7:15	SMALL	Fire Alarm System	Z3-037560	House hear in discinct botter four invites
					POCA inspections and test of fire protection systems
Sheffield High	6/4/2024 8:42		Fire Alarm System	Z3-017066	
Sheffield High	2/15/2024 8:37	SMALL	Fire Extinguishers	Z3-001513	need (2) fire extinguishers in gym.
					fire extinguisher need in Auditorium next to the Boys Dressing and Restroom 221A.
Sheffield High	2/15/2024 8:28	SMALL	Fire Extinguishers	Z3-001506	
Sheffield High	11/15/2024 12:08	CASEY	Flooring	Z3-041092	Requesting for the gym floor to be sanded and re-finish for the first home game on December 3
Sheffield High	9/17/2024 11:01	SIMS	Heating/Ventilation/Air Conditioning	Z3-033187	209 Unit loud noise I turned off
Sheffield High	9/16/2024 9:04	SIMS	Heating/Ventilation/Air Conditioning	Z3-032846	205 HVAC leak
Sheffield High	8/16/2024 13:09	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-028151	Room 117
Sheffield High	8/13/2024 9:07	SIMS	Heating/Ventilation/Air Conditioning	Z3-027215	Unit leaking
_					c/r 103 is not cooling
Sheffield High	4/18/2024 10:50	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-010314	ROTC is not coming on
Sheffield High	4/18/2024 10:29	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-010271	and A to and a series and
Sheffield High	4/18/2024 10:27	WHITWORTH	Heating/Ventilation/Air Conditioning		gym A is not coming on
Sheffield High				Z3-010269	
	4/10/2024 7:41	WHITWORTH			need 5 thermostats replaced students torn them off walls.
Sheffield High	4/10/2024 7:41 10/22/2024 14:23	WHITWORTH MALONE	Heating/Ventilation/Air Conditioning Key & Lock	Z3-010269 Z3-008496 Z3-037892	need 5 thermostats replaced students torn them off walls. 107 door want lock Band room
Sпетівіа нідп			Heating/Ventilation/Air Conditioning	Z3-008496	107 door want lock Band room
Sheffield High			Heating/Ventilation/Air Conditioning	Z3-008496	107 door want lock Band room 3rd floor boy's restroom across from c/r 311 missing (1) wall tile on left side of wall.
Ū	10/22/2024 14:23	MALONE	Heating/Ventilation/Air Conditioning Key & Lock	Z3-008496 Z3-037892	107 door want lock Band room 3rd floor boy's restroom across from c/r 311 missing (1) wall tile on left side of wall. c/r 202 hole along bottom of window frame needs filling
Sheffield High	10/22/2024 14:23 5/17/2024 13:24 4/10/2024 8:13	MALONE BURCHETT CORONADO	Heating/Ventilation/Air Conditioning Key & Lock Masonry Masonry	Z3-008496 Z3-037892 Z3-015072 Z3-008520	107 door want lock Band room 3rd floor boy's restroom across from c/r 311 missing (1) wall tile on left side of wall.
Sheffield High Sheffield High	10/22/2024 14:23 5/17/2024 13:24 4/10/2024 8:13 4/10/2024 7:49	BURCHETT CORONADO CORONADO	Heating/Ventilation/Air Conditioning Key & Lock Masonry Masonry Masonry	Z3-008496 Z3-037892 Z3-015072 Z3-008520 Z3-008503	107 door want lock Band room 3rd floor boy's restroom across from c/r 311 missing (1) wall tile on left side of wall. c/r 202 hole along bottom of window frame needs filling c/r 311 large gap at bottom of (2) windows frames need cement.
Sheffield High Sheffield High Sheffield High Sheffield High	10/22/2024 14:23 5/17/2024 13:24 4/10/2024 8:13 4/10/2024 7:49 5/17/2024 13:42	BURCHETT CORONADO CORONADO CORONADO	Heating/Ventilation/Air Conditioning Key & Lock Masonry Masonry Masonry Masonry Masonry	Z3-008496 Z3-037892 Z3-015072 Z3-008520 Z3-008503 WO980408	107 door want lock Band room 3rd floor boy's restroom across from c/r 311 missing (1) wall tile on left side of wall. c/r 202 hole along bottom of window frame needs filling c/r 311 large gap at bottom of (2) windows frames need cement. got several cracks in concrete in the floor that need to be filled in room 105, weight room
Sheffield High Sheffield High Sheffield High Sheffield High Sheffield High	10/22/2024 14:23 5/17/2024 13:24 4/10/2024 8:13 4/10/2024 7:49 5/17/2024 13:42 10/17/2024 7:53	BURCHETT CORONADO CORONADO CORONADO BURCHETT	Heating/Ventilation/Air Conditioning Key & Lock Masonry Masonry Masonry Masonry Masonry Painting	Z3-008496 Z3-037892 Z3-015072 Z3-008520 Z3-008503 WO980408 Z3-037302	107 door want lock Band room 3rd floor boy's restroom across from c/r 311 missing (1) wall tile on left side of wall. c/r 202 hole along bottom of window frame needs filling. c/r 311 large gap at bottom of (2) windows frames need cement. got several cracks in concrete in the floor that need to be filled in room 105, weight room 3rd Floor hallway and 315 Art class
Sheffield High Sheffield High Sheffield High Sheffield High Sheffield High Sheffield High	10/22/2024 14:23 5/17/2024 13:24 4/10/2024 7:49 5/17/2024 13:42 10/17/2024 7:53 6/17/2024 7:48	BURCHETT CORONADO CORONADO CORONADO BURCHETT BURCHETT	Heating/Ventilation/Air Conditioning Key & Lock Masonry Masonry Masonry Masonry Painting Painting	Z3-008496 Z3-037892 Z3-015072 Z3-008520 Z3-008503 WO980408 Z3-037302 Z3-018465	107 door want lock Band room 3rd floor boy's restroom across from c/r 311 missing (1) wall tile on left side of wall. c/r 202 hole along bottom of window frame needs filling c/r 311 large gap at bottom of (2) windows frames need cement. got several cracks in concrete in the floor that need to be filled in room 105, weight room 3rd Floor hallway and 315 Art class Paint door inside of the girls restroom
Sheffield High Sheffield High Sheffield High Sheffield High Sheffield High Sheffield High	10/22/2024 14:23 5/17/2024 13:24 4/10/2024 7:49 5/17/2024 13:42 10/17/2024 7:48 6/17/2024 7:48	BURCHETT CORONADO CORONADO CORONADO BURCHETT BURCHETT BURCHETT	Heating/Ventilation/Air Conditioning Key & Lock Masonry Masonry Masonry Masonry Painting Painting Painting	Z3-008496 Z3-037892 Z3-015072 Z3-008520 Z3-008503 WO980408 Z3-037302 Z3-018465 Z3-018464	107 door want lock Band room 3rd floor boy's restroom across from c/r 311 missing (1) wall tile on left side of wall. c/r 202 hole along bottom of window frame needs filling c/r 311 large gap at bottom of (2) windows frames need cement. got several cracks in concrete in the floor that need to be filled in room 105, weight room 3rd Floor hallway and 315 Art class Paint door inside of the girls restroom Ceiling need painting
Sheffield High Sheffield High Sheffield High Sheffield High Sheffield High Sheffield High	10/22/2024 14:23 5/17/2024 13:24 4/10/2024 7:49 5/17/2024 13:42 10/17/2024 7:53 6/17/2024 7:48	BURCHETT CORONADO CORONADO CORONADO BURCHETT BURCHETT	Heating/Ventilation/Air Conditioning Key & Lock Masonry Masonry Masonry Masonry Painting Painting	Z3-008496 Z3-037892 Z3-015072 Z3-008520 Z3-008503 WO980408 Z3-037302 Z3-018465	107 door want lock Band room 3rd floor boy's restroom across from c/r 311 missing (1) wall tile on left side of wall. c/r 202 hole along bottom of window frame needs filling c/r 311 large gap at bottom of (2) windows frames need cement. got several cracks in concrete in the floor that need to be filled in room 105, weight room 3rd Floor hallway and 315 Art class Paint door inside of the girls restroom
Sheffield High Sheffield High Sheffield High Sheffield High Sheffield High Sheffield High	10/22/2024 14:23 5/17/2024 13:24 4/10/2024 7:49 5/17/2024 13:42 10/17/2024 7:48 6/17/2024 7:48	BURCHETT CORONADO CORONADO CORONADO BURCHETT BURCHETT BURCHETT	Heating/Ventilation/Air Conditioning Key & Lock Masonry Masonry Masonry Masonry Painting Painting Painting	Z3-008496 Z3-037892 Z3-015072 Z3-008520 Z3-008503 WO980408 Z3-037302 Z3-018465 Z3-018464	107 door want lock Band room 3rd floor boy's restroom across from c/r 311 missing (1) wall tile on left side of wall. c/r 202 hole along bottom of window frame needs filling c/r 311 large gap at bottom of (2) windows frames need cement. got several cracks in concrete in the floor that need to be filled in room 105, weight room 3rd Floor hallway and 315 Art class Paint door inside of the girls restroom Ceiling need painting Ceiling need painting
Sheffield High	10/22/2024 14:23 5/17/2024 13:24 4/10/2024 8:13 4/10/2024 7:49 5/17/2024 7:53 6/17/2024 7:48 6/17/2024 7:48 6/17/2024 7:45	BURCHETT CORONADO CORONADO CORONADO BURCHETT BURCHETT BURCHETT BURCHETT	Heating/Ventilation/Air Conditioning Key & Lock Masonry Masonry Masonry Masonry Painting Painting Painting Painting	Z3-008496 Z3-037892 Z3-015072 Z3-008520 Z3-008503 WO980408 Z3-037302 Z3-018465 Z3-018464 Z3-018462	107 door want lock Band room 3rd floor boy's restroom across from c/r 311 missing (1) wall tile on left side of wall. c/r 202 hole along bottom of window frame needs filling c/r 311 large gap at bottom of (2) windows frames need cement. got several cracks in concrete in the floor that need to be filled in room 105, weight room 3rd Floor hallway and 315 Art class Paint door inside of the girls restroom Celling need painting Ceiling need painting

Choffiold High	E /1E /2024 11:2E	BUDGUETT	Dointing	70.014005	Girls Restroom on 3rd floor 2nd stall door needs painting has a new wooden door installed.
Sheffield High	5/15/2024 11:25	BURCHETT	Painting	Z3-014685	
					south stairwell on 3rd floor ceiling needs scraping and painting, peeling around light fixture.
Sheffield High	4/29/2024 13:06	BURCHETT	Painting	Z3-012047	
					library east entrance paint is peeling inside doorway.
Sheffield High	4/26/2024 7:54	BURCHETT	Painting	Z3-011649	
					requesting for the Varsity Dressing Room ceiling be scrap, mud and painted. Ceiling in
0. (7. 111)	0/00/000444.05	2112211577		70.00===.	rough condition
Sheffield High	3/20/2024 11:25	BURCHETT	Painting	Z3-005554	on 3rd floor in Boy's Restroom Ceiling is Peeling needs scraping and repainting.
Sheffield High	2/27/2024 7:36	BURCHETT	Painting	Z3-002955	on signoon in boy's nestroom Cennig is reening needs scraping and repainting.
Sheffield High	11/21/2024 9:31	BARNES	Plumbing	Z3-041886	The pipe has come unattached
Sheffield High	11/19/2024 11:01	TOLES	Plumbing	Z3-041501	Drain under sink by cafeteria manager office is not draining properly it's holding water
• • • • •			3		Boys locker room urinals flusher water flush low
Sheffield High	10/31/2024 14:44	BARNES	Plumbing	Z3-039148	
Shelby Oaks Elementary	11/12/2024 11:14	POWELL	Electrical	Z2-040458	Kitchen Hood not working
Shelby Oaks Elementary	11/12/2024 11:13	POWELL	Electrical	Z2-040456	Ballast out in entire light fixture
Shelby Oaks Elementary	10/7/2024 13:34	POWELL	Electrical	Z2-036501	3 Dome lights out. Requires Lift
Shelby Oaks Elementary	10/7/2024 13:33	POWELL	Electrical	Z2-036499	4 Dome lights out. Requires lift
					Alarm Reading Trouble: Control Module Address 30 Z00 Open Circuit. System Ground Fault.
Shelby Oaks Elementary	11/22/2024 16:54	Coleman	Fire Alarm System	Z2-042130	Tamper Piv Z23 Invalid Reply
Siletby Oaks Eternentary	11/22/2024 10:54	Coteman	The Alaim System	22-042130	Requesting Smoke Detector D-02 gets repaired to report to device
Shelby Oaks Elementary	10/21/2024 9:30	Coleman	Fire Alarm System	Z2-037622	noquesting official potential of the particle at report to define
Shelby Oaks Elementary	6/4/2024 8:19	Coleman	Fire Alarm System	Z2-017054	Alarm sounding and reading multiple troubles
,			,		Replace Missing Escutcheon in Cafeteria
Shelby Oaks Elementary	12/4/2024 15:11	Coleman	Fire Sprinkler System	Z2-043406	
					HVAC UNIT IN PORT #327B - NOT HEATING PM/WARR 416-4305
Shelby Oaks Elementary	10/18/2024 8:25	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-037449	
Shelby Oaks Elementary	10/4/2024 11:16	MALONE	Key & Lock	Z2-036300	equesting room gets Re-Keyed. Teacher's key was unfortunately stolen during vehicle break in
Shelby Oaks Elementary	7/9/2024 9:38	SMITH	Key & Lock	Z2-020547	Plant Manager's keys not working on exterior doors at Door 3
Shelby Oaks Elementary Shelby Oaks Elementary	8/8/2024 9:04 7/24/2024 10:09	BURCHETT	Masonry Painting	Z2-026281 Z2-022311	Requesting ceramic tile and small portion of wall be replaced in restroom Requesting Crosswalks get re-striped
Shelby Oaks Elementary	7/24/2024 10:09	BURCHETT	Painting	Z2-022311 Z2-022309	Requesting Crosswards get re-striped
Shelby Oaks Elementary	5/29/2024 10:44	BURCHETT	Painting	Z2-022303 Z2-016292	Requesting Cafeteria gets painted
Shelby Oaks Elementary	5/29/2024 10:43	BURCHETT	Painting	Z2-016291	Requesting Office gets painted
Shelby Oaks Elementary	5/29/2024 10:20	BURCHETT	Painting	Z2-016280	Requesting painting of all hallways
Shelby Oaks Elementary	5/29/2024 10:17	BURCHETT	Painting	Z2-016279	Requesting all student restrooms be painted
Shelby Oaks Elementary	3/12/2024 7:54	BURCHETT	Painting	Z2-004861	ıys walls and Entry/Exit doors get painted due to unsafe conditions (i.e. chipped paint, holes in some walls etc.)
Shelby Oaks Elementary	3/11/2024 14:25	BURCHETT	Painting	Z2-004844	lequesting restrooms get painting due to unsafe conditions such as rusting and chipped paint
Shelby Oaks Elementary	5/17/2024 14:26	MYERS	Painting	WO1011054	Chipped Paint and drywall in kitchen.
Shelby Oaks Elementary	12/12/2024 9:40	HARDWAY	Plumbing	Z2-044631	3 compartment sink leaking
Shelby Oaks Elementary Sherwood Elementary	12/10/2024 9:06 12/9/2024 17:04	HARDWAY FORD	Plumbing	Z2-044188 Z4-044129	Toilet in stall number 3 not flushing properly
Sherwood Elementary	12/9/2024 17:04	HALL	Carpentry Electrical	Z4-044129 Z4-044130	Repair hole in Sheetrock wall at bottom near floor trim. Replace blown ballast or wiring, light over entrance door to Cafeteria.
Sherwood Elementary	12/5/2024 17:00	HALL	Electrical	Z4-043130	Please replace damaged lens cover in stainwell.
Sherwood Elementary	5/17/2024 14:25	HALL	Electrical	WO1009284	
Sherwood Elementary	12/2/2024 11:24	CALDWELL	Elevators	Z4-042486	Elevator door open, will not close.
					1fl ROOM 117C PAD4 IV2 TBL MON
					1FL BY ROOM 117C CORRIDOR PS1.011
Sherwood Elementary	12/12/2024 12:23	CALDWELL	Fire Alarm System	Z4-044725	
Sherwood Elementary	10/25/2024 12:04	MALONE	Key & Lock	Z4-038369	Please repair lock on Exterior entrance door (jammed) key cannot turn or open door.
Sherwood Elementary	9/25/2024 10:02	MALONE	Key & Lock	Z4-034630	Requesting Elevator key (L206)
Sherwood Elementary Sherwood Elementary	5/14/2024 17:12 10/2/2024 16:22	SMITH BURCHETT	Key & Lock Masonry	Z4-014567 Z4-035973	Please cut (1) A key for inside door in main office. Please replace hazardous & cracked concrete floor tile with hole install 1st stall.
Sherwood Elementary	9/27/2024 15:31	BURCHETT	Masonry	Z4-035973 Z4-035240	Please repiace nazaroous & cracked concrete noor the with note install 1st stall. Please repair 2 large holes in wall tile.
onerwood Eternentary	JIZ/12024 15.51	DONOTIETT	r-iasoni y	24-000240	i tease repair 2 targe notes in wait tite.
					Please repair cracked, chipped,& damaged concrete ceiling above entrance/ exit door.
Sherwood Elementary	9/26/2024 16:36	BURCHETT	Masonry	Z4-034980	
Sherwood Elementary	5/17/2024 13:41	CORONADO	Masonry	WO979943	Damaged and detach concrete wall tile outside girls restroom near 215.
Sherwood Elementary	9/6/2024 16:12	BURCHETT	Painting	Z4-031390	Please paint 4 brick columns outside Entrance
Sherwood Elementary	9/6/2024 16:08	BURCHETT	Painting	Z4-031388	Please paint very faded Marquee/ Out front Sign

Sherwood Elementary	9/6/2024 16:04	BURCHETT	Painting	Z4-031387	Please paint faded Exterior Entrance double doors facing Rhodes Street.
Sherwood Elementary	8/7/2024 7:50	BURCHETT	Painting	Z4-025867	Please paint newly installed counter & top in main office
Sherwood Elementary	5/14/2024 17:02	BURCHETT	Painting	Z4-014566	Please paint walls in Lobby area thats not concrete tile and stairwell.
Sherwood Elementary	5/14/2024 16:57	BURCHETT	Painting	Z4-014565	Please paint Teachers Lounge in Main Lobby.
Sherwood Elementary	5/14/2024 16:54	BURCHETT	Painting	Z4-014564	Please paint 1st floor walls that is not concrete tile fin hallway from 101 - elevator landing
Sherwood Elementary	5/14/2024 16:43	BURCHETT	Painting	Z4-014563	Please paint wall in hallway on 2nd floor near rooms 201- 213. (where concrete is not.)
Sherwood Elementary	5/14/2024 16:38	BURCHETT	Painting	Z4-014562	Please paint walls and columns in Annex 3rd floor hallway and stairwell.
Sherwood Elementary	5/14/2024 16:34	BURCHETT	Painting	Z4-014561	Please paint walls and columns in Annex 2nd floor hallway and stairwell.
Sherwood Elementary	5/14/2024 16:28	BURCHETT	Painting	Z4-014559	Please paint P. E. room #100 per Principal Stigger
Sherwood Elementary	5/14/2024 16:18	BURCHETT	Painting	Z4-014557	Please paint room #223 Admin Data room in Annex per Principal Stigger.
Sherwood Elementary	11/13/2024 7:54	JOHNSON	Plumbing	Z4-040562	Faucet handle stripped, won't turn off
one weed Elementary	11/10/2024 / 104	7011110011	. tamonig	24 0 10002	CHILLER IS ON BUT NOT COOLING - AFFECTING THE ENTIRE & 2ND FLOOR
					P/M OUINN 416-4864
Sherwood Elementary	7/31/2024 7:58	TEDDER	Plumbing	Z4-023957	1111 QUINT 410 4004
Sherwood Middle	6/13/2024 10:21	FORD	Carpentry	Z4-018278	Put exits doors back with/ exit sign
Sherwood Pilidate	0/13/2024 10.21	TOND	Carpentry	24-010270	Need adjustments
Sherwood Middle	6/13/2024 10:18	FORD	Carpentry	Z4-018276	Need adjustificitis
Sherwood Middle	6/13/2024 10:18	FORD	. ,	Z4-018270 Z4-018271	Door east side/ needs adjusted
	6/13/2024 7:45	FORD	Carpentry		
Sherwood Middle			Carpentry	Z4-018239	Needs to mounted back up
Sherwood Middle	5/6/2024 13:46	BURCHETT	Carpentry	Z4-013242	Repair wall sheet rock
Sherwood Middle	12/11/2024 8:38	HALL	Electrical	Z4-044427	Ballast needs replacing
Sherwood Middle	12/9/2024 8:38	HALL	Electrical	Z4-043972	Needs replacing
Sherwood Middle	11/12/2024 11:00	HALL	Electrical	Z4-040450	Replace Len on light
Sherwood Middle	10/24/2024 10:13	HALL	Electrical	Z4-038159	Replenished lights/ safety hazard thx
Sherwood Middle	10/14/2024 8:06	HALL	Electrical	Z4-036776	Ballast needs replacing
					re key locks
Sherwood Middle	12/16/2024 8:18	MORRIS	Key & Lock	Z4-044974	
Sherwood Middle	12/11/2024 9:57	MALONE	Key & Lock	Z4-044448	Key stuck in door#127
Sherwood Middle	10/25/2024 11:48	MALONE	Key & Lock	Z4-038365	Replace A key / broken
Sherwood Middle	9/30/2024 11:23	MALONE	Key & Lock	Z4-035452	Lock needs change/ security issues
Sherwood Middle	9/11/2024 13:34	SMITH	Key & Lock	Z4-032036	Keys made
Sherwood Middle	10/30/2024 11:31	BURCHETT	Masonry	Z4-038916	Special cut around piping area
Sherwood Middle	5/30/2024 11:23	BURCHETT	Masonry	Z4-016496	Holes in wall needs repair
Sherwood Middle	5/23/2024 10:05	BURCHETT	Masonry	Z4-015804	Foundation needs repair/ when raining come through / several work order been done
Sherwood Middle	3/25/2024 8:21	CORONADO	Masonry	Z4-006078	Foundation /floor needs repair/ hole/ keep rodent out & base board needs replace
Sherwood Middle	5/22/2024 9:36	BURCHETT	Painting	Z4-015586	Graffiti 1st floor
Sherwood Middle	12/11/2024 8:37	JOHNSON	Plumbing	Z4-044426	Flush valve leaking
Sherwood Middle	12/4/2024 12:04	JOHNSON	Plumbing	Z4-043354	Replace faucet
Sherwood Middle	9/23/2024 11:19	TEDDER	Plumbing	Z4-034229	Sink stop -up
Sherwood Middle	6/27/2024 10:09	JOHNSON	Plumbing	Z4-019629	Toilet needs replacing/ safety hazard
					Ballast in back need replacing
Shrine School	12/16/2024 6:49	SCOTT	Electrical	Z3-044961	· · · · · · · · · · · · · · · · · · ·
					outside parking lot lights blown and the lights under the canopy front entrance.
Shrine School	12/13/2024 9:54	SCOTT	Electrical	Z3-044865	
ommo denede	12/10/2024 010-4	00011	Elocation	20 0 1 1000	Repair empty slots in electrical box (Poca) per inspector
Shrine School	12/3/2024 11:07	SCOTT	Electrical	Z3-042890	Topan ampty acts in account out to a feet maps acts
Shrine School	11/21/2024 8:14	SCOTT	Electrical	Z3-042830 Z3-041842	Light need replacing (blown)
Shrine School	9/20/2024 13:10	SCOTT	Electrical	Z3-041042 Z3-034041	No power outlet back of classroom
Shrine School	8/27/2024 8:39	BARNES	Electrical	Z3-034041 Z3-029729	Loose magnet on fire exit door by plant manager office
Silline School	0/2//2024 0.39	DANNES	Electricat	23-029729	exit sign bulbs or unit needs to be replaced
Shrine School	8/14/2024 14:16	SCOTT	Electrical	Z3-027574	exit sign buttes of utilit fleeds to be replaced
Silline School	8/14/2024 14.10	30011	Electricat	23-02/5/4	Computer Oranga Outlet
	5/04/0004700			70 045045	Computer Orange Outlet
Shrine School	5/21/2024 7:22	WHITWORTH	Electrical	Z3-015315	I reset it but still making humming sound
Shrine School	4/15/2024 9:20	WHITWORTH	Electrical	Z3-009192	Light balance replacement
Shrine School	4/14/2024 14:42	SCOTT	Electrical	Z3-009092	Replace broken
Shrine School	4/5/2024 11:03	WHITWORTH	Electrical	Z3-007906	Receptacle cover came back off
Shrine School	3/1/2024 8:54	WHITWORTH	Electrical	Z3-003503	Flag pole cord repair/replace for future utilizing daily use.
Shrine School	2/27/2024 8:13	SMALL	Electrical	Z3-002970	ice check of generator reason for these children must have an operable generator for life and health reasons.
					T here's a need for an mounted fire extinguisher An ABC dry chem fire extinguisher
					should be located inside the nurse's station or directly outside of the wall where the nurse's
					station is located. per Allison Perry MSN,BSN
Shrine School	11/7/2024 9:50	SMALL	Fire Extinguishers	Z3-040079	
					Ms. Jones, 69184 no heat entrire building
Shrine School	12/2/2024 8:42	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-042290	

WALL UNIT LEAKING - CL-RM 45 P/M JONES 416-9184

					P/M JONES 416-9184
Shrine School	10/2/2024 7:43	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-035808	
					WALL UNIT NOT COMING ON - CL-RM 39
					P/M JONES 416-9184
Shrine School	10/2/2024 7:42	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-035806	
Shrine School	8/7/2024 9:45	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-025980	Units is leaking
Shrine School	10/23/2024 12:12	MALONE	Key & Lock	Z3-038017	Cylinder needs replaced
Shrine School	10/23/2024 12:09	MALONE	Key & Lock	Z3-038013	Per principal
Shrine School	10/23/2024 12:06	MALONE	Key & Lock	Z3-038010	Asst Principal office need re-key per principal
Shrine School	4/9/2024 14:18	CORONADO	Masonry	Z3-008448	Broken tile
Shrine School	4/25/2024 11:26	BURCHETT	Painting	Z3-011518	Paint gym exit door for superintendent visit May 1,2024
Shrine School	4/24/2024 7:41	BURCHETT	Painting	Z3-011178	Library window need corking and painting
Shrine School	4/18/2024 8:33	SCHAEFFER	Painting	Z3-010135	Driving Lanes directional marking
Shrine School	4/15/2024 9:19	BURCHETT	Painting	Z3-009191	Ceiling rework
Shrine School	11/6/2024 10:22	TOLES	Plumbing	Z3-039823	Outside drain needs to be unclog (2nd) drain
			_		
Shrine School	2/7/2024 14:01	BARNES	Plumbing	Z3-000584	Faucet leak and sink slowly drains
Shrine School	10/1/2024 6:38	SMALL	Roll Up Doors	Z3-035561	Roll up door need inspection.
Shrine School	12/4/2024 7:52	HATCH	Sheet Metal	Z3-043117	Roll up door needs repaired (POCA)
					Drug Free School Zone
					Gang Free School Zone
					Gun Free School Zone
Shrine School	4/18/2024 8:29	BARNES	Sheet Metal	Z3-010130	Signs for Restricted and or non public area
Simile Concet	10/2024 0120	57111125	SHOOT HOLD	20 010100	MS. jones 69184 someone knocked gate down
Shrine School	12/2/2024 7:50	KINARD	Malding	Z3-042237	110. joines 00104 someone knocked gate down
Silline School	12/2/2024 7.50	KINARD	Welding	23-042237	
					Side of bleachers coming apart
Snowden School	8/13/2024 17:23		Bleachers and Seats	Z1-027366	
					Grids for new ceiling tiles
Snowden School	10/30/2024 14:37	RUSSELL	Carpentry	Z1-038968	
					Need new grids to replace ceiling tiles
Snowden School	10/30/2024 11:58	RUSSELL	Carpentry	Z1-038928	
					Marvin, 66125 broken window
Snowden School	10/28/2024 14:13	ARNOLD	Carpentry	Z1-038580	
					Ceiling tile hanging in cafeteria to high for plant manager
Snowden School	5/13/2024 7:58	RUSSELL	Carpentry	Z1-014161	
					POCA The rescue window is bolted shut and will not open from the inside.
Snowden School	5/2/2024 12:21	STEPHENS	Carpentry	Z1-012821	
					repair window in choir room
Snowden School	4/24/2024 9:26	JOHNSON	Carpentry	Z1-011236	,
Snowden School	12/5/2024 13:35	ANDREWS	Electrical	Z1-043658	Receptacle making loud noises
Showden School	12/3/2024 13:33	ANDINEWS	Electricat	21-043030	·
	44/0/000440		· · ·	74 000007	All night lights out
Snowden School	11/6/2024 10:29	ANDREWS	Electrical	Z1-039827	
Snowden School	7/22/2024 9:07	ANDREWS	Electrical	Z1-021837	Electrical drops for new Ex Ray machine
					Fire alarm not working in the portables
Snowden School	10/23/2024 11:53	GREER	Fire Alarm System	Z1-038001	
					Fire alarm system is in trouble mode, it's also having trouble with the pull station in the
					portables
Snowden School	8/13/2024 15:52	GREER	Fire Alarm System	Z1-027365	
					POCA Auditorium Seating needs to be serviced
Snowden School	5/2/2024 12:55	GREER	Fire Alarm System	Z1-012840	
			-		HEATING UNIT IN THE CEILING OF RM 226 - LEAKING DOWN INTO RM 136 - PM/CRADDOCK
					416-6125
Snowden School	12/9/2024 8:30	WEBB	Heating/Ventilation/Air Conditioning	Z1-043967	
onewach conser	12/0/2024 0:00	11235	Trouble Formacions in Conditioning	21 0 10007	HEATING UNIT FOR THE CAFE - BLOWING NOT HEATING PM/CRADDOCK 416-6125
Snowden School	12/4/2024 13:47	WEBB	Heating/Ventilation/Air Conditioning	Z1-043393	
					Discount of 14 -1-
Snowden School	12/3/2024 6:24	WEBB	Heating/Ventilation/Air Conditioning	Z1-042667	Blowing cold air
Snowden School	12/3/2024 6:23	WEBB	Heating/Ventilation/Air Conditioning	Z1-042666	Cold air blowing in the room
Snowden School	12/3/2024 6:13	WEBB	Heating/Ventilation/Air Conditioning	Z1-042663	Unit not working it's broken
					Air conditioning leaking
Snowden School	11/6/2024 10:03	WEBB	Heating/Ventilation/Air Conditioning	Z1-039810	
					Air conditioning leak
Snowden School	11/6/2024 10:02	WEBB	Heating/Ventilation/Air Conditioning	Z1-039808	

	10/00/000115 10	14/500		74 000000	Ceiling leaking
Snowden School	10/23/2024 15:46	WEBB	Heating/Ventilation/Air Conditioning	Z1-038063	Unit leaking
Snowden School	10/16/2024 8:17	WEBB	Heating/Ventilation/Air Conditioning	Z1-037148	Unit teaming
Shortach School	10, 10, 202-1 0, 17	***	riousing volumesons in containoning	21 00/110	Columns painted outside
Snowden School	7/31/2024 9:04	BURCHETT	Painting	Z1-024023	
Snowden School	4/26/2024 8:41	BURCHETT	Painting	Z1-011660	Paint restroom walls and partitions to remove graffiti
			_		Mr. Cradock
					66125
					water flowing from floor
Snowden School	12/16/2024 8:05		Plumbing	Z1-044973	
					Mr. Cradock
					66125
					water flowing from ceiling
Snowden School	12/16/2024 8:05		Plumbing	Z1-044972	
Snowden School	12/11/2024 8:10	AVANZI	Plumbing	Z1-044418	Leak under sink in room 132
	F 100 1000 1 1 1 F0			74 040404	get bottle fillers ready for inspections
Snowden School	5/28/2024 11:58	WILSON	Plumbing	Z1-016121	O and for the month bloom
Snowden School	5/17/2024 14:25	BENTON	Shades/Blinds	WO1008055	3 sets for the portables RE ATTACH GUTTERS
Snowden School	4/26/2024 13:53	Williams	Sheet Metal	Z1-011796	RE ATTACH GUTTERS
South Park Elementary	11/1/2024 14:32	SCOTT	Electrical	Z3-039313	106 need electric plug under board
South Park Elementary	10/31/2024 11:48	SCOTT	Electrical	Z3-039096	Put this in was cancelled
South Park Elementary	8/1/2024 12:21	SCOTT	Electrical	Z3-033030	Outlet not working under the water fountain
South Park Elementary	7/25/2024 13:55	WHITWORTH	Electrical	Z3-022681	No outlets work
South Park Elementary	7/25/2024 13:54	WHITWORTH	Electrical	Z3-022679	No light in restroom
South Park Elementary	8/22/2024 11:22	SMALL	Fire Alarm System	Z3-029122	The alarm needs be cleared of all violations
,			,		fire alarm isn't working in room 211
South Park Elementary	4/19/2024 15:58	SMALL	Fire Alarm System	Z3-010785	·
			-		HVAC UNIT - FOR THE MAIN OFC - NOT BLOWING PM/KING 416-5024
South Park Elementary	5/21/2024 14:35	SCOTT	Heating/Ventilation/Air Conditioning	Z3-015492	
					KEY WILL NOT TURN IN THE CYLINDER - CL-RM 102-TEACHERS KEYS & PERSONAL
					BELONGINGS IS IN THE ROOM
					P/M JOSHUA KING 416-5024
South Park Elementary	12/10/2024 14:34	MALONE	Key & Lock	Z3-044352	
South Park Elementary	9/13/2024 10:07	SMITH	Key & Lock	Z3-032607	Assistance principles office
South Park Elementary	5/14/2024 10:06	SMITH	Key & Lock	Z3-014455	The key hold not letting anyone in
South Park Elementary	9/5/2024 10:21	BURCHETT	Painting	Z3-031108	Girls restroom need painting
South Park Elementary	8/1/2024 15:22	BURCHETT	Painting	Z3-024569	Need wall painted
South Park Elementary	12/10/2024 13:25	TOLES	Plumbing	Z3-044326	Sink is leaking
South Park Elementary	8/15/2024 15:09	KINARD	Welding	Z3-027908	Flag rope has broken need be replaced
					we need the cubical taken down from the (parent welcoming center) then we need the
					truancy office cubicle taken down and brought over to the welcoming center
Southeast Truancy Office	9/16/2024 13:18	BARNES	Carpentry	Z3-032980	tidancy office cubicle taxen down and blought over to the welcoming center
Southwest Career & Technology Center	10/17/2024 9:46	HALL	Electrical)al is requesting that the exterior lights outside the building be replaced, due to darkness in the a.m.
countries career a realmone, contain	10/1//2024 0140	10122	Eloculout	24 007041	action requesting that the extense agree eachies and banding so replaced, and to during any
					4 outlets are out and the class isn't able to make any cuts for projects & activities.
Southwest Career & Technology Center	8/27/2024 10:07	HALL	Electrical	Z4-029794	
Southwest Career & Technology Center	7/23/2024 11:48	HALL	Electrical	Z4-022131	Light balance needs to be fixed
Southwest Career & Technology Center	4/9/2024 11:22	HALL	Electrical	Z4-008389	Reset outside kiosk
Southwest Career & Technology Center	9/24/2024 12:28	CALDWELL	Fire Alarm System	Z4-034487	re panel has a trouble shooting and it is causing a high frequency noise to occur every few minutes.
Southwest Career & Technology Center	5/30/2024 10:44	CALDWELL	Fire Sprinkler System	Z4-016470	Need updated inspection
Southwest Career & Technology Center	8/26/2024 11:31	FINNIE	Masonry	Z4-029575	The steps that lead to the flag pole need to be repaired. Those steps are made of brick.
					the storage room ceiling have been damage due to roof leak
Southwind Elementary	10/9/2024 10:30	CROUSE	Carpentry	Z3-036715	
					boiler inspector request to have a carbon monoxide detectors install.
Southwind Elementary	12/12/2024 8:46	SCOTT	Electrical	Z3-044571	
0 11 1 151			- · · ·	70.0445	boiler inspector request to have carbon monoxide detectors install.
Southwind Elementary	12/12/2024 8:42	SCOTT	Electrical	Z3-044567	
					The issues with the intercom and bells yet have not been resolved, the contractor stated
					that he would be back to finish , just trying to find out the status.
Southwind Elementary	11/14/2024 14:15	JOHNSON	Electrical	Z3-040917	and the would be back to minon, just it ying to min out the status.
ooddiwind Etellielitaly	1111712024 14.1U	70111400IN	Licotificat	20 04001/	

					hoth lights is blow out
Southwind Elementary	9/10/2024 16:14	SCOTT	Electrical	Z3-031842	both lights is blow out.
Coudiwing Eternentary	3/10/2024 10:14	00011	Electricat	20 001042	
					Due to bells not working the principal request for the bells to be reprogrammed.
Southwind Elementary	8/6/2024 9:40	SCOTT	Electrical	Z3-025574	
					Service FAP. Panel is blank.
Southwind Elementary	12/3/2024 8:09	SMALL	Fire Alarm System	Z3-042723	
					When the fire alarm goes off, the fire doors do not release B hallway fire door. fire alarm in
					reads trouble AHU -2 return duct detector. 400 hallway restrooms duct detector. Duct
Southwind Elementary	2/12/2024 10:53	SMALL	Fire Alarm System	Z3-000995	detectors and air handlers in Gym area.
Southwind Eternentary	2/12/2024 10:55	SIMEL	The Alaini System	25-000333	missing Escutcheon ring need to be replaced
Southwind Elementary	9/17/2024 12:04	SMALL	Fire Sprinkler System	Z3-033215	mooning Ecoatonicon mily nood to be replaced
,					several floor tiles coming up due floor tile is old and the glue no longer sticking.
Southwind Elementary	11/18/2024 10:32	CASEY	Flooring	Z3-041243	
					need the other half of the floor tile remove due to crack floor tile.
Southwind Elementary	10/31/2024 13:03	CASEY	Flooring	Z3-039118	
					HVAC UNIT IN RM 120 - NOT COOLINGPM/FOSTER 416-2805
Southwind Elementary	7/15/2024 12:55	White	Heating/Ventilation/Air Conditioning	Z3-021236	LINAO LINITINI DIA 400. NOT COCCUNIODIA/FOCTED 440.000F
Southwind Elementary	7/15/2024 12:54	White	Heating/Ventilation/Air Conditioning	Z3-021235	HVAC UNIT IN RM 102 - NOT COOLINGPM/FOSTER 416-2805
Southwind Elementary	//15/2024 12.54	wille	neaung/ventitation/Air Conditioning	23-021235	HVAC UNIT FOR RM 158 NOT COOLING PM/FOSTER 416-2805
Southwind Elementary	5/20/2024 8:18	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-015143	TIVAC DIVITI DIVINI 130 NOI COOLINO I PIN OSTERI 410-2003
ooddining Etomontary	0/20/2024 0:10		round roundadin in Conditioning	20 020240	unable to lock the door with the key.
Southwind Elementary	9/18/2024 10:18	SMITH	Key & Lock	Z3-033415	•
,			•		principal request two keys
Southwind Elementary	8/22/2024 8:42	SMITH	Key & Lock	Z3-029046	
					wall has a foundation cracked
Southwind Elementary	7/15/2024 13:57	CORONADO	Masonry	Z3-021254	
					both sides of the wall has a foundation cracked.
Southwind Elementary	7/15/2024 13:53	CORONADO	Masonry	Z3-021253	wall has a foundation cracked.
Southwind Elementary	7/15/2024 13:13	CORONADO	Masonry	Z3-021242	watt has a foundation cracked.
Southwind Eternentary	7713/2024 13:13	CONONADO	i-iasoni y	25-021242	annual testing of4- backflow preventers
Southwind Elementary	10/3/2024 13:34	WILSON	Plumbing	Z3-036151	annual todaing of Foundation professions
,			· ·		has a roof leak at the storage entrance door.
Southwind Elementary	11/6/2024 9:52	BUFORD	Roofing	Z3-039795	
Southwind High	2/3/2024 17:04	LEWIS	Asbestos	WO1017732	$2"\ copper\ pipe\ in\ ceiling\ in\ front\ of\ gym\ entrance\ estimating\ 10'\ of\ 2.1/2"\ fiberglass\ insulation\ needed\ to\ complete$
					NEED COVERS PUT ON FIRE ALARMS IN STADIUM RESTROOMS HOME AND AWAY SIDE.
	0117100011510	2.20152		70.010011	ALSO, IN THE LOCKER ROOMS NEED A COVER OVER THE ALARM
Southwind High	6/17/2024 15:16	BARNES	Carpentry	Z3-018611	TICKET BOOTH AT SOUTH ENTRY THE WINDOW IS STUCK CLOSED SHUT AND CANNOT
					OPEN
Southwind High	3/7/2024 9:31	TAYLOR	Carpentry	Z3-004384	OI EN
Southwind High	5/17/2024 14:26	LEWIS	Carpet Repair		r Bush has requested that the carpet be repaired or replaced in main oggice. Its badly ripped up.
Southwind High	5/17/2024 14:24	BENTON	Carpet Repair		rpet repair in band room or removed it has a smell to it even after its cleaned and it badly tore up
Southwind High	5/17/2024 14:24	BENTON	Carpet Repair	WO1006961	carpet to be repaired in auditorium
Southwind High	5/17/2024 14:24	BENTON	Carpet Repair	WO1006955	carpet needs repaired in AUDITORIUM looks bad.
Southwind High	5/17/2024 14:22	BENTON	Carpet Repair	WO1004321	arpet be repaired or taken up in band room. It also has a smell to it and has been cleaned several times.
Southwind High	5/17/2024 14:19	BENTON	Carpet Repair	WO1002578	rpet be removed or repaired in room S156 . It holds a smell even when shampooed. Its badly woren.
Southwind High	5/17/2024 13:36	LEWIS	Carpet Repair	WO967914	Please repair carpet in main office and in hall way in main office.
Southwind High	12/9/2024 9:21	SCOTT	Electrical	Z3-043997	Lights in the middle section of the auditorium
Southwind High	11/21/2024 12:10	SCOTT	Electrical	Z3-041949	Main hall key switch is loose
Southwind High	11/20/2024 10:14	SCOTT	Electrical	Z3-041682	Outlets hanging out the wall
•					Upgrade gym lights to LED
Southwind High	11/1/2024 12:12	CHALK	Electrical	Z3-039275	
Southwind High	10/21/2024 11:33	SCOTT	Electrical	Z3-037674	Ballast out need to be replaced all new lights buds in there already
Southwind High	9/20/2024 9:42	SCOTT	Electrical	Z3-033946	5 light poles along side of the football field are out
Southwind High	9/16/2024 12:11	SCOTT	Electrical	Z3-032943	Two lights in the back of the library need ballet
					2 balances out
Southwind High	9/9/2024 12:45	SCOTT	Electrical	Z3-031560	
					internet parte net working

Z3-026769

8/9/2024 13:48

SCOTT

Electrical

Southwind High

internet ports not working.

					balance out
Southwind High	8/1/2024 7:20	SCOTT	Electrical	Z3-024199	balance out
Southwind High	7/24/2024 9:49	SCOTT	Electrical	Z3-022300	balance out
Southwilla High	772472024 9.49	SCOTT	Electrical	23-022300	light cover broke off and bad balance
Southwind High	7/1/2024 10:40	SCOTT	Electrical	Z3-019931	-
Southwind High	7/1/2024 8:11	SCOTT	Electrical	Z3-019868	several lights out
					several lights out needs replaced
Southwind High	7/1/2024 8:10	SCOTT	Electrical	Z3-019867	plant manager office needs lights storage room
Southwind High	7/1/2024 8:09	SCOTT	Electrical	Z3-019866	prant manager office needs agrits storage room
Occade and Hinds	0/44/000440-04	20077	Floring	70.040400	s160 bad balance
Southwind High	6/14/2024 13:01	SCOTT	Electrical	Z3-018422	broken light cover and lights can't be replaced something stuck in it
Southwind High	6/14/2024 10:20	SCOTT	Electrical	Z3-018381	
Southwind High	6/12/2024 12:09	SCOTT	Electrical	Z3-018169	lights want come on
					several lights out needs replaced
Southwind High	4/30/2024 9:13	SCOTT	Electrical	Z3-012184	lights will not come on inside i checked breakers nothing is tripped.
Southwind High	4/30/2024 6:37	SCOTT	Electrical	Z3-012121	agnis wat not come of inside 1 checked bleakers nothing is appeal.
		00077	· · ·	70.044500	several lights out need replaced
Southwind High	4/25/2024 13:59	SCOTT	Electrical	Z3-011596	RECEPTACLES (4) HAS NO POWER - CL-RM A127
					P/M THOMAS 416-3250
Southwind High	4/23/2024 8:02	SCOTT	Electrical	Z3-010993	balance out
Southwind High	4/5/2024 7:45	SCOTT	Electrical	Z3-007832	Suanos out
Southwind High	4/3/2024 12:45	SCOTT	Electrical	Z3-007607	big circle light needs replaced soon please
Southwilla High	4/3/2024 12.43	30011	Electricat	23-00/00/	i have a lot of lights out in the auditorium needs to be replaced
Southwind High	2/23/2024 6:34	CHALK	Electrical	Z3-002561	
Southwind High	2/7/2024 10:30	WHITWORTH	Electrical	Z3-000540	Emergency exit Light replaced on Ghall upstairs
Southwind High	11/20/2024 10:32	SMALL	Fire Alarm System	Z3-041696	Pull station has a bad sensor
					The fire panel in the closet by #134 is malfunctioning and beeping. Giving out default readings: RM 159 EXIT PULL STATION. "A" DOORS @RM 130 SMOKE DETECTORS DIRTY.
					CAFE NORTH UNIT RTU-E3 DUC DETECTOR EXCESSIVELY DIRTY. STAIRS @ RM-153 PULL
					STATION OPEN CKT TROUBLE.
Southwind High	5/20/2024 13:39	SMALL	Fire Alarm System	Z3-015269	
Southwind High	9/19/2024 12:26	CASEY	Flooring	Z3-033784	Carpet removal
Southwind High	9/19/2024 12:19	CASEY	Flooring	Z3-033771	Carpet removal
Southwind High	9/19/2024 12:16	CASEY	Flooring	Z3-033768	Carpet need to be removed
Southwind High	12/10/2024 13:40	BRYSON	Heating/Ventilation/Air Conditioning	Z3-044331	Wall Thermostat do not work need to be replaced
Southwind High	12/9/2024 8:54	BRYSON	Heating/Ventilation/Air Conditioning	Z3-043979	Heat not working has an alarm on it from Energy management HEATING UNIT IN CAFE - NOT COMING ON SUPERVISOR MERRITT -416-3250
Southwind High	12/3/20247:11	BRYSON	Heating/Ventilation/Air Conditioning	Z3-042682	TIEATING ONLY IN CALE - NOT COMING ON 301 ENVISOR PIERWIT -410-3230
					unit not cooling
Southwind High	7/26/2024 11:39	JOHNSON	Heating/Ventilation/Air Conditioning	Z3-022925	unit not cooling
Southwind High	7/26/2024 11:38	JOHNSON	Heating/Ventilation/Air Conditioning	Z3-022924	· ·
Southwind High	10/30/2024 11:43	MALONE	Key & Lock	Z3-038921	The lock on the doors won't latch to lock them
Southwind High	9/23/2024 12:40	MALONE	Key & Lock	Z3-034272	Doors won't lock
ooutiwiiid riigii	3/20/2024 12.40	TIMEONE	ncy a Lock	20 004272	home side concession stand door want lock
Southwind High	9/9/2024 10:13	SMITH	Key & Lock	Z3-031490	nome side concession stand door want took
30utii wiii u riigii	3/3/2024 10:13	Simili	Key & LUCK	25-051450	cracks in the floor needs sealing pest control came out sprayed due to ants coming threw
					the cracks he said
Southwind High	4/29/2024 12:38	CORONADO	Masonry	Z3-012028	to be painted please
Southwind High	6/10/2024 10:06	BURCHETT	Painting	Z3-017836	Fa booos
O	F /4 4 /000 1 1 0 00	DI IDO: :577	Del et e	70.04.405	The Assistant Principal is requesting that a discolored wall in her office be painted
Southwind High	5/14/2024 12:28	BURCHETT	Painting	Z3-014495	

Southwind High	12/12/2024 9:20	TOLES	Plumbing	Z3-044594	Hot water not working
Southwind High	12/3/2024 12:13	WARREN	Plumbing	Z3-042948	Toilet stopped up bad
Southwind High	12/3/2024 11:54	WARREN	Plumbing	Z3-042935	Toilet stopped up
Southwind High	11/13/2024 8:20	BARNES	Roofing	Z3-040567	Roof leaking
Southwind High	12/11/2024 14:52	KINARD	Welding	Z3-044511	Gates
			3		the white metal gates are broken causing them to lean on the ground
Southwind High	6/3/2024 8:25	KINARD	Welding	Z3-016851	
ooddiiiiid i ligii	0/0/2024 0:20	NII W II I	Trouble 1	20 010001	used fluorescent bulb pick up
Springdale Elementary	12/15/2024 19:21	LANE	Asbestos	Z1-044948	add tad dodd to data plot ap
Springdate Elementary	11/15/2024 11:26	ARNOLD	Carpentry	Z1-041082	Door needs to be replaced
Springdate Elementary	2/3/2024 17:07	STEPHENS	Carpentry	WO1016899	
Springdale Elementary	2/3/2024 17:07	STEPHENS	Carpentry	WO1016889	<u> </u>
Springdale Elementary	2/3/2024 17:07	STEPHENS	Carpentry	WO1016869	
Springdate Elementary	2/3/2024 17:07	ARNOLD	Carpentry	WO1016031	· · · · · · · · · · · · · · · · · · ·
Springdale Elementary	2/3/2024 14:09	STEPHENS	Carpentry	WO1016911 WO1016884	<u> </u>
		STEPHENS		WO1016864 WO1016892	
Springdale Elementary	2/3/2024 14:09		Carpentry		· · · · · · · · · · · · · · · · · · ·
Springdale Elementary	2/3/2024 14:09	STEPHENS	Carpentry	WO1016882	
Springdale Elementary	9/16/2024 7:05	CHALK	Electrical	Z1-032759	Lights are out
Springdale Elementary	9/16/2024 7:02	CHALK	Electrical	Z1-032756	Exterior lights are not on
Springdale Elementary	9/16/2024 7:01	CHALK	Electrical	Z1-032755	Exterior lights are not on
Springdale Elementary	9/16/2024 6:44	CHALK	Electrical	Z1-032753	All lights are out or blown in the back except rear cafeteria dock lights
Springdale Elementary	8/13/2024 8:07	SMITH	Electrical	Z1-027178	Pre K/4 lamps blown in cafe(lift needed)
					Pre K
Springdale Elementary	7/29/2024 9:25	SMITH	Electrical	Z1-023205	Need emergency lights installed and mounted on walls
Springdale Elementary	4/18/2024 8:09	SMITH	Electrical	Z1-010109	Flood lights for the stage lighting are blown
Springdale Elementary	4/18/2024 8:06	SMITH	Electrical	Z1-010105	5 lamps blown (need lift)
Springdale Elementary	2/3/2024 16:58	CHALK	Electrical	WO1019271	Over hanging lamp off of building not coming on.
Springdale Elementary	2/3/2024 16:58	CHALK	Electrical	WO1019269	Exterior lights are not coming on.
Springdale Elementary	11/18/2024 9:49	LEWIS	Flooring	Z1-041229	Repair subfloor and VCT
					REPLACE TEC CONTROLLER IN CAFE UNIT #3
Springdale Elementary	4/12/2024 7:23	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-008946	
Springdale Elementary	2/16/2024 9:35	SMITH	Key & Lock	Z1-001692	Need key for lock or lock cylinder changed to keep students/staff from entering
Springdale Elementary	2/16/2024 9:33	SMITH	Key & Lock	Z1-001689	or old lock or need new lock cylinder to lock restroom/storage room to isolate students/staff from entry
Springdale Elementary	10/16/2024 8:53	BURCHETT	Painting	Z1-037173	Scraping/painting needed
Springdale Elementary	10/16/2024 8:52	BURCHETT	Painting	Z1-037170	Scraping/painting
Springdale Elementary	11/18/2024 13:56	WILSON	Roofing	Z1-041341	Ceiling leaking while raining
Springdale Elementary	7/18/2024 9:52	STEPHENS	Sheet Metal	Z1-021625	Need sheet metal to cover holes in floor
Springdale Elementary	2/3/2024 17:07	HATCH	Sheet Metal	WO1016905	Gutter missing
Springdale Elementary	2/3/2024 17:07	HATCH	Sheet Metal	WO1016906	gutter missing
Springdale Elementary	2/3/2024 14:09	HATCH	Sheet Metal	WO1016894	Broken/missing gutters
Springdale Elementary	2/3/2024 14:09	HATCH	Sheet Metal	WO1016895	Broken/missing gutters
					Please inspect electrical sockets located in room E-101. The sockets located in the back
					office are dead. The building engineer has checked all breakers.
Teaching & Learning Academy	12/10/2024 8:56	POWELL	Electrical	Z2-044184	0.0
,					
					Please replace Ballast's in two four tube lights located on the second-floor office area.
Teaching & Learning Academy	10/29/2024 8:44	POWELL	Flectrical	Z2-038654	· · · · · · · · · · · · · · · · · · ·
					Please replace the Auditorium outside entrance door lights all of the lights to each of these
					doors are out.
Teaching & Learning Academy	7/9/2024 8:11	POWELL	Electrical	Z2-020502	20010 210 0211
reaching & Leanning Academy	77372024 0.11	TOWLLL	Liectificat	22-020302	Please replace the canopy lights located on the South and East side of the building all the
					lights are out.
Tooching 9 Loorning Academy	7/9/2024 8:08	POWELL	Floatrical	Z2-020495	ugits are out.
Teaching & Learning Academy			Electrical	Z2-020495 Z2-043068	Discourse is INVACILISM ANNIA
Teaching & Learning Academy	12/4/2024 5:07	HANSON	Heating/Ventilation/Air Conditioning	22-043008	Please repair HVAC Unit AHU 6
					Plant Manager Whitt reported the HVAC unit in the Distant learning Center room on the
					second floor is blowing cold air. 416-3426.
Teaching & Learning Academy	12/2/2024 8:06	HANSON	Heating/Ventilation/Air Conditioning	Z2-042247	contribution of the state
					unit leaking in attic
Teaching & Learning Academy	11/18/2024 6:20	HANSON	Heating/Ventilation/Air Conditioning	Z2-041158	
Teaching & Learning Academy	5/9/2024 8:24	BURCHETT	Masonry	Z2-013781	ir or replace the missing bricks located just outside of the Telecommunications building. Handicap ramp.
					NEW WATER FOUNTAIN ON THE 1ST FLR - LINE HAS BUSTED - PM/WHIT 416-3426
Teaching & Learning Academy	11/15/2024 8:46	SEMLER	Plumbing	Z2-041018	
					check roof over office where plaster fell
Teaching & Learning Academy	11/19/2024 6:27	STEVENS	Roofing	Z2-041377	

					we are in need of a swinging door in our main office separating the staff from the parents to
Treadwell Elementary	11/4/2024 8:34	STAFFORD	Carpentry	Z2-039378	keep others from freely going behind counter
Treadwell Elementary	11/4/2024 8.34	STAFFORD	Сагреппу	22-039378	exit door in classroom will not shut properly, needs to be adjusted
Treadwell Elementary	8/8/2024 11:29	BURKE	Carpentry	Z2-026402	Lights are out over the cafeteria door and need to be changed out we have after care and it
					gets dark
Treadwell Elementary	12/11/2024 10:32	POWELL	Electrical	Z2-044459	Girls restroom lights are out and need a balanceer I have taken the bulbs out and it's in pre k
					so it needs lighting
Treadwell Elementary	12/11/2024 10:22	POWELL	Electrical	Z2-044457	Hallway lights in frot of main office balance is out and is dark on that end have taken bulbs
					out for repair
Treadwell Elementary	12/5/2024 10:52	POWELL	Electrical	Z2-043569	2 light fixtures are out and need new balance is dark in there pre k
Treadwell Elementary	12/5/2024 9:23	POWELL	Electrical	Z2-043515	2 ught inxtures are out and need new datance is dark in there pre-k
					Needing lights put in over door leading to the cafeteria it's dark early and ymca after care has started
Treadwell Elementary	11/20/2024 12:15	POWELL	Electrical	Z2-041745	nas staneu
					there is a helphony that people to be about ad an the 1 at floor hellows lights are already out
Treadwell Elementary	11/8/2024 9:11	POWELL	Electrical	Z2-040255	there is a balancer that needs to be changed on the 1st floor hallway lights are already out
Treadwell Elementary	10/7/2024 13:07	POWELL	Electrical	Z2-036491	1st floor main building janitorial closet lights are out and balancer needs changing
					room 303 has a shortage in the the 2nd outlet to the right as you enter the room
Treadwell Elementary	10/1/2024 11:23	POWELL	Electrical	Z2-035713	
					girls restroom on the 2nd floor lights go out every other day balancer needs changing
Treadwell Elementary	9/5/2024 8:48	POWELL	Electrical	Z2-031054	room 212 need balancers changed bulbs have been removed
Treadwell Elementary	8/9/2024 10:24	POWELL	Electrical	Z2-026680	
					hall lights are out near the exit door by the 2nd staircase in the main building needs a cover also
Treadwell Elementary	8/9/2024 10:20	POWELL	Electrical	Z2-026675	
					need lights checked in the boys bathroom and in the hallways in the annex pre k building. balancer needs to be checked
Treadwell Elementary	7/15/2024 10:40	POWELL	Electrical	Z2-021199	
Treadwell Elementary	12/12/2024 13:44		Elevators	Z2-044757	Our elevator is not working doors will not open lights up but want move
,					i am requesting for a battery replacement in our main building for our fire alarm system-
Treadwell Elementary	10/18/2024 7:37	Coleman	Fire Alarm System	Z2-037429	secondary power
Treadwell Elementary	6/14/2024 9:44	LEWIS	Fire Alarm System	Z2-018375	System is down an continues to beep and want set reading trouble
Treadwell Elementary	6/11/2024 13:04	LEWIS	Fire Alarm System	Z2-018038	needing covers for sprinkler unit stated by fire marshall
Treadwell Elementary	8/9/2024 13:26	LEWIS	Heating/Ventilation/Air Conditioning	Z2-026761	Pipes needing to be wrapped cause pipes are leaking and need to fixed soon due to leaking
Treadwell Elementary	10/2/2024 8:45	MALONE	Key & Lock	Z2-035839	keys for room 85 86 89 93
Treadwell Elementary	10/2/2024 0.40	TIALONE	ncy a Lock	22 000000	needing boys restroom doors painted all doors have paint chipping bad and has peeled of
Treadwell Elementary	11/13/2024 11:22	BURCHETT	Painting	Z2-040648	doors
Treadwell Elementary	11/15/2024 11:22	DONGLIETI	ranning	22-040040	MAIN BUILDING PAINT ON STAIRWAYS IS PELLING BAD ITS CHIPPING BAD AND COULD
Troodwoll Elementary	7/31/2024 12:02	BURCHETT	Painting	Z2-024104	POSSIBLE BE A HAZARD.
Treadwell Elementary	//31/2024 12.02	DUNUTEII	ranning	£2-U241U4	all front stall doors in boys restroom are needing painting due to the bad graffiti drawn on
Townshire U.S.	0.14.0.1000 1.00.00	DUDO::	D. C. C.	70.01011	the doors
Treadwell Elementary Treadwell Elementary	6/16/2024 23:29 5/28/2024 18:39	BURCHETT BURCHETT	Painting Painting	Z2-018444 Z2-016190	12nd floor all doors on stalls need painting curse words and sexual content written on all doors inside and out
Treadwell Elementary	4/15/2024 9:18	BURCHETT	Painting	Z2-009190	Steps wall is in need of repair
Treadwell Elementary	5/17/2024 14:23	YOUNG	Painting	WO1004831	The plaster and paint are peeling off the wall in the middle stairwell.
Treadwell Elementary	6/8/2024 9:01	WILSON	Plumbing	Z2-017772	prep bottle fillers for inspections
Treadwell Elementary	0/0/2024 3.01	WILSON	i tuilibilig	22-01///2	

					A water leak has been noticed in room A3 in the new annex regional building the tile is	
					discolored and shows a water spot	
Treadwell Elementary	12/11/2024 10:28	STAFFORD	Roofing	Z2-044458		
					Please replace hinges on stalls 3, 4, and 5.	
Treadwell Middle School	12/3/2024 14:15	BURKE	Carpentry	Z2-043030		
					Please repair south wall in room 128.	
Treadwell Middle School	7/30/2024 13:27	BURKE	Carpentry	Z2-023808		
					Please repair north wall in room 112 right side.	
Treadwell Middle School	7/30/2024 13:27	BURKE	Carpentry	Z2-023806	·	
					Please repair north wall in room 110A.	
Treadwell Middle School	7/30/2024 13:25	BURKE	Carpentry	Z2-023805	· case repair not a maximise in 124 in	
Treadwell Filladie School	773072024 13.23	DOTAL	Carpentry	22-023003	Per Code Enforcement Inspector: 1. Please adjust nudging timer. 2. Replace all broken key	
					switches on all (4) floors.3.Clean Elevator Pit	
Treadwell Middle School	5/17/2024 14:27	LEWIS	Elevators	WO1011257		
					Fire alarm panel has Positive Ground Fault Trouble Input.	
Treadwell Middle School	6/21/2024 8:41	LEWIS	Fire Alarm System	Z2-018996		
					Cover space where old fire alarm pull station was.	
Treadwell Middle School	5/7/2024 17:30	Coleman	Fire Alarm System	Z2-013544		
					Please replace broken tiles in center of cafeteria from east to west walls.	
Treadwell Middle School	11/15/2024 14:49	CASEY	Flooring	Z2-041141		
			· ·		ELEVATED HVAC UNIT IN THE MAIN GYM - BOYS & GIRLS RR - NOT COMING ON -	
					PM/RAYFORD 416-9211	
Treadwell Middle School	12/4/2024 10:46	HANSON	Heating/Ventilation/Air Conditioning	Z2-043297		
Treadwell Fillude School	12/4/2024 10.40	HANSON	Heating/ventitation/Air Conditioning	22-043297		
					I need (3) 221 keys for the cabinets in room 101 (the community resource room). Thanks.	
Treadwell Middle School	10/22/2024 11:08	MALONE	Key & Lock	Z2-037832		
Treadwell Middle School	9/27/2024 7:49	MALONE	Key & Lock	Z2-035012	The southwest door of the gym key cylinder is coming out.	
Treadwell Middle School	3/28/2024 10:29	SMITH	Key & Lock	Z2-006756	$in \ room\ 121B\ as\ testing\ room\ location\ has\ moved.\ Also,\ please\ bring\ 4\ keys\ for\ those\ who\ need\ access\ to\ the\ room,\ as\ this\ room\ is\ also\ as\ office.$	
					Teacher broke her key in her classroom door.	
Treadwell Middle School	2/27/2024 16:19	SMITH	Key & Lock	Z2-003106		
			-		Please paint repaired walls in cafeteria on southeast ceiling near gym and on the northeast	
					wall next to mechanical room.	
Treadwell Middle School	8/7/2024 10:23	BURCHETT	Painting	Z2-026018		
TTCGGWCIITTIGGIC OCTIOOL	0///2024 10.20	DOMONETT	i umung	22 020010		
					Please paint walls in room 122 Repairs were made to the walls, and they need to be	
					Please paint walls, in room 122. Repairs were made to the walls, and they need to be	
To a door!! Middle Oaks at	0/07/000444-00	PUPOUETT	Detection	70.040000	Please paint walls, in room 122. Repairs were made to the walls, and they need to be painted.	
Treadwell Middle School	6/27/2024 14:38	BURCHETT	Painting	Z2-019686	painted.	
Treadwell Middle School Treadwell Middle School	6/27/2024 14:38 11/21/2024 11:26	BURCHETT SEMLER	Painting Plumbing	Z2-019686 Z2-041940	painted. Please replace broken spigot	
					painted.	
					painted. Please replace broken spigot	
Treadwell Middle School	11/21/2024 11:26	SEMLER	Plumbing	Z2-041940	painted. Please replace broken spigot	
Treadwell Middle School	11/21/2024 11:26	SEMLER	Plumbing	Z2-041940 Z2-017770	painted. Please replace broken spigot prep bottle fillers for inspections	
Treadwell Middle School Treadwell Middle School	11/21/2024 11:26 6/8/2024 8:57	SEMLER	Plumbing Plumbing	Z2-041940	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door.	
Treadwell Middle School Treadwell Middle School Treadwell Middle School	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19	SEMLER WILSON STAFFORD	Plumbing Plumbing Welding	Z2-041940 Z2-017770 Z2-043033	painted. Please replace broken spigot prep bottle fillers for inspections	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22	SEMLER WILSON STAFFORD LANE	Plumbing Plumbing Welding Asbestos	Z2-041940 Z2-017770 Z2-043033 Z1-044949	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01	SEMLER WILSON STAFFORD LANE SMITH	Plumbing Plumbing Welding Asbestos Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22	SEMLER WILSON STAFFORD LANE	Plumbing Plumbing Welding Asbestos	Z2-041940 Z2-017770 Z2-043033 Z1-044949	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating property	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53	SEMLER WILSON STAFFORD LANE SMITH SMITH	Plumbing Plumbing Welding Asbestos Electrical Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center Trezevant Career & Technology Center Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH	Plumbing Plumbing Welding Asbestos Electrical Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating property Lights need replacing in MEP Warehouse Room 110.	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53	SEMLER WILSON STAFFORD LANE SMITH SMITH	Plumbing Plumbing Welding Asbestos Electrical Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating property	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center Trezevant Career & Technology Center Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH	Plumbing Plumbing Welding Asbestos Electrical Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating property Lights need replacing in MEP Warehouse Room 110.	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH	Plumbing Plumbing Welding Asbestos Electrical Electrical Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-021223	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating properly Lights need replacing in MEP Warehouse Room 110. Lights aren't operating properly one set on other two not	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/23/2024 7:47	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH SMITH	Plumbing Plumbing Welding Asbestos Electrical Electrical Electrical Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-021223 Z1-015755 Z1-006815	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating property Lights need replacing in MEP Warehouse Room 110. Lights aren't operating property one set on other two not Two ballasts fixtures need replace.	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/23/2024 7:47 3/28/2024 14:09	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH SMITH SMITH	Plumbing Plumbing Welding Asbestos Electrical Electrical Electrical Electrical Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-021223 Z1-015755 Z1-006815 Z1-000787	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating property Lights need replacing in MEP Warehouse Room 110. Lights aren't operating properly one set on other two not Two ballasts fixtures need replace. Plate cover for light switch in the closet	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/23/2024 7:47 3/28/2024 14:09 2/9/2024 8:20 5/17/2024 14:26	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH SMITH SMITH SMITH CHALK	Plumbing Plumbing Welding Asbestos Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-021223 Z1-015755 Z1-006815 Z1-000787 WO1010789	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating properly Lights need replacing in MEP Warehouse Room 110. Lights aren't operating properly one set on other two not Two ballasts fixtures need replace. Plate cover for light switch in the closet 2 out 2 in front, 3 on left side, 2 at the back, all on right side please send someone out to fix/place bulbs Thanks hortage. Lights where replaced, however none would come on. We need the issue fixed for safety precautions. Exterior Building.	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/23/2024 7:47 3/28/2024 14:09 2/9/2024 8:20 5/17/2024 14:26 10/8/2024 13:57	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH SMITH SMITH CHALK CHALK	Plumbing Plumbing Welding Asbestos Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Fire Sprinkler System	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-021223 Z1-015755 Z1-006815 Z1-000787 WO1010789 Z1-036645	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating property Lights need replacing in MEP Warehouse Room 110. Lights aren't operating property one set on other two not Two ballasts fixtures need replace. Plate cover for light switch in the closet 2 out 2 in front, 3 on left side, 2 at the back, all on right side please send someone out to fix/place bulbs Thanks hortage. Lights where replaced, however none would come on. We need the issue fixed for safety precautions. Exterior Building. On and off handle/knob needs to be replaced it's broken into pieces	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/23/2024 7:47 3/28/2024 14:09 2/9/2024 8:20 5/17/2024 14:26	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH SMITH SMITH SMITH CHALK	Plumbing Plumbing Welding Asbestos Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-021223 Z1-015755 Z1-006815 Z1-000787 WO1010789	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating property Lights need replacing in MEP Warehouse Room 110. Lights aren't operating properly one set on other two not Two ballasts fixtures need replace. Plate cover for light switch in the closet out 2 in front, 3 on left side, 2 at the back, all on right side please send someone out to fix/place bulbs Thanks hortage. Lights where replaced, however none would come on. We need the issue fixed for safety precautions. Exterior Building. On and off handle/knob needs to be replaced it's broken into pieces Classroom tempting at 65 degrees	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/33/2024 7:47 3/28/2024 14:09 2/9/2024 8:20 5/17/2024 14:26 10/8/2024 13:57 12/2/2024 9:32	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH SMITH CHALK CHALK WILLIAMS	Plumbing Plumbing Welding Asbestos Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-021223 Z1-015755 Z1-006815 Z1-000787 WO1010789 Z1-036645 Z1-042352	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating property Lights need replacing in MEP Warehouse Room 110. Lights aren't operating property one set on other two not Two ballasts fixtures need replace. Plate cover for light switch in the closet 2 out 2 in front, 3 on left side, 2 at the back, all on right side please send someone out to fix/place bulbs Thanks hortage. Lights where replaced, however none would come on. We need the issue fixed for safety precautions. Exterior Building. On and off handle/knob needs to be replaced it's broken into pieces	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/23/2024 7:47 3/28/2024 14:09 2/9/2024 8:20 5/17/2024 13:57 12/2/2024 9:32 12/3/2024 7:34	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH SMITH SMITH CHALK CHALK WILLIAMS MORRIS	Plumbing Plumbing Welding Asbestos Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-021223 Z1-015755 Z1-006815 Z1-000787 W01010789 Z1-036645 Z1-042352 Z1-042696	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating properly Lights need replacing in MEP Warehouse Room 110. Lights aren't operating properly one set on other two not Two ballasts fixtures need replace. Plate cover for light switch in the closet out 2 in front, 3 on left side, 2 at the back, all on right side please send someone out to fix/place bulbs Thanks hortage. Lights where replaced, however none would come on. We need the issue fixed for safety precautions. Exterior Building. On and off handle/knob needs to be replaced it's broken into pieces Classroom tempting at 65 degrees Key cylinder in lock set.	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/23/2024 7:47 3/28/2024 14:09 2/9/2024 8:20 5/17/2024 14:26 10/8/2024 13:57 12/2/2024 9:32 12/3/2024 7:34 9/25/2024 10:14	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH CHALK CHALK WILLIAMS MORRIS MALONE	Plumbing Plumbing Welding Asbestos Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock Key & Lock	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-006815 Z1-000787 WO1010789 Z1-036645 Z1-042352 Z1-042696 Z1-042696 Z1-034634	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating properly Lights need replacing in MEP Warehouse Room 110. Lights aren't operating properly one set on other two not Two ballasts fixtures need replace. Plate cover for light switch in the closet out 2 in front, 3 on left side, 2 at the back, all on right side please send someone out to fix/place bulbs Thanks hortage. Lights where replaced, however none would come on. We need the issue fixed for safety precautions. Exterior Building. On and off handle/knob needs to be replaced it's broken into pieces Classroom tempting at 65 degrees Key cylinder in lock set. We are in need of two emergency A keys via Principal Dixon	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/23/2024 7:47 3/28/2024 14:09 2/9/2024 8:20 5/17/2024 14:26 10/8/2024 13:57 12/2/2024 9:32 12/3/2024 7:34 9/25/2024 10:14 8/15/2024 8:41	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH SMITH CHALK CHALK WILLIAMS MORRIS MALONE SMITH	Plumbing Plumbing Welding Asbestos Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-021223 Z1-015755 Z1-006815 Z1-000787 WO1010789 Z1-036645 Z1-042352 Z1-042696 Z1-042696 Z1-034634 Z1-027693	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating property Lights need replacing in MEP Warehouse Room 110. Lights aren't operating properly one set on other two not Two ballasts fixtures need replace. Plate cover for light switch in the closet out 2 in front, 3 on left side, 2 at the back, all on right side please send someone out to fix/place bulbs Thanks hortage. Lights where replaced, however none would come on. We need the issue fixed for safety precautions. Exterior Building. On and off handle/knob needs to be replaced it's broken into pieces Classroom tempting at 65 degrees Key cylinder in lock set. We are in need of two emergency A keys via Principal Dixon Requesting a bldg key that's opens all the classrooms	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/23/2024 7:47 3/28/2024 14:09 2/9/2024 8:20 5/17/2024 14:26 10/8/2024 13:57 12/2/2024 9:32 12/3/2024 7:34 9/25/2024 10:14	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH CHALK CHALK WILLIAMS MORRIS MALONE	Plumbing Plumbing Welding Asbestos Electrical Fire Sprinkler System Heating/Ventilation/Air Conditioning Key & Lock Key & Lock	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-006815 Z1-000787 WO1010789 Z1-036645 Z1-042352 Z1-042696 Z1-042696 Z1-034634	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating properly Lights need replacing in MEP Warehouse Room 110. Lights aren't operating properly one set on other two not Two ballasts fixtures need replace. Plate cover for light switch in the closet out 2 in front, 3 on left side, 2 at the back, all on right side please send someone out to fix/place bulbs Thanks hortage. Lights where replaced, however none would come on. We need the issue fixed for safety precautions. Exterior Building. On and off handle/knob needs to be replaced it's broken into pieces Classroom tempting at 65 degrees Key cylinder in lock set. We are in need of two emergency A keys via Principal Dixon	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/23/2024 7:47 3/28/2024 14:09 2/9/2024 8:20 5/17/2024 14:26 10/8/2024 13:57 12/2/2024 9:32 12/3/2024 7:34 9/25/2024 10:14 8/15/2024 8:41	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH SMITH CHALK CHALK WILLIAMS MORRIS MALONE SMITH	Plumbing Plumbing Welding Asbestos Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-021223 Z1-015755 Z1-006815 Z1-000787 WO1010789 Z1-036645 Z1-042352 Z1-042696 Z1-042696 Z1-034634 Z1-027693	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating properly Lights ned replacing in MEP Warehouse Room 110. Lights aren't operating properly one set on other two not Two ballasts fixtures need replace. Plate cover for light switch in the closet out 2 in front, 3 on left side, 2 at the back, all on right side please send someone out to fix/place bulbs Thanks hortage. Lights where replaced, however none would come on. We need the issue fixed for safety precautions. Exterior Building. On and off handle/knob needs to be replaced it's broken into pieces Classroom tempting at 65 degrees Key cylinder in lock set. We are in need of two emergency A keys via Principal Dixon Requesting a bldg key that's opens all the classrooms Broken key off in the door	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/23/2024 7:47 3/28/2024 14:09 2/9/2024 8:20 5/17/2024 14:26 10/8/2024 13:57 12/2/2024 9:32 12/3/2024 7:34 9/25/2024 10:14 8/15/2024 8:41	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH SMITH CHALK CHALK WILLIAMS MORRIS MALONE SMITH	Plumbing Plumbing Welding Asbestos Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-021223 Z1-015755 Z1-006815 Z1-000787 WO1010789 Z1-036645 Z1-042352 Z1-042696 Z1-042696 Z1-034634 Z1-027693	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating property Lights need replacing in MEP Warehouse Room 110. Lights aren't operating properly one set on other two not Two ballasts fixtures need replace. Plate cover for light switch in the closet out 2 in front, 3 on left side, 2 at the back, all on right side please send someone out to fix/place bulbs Thanks hortage. Lights where replaced, however none would come on. We need the issue fixed for safety precautions. Exterior Building. On and off handle/knob needs to be replaced it's broken into pieces Classroom tempting at 65 degrees Key cylinder in lock set. We are in need of two emergency A keys via Principal Dixon Requesting a bldg key that's opens all the classrooms	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/23/2024 7:47 3/28/2024 14:09 2/9/2024 8:20 5/17/2024 14:26 10/8/2024 13:57 12/2/2024 9:32 12/3/2024 7:34 9/25/2024 10:14 8/15/2024 8:41	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH SMITH CHALK CHALK WILLIAMS MORRIS MALONE SMITH	Plumbing Plumbing Welding Asbestos Electrical	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-021223 Z1-015755 Z1-006815 Z1-000787 WO1010789 Z1-036645 Z1-042352 Z1-042696 Z1-042696 Z1-034634 Z1-027693	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating properly Lights ned replacing in MEP Warehouse Room 110. Lights aren't operating properly one set on other two not Two ballasts fixtures need replace. Plate cover for light switch in the closet out 2 in front, 3 on left side, 2 at the back, all on right side please send someone out to fix/place bulbs Thanks hortage. Lights where replaced, however none would come on. We need the issue fixed for safety precautions. Exterior Building. On and off handle/knob needs to be replaced it's broken into pieces Classroom tempting at 65 degrees Key cylinder in lock set. We are in need of two emergency A keys via Principal Dixon Requesting a bldg key that's opens all the classrooms Broken key off in the door	
Treadwell Middle School Treadwell Middle School Treadwell Middle School Treadwell Middle School Trezevant Career & Technology Center	11/21/2024 11:26 6/8/2024 8:57 12/3/2024 14:19 12/15/2024 19:22 12/5/2024 12:01 11/21/2024 10:53 10/8/2024 6:16 7/15/2024 11:26 5/23/2024 7:47 3/28/2024 14:09 2/9/2024 8:20 5/17/2024 14:26 10/8/2024 13:57 12/2/2024 9:32 12/3/2024 7:34 9/25/2024 10:14 8/15/2024 8:41 3/8/2024 7:07	SEMLER WILSON STAFFORD LANE SMITH SMITH SMITH SMITH SMITH CHALK CHALK WILLIAMS MORRIS MALONE SMITH SMITH	Plumbing Plumbing Welding Asbestos Electrical Electrica	Z2-041940 Z2-017770 Z2-043033 Z1-044949 Z1-043605 Z1-041917 Z1-036545 Z1-006815 Z1-000787 WO1010789 Z1-036645 Z1-042352 Z1-042696 Z1-034634 Z1-027693 Z1-004547	painted. Please replace broken spigot prep bottle fillers for inspections Please inspect/repair rollup door. used fluorescent bulb pick up Wall socket not operating Lights not operating properly Lights ned replacing in MEP Warehouse Room 110. Lights aren't operating properly one set on other two not Two ballasts fixtures need replace. Plate cover for light switch in the closet out 2 in front, 3 on left side, 2 at the back, all on right side please send someone out to fix/place bulbs Thanks hortage. Lights where replaced, however none would come on. We need the issue fixed for safety precautions. Exterior Building. On and off handle/knob needs to be replaced it's broken into pieces Classroom tempting at 65 degrees Key cylinder in lock set. We are in need of two emergency A keys via Principal Dixon Requesting a bldg key that's opens all the classrooms Broken key off in the door	

Trezevant Career & Technology Center	8/5/2024 12:54	BURCHETT	Painting	Z1-025306	Can I get a color match to my bldg so I can do touch ups around the school
Trezevant Career & Technology Center	9/19/2024 10:28		Plumbing	Z1-033691	Pilots need to be lit
					Mount bears logo over scoreboards.
Trezevant High	9/6/2024 12:17	RUSSELL	Carpentry	Z1-031332	
			. ,		Put banners back up over basketball court.
Trezevant High	9/6/2024 12:11	RUSSELL	Carpentry	Z1-031329	·
Trezevant High	6/5/2024 13:40	HOODELL	Carpentry	Z1-017371	Escape window need to be put in correctly.
· ·					· · · · · · · · · · · · · · · · · · ·
Trezevant High	6/5/2024 13:37		Carpentry	Z1-017369	Need escape emergency window replaced.
					Need brighter lighting inside Auditorium.
Trezevant High	12/12/2024 8:40	SMITH	Electrical	Z1-044566	
					Need to ballast replace in fixtures.
Trezevant High	12/9/2024 9:44	SMITH	Electrical	Z1-044006	
					Two light fixtures need ballast replace.
Trezevant High	12/4/2024 13:24	SMITH	Electrical	Z1-043384	·
					RECEPTACLE IN RM 141 - IT'S IN THE FLOOR BESIDE A HVAC UNIT WHICH IS LEAKING -
					NEEDS TO BE REMOVED AND COVERED UP PM/NOLEN 416-3760
Tropougnt High	10/1/2024 10:22	SMITH	Floatrical	71 025000	NEEDS TO BE REPTOVED AND COVERED OF THINOEEN 410-5700
Trezevant High	10/1/2024 10:23	SMITH	Electrical	Z1-035688	
					Bad ballasts and bad circuit breaker panel need to be replaced.
Trezevant High	9/6/2024 12:30	SMITH	Electrical	Z1-031340	
					Bad lights and ballasts over Basketball court need replaced.
Trezevant High	9/6/2024 12:23	SMITH	Electrical	Z1-031336	
Trezevant High	4/22/2024 7:20	SMITH	Electrical	Z1-010801	Repair empty slots in electrical panel box.
Trezevant High	4/16/2024 13:55	SMITH	Electrical	Z1-009683	Exit sign need replace.
Trozovani ringii	-17 10/2024 10/00	0	Liberiout	21 000000	Exit light 64 out.
Townson & Disch	4/40/000440-54	CMITH	Florida	74 000000	Exit tight 04 out.
Trezevant High	4/16/2024 13:51	SMITH	Electrical	Z1-009682	E NO. 4
					Exit light
Trezevant High	4/16/2024 13:48	SMITH	Electrical	Z1-009679	
Trezevant High	12/13/2024 10:05	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044868	Rooftop unit not heating
					HEATING UNIT IN THE ASSIST PRIN OFC - LEAKING BAD PM/NOLEN 416-3760
Trezevant High	12/6/2024 9:19	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-043761	
			0 1 1 1 1 1 1 1 1		HEATING UNIT IN RM 242 - LEAKING AND NOT HEATING - PM/NOLEN 416-3760
Trezevant High	12/5/2024 9:11	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-043502	TIE MINO OTHER WITH EAST CONTROL TO THE MINO THE MODEL WATER OF SOME
riezevant riigii	12/3/2024 9.11	WILLIAMS	Heating/Ventilation/All Conditioning	21-043302	HEATING UNIT IN RM 277 - NOT HEATING - PM/NOLEN 416-3760
					HEATING UNIT IN KM 2// - NOT HEATING - PM/NOLEN 416-3/60
Trezevant High	12/5/2024 9:10	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-043501	
					HEATING UNIT IN RM 272 - NOT HEATING - PM/NOLEN 416-3760
Trezevant High	12/5/2024 9:10	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-043500	
					HEATING UNIT IN RM 278 - NOT HEATING - PM/NOLEN 416-3760
Trezevant High	12/5/2024 9:09	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-043498	
_					HEATING UNIT IN RM 243 - NOT HEATING - PM/NOLEN 416-3760
Trezevant High	12/5/2024 9:09	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-043497	
rrezevantriign	12/0/2024 0.00	WILLIAM	ricating ventuation/air Contactoning	21 040407	HEATING UNIT IN RM 230 - NOT HEATING - PM/NOLEN 416-3760
					REALING UNIT IN KM 230 - NOT REALING - PM/NOLEN 410-3/00
Trezevant High	12/5/2024 9:08	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-043495	
					HEATING UNIT IN RM 231 - NOT HEATING - PM/NOLEN 416-3760
Trezevant High	12/5/2024 9:07	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-043494	
					HEATING UNIT IN RM 237 - NOT HEATING - PM/NOLEN 416-3760
Trezevant High	12/5/2024 9:06	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-043492	
					RTU - MAIN OFC - ENERGY MNGT IS SHOWING TXCM FAILURE - NOT COOLING PM/NOLEN
					416-3760
Trezevant High	10/15/2024 9:21	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-037011	410 07 00
· ·	8/7/2024 15:32	WILLIAMS		Z1-03/011 Z1-026185	Need air condition install inside window.
Trezevant High	8///2024 15:32	WILLIAMS	Heating/Ventilation/Air Conditioning	21-026185	Need air condition install inside window.
					Plant Manager Nolen reported the ac unit in room 186 is blowing warm air. 416-9930.
Trezevant High	7/18/2024 15:12	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-021731	
					Keys needed Two (2) Admin. Sets, Five (5) AC2, Room 236, Attendance (2) SA9, Guidance -
					(2) SA1, and Gym locker room Boy and Girls (2) two of each.
Trezevant High	10/3/2024 11:38	MALONE	Key & Lock	Z1-036101	
			, 2 222		Need door lock replaced.
Trezevant High	9/10/2024 11:06	SMITH	Key & Lock	Z1-031745	ivecu uooi tock ieptaceu.
=			-		
Trezevant High	4/23/2024 14:50	SMITH	Key & Lock	Z1-011130	Need new lock on door or replace.
Trezevant High	2/13/2024 9:40	SMITH	Key & Lock	Z1-001157	Need key cylinder install.
					Two showers' areas need bricks replace in wall.
Trezevant High	9/10/2024 13:21	BURCHETT	Masonry	Z1-031789	
					Need hallway walls painted same colors.
Trezevant High	10/23/2024 8:23	BURCHETT	Painting	Z1-037920	

		BUBBUTT.		74 000400	Office C need room painted half purple and half bone or off white.
Trezevant High	10/3/2024 14:17	BURCHETT	Painting	Z1-036163	Assistant principal office pood pointing heirs color
Trezevant High	8/5/2024 18:09	BURCHETT	Painting	Z1-025409	Assistant principal office need painting beige color.
Trezevant High	5/17/2024 14:23	BURCHETT	Painting	WO1005127	Please paint stalls purple and wall white.
Trezevant High	5/17/2024 14:23	BURCHETT	Painting	WO1005127 WO1005130	
•	12/14/2024 11:59	AVANZI	Plumbing	Z1-044939	· · · ·
Trezevant High Trezevant High	12/14/2024 11:59	AVANZI	9	Z1-044939 Z1-044500	First Lav leaking from grid strainer gasket. Water bubbling out of the parking lot ground.
rrezevant nigii	12/11/2024 14.10	AVAINZI	Plumbing	21-044500	Need new shades.
Trozovant High	10/1/2024 9:38	BENTON	Shades/Blinds	Z1-035654	Need flew Strates.
Trezevant High Trezevant High	3/11/2024 9:38	ARNOLD	Sheet Metal	Z1-035654 Z1-004772	Many audience-seats need replaced or fixed.
rrezevant High	3/11/2024 8:21	AKNOLD	Sneet Metal	21-004//2	
Trezevant High	4/12/2024 14:07	SHIPPS	Welding	Z1-009058	Need fence put back in place.
rrezevant nigii	4/12/2024 14.0/	SHIFFS	wetung	21-009058	used fluorescent hulb mistrus
Vollentine Elementary	12/15/2024 19:18	CRUTCHER	Asbestos	Z1-044945	used fluorescent bulb pick up
,					DECLIFERED ACADA ADOLE CARDET DEING DILLED UD AND DEDLACED IN THE MAIN & CIDE OFFICER MEED ACAD THANK YOU CT
Vollentine Elementary	5/17/2024 13:59	BENTON	Carpet Repair	W0992263	
Vollentine Elementary	5/17/2024 13:59 11/15/2024 10:11	BENTON CASEY	Carpet Repair	WO992264 Z1-041049	SHE REQUESTED AGAIN ABOUT CARPET NEEDS TO BE PULLED UP IN LIBRARY OFFICE AREA. NEED ASAP THANK YOU, STL
Vollentine Elementary			Flooring		In need of carpet removal.
Vollentine Elementary	9/17/2024 10:02	CASEY	Flooring	Z1-033139	Requesting the carpet to be removed inside the main office.
					Mr. Anderson (416 4632) Volluntine ES Rm 213 2nd floor Unit blowing air but not blowing
	40/5/0004050	14/500		74 040400	heat
Vollentine Elementary	12/5/2024 8:59	WEBB	Heating/Ventilation/Air Conditioning	Z1-043489	
					Mr. Anderson (416 4632) Volluntine ES Rm 208 2nd floor Unit blowing air but not blowing
Vellentine Florenten	40/5/00040-50	WEDD	Linear and to add to a thing of a single or in a	74 040400	heat
Vollentine Elementary	12/5/2024 8:58	WEBB	Heating/Ventilation/Air Conditioning	Z1-043488	LIFATING UNIT IN DW COS. DI CHUNG NOT LIFATING DW/ANDFDOON 440 4000
Vellentine Florenten	40/0/00047-54	WEDD	Linear and to add to a thing of a single or in a	74 040744	HEATING UNIT IN RM 235 - BLOWING NOT HEATING PM/ANDERSON 416-4662
Vollentine Elementary	12/3/2024 7:51	WEBB	Heating/Ventilation/Air Conditioning	Z1-042711	UESTINO INTERNATIONAL PROGRAMMA NATUESTINO DALLINGTERO DALLING PROGRAMMA
	40/0/000477	14/500		74 040740	HEATING UNIT IN RM 230 - BLOWING NOT HEATING PM/ANDERSON 416-4662
Vollentine Elementary	12/3/2024 7:51	WEBB	Heating/Ventilation/Air Conditioning	Z1-042710	LIFATING LINET IN DW 600. DI CHURIO NOT LIFATING DW/ANDFDOON 440, 4000
Vellentine Florenten	40/0/00047-50	WEDD	Linear and to add to a thing of a single or in a	74 040700	HEATING UNIT IN RM 229 - BLOWING NOT HEATING PM/ANDERSON 416-4662
Vollentine Elementary	12/3/2024 7:50	WEBB	Heating/Ventilation/Air Conditioning	Z1-042709	LIFATING LINET IN DW 600. DI CHURIO NOT LIFATING DW/ANDFDOON 440, 4000
Vellentine Florenten	12/3/2024 7:50	WEBB	Linear and to add to a thing of a single or in a	Z1-042708	HEATING UNIT IN RM 226 - BLOWING NOT HEATING PM/ANDERSON 416-4662
Vollentine Elementary	12/3/2024 /:50	WEBB	Heating/Ventilation/Air Conditioning	21-042/08	
	40/0/0004740			74 0 40707	HEATING UNIT IN RM 225 - BLOWING NOT HEATING PM/ANDERSON 416-4662
Vollentine Elementary	12/3/2024 7:49	WEBB	Heating/Ventilation/Air Conditioning	Z1-042707	HEATING UNIT IN RM 140 - BLOWING NOT HEATING PM/ANDERSON 416-4662
Vallantina Flamenton	12/3/2024 7:49	WEBB	Lingting Montilation / Air Conditioning	Z1-042706	REALING UNIT IN KM 140 - BLOWING NOT REALING PM/ANDERSON 410-4002
Vollentine Elementary	12/3/2024 /.49	VVEDD	Heating/Ventilation/Air Conditioning	21-042/06	UNIT NOT COOLING - MAIN OFFICE AREA
					P/M ANDERSON 416-4632
Vollentine Elementary	10/25/2024 8:09	WEBB	Heating/Ventilation/Air Conditioning	Z1-038301	F/11 AINDENSON 410-4032
vollentine Elementary	10/23/2024 6.09	WEDD	Heating/Verititation/Air Conditioning	21-030301	Anderson, 64632, room not cooling
Vollentine Elementary	9/24/2024 7:53	WEBB	Heating/Ventilation/Air Conditioning	Z1-034352	Anderson, 64632, fourn not cooling
Vollentine Elementary	11/22/2024 7:10	MALONE	Key & Lock	Z1-034332 Z1-042003	Teacher's desk needs to be rekeyed
Vollentine Elementary	8/28/2024 10:46	SMITH	Key & Lock	Z1-042003 Z1-030039	In need of all exterior door keys. Thank you
Vollentine Elementary	11/20/2024 9:32	BURCHETT	Painting	Z1-030039 Z1-041660	In need of painting to wall damaged from moisture.
vollentine Elementary	11/20/2024 5.32	BUNCHETT	Failting	21-041000	please paint stall door in the shop for Curtis Russell.
Vollentine Elementary	9/25/2024 14:36	BURCHETT	Painting	Z1-034764	prease paint state door in the shop for Gurus hussett.
vollentine Elementary	9/25/2024 14.30	BUNCHETT	Failting	21-034/04	Bottle filler inspections
Vollentine Elementary	5/3/2024 7:51	WILSON	Plumbing	Z1-012905	bottle inter inspections
Wells Station Elementary	12/9/2024 8:07	POWELL	Electrical	Z2-043946	Wall sockets aren't working
Wells Station Elementary	12/5/2024 9:17	POWELL	Electrical	Z2-043546 Z2-043506	sockets aren't working I have tried breaker switches and still no power for certain sockets in rooms
wells Station Elementary	12/3/2024 9.1/	FOWELL	Electricat	22-043300	PARTIAL POWER OUTAGE - ONLY ON THE 2ND FLR PM/WOODS 416-2172
Wolle Station Flomentany	12/3/2024 6:54	POWELL	Electrical	Z2-042673	PARTIAL FOWER COURSE CONTINUE AND FEMALES AT 10-21/2
Wells Station Elementary Wells Station Elementary	12/3/2024 6:54	POWELL	Electrical	Z2-042673 Z2-040017	Wall socket has no power
,					·
Wells Station Elementary Wells Station Elementary	11/7/2024 8:09 9/10/2024 11:27	POWELL POWELL	Electrical Electrical	Z2-040007 Z2-031755	Wall electrical socket has no power Blown light ballast
Wells Station Elementary	8/13/2024 10:44	POWELL	Electrical	Z2-031755 Z2-027259	Please replace ballast in light fixture. Thanks
Wells Station Elementary	8/7/2024 9:55	POWELL	Electrical	Z2-027259 Z2-025988	lace ballast of 10 light fixtures in the hallway and restrooms 1st and 2nd floor annex building. Thank you
Wells Station Elementary	7/31/2024 11:53	POWELL	Electrical	Z2-025988 Z2-024100	Light are blinking please replace the ballast
· ·	5/22/2024 11:53	POWELL	Electrical	Z2-024100 Z2-015726	
Wells Station Elementary	3/22/2024 13.0/	POWELL	Electricat	22-013/26	Please repair wall repetacle wire is expose this a hazardous to the students replace missing plate cover
Wells Station Elementary	4/17/2024 12:48	POWELL	Electrical	Z2-009956	replace missing place cover
Wells Station Elementary	4/12/2024 7:53	POWELL	Electrical	Z2-009956 Z2-008960	Replace exit sign it is not working
Wells Station Elementary	3/12/2024 7:53	POWELL	Electrical	Z2-008960 Z2-004884	Please repair the 3 lights with bad ballast
. rous outron Elementary	0/12/2024 3.23	IOWELL	Licetificat	22 004004	r touse repair the oragins man bad battast

Wells Station Elementary	3/5/2024 8:23	POWELL	Electrical	Z2-003894	There are 2 lights out please repair the ballast
Wells Station Elementary	3/5/2024 8:23	POWELL	Electrical	Z2-003894	There are 2 lights out please repair the ballast
					Please repair the ballast in light.
Wells Station Elementary	3/5/2024 8:20	POWELL	Electrical	Z2-003893	
Wells Station Elementary	12/13/2024 13:25		Energy Management System	Z2-044915	State inspector said the room needs a "ESTOP" (Emergency stop) button installed
Wells Station Elementary	5/17/2024 14:20	Contractor	Fire Alarm System	WO1003160	POCA Need portable buildings tied into fire alarm system.
Wells Station Elementary	9/4/2024 12:34	Coleman	Fire Extinguishers	Z2-030925	Need 5 new fire extinguishers for the 3rd grade hall upstairs and downstairs
			0		Repair Leak in 3" Pipe in Hallway and install new 15-gallon air compressor.
					Return dry pipe system to service once repairs are complete.
Wells Station Elementary	11/20/2024 8:02	Coleman	Fire Sprinkler System	Z2-041616	
Wells Station Elementary	5/17/2024 14:18	LEWIS	Flooring	WO1001143	Please repair stage floor it has buckle uo due to water damage.
Wells Station Elementary	12/12/2024 8:09	WILSON	Heating/Ventilation/Air Conditioning	Z2-044542	Rooms are still blowing cold air and heat is on
Wells Station Elementary	12/4/2024 12:38	WILSON	Heating/Ventilation/Air Conditioning	Z2-043367	Classroom is cold and Thermostat reading 67 degrees inside classroom
Wells Station Elementary	9/11/2024 11:31	WILSON	Heating/Ventilation/Air Conditioning	Z2-031995	rom Gibson have said both rooms #108, and 114 have broken actuators and rooms are both reading over 77°
Wells Station Elementary	10/15/2024 13:07	MALONE	Key & Lock	Z2-037074	Principal requested for a copy of the GM2 key for annex building
Wells Station Elementary	9/12/2024 10:40	SMITH	Key & Lock	Z2-032227	cipal has requested for both doors that lead to her office have locks changed and new set of keys
Wells Station Elementary	9/13/2024 11:28	BURCHETT	Painting	Z2-032227 Z2-032672	Classroom has peeling and chipped paint all throughout classroom
Wells Station Elementary	9/4/2024 9:55	BURCHETT	Painting	Z2-032072 Z2-030856	ested that the walls be repainted for 3rd grade hall upstairs and downstairs the paint is peeling off the walls
wells Station Elementary	5/4/2024 5.55	BUNCHETT	Failiulig	22-030630	Pipe leaking in ceiling
Wells Station Elementary	9/10/2024 10:06	PILKINGTON	Dismining	Z2-031709	Fipe teaking in Ceiting
,			Plumbing		Look in coiling
Wells Station Elementary	11/7/2024 8:14 9/30/2024 14:44	STEVENS STEVENS	Roofing	Z2-040012 Z2-035537	Leak in ceiling
Wells Station Elementary	9/30/2024 14.44	STEVENS	Roofing	22-035537	Leak in ceiling
	0/0/0004.004			70.004507	install vent for new water heater
Wells Station Elementary	8/2/2024 6:21	WHITE	Sheet Metal	Z2-024597	
	10/0/000115 00	50.005		7	Requesting a carpenter to add tiles inside walk in freezer at Westhaven Elem
Westhaven Elementary	10/2/2024 15:38	FINNIE	Carpentry	Z4-035966	
Westhaven Elementary	11/19/2024 13:13	HALL	Electrical	Z4-041530	LED light strip out in kitchen janitorial closet.
Westhaven Elementary	9/4/2024 8:38	HALL	Electrical	Z4-030807	LED light needs to be replaced in the serving line
Westhaven Elementary	4/29/2024 14:16	LEWIS	Flooring	Z4-012081	Replace floor tiles middle of the floor and the locker's
					Generator has Alarm ringing
					"SD Throttle Stuck"
Westhaven Elementary	4/16/2024 8:20	CALDWELL	Generators	Z4-009488	
					UNIT NOT HEATING - CL-RM C86
					P/M XAVIER COATES 416-8740
Westhaven Elementary	12/4/2024 7:40	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043107	
					UNIT NOT HEATING - CL-RM B68
					P/M XAVIER COATES 416-8740
Westhaven Elementary	12/4/2024 7:39	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043104	
					UNIT NOT HEATING - CL-RM B55
					P/M XAVIER COATES 416-8740
Westhaven Elementary	12/4/2024 7:38	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043102	
					UNIT NOT HEATING - CL-RM B54
					P/M XAVIER COATES 416-8740
Westhaven Elementary	12/4/2024 7:37	DOWNER	Heating/Ventilation/Air Conditioning	Z4-043101	
Westhaven Elementary	11/25/2024 7:42	MALONE	Key & Lock	Z4-042143	Classroom C86 has a spinning key cylinder, please advise.
Westhaven Elementary	11/19/2024 13:30	MALONE	Key & Lock	Z4-041542	Door on cafeteria hallway needs a new cylinder. Please advise.
Westhaven Elementary	6/14/2024 9:27	BURCHETT	Painting	Z4-018373	Paint peeling under window
Westhaven Elementary	6/14/2024 9:17	BURCHETT	Painting	Z4-018369	Paint peeling under window and back wall baseboard
Westhaven Elementary	6/14/2024 9:00	BURCHETT	Painting	Z4-018365	Paint peeling under emergency window
Westhaven Elementary	6/14/2024 8:58	BURCHETT	Painting	Z4-018364	Paint peeling under emergency window first floor
Westhaven Elementary	5/29/2024 15:15	BURCHETT	Painting	Z4-016348	Paint peeling by the window
Westhaven Elementary	5/29/2024 12:18	BURCHETT	Painting	Z4-016319	Paint peeling under the window
Westhaven Elementary	5/29/2024 10:13	BURCHETT	Painting	Z4-016277	Principal wants all classroom doors painted black
Westhaven Elementary	5/28/2024 13:32	BURCHETT	Painting	Z4-016144	Paint the trimming round the door frames. And classrooms
Westhaven Elementary	5/22/2024 13:56	BURCHETT	Painting	Z4-015706	Paint under the Emergency window
Westhaven Elementary	5/22/2024 11:58	BURCHETT	Painting	Z4-015665	Paint under window
Westhaven Elementary	5/22/2024 11:54	BURCHETT	Painting	Z4-015663	The walls need to be painted by the windows
Westhaven Elementary	5/22/2024 11:51	BURCHETT	Painting	Z4-015661	The walls need to be painted
Westhaven Elementary	9/9/2024 7:29	HARRIS	Plumbing	Z4-031428	
•			-		
					WH (music room), OHM (rm125), CHS (weight room), Sher MD (rm 105), Levi (rm 4A)
Westhaven Elementary	11/20/2024 8:10	SMITH	Sheet Metal	Z4-041622	
,					

					leatell amount sailing tile in the kitchen that are missing
Westside Elementary	8/7/2024 7:06	RUSSELL	Carpentry	Z1-025846	Install gypsum ceiling tile in the kitchen that are missing.
,			,		please repair the floor tile in room 109
Westside Elementary	6/27/2024 7:52	JOHNSON	Carpentry	Z1-019585	
Westside Elementary	10/25/2024 13:02	SMITH	Electrical	Z1-038379	Please repair the lights in the cafeteria
Westside Elementary	10/25/2024 13:00	SMITH	Electrical	Z1-038377	Please repair the lights in room 130 has blown ballasts
					please repair the lights in the front and back of the building. We don't have lights in the front or back. It is pitch black and staff members do not feel safe at night leaving campus.
Westside Elementary	9/20/2024 9:09	SMITH	Electrical	Z1-033926	
		014771	· · ·	74 000044	blown ballast in room 130
Westside Elementary	9/18/2024 7:40	SMITH	Electrical	Z1-033344	please repair blown ballast in classroom 109
Westside Elementary	7/25/2024 13:53	SMITH	Electrical	Z1-022678	predict repair blown ballast in causiforn 200
					please repair blown ballast in classroom 114
Westside Elementary	7/25/2024 13:49	SMITH	Electrical	Z1-022671	alessa saraia blava ballastia alessa sara 440
Westside Elementary	7/25/2024 13:47	SMITH	Electrical	Z1-022668	please repair blown ballast in classroom 110
Westside Elementary	772072024 10.47	OI IIIII	Licetricut	21 022000	please repair blown ballast in the room 101
Westside Elementary	7/25/2024 13:09	SIMMONS	Elevators	Z1-022635	
					Ms Christian (9484) Heat isnt blowing out. Unit only blows cool air
Westside Elementary	12/13/2024 8:44	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044842	Ms Christian (9484) Heat isnt blowing out. Unit only blows cool air
Westside Elementary	12/13/2024 8:43	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-044841	ris Cinistian (9404) neat isnt blowing out. One only blows cool an
,					Ms. Christian 69484 not blowing heat
Westside Elementary	12/3/2024 14:16	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-043031	
Manadala Flancanton	40/0/000440-57	CIMMONIC	Lie skip of Armatilaki an (Ain Occadisi ani an	74 040005	HEATING UNIT IN RM 141 - BLOWING NOT HEATING PM/CHRISTAN 416-9484
Westside Elementary	12/3/2024 13:57	SIMMONS	Heating/Ventilation/Air Conditioning	Z1-043025	HEATING UNIT IN RM 140 - BLOWING NOT HEATING PM/CHRISTAN 416-9484
Westside Elementary	12/3/2024 13:57	SIMMONS	Heating/Ventilation/Air Conditioning	Z1-043022	TEATHORN THE PERMITTER SECTION OF THE PERMITTE
	40/0/000444			74 040400	Phyllis Christian (3100) Units(2) not heating Westside ES Teachers Lounge Rm131
Westside Elementary	12/2/2024 11:06	SIMMONS	Heating/Ventilation/Air Conditioning	Z1-042466	
					HVAC UNIT FOR THE MAIN OFC - BLOWING NOT HEATING PM/CHRISTIN 416-9484
Westside Elementary	11/22/2024 8:15	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-042018	
					Plant Manager Christian reported the Coil is busted in the cafeteria. 416-3137.
Westside Elementary	6/24/2024 11:07	WILLIAMS	Heating/Ventilation/Air Conditioning	Z1-019190	And the distriction of the delication of the del
Westside Elementary	5/17/2024 14:24 10/24/2024 11:52	CORONADO BURCHETT	Masonry Painting	WO1007389 Z1-038203	0, 1, 0
Westside Elementary	10/24/2024 11.52	BURCHETT	Painting	21-036203	Paint 1st floor hallway and steps of the 2 story building (Blue paint) please paint the doors and door closure and ramp on 1st floor
Westside Elementary	7/8/2024 14:19	DIXON	Painting	Z1-020463	please paint the doors and door closure and ramp on 1st toor
Westside Elementary	77072024 14.19	DIXON	Faillung	21-020403	please painting lines on the front parking lot
Westside Elementary	6/28/2024 15:04	BURCHETT	Painting	Z1-019802	produce paritaing arrow on the none paritaing for
Westwood High	10/4/2024 10:18	AMOS	Asbestos	Z4-036271	In this room the floor tiles needs to be replaced
Westwood High	12/12/2024 14:42	TEDDER	Carpentry	Z4-044779	The camera in the Votech special cut
Westwood High	12/6/2024 14:27	HALL	Carpentry	Z4-043876	It's a fan in the elevator needs to cover over it
Westwood High	10/8/2024 9:15	TEDDER	Carpentry	Z4-036593	4 boxes of shades and blinds
					Broke window in room 114
Westwood High	8/22/2024 11:27	FINNIE	Carpentry	Z4-029124	
Montuned High	8/19/2024 13:59	ARNOLD	Comentn	Z4-028441	Vocational building room number 4 door handle doesn't lock at all
Westwood High	8/19/2024 13:59	AKNOLD	Carpentry	24-028441	RECEPTACLE ON THE OUTSIDE IN FRONT OF BLDG - WHERE SECURITY CHECK POINT NOT
					WORKING PM/MOSLEY 416-8000
Westwood High	12/16/2024 7:29	HALL	Electrical	Z4-044966	
Westwood High	12/12/2024 10:31	HALL	Electrical	Z4-044687	The library needs a new receptacle outside of the librarian office
Westwood High	12/8/2024 13:51	HALL	Electrical	Z4-043906	Room 123 has two lights out, need balances in them
Westwood High	12/6/2024 14:26	HALL	Electrical	Z4-043873	The Elevator have to lights out
Westwood High	12/6/2024 13:39	HALL	Electrical	Z4-043858	Room 107 have a set of lights out needs a balance in it
Westwood High	12/5/2024 13:34	HALL	Electrical	Z4-043654	Room 118 2 sets of lights out needs balances in them
Westwood High	12/4/2024 10:43	HALL	Electrical	Z4-043294	The elevator has two lights out, needs to be replaced
Westwood High	12/3/2024 7:37	HALL	Electrical	Z4-042701	The Bose basketball team locker room outlet is out
Westwood High	12/2/2024 14:39	HALL	Electrical	Z4-042602	An outlet in the boys locker room needs to be fixed for their television
Westwood High	12/2/2024 7:26		Electrical	Z4-042222	d the corner from the band room have Two more sets of lights out, need balances in the back of the mechanical room

Westwood High Westwood High Westwood High Westwood High	11/25/2024 9:54 11/25/2024 9:05 11/22/2024 13:21 11/21/2024 10:39	HALL HALL HALL HALL	Electrical Electrical Electrical Electrical	Z4-042170 Z4-042162 Z4-042090 Z4-041912	ROTC building gun range have to sets of lights out needs a balance in them The classroom and ROTC building two lights are out need balances in them Clothing management room closet have a set of lights out needs a balance in it Band room closet have one set of lights out needs a balance in them A set of lights that was never put up in the back of the building, and a lot of wires are hanging
					for cameras and lights that was never finished
Westwood High	11/21/2024 8:50	HALL	Electrical	Z4-041862	It 4lights out in this room needs a balance in them
Westwood High	11/5/2024 9:02	HALL	Electrical	Z4-039566	it sugnite out in the room needs a saturbe in trem
Westwood High	10/3/2024 12:28	TEDDER	Electrical	Z4-036123	Room 130 electrical box needs some spacers in the box
Westwood High	9/24/2024 9:07	HALL	Electrical	Z4-034419	The exit light is not working by the cafeteria door
Westwood High	9/17/2024 11:42	HALL	Electrical	Z4-033210	It's a light out in the hallway right on the side of the elevator needs a balance
Westwood High	9/9/2024 11:32	HALL	Electrical	Z4-031529	The supply room in the ROTC building have two sets of lights out, need balances in them
Westwood High	9/5/2024 13:29	HALL	Electrical	Z4-031182	The exit sign by the cafeteria isn't lighting up
					It's a set of lights out in the hallway between room 215 and 231
Westwood High	8/28/2024 10:11	HALL	Electrical	Z4-030019	
Westwood High	8/27/2024 10:04	HALL	Electrical	Z4-029793	All the auditorium stage lights are out needs to be replaced
Troctinood riigii	0/2//2024 20:04	111111111111111111111111111111111111111	Eloourout	21 020700	
					Room inside the the library room 212F two set of lights out needs a balance in them
Westwood High	8/27/2024 9:48	HALL	Electrical	Z4-029777	
					It's 12 lights out in the library needs balances in them
Westwood High	8/27/2024 9:44	HALL	Electrical	Z4-029774	
	0.007.0004.0.04		· · ·	7	In the gym it's to sets of lights out needs a balance in them
Westwood High	8/27/2024 9:21	HALL	Electrical	Z4-029766	It's one set of lights out in class room
Westwood High	8/27/2024 9:14	HALL	Electrical	Z4-029764	it's one set of agits out in class room
Westwood riigh	0/2//2024 0.14	TIALL	Electrical	24 020704	Plant Manager Mosely reported there are exposed bare electrical wires in the closet behind
					the cafeteria as the cover is missing. 416-8000.
Westwood High	8/20/2024 7:35	HALL	Electrical	Z4-028509	
	7/05/0004.0.44		- · · ·	7	It's a set of out in the stairwell by room 126 need a balance in it right by the back door exit
Westwood High	7/25/2024 8:41	HALL	Electrical	Z4-022515	the two lights out we high honging aver the gorden needs to be replaced
Westwood High	7/17/2024 8:57	HALL	Electrical	Z4-021496	It's two light's out up high hanging over the garden needs to be replaced
westwood riigii	7/1//2024 0.37	TIALL	Liectricat	24-021430	There are two lights out in the Gymnasium
Westwood High	7/17/2024 8:46	HALL	Electrical	Z4-021494	······································
Westwood High	12/4/2024 11:23	LEWIS	Flooring	Z4-043333	The floor in the stairwell around the corner for my office by the back door needs to be repaired
Westwood High	12/4/2024 10:06	LEWIS	Flooring	Z4-043265	The floor at the end of the hallway in the voltage building needs repairing
Westwood High	11/15/2024 19:26	CASEY	Flooring	Z4-041148	The floor at the of the hall way in the vocational building needs to be repaired
Westwood High	10/31/2024 8:47	CASEY	Flooring	Z4-039023	The second floor stairwell floor needs to be repaired by room 226
Westwood High	10/9/2024 10:43	CASEY	Flooring	Z4-036716	The floor tiles at the double doors going inside the gym needs to be replaced
					mr. everett
					68000
					no heat
					energy management stated all rooms are connected to this one unit
					210
					208
					206
					204
					209
Westwood High	12/12/2024 9:57	MADUNATUM	Heating/Ventilation/Air Conditioning	Z4-044664	
Westwood High	12/11/2024 14:14	MALONE	Key & Lock	Z4-044505	We can't get into room 106. It needs a new key and lock. On this door.
Westwood High	12/9/2024 12:20	MALONE	Key & Lock	Z4-044068	Needs new cylinder cylinder damaged
Westwood High	12/3/2024 8:01	MALONE	Key & Lock	Z4-042720	Room 104 needs a new key and lock
Westwood High	12/2/2024 14:42	MALONE	Key & Lock	Z4-042604	Room 104 needs a new lock and key NEED A KEY MADE TO THE OLD AUTO MECHANIC BUILDING AT WESTWOOD HS
					THE NUMBER ON THE KEY IS 211
					I HAVE THE KEY IF YOU NEED TO SEE BEFORE YOU CUT NEW KEY
Westwood High	5/16/2024 15:31	SMITH	Key & Lock	Z4-014942	
Westwood High	12/10/2024 6:55	BURCHETT	Painting	Z4-044145	nt is chipping in the kitchen area, and it may fall into food in the walk-in area from the serving line
Westwood High	12/4/2024 11:11	BURCHETT	Painting	Z4-043320	Exterior doors in the ROTC building needs to be painted
Westwood High	12/4/2024 11:07	BURCHETT	Painting	Z4-043319	I'll exterior doors in the Votech building needs to be painted
Westwood High	12/4/2024 11:05	BURCHETT	Painting	Z4-043316	All Exterior door in the Gym needs to painted

Westwood High	12/4/2024 11:03	BURCHETT	Painting	Z4-043313	All Exterior doors needs to painted very badly in the building
Westwood High	10/9/2024 14:19	BURCHETT	Painting	Z4-036748	The doors in front of the school needs to be painted
Westwood High	9/30/2024 14:09	BURCHETT	Painting	Z4-035530	All the class rooms and doors needs to be painted
					The 12 Arms that's on the gym front and back needs to be painted
Westwood High	7/30/2024 16:56	BURCHETT	Painting	Z4-023890	
Troctifoda i ligit	77007202-10.00	DOMONETT	- dinting	21 020000	The Guidances counselor want her office painted white
	= /	DUDOUETT.	B 1 41 .	7	The oditionices counselor want her office painted write
Westwood High	7/18/2024 14:26	BURCHETT	Painting	Z4-021724	
Westwood High	12/3/2024 10:58	HARRIS	Plumbing	Z4-042886	The water fountains in the gym is not working
Westwood High	12/2/2024 7:28	HARRIS	Plumbing	Z4-042223	corner from my office is not working properly. I have changed the water filters in the water fountains still not Working properly
Westwood High	10/30/2024 9:21	HARRIS	Plumbing	Z4-038851	The the toilet is leaking from the top of the cylinder I turned the water off on the commode
Westwood High	10/30/2024 9:11	HARRIS	Plumbing	Z4-038848	The girls second stall in the restroom commode will not flush
Westwood High	10/24/2024 13:16	HARRIS	Plumbing	Z4-038229	The sink on the second floor is leaking by room 223
•			<u> </u>		9 /
Westwood High	10/24/2024 13:13	HARRIS	Plumbing	Z4-038227	The girls restroom toilet is leaking on top
Westwood High	10/24/2024 6:47	HARRIS	Plumbing	Z4-038077	The water found, but the auditorium is leaking
Westwood High	10/24/2024 6:46	HARRIS	Plumbing	Z4-038076	The sink is leaking in the women's restroom on the side of the auditorium
Westwood High	10/22/2024 8:02	HARRIS	Plumbing	Z4-037764	The boys restroom across from room 116 a toilet is out of order
Westwood High	9/27/2024 9:38	HARRIS	Plumbing	Z4-035070	The teacher work women's restroom sink is leaking down low from the pipe under the sink
Westwood High	9/11/2024 8:55	HARRIS	Plumbing	Z4-031900	The Girls restroom on the second floor sink pipe is leaking
•			<u> </u>		
Westwood High	11/6/2024 8:22	BENTON	Shades/Blinds	Z4-039719	I need 4 boxes of blinds
White Station Elementary	12/9/2024 8:54	POWELL	Electrical	Z2-043977	Ballast blown out in pantry closet.
White Station Elementary	11/22/2024 7:26	POWELL	Electrical	Z2-042004	Ballast has gone out in teachers Lounge.
White Station Elementary	11/7/2024 14:43	POWELL	Electrical	Z2-040197	There is a ballast blown out.
White Station Elementary	10/7/2024 8:30	POWELL	Electrical	Z2-036387	Ballast has blown out.
,					
White Station Elementary	10/29/2024 14:31	Coleman	Fire Alarm System	Z2-038787	I need a riser room door sign
White Station Elementary	7/30/2024 12:55	Coleman	Fire Extinguishers	Z2-023784	Need stickers for fire extinguishers
					I have a fire extinguisher that isn't labeled properly needs attention also I need a hook to
					mount it.
White Station Elementary	7/15/2024 17:02	Coleman	Fire Extinguishers	Z2-021275	
White Station Elementary	11/20/2024 12:46	Coleman	Fire Sprinkler System	Z2-041755	Repair conduit with wires hanging out and wires not connected. Please also check module .
White oldfor Elementary	11/20/2024 12:40	Ooteman	i ii e opinikier oystem	22 041700	OVERHEATING (94 DEGREES) CL-RM D112
					P/M HARPER 416-8900
White Station Elementary	12/6/2024 8:15	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-043731	
					OVERHEATING (91 DEGREES) CL-RM D111
					P/M HARPER 416-8900
White Station Elementary	12/6/2024 8:14	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-043730	
Time oracion Economically	12/0/2024 0:114	OTTHORE IND	Tiodany Vondidania and Condidaning	22 0 107 00	OVERHEATING (94 DEGREES) CL-RM D110
					P/M HARPER 416-8900
White Station Elementary	12/6/2024 8:13	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-043729	
					OVERHEATING (92 DEGREES) CL-RM D109
					P/M HARPER 416-8900
White Station Elementary	12/6/2024 8:12	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-043728	
White Station Elementary	10/22/2024 11:05	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-037831	a HVAC pipe that has a constant leak that won't stop it's been leaking for sometime needs attention.
White Station Elementary	10/23/2024 10:55	MALONE	Key & Lock	Z2-037983	I need a SKD14 made for this room
White Station Elementary	8/1/2024 13:45	SMITH	Key & Lock	Z2-024530	Need master keys for classrooms hallway
White Station Elementary	7/26/2024 10:08	SMITH	Key & Lock	Z2-022864	Need lock to be changed back to fit master key
White Station Elementary	4/25/2024 10:26	SMITH	Key & Lock	Z2-011486	k on this classroom won't allow the teacher to lock her classroom door can we get this taken care of
White Station Elementary	8/23/2024 15:12	BURCHETT	Masonry	Z2-029340	Tiles need replaced on wall
White Station Elementary	7/15/2024 16:08	BURCHETT	Masonry	Z2-021268	Boys restroom has missing tiles need replacing.
	77107202410.00	DOMONETT			
White Station Elementary	4/11/2024 12:04	CORONADO	Mananni		Hale in wall needs to be repaired and tiles replaced
	4/11/2024 13:04	CORONADO	Masonry	Z2-008867	Hole in wall needs to be repaired and tiles replaced
White Station Elementary	2/15/2024 10:12	CORONADO	Masonry	Z2-008867 Z2-001549	I have tiles missing out the floor in this restroom can we get this taken care of
White Station Elementary White Station Elementary				Z2-008867	
	2/15/2024 10:12	CORONADO	Masonry Painting	Z2-008867 Z2-001549	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling
White Station Elementary White Station Elementary	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23	CORONADO BURCHETT BURCHETT	Masonry Painting Painting	Z2-008867 Z2-001549 Z2-040815 Z2-035451	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling
White Station Elementary White Station Elementary White Station Elementary	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23 8/8/2024 12:15	CORONADO BURCHETT BURCHETT BURCHETT	Masonry Painting Painting Painting	Z2-008867 Z2-001549 Z2-040815 Z2-035451 Z2-026429	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling We need handicap spots repainted again
White Station Elementary White Station Elementary White Station Elementary White Station Elementary	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23 8/8/2024 12:15 5/6/2024 12:20	CORONADO BURCHETT BURCHETT BURCHETT BURCHETT	Masonry Painting Painting Painting Painting	Z2-008867 Z2-001549 Z2-040815 Z2-035451 Z2-026429 Z2-013214	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling We need handicap spots repainted again Classroom needs painting and holes covered up in this classroom over promethean board.
White Station Elementary	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23 8/8/2024 12:15 5/6/2024 12:20 4/23/2024 15:08	CORONADO BURCHETT BURCHETT BURCHETT BURCHETT BURCHETT BURCHETT	Masonry Painting Painting Painting Painting Painting	Z2-008867 Z2-001549 Z2-040815 Z2-035451 Z2-026429 Z2-013214 Z2-011139	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling We need handicap spots repainted again Classroom needs painting and holes covered up in this classroom over promethean board. Can we get the edges of the awning front and sides painted
White Station Elementary White Station Elementary White Station Elementary White Station Elementary White Station Elementary White Station High	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23 8/8/2024 12:15 5/6/2024 12:20 4/23/2024 15:08 12/8/2024 11:27	CORONADO BURCHETT BURCHETT BURCHETT BURCHETT BURCHETT BURKE	Masonry Painting Painting Painting Painting Painting Painting Carpentry	Z2-008867 Z2-001549 Z2-040815 Z2-035451 Z2-026429 Z2-013214 Z2-011139 Z2-043902	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling We need handicap spots repainted again Classroom needs painting and holes covered up in this classroom over promethean board. Can we get the edges of the awning front and sides painted Freshman across from F214 door closer needs repairs.
White Station Elementary	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23 8/8/2024 12:15 5/6/2024 12:20 4/23/2024 15:08	CORONADO BURCHETT BURCHETT BURCHETT BURCHETT BURCHETT BURCHETT	Masonry Painting Painting Painting Painting Painting	Z2-008867 Z2-001549 Z2-040815 Z2-035451 Z2-026429 Z2-013214 Z2-011139	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling We need handicap spots repainted again Classroom needs painting and holes covered up in this classroom over promethean board. Can we get the edges of the awning front and sides painted
White Station Elementary White Station Elementary White Station Elementary White Station Elementary White Station Elementary White Station High	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23 8/8/2024 12:15 5/6/2024 12:20 4/23/2024 15:08 12/8/2024 11:27	CORONADO BURCHETT BURCHETT BURCHETT BURCHETT BURCHETT BURKE	Masonry Painting Painting Painting Painting Painting Painting Carpentry	Z2-008867 Z2-001549 Z2-040815 Z2-035451 Z2-026429 Z2-013214 Z2-011139 Z2-043902	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling We need handicap spots repainted again Classroom needs painting and holes covered up in this classroom over promethean board. Can we get the edges of the awning front and sides painted Freshman across from F214 door closer needs repairs.
White Station Elementary White Station High White Station High White Station High	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23 8/8/2024 12:15 5/6/2024 12:20 4/23/2024 15:08 12/8/2024 11:27 12/5/2024 9:08 12/12/2024 9:37	CORONADO BURCHETT BURCHETT BURCHETT BURCHETT BURCHETT BURKE BURKE POWELL	Masonry Painting Painting Painting Painting Painting Painting Carpentry Carpentry Electrical	Z2-008867 Z2-001549 Z2-040815 Z2-035451 Z2-026429 Z2-013214 Z2-011139 Z2-043902 Z2-043496 Z2-044626	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling We need handicap spots repainted again Classroom needs painting and holes covered up in this classroom over promethean board. Can we get the edges of the awning front and sides painted Freshman across from F214 door closer needs repairs. 3 exit interior door handle is broke and needs repairing. This is 3rd floor East annex by room E301 Need a light cover for this light fixture
White Station Elementary White Station High White Station High White Station High White Station High	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23 8/8/2024 12:15 5/6/2024 12:20 4/23/2024 15:08 12/8/2024 11:27 12/5/2024 9:08 12/12/2024 9:37	CORONADO BURCHETT BURCHETT BURCHETT BURCHETT BURCHETT BURKE BURKE POWELL POWELL	Masonry Painting Painting Painting Painting Painting Carpentry Electrical Electrical	Z2-008867 Z2-001549 Z2-040815 Z2-035451 Z2-026429 Z2-013214 Z2-011139 Z2-043902 Z2-043496 Z2-044626 Z2-044554	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling We need handicap spots repainted again Classroom needs painting and holes covered up in this classroom over promethean board. Can we get the edges of the awning front and sides painted Freshman across from F214 door closer needs repairs. Exit interior door handle is broke and needs repairing. This is 3rd floor East annex by room E301 Need a light cover for this light fixture front outlets in the auditorium are not working and breaker was checked and nothing was tripped
White Station Elementary White Station High	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23 8/8/2024 12:15 5/6/2024 12:20 4/23/2024 15:08 12/8/2024 11:27 12/5/2024 9:08 12/12/2024 9:37 12/12/2024 9:27 12/12/2024 8:27	CORONADO BURCHETT BURCHETT BURCHETT BURCHETT BURKE BURKE POWELL POWELL	Masonry Painting Painting Painting Painting Painting Carpentry Carpentry Electrical Electrical	Z2-008867 Z2-001549 Z2-040815 Z2-035451 Z2-026429 Z2-013214 Z2-011139 Z2-043902 Z2-043496 Z2-044626 Z2-044554 Z2-044554	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling We need handicap spots repainted again Classroom needs painting and holes covered up in this classroom over promethean board. Can we get the edges of the awning front and sides painted Freshman across from F214 door closer needs repairs. • exit interior door handle is broke and needs repairing. This is 3rd floor East annex by room E301 Need a light cover for this light fixture front outlets in the auditorium are not working and breaker was checked and nothing was tripped Jm back stage lights need to be replaced it's dark and safety hazard with students working back stage.
White Station Elementary White Station High	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23 8/8/2024 12:15 5/6/2024 12:20 4/23/2024 15:08 12/8/2024 11:27 12/5/2024 9:08 12/12/2024 9:37 12/12/2024 8:27 12/12/2024 8:25 12/11/2024 10:16	CORONADO BURCHETT BURCHETT BURCHETT BURCHETT BURKE BURKE POWELL POWELL POWELL	Masonry Painting Painting Painting Painting Painting Carpentry Carpentry Electrical Electrical Electrical	Z2-008867 Z2-001549 Z2-040815 Z2-035451 Z2-026429 Z2-013214 Z2-011139 Z2-043902 Z2-0444626 Z2-044654 Z2-044553 Z2-044553 Z2-044455	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling We need handicap spots repainted again Classroom needs painting and holes covered up in this classroom over promethean board. Can we get the edges of the awning front and sides painted Freshman across from F214 door closer needs repairs. Exit interior door handle is broke and needs repairing. This is 3rd floor East annex by room E301 Need a light cover for this light fixture front outlets in the auditorium are not working and breaker was checked and nothing was tripped John Back stage lights need to be replaced it's dark and safety hazard with students working back stage. Joutlets in classroom E207 are not working and I checked the breaker box nothing was tripped
White Station Elementary White Station High	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23 8/8/2024 12:15 5/6/2024 12:20 4/23/2024 15:08 12/8/2024 11:27 12/5/2024 9:37 12/12/2024 9:37 12/12/2024 8:25 12/11/2024 10:16 12/10/2024 9:30	CORONADO BURCHETT BURCHETT BURCHETT BURCHETT BURKE BURKE POWELL POWELL POWELL POWELL	Masonry Painting Painting Painting Painting Painting Carpentry Carpentry Electrical Electrical Electrical Electrical	Z2-008867 Z2-001549 Z2-040815 Z2-035451 Z2-026429 Z2-013214 Z2-011139 Z2-043902 Z2-043496 Z2-044553 Z2-0444553 Z2-044455 Z2-044455	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling We need handicap spots repainted again Classroom needs painting and holes covered up in this classroom over promethean board. Can we get the edges of the awning front and sides painted Freshman across from F214 door closer needs repairs. Evit interior door handle is broke and needs repairing. This is 3rd floor East annex by room E301 Need a light cover for this light fixture front outlets in the auditorium are not working and breaker was checked and nothing was tripped un back stage lights need to be replaced it's dark and safety hazard with students working back stage. Outlets in classroom E207 are not working and I checked the breaker box nothing was tripped ights over by stand up urinals are not working and bulbs have been changed. Senior gym lobby
White Station Elementary White Station High	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23 8/8/2024 12:15 5/6/2024 12:20 4/23/2024 15:08 12/8/2024 11:27 12/5/2024 9:08 12/12/2024 9:37 12/12/2024 8:27 12/12/2024 8:25 12/11/2024 10:16	CORONADO BURCHETT BURCHETT BURCHETT BURCHETT BURKE BURKE POWELL POWELL POWELL	Masonry Painting Painting Painting Painting Painting Carpentry Carpentry Electrical Electrical Electrical	Z2-008867 Z2-001549 Z2-040815 Z2-035451 Z2-026429 Z2-013214 Z2-011139 Z2-043902 Z2-0444626 Z2-044654 Z2-044553 Z2-044553 Z2-044455	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling We need handicap spots repainted again Classroom needs painting and holes covered up in this classroom over promethean board. Can we get the edges of the awning front and sides painted Freshman across from F214 door closer needs repairs. Exit interior door handle is broke and needs repairing. This is 3rd floor East annex by room E301 Need a light cover for this light fixture front outlets in the auditorium are not working and breaker was checked and nothing was tripped John Back stage lights need to be replaced it's dark and safety hazard with students working back stage. Joutlets in classroom E207 are not working and I checked the breaker box nothing was tripped
White Station Elementary White Station High	2/15/2024 10:12 11/14/2024 10:03 9/30/2024 11:23 8/8/2024 12:15 5/6/2024 12:20 4/23/2024 15:08 12/8/2024 11:27 12/5/2024 9:37 12/12/2024 9:37 12/12/2024 8:25 12/11/2024 10:16 12/10/2024 9:30	CORONADO BURCHETT BURCHETT BURCHETT BURCHETT BURKE BURKE POWELL POWELL POWELL POWELL	Masonry Painting Painting Painting Painting Painting Carpentry Carpentry Electrical Electrical Electrical Electrical	Z2-008867 Z2-001549 Z2-040815 Z2-035451 Z2-026429 Z2-013214 Z2-011139 Z2-043902 Z2-044396 Z2-044554 Z2-044553 Z2-044455 Z2-0444206 Z2-044206 Z2-042547	I have tiles missing out the floor in this restroom can we get this taken care of Outside cafeteria doors need painting they are peeling Cafeteria door needs painting it's peeling We need handicap spots repainted again Classroom needs painting and holes covered up in this classroom over promethean board. Can we get the edges of the awning front and sides painted Freshman across from F214 door closer needs repairs. Evit interior door handle is broke and needs repairing. This is 3rd floor East annex by room E301 Need a light cover for this light fixture front outlets in the auditorium are not working and breaker was checked and nothing was tripped un back stage lights need to be replaced it's dark and safety hazard with students working back stage. Outlets in classroom E207 are not working and I checked the breaker box nothing was tripped ights over by stand up urinals are not working and bulbs have been changed. Senior gym lobby

White Station High		DOME.	F1	70.010101	and the second s
	11/25/2024 13:39	POWELL	Electrical	Z2-042181	Lights are flickering the back two in back on left side
White Station High	11/19/2024 18:12	POWELL	Electrical	Z2-041571	The emergency exit light located by the exit door in the East gym is not working
White Station High	11/15/2024 14:26	POWELL	Electrical	Z2-041123	The outlets won't come on and no breakers were tripped can't get smart board won't come on
White Station High	11/12/2024 15:16	POWELL	Electrical	Z2-040521	Ballast has gone out.
White Station High	11/5/2024 14:07	POWELL	Electrical	Z2-039629	he front of auditorium stage is not working and the breaker was checked but still no power to that outlet
White Station High	11/5/2024 12:58	POWELL	Electrical	Z2-039622	vitch to be repaired in M224 special needs classroom it is loose and lights are not properly coming on and off.
-					
White Station High	11/4/2024 12:58	POWELL	Electrical	Z2-039486	Emergency light not working in the auditorium lobby
White Station High	11/1/2024 13:42	POWELL	Electrical	Z2-039307	Need light covers for light fixtures in girls locker room G127
White Station High	10/31/2024 10:32	POWELL	Electrical	Z2-039071	The ballast is out and the bulbs have been changed in the Senior gym boys locker room
White Station High	10/28/2024 7:25	POWELL	Electrical	Z2-038431	I have a damaged light lense that needs to be changed in cafeteria
White Station High	10/28/2024 5:37	POWELL	Electrical	Z2-038409	e a damaged light lense located in the cafeteria close by South entrance that needs to be replaced
White Station High	10/14/2024 14:09	POWELL	Electrical	Z2-036905	Need several bulbs replaced on the auditorium stage it's over my height.
White Station High	10/14/2024 11:08	POWELL	Electrical	Z2-036843	Several light bulbs are out in the back of auditorium and need to be replaced
White Station High	10/14/2024 7:25	POWELL	Electrical	Z2-036766	panel by room M217A keeps tripping the switch is loosening when flicking the switch to turn them back on
White Station High	10/9/2024 13:05	POWELL	Electrical	Z2-036743	Emergency light not working near south side of auditorium exit door
White Station High	10/9/2024 13:03	POWELL	Electrical	Z2-036742	Emergency light fixture is not working located by the auditorium steps near the exit door
White Station High	10/9/2024 12:55	POWELL	Electrical	Z2-036739	Emergency light is not working located by by lift in the stage area of auditorium
White Station High	10/9/2024 12:53	POWELL	Electrical	Z2-036738	Emergency light in cafeteria number 14 is not working
White Station High	10/8/2024 15:44	POWELL	Electrical	Z2-036667	Emergency light fixture located in cafeteria not working number 13
White Station High	10/8/2024 12:15	POWELL	Electrical	Z2-036620	Emergency light fixture is not working located in the cafeteria by water fountain
White Station High	10/8/2024 11:16	POWELL	Electrical	Z2-036615	The emergency light is not working needs to be fixed located inside the cafeteria
White Station High	10/8/2024 11:15	POWELL	Electrical	Z2-036614	The light fixture lense is broke and needs replacing
Winte Station Flight	10/0/2024 11:10	TOWLLL	Electrical	22 000014	Replace receptacles with GFIC where needed
			- · · ·	70.04000	neplace receptacies with OFIC where needed
White Station High	4/29/2024 11:58	CHALK	Electrical	Z2-012003	
White Station High	12/2/2024 12:13	Coleman	Elevators	Z2-042524	The elevator is not functioning properly on the 3rd floor it will not go to the next floor
White Station High	2/19/2024 12:36	Coleman	Elevators	Z2-001910	Custodial worker got stuck on elevator. Please check for issues.
White Station High	2/3/2024 15:49	Hart	Elevators	WO1026531	The button to elevator is broke on the 3rd floor East Annex.
White Station High	2/3/2024 15:52	Hart	Elevators	WO1025404	
White Station High	8/14/2024 12:27	Coleman	Fire Alarm System	Z2-027531	Fire alarm system is showing trouble
Willte Station Figh	0/14/2024 12.2/	Coteman	File Alailii Systeiii	22-02/331	
					Basement boiler room pull station is hanging off the wall
White Station High	5/1/2024 9:13	LEWIS	Fire Alarm System	Z2-012480	
White Station High	5/17/2024 14:24	Systems	Fire Alarm System	WO1007439	ystem fire alarm panel is showing tamper trouble in the ROTC building the module needs repairing.
White Station High	12/13/2024 13:21		Flooring	Z2-044914	ditorium stage to be sanded only all repairs have been completed. After sanding the painters will paint it black.
White Station High	12/12/2024 11:48		Flooring	Z2-044713	Need gym floor repaired the wood is broken and is a safety hazard for students
					Ms. Cowan (416 7880) White station HS All four HVAC units are showing a fail signal inside
					senior gym
White Station High	12/9/2024 13:15	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-044083	_
White Station High	12/9/2024 13:15	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-044083	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG
White Station High	12/9/2024 13:15	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-044083	_
-					OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG
White Station High White Station High	12/9/2024 13:15 12/5/2024 11:54	STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-044083 Z2-043599	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880
-					OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG
White Station High	12/5/2024 11:54	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-043599	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880
-					OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880
White Station High	12/5/2024 11:54	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-043599	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG
White Station High	12/5/2024 11:54	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-043599	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880
White Station High	12/5/2024 11:54	STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG
White Station High White Station High	12/5/2024 11:54 12/5/2024 11:53	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880
White Station High White Station High	12/5/2024 11:54 12/5/2024 11:53	STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237x
White Station High White Station High White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52	STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880
White Station High White Station High	12/5/2024 11:54 12/5/2024 11:53	STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237x P/M COWAN 416-7880
White Station High White Station High White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52	STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237X P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231
White Station High White Station High White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52	STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237x P/M COWAN 416-7880
White Station High White Station High White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52	STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237X P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231
White Station High White Station High White Station High White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52 12/5/2024 11:47	STRICKLAND STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595 Z2-043593	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237x P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231 P/M COWAN 416-7880
White Station High White Station High White Station High White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52 12/5/2024 11:47	STRICKLAND STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595 Z2-043593	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237x P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231 P/M COWAN 416-7880 INS. COWAN
White Station High White Station High White Station High White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52 12/5/2024 11:47	STRICKLAND STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595 Z2-043593	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237X P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231 P/M COWAN 416-7880 ms. cowan 67880
White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52 12/5/2024 11:47 12/5/2024 11:46	STRICKLAND STRICKLAND STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595 Z2-043593 Z2-043592	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237x P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231 P/M COWAN 416-7880 INS. COWAN
White Station High White Station High White Station High White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52 12/5/2024 11:47	STRICKLAND STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595 Z2-043593	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237x P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231 P/M COWAN 416-7880 INS. COWAN 16-7880 no heat
White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52 12/5/2024 11:47 12/5/2024 11:46	STRICKLAND STRICKLAND STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595 Z2-043593 Z2-043592	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237X P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231 P/M COWAN 416-7880 ms. cowan 67880
White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52 12/5/2024 11:47 12/5/2024 11:46	STRICKLAND STRICKLAND STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595 Z2-043593 Z2-043592	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237x P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231 P/M COWAN 416-7880 INS. COWAN 67880 no heat
White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52 12/5/2024 11:47 12/5/2024 11:46	STRICKLAND STRICKLAND STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595 Z2-043593 Z2-043592	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237x P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231 P/M COWAN 416-7880 ms. cowan 67880 no heat ms. cowan
White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52 12/5/2024 11:47 12/5/2024 11:46 12/4/2024 11:03	STRICKLAND STRICKLAND STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595 Z2-043593 Z2-043592 Z2-043312	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237x P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231 P/M COWAN 416-7880 ms. cowan 67880 no heat ms. cowan 67880
White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52 12/5/2024 11:47 12/5/2024 11:46	STRICKLAND STRICKLAND STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595 Z2-043593 Z2-043592	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237x P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231 P/M COWAN 416-7880 ms. cowan 67880 no heat ms. cowan 67880
White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52 12/5/2024 11:47 12/5/2024 11:46 12/4/2024 11:03	STRICKLAND STRICKLAND STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595 Z2-043593 Z2-043592 Z2-043312	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237X P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231 P/M COWAN 416-7880 ms. cowan 67880 no heat ms. cowan 67880 no heat
White Station High White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52 12/5/2024 11:47 12/5/2024 11:46 12/4/2024 11:03	STRICKLAND STRICKLAND STRICKLAND STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043596 Z2-043595 Z2-043593 Z2-043592 Z2-043312 Z2-043309	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237x P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231 P/M COWAN 416-7880 ms. cowan 67880 no heat ms. cowan 67880
White Station High	12/5/2024 11:54 12/5/2024 11:53 12/5/2024 11:52 12/5/2024 11:47 12/5/2024 11:46 12/4/2024 11:03	STRICKLAND STRICKLAND STRICKLAND STRICKLAND STRICKLAND	Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning Heating/Ventilation/Air Conditioning	Z2-043599 Z2-043596 Z2-043595 Z2-043593 Z2-043592 Z2-043312	OVERHEATING (80 DEGREES) - CL-RM F218 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F209 - FRESHMEN BLDG P/M COWAN 416-7880 OVERHEATING (80 DEGREES) - CL-RM F124 - FRESHMEN BLDG P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M237X P/M COWAN 416-7880 UNIT NOT HEATING - CL-RM M231 P/M COWAN 416-7880 ms. cowan 67880 no heat ms. cowan 67880 no heat

White Station High	12/3/2024 12:31	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-042968	HEATING UNIT FOR RM E207 - BLOWING COLD AIR PM/COWAN 416-7880
White Station High	12/3/2024 12:31	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-042962	HEATING UNIT FOR RM M119 - BLOWING COLD AIR PM/COWAN 416-7880
-					HEATING UNIT FOR AUD - BLOWING COLD AIR PM/COWAN 416-7880
White Station High	12/3/2024 12:27	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-042960	HEATING UNIT FOR RM F217 - BLOWING COLD AIR PM/COWAN 416-7880
White Station High	12/3/2024 12:25	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-042959	White Station Highschool Class e Unit Stephanie Cowan 7880
White Station High	11/19/2024 9:13	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-041438	Mr. Harper 68880 air is not working
White Station High	11/12/2024 10:18	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-040434	UNIT LEAKING HEAVILY (BUSTED COIL) CL-R M023 IN BASEMENT P/M STEPHANIE COWAN 416-7880
White Station High	9/18/2024 7:45	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-033348	HVAC UNITS IN RM M22B - NOT COOLING - PM/COWAN 416-7880
White Station High	9/5/2024 13:23	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-031176	
White Station High	8/29/2024 13:45	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-030325	Plant Manager Cowan reported the ac unit room E305 is blowing hot air. 416-7880.
					HVAC UNIT FOR RM F128 - NOT COOLING PM/COWAN 416-7880
White Station High	8/26/2024 8:09	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-029410	
White Station High	12/13/2024 12:27	MALONE	Key & Lock	Z2-044901	Need a key made to both concessions in the auditorium lobby A106
White Station High	10/15/2024 9:19	MALONE	Key & Lock	Z2-037010	The exit exterior door located by F128 you can't get in using your key it will not open
White Station High	9/16/2024 16:02	CORONADO	Masonry	Z2-033036	cross from Teachers lounge the floor tile is broken up in pieces and needs to be replaced so no students will trip over it
White Station High	5/14/2024 7:52	BURCHETT	Masonry	Z2-014362	aking from the outside and the foundation on the outside needs to be chalked up the ceiling and come apart this room is M023
White Station High	3/6/2024 6:10	CORONADO	Masonry	Z2-004108	Boys restroom 1st floor main building floor tile is broken into pieces and needs repairs.
White Station High	12/10/2024 9:08	BURCHETT	Painting	Z2-044192	Need for plaster to be replaced on wall
White Station High	9/10/2024 17:20	BURCHETT	Painting	Z2-031844	Classroom M206 wall needs to be painted to remove previous painting and artwork
White Station High	8/28/2024 8:03	BURCHETT	Painting	Z2-029937	Teacher requests for room to be painted to cover up drawings that is covered on the walls
White Station High	5/28/2024 9:45	BURCHETT	Painting	Z2-016069	Library walls need to be painted. The paint is peeling in several places.
White Station High	5/14/2024 10:45	BURCHETT	Painting	Z2-014472	Auditorium lobby needs to be painted
White Station High	5/17/2024 14:19	BURCHETT	Painting	WO1002355	
White Station High	5/17/2024 14:18	BURCHETT	Painting	WO1001625	
White Station High	12/13/2024 10:28	STAFFORD	Plumbing	Z2-044879	d for girls basketball locker room toilets to be replaced with appropriate toilets designed for girls
White Station High	12/13/2024 9:38	STAFFORD	Plumbing	Z2-044863	Is basketball locker room located in the Senior gym the showers are not working can it be repaired please
White Station High	12/13/2024 9:33	STAFFORD	Plumbing	Z2-044861	Girls basketball locker the water to the sink functioning doesn't work at all.
White Station High	12/8/2024 11:28	PILKINGTON	Plumbing		tall is not flushing properly used the auger to unstop and it still didn't work. Freshman across from F214
White Station High	12/5/2024 13:45	PILKINGTON	Plumbing	Z2-043667	Hot water heater is not working in the mechanical room of the basement
White Station High	12/5/2024 9:11	PILKINGTON	Plumbing	Z2-043503	The back of the toilet is leaking located in the East gym girls locker room
White Station High	12/2/2024 12:15	PILKINGTON	Plumbing	Z2-042527	stroom nozzles to all of the hand sinks are missing and the water splashing all over the floor when in use. unit leaking
White Station High	11/6/2024 7:52	PILKINGTON	Plumbing	Z2-039695	
White Station High	9/19/2024 6:58	PILKINGTON	Plumbing	Z2-033543	The faucet in G132 faucet will cut off south locker room
White Station High	8/6/2024 5:57	PILKINGTON	Plumbing	Z2-025417	Water filler is leaking located across from room227
White Station High	8/6/2024 5:56	PILKINGTON	Plumbing	Z2-025416	Leaking water filler located in basement by boys and girls restroom
White Station High	8/1/2024 9:27	PILKINGTON	Plumbing	Z2-024308	2nd floor main building water fountain is leaking by girls and boys restroom
White Station High	8/1/2024 7:38	PILKINGTON	Plumbing	Z2-024213	Water fountain is leaking on the first floor Freshman building by girls and boys restroom
White Station High	10/3/2024 12:52	BENTON	Shades/Blinds	Z2-036130	Need for shades to be replaced Per request by the principal is to have all the damaged carpet replaced with tile in the Main office area.
					Thank you
White Station Middle	11/6/2024 9:45	BENTON	Carpet Repair	Z2-039784	mank you
winte station rilidate	11/0/2024 3.43	BENTON	Garpet Nepan	22-033704	A request is to have the school time clocks set for the outside lights to come on due to fall back time.
					Thank you
White Station Middle	10/16/2024 7:10	POWELL	Electrical	Z2-037123	
					A Request is to have the scoreboard switch repaired before basketball season starts it work sometimes and sometimes not? Thank you
White Station Middle	8/26/2024 14:45	POWELL	Electrical	Z2-029642	

The 2-switch light fixture at the entrance has a shortage and sparks in need of repair. in classroom D-118 1st floor Thank you

White Station Middle	3/25/2024 11:36	POWELL	Electrical	Z2-006148	
					A request is for an updated Elevator Operating Certificate for this location. Thank you
White Station Middle	4/19/2024 8:02	LEWIS	Elevators	Z2-010625	you
					A request is to have the panel repaired do to a trouble showing strobe CKT HFF #2 Trigger
					A request is to have the panet repaired do to a trouble showing strobe CK1 HFF #2 Higger
Militar Objeti a a Mistalla	0/04/00044440	0-1	Fire Marris Octobers	70.000040	Thank you
White Station Middle	8/21/2024 14:16	Coleman	Fire Alarm System	Z2-028948	A request is to have the Kiln machine vented or removed due to fire Marsal inspection.
					POCA
White Station Middle	5/2/2024 10:09	LEWIS	Fire Alarm System	Z2-012751	Thank you.
					1. Repair Panel showing trouble in NAC NFC-50-100 system 2. Need to replace a damaged
					strobe light (strobe damaged due to previous sprinkler pipe leak that has been repaired in Room A-161.)
White Station Middle	2/3/2024 17:02	Contractor	Fire Alarm System	WO1018437	HOURIN TOLL
					A request is for a 5 Year Sprinkler Inspection document for the building engineer to have in
					the fire and safety book Thank you
White Station Middle	10/30/2024 7:19	Coleman	Fire Sprinkler System	Z2-038813	
					A request is to have the sprinkler head adjusting in the Counselors office in Admin area the office is Dr. Ford.
					Thankyou
White Station Middle	10/23/2024 13:15	LEWIS	Fire Sprinkler System	Z2-038030	Mr. hughes
					62148
White Station Middle	12/5/2024 7:42	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-043435	NO HEAT IN GYM
Wille Station Pludle	12/3/2024 /.42	STRICKLAND	reading/ventitation/Air Conditioning	22-043433	Mr. hughes
					62148
White Station Middle	12/5/2024 7:41	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-043434	NO HEAT IN GYM
	40/0/0004040	077101/1 1117		70.005054	HVAC UNIT ON THE 2ND FLR - RM G220 - LEAKING PM/HUGHES 416-2184
White Station Middle	10/2/2024 9:16	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-035854	Classroom unit not cooling
White Station Middle	9/19/2024 7:44	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-033557	
					UNIT NOT COOLING - CL-RM G227, 2ND FLOOR P/M DON HUGHES 416-2184
White Station Middle	8/28/2024 7:40	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-029922	
White Station Middle	8/13/2024 8:38	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-027201	RTU - FOR THE CAFE - NOT COMING ON - PM/HUGHES 416-2184
					RTU FOR THE KITC - NOT COOLING PM/HUGHES 416-2184
White Station Middle	8/9/2024 12:25	STRICKLAND	Heating/Ventilation/Air Conditioning	Z2-026731	A request is for an SDK 13 for the key box in the plant managers office.
					Thank you
White Station Middle	11/18/2024 11:37	MALONE	Key & Lock	Z2-041295	
					A request is to have GMA Key replaced it has broken into pieces it's being sent in the mail.
				70.04000	Thank you
White Station Middle	11/8/2024 11:36	MALONE	Key & Lock	Z2-040282	A request is for several keys made for the B- Hallway for the key box
	44/7/00		, -···	70.0	Thankyou
White Station Middle	11/7/2024 14:53	MALONE	Key & Lock	Z2-040199	A request is to have several keys to be made for the storage room in classroom 133 A-21
					#134382
White Station Middle	11/7/2024 14:28	MALONE	Key & Lock	Z2-040194	Thank you
.vinto otation riludio	11///2024 14.20	LINEONE	NO, OLDOR	22 0-0104	

A request is to have keys made for Classroom on the A Hallway

Thank you

					Thank you
White Station Middle	8/8/2024 11:48	SMITH	Key & Lock	Z2-026418	
					A request is to have keys made for Classroom on the B Hallway
					Thank you
White Station Middle	8/8/2024 11:47	SMITH	Key & Lock	Z2-026415	
					A request is to have an annual updated report on the rollup doors per request by the fire
					Marshall.
	= 10 1000 1 0 = 0			70.040050	POCA
White Station Middle	5/8/2024 9:53	Coleman	Roll Up Doors	Z2-013658	A
					A request is to have an annual updated report on the rollup doors per request by the fire Marshall.
					Marshall. POCA
White Station Middle	5/2/2024 14:17	LEWIS	Roll Up Doors	Z2-012855	PUCA
Whitehaven Elementary	11/8/2024 15:31	HALL	Electrical	Z4-040334	Exterior light at the corner of the building is out
Willtellavell Eterlientary	11/0/2024 15.51	HALL	Electricat	24-040334	HEATING UNIT IN RM E136 - BLOWING NOT HEATING PM/COATS 416-8740
Whitehaven Elementary	12/12/2024 8:23	WRIGHT	Heating/Ventilation/Air Conditioning	Z4-044551	TIEATING GIVE IN THE E130 - BEOWING NOT TIEATING 1 PI/COA13 410-0/40
Whitehaven Elementary	12/3/2024 11:20	WRIGHT	Heating/Ventilation/Air Conditioning	Z4-042900	Blowing cool air
Whitehaven Elementary	10/7/2024 11:04	BURCHETT	Painting	Z4-036463	Paint peeling underneath Emergency window
Whitehaven Elementary	9/10/2024 13:24	BURCHETT	Painting	Z4-031791	Office needs to be painted
Whitehaven Elementary	8/5/2024 13:30	BURCHETT	Painting	Z4-025342	Paint peeling underneath the window ceil
Whitehaven Elementary	7/23/2024 9:40	BURCHETT	Painting	Z4-022086	Office need to be painted
Whitehaven Elementary	7/18/2024 7:45	BURCHETT	Painting	Z4-021574	Re-plaster right side wall and paint underneath window
Whitehaven Elementary	7/9/2024 13:10	BURCHETT	Painting	Z4-020617	2nd floor paint peeling underneath the window
Whitehaven Elementary	7/8/2024 13:30	BURCHETT	Painting	Z4-020454	Paint the trimmings around all classroom doors frames
Whitehaven Elementary	7/8/2024 13:24	BURCHETT	Painting	Z4-020453	Principal wants all classroom doors painted black
Whitehaven Elementary	7/3/2024 9:58	BURCHETT	Painting	Z4-020166	Re-plaster break room, restroom, and paint
Whitehaven Elementary	12/13/2024 13:27	HARRIS	Plumbing	Z4-044916	The 2nd sink has a slow drain
Whitehaven Elementary	12/3/2024 10:59	HARRIS	Plumbing	Z4-042887	Girls restroom toilet leaking around the back need a wax seal
Whitehaven Elementary	11/18/2024 13:25	HARRIS	Plumbing	Z4-041331	Needs a flush valve on the toilet
Whitehaven Elementary	10/28/2024 14:34	HARRIS	Plumbing	Z4-038587	The toilet seal is leaking from the back
Whitehaven Elementary	10/23/2024 11:09	HARRIS	Plumbing	Z4-037987	Toilet has crack along the side stall number # 10 by the window
Whitehaven Elementary	10/23/2024 11:04	HARRIS	Plumbing	Z4-037985	Toilet has a crack on the left side stall number #9
Whitehaven Elementary	9/30/2024 10:38	HARRIS	Plumbing	Z4-035427	Boys restroom number 4, toilet seat split in half
					Dial frame not flushing, number #6 last one by the window
Whitehaven Elementary	9/26/2024 13:57	HARRIS	Plumbing	Z4-034958	
Whitehaven Elementary	9/16/2024 14:13	HARRIS	Plumbing	Z4-033012	Number 7# stall toilet flush valve is leaking water around the neck
Whitehaven Elementary	9/10/2024 15:34	HARRIS	Plumbing	Z4-031837	Girls restroom # 6 stall needs to be replaced
Whitehaven Elementary	9/10/2024 15:29	HARRIS	Plumbing	Z4-031834	Girls restroom number 4 toilet seat needs replaced
Whitehaven Elementary	8/19/2024 13:23	HARRIS	Plumbing	Z4-028439	The faucet the first one right behind the wall is loose
					On the 2nd floor urinal leaking from the bottom the last stall by the window
Whitehaven Elementary	8/15/2024 13:43	HARRIS	Plumbing	Z4-027869	
Whitehaven Elementary	8/12/2024 15:10	HARRIS	Plumbing	Z4-027081	The big double sink's leaking water underneath the sink.
Whitehaven Elementary	7/19/2024 19:33	HARRIS	Plumbing	Z4-021760	Number #5 toilet has a crack on it water is coming from
Whitehaven High	9/20/2024 8:02	SMITH	Audio Visual	Z4-033890	A building cannot hear the intercom.
Whitehaven High Whitehaven High	12/16/2024 7:23 12/12/2024 12:33	ARNOLD ANDERSON	Carpentry Carpentry	Z4-044963 Z4-044728	One of cabinet doors is off the hinges. Boys softball locker room 3 window panes need to be replaced.
Whitehaven High	12/12/2024 12:39	ANDERSON	Carpentry	Z4-044726 Z4-044726	Boys football locker room needs 8 window panes replaced.
Whitehaven High	12/11/2024 12:29	ARNOLD	Carpentry	Z4-044726 Z4-044411	The swing door spring is broke.
Whitehaven High	9/30/2024 12:53	TEDDER	Electrical	Z4-035489	Stairwells next to the teacher lounge low balance light.
Whitehaven High	9/30/2024 11:39	HALL	Electrical	Z4-035461	I have 2 rounds big lights.
Whitehaven High	9/19/2024 8:48	HALL	Electrical	Z4-033588	DMZ 1 low balance light.
Whitehaven High	9/6/2024 13:51	HALL	Electrical	Z4-031358	I have 1. exterior light out on the Elvis Presley side.
Whitehaven High	9/6/2024 13:41	HALL	Electrical	Z4-031354	I have 1 exterior light out on the Elvis Presley side.
Whitehaven High	9/6/2024 13:35	HALL	Electrical	Z4-031353	I have 2 lights out next to the boys room.
Whitehaven High	9/6/2024 12:29	HALL	Electrical	Z4-031339	I have 4 lights out.
Ü					I have 3 lights out in the back of the A building.
Whitehaven High	9/6/2024 12:05	HALL	Electrical	Z4-031328	-
Whitehaven High	9/6/2024 12:01	HALL	Electrical	Z4-031327	I have 1 light out on side of the building.
Whitehaven High	9/6/2024 11:57	HALL	Electrical	Z4-031325	I have 4 lights out.
Whitehaven High	9/4/2024 10:51	HALL	Electrical	Z4-030883	The projector light bulb is blown out the projector is in the center of the auditorium.
Whitehaven High	8/21/2024 10:06	HALL	Electrical	Z4-028869	One stage light is blown out.
Whitehaven High	5/17/2024 14:24	CHALK	Electrical	WO1006257	Poles are not lite the two coming in from the Football Field in the Student Parking Lot

					D
Whitehaven High	11/4/2024 8:09	CALDWELL	Fire Alarm System	Z4-039362	Duct det 1st floor AHU 7B Return
_			-		HEATING UNIT IN RM A106 - BLOWING COLD AIR PM/ORR 416-7172
Whitehaven High	12/6/2024 13:34	WILSON	Heating/Ventilation/Air Conditioning	Z4-043857	
					MS. ORR 67172
					BLOWING COLD AIR
Whitehaven High	12/6/2024 8:28	WILSON	Heating/Ventilation/Air Conditioning	Z4-043736	BEOTHING GOLD FAIR
					Ms. Orr (901 7172 416) Whitehaven HS RmA106
Whitehaven High	12/4/2024 8:31	WILSON	Heating/Ventilation/Air Conditioning	Z4-043145	
					UNIT NOT HEATING - CL-RM A202, 2ND FLOOR
Whitehaven High	12/4/2024 8:07	WILSON	Heating/Ventilation/Air Conditioning	Z4-043125	P/M 416-7172
willenaven riign	12/4/2024 6.07	WILSON	rieating/ventitation/All Conditioning	24-043123	UNIT NOT COMING ON - CL-RM D130
					P/M 416-7172
Whitehaven High	12/4/2024 8:06	WILSON	Heating/Ventilation/Air Conditioning	Z4-043124	
					OVER HEATING (80 DEGREES) - CL-RM B106
Whitehoven High	12/4/2024 0:04	MUS CON	Liceting Alentilation / Air Conditioning	74.042120	P/M 416-7172
Whitehaven High	12/4/2024 8:04	WILSON	Heating/Ventilation/Air Conditioning	Z4-043120	OVER HEATING (80 DEGREES) - CL-RM A200
					P/M 416-7172
Whitehaven High	12/4/2024 8:02	WILSON	Heating/Ventilation/Air Conditioning	Z4-043119	
Whitehaven High	12/16/2024 7:36	MALONE	Key & Lock	Z4-044967	Electrical room lock replaced.
Whitehaven High	12/5/2024 11:16	MALONE	Key & Lock	Z4-043575	Exterior door needs a key cylinder.
Whitehaven High	12/5/2024 11:10	MALONE	Key & Lock	Z4-043572	Need a key cylinder.
Whitehaven High	11/19/2024 8:32	MALONE	Key & Lock	Z4-041414	Lock needs to be replaced.
Whitehaven High	10/31/2024 10:21	MALONE	Key & Lock	Z4-039062	Exterior door lock need to be replaced.
Whitehaven High	7/29/2024 13:29	SMITH	Key & Lock	Z4-023410	I. Need a key made the key number is. Stargent BBB
Whitehaven High	7/26/2024 12:23	SMITH	Key & Lock	Z4-022951	Need two keys made . A50. Key and A51 key.
Whitehaven High	4/16/2024 12:30	BURCHETT	Painting	Z4-009631	Repaint teacher and student lot remove title put you can put staff
Whitehaven High	4/5/2024 9:06	BURCHETT	Painting	Z4-007860	Lines and Directional markings
Whitehoven High	2/22/2024 12:00	DUDCUETT	Dointing	74 000004	Stripe parking lot near side entrance
Whitehaven High	2/23/2024 13:00	BURCHETT	Painting	Z4-002684	Stripe parking lot near stadium
Whitehaven High	2/23/2024 13:00	BURCHETT	Painting	Z4-002683	only parking of near station
Whitehaven High	5/17/2024 13:53	DIXON	Painting	WO989307	Paint peeling off the walls in hallway by A208
Whitehaven High	12/12/2024 10:30	HARRIS	Plumbing	Z4-044686	2 urinal stop up.
					bleed gas line
Whitehaven High	12/10/2024 14:30	JOHNSON	Plumbing	Z4-044351	
Whitehaven High	12/6/2024 13:25	HARRIS	Plumbing	Z4-043853	The lady restroom needs a toilet seat.
Whitehavon High	12/4/2024 8:53	HARRIS	Plumbing	Z4-043174	The 3rd toilet is stop up.
Whitehaven High Whitehaven High	12/4/2024 12:29	HARRIS	Plumbing	Z4-043174 Z4-042537	The toilet won't flush .
Whitehaven High	9/19/2024 11:05	HARRIS	Plumbing	Z4-042337 Z4-033735	Toilet needs to be replaced in the girls restroom.
Whitehaven High	9/19/2024 10:57	HARRIS	Plumbing	Z4-033733	Girls restroom c hall needs to be replaced.
Williamon Figure	3/13/2024 10:07	Tiratio	r turnomig	24 000720	Toilet leaking
Whitehaven High	4/30/2024 8:35	HARRIS	Plumbing	Z4-012166	
Whitehaven High	11/19/2024 10:01	STEVENSON	Roofing	Z4-041473	Has a roof leak.
Whitehaven High	11/14/2024 14:22	STEVENSON	Roofing	Z4-040923	Has a roof leak.
					Has a roof leak.
Whitehaven High	11/14/2024 8:13	STEVENSON	Roofing	Z4-040762	
Whitehaven High	11/6/2024 7:22 10/17/2024 12:18	STEVENSON STEVENSON	Roofing	Z4-039686	I have a roof leak. Roof leak.
Whitehaven High	10/1//2024 12:18	STEVENSON	Roofing	Z4-037388	коот цеак.
					Hi,
					It was verified that the lights in the concession stand does not work on Monday 3/18
Whitehaven Stadium	3/22/2024 14:16	HALL	Electrical	Z4-005994	
					KEYS TO OPEN ALL AREAS TO STADIUM - TICKET BOOTH PRESSBOX CONCESSION STAND
Whitehaven Stadium	8/5/2024 11:01	TAYLOR	Vou 9 Look	Z4-025259	AND MASTER KEY TO OPEN ALL DOORS INSIDE STADIUM - MECHANICAL ROOM ETC.
	8/5/2024 11:01 4/25/2024 7:12	IATLUK	Key & Lock	Z4-025259 Z1-011415	The vent come off the air conditioner unit
Whitney Elementary Whitney Elementary	4/25/2024 7:12		Carpet Repair Carpet Repair	Z1-011415 Z1-011036	Second stall door is broken
Whitney Elementary	4/4/2024 6:44		Carpet Repair		rea I have ceiling tiles fall out ceiling, don't have ladder that can reach that high, don't it fall on the kids
**************************************	41412024 0.44		Carpernepail	21-00/002	ca mayo colung alco lak out celung, don thave tadder that can reach that high, don tit lak on the Nus

					In the gym area i have broking cover have handle from the light fixture.
Whitney Elementary	2/13/2024 8:44	CASEY	Carpet Repair	Z1-001125	in the 5) in also that established color has handle from the again interest
Whitney Elementary	12/13/2024 12:41	SMITH	Electrical	Z1-044902	Serving area in the kitchen fire is coming from the plug
Whitney Elementary	9/6/2024 14:02	CHALK	Electrical	Z1-031364	Exterior light on back parking lot is out
					on the parking lot of my building have four pole light out
Whitney Elementary	2/20/2024 10:03	CHALK	Electrical	Z1-002056	
Whitney Elementary	5/17/2024 14:31	CHALK	Electrical	WO1014296	
Whitney Flomenton	12/12/2024 8:38	WEBB	Heating/Ventilation/Air Conditioning	Z1-044565	HEATING UNIT FOR THE MAIN OFC - NOT HEATING PM/JOHNSON 416-3949
Whitney Elementary	12/12/2024 6.36	WEDD	Heating/ventitiation/Air Conditioning	21-044565	HEATING UNIT FOR RM 5 - NOT HEATING PM/JOHNSON 416-3949
Whitney Elementary	12/12/2024 8:38	WEBB	Heating/Ventilation/Air Conditioning	Z1-044562	
Trincing Etomonicary	12/12/2024 0100	***************************************	riodanily romandom in Conditioning	21 011002	HEATING UNIT FOR RM 6 - NOT HEATING PM/JOHNSON 416-3949
Whitney Elementary	12/12/2024 8:37	WEBB	Heating/Ventilation/Air Conditioning	Z1-044561	
					HEATING UNIT FOR THE PRIN OFC - NOT COMING ON PM/JOHNSON 416-3949
Whitney Elementary	12/6/2024 8:39	WEBB	Heating/Ventilation/Air Conditioning	Z1-043740	
					HEATING UNIT IN THE FINANCE OFC - NOT COMING ON PM/JOHNSON 416-4939
Whitney Elementary	12/3/2024 7:05	WEBB	Heating/Ventilation/Air Conditioning	Z1-042677	
		14/500		74 040455	MR. JOHNSON 63949 NO HEAT
Whitney Elementary	12/2/2024 11:00	WEBB	Heating/Ventilation/Air Conditioning	Z1-042455	Mr Jhonson (4939) Whitney ES Pre K room 39 Unit not turning on at all
Whitney Elementary	12/2/2024 8:27	WEBB	Heating/Ventilation/Air Conditioning	Z1-042271	MI JIIONSON (4939) WHITHEY ES PIE K TOOM 39 OME NOT TURNING ON AT ALL
William Elementary	12/2/2024 0.2/	WEDD	rieding/ventilation/Air Conditioning	21-0422/1	Mr Jhonson (4939) Whitney ES Classroom 28 Unit not turning on at all
Whitney Elementary	12/2/2024 8:21	WEBB	Heating/Ventilation/Air Conditioning	Z1-042267	The shouldest (1996) Whiteled Ed Galderson 25 Onterior talking of actual
, , , , , , , , , , , , , , , , , , , ,					The air conditioning unit new board on it some can cut on
Whitney Elementary	11/21/2024 7:23	WEBB	Heating/Ventilation/Air Conditioning	Z1-041825	
Whitney Elementary	11/19/2024 8:44	WEBB	Heating/Ventilation/Air Conditioning	Z1-041418	The board need to be repaired
					FLOOR UNIT LEAKING - CL-RM 20
					P/M JOHNSON 416-3949
Whitney Elementary	9/24/2024 8:30	WEBB	Heating/Ventilation/Air Conditioning	Z1-034386	LINIT NOT COOLING 40
					UNIT NOT COOLING - 10 P/M JOHNSON 416-3949
Whitney Elementary	9/24/2024 8:21	WEBB	Heating/Ventilation/Air Conditioning	Z1-034370	P/M JUNISUN 416-3949
William Elementary	3/24/2024 0.21	WEDD	rieding/ventilation/Air Conditioning	21-034370	HVAC UNIT IN PREK RM 30 - UNIT IS BLOWING HEAT PM/JOHNSON 416-3949
Whitney Elementary	9/17/2024 13:43	WEBB	Heating/Ventilation/Air Conditioning	Z1-033263	THE STATE OF
, ,					HVAC UNIT FOR CAFE/KITC AREA - BLOWING HOT AIR PM/JOHNSON 416-3949
Whitney Elementary	9/16/2024 13:08	WEBB	Heating/Ventilation/Air Conditioning	Z1-032970	
Whitney Elementary	10/15/2024 10:24	MALONE	Key & Lock	Z1-037039	Main often need a whole new door knob
Whitney Elementary	5/17/2024 14:04	BURTON	Masonry	WO994896	
Whitney Elementary	5/15/2024 8:32	BURCHETT	Painting	Z1-014618	
					The gym area need paint bad it has black stuff on the wall, that my cleaning staff can't get
Whitney Elementary	3/7/2024 7:24	BURCHETT	Painting	Z1-004313	off.
williney Elementary	3///2024 /.24	BUNCHETT	Failtung	21-004313	the outside school sign needs to be paint.
Whitney Elementary	3/6/2024 7:19	BURCHETT	Painting	Z1-004133	are outside school sign needs to be paint.
, , , , , , , , , , , , , , , , , , , ,					Outside of the school need be painting the wood is rotten wood.
Whitney Elementary	3/5/2024 9:43	BURCHETT	Painting	Z1-003951	
Whitney Elementary	12/5/2024 12:08	Jordan	Plumbing	Z1-043609	Need drainer covers
Whitney Elementary	12/5/2024 12:06	Jordan	Plumbing	Z1-043608	Need drain covers over the boy restroom
Whitney Elementary	12/4/2024 7:48	Jordan	Plumbing	Z1-043114	Boys Restroom back hallway urinals is leaking very first one in the corner
	7/00/0004047	07501510		74 000500	HVAC UNIT IN PRE-K RM 32 - LEAKING PM/JOHNSON 416-3949
Whitney Elementary	7/30/2024 8:17	STEPHENS	Plumbing	Z1-023592	Mond you blinds in this alconous
Whitney Elementary	3/12/2024 10:28	CONNER	Shades/Blinds	Z1-004907	Need new blinds in this classroom
williney Elementary	3/12/2024 10.20	CONNER	Sildues/bullus	21-004907	Need new blinds in this classroom
Whitney Elementary	3/12/2024 10:26	CONNER	Shades/Blinds	Z1-004906	Tood not build in the back of
,					Need new blinds for this classroom
Whitney Elementary	3/12/2024 10:25	CONNER	Shades/Blinds	Z1-004905	
					Need new blinds in this classroom
Whitney Elementary	3/12/2024 10:23	CONNER	Shades/Blinds	Z1-004903	
					Need new blinds in this classroom.
Whitney Elementary	3/12/2024 10:23	CONNER	Shades/Blinds	Z1-004902	Mandania bilada in Abi
Whitney Florenten	2/12/2024 10:22	CONNER	Chades/Blinds	Z1-004901	Need new blinds in this classroom
Whitney Elementary	3/12/2024 10:22	CONNER	Shades/Blinds	21-004901	

					Need new blinds in this classroom
Whitney Elementary	3/12/2024 10:21	CONNER	Shades/Blinds	Z1-004900	Need flew builds in this classiooni
Wildley Eternentary	0/12/2024 10:21	CONTREIN	onduca/ bunda	21 004000	Need new blinds in this area.
Whitney Elementary	3/12/2024 10:19	CONNER	Shades/Blinds	Z1-004899	
					Need new blinds in classroom
Whitney Elementary	3/12/2024 10:17	CONNER	Shades/Blinds	Z1-004898	
					Classroom 16 needs new blinds.
Whitney Elementary	2/22/2024 10:01	BENTON	Shades/Blinds	Z1-002459	
					ClaSSROOM 12 need new blinds
Whitney Elementary	2/22/2024 10:00	BENTON	Shades/Blinds	Z1-002457	
	0.00.000.000	DELITON		74 000 450	Classroom 13 need blinds
Whitney Elementary	2/22/2024 9:59	BENTON	Shades/Blinds	Z1-002456	Classroom 14 need new blinds
Whitney Elementary	2/22/2024 9:58	BENTON	Shades/Blinds	Z1-002454	Classionii 14 need new bunds
Wildley Eternelitary	2/22/2024 0.00	DENTON	Silades/Billas	21 002404	Classroom 25 need blinds' replaced.
Whitney Elementary	2/22/2024 9:43	BENTON	Shades/Blinds	Z1-002447	Salosoon 20 nood bando ropadoda
,,					Classroom 27 need blinds replaced
Whitney Elementary	2/22/2024 9:22	BENTON	Shades/Blinds	Z1-002435	
William Herbert Brewster Elementary	12/11/2024 8:11		Audio Visual	Z2-044419	The cameras are not working
William Herbert Brewster Elementary	11/15/2024 9:05	STOWE	Audio Visual	Z2-041022	The intercom isn't working, it's beeping out of control and not picking up in all areas.
William Herbert Brewster Elementary	11/18/2024 11:26	BURKE	Carpentry	Z2-041287	Rubber is coming off stairs.
William Herbert Brewster Elementary	11/14/2024 16:41	BURKE	Carpentry	Z2-040950	Rubber is coming off the stairs which is hazardous
William Herbert Brewster Elementary	10/28/2024 9:15	POWELL	Electrical	Z2-038477	There are about 10 blown bulbs in the cafeteria that requires a lift to change.
William Herbert Brewster Elementary	10/28/2024 9:15	POWELL	Electrical	Z2-038477 Z2-038422	2nd floor east end, ballast is out and it's dark
,					
William Herbert Brewster Elementary	10/22/2024 10:06	POWELL	Electrical	Z2-037802	All of the lights on the front of have blown out.
William Herbert Brewster Elementary	10/22/2024 10:05	POWELL	Electrical	Z2-037801	There are 6 blown lights out in the back parking lot, very dark.
William Herbert Brewster Elementary	10/21/2024 8:16	POWELL	Electrical	Z2-037594	There are 6 lights out in the front parking lot
William Herbert Brewster Elementary	10/7/2024 13:06	POWELL	Electrical	Z2-036490	Ballast out in girls RR
William Herbert Brewster Elementary	9/30/2024 6:33	POWELL	Electrical	Z2-035262	2nd landing has 2blown bulbs, the fixture requires a special tool to open
William Herbert Brewster Elementary	8/6/2024 13:14	POWELL	Electrical	Z2-025750	16 lights out requires a lift
William Herbert Brewster Elementary	7/30/2024 9:14	POWELL	Electrical	Z2-023644	Light switch buzzes when being turned on and off.
William Herbert Brewster Elementary	7/26/2024 8:21	POWELL	Electrical	Z2-022762	Bulbs blown, requires a special tool to open
William Herbert Brewster Elementary	5/15/2024 6:58	POWELL	Electrical	Z2-014582	Outlet isn't working and it's not the breaker
William Herbert Brewster Elementary	5/6/2024 16:35	POWELL	Electrical	Z2-013277	This is a POCA
William Herbert Brewster Elementary	11/21/2024 11:27	Coleman	Elevators	Z2-041941	The elevator door is not closing properly.
William Herbert Brewster Elementary	4/8/2024 7:58	LEWIS	Elevators	Z2-041941 Z2-008040	or isn't working properly, it's stalling again. We have a special needs student that has to use it quite often.
William Herbert Brewster Elementary	4/11/2024 11:29	LEWIS	Fire Alarm System	Z2-008820	Alarm Panel has this message
William Herbert Brewster Elementary	8/15/2024 10:09	SMITH	Key & Lock	Z2-027760	Key keeps getting stuck in door
William Herbert Brewster Elementary	7/25/2024 6:02	SMITH	Key & Lock	Z2-022472	Maintenance closet
William Herbert Brewster Elementary		SMITH	Key & Lock		
	7/24/2024 5:54			Z2-022222	Pre k cabinet lock fell out
William Herbert Brewster Elementary	7/24/2024 5:54 5/10/2024 10:29	SMITH	Key & Lock	Z2-014058	Pre k cabinet lock fell out Key won't go in lock
William Herbert Brewster Elementary William Herbert Brewster Elementary					
,	5/10/2024 10:29	SMITH	Key & Lock	Z2-014058	Key won't go in lock
William Herbert Brewster Elementary	5/10/2024 10:29 6/13/2024 10:56	SMITH BURCHETT	Key & Lock Painting	Z2-014058 Z2-018292	Key won't go in lock Requesting touch up paint r principal,please paint "reserve "/post signage on at least 4 parking spaces in front of building.
William Herbert Brewster Elementary William Herbert Brewster Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23	SMITH BURCHETT BURCHETT	Key & Lock Painting Painting	Z2-014058 Z2-018292 Z2-005571	Key won't go in lock Requesting touch up paint
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39	SMITH BURCHETT BURCHETT BARNES	Key & Lock Painting Painting Carpentry	Z2-014058 Z2-018292 Z2-005571 Z3-016290	Key won't go in lock Requesting touch up paint r principal, please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected.
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39 11/6/2024 7:45	SMITH BURCHETT BURCHETT BARNES SCOTT	Key & Lock Painting Painting Carpentry Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693	Key won't go in lock Requesting touch up paint r principal,please paint "reserve "/post signage on at least 4 parking spaces in front of building.
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39	SMITH BURCHETT BURCHETT BARNES	Key & Lock Painting Painting Carpentry	Z2-014058 Z2-018292 Z2-005571 Z3-016290	Key won't go in lock Requesting touch up paint r principal, please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected.
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39 11/6/2024 7:45	SMITH BURCHETT BURCHETT BARNES SCOTT	Key & Lock Painting Painting Carpentry Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693	Key won't go in lock Requesting touch up paint r principal, please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary Willow Oaks Elementary Willow Oaks Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39 11/6/2024 7:45 9/16/2024 9:13	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH	Key & Lock Painting Painting Carpentry Electrical Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693 Z3-032856	Key won't go in lock Requesting touch up paint r principal, please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:13	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT	Key & Lock Painting Painting Carpentry Electrical Electrical Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693 Z3-032856 Z3-029468	Key won't go in lock Requesting touch up paint r principal,please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights. Thx
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:13 8/26/2024 9:12	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT SCOTT SCOTT	Key & Lock Painting Painting Carpentry Electrical Electrical Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693 Z3-032856 Z3-029468 Z3-029467 Z3-029465	Key won't go in lock Requesting touch up paint r principal, please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights. Thx Replace emergency lights. Thx Replace emergency lights. Thx
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:12 8/26/2024 9:11 8/26/2024 9:11	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT SCOTT SCOTT SCOTT	Key & Lock Painting Painting Carpentry Electrical Electrical Electrical Electrical Electrical Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693 Z3-032856 Z3-029465 Z3-029465 Z3-029465 Z3-029465	Key won't go in lock Requesting touch up paint r principal, please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights. Thx
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:12 8/26/2024 9:11 8/26/2024 9:11 8/26/2024 9:10	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT SCOTT SCOTT SCOTT SCOTT	Key & Lock Painting Painting Carpentry Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693 Z3-032856 Z3-029468 Z3-029467 Z3-029464 Z3-029464 Z3-029464	Key won't go in lock Requesting touch up paint r principal,please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights. Thx
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:12 8/26/2024 9:11 8/26/2024 9:11 8/26/2024 9:10 8/26/2024 9:09	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT	Key & Lock Painting Painting Carpentry Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693 Z3-032856 Z3-029468 Z3-029465 Z3-029464 Z3-029462 Z3-029462 Z3-029462	Key won't go in lock Requesting touch up paint r principal, please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights. Thx
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:12 8/26/2024 9:11 8/26/2024 9:11 8/26/2024 9:09 8/26/2024 9:09	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT SCOTT	Key & Lock Painting Painting Carpentry Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693 Z3-029465 Z3-029465 Z3-029464 Z3-029464 Z3-029460 Z3-029460 Z3-029460	Key won't go in lock Requesting touch up paint r principal,please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights. Thx
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:12 8/26/2024 9:11 8/26/2024 9:11 8/26/2024 9:11 8/26/2024 9:09 8/26/2024 9:08 8/26/2024 9:09	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT	Key & Lock Painting Painting Carpentry Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693 Z3-029468 Z3-029467 Z3-029465 Z3-029464 Z3-029468 Z3-029468 Z3-029458	Key won't go in lock Requesting touch up paint r principal, please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights. Replace emergency lights.
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:12 8/26/2024 9:11 8/26/2024 9:11 8/26/2024 9:10 8/26/2024 9:09 8/26/2024 9:08 8/26/2024 9:08 8/26/2024 9:06	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT	Key & Lock Painting Painting Carpentry Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693 Z3-032856 Z3-029468 Z3-029467 Z3-029462 Z3-029462 Z3-029455 Z3-029455	Key won't go in lock Requesting touch up paint r principal,please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights.
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:12 8/26/2024 9:11 8/26/2024 9:11 8/26/2024 9:09 8/26/2024 9:09 8/26/2024 9:08 8/26/2024 9:08 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:06	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT	Key & Lock Painting Painting Carpentry Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-032856 Z3-029468 Z3-029465 Z3-029462 Z3-029460 Z3-029458 Z3-029452 Z3-029455 Z3-029455 Z3-029455 Z3-029455	Key won't go in lock Requesting touch up paint r principal,please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights. Replace emergency lights. Replace emergency lights. Thx Replace emergency lights. Replace emergency lights. Thx Replace emergency lights. Thx Replace emergency lights. Thx
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 12:23 5/29/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:12 8/26/2024 9:11 8/26/2024 9:11 8/26/2024 9:09 8/26/2024 9:09 8/26/2024 9:09 8/26/2024 9:07 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:06	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT	Key & Lock Painting Painting Carpentry Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693 Z3-029465 Z3-029465 Z3-029464 Z3-029462 Z3-029458 Z3-029457 Z3-029455 Z3-029455 Z3-029454 Z3-029454 Z3-029454 Z3-029454	Key won't go in lock Requesting touch up paint r principal, please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights. Replace emergency lights. Replace emergency lights. Replace emergency lights. Thx
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:12 8/26/2024 9:11 8/26/2024 9:11 8/26/2024 9:09 8/26/2024 9:09 8/26/2024 9:08 8/26/2024 9:08 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:06	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT	Key & Lock Painting Painting Carpentry Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-032856 Z3-029468 Z3-029465 Z3-029462 Z3-029460 Z3-029458 Z3-029452 Z3-029455 Z3-029455 Z3-029455 Z3-029455	Key won't go in lock Requesting touch up paint r principal, please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights. Replace emergency lights. Replace emergency lights. Replace emergency lights. Thx
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:13 8/26/2024 9:11 8/26/2024 9:11 8/26/2024 9:10 8/26/2024 9:09 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:04 8/16/2024 9:04	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT	Key & Lock Painting Painting Carpentry Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693 Z3-032856 Z3-029468 Z3-029467 Z3-029462 Z3-029462 Z3-029455 Z3-029455 Z3-029454 Z3-029451 Z3-029451 Z3-029451 Z3-029451	Key won't go in lock Requesting touch up paint r principal, please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights. Replace emergency lights. Replace emergency lights. Replace emergency lights. Thx
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 10:56 3/20/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:12 8/26/2024 9:11 8/26/2024 9:10 8/26/2024 9:09 8/26/2024 9:09 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:04 8/16/2024 9:04 8/16/2024 9:04	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT	Key & Lock Painting Painting Carpentry Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-032856 Z3-029468 Z3-029465 Z3-029462 Z3-029460 Z3-029452 Z3-029452 Z3-029454 Z3-029454 Z3-029455 Z3-029454 Z3-029454 Z3-029454 Z3-029457 Z3-029454 Z3-029457 Z3-029454 Z3-029457 Z3-029457 Z3-029457 Z3-029457 Z3-029457 Z3-029457 Z3-029457 Z3-029457	Key won't go in lock Requesting touch up paint r principal, please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights. Replace emergency lights. Replace emergency lights. Replace emergency lights. Thx
William Herbert Brewster Elementary William Herbert Brewster Elementary Willow Oaks Elementary	5/10/2024 10:29 6/13/2024 10:56 3/20/2024 10:39 11/6/2024 7:45 9/16/2024 9:13 8/26/2024 9:13 8/26/2024 9:11 8/26/2024 9:11 8/26/2024 9:10 8/26/2024 9:09 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:06 8/26/2024 9:04 8/16/2024 9:04	SMITH BURCHETT BURCHETT BARNES SCOTT WHITWORTH SCOTT	Key & Lock Painting Painting Carpentry Electrical	Z2-014058 Z2-018292 Z2-005571 Z3-016290 Z3-039693 Z3-032856 Z3-029468 Z3-029467 Z3-029462 Z3-029462 Z3-029455 Z3-029455 Z3-029454 Z3-029451 Z3-029451 Z3-029451 Z3-029451	Key won't go in lock Requesting touch up paint r principal, please paint "reserve "/post signage on at least 4 parking spaces in front of building. Cafe entry doors left side door has lost magnetization. Won't stay open and connected. Replace bad ballast in lights. Thx Door has lost magnetization. Thx Replace emergency lights. Replace emergency lights. Replace emergency lights. Replace emergency lights. Thx

MEH O-I Flam	0/4 4/000 4 00:04	COOTT	Flooring	70 007040	Produce combination will the Thir
Willow Oaks Elementary	8/14/2024 22:01	SCOTT	Electrical	Z3-027612	Replace combo emergency light. Thx
Willow Oaks Elementary	8/14/2024 22:00	SCOTT	Electrical	Z3-027611	Replace combo emergency light. Thx
Willow Oaks Elementary	8/5/2024 11:22	SCOTT	Electrical	Z3-025269	Replace lighting component. Bulbs are shorting out. Thx
Willow Oaks Elementary	7/29/2024 9:16	SCOTT	Electrical	Z3-023196	Bad ballast needs replacing.
Willow Oaks Elementary	6/18/2024 9:17	SCOTT	Electrical	Z3-018704	Barn light has fallen from bldg. Fixture and bulb needs replacing.
Willow Oaks Elementary	12/13/2024 10:19		Fire Alarm System	Z3-044874	Fire panel for G bldg annex has a trouble detected.
Willow Oaks Elementary	12/2/2024 8:24		Fire Alarm System	Z3-042269	Fire panel showing trouble.
Willow Oaks Elementary	9/3/2024 8:41		Fire Alarm System	Z3-030609	Trouble detected.
Willow Oaks Elementary	5/6/2024 12:57	SMALL	Fire Alarm System	Z3-013226	Fire alarm panel in trouble.
,	5/16/2024 10:44	SMALL		Z3-013220 Z3-014845	·
Willow Oaks Elementary			Fire Extinguishers		Fire extinguisher is in need of recharging services. Thx
Willow Oaks Elementary	3/19/2024 10:48	SMALL	Fire Extinguishers	23-0053/3	esting a new class K extinguisher for kitchen area. Current extinguisher has been used recently. Thx
					Requesting a first time sprinkler inspection visit and report for new addition. Thx
Willow Oaks Elementary	8/7/2024 14:18	SMALL	Fire Sprinkler System	Z3-026156	
Willow Oaks Elementary	3/19/2024 13:37	CORONADO	Masonry	Z3-005430	Need holes left from removed sink to be filled in. Thx
Willow Oaks Elementary	12/16/2024 8:41	TOLES	Plumbing	Z3-044983	Replace missing floor drain cover. Thx
-			-		Requesting enclosed fencing around new annex to prevent unauthorized entry. A visit to
					discuss is welcomed. Thx
Willow Oaks Elementary	8/22/2024 9:17	KINARD	Welding	Z3-029052	
Winchester Elementary	9/4/2024 14:10	FORD	Carpentry	Z4-030962	The hinge on the handicap stall door is broken and causes the door to swing wide with force.
	5/17/2024 13:59	BENTON		W0992104	
Winchester Elementary			Carpet Repair		Can the carpet in room 34 please be removed because of mildew?
Winchester Elementary	12/10/2024 9:45	TEDDER	Electrical	Z4-044225	The emergency in the entry to the cafeteria isn't coming on.
Winchester Elementary	12/9/2024 7:05	HALL	Electrical	Z4-043928	The right exterior light is not coming on.
Winchester Elementary	10/30/2024 7:07	HALL	Electrical	Z4-038812	exterior light mounted to the brick wall outside of room 27 isn't coming on with the other lights
					Plant Manager Toliver reported there is a partial power outage at the school. It is affecting
					all badge readers, all HVAC units, and some receptacles. 416-3152.
Winchester Elementary	9/23/2024 7:05	TEDDER	Electrical	Z4-034088	
Winchester Elementary	6/28/2024 9:00	HALL	Electrical	Z4-019732	The right bottle fill station doesn't have power to it while being plugged in.
Winchester Elementary	5/1/2024 9:11	HALL	Electrical	Z4-012479	Exit sign above side exit door not coming on.
•					ů
Winchester Elementary	5/17/2024 14:23	CHASE	Flooring	WO1005046	rpet replaced with tile due to bad odor, age, and damage? The custodial vendor has tried extracting and still has odor issues.
					Mr. Tollzer (212 2535) Boiler is working but No heat in room 28
Winchester Elementary	12/12/2024 8:52	WRIGHT	Heating/Ventilation/Air Conditioning	Z4-044575	
					Mr. Tollzer (212 2535) Boiler is working but No heat in room 13
Winchester Elementary	12/12/2024 8:50	WRIGHT	Heating/Ventilation/Air Conditioning	Z4-044573	
Winchester Elementary	10/28/2024 8:12	MALONE	Key & Lock	Z4-038445	Can I please get a key made for room 24?
Winchester Elementary	9/6/2024 10:46	SMITH	Key & Lock	Z4-031302	Can I please get a key made for the custodial access to the C building/Annex building
Winchester Elementary	8/1/2024 10:36	BURCHETT	Masonry	Z4-024377	Can I please get broken tile replaced over the 2 comp sink under the window seal?
Winchester Elementary	9/5/2024 7:43	BURCHETT	Painting	Z4-031011	There are multiple areas of paint chipping on the wall directly beneath the stage.
-			-		
Winchester Elementary	8/1/2024 10:34	BURCHETT	Painting	Z4-024373	e supervisors office painted and areas around the windows throughout the kitchen painted because of peeling?
Winchester Elementary	7/25/2024 10:17	BURCHETT	Painting	Z4-022555	Can I please get the entire wall near the dry erase board painted?
Winchester Elementary	12/13/2024 9:19	JOHNSON	Plumbing	Z4-044857	Can I please get a new toilet seat for the principals toilet?
Winchester Elementary	12/10/2024 7:20	JOHNSON	Plumbing	Z4-044151	The toilet is leaking around the base or seal when the toilet is flushed
Winchester Elementary	12/9/2024 7:19	JOHNSON	Plumbing	Z4-043930	The last stall isn't flushing
Winchester Elementary	11/1/2024 6:49	JOHNSON	Plumbing	Z4-039166	The last urinal has a leak from the flush valve when flushed
Winchester Elementary	10/21/2024 9:54	JOHNSON	Plumbing	Z4-037641	The last urinal is leaking from the flush valve handle
Winchester Elementary	6/13/2024 9:17	JOHNSON	Plumbing	Z4-018258	The filter light isn't resetting for the new filter install.
·····,					the cabinet door is fallen off and this is a sped classroom
Winridge Elementary	9/23/2024 10:05	WEBB	Carpentry	Z3-034176	the capital door to falcer on that this is a speed classicom
Willinge Elementary	3/23/2024 10:03	WEDD	Carpentry	23-034170	I have a provide out aciliar tile that has an axis size handing from it
					I have a special cut ceiling tile that has an exit sign hanging from it
Winridge Elementary	9/13/2024 10:00	WEBB	Carpentry	Z3-032597	
Winridge Elementary	6/21/2024 13:26	BARNES	Carpentry	Z3-019074	The window was hit by a bullet or rock however needs to be replaced
Winridge Elementary	12/5/2024 7:23	SCOTT	Electrical	Z3-043425	Ballast is partially blown in this room 1st row 2nd light
Winridge Elementary	12/5/2024 7:22	SCOTT	Electrical	Z3-043424	Ballast blown in this room 1st row 2nd light
Winridge Elementary	12/4/2024 10:02	SCOTT	Electrical	Z3-043258	Ballast blown in front office area
Winridge Elementary	12/4/2024 10:01	SCOTT	Electrical	Z3-043256	Ballast blown in front area oval
Winridge Elementary	12/4/2024 9:59	SCOTT	Electrical	Z3-043254	Ballast blown in the front oval area multiple are principal would like them fixed by the 20
Winridge Elementary	12/4/2024 9:59	SCOTT	Electrical	Z3-043254 Z3-043252	Ballast blown in the front area oval multiple
		SCOTT			
	10/4/00040-57	SCOTI	Electrical	Z3-043250	Ballast blown in the oval area multiple
Winridge Elementary	12/4/2024 9:57	000			
					we have four lights in this area can we do them over fall break
Winridge Elementary Winridge Elementary	12/4/2024 9:57 10/2/2024 10:06	SCOTT	Electrical	Z3-035893	
			Electrical	Z3-035893	we nave rour lights in this area can we do them over rail break we have seven lights out in this area. The lift is here but need to be charged
			Electrical Electrical	Z3-035893 Z3-035892	
Winridge Elementary	10/2/2024 10:06	SCOTT			
Winridge Elementary	10/2/2024 10:06	SCOTT			we have seven lights out in this area. The lift is here but need to be charged

Winridge Elementary	7/30/2024 7:47	WHITWORTH	Electrical	Z3-023570	Partial ballast blown in this room can we add a receptacle in this room its only one
Winridge Elementary Winridge Elementary	7/22/2024 15:41 5/22/2024 12:26	SCOTT	Electrical Fire Alarm System	Z3-022018 Z3-015685	POCA These doors need a Magnet connection The only discrepancies noted were with the BPS batteries. There are a total of five BPSs - four above the FACP and one in Electrical Room D112. All batteries are depleted below the lowest acceptable power level and must be replaced. A total of ten 12V 7ah batteries.
Winridge Elementary	2/6/2024 11:33	SMALL	Fire Alarm System	Z3-000386	
Winridge Elementary	5/22/2024 12:13	SMALL	Fire Sprinkler System	Z3-015669	POCA need sprinkler head in office record room. Need a sprinkler ring/head in room A112 BOILER - PUMP 6 & 7 IS IN ALARM PM/PHILLIPS 416-6618
Winridge Elementary	12/12/2024 12:47	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-044730	
Winridge Elementary	12/4/2024 7:47	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-043112	Ms. Phillip (6618) Windridge ES Boiler keeps going to alarm. wont warm up entire building ms. PHILLIPS, 66618 BOILER IN ALARM
Winridge Elementary	12/2/2024 10:11	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-042391	AHU #4 - SHORTAGE OUT YESTERDAY - HAS A BURNING SMELL - FIRE DEPT CAME OUT - PM/PHILLIPS 416-6618
Winridge Elementary	10/7/2024 7:12	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-036370	t is a leak in the kitchen coming from the HVAC the roofer has identified it
Winridge Elementary	9/17/2024 10:51	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-033182	Plant Manager Phillips reported the ac unit in the guidance suite is not coming on at all. 416- 6618.
Winridge Elementary	8/6/2024 14:24	GOETHIE	Heating/Ventilation/Air Conditioning	Z3-025791	0010.
Winridge Elementary	5/28/2024 15:57	SMITH	Key & Lock	Z3-016186	The lock is on the wrong side we are using it as an office area and we need this door to lock the principal is requesting to have this room painted
Winridge Elementary	7/31/2024 9:12	BRYANT	Painting	Z3-024042	annual testing of 4- backflow preventers
Winridge Elementary	10/3/2024 13:38	WILSON	Plumbing	Z3-036152	annual testing of 4 bucktow preventers
Winridge Elementary	8/29/2024 7:15	HATCH	Sheet Metal	Z3-030148	I have several downward water spouts that are bent up
Winridge Elementary	8/29/2024 7:13	HATCH	Sheet Metal	Z3-030147	I have some downward water spouts that are bent up slams very hard needs to be slowed down
Wooddale High Wooddale High	12/13/2024 12:15 12/13/2024 12:14	WEBB	Carpentry Carpentry	Z3-044899 Z3-044898	door is to hard to pull open
		WEBB			door handle broke hanging down
Wooddale High	12/13/2024 11:04		Carpentry	Z3-044885	needs handles
Wooddale High	12/13/2024 8:39	WEBB	Carpentry	Z3-044840	needs handles
Wooddale High	12/13/2024 8:36	WEBB	Carpentry	Z3-044839	both doors need handles
Wooddale High	12/12/2024 13:34	WEBB	Carpentry	Z3-044753	special cut tiles high ceiling in the library needs replaced
Wooddale High	9/23/2024 10:56	CROUSE	Carpentry	Z3-034208	needs new sheet rock
Wooddale High	9/20/2024 11:44	WEBB	Carpentry	Z3-034008	
Wooddale High	3/25/2024 10:12	BARNES	Carpentry	Z3-006122	Window need to be replaced
Wooddale High	3/25/2024 10:06	BARNES	Carpentry	Z3-006120	Window need to be replaced
Wooddale High	3/25/2024 9:48	BARNES	Carpentry	Z3-006109	Window need to be replaced ballas out i see the ticket closed out but it's still out
Wooddale High	12/12/2024 13:06	SCOTT	Electrical	Z3-044742	several lights are out. Staff and students are feeling unsafe leaving the building. It is
Wooddale High	12/3/2024 6:30	SCOTT	Electrical	Z3-042669	basketball season please help.
Wooddale High	11/19/2024 10:31	SCOTT	Electrical	Z3-041486	switches to turn lights out
Wooddale High	11/1/2024 12:24	CHALK	Electrical	Z3-039283	Upgrade gym lights to LED high ceiling lights need bulbs replaced
Wooddale High	10/16/2024 12:34	SCOTT	Electrical	Z3-037237	туп сенту чуть песи иших терисси

					stage lights
Wooddale High	10/16/2024 9:38	SCOTT	Electrical	Z3-037187	stage ugits
Wooddale High	9/27/2024 7:09	SCOTT	Electrical	Z3-035003	ballast out
_					several ballast out
Wooddale High	9/25/2024 7:07	SCOTT	Electrical	Z3-034559	several ballast out
Wooddale High	9/25/2024 7:06	SCOTT	Electrical	Z3-034558	Thomas, 416-2448 Flickering lights when turned on. Not coming completely on
Wooddale High	9/24/2024 7:24	SCOTT	Electrical	Z3-034341	
Wooddale High	9/23/2024 13:47	SCOTT	Electrical	Z3-034298	ballast out
Wooddale High	9/23/2024 10:52	SCOTT	Electrical	Z3-034199	stage lights out
					ballast out
Wooddale High	9/20/2024 13:33	SCOTT	Electrical	Z3-034050	balance out
Wooddale High	9/19/2024 13:05	SCOTT	Electrical	Z3-033806	several lights out please help trying to prepare for the superintend
Wooddale High	9/19/2024 7:18	SCOTT	Electrical	Z3-033549	
Wooddale High	9/18/2024 7:12	SCOTT	Electrical	Z3-033330	balance out
Wooddale High	9/18/2024 7:11	SCOTT	Electrical	Z3-033329	parking lot lights
					Kitchen hood not working
Wooddale High	8/14/2024 14:02	WHITWORTH	Electrical	Z3-027565	
Wooddale High	5/28/2024 14:56	SCOTT	Electrical	Z3-016175	Exit sign out stage floor needs to be repaired.
Wooddale High	12/12/2024 9:17		Flooring	Z3-044589	otago noor noodo to po repunda.
			_		stage to be polished for the arrival of the superintendent
Wooddale High	9/19/2024 8:08	CASEY	Flooring	Z3-033567	
Wooddale High	5/17/2024 13:54	CHASE	Flooring	WO991001	carpet remover in room 103 heater blowing cold air
Wooddale High	12/12/2024 7:49	WALLACE	Heating/Ventilation/Air Conditioning	Z3-044537	neater blowing cold an
					blowers need to be turned off
Wooddale High	12/5/2024 9:19	WALLACE	Heating/Ventilation/Air Conditioning	Z3-043508	help install door
Wooddale High	9/27/2024 6:39	SIMS	Heating/Ventilation/Air Conditioning	Z3-034996	
Wooddale High	7/31/2024 7:51	WALLACE	Heating/Ventilation/Air Conditioning	Z3-023948	Air unit not working
Wooddale High	4/18/2024 9:59	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-010219	Air not cooling
Wooddato Mg.	-17 20/2024 0100		riodanig vondadonina condidoning	20 010210	key needed for room 118A it is a different key from the main door it is a sperate office inside
					of the attendance office
Wooddale High	12/13/2024 12:13	MALONE	Key & Lock	Z3-044897	
				70.044000	GMA key principle broke hers i have the brook one
Wooddale High	12/13/2024 12:11	MALONE	Key & Lock	Z3-044896	key needed records room 118D
Wooddale High	12/12/2024 7:47	MALONE	Key & Lock	Z3-044536	stairwell key no number
Wooddale High	12/10/2024 13:38	MALONE	Key & Lock	Z3-044330	Stall welt key no number
					is requesting a Akey
Wooddale High	12/3/2024 9:37	MALONE	Key & Lock	Z3-042796	A KEY OR GMA
Wooddale High	10/29/2024 12:30	MALONE	Key & Lock	Z3-038745	
Wooddale High	10/29/2024 6:40	MALONE	Key & Lock	Z3-038599	Custodial Akey broke need a Akey
v			-		my ticket says completed but i did not receive a key for this room i put the request in after Mr. Morris left.
Wooddale High	10/24/2024 11:09	MALONE	Key & Lock	Z3-038191	rii. rionis lett.
	6/21/2024 9:53	SMALL	Key & Lock Kitchen Hood	Z3-038191 Z3-019015	Kitchen hoods not working
Wooddale High	0/21/2024 5.33	SIMALL	Kitchen nood	79-019019	base of the stage to be painted back white
Wooddale High	9/24/2024 8:12	BURCHETT	Painting	Z3-034364	bade of the stage to be painted back time
Ü			ŭ		office needs painting
Wooddale High	9/20/2024 11:46	BURCHETT	Painting	Z3-034009	
Wooddale High	6/7/2024 10:17	BURCHETT	Painting	Z3-017704	Need to be painted

Wooddale High	6/7/2024 10:14	BURCHETT	Painting	Z3-017703	Need to be painted
Wooddale High	6/7/2024 10:08	BURCHETT	Painting	Z3-017701	Needs to be painted
Wooddale High	6/7/2024 10:06	BURCHETT	Painting	Z3-017699	Needs to be painted
•			=		·
Wooddale High	6/7/2024 10:03	BURCHETT	Painting	Z3-017695	Needs to be painted
Wooddale High	6/7/2024 10:00	BURCHETT	Painting	Z3-017691	Needs to be painted
Wooddale High	5/17/2024 14:18	BURCHETT	Painting	WO1000894	Classroom 113 need to be painted
ŭ			· ·		sink want turn off on the hot side. But i have shut the water off
Wooddolo High	12/10/2024 10:02	DEADCON	Dismbing	70.044041	Sink that tall on on the not older part have shall the find of
Wooddale High	12/10/2024 10:03	PEARSON	Plumbing	Z3-044241	
					upstairs water fountain push button not working
Wooddale High	11/7/2024 13:34	BARNES	Plumbing	Z3-040157	
					Inspection prep for bottle fillers, Larry Rucker and Albert Herman
Wooddolo High	2/21/2024 7:17	CHALK	Dismbing	Z3-002192	,,,,,,,,,,
Wooddale High	2/21/2024 /.1/	CHALK	Plumbing	23-002192	
					Repair Gym Roof
Wooddale High	12/9/2024 8:04	BUFORD	Roofing	Z3-043944	
					Requesting for mold to be removed from room 410. The percentage of mold is too much for
					Building Engineer to remove.
Woodstock Middle	11/14/2024 9:08	LEWIS	Apparent Mold Growth (AMG)	Z1-040785	
Woodstock Middle	11/14/2024 9.06	LEVVIO	Apparent Piota Growth (APIG)	21-040763	
					Requesting for speaker to be placed on building outside for safety and security reason. This
					is so that staff can hear what is being said over intercom from outside.
Woodstock Middle	11/15/2024 13:26	SMITH	Audio Visual	Z1-041101	· ·
Woodstock i-lidute	11/13/2024 13:20	JI-IIIII	Addio Visual	21-041101	Description of the condition and the colored and the condition of the cond
					Requesting for a cork board to be placed on the wall next to room 400.
Woodstock Middle	11/20/2024 7:57	RUSSELL	Carpentry	Z1-041613	
					Requesting for a partition to be placed along one side to the opposite side of the wall just as
					you enter the main hall. This to keep visitors etc. from continue to walk down the main
					hallway.
Woodstock Middle	11/14/2024 14:00	STEPHENS	Carpentry	Z1-040908	
					Requesting for a special cut for the ceiling tile around the smoke detector in the mechanical
					room 100 hallway across from the lockers.
Woodstock Middle	8/7/2024 9:16	ARNOLD	Carpentry	Z1-025944	,
Woodstock Middle	8///2024 9.10	ANNOLD	Carpentry	21-025544	
					Requesting for the light switch in the boy's restroom on the 400 hallways be repaired. The
					light switch is difficult to turn on and the restroom do not have light, and the light switch
					need a cover because the students is tampering with it.
					need a cover because are stadents to tampering with the
Woodstock Middle	10/30/2024 13:47	SMITH	Electrical	Z1-038961	
					Requesting for metal light cover to be replaced/repaired. Cover latches is broken cover will
					not stay hanging in light fixture. having to remove cover/screen
	40/00/00040	014771	5	74 000050	not stay hanging in ught inxture. having to remove cover/screen
Woodstock Middle	10/30/2024 9:33	SMITH	Electrical	Z1-038859	
					HAS A BURNT SMELL ON THE 400 HALL & OUTSIDE - NOT SURE WHAT IS BURNING
					PM/DOUGLASS 416-4180
Woodstock Middle	10/30/2024 8:02	SMITH	Electrical	Z1-038830	
Woodstock i naute	10/00/2024 0.02	Ormin	Electricat	21 000000	Requesting for the light switch to be replaced. on/off switch is broken.
					Requesting for the light switch to be replaced, official switch is broken.
Woodstock Middle	10/18/2024 12:02	SMITH	Electrical	Z1-037507	
					requesting for 2 light fixture ballast to be replaced in cafeteria prep area.
Woodstock Middle	10/14/2024 12:33	SMITH	Electrical	Z1-036873	
TTO GUSTOOK T HUUTO	10/1-7/2024 12:00	0	Etottiout	21 000070	light fixture in the mechanical room next to plant manager office needs an entire frame and
					screen. Mechanical room on 100 hallway.
Woodstock Middle	8/7/2024 13:23	SMITH	Electrical	Z1-026131	
					RECEPTACLES ARE NOT WORKING IN THE CAFE - PM/DOUGLASS 416-4477
Woodstock Middle	8/2/2024 10:37	SMITH	Flectrical	Z1-024720	
					Emandana lighta need to be fixed
Woodstock Middle	4/9/2024 11:30	SMITH	Electrical	Z1-008394	Emergency lights need to be fixed
Woodstock Middle	5/17/2024 14:27	CHASE	Flooring	WO1011967	ve the Damaged carpet removed from the Dance room in the Annex building and replaced with tile.Thank you
					HEATING UNIT IN RM 302 - BLOWING COLD AIR - SHOWING 56 DEGREES - PM/DOUGLASS
					416-4180
Woodstook Middle	12/2/2024 0:00	WEDD	Heating/Ventilation/Air Conditioning	71 040770	-120 -1200
Woodstock Middle	12/3/2024 9:08	WEBB	Heating/Ventilation/Air Conditioning	Z1-042773	
					HVAC UNIT IN RM RM 303 - BLOWING NOT COOLING PM/DOUGLAS 416-4180
Woodstock Middle	8/6/2024 8:44	WEBB	Heating/Ventilation/Air Conditioning	Z1-025513	
			_		Requesting for the lock to be repaired in room 402. The doorknob is not loose, but you
					cannot open the door from inside the classroom.
M/	40/0/000	MALONE	W 2 1 1	74 0	cannot open the door from fisher the classroom.
Woodstock Middle	12/9/2024 11:12	MALONE	Key & Lock	Z1-044048	

Requesting for the bricks over the gym boy's locker room back door to be repaired.	
------------------------------------------------------------------------------------	--

					nequesting for the briefs over the gyrir boy's token footh back door to be repaired.	
Woodstock Middle	9/4/2024 9:33	BURCHETT	Masonry	Z1-030840		
					Requesting for the wall tile to be replaced that were removed in the boys restroom to repair	
					the pipes in the wall for water bottle filler.	
Woodstock Middle	8/7/2024 8:31	BURCHETT	Masonry	Z1-025895		
			,		Requesting for the TVA game room to be painted.	
Woodstock Middle	0/20/2024 0:42	DUDCUETT	Deinting	71 025245	requesting for the FVA game four to be partieu.	
Woodstock Middle	9/30/2024 8:43	BURCHETT	Painting	Z1-035345		
					Requesting for the left and right-side parking spaces in the front of the building be painted,	
					(principal, asst principal etc.) the no parking spaces in front of the building be painted	
					including the yellow on the front curb /sidewalk in the front of the building. Handicap	
					spaces. spaces on large parking area on the left side of the building.	
Woodstock Middle	9/6/2024 12:43	BURCHETT	Painting	Z1-031346	oparest spaces on ango paraning area on the text state of the ballating.	
Woodstock Middle	6/6/2024 13:31	BURCHETT	Painting	Z1-017586	Classrooms need to be repainted	
Woodstock Middle	5/17/2024 14:26	BURCHETT	Painting	WO1010706	e the shower area in the Girls locker room painted due to chipping paint as well as damaged drywall.Thank you.	
Woodstock Middle	5/17/2024 14:26	BURCHETT	Painting	WO1010653	est is to have the entire cafeteria painted due to chipping and getting into some food trays. Thank you	
					The water fountains boards on the 400-hallway red light continue to stay on. The water	
					bottle filter has been changed, student will not use fountain with light on, fountain across	
					from room 402 and 406.	
Maradaka ali Milalda	40/40/000440-00		Diversión	74 044070	11011 10011 402 and 400.	
Woodstock Middle	12/13/2024 10:26		Plumbing	Z1-044878		
					The restroom in the parent teacher conference room smells like sewage and the smell is	
					coming out into the front lobby/ hallway. There is no floor drain to pour water down as if the	
					drain were dry. room location is across the hallway from the main office, first door on the	
					left.	
Woodstock Middle	12/13/2024 8:47	SINK	Plumbing	Z1-044845		
Woodstock i-liddle	12/13/2024 0.4/	SIIVIK	i tullibilig	21-044043	Test RP device as noted on letter.	
					rest RP device as noted on retter.	
Woodstock Middle	12/10/2024 10:06	OWENS	Plumbing	Z1-044242		
					the pipes in room 412 is leaking from the water valve.	
Woodstock Middle	11/7/2024 10:25	Jordan	Plumbing	Z1-040107		
			_		annule testing of backflow devices	
Woodstock Middle	10/3/2024 12:40	WILSON	Plumbing	Z1-036126		
WoodstockThadic	10/0/2024 12.40	WILDON	i tumbing	21 000120		
					Room 401 has a roof, Leake. again. location: just as you walk into room to the right.	
Woodstock Middle	12/12/2024 10:54	DIAZ	Roofing	Z1-044696	Room 401 has a root, Leake. again. location: just as you walk into room to the right.	
Woodstock Middle	12/12/2024 10:54	DIAZ	Roofing	Z1-044696	Room 4U1 has a root, Leake. again. location: just as you walk into room to the right.	
Woodstock Middle	12/12/2024 10:54	DIAZ	Roofing	Z1-044696	Noom 401 has a root, Leake, again, location: just as you walk into room to the right. Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening	
			-			
Woodstock Middle Zone 1 Monthly	12/12/2024 10:54 7/24/2024 9:26	DIAZ	Roofing Carpentry	Z1-044696 Z1-022289		
			-		Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening	
			-		Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH	
Zone 1 Monthly	7/24/2024 9:26	OLIVER	Carpentry	Z1-022289	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening	
			-		Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH	
Zone 1 Monthly	7/24/2024 9:26	OLIVER	Carpentry	Z1-022289	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH	
Zone 1 Monthly	7/24/2024 9:26	OLIVER	Carpentry	Z1-022289	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024	
Zone 1 Monthly	7/24/2024 9:26	OLIVER	Carpentry	Z1-022289	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF	
Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54	OLIVER	Carpentry Heating/Ventilation/Air Conditioning	Z1-022289 Z1-042120	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE	
Zone 1 Monthly	7/24/2024 9:26	OLIVER	Carpentry	Z1-022289	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF	
Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54	OLIVER	Carpentry Heating/Ventilation/Air Conditioning	Z1-022289 Z1-042120	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024	
Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54	OLIVER	Carpentry Heating/Ventilation/Air Conditioning	Z1-022289 Z1-042120	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF	
Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54	OLIVER	Carpentry Heating/Ventilation/Air Conditioning	Z1-022289 Z1-042120	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59	OLIVER	Carpentry Heating/Ventilation/Air Conditioning Plumbing	Z1-022289 Z1-042120 Z1-042123	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF	
Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54	OLIVER ANDREWS Jordan	Carpentry Heating/Ventilation/Air Conditioning	Z1-022289 Z1-042120	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59	OLIVER ANDREWS Jordan	Carpentry Heating/Ventilation/Air Conditioning Plumbing	Z1-022289 Z1-042120 Z1-042123	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW - FOR ZONE 2 - ELECTRICAL/HVAC MATERIALS/SUPPLIES FOR DECEMBER	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59 11/22/2024 15:01	OLIVER ANDREWS Jordan SHIPPS	Carpentry Heating/Ventilation/Air Conditioning Plumbing Sheet Metal	Z1-022289 Z1-042120 Z1-042123 Z1-042124	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59	OLIVER ANDREWS Jordan	Carpentry Heating/Ventilation/Air Conditioning Plumbing	Z1-022289 Z1-042120 Z1-042123	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW - FOR ZONE 2 - ELECTRICAL/HVAC MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59 11/22/2024 15:01	OLIVER ANDREWS Jordan SHIPPS	Carpentry Heating/Ventilation/Air Conditioning Plumbing Sheet Metal	Z1-022289 Z1-042120 Z1-042123 Z1-042124	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW - FOR ZONE 2 - ELECTRICAL/HVAC MATERIALS/SUPPLIES FOR DECEMBER	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59 11/22/2024 15:01	OLIVER ANDREWS Jordan SHIPPS	Carpentry Heating/Ventilation/Air Conditioning Plumbing Sheet Metal	Z1-022289 Z1-042120 Z1-042123 Z1-042124	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW - FOR ZONE 2 - ELECTRICAL/HVAC MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59 11/22/2024 15:01 11/25/2024 7:35	OLIVER ANDREWS Jordan SHIPPS HAMMETT	Carpentry Heating/Ventilation/Air Conditioning Plumbing Sheet Metal Heating/Ventilation/Air Conditioning	Z1-022289 Z1-042120 Z1-042123 Z1-042124 Z2-042142	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW - FOR ZONE 2 - ELECTRICAL/HVAC MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - ROOFERS/SHEETMETAL/WELDERS MATERIALS/SUPPLIES	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59 11/22/2024 15:01	OLIVER ANDREWS Jordan SHIPPS	Carpentry Heating/Ventilation/Air Conditioning Plumbing Sheet Metal	Z1-022289 Z1-042120 Z1-042123 Z1-042124	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW - FOR ZONE 2 - ELECTRICAL/HVAC MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - ROOFERS/SHEETMETAL/WELDERS MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59 11/22/2024 15:01 11/25/2024 7:35	OLIVER ANDREWS Jordan SHIPPS HAMMETT	Carpentry Heating/Ventilation/Air Conditioning Plumbing Sheet Metal Heating/Ventilation/Air Conditioning	Z1-022289 Z1-042120 Z1-042123 Z1-042124 Z2-042142	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW - FOR ZONE 2 - ELECTRICAL/HVAC MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - ROOFERS/SHEETMETAL/WELDERS MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - PLUMBERS/CARPENTERS MATERIALS/SUPPLIES FOR	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly Zone 2 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59 11/22/2024 15:01 11/25/2024 7:35 11/25/2024 7:49	OLIVER ANDREWS Jordan SHIPPS HAMMETT STAFFORD	Carpentry Heating/Ventilation/Air Conditioning Plumbing Sheet Metal Heating/Ventilation/Air Conditioning Plumbing	Z1-022289 Z1-042120 Z1-042123 Z1-042124 Z2-042142 Z2-042148	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW - FOR ZONE 2 - ELECTRICAL/HVAC MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - ROOFERS/SHEETMETAL/WELDERS MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59 11/22/2024 15:01 11/25/2024 7:35	OLIVER ANDREWS Jordan SHIPPS HAMMETT	Carpentry Heating/Ventilation/Air Conditioning Plumbing Sheet Metal Heating/Ventilation/Air Conditioning	Z1-022289 Z1-042120 Z1-042123 Z1-042124 Z2-042142	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW - FOR ZONE 2 - ELECTRICAL/HVAC MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - ROOFERS/SHEETMETAL/WELDERS MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - PLUMBERS/CARPENTERS MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly Zone 2 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59 11/22/2024 15:01 11/25/2024 7:35 11/25/2024 7:49	OLIVER ANDREWS Jordan SHIPPS HAMMETT STAFFORD	Carpentry Heating/Ventilation/Air Conditioning Plumbing Sheet Metal Heating/Ventilation/Air Conditioning Plumbing	Z1-022289 Z1-042120 Z1-042123 Z1-042124 Z2-042142 Z2-042148	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW - FOR ZONE 2 - ELECTRICAL/HVAC MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - ROOFERS/SHEETMETAL/WELDERS MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - PLUMBERS/CARPENTERS MATERIALS/SUPPLIES FOR	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly Zone 2 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59 11/22/2024 15:01 11/25/2024 7:35 11/25/2024 7:49	OLIVER ANDREWS Jordan SHIPPS HAMMETT STAFFORD	Carpentry Heating/Ventilation/Air Conditioning Plumbing Sheet Metal Heating/Ventilation/Air Conditioning Plumbing	Z1-022289 Z1-042120 Z1-042123 Z1-042124 Z2-042142 Z2-042148	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW - FOR ZONE 2 - ELECTRICAL/HVAC MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - ROOFERS/SHEETMETAL/WELDERS MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - PLUMBERS/CARPENTERS MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly Zone 2 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59 11/22/2024 15:01 11/25/2024 7:35 11/25/2024 7:49	OLIVER ANDREWS Jordan SHIPPS HAMMETT STAFFORD	Carpentry Heating/Ventilation/Air Conditioning Plumbing Sheet Metal Heating/Ventilation/Air Conditioning Plumbing	Z1-022289 Z1-042120 Z1-042123 Z1-042124 Z2-042142 Z2-042148	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW - FOR ZONE 2 - ELECTRICAL/HVAC MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - ROOFERS/SHEETMETAL/WELDERS MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - PLUMBERS/CARPENTERS MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW FOR ZONE 3/ELECTRICAL/HVAC MATERIALS SUPPLIES FOR THE MONTH	
Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly Zone 1 Monthly Zone 2 Monthly	7/24/2024 9:26 11/22/2024 14:54 11/22/2024 14:59 11/22/2024 15:01 11/25/2024 7:35 11/25/2024 7:49	OLIVER ANDREWS Jordan SHIPPS HAMMETT STAFFORD	Carpentry Heating/Ventilation/Air Conditioning Plumbing Sheet Metal Heating/Ventilation/Air Conditioning Plumbing	Z1-022289 Z1-042120 Z1-042123 Z1-042124 Z2-042142 Z2-042148	Disassemble 13 desks and 2 conference tables that are allocated for Fairley High reopening MONTHLY DRAW FOR ZONE 1/ELECTRICAL/HVAC MATERIAL SUPPLIES FOR THE MONTH DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW FOR ZONE 1/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF DECEMBER 2024 MONTHLY DRAW - FOR ZONE 2 - ELECTRICAL/HVAC MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - ROOFERS/SHEETMETAL/WELDERS MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW - FOR ZONE 2 - PLUMBERS/CARPENTERS MATERIALS/SUPPLIES FOR DECEMBER - 2024 HW MONTHLY DRAW FOR ZONE 3/ELECTRICAL/HVAC MATERIALS SUPPLIES FOR THE MONTH OF	

MONTHLY DRAW FOR ZONE 3/ELECTRICAL/HVAC MATERIALS SUPPLIES FOR THE MONTH

OF
NOVEMBER 2024

7 014 111		14/1/17/1/05/71/1		70 000100	NOVERIBEN 2024
Zone 3 Monthly	11/1/2024 8:44	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-039199	
					MONTHLY DRAW FOR ZONE 3/ELECTRICAL/HVAC MATERIALS SUPPLIES FOR THE MONTH
					OF
					OCTOBER 2024
Zone 3 Monthly	9/30/2024 10:12	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-035414	
,					MONTHLY DRAW FOR ZONE 3/ELECTRICAL/HVAC MATERIALS SUPPLIES FOR THE MONTH
					OF
					SEPTEMBER 2024
Zone 3 Monthly	9/3/2024 9:32	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-030652	
					MONTHLY DRAW FOR ZONE 3/ELECTRICAL/HVAC MATERIALS
					SUPPLIES FOR THE MONTH OF AUGUST 2024
Zone 3 Monthly	8/6/2024 9:58	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-025596	
Zone 3 Hondry	6/0/2024 9:36	WITHWORTH	rieding/ventilation/All Conditioning	25-025550	MONTHLY DRAW FOR ZONE 3/ELECTRICAL/HVAC MATERIALS
					SUPPLIES FOR THE MONTH OF JULY 2024
Zone 3 Monthly	7/1/2024 7:25	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-019840	
					MONTHLY DRAW FOR ZONE 3/ELECTRICAL/HVAC MATERIALS
					SUPPLIES FOR THE MONTH OF JUNE 2024
Zone 3 Monthly	6/3/2024 7:51	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-016833	
Zone or ionary	0/0/2024 / .01	WILLIAMORTH	ricanily ventuation / in Conditioning	20 010000	MONTHLDY DRAW FOR ZONE 3/ELECTRICAL/HVAC MATERIALS
					SUPPLIES FOR THE MONTH OF APRIL 2024
Zone 3 Monthly	4/1/2024 11:01	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-007005	
					MONTHLDY DRAW FOR ZONE 3/ELECTRICAL/HVAC MATERIALS
					SUPPLIES FOR THE MONTH OF MARCH 2024
Zone 3 Monthly	3/1/2024 9:04	WHITWORTH	Heating/Ventilation/Air Conditioning	Z3-003508	
20110 01 10110119	3, 1, 2, 5, 5, 5, 5	***************************************	Trouble Vollatation 7 to Conditioning	20 000000	MONTHLY DRAW FOR ZONE 3/PLUMBERS/CARPENTERS/ROOFERS SUPPLIES FOR THE
					MONTH OF
					December 2024
Zone 3 Monthly	11/22/2024 14:36	TOLES	Plumbing	Z3-042112	
					MONTHLY DRAW FOR ZONE 3/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF
					December 2024
Zone 3 Monthly	11/22/2024 14:42	HATCH	Sheet Metal	Z3-042114	
,					MONTHLY DRAW FOR ZONE 4/ELECTRICAL/HVAC MATERIALS
					SUPPLIES FOR THE MONTH OF December 2024
				7	SUFFLIES FOR THE MONTH OF December 2024
Zone 4 Monthly	11/22/2024 13:58	JACKSON	Heating/Ventilation/Air Conditioning	Z4-042100	
					MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING
					MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING SUPPLIES FOR THE MONTH OF December 2024
Zone 4 Monthly	11/22/2024 13:56	TEDDER	Plumbing	Z4-042098	
Zone 4 Monthly	11/22/2024 13:56	TEDDER	Plumbing	Z4-042098	
Zone 4 Monthly	11/22/2024 13:56	TEDDER	Plumbing	Z4-042098	SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING
-					SUPPLIES FOR THE MONTH OF December 2024
Zone 4 Monthly Zone 4 Monthly	11/22/2024 13:56 10/31/2024 11:06	TEDDER	Plumbing Plumbing	Z4-042098 Z4-039085	SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING SUPPLIES FOR THE MONTH OF November 2024
-					SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING SUPPLIES FOR THE MONTH OF November 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING
-					SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING SUPPLIES FOR THE MONTH OF November 2024
-					SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING SUPPLIES FOR THE MONTH OF November 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING
Zone 4 Monthly	10/31/2024 11:06	TEDDER	Plumbing	Z4-039085	SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING SUPPLIES FOR THE MONTH OF November 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING
Zone 4 Monthly	10/31/2024 11:06	TEDDER	Plumbing	Z4-039085	SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING SUPPLIES FOR THE MONTH OF November 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF December 2024
Zone 4 Monthly Zone 4 Monthly	10/31/2024 11:06 11/22/2024 13:52	TEDDER TEDDER	Plumbing Sheet Metal	Z4-039085 Z4-042096	SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING SUPPLIES FOR THE MONTH OF November 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING
Zone 4 Monthly	10/31/2024 11:06	TEDDER	Plumbing	Z4-039085	SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING SUPPLIES FOR THE MONTH OF November 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF November 2024
Zone 4 Monthly Zone 4 Monthly	10/31/2024 11:06 11/22/2024 13:52 10/31/2024 11:07	TEDDER TEDDER TEDDER	Plumbing Sheet Metal Sheet Metal	Z4-039085 Z4-042096 Z4-039086	SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING SUPPLIES FOR THE MONTH OF November 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING
Zone 4 Monthly Zone 4 Monthly	10/31/2024 11:06 11/22/2024 13:52	TEDDER TEDDER	Plumbing Sheet Metal	Z4-039085 Z4-042096	SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING SUPPLIES FOR THE MONTH OF November 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF November 2024 replace convertor and winch for sewer machine
Zone 4 Monthly Zone 4 Monthly	10/31/2024 11:06 11/22/2024 13:52 10/31/2024 11:07 11/21/2024 8:00	TEDDER TEDDER TEDDER STAFFORD	Plumbing Sheet Metal Sheet Metal Vehicle Maintenance	Z4-039085 Z4-042096 Z4-039086 Z1-041835	SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING SUPPLIES FOR THE MONTH OF November 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF November 2024
Zone 4 Monthly Zone 4 Monthly	10/31/2024 11:06 11/22/2024 13:52 10/31/2024 11:07	TEDDER TEDDER TEDDER	Plumbing Sheet Metal Sheet Metal	Z4-039085 Z4-042096 Z4-039086	SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/PLUMBING/CARPENTRY/ROOFING SUPPLIES FOR THE MONTH OF November 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF December 2024 MONTHLY DRAW FOR ZONE 4/SHEET METAL/WELDING SUPPLIES FOR THE MONTH OF November 2024 replace convertor and winch for sewer machine

Dec. 15, 2024 Intercom Project Update

School	MSCS Board Member	Est 2024-25 Completion	Cabling	Equipment Order Status	Est Equip Install	Est Switch Install
Brewster ES	McKinney	Dec-24	Complete	Delivered	Nov-24	Complete
Cherokee ES	Coleman	Complete	Complete	Delivered	Complete	Complete
Douglass ES	McKinney	Jan-25	Complete	Delivered	Jan-25	Complete
Idlewild ES	McKissack	Jan-25	Complete	Delivered	Dec-24	Complete
Keystone ES	Love	Complete	Complete	Delivered	Complete	Complete
Oakshire ES	Porter	Feb-25	Complete	Delivered	Dec-24	Complete
Peabody	McKissack	Dec-24	Complete	Delivered	Complete	Complete
Richland ES	Huett-Garcia	Feb-25	Complete	Delivered	Dec-24	Complete
Ridgeway HS	Coleman	March-25	TBD	Delivered	Feb-25	Jan-25
Riverwood ES	Sable Otey	Feb-25	TBD	Delivered	Feb-25	Jan-25
Rozelle ES	McKissack	Dec-24	Complete	Delivered	Jan-25	Dec-24
Sharpe ES	Coleman	Complete	Complete	Delivered	Complete	Complete
Sherwood ES	Coleman	March-25	TBD	Delivered	March-25	Jan-25
Treadwell ES	McKinney	March-25	TBD	Delivered	March-25	Jan-25
Westside ES	Love	Complete	Complete	Delivered	Complete	Complete
Whitehaven ES	Williams	Dec-24	TBD	Delivered	Dec-24	Dec-24

	1
Bottle Filler Update 12-15-24	
Phase I Location	Status
A. Maceo MS	in prog
Balmoral ES	
Belle Forest ES	
Bolton HS	complete
Booker T. Washington MS/HS	
Carver HS	
Central HS	
Colonial MS	next
Cordova ES	
Cordova HS	
Cordova MS	
Craigmont HS	
Crump ES	
Cummings ES	in prog
Dexter ES	
Dexter MS	
Douglass Head Start	
East HS	in prog
Fairley HS	
Ford Rd. ES	
Fox Meadows ES	
Geeter MS	
Georgian Hills MS	
Germanshire ES	next
Getwell ES	
Gordon ES	
Grahamwood ES	
Grandview Hts. ES/MS	
Hamilton HS	
Hamilton MS	
Hanley ES	
Hickory Ridge ES	
Hickory Ridge MS	
Ida B. Wells Academy	
Idlewild ES	
Jackson ES	in prog
Kate Bond ES	in prog
Kate Bond MS	
Keystone ES	
Kirby HS	
LaRose ES	
Macon-Hall ES	
·	

Manassas HS	
Melrose	complete
Mt. Pisgah MS	
Newberry ES	
Oakhaven HS	in prog
Oakhaven MS	in prog
Overton HS	
Parkway Village ES	
Peabody ES	
Ral-Egypt MS	
Ridgeway HS	
Ridgeway MS	
Riverview MS	
Robert R. Church ES	
Rozelle ES	
Sea Isle ES	
Sherwood ES	next
Sherwood MS	next
Springdale ES	
Treadwell ES	in prog
Treadwell MS	in prog
Trezevant CTC	
Trezevant HS	
Westwood HS	
White Station HS	
Willow Oaks ES	
Winridge ES	

Location	Enrollment/ Staff	Age of Building (Years)	Project Type			tal Cost	Start Date	End Date	Status	MSCS Board Member	Funding Source
									Scope developed and		
				Outdoor Lighting					submitted to		
				Outdoor Lighting (softball, baseball,					Procurement for bid process. Est. January		
Bolton HS	673/77	64	Athletics	soccer)	\$	730,000	TBD		Board	Huett-Garcia	Shelby County
	515,11			LED Lighting	1	100,000					
Bolton HS	673/77	64	Electric	Upgrade-Gym	\$	35,000	TBD	TBD	Equipment Ordered	Huett-Garcia	City of Memphis
Booker T									Design		
Washington HS	435/80	75	Roof	Roof Replacement	\$	2,460,210	10/20/2024	12/15/2025	_	McKissack	MSCS - ESSER
Booker T				Window	l .				Notice to proceed		
Washington HS	435/80	75	Windows	Replacement	\$	2,292,351	10/20/2024	7/30/2025	issued.	McKissack	MSCS - ESSER
Booker T				LED Lighting	l .						
Washington HS	435/80	75	Electric	Upgrade-Gym	\$	35,000	TBD	TBD	Equipment Ordered	McKissack	City of Memphis
									Scope developed and		
									submitted to		
									Procurement for bid		
Condova	2406/404	27	Davisa	Futing Lat	_	1 000 000	TDD	TDD	process. Est. January	Otavi	Challes Cassats
Cordova HS	2186/194	27	Paving	Entire Lot	\$	1,000,000	TBD	TBD	Board	Otey	Shelby County
									Scope developed and		
				Outdoor Lighting					submitted to Procurement for bid		
				(softball, baseball,					process. Est. January		
Cordova HS	2186/194	27	Athletics	soccer)	\$	735,000	TBD	TBD	Board	Otey	Shelby County
Cordovario	2100/134		/ terricules	3000017		733,000	100	100	Scope developed and	Oley	Onetal County
									submitted to		
									Procurement for bid		
									process. Est. January		
Cordova MS	664/66	31	Paving	Entire Lot	\$	600,000	TBD	TBD	Board	Otey	MSCS Fund 1

Location	Enrollment/ Staff	Age of Building (Years)	Project Type		Total Cost	Start Date	End Date	Status	MSCS Board Member	Funding Source
Craigmont HS	808/90	51	Electric	LED Lighting Upgrade-Gym	\$ 35,000	TBD	TBD	Equipment Ordered	McKinney	City of Memphis
Craigmont MS	484/60	23	Electric	LED Lighting Upgrade-Gym	\$ 35,000	TBD	TBD	Equipment Ordered	McKinney	City of Memphis
Cromwell ES	489/67	61	HVAC	Replace Chiller, Boiler, Pumps, RTU, UV, Controls	\$ 1,938,662	10/20/2024	12/15/2025	Notice to proceed issued.	Murphy	MSCS - ESSER
								Scope developed and submitted to Procurement for bid process. Est. January		
Crump Stadium	N/A	90	Athletics	Track resurfacing	\$ 600,000	TBD	TBD	Board	McKissack	MSCS Fund 1
Dunbar ES	199/38	68	Windows	Window Replacement	\$ 1,657,650	10/20/2024	7/30/2025	Notice to proceed issued.	Coleman	MSCS - ESSER
East HS	999/106	76	Windows	Window Replacement	\$ 6,648,000	10/20/2024	7/30/2025	Notice to proceed issued.	McKinney	MSCS - ESSER
Egypt ES	504/57	58	HVAC	Replace Chiller, Boiler, UV, RTU, Pumps, Controls	\$ 2,758,457	10/20/2024	12/15/2025	Received drawings and submittals. Equipment ordered.	Love	MSCS - ESSER
Ford Road ES	588/68	72	HVAC	Chiller(2), CT(2), Boiler(2), RTU, Controls	\$ 2,919,390	10/20/2024	12/15/2025	Notice to proceed issued.	Williams	MSCS - ESSER
Fox Meadows ES	534/69	59	Roof	Roof Replacement	\$ 1,074,229	10/20/2024		Design	Coleman	MSCS - ESSER
Frayser-Corning ES	378/47	70	Foundation	Repair NW Exterior Stairwell	\$ 315,000	TBD	TBD	Scope developed and submitted to Procurement for bid process. Est. January Board	Love	City of Memphis

Location	Enrollment/ Staff	Age of Building (Years)	Project Type		otal Cost	Start Date	End Date	Status	MSCS Board Member	Funding Source
Geeter K8	637/77	63	Roof	Roof Replacement	\$ 1,965,182	10/20/2024	12/15/2025	Design	Williams	MSCS - ESSER
Georgian Hills MS	290/49	65	Electric	LED Lighting Upgrade-Gym	\$ 35,000	TBD	TBD	Equipment Ordered	Love	City of Memphis
Germantown HS	1708/164	60	1 '	Replace Fire Detection System	\$ 1,500,000	TBD		Scope developed and submitted to Procurement for bid process. Est. January Board	Porter	Shelby County
Gordon Alternative	161/48	85		Water cooled chiller, CT, Boiler, Pumps, Controls	\$ 1,422,099	10/20/2024		Notice to proceed issued.	McKissack	MSCS - ESSER
Grandview MS	413/63	71	Roof	Roof Replacement	\$ 2,105,269	10/20/2024	12/15/2025	Design	Love	MSCS - ESSER
Hollywood Admin.	350	62		Replace Fire Detection System	\$ 600,000	TBD		Scope developed and submitted to Procurement for bid process. Est. January Board	McKissack	Shelby County
Holmes Rd. ES	754/94	23	,	Replace Chiller, Boiler, Cooling Tower and Pumps, Controls	\$ 1,885,270	10/20/2024		Notice to proceed issued.	Williams	MSCS - ESSER
Idlewild ES	591/66	121	Plumbing	Reroute Sewer Line to Gym	\$ 319,500	TBD	TBD	Scope developed and submitted to Procurement for bid process. Est. January Board	McKissack	MSCS Fund 1
Invictus Academy (Airways)	225/45	56		Window Replacement	\$ 687,779	10/20/2024	7/30/2025	Notice to proceed issued.	Murphy	MSCS - ESSER

Location	Enrollment/ Staff	Age of Building (Years)	Project Type	Description	To	otal Cost	Start Date	End Date	Status	MSCS Board Member	Funding Source
Kingsbury HS	1344/139	74	HVAC	Replace SCUVs, Chiller, AHU, RTU, Controls	\$	5,708,931	10/20/2024		Notice to proceed issued.	McKinney	MSCS - ESSER
Kingsbury MS/HS	1883/192	74	Athletics	Outdoor Lighting (softball, baseball, soccer)	\$	300,000	TBD		Scope developed and submitted to Procurement for bid process. Est. January Board	McKinney	MSCS Fund 1
Kingsbury MS/HS	1883/192	74	Plumbing	Replace Gas Line	\$	3,500,000	TBD		Scope developed and submitted to Procurement for bid process. Est. January Board	McKinney	MSCS Fund 1
Kirby HS	736/95	44	Electric	LED Lighting Upgrade-Gym	\$	35,000	TBD		Equipment Ordered	Porter	City of Memphis
Norris Achievement Academy	174/21	63	HVAC	Replace Chiller and Controls	\$	469,270	10/20/2024		Notice to proceed issued.	Murphy	MSCS - ESSER
Norris Achievement Academy	174/21	63		Window Replacement	\$	2,075,546	10/20/2024		Notice to proceed issued.	Murphy	MSCS - ESSER
Oakshire ES	393/61	58		Chiller(2), Boiler(2), Pumps, UV, Controls	\$	3,168,197	10/20/2024		Notice to proceed issued.	Williams	MSCS - ESSER

Location	Enrollment/ Staff	Age of Building (Years)	Project Type			Total Cost	Start Date	End Date	Status	MSCS Board Member	Funding Source
									Scope developed and		
									submitted to		
									Procurement for bid		
	4.450/4.07	65	<u>.</u>						process. Est. January		
Overton HS	1453/137	65	Paving	Entire Lot	\$	600,000	TBD	TBD	Board	Coleman	MSCS Fund 1
				Replace Chiller, CT,			/ /		Notice to proceed		
Raileigh Egypt MS	483/52	45	HVAC	Controls	\$	1,119,073	10/20/2024	12/15/2025	issued.	Love	MSCS - ESSER
Raleigh Bartlett ES	451/55	53	Roof	Roof Replacement	\$	1,672,470	10/20/2024	12/15/2025	Design	Love	MSCS - ESSER
									Scope developed and submitted to Procurement for bid process. Est. January		
Ridgeway HS	764/87	54	Paving	60% of Lot	\$	600,000	TBD		Board	Coleman	MSCS Fund 1
				LED Lighting		-					
Ridgeway HS	764/87	54	Electric	Upgrade-Gym	\$	35,000	TBD	TBD	Equipment Ordered	Coleman	City of Memphis
				Repair Lower Floor					Scope developed and submitted to Procurement for bid process. Est. January		
Rozelle ES	237/38	110	Foundation	Walls (east end)	\$	157,500	TBD	TBD	Board	McKissack	City of Memphis
Shady Grove PK	60/50	61	Roof	Roof Replacement	\$	977,152	10/20/2024	12/15/2025	Design	Huett-Garcia	MSCS - ESSER
Sheffield HS	544/68	57	Roof	Roof Replacement	\$	3,290,000	10/20/2024	12/15/2025	Design	Coleman	MSCS - ESSER
			- 4.15						Scope developed and submitted to Procurement for bid		
Ch official data	F44/C0	F-7	Fire/Life	Replace Fire	_	700 000	TDD		process. Est. January	Colores	Challey Carrate
Sheffield HS	544/68	57	Safety	Detection System	\$	700,000	TBD	TBD	Board	Coleman	Shelby County

Location	Enrollment/ Staff	Age of Building (Years)	Project Type	Description	Tota	al Cost	Start Date	End Date	Status	MSCS Board Member	Funding Source
				Repair Library Wing					Notice to proceed		
Sherwood MS	694/82	67	Foundation	Walls	\$	202,000	TBD	TBD	issued.	Coleman	MSCS - ESSER
Shrine School	142/63	48	HVAC	Replace Boilers, Pumps, Chillers, Controls	\$	901,285	10/20/2024	12/15/2025	Notice to proceed issued.	Coleman	MSCS - ESSER
Snowden K8	1247/130	115	Paving	Entire Lot	\$	200,000	TBD		Scope developed and submitted to Procurement for bid process. Est. January Board	McKinney	City of Memphis
Southwind HS	1596/142	17	Athletics	Outdoor Lighting (softball, baseball, soccer)	\$	735,000	TBD		Scope developed and submitted to Procurement for bid process. Est. January Board	Porter	MSCS Fund 1
Southwillaris	1330/142	Ι,	Attricties	LED Lighting	7	755,000	100	100	Dodia	1 01101	110001 unu 1
Southwind HS	1596/142	17	Electric	Upgrade-Gym	\$	35,000	TBD	TBD	Equipment Ordered	Porter	City of Memphis
Springdale ES	230/40	84	HVAC	UV, RTU, AHU, Boiler, Pump, Chiller, Controls	\$	2,423,502	10/20/2024		Notice to proceed issued.	McKinney	MSCS - ESSER
TLA Admin	200	79	Roof	Roof Replacement	\$	184,902	10/20/2024	12/15/2025	Design	McKissack	MSCS - ESSER
White Station HS	1923/165	71	Electric	LED Lighting Upgrade-Gym	\$	35,000	TBD	TBD	Equipment Ordered	Huett-Garcia	City of Memphis
Wooddale HS	657/73	57	Electric	LED Lighting Upgrade-Gym	\$	35,000	TBD	TBD	Equipment Ordered	Coleman	City of Memphis

		December 15, 2024 Ongoing Capit	tal Projects Update	!		
			Contract End			MSCS Board
School	Project Category	Scope	Date	Phase	Status	Member
A.B. Hill ES	Roof	AB Hill ES Roof Replacement	12/30/2024	Const	Board approved November	McKissack
					3rd floor underway; quote received for fire	
Bayer	Storm Repair	Bayer Building Repair-Insurance	5/1/2025	Const	pump	McKinney
Bethel Grove ES	Fire Alarm System	Bethel Grove ES Fire Alarm Upgrades	3/1/2025	Const	Construction ongoing	Coleman
		Bolton HS Roof Replacement Phase II-				
Bolton HS	Roof	Construction	TBD	Const	Board approved November	Huett-Garcia
					Complete; Fire marshal inspection to be	
					scheduled (simultaneous to Sea Isle	
Bruce ES	Fire Alarm System	Bruce ES Fire Alarm Upgrades	12/30/2024	Const	Inspect)	McKissack
					Classrooms complete. Boilers and pumps	
Cherokee ES	HVAC	Cherokee ES HVAC Replacement	12/30/2024	Const	underway.	Coleman
					Construction in process; Est complete	
Craigmont HS	Fire Alarm System	Craigmont HS Fire Alarm Upgrades	12/30/2024	Const	Dec.	McKinney
Craigmont MS	Foundation Repair	Craigmont MS Foundation	12/15/2024	Const	Construction ongoing	McKinney
Dexter ES	Roof	Dexter ES Roof Replacement	12/30/2024	Const	Board approved November	Huett-Garcia
Double Tree ES	Fire Alarm System	Double Tree ES Fire Alarm Upgrades	12/30/2024	Const	Complete; Fire Marshal rescheduled	Williams
Douglass K8	Fire Alarm System	Douglass K8 Fire Alarm Upgrades	3/1/2025	Const	Construction ongoing	McKinney
Douglass K8	Intercom System	Douglass K8 Intercom System	1/30/2025	Const	Intercom Phase II; Est complete Jan-25	McKinney
East HS	Restroom Reno.	East HS Restroom Renovation	11/12/2024	ł	Construction ongoing	McKinney
Egypt ES	Fire Alarm System	Egypt ES Fire Alarm Upgrades	3/1/2025		Construction ongoing	Love
					Complete; Fire Marshal inspection next	
Evans ES	Fire Alarm System	Evans ES Fire Alarm Upgrades	12/30/2024	Const	(simultaneously with Newberry Inspect)	Coleman
Georgian Hills MS	Roof	Georgian Hills MS Roof Replacement	7/15/2025	 	Board approved November	Love
Ocorgian i illo i ilo	11001	ocorbian rinto rio nooi nepiacement	//13/2023	Const	Construction-old floor demo; colors	LOVE
Germantown HS	Gym Floor	Germantown HS Gym Floor Replacement	8/31/2025	Const	chosen	Porter
Comantown no	Oyiii i tool	Octimatiowith Goyint tool neptacement	0/31/2023	Const	Controls installed, installing boiler plant;	i orter
Getwell ES	HVAC	Getwell ES HVAC Upgrades	12/30/2024	Const	move to chilled plant in winter	Murphy

		December 15, 2024 Ongoing Capita	al Projects Update			
			Contract End			MSCS Board
School	Project Category	Scope	Date	Phase	Status	Member
					Construction in process; half asbestos	
Havenview MS	Fire Alarm System	Havenview MS Fire Alarm Upgrades	12/30/2024	Const	abatement complete	Williams
					Installing controls, pumps, VFDs; cooling	
Idlewild ES	HVAC	Idlewild ES HVAC	12/30/2024	Const	tower complete	McKissack
Idlewild ES	Intercom System	Idlewild ES Intercom System	1/30/2025	Const	Intercom Phase II; Est complete Jan-25	McKissack
					Construction in process; mid-December	
Invictus Acad. (Airways)	Fire Alarm System	Invictus Academy Fire Alarm Upgrades	12/30/2024	Const	estimated complete	Murphy
Keystone ES	Roof	Keystone Elementary Roof Replacement	7/15/2025	Const	Notice to proceed issued	Love
New East Reg HS	New School Const	New East Region High School Project Mgmt.	6/30/2027	Hold	Awaiting survey; geotechnical analysis; Railroad released easement; City Council denied zoning change	Otey
New Frayser HS	New School Const	New Frayser HS New Const-Design	6/30/2027	Design	Demo complete; Value Engineering to \$120M complete	Love
Newberry ES	Fire Alarm System	Newberry ES Fire Alarm Upgrades	3/1/2025	Const	Complete; Fire Marshal inspection being scheduled (simultaneously with Evans inspect)	Murphy
Oakshire ES	Intercom System	Oakshire ES Intercom System	2/28/2025	Const	Intercom Phase II; Est complete Jan-25	Williams
Overton HS	HVAC	Overton HS HVAC Upgrades	12/30/2024	Const	All SCUVs in place; awaiting 5 additional units	Coleman
Peabody ES	Fire Alarm System	Peabody ES Fire Alarm Upgrades	10/30/2024	Const	Construction in progress; est. complete Dec 15	McKissack
Raleigh Egypt MS	Gym Floor	Raleigh-Egypt MS gym floor	8/31/2025	Const	Notice to proceed issued; pre- construction meeting conducted	Love
Raleigh Egypt MS/HS	HVAC	Raleigh-Egypt HS HVAC Upgrades	12/30/2024	Const	UV, AHU, controls, boilers, pumps are installed; Gym RTUs/boilers and completing chiller install remain	Love

		December 15, 2024 Ongoing Cap	oital Projects Update	!		
			Contract End			MSCS Board
School	Project Category	Scope	Date	Phase	Status	Member
					Engineering plans complete and contract	
	Drainage/Building	Richland ES Drainage Enhancement /			request submitted; Pickering architecture	
Richland ES	Envelope	Building Envelope Repair & Enhance	TRD	Design	contract under review	Huett-Garcia
THOMAIN EO	Livetope	Partaing Envelope Repair & Envelope	155	Doorgin	oontract ander review	Tracti Gardia
Richland ES	Intercom System	Richland ES Intercom System	2/28/2025	Const	Intercom Phase II; Est complete Feb-25	Huett-Garcia
Ridgeway HS	Intercom System	Ridgeway HS Intercom System	3/31/2025	Const	Intercom Phase II; EST complete March-25	Coleman
<u> </u>	,	Sustainability Grant (HVAC, windows,			<u> </u>	
Riverview K8	Fed Grant	lighting)	TBD	Planning	Project scope complete. Est Feb. Board	Williams
Riverwood ES	Intercom System	Riverwood ES Intercom System	2/28/2025	Const	Intercom Phase II; EST complete Feb-25	Otey
						,
Rozelle ES	Intercom System	Rozelle ES Intercom System	12/31/2024	Const	Intercom Phase II; EST complete Dec.	Murphy
					Complete; Fire Marshall inspection to be	
					scheduled (simultaneously with Bruce	
Sea Isle ES	Fire Alarm System	Sea Isle ES Fire Alarm Upgrades	12/30/2024	Const	inspect)	Coleman
Sherwood ES	Intercom System	Sherwood ES Intercom System	3/31/2025	Const	Intercom Phase II; Est complete Feb-25	Coleman
Springdale ES	Fire Alarm System	Springdale Fire Alarm	3/1/2025	Const	Construction in process	McKinney
Treadwell ES	Fire Alarm System	Treadwell ES Fire Alarm Upgrades	12/30/2024	Const	Construction in process	McKinney
Treadwell ES	Intercom System	Treadwell ES Intercom System	3/31/2025	Const	Intercom Phase II; EST complete March-25	McKinney
Treadwell ES/MS	Roof	Treadwell K8 Roof Replace	12/30/2024	Const	Board approved November	McKinney
Freadwell MS	Auditorium	Treadwell Auditorium Renovation	4/11/2025	Const	Notice to proceed issued	McKinney
			40/00/0004		Construction in process; Late Nov.	
Freadwell MS	Fire Alarm System	Treadwell MS Fire Alarm Upgrades	12/30/2024	Const	estimated complete	McKinney
Trezevant HS	HVAC	Trezevant HS Chiller Replace	1/1/2025	Const	Chiller to be delivered; on track	Love
TTC (Gragg)	HVAC	TTC HVAC	12/30/2024	Const	Construction ongoing	McKinney
Wells Station ES	Foundation Repair	Wells Station ES Foundation Repair	12/31/2024	Const	Construction ongoing	McKinney

		December 15, 2024 Ongoing Capi	tal Projects Update)		
			Contract End			MSCS Board
School	Project Category	Scope	Date	Phase	Status	Member
Westwood HS	Roof	Westwood HS Roof	2/15/2025	Const	Construction ongoing	Keith Williams
Whitehaven ES	Intercom System	Whitehaven ES Intercom System	8/31/2024	Const	Intercom Phase II; Est complete Dec.	Williams
Whitehaven HS	Building Addition	Whitehaven HS STEM building Addition	TBD	Const	Site prep and foundation work	Williams
Whitehaven HS	Intercom System	Whitehaven HS Intercom System	12/31/2024	Const	Adding speakers	Williams
William H. Brewster ES	Intercom System	William H. Brewster ES Intercom System	12/31/2024	Const	Intercom Phase II; Est complete Jan-25	McKinney

New Frayser HS

Demolition began 8/14/24

Update - Last 30 Days:

TWF Builders office & safety trailer setup onsite

Construction fence installation complete

Earthwork mobilization and site clearing continues

Abatement Complete

Interior / Exterior demolition complete

Phase 1 erosion control installed

MLGW utility disconnect provided to MSCS

Steel order and specs to be determined

Content area meetings with District staff continue (low voltage,

performing arts, STEM)

Awaiting District payment of ERP3 (Early Release Package funding for construction materials)

Value engineering/redesign reduced construction cost to \$120M Groundbreaking planning ongoing

Mayor announced support for more funding from County County Commission Committee voted in favor of funding Dec. 11 (not official)

County Commission Dec. 16

New East Region HS

NERHS Site

- No Additional Action Letter issued by TDEC for former CSX Rail Spur
- CSX removed the deed restrictions from the Rail Spur that currently limit school and athletic uses
- NERHS Planned Development APPROVED unanimously by the Land Use Control Board; heard in City Council Committee (Aug. 20)
- NERHS Planned Development scheduled for City Council vote in September

Site Next Steps:

- Continue due diligence on Baptist/Ferrell Paving site
- Submit Baptist/Ferrell Paving site PD to LUCB for zoning
- ■Design Development will continue pending:
- Approval of VE Changes & Target Project Cost; under review
- Recommendations on cuts to Program/scope to further reduce costs
- ALTA Survey and Geotechnical Analysis Summaries District authorization needed Cost to be updated by CMAR at 100% DDs

City Council Meeting 9/10/24-removed from agenda

City Council Meeting 10/2/24 (removed from agenda; second removal)

City Council Meeting in November 12

CITY COUNCIL VOTED NO ON LAND USE ZONING CHANGE
NERHS CAN NOT BE BUILT ON SELECTED SITE
STAFF IS INVESTIGATING ALTERNATIVES AND WILL PRESENT OPTIONS