

Project Data	
Location Code:	030
Address:	3925 Wales
Year Built:	1957
Grade Configuration:	K-6
Student Capacity:	460/600
Ideal Capacity:	403
ADA Student Enrollment:	0
Portables:	7
Building & Addition	50,376 s. f.

Description:	
Upgrade to ADA guidelines.	
Timeline:	Cost:
2013-14	\$810,000

Description: Replace approximately (264) windows Image: Timeline: 2016-17

Description: Floor tile contain asbestos and is in poor condition overall.	
Timeline:	Cost:
TBD	\$105,000

Description: Doors in kitchen are old, in poor condition and creating health department issues.	
Timeline: TBD	Cost: \$7,000
	\$7,000
	· ·
Description: Door frames in the kitchen are rusting and creating health department issues.	Cost:

TBD

Description:	
No A/C in kitchen.	
	Picture not available
Timeline:	Cost:
TBD	\$55,000

\$4,700

Playground/Surfaces Equipment Status:

Partially equipped Has woodchips w crossties border surface

Playground Equipment / Surface Condition:

Used, needs updating. Does not need replacing. Poor surface No fence enclosure



Description:	-
Tuck point, clean, seal and paint exterior	
Timeline:	Cost:
2010-11	\$133,600

Description: PVC Single Ply Roof: 5 years-Good	
Timeline:	Cost:
TBD	\$144,250

Description:	
Intercom System:	
Dukane 3200	
Installation Date: 1995	
Timeline:	Cost:
TBD	¢ =0,000
	\$50,000