



THE OFFICE OF FACILITY MAINTENANCE

1364 Farmville Road • Memphis, TN 38112 • (901) 416-9670 • www.scsk12.org

Attachment 'B'

DATE: September 10, 2025

To:

From: Shonda Morrow, Environmental Health & Safety Manager

Subject: Whitney ES Full Fire Panel Replacement

In accordance with Asbestos Hazard Emergency Response Act (AHERA) the following building materials have been identified as ACM. The following materials were identified in accordance with AHERA regulations. Any activity that requires the demolition or repairs either exterior or interior, of any building components, is required to be sampled by a certified and accredited asbestos inspector.

1. Boiler Insulation
2. Residual Spray On (Bldg. 1)
3. 9x9 Floor Tile
4. Electrical Wiring (Bldg. 1)
5. Flooring mastic
6. 12X12 Floor Tile
7. Int. Win Frame Caulk

Please contact me via email MorrowS@scsk12.org and let me know if I can be of any further assistance.



THE OFFICE OF FACILITY MAINTENANCE

1364 Farmville Road • Memphis, TN 38112 • (901) 416-9670 • www.scsk12.org

Attachment 'B'

DATE: September 11, 2025

To:

From: Shonda Morrow, Environmental Health & Safety Manager

Subject: Booker T Washington (BTW) Full Fire Panel Replacement

In accordance with Asbestos Hazard Emergency Response Act (AHERA) the following building materials have been identified as ACM. The following materials were identified in accordance with AHERA regulations. Any activity that requires the demolition or repairs either exterior or interior, of any building components, is required to be sampled by a certified and accredited asbestos inspector.

1. Flooring Mastic
2. 12x12 Floor Tile

Please contact me via email Morrow@scsk12.org and let me know if I can be of any further assistance.



THE OFFICE OF FACILITY MAINTENANCE

1364 Farmville Road • Memphis, TN 38112 • (901) 416-9670 • www.scsk12.org

Attachment 'B'

DATE: September 10, 2025

To:

From: Shonda Morrow, Environmental Health & Safety Manager

Subject: Snowden K-8 Full Fire Panel Replacement

In accordance with Asbestos Hazard Emergency Response Act (AHERA) the following building materials have been identified as ACM. The following materials were identified in accordance with AHERA regulations. Any activity that requires the demolition or repairs either exterior or interior, of any building components, is required to be sampled by a certified and accredited asbestos inspector.

1. H2O Tank Insulation
2. Pipe Insulation
3. Cement & Elbows
4. Electrical Wiring (Bldg. 6)
5. Flooring mastic
6. 12X12 Floor Tile

Please contact me via email Morrow@scsk12.org and let me know if I can be of any further assistance.



THE OFFICE OF FACILITY MAINTENANCE

1364 Farmville Road • Memphis, TN 38112 • (901) 416-9670 • www.scsk12.org

Attachment 'B'

DATE: September 11, 2025

To:

From: Shonda Morrow, Environmental Health & Safety Manager

Subject: Highland Oaks ES Full Fire Panel Replacement

In accordance with Asbestos Hazard Emergency Response Act (AHERA) there have been inspections conducted at said location. Per documents submitted on 6/9/95, this location has an asbestos free management plan. Supporting documentation has been attached for reference.

Please contact me via email Morrow@scsk12.org and let me know if I can be of any further assistance.



THE OFFICE OF FACILITY MAINTENANCE

1364 Farmville Road • Memphis, TN 38112 • (901) 416-9670 • www.scsk12.org

Attachment 'B'

DATE: September 11, 2025

To:

From: Shonda Morrow, Environmental Health & Safety Manager

Subject: Kate Bond ES Full Fire Panel Replacement

In accordance with Asbestos Hazard Emergency Response Act (AHERA) there have been inspections conducted at said location. Per documents submitted on 6/9/95, this location has an asbestos free management plan for the main building. Supporting documentation has been attached for reference.

In accordance with Asbestos Hazard Emergency Response Act (AHERA) the following building materials have been identified as ACM in a portable building. The following materials were identified in accordance with AHERA regulations. Any activity that requires the demolition or repairs either exterior or interior, of any building components, is required to be sampled by a certified and accredited asbestos inspector.

1. Portable 315 Flooring Mastic

Please contact me via email MorrowS@scsk12.org and let me know if I can be of any further assistance.



THE OFFICE OF FACILITY MAINTENANCE

1364 Farmville Road • Memphis, TN 38112 • (901) 416-9670 • www.scsk12.org

Attachment 'B'

DATE: September 10, 2025

To:

From: Shonda Morrow, Environmental Health & Safety Manager

Subject: Kingsbury CTC (VoTech) Full Fire Panel Replacement

In accordance with Asbestos Hazard Emergency Response Act (AHERA) the following building materials have been identified as ACM. The following materials were identified in accordance with AHERA regulations. Any activity that requires the demolition or repairs either exterior or interior, of any building components, is required to be sampled by a certified and accredited asbestos inspector.

1. Cement Elbows & Tees
2. Transite Board
3. Flooring mastic
4. 12X12 Floor Tile

Please contact me via email MorrowS@scsk12.org and let me know if I can be of any further assistance.