



2010 FACILITIES ASSESSMENT LEVI ELEMENTARY




Project Data	
Location Code:	165
Address:	3939 Highway 61 South
Year Built:	1928
Grade Configuration:	K-6
Baseline Enrollment: (current enrollment excluding CDC and Pre-K)	436
Programmatic Capacity: (without portables)	480
Ideal Capacity:	386
Size:	9.24 acres
Portables:	0
Building & Addition	71,179 s. f.




2010 FACILITIES ASSESSMENT LEVI ELEMENTARY

<p>Description:</p> <p>Dumpster needs enclosed</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$5,000</p>


<p>Description:</p> <p>Exterior of building needs pressure washing.</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$1,200</p>

<p>Description:</p> <p>Built up: 18 years-poor</p> <p>Metal roof: 18 years-fair</p> <p>Built up modified roof: 18 years-poor</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Cost:</p> <p>\$186,750</p>


2010 FACILITIES ASSESSMENT LEVI ELEMENTARY

<p>Playground/Surfaces Equipment Status:</p> <p>Fully equipped, various, Used-modern-large swing set, Slide, monkey bars/ladder structure Woodchips w/ heavy plastic border surface</p>	
<p>Playground Equipment / Surface Condition:</p> <p>Used, but adequate, does not need replacing Good surface No fence enclosure</p>	
<p>Description:</p> <p>Paint interior of building</p>	
<p>Timeline:</p> <p>2012-13</p>	<p>Cost:</p> <p>\$85,000</p>

2010 FACILITIES ASSESSMENT
LEVI ELEMENTARY

<p>Description:</p> <p>Patch, crack, repair and overlay (6,600) sq. yd. asphalt parking lot</p>	
<p>Timeline:</p> <p>2011-12</p>	<p>Cost:</p> <p>\$75,000</p>

2010 FACILITIES ASSESSMENT LEVI ELEMENTARY

<p>Description:</p> <p>Intercom System:</p> <p>Dukane 3200</p> <p>Installation Date: 1994</p>	
<p>Timeline:</p> <p>TBD</p>	<p>Costs:</p> <p>\$50,000</p>