

WINRIDGE ELEMENTARY- WALL DAMAGE- PHOTOGRAPHS




08/10/21- Exterior wall damage from vehicle



08/10/21- Direction vehicle came from



08/10/21- Exterior wall damage from vehicle



08/10/21- Interior classroom damage



08/10/21- Interior classroom damage



08/10/21- Interior classroom damage

WINRIDGE ELEMENTARY- WALL DAMAGE- PHOTOGRAPHS



08/10/21- Interior classroom damage



08/10/21- Interior classroom damage



08/10/21- Interior classroom damage



08/10/21- Interior classroom damage

